



AHERA ASBESTOS REINSPECTION

Gymnasium Annex
200 South Dayton Street
Kennewick, Washington

Prepared For:
Kennewick School District

Prepared By:
PBS Engineering + Environmental
320 North Johnson Street, Suite 700
Kennewick, Washington 99336

August 2013
Project #63601.00

320 N. Johnson St.
Suite 700
Kennewick, WA 99336
509.735.2698 PHONE
509.735.1867 FAX

ENGINEERING AND ENVIRONMENTAL

www.pbsenv.com

Gymnasium Annex

This reinspection process under the AHERA rules states that a school building must be reinspected by an accredited inspector at least every three years. The results of the reinspection are reported in these documents.

LIST OF DOCUMENTS

Material Summary Page 1.1
 Updated Assessments Page 2.1
 Bulk Sample Information (if samples taken) Page 3.1

ACTIVITY DATES

09/06/88 Management Plan Implementation Date
 08/21/13 Reinspection
08/21/16 Next Reinspection Due

REINSPECTION SUMMARY

Asbestos-containing 9" x 9" vinyl floor tile and presumed asbestos-containing (PAC) floor tile mastic are present on the Main Floor Boy's and Girl's Locker Room landings. The CAB in the Boys and Girls Locker Rooms is now covered with reinforced fiberglass and is still exposed on the upper North wall of the East Gymnasium; no damage to the CAB was noted.

SIGNATURES

Inspector

Management Planner



David Ross Date
 Accreditation IR-13-6483A

Steve Devine Date
 Accreditation IMR-13-7647A

PBS Environmental
 320 N. Johnson St., Ste. 700
 Kennewick, WA 99336
 (509) 735-2698
 Project No. 63601.00

Gymnasium Annex

Known or suspected asbestos-containing building materials are listed below in order of hazard priority. The priorities are established by the Accredited Inspector(s) and Accredited Management Planner(s), and are based on the assessments. A material may be listed more than once if its location varies and if the assessment criteria also dramatically changes.

1. MATERIAL 9"x 9: Vinyl Floor Tile and Adhesive
LOCATION Throughout locker room landings
CATEGORY Low Concern
Tested Positive ACM with potential for damage.

2. MATERIAL 12"x 12: Vinyl Floor Tile and Adhesive
LOCATION Throughout hallways of main gymnasium floor
CATEGORY Low Concern
Tested Positive ACM with potential for damage.

3. MATERIAL Cement Asbestos Board
LOCATION Locker rooms and upper North wall of the East gymnasium
CATEGORY Low Concern
Nonfriable presumed ACM

Gymnasium Annex

PRIORITY NO. 1

MATERIAL **9”x 9” Vinyl Floor Tile and Mastic**

LOCATION Boy’s and Girl’s locker Room Landings

DESCRIPTION

Manufactured floor tiles typically 9” x 9” or 12” x 12”, composed of a dense vinyl matrix that often contains asbestos and is adhered to the substrate with a mastic that often contains asbestos.

QUANTITY Not quantified

SAMPLE RESULTS **POSITIVE**

ASSESSMENT Low Concern - Non friable

CURRENT DAMAGE Yes

UNDAMAGED AREA **GOOD**

FRIABILITY LOW

ACCESSIBILITY **LOW**

DAMAGE POTENTIAL **MODERATE**

DAMAGE TYPE Impact

DAMAGE CAUSE Age Impact

DISCUSSION

Floor tiles and mastic pose a relatively low concern unless made friable through sanding, drilling, cutting, etc. Use of abrasive floor buffers should be avoided.

RESPONSE ACTIONS

- Preventative Measures Prior to Abatement
- Continue to implement Operations & Maintenance Program.
- Recommended Abatement Action
- None required after enacting Preventative Measure.
- Other Options – None suggested.

PRIORITY NO. 2

MATERIAL **12"x 12" Vinyl Floor Tile and Mastic**

LOCATION Throughout Main Floor Hallways

DESCRIPTION

Manufactured floor tiles typically 9" x 9" or 12" x 12", composed of a dense vinyl matrix that often contains asbestos and is adhered to the substrate with a mastic that often contains asbestos.

QUANTITY Not quantified

SAMPLE RESULTS ASSUMED POSITIVE

ASSESSMENT Low Concern - Non friable

CURRENT DAMAGE Yes

UNDAMAGED AREA GOOD

FRIABILITY LOW

ACCESSIBILITY LOW

DAMAGE POTENTIAL MODERATE

DAMAGE TYPE Impact

DAMAGE CAUSE Age Impact

DISCUSSION

Floor tiles and mastic pose a relatively low concern unless made friable through sanding, drilling, cutting, etc. Use of abrasive floor buffers should be avoided.

RESPONSE ACTIONS

Preventative Measures Prior to Abatement

Continue to implement Operations & Maintenance Program.

Recommended Abatement Action

None required after enacting Preventative Measure.

Other Options – None suggested.

PRIORITY NO. 3

MATERIAL Cement Asbestos Board

LOCATION Boy's and Girl's locker Rooms (now beneath reinforced fiberglass) and North upper wall of the East Gymnasium

DESCRIPTION

Manufactured cementitious sheets with asbestos fibers bound into the material's matrix. The sheets were generally held in place with nails or screws.

QUANTITY Not quantified

SAMPLES TAKEN: None

ASSESSMENT AHERA CLASSIFICATION Nonfriable suspected ACBM

CONCERN CATEGORY Low Concern

CURRENT DAMAGE None

UNDAMAGED AREA Good

FRIABILITY Low

ACCESSIBILITY Low

DAMAGE POTENTIAL Low

DAMAGE TYPE

DAMAGE CAUSE

DISCUSSION

The material presents a relatively low concern in its current condition. Avoid activities that may impact this material.

RESPONSE ACTIONS

Preventative Measures Prior to Abatement
Continue to implement Operations & Maintenance Program.
Recommended Abatement Action
None required after enacting preventative measures.
Other Options – None suggested.

THIS IS TO CERTIFY THAT

DAVID D ROSS

HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE
for
ASBESTOS INSPECTOR REFRESHER

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

Course Date: 01/18/2013

Course Location: Kennewick, WA

Certificate: IR-13-6483A



**Engineering +
Environmental**

Expiration Date: 01/18/2014

AHERA is the Asbestos Hazard
Emergency Response Act enacting Title II
of Toxic Substance Control Act (TSCA)

For verification of the authenticity of this
certificate contact:
PBS Environmental
4412 SW Corbett Avenue
Portland, OR 97239
(503) 248-1939

A handwritten signature in black ink that reads "David Stover". The signature is written in a cursive style with a prominent "D" and "S".

David Stover, Director of Training

THIS IS TO CERTIFY THAT

STEVE DEVINE


HAS SUCCESSFULLY COMPLETED THE TRAINING COURSE

for

**ASBESTOS INSPECTOR / MANAGEMENT
PLANNER REFRESHER**

In accordance with TSCA Title II, Part 763, Subpart E, Appendix C of 40 CFR

Course Date: 01/18/2013
Course Location: Kennewick, WA
Certificate: IMR-13-7647A



**Engineering +
Environmental**

Expiration Date: 01/18/2014

AHERA is the Asbestos Hazard
Emergency Response Act enacting Title II
of Toxic Substance Control Act (TSCA)

For verification of the authenticity of this
certificate contact:
PBS Environmental
4412 SW Corbett Avenue
Portland, OR 97239
(503) 248-1939

David Stover

David Stover, Director of Training