


# Washington School Structural Evaluation

SPECIAL BOARD MEETING AUGUST 12, 2022



# History


---



# Building Information



3D Model of the Building



Typical Wall Section

- Building Type is “Enhanced” Unreinforced Masonry, meaning the brick has been improved with a layer of concrete
- Unreinforced Masonry (URM) has been phased out of construction entirely in CA due to poor seismic performance

# Structural Evaluation

---

19six Engineers conducted the following:

- On site structural visual observations
- Review of prior structural and geotechnical reports, as-built drawings, local and state jurisdiction correspondence
- Prepare ASCE41 Tier 1 Evaluation of the building for Life Safety level of seismic performance, identifying potential deficiencies based on prescriptive checklists
- Obtain an updated soils report for the site



# Life Safety – Structural Performance Level

---

- Different seismic performance levels exist and are chosen based on the building's use, occupancy
- Performance levels define the level of earthquake applied and the relative safety of structure after the seismic event
- The District has chosen Life Safety, defined by ASCE41-17 as:
  - “...the post-earthquake damage state in which a structure has damaged components but retains a margin of safety against the onset of partial or total collapse.”* (2.3.1.3)
- Life Safety is recommended for cases:
  - “Where public safety is the primary concern, the standard's Life Safety Performance Level is often appropriate... [The] provisions were developed to support programs focused on the safety of persons, as opposed to programs seeking to minimize repair cost or downtime.”* (B2.1)

# Findings – Structural Deficiencies

---

# Deficiencies – Wall Anchors

---



- These type of wall anchors are not recommended to resist seismic forces without further enhancement. Therefore, the walls are missing proper out-of-plane anchorage.


# Deficiencies – Wall Cracking

---



- Presence of surface cracking indicates possible damage to reinforcing and/or concrete layer.

# Deficiencies – Overstressed and Slender Walls



Typical Wall Section

- When analyzing the walls for seismic forces, a vast majority of the shear walls are overstressed when considering the shear walls as unreinforced masonry (URM). Only one of the walls is overstressed when analyzed as concrete.
- The height-to-thickness proportions of the masonry and concrete walls exceed the limits of the checklists.



# Unknowns



- **Extent of damage to the exterior walls** - Cracking, multiple past repairs, deterioration of shotcrete coating, bond between the brick and shotcrete are unknown
- **Seismic retrofit detailing** – Detailing of rebar, embedment length into foundation elements will affect seismic performance
- **Behavior of floor diaphragms** - Damage can result from incompatibility between flexible wood floors and rigid concrete floors during a seismic event
- **Reliability of existing “Government” type wall anchors** – These are now considered unreliable, can be enhanced
- **Enhanced masonry bearing wall seismic performance** – Shotcrete was added to the URM walls to improve performance. However, limited testing and real-world examples make it difficult to predict how well the system will perform.

# Conclusions

---

## ***Can Washington School be DSA Approved as a Public School?***

### ***Feasibility of returning school building to DSA-use:***

- DSA does not allow the use of unreinforced brick masonry walls (URM) to support gravity or seismic loads, therefore a new structural system would be required to be constructed within the building. Rehabilitation costs are likely to exceed replacement costs for the building, due to fire / life safety, accessibility, and structural upgrades.

## ***Does the building meet the District's chosen ASCE41 seismic performance criteria (Life Safety) for its current use as a non-DSA educational facility?***

- Not at present time. Mitigation of the checklist of deficiencies is possible.
- Mitigating the Tier 1 checklist items will bring the building into conformance with the ASCE41 Tier 1 seismic performance criteria and certainly improve on certain seismic weaknesses of the building. However, due to building age and construction type, its seismic performance cannot be determined with a great deal of accuracy. The Significance of Unknown Information section of the report highlights the concerns that cannot be mitigated without substantial retrofit work.

# Questions?

---

