

Asbestos Hazard Emergency Response Act Three-Year Asbestos Re-Inspection and Management Plan Update

for
Trumbull High School

For Compliance with
State of Connecticut Department of Public Health
Asbestos-Containing Materials in Schools Regulation
(Sections 19a - 333-1 through 19a - 333-13)
and
EPA Asbestos Hazard Emergency Response Act
(Title 40 CFR, Part 763, Subpart E)

Trumbull Public Schools
Trumbull, Connecticut

June 2024



59 Elm Street – Suite 500
New Haven, CT 06510

June 11, 2024

Mr. David P. Cote, PE.
Director of Operations
Trumbull Public Schools
72 Strobel Road
Trumbull, CT 06611

RE: Three-Year AHERA Asbestos Re-Inspection and Management Plan Update
Re-Inspection Date: April 11, 2024
Trumbull High School
72 Strobel Road, Trumbull, CT.
Fuss & O'Neill Project No. 20201149.A30

Enclosed is the three-year AHERA Asbestos Re-Inspection and Asbestos Management Plan (AMP) Update report prepared by Fuss & O'Neill, Inc. at the Trumbull High School located at 72 Strobel Road in Trumbull, Connecticut (the "Site"). The inspection was performed for the Trumbull Public Schools (the "Client"). This report is an important document that must be kept on file at the school as well as at a central location where the AMPs are maintained.

If you should have any questions regarding this report, please do not hesitate to contact me. Thank you for this opportunity to have served your environmental needs.

Sincerely,



Eduardo Miguel Marques
Senior Environmental Analyst

EMM/nw

Enclosure

Table of Contents

Asbestos Hazard Emergency Response Act Three-Year Re-Inspection and Management Plan Update School Name

1	Introduction.....	1
1.1	Background.....	1
1.2	Local Education Agency (LEA) Responsibilities	1
1.3	Accreditation.....	2
2	Building and Mechanical System Description.....	3
3	Three Year Re-Inspection	3
3.1	Re-Inspection Procedures	3
4	Re-Inspection Report	3
4.1	Review of Existing Records	3
4.2	Re-Inspection Summary	3
4.3	Newly Identified or Re-sampled ACBM Materials	8
4.4	Physical Assessment of ACBM	9
5	Management Plan Update	9
5.1	Recommended Response Actions	9
5.2	Periodic Surveillance	11
5.3	Preventive Measures.....	11
5.4	Abatement (Removal) Cost Estimates	11
6	EPA Accreditation Requirements	11

Appendices

End of Report

APPENDIX A	EXISTING RECORDS CHECKLIST
APPENDIX B	RE-INSPECTION FORM 1A
APPENDIX C	RE-INSPECTION FORM 2
APPENDIX D	SAMPLE 6-MONTH PERIODIC SURVEILLANCE FORM
APPENDIX E	PREVENTIVE MEASURES
APPENDIX F	ASBESTOS INSPECTOR AND MANAGEMENT PLANNER STATE LICENSES AND EPA ACCREDITATIONS

1 Introduction

1.1 Background

The Clean Air Act required the United States Environmental Protection Agency (EPA) to develop standards to address the potential health risks associated with adverse effects of asbestos exposure as an indoor contaminant. In October 1986, the EPA promulgated the Asbestos Hazard Emergency Response Act (AHERA) located at Title 40 CFR, Part 763, Subpart E.

The AHERA regulations required that local education agencies (LEAs) conduct inspections of each school building that they lease, own, or otherwise use as a school building to identify friable (easily crumbled or crushed to powder by hand pressure) and non-friable asbestos-containing building materials (ACBM) locations. The original inspections were required to have been completed prior to October 12, 1988.

AHERA also requires that any building leased or acquired on or after October 12, 1988, that is to be used as a school building shall be inspected for friable and non-friable ACBM prior to use as a school building. In the event of an emergency use of a building that has not been inspected for ACBM, the building shall be inspected within 30 days after commencement of such use.

The regulatory requirements remain in effect for private or public-school systems, a church-affiliated school of any denomination, a school dedicated to the education of children with special needs, or a charter school. In the State of Connecticut, the Department of Public Health (CTDPH) is responsible for AHERA regulation enforcement.

1.2 Local Education Agency (LEA) Responsibilities

The LEA is responsible for compliance with the AHERA regulation. The following responsibilities must be followed:

1. The LEA must designate a person to ensure that all of the AHERA requirements are properly implemented. The Designated Person must receive adequate training to perform their duties.
2. The LEA must ensure that the asbestos management plans (AMPs) are maintained in a central location, as well as at each facility, and such plans and records are available for inspection or review at all times.
3. The LEA must inform all workers, building occupants or their legal representative in writing at least once per school year about asbestos-related activities, and the availability of the AHERA AMPs for the school buildings.
4. The LEA must ensure proper accreditations for all persons who perform asbestos inspections, asbestos re-inspections, develop/update AMPs, develop response actions, and perform required response actions including operations and maintenance (O&M) activities that may disturb asbestos.

5. The LEA must provide training for all custodial and maintenance staff who regularly perform building maintenance where ACBM are present. The training must be provided upon initial hire, as well as annual updates.
6. The LEA must provide information (disclosure) to any workers who may perform work and may come into contact with asbestos in school buildings where ACBM or presumed ACBM are present.
7. The LEA must ensure that known ACBM or presumed ACBM are provided with warning labels in routine maintenance areas.
8. The LEA must ensure that periodic surveillance is performed at least once every six months, after AMP implementation, in all school buildings that it leases, owns, or otherwise uses that contain ACBM or presumed ACBM.
9. The LEA must ensure that once every three years, after an AMP is implemented, a Re-Inspection is performed at each school building that it leases owns or otherwise uses that contains ACBM or presumed ACBM.

Refer to above-mentioned regulation for full requirements and responsibilities.

1.3 Accreditation

- A. LEA: Trumbull Public Schools
 Address: 72 Strobel Road
 Trumbull, CT
 Phone: (203) 452-4300
- B. Designated Person: Mr. David P. Cote, PE.
 Address: 72 Strobel Road
 Trumbull, CT
 Phone: (203) 452-4300
- C. Asbestos Consultant:
 Firm: Fuss & O'Neill, Inc.
 Address: 59 Elm Street – Suite 500
 New Haven, CT
 Phone: (203) 374-3748
 Fax: (860) 533-5143
- D. Asbestos Inspector:
 Inspector: Sandra L. Guzman
 CTDPH License #: 000335
 Expiration Date: 08/31/2024

E. Asbestos Inspector/Management Planner:

Planner:	Eduardo Miguel Marques
CTDPH License #:	000201
Expiration:	02/28/2025

2 Building and Mechanical System Description

The original Trumbull High School is a two-story building and was reportedly constructed in 1962. The building contains approximately 280,000 square feet (SF) of total floor area. The building had undergone major renovations throughout the building during 2010 to 2012. The building is heated by gas-fired hot water and rooftop heating, ventilation and air conditioning (HVAC) units.

3 Three Year Re-Inspection

3.1 Re-Inspection Procedures

This three-year asbestos re-inspection was conducted in accordance with EPA requirements of the AHERA regulation, Title 40 CFR, Part 763, Section 763.85 (b).

On April 11, 2024, Fuss & O'Neill, Inc. (Fuss & O'Neill) representatives Ms. Sandra Guzman performed the re-inspection.

A. During the re-inspection, Fuss & O'Neill conducted the following required tasks:

1. A visual re-inspection and reassessment of all known friable or assumed ACBM.
2. A visual re-inspection of ACBM that was previously considered non-friable to determine if the present condition of the material has become friable.
3. Identification and assessment of any newly identified homogeneous area that contains friable ACBM since the last inspection or re-inspection.

4 Re-Inspection Report

4.1 Review of Existing Records

An important part of this AHERA re-inspection involved researching prior documentation that is required to be present at the school, as well as at the central recordkeeping location where AMPs are stored.

Please see *Appendix A* for the checklist for existing records.

4.2 Re-Inspection Summary

The on-site portion of the re-inspection was documented on forms modeled after examples provided by the EPA and reviewed with the CTDPH. The first form, **Re-Inspection Form 1A**, identifies previous inspection data gathered during the initial AHERA inspection and subsequent re-inspection (see *Appendix B*). This form is useful to reference response actions (if any), which have been performed since the last inspection, as

well as identifying the last known conditions of ACBM in the building. It additionally provides the inspector a "quick glance" reference when performing the re-inspection.

The second EPA form, **Re-Inspection Form 1B**, is used to list all known or assumed asbestos-containing materials that were previously unidentified. No new materials were included in the current re-inspection report therefore Form 1B is not included.

The third EPA form, **Re-Inspection Form 2**, was used to provide information and justification regarding re-assessment of the ACBM (see *Appendix C*). This form also provides response action recommendations, including a tentative schedule for completing response actions that recommend removal or repair.

No bulk samples were collected during this re-inspection.

Using EPA protocol and criteria, the following materials existing in Trumbull High School at the time of this three-year re-inspection have been determined and/or assumed to be ACBM. Please refer to the above-mentioned Re-Inspection Forms for specific locations of the materials.

Table 1
Asbestos-Containing Building Materials

Material	Location	Reference	Asbestos Content
Black & Yellow 12" x 12" Floor Tile & associated Mastic	Gym Foyer, 1 st Floor Industrial Arts, Women's Lavatory Foyer Infilled in Senior Lounge, Rooms A16-A19, A31-A34, B16-B19, and C32-C35	EnviroMed 2015 Re-Inspection	Assumed
Black 12" x 12" Floor Tile and Yellow 12" x 12" Floor Tile (checkered pattern) & associated Mastic	G67 Weight Room Hallway, Classroom A17A, A18, A32 Storage, Classrooms A31 - A34, 1 st Floor Senior Lounge Commons, Classrooms C33, C34, C35, Infilled in Hallway by Rooms A16-A19	EnviroMed 2015 Re-Inspection	Assumed
Black with White Specks 12"x12" Floor Tile & associated Mastic	A25 Prep Room, Classrooms B27, B28 (including prep rooms)	EnviroMed 2015 Re-Inspection	Assumed
Brown with Black and White specks 12"x12" Floor Tile & associated Mastic	Industrial Arts Corridor	EnviroMed 2015 Re-Inspection	Assumed
Cream 12"x12" Floor Tile & associated Mastic	Mc214 Workroom, MC209 Book Storage, Room M21, Classrooms C15 - C17	EnviroMed 2015 Re-Inspection	Assumed
Cream with Brown Specks 12" x 12" Floor Tile & associated Mastic	Faculty Dining Room, Storage G14 Girls Locker Room, G6 Coach's Locker Room, M208 Storage, Classrooms A1, A16-A19, A21 - A28, A30-A34, B2 - B11, B16-B19, B21, B26, and Prep Rooms, B29 - B31, C3, C4, C10, C21 - C35, C201, M18, MC202, MC203B, MC208, MC209, MC213, MC220, MC224A, B29	EnviroMed 2015 Re-Inspection	Assumed
Light Gray (multiple types) 12" x 12" Floor Tile & associated Mastic	1 st Floor Senior Lounge Commons, M19, M19A, M20, Wood Shop, Wood Storage	EnviroMed 2015 Re-Inspection	Assumed

Material	Location	Reference	Asbestos Content
Light Gray with Brown and White Specks 12"x12" Floor Tile & associated Mastic	Rooms M45, M55, M55 Storage, M55A	EnviroMed 2015 Re-Inspection	Assumed
Peach with Brown Specks 12"x12" Floor Tile and associated Mastic	M45 Office	EnviroMed 2015 Re-Inspection	Assumed
Tan 12"x12" Floor Tile & associated Mastic	Classroom A13, C5 - C9	EnviroMed 2015 Re-Inspection	Assumed
Tan with Brown Specks 12"x12" Floor Tile & associated Mastic	Coach's Office, G51 Trainer's Office, G52, G52 Closet, Coach's Hallway, G6 Coach's Hallway, M24 - M27, M11 E, F, M11 A, M11 C, M11 H, AUD 14, AUD 12, AUD 17, AUD 24, AUD 25, AUD 22, Equipment Room Hallway, Practice Rooms M51, M52, M54, M15A, M5, M5A, M5B, Rooms M12, 1st floor Custodial Closet, 1st floor Mechanical room, M37, C1, C11	EnviroMed 2015 Re-Inspection	Assumed
Tan with Cream Specks 12"x12" Floor Tile & associated Mastic	AUD16, Rooms A2 - 12, A15, A16, B1, B12 - B14	EnviroMed 2015 Re-Inspection	Assumed
White 12"x12" Floor Tile & associated Mastic	Rooms M116, M117, M107 Conference Hallway, Work Room, M119, Nurse, M10A Office, M10 Storage, M9 Office, M9A Storage, M4 Sewing Room, M10, M7 Hallway, M8 Computer Lab, M9 Drafting, M3 Laundry Room, Hallway M3, Room M1, M3	EnviroMed 2015 Re-Inspection	Assumed
White with Gray and Yellow Specks 12"x12" Floor Tile & associated Mastic	Room A16, A17A, A18, A19, 1st floor Wing a Hallway, B16 - B19	EnviroMed 2015 Re-Inspection	Assumed
Grout and Thin-set Mortar associated with Black Ceramic Floor and Wall Tiles (various sizes)	1 st Floor B-Wing Bathrooms, Boys Showers / Lockers / Bathroom, G11 Girls Showers, G21 Girls Locker Room, G6 Girl's Bathroom, G25 Girls Showers, G52 Bathroom, 1 st Floor C-Wing Girls Bathroom	EnviroMed 2015 Re-Inspection	Assumed
Grout and Thinset associated with Dark Gray 12"x12" Ceramic Floor Tile	M10 bathroom, M104 bathroom, M119 bathroom, 1st floor Adim wing bathroom, M20A	EnviroMed 2015 Re-Inspection	Assumed
Grout and Thinset associated with Gray 12"x12" Ceramic Floor Tile	1 st floor Industrial Arts bathrooms, 1st floor Maintenance bathroom & locker room	EnviroMed 2015 Re-Inspection	Assumed
Terrazzo Flooring	A-C Wing Hallways, M-Wing Hallway, Gym Girls' and Boys' Foyer, 1 st Floor C36, Cafeteria and Commons	EnviroMed 2015 Re-Inspection	Assumed
Carpet Glue	M112 - M115, Hall to Dean's Office, M107, Main Office, M110, M104, B House Principal's Office, B House Conference Room, B106 Guidance, C-House Guidance, C103 - C109, AD26, 1 st Floor Industrial Arts Practice Rooms,	EnviroMed 2015 Re-Inspection	Assumed

Material	Location	Reference	Asbestos Content
	M45, M2, M22, M23, B102, B104, B105, Media Center, C24, MC 209 A, MC 218, MC204, MC201, MC221 Office, MC216, MC223 - MC225, MC211, MC210B, MC210		
Floor Underlayment Tar Paper	Gym, Auxiliary Gym, M14	EnviroMed 2015 Re-Inspection	Assumed
Black 4" Cove Base Molding and associated Glue	Senior Lounge, C36 Storage, G15, 1st Floor Gym Wing Girls' and Boys' Foyer, Hallway G67, Gym Foyer, G21, Girls' Locker Room, G6, G25, Hallway A, M19, M20, Hallway B, Wood Shop, M13, M19A, 1st Floor A-Wing Hallway, A16 - A19, B6, B7, B16 - B19, 1st Floor C-Wing Hallway, A211, C201, A25, A26, B27, B28, B22, C32 - C35	EnviroMed 2015 Re-Inspection	Assumed
Black 6" Cove Base Molding and associated Glue	G15, G67, 1st Floor Industrial Arts Wing Hallway, A31 - A34, B24, B25	EnviroMed 2015 Re-Inspection	Assumed
Gray 6" Cove Base Molding and associated Glue	M107, M112 - M114, M116, M117, B106, Faculty Dining Room, 1st Floor Administration Work Room, C121, G35, G65, G51, G52, G6, G4, M4, M10, M24 - M27, M11 A, C, E, F, H, M7 - M9, AUD22, AUD 24, AUD25, AUD16, M51, M52, M54, M3, M10A, M20B, M15A, M9, M12, Custodian's Office, 1st Floor Mechanical Office, M55, M45, M1 - M5, A1 - A13, A15, A16, B1 - B14, B-Wing House Rooms 102, 104, 105, C1 - C11, C15 - C17, Media Center, C23, C24, MC208 - MC214, MC201 - MC205, MC208, MC224 - MC225, A21 - A30, B21 - B30, C21 - C31	EnviroMed 2015 Re-Inspection	Assumed
Tan 6" Cove Base Molding and associated Glue	C-House Guidance	EnviroMed 2015 Re-Inspection	Assumed
Wall Panel Glue	M45, M45A	EnviroMed 2015 Re-Inspection	Assumed
Wallboard & Joint Compound	M112, PTSA Office, G14, 2 nd Floor Stairs Ceilings	EnviroMed 2015 Re-Inspection	Assumed
Grout and Thin Set associated with Yellow and Pink Ceramic Wall Tiles	M Locker Room, G15, G52, G49, Boys Shower Room, G21, G11, G6, G25, M20A, 1 st Floor Wing B bathrooms, 2 nd Floor C-Wing Girls Bathroom	EnviroMed 2015 Re-Inspection	Assumed
2'x2' Suspended Ceiling Tiles (multiple types including short slots & pinholes, textured with pinholes, and pinholes)	M104, M107, M112 - M115, M119, M11, M7 Hallway, M9, 1st Floor Industrial Arts Hallway, Industrial Arts Practice Room, M2, M55A, M45A, A17 Storage, Senior Lounge, M45, A16 - A19, A31 - A34, B16 - B19, C32 - C35, B	EnviroMed 2015 Re-Inspection	Assumed

Material	Location	Reference	Asbestos Content
	House Principal's office, B House Conference Room, C House Guidance, C103 - C105, C107 - C109, Gym Foyer, A1 - A16, B2 - B11, B Wing Hallway by B6 & B7, C15 - C17, Media Center, C201, MC209, MC213, MC214, MC218, MC201 - MC205, MC210, MC211, MC216, MC223 - MC224		
2'x4' Suspended Ceiling Tiles (multiple types including brown, flat white, slots & pinholes, white with bird tracks, pinholes)	Media Center, Food Service Room, F7, G13, M37, M5A, M110 Lavatory, First Floor Maintenance Custodians Office, Mechanical Room Office, Bath Room Locker Room, M Locker, M107, M116, M117, M119, M10 A Office, M10 Storage, M19A Book Room, Women's Lavatory Hall, Ladies' Lavatory Foyer, Men's Lavatory, Women's Lavatory, Equipment Room, M4, M10, M24 - M27, Hallway A, M19, M20, M20 A, M11 E, F, M11 C, Hallway C, Commons Cafeteria, M7, M8, Hallway, AUD 22, AUD 16, Practice Rooms M51, M52, M54, M3 Laundry Room, M3 Hallway, Rooms M12, M55 Closet, M55 Storage, M45, M45 Office, M1, M2, M1 Closet, M5 B, M3, M22/M23 Storage, F9 Office, Faculty Dining Room, B106 Guidance Rooms 1-7, C121, C35 Office, G65 Office, G36 Storage, Coach's Office, G51 Trainers, G52, G52 Bathroom, Coach's Hallway, C6 Coach's, C6 Coach's Bathroom, G 6 Coaches Locker Room, G 4 Equipment Storage, G67, B12, B13, B102, B104, B105, B14, B1, C2- 12, A211, C23, C24, MC208, MC209, MC225, B 29, A21 - A30, B21, B24 - B31, C21 - C31, F13	EnviroMed 2015 Re-Inspection	Assumed
Plaster Ceiling Base & Skim Coat	Boys locker Room, Boys Showers, Locker Bathroom, Locker Shower, Boys Bath Room, G11, G21, G6, M14, M15A, M15B, 1 st Floor Industrial Arts Men's' and Women's' Bathroom, M11A, AUD12, Generator Room, 1 st Floor B-Wing Girls Bathroom	EnviroMed 2015 Re-Inspection	Assumed
Tectum Ceiling Panel	Gym, Auxiliary Gym, Auto Shop, Wood Shop, M13, M14, M12A, Boiler Room	EnviroMed 2015 Re-Inspection	Assumed
Chalkboard and Tackboard Adhesive	M9, M24, M9	EnviroMed 2015 Re-Inspection	Assumed
Gray Sink Undercoat	B16, B18	EnviroMed 2015 Re-Inspection	Assumed

Material	Location	Reference	Asbestos Content
Black Sink Undercoat	G52, M4, M7, M13, M3, MC205, MC209, MC213, MC220, B29, B22, B27/B28 Prep Room, C23, C24	EnviroMed 2015 Re-Inspection	Assumed
Black Countertop	M25, B29, A21 - A28, B21 - B28	EnviroMed 2015 Re-Inspection	Assumed
Door Frame Caulking	G49, Gym Wing Boys' Foyer	EnviroMed 2015 Re-Inspection	Assumed
Window Frame Caulking	Gym, M14-3, M19, M0	EnviroMed 2015 Re-Inspection	Assumed
Pipe & Pipe Fitting Insulation	Behind Walls and Fixed Ceilings (Assumed to be present)	EnviroMed 2015 Re-Inspection	Assumed

Using the EPA protocol, samples of the following suspect materials were collected and analyzed. The analytical results indicated that these materials are **non-ACBM**:

Table 2
Non-Asbestos-Containing Building Materials (Previous Re-Inspections)

Material	Location	Reference
Black and Beige Stage Curtains	Stage	Eagle Environmental February 29, 2024

Mr. Eduardo Miguel Marques reviewed the information obtained during this Re-Inspection. Mr. Marques is an EPA-accredited and CTDPH-licensed Asbestos Inspector/Management Planner.

4.3 Newly Identified or Re-sampled ACBM Materials

The following newly identified suspect ACBM have been identified in the building:

- 4" Gray Cove Base Molding and associated Adhesive;
- Brown 6" Cove Base Molding and associated Adhesive;
- Gray CMU Wall Block/Mortar;
- Wall Padding Adhesives;
- Brown Window Glazing Compound; and
- Electrical Fixtures Wiring.

The above-listed materials may have been recently installed. If the materials have been recently installed, the Client may obtain a letter from an Architect for renovations conducted at the Site, a Safety Data Sheet (SDS) for the product or a letter from the material manufacturer stating asbestos was not used in the manufacturing of the product. Alternatively, the material may be sampled to determine potential asbestos content. If this information cannot be obtained, this material will be quantified and included in the AMP during the next triennial update.

AHERA regulations pertain to interior identified or assumed ACBM and limited exterior ACBM. AHERA regulations do include ACBM located on exterior porticos, covered walkways, and mechanical equipment used to condition interior building air.

Any suspect material encountered during renovation/demolition/maintenance activities that is not specifically identified in the AMP as a non-ACBM should be assumed to contain asbestos unless sample results indicate otherwise.

Additional Information:

- Asbestos-containing floor tile and associated mastics may exist below non-moveable objects such as cabinets, platforms, sheetrock walls, lockers, etc.;
- Samples of exterior building materials not covered under AHERA, such as caulking and glazing compounds, roofing materials and materials behind exterior walls and panels should be collected and analyzed to determine asbestos content prior to performing activities that would disturb them;
- Asbestos-containing vapor barriers and waterproofing materials may exist beneath wood floors, behind walls, exterior below ground surface foundations, etc.; and
- Subsurface cementitious pipe (i.e., asbestos cement pipe).

4.4 Physical Assessment of ACBM

During the inspection, suspect ACBM were separated into three EPA categories. These categories are thermal system insulation (TSI), surfacing ACBM, and miscellaneous ACBM. TSI includes all materials used to prevent heat loss or gain or water condensation on mechanical systems. Examples of TSI are pipe and fitting insulations, boiler insulation, and duct insulation. Surfacing ACBM is commonly used for fireproofing, decorative, and acoustical applications. Miscellaneous materials include all ACBM not listed in TSI or surfacing, such as sheet flooring, vinyl asbestos flooring, ceiling tiles, and construction mastics/adhesives.

Finally, ACBM were quantified in linear and/or square feet, depending on the nature of the material.

The ACBM identified during the inspection and still remaining in the school were re-assessed using the CTDPH and AHERA guidelines for assessment of ACBM. The following assessment categories are listed:

1. Damaged or significantly damaged TSI ACBM
2. Damaged friable surfacing ACBM
3. Significantly damaged friable surfacing ACBM
4. Damaged or significantly damaged friable miscellaneous ACBM
5. ACBM with potential for damage
6. ACBM with potential for significant damage
7. Any remaining friable ACBM or friable suspected ACBM

Material locations, assessments, and recommended response actions are listed in the Re-Inspection forms.

5 Management Plan Update

5.1 Recommended Response Actions

Based on the inspection report, physical walk-through inspection, and existing ACBM conditions, the following response actions are recommended:

1. Removal - Not Applicable

2. Repair - Not Applicable
3. Enclosure - Not Applicable
4. Encapsulation - Not Applicable
5. Operations and Maintenance (O & M) - All remaining ACBM and:
 - Repair 3 cream with brown specks 12" x 12" floor tiles cracked at Room A31.
 - Repair 2 SF of wallboard & joint compound at 2nd floor A Wing Stairs ceiling.

It should be noted that only ACBM with assessments of 1 or 2 are recommended for removal or repair. The remaining ACBM should be included in the O & M Program. The condition of these ACBM will be monitored until all of the ACBM have been completely removed from the building. A successful O & M Program includes the following elements:

- A. Cleaning: All areas of the school where friable ACBM or assumed friable ACBM are present should be cleaned at least once after completion of the initial inspection. Additional cleaning may be necessary if the Management Planner makes a written recommendation indicating the methods and frequency of such cleaning.
- B. O & M Activities: The LEA shall ensure that the procedures described below are followed to protect building occupants from O & M activities that may disturb known or assumed ACBM:
 1. Restrict entry into the area either by physically isolating or by scheduling.
 2. Post asbestos warning signs to prevent entry by unauthorized persons.
 3. Deactivate or temporarily shut off or divert the air-handling system to the area.
 4. Use proper work practices and engineering controls, such as wet methods, protective clothing, High Efficiency Particulate Air (HEPA) vacuums, mini enclosures/glove bags, etc. to inhibit fiber migration.
 5. Place asbestos debris and other contaminated materials into a sealed, leak-tight container for disposal.
- C. Minor Fiber Release Episode: The LEA shall ensure that the procedures described below are followed in the event of a minor fiber release episode (i.e., disturbance of less than or equal to 3 linear/square feet of friable ACBM):
 1. Saturate the debris using wet method.
 2. Place the debris in a sealed, leak-tight container and clean the area.
 3. Repair the area of damaged ACBM with materials such as asbestos-free spackling, plaster or insulation or seal with an encapsulant.
- D. Major Fiber Release Episode: The LEA shall ensure that the procedures described below are followed in the event of a major fiber release episode (i.e., disturbance of greater than 3 linear/square feet of friable ACBM):
 1. Restrict entry into the area and post asbestos warning signs.
 2. Deactivate or temporarily shut off or divert the air handling system from the area to prevent fiber migration.
 3. The response action for any major fiber release episode must be prepared by EPA-accredited Asbestos Project Designers and conducted by EPA-accredited personnel.

4. The LEA shall notify the CTDPH of any major fiber release episode within twenty-four hours of its occurrence and, if necessary, provide written notification as required by applicable federal and/or state regulations.

5.2 Periodic Surveillance

At least once every six months after an AMP is implemented, the LEA will conduct periodic surveillance in the school that contains ACBM or assumed ACBM. The person conducting periodic surveillance will visually inspect all areas in the school where ACBM have been identified in the AMP, record the date of surveillance, their name, any changes in the ACBM condition and submit the record to the LEA Designated Person for inclusion in the AMP.

Please see *Appendix D* for the sample Periodic Surveillance Form that may be used for conducting periodic surveillance.

5.3 Preventive Measures

The LEA shall institute appropriate preventive measures to eliminate the reasonable likelihood that ACBM will become damaged, deteriorated, or delaminated.

Please see *Appendix E* for preventive measures designed for various types of ACBM that may exist in the school.

5.4 Abatement (Removal) Cost Estimates

At the time of the April 11, 2024, re-inspection, no materials were observed to be damaged (other than O&M repairs); therefore, estimated abatement cost have not been provided.

6 EPA Accreditation Requirements

The EPA accreditations and the CTDPH Asbestos Inspector licenses for Sandra Guzman and Eduardo Miguel Marques are provided in *Appendix F*.

Report prepared by Environmental Analyst I, Sandra Guzman.

Reviewed by:



Eduardo Miguel Marques
Senior Environmental Analyst



Kathleen C. Pane
Associate | Department Manager

Appendix A

Existing Records Checklist

Existing Records Checklist

Local Education Agency (LEA): Trumbull Public Schools
6254 Main Street
Trumbull, CT 06611

School Building: Trumbull High School,
72 Strobel Road, Trumbull, CT 06611

The following documentation is required to be present in both the LEA's office, as well as in a centralized location in the school administrative office. The information included in this checklist will be verified to be present and complete as part of a three-year Re-Inspection.

DOCUMENTATION		LOCATION	
		School	LEA Office
1	Original AHERA Operations and Maintenance Plan/Inspection Report	No	No
2	Three Year Re-Inspection (First and All Subsequent Inspections)	No	Limited
3	Parents and Teachers Notifications (Annually Since Last Re-Inspection)	No	Yes
4	Designated Person Identification and Proper Training (Person Must Be Named and Have Appropriate Training)	No	-
5	Designated Person Periodic Surveillance (Once Every Six Months)	No	Yes
6	Maintenance Staff Awareness Training Records	No	Yes
7	Outside Vendor Awareness Notification	No	Yes
8	Asbestos Warning Signs and Labels (Required Posting in Boiler Rooms and Mechanical Spaces Only)	No	NA
9	Response Action Records (Includes Any Abatement Conducted Since Last 3-Year Re-Inspection)	No	Yes

Comments: Items marked "No" indicate not present/available at the time of this inspection.

Inspector (LEA Office): Sandra Guzman

Date: April 8, 2024

Inspector (School): Sandra Guzman

Date: April 11, 2024

Appendix B

Re-Inspection Form 1A



Re-Inspection Form 1 (A) – List of Identified ACBMP Page 1 of 1

School: Trumbull High School Date(s) of Original Inspection: 1990
 Address: 72 Strobel Road, Trumbull, CT Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Page 1 of 10

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
NA	Assumed	Black & Yellow 12" x 12" Floor Tile & associated Mastic	Misc.	NF	5	Gym Foyer, 1 st Floor Industrial Arts, Women's Lavatory Foyer Infilled in Senior Lounge, Rooms A16-A19, A31-A34, B16-B19, and C32-C35	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Black 12" x 12" Floor Tile and Yellow 12" x 12" Floor Tile (checkered pattern) & associated Mastic	Misc.	NF	5	G67 Weight Room Hallway, Classroom A17A, A18, A32 Storage, Classrooms A31 - A34, 1 st Floor Senior Lounge Commons, Classrooms C33, C34, C35, Infilled in Hallway by Rooms A16-A19	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Black with white specks 12"x12" Floor Tile & associated Mastic	Misc.	NF	5	A25 Prep Room, Classrooms B27, B28 (including prep rooms)	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Brown with Black and White Specks 12"x12" Floor Tile & associated Mastic	Misc.	NF	5	Industrial Arts Corridor	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Cream 12"x12" floor Tile & associated Mastic	Misc.	NF	5	Mc214 Workroom, MC209 Book Storage, Room M21, Classrooms C15 - C17	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Cream with Brown Specks 12" x 12" Floor Tile & associated Mastic	Misc.	NF	5	Faculty Dining Room, Storage G14 Girl's' Locker Room, G6 Coach's Locker Room, M208 Storage, Classrooms A1, A16-A19, A21 - A28, A30-A34, B2 - B11, B16-B19, B21, B26, and Prep Rooms, B29 - B31, C3, C4, C10, C21 - C35,	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance



Re-Inspection Form 1 (A) – List of Identified ACBMP Page 2 of 1

School: Trumbull High School Date(s) of Original Inspection: 1990
 Address: 72 Strobel Road, Trumbull, CT Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Page 2 of 10

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
						C201, M18, MC202, MC203B, MC208, MC209, MC213, MC220, MC224A, B29	
NA	Assumed	Light Gray (multiple types) 12" x 12" Floor Tile & associated Mastic	Misc.	NF	5	1 st Floor Senior Lounge Commons, M19, M19A, M20, Wood Shop, Wood Storage	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Light Gray with Brown and White Specks 12"x12" Floor Tile & associated Mastic	Misc.	NF	5	Rooms M45, M55, M55 Storage, M55A	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Peach with Brown Specks 12"x12" Floor Tile and associated Mastic	Misc.	NF	5	M45 Office	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Tan 12"x12" floor tile & associated mastic	Misc.	NF	5	Classroom A13, C5 - C9	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Tan with brown Specks 12"x12" Floor Tile & associated Mastic	Misc.	NF	5	Coach's Office, G51 Trainer's Office, G52, G52 Closet, Coach's Hallway, G6 Coach's Hallway, M24 - M27, M11 E, F, M11 A, M11 C, M11 H, AUD 14, AUD 12, AUD 17, AUD 24, AUD 25, AUD 22, Equipment Room Hallway, Practice Rooms M51 , M52, M54, M15A, M5, M5A, M5B, Rooms M12, 1 st floor	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance



Re-Inspection Form 1 (A) – List of Identified ACBMP Page 3 of 1

School: Trumbull High School Date(s) of Original Inspection: 1990
 Address: 72 Strobel Road, Trumbull, CT Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Page 3 of 10

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
						Custodial Closet, 1 st floor Mechanical Room, M37, C1, C11	
NA	Assumed	Tan with cream specks 12"x12" Floor Tile & associated Mastic	Misc.	NF	5	AUD16, Rooms A2 - 12, A15, A16, B1, B12 - B14	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	White 12"x12" Floor Tile & associated Mastic	Misc.	NF	5	Rooms M116, M117, M107 Conference Hallway, Work Room, M119, Nurse, M10A Office, M10 Storage, M9 Office, M9A Storage, M4 Sewing Room, M10, M7 Hallway, M8 Computer Lab, M9 Drafting, M3 Laundry Room, Hallway M3, Room M1, M3	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	White with Gray and Yellow Specks 12"x12" Floor Tile & associated Mastic	Misc.	NF	5	Room A16, A17A, A18, A19, 1st floor Wing A Hallway, B16 - B19	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Grout and Thin-set Mortar associated with Black Ceramic Floor and Wall Tiles (various sizes)	Misc.	NF	5	1 st Floor B-Wing Bathrooms, Boys Showers / Lockers / Bathroom, G11 Girl's Showers, G21 Girls Locker Room, G6 Girl's Bathroom, G25 Girls Showers, G52 Bathroom, 1 st Floor C-Wing Girls Bathroom	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Grout and thinset associated with Dark Gray 12"x12" ceramic floor tile	Misc.	NF	5	M10 bathroom, M104 bathroom, M119 bathroom, 1st floor Adim wing bathroom, M20A	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance

Re-Inspection Form 1 (A) – List of Identified ACBM Page 4 of 1

School: Trumbull High School Date(s) of Original Inspection: 1990
Address: 72 Strobel Road, Trumbull, CT Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Page 4 of 10

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
NA	Assumed	Grout and thinset associated with Gray 12"x12" ceramic floor tile	Misc.	NF	5	1 st Floor Industrial Arts bathrooms, 1 st Floor Maintenance Bathroom & Locker Room	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Terrazzo Flooring	Misc.	NF	5	A-C Wing Hallways, M-Wing Hallway, Gym Girls' and Boys Foyer, 1 st Floor C36, Cafeteria and Commons	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Carpet Glue	Misc.	NF	5	M112 - M115, Hall to Dean's Office, M107, Main Office, M110, M104, B House Principal's Office, B House Conference Room, B106 Guidance, C-House Guidance, C103 - C109, AD26, 1 st Floor Industrial Arts Practice Rooms, M45, M2, M22, M23, B102, B104, B105, Media Center, C24, MC 209 A, MC 218, MC204, MC201, MC221 Office, MC216, MC223 - MC225, MC211, MC210B, MC210	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Floor Underlayment Tar Paper	Misc.	NF	5	Gym, Auxiliary Gym, M14	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Black 4" Cove Base Molding and associated Glue	Misc.	NF	5	Senior Lounge, C36 Storage, G15, 1 st Floor Gym Wing Girls' and Boys Foyer, Hallway G67, Gym Foyer, G21, Girls Locker Room, G6, G25, Hallway A, M19,	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance



Re-Inspection Form 1 (A) – List of Identified ACBM Page 5 of 1

School: Trumbull High School Date(s) of Original Inspection: 1990
 Address: 72 Strobel Road, Trumbull, CT Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Page 5 of 10

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
						M20, Hallway B, Wood Shop, M13, M19A, 1 st Floor A-Wing Hallway, A16 - A19, B6, B7, B16 - B19, 1 st Floor C-Wing Hallway, A211, C201, A25, A26, B27, B28, B22, C32 - C35	
NA	Assumed	Black 6" Cove Base Molding and associated Glue	Misc.	NF	5	G15, G67, 1st Floor Industrial Arts Wing Hallway, A31 - A34, B24, B25	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Gray 6" Cove Base Molding and associated Glue	Misc.	NF	5	M107, M112 - M114, M116, M117, B106, Faculty Dining Room, 1 st Floor Administration Work Room, C121, G35, G65, G51, G52, G6, G4, M4, M10, M24 - M27, M11 A, C, E, F, H, M7 - M9, AUD22, AUD 24, AUD25, AUD16, M51, M52, M54, M3, M10A, M20B, M15A, M9, M12, Custodian's Office, 1st Floor Mechanical Office, M55, M45, M1 - M5, A1 - A13, A15, A16, B1 - B14, B-Wing House Rooms 102, 104, 105, C1 - C11, C15 - C17, Media Center, C23, C24, MC208 - MC214, MC201 - MC205, MC208, MC224 - MC225, A21 - A30, B21 - B30, C21 - C31	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance

Re-Inspection Form 1 (A) – List of Identified ACBMP Page 6 of 1

School: Trumbull High School Date(s) of Original Inspection: 1990
 Address: 72 Strobel Road, Trumbull, CT Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Page 6 of 10

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
NA	Assumed	Tan 6" Cove Base Molding and associated Glue	Misc.	NF	5	C-House Guidance	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Wall Panel Glue	Misc.	NF	5	M45, M45A	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Wallboard & Joint Compound	Misc.	NF	5	M112, PTSA Office, G14, 2 nd Floor Stairs Ceilings	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Grout and Thin Set associated with Yellow and Pink Ceramic Wall Tiles	Misc.	NF	5	M Locker Room, G15, G52, G49, Boys Shower Room, G21, G11, G6, G25, M20A, 1st Floor Wing B bathrooms, 2 nd Floor C-Wing Girls Bathroom	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	2'x2' Suspended Ceiling Tiles (multiple types including short slots & pinholes, textured with pinholes, and pinholes)	Misc.	NF	5	M104, M107, M112 - M115, M119, M11, M7 Hallway, M9, 1st Floor Industrial Arts Hallway, Industrial Arts Practice Room, M2, M55A, M45A, A17 Storage, Senior Lounge, M45, A16 - A19, A31 - A34, B16 - B19, C32 - C35, B House Principal's office, B House Conference Room, C House Guidance, C103 - C105, C107 - C109, Gym Foyer, A1 - A16, B2 - B11, B Wing Hallway by B6 & B7, C15 - C17, Media Center, C201, MC209, MC213,	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance



Re-Inspection Form 1 (A) – List of Identified ACBMPage 7 of 1

School: Trumbull High School Date(s) of Original Inspection: 1990
 Address 72 Strobel Road, Trumbull, CT Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Page 7 of 10

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
						MC214, MC218, MC201 - MC205, MC210, MC211, MC216, MC223 - MC224	
NA	Assumed	2'x4' Suspended Ceiling Tiles (multiple types including brown, flat white, slots & pinholes, white with bird tracks, pinholes)	Misc.	NF	5	Media Center, Food Service Room, F7, G13, M37, M5A, M110 Lavatory, First Floor Maintenance Custodians Office, Mechanical Room Office, Bath Room Locker Room, M Locker, M107, M116, M117, M119, M10 A Office, M10 Storage, M19A Book Room, Women's Lavatory Hall, Ladies' Lavatory Foyer, Men's Lavatory, Women's Lavatory, Equipment Room, M4, M10, M24 - M27, Hallway A, M19, M20, M20 A, M11 E, F, M11 C, Hallway C, Commons Cafeteria, M7, M8, Hallway, AUD 22, AUD 16, Practice Rooms M51, M52, M54, M3 Laundry Room, M3 Hallway, Rooms M12, M55 Closet, M55 Storage, M45, M45 Office, M1, M2, M1 Closet, M5 B, M3, M22/M23 Storage, F9 Office, Faculty Dining Room, B106 Guidance Rooms 1-7, C121, C35 Office, G65 Office, G36 Storage, Coach's Office, G51 Trainers, G52, G52 Bathroom, Coach's Hallway, C6 Coach's, C6 Coach's Bathroom, G 6 Coach's Locker	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance



Re-Inspection Form 1 (A) – List of Identified ACBM Page 8 of 1

School: Trumbull High School Date(s) of Original Inspection: 1990
 Address 72 Strobel Road, Trumbull, CT Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Page 8 of 10

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
						Room, G 4 Equipment Storage, G67, B12, B13, B102, B104, B105, B14, B1, C2- 12, A211, C23, C24, MC208, MC209, MC225, B 29, A21 - A30, B21, B24 - B31, C21 - C31, F13	
NA	Assumed	Plaster Ceiling Base & Skim Coat	Surf.	F	5	Boys' locker Room, Boys Showers, Locker Bathroom, Locker Shower, Boys Bathroom, G11, G21, G6, M14, M15A, M15B, 1 st Floor Industrial Arts Men's and Women's' Bathroom, M11A, AUD12, Generator Room, 1st Floor B-Wing Girls Bathroom	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Tectum Ceiling Panel	Misc.	NF	5	Gym, Auxiliary Gym, Auto Shop, Wood Shop, M13, M14, M12A, Boiler Room	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Chalkboard and Tackboard Adhesive	Misc.	NF	5	M9, M24, M9	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Gray Sink Undercoat	Misc.	NF	5	B16, B18	Not Regulated By AHERA; For Informational Purposes Only. Material Must Be Managed/Disposed Of As ACBM Maintain Under O & M Plan.



Re-Inspection Form 1 (A) – List of Identified ACBM Page 9 of 1

School: Trumbull High School Date(s) of Original Inspection: 1990
 Address: 72 Strobel Road, Trumbull, CT Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Page 9 of 10

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
							Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Black Sink Undercoat	Misc.	NF	5	G52, M4, M7, M13, M3, MC205, MC209, MC213, MC220, B29, B22, B27/B28 Prep Room, C23, C24	Not Regulated by AHERA; For Informational Purposes Only. Material Must be Managed/Disposed of as ACBM Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Black Countertop	Misc.	NF	5	M25, B29, A21 - A28, B21 - B28	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Door Frame Caulk	Misc.	NF	5	G49, Gym Wing Boys Foyer	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance
NA	Assumed	Window Frame Caulking	Misc.	NF	5	Gym, M14-3, M19, M0	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance



Re-Inspection Form 1 (A) – List of Identified ACBMPage 10 of 1

School: Trumbull High School Date(s) of Original Inspection: 1990
Address 72 Strobel Road, Trumbull, CT Date(s) of Subsequent Re-Inspections: 2015, 2021, 2024

Page 10 of 10

Homogeneous Material			Material Category	Friability	Assessment Category (1-7)	Recorded Locations	Response Actions Taken/Renovations/Other Comments
Sample Number	Asbestos Content	Material Description					
NA	Assumed	Pipe & Pipe Fitting Insulation	TSI	NF	5	Behind Walls and Fixed Ceilings (Assumed to be present)	Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance

Information abstracted by: Sandra Guzman

Date: April 11, 2024

Material Category: TSI = Thermal System Insulation, Surf. = Surfacing, Misc. = Miscellaneous

Friability: F = Friable, NF = Non-Friable

AHERA Assessment Categories: 1 = Damaged or significantly damaged TSI ACBM; 2 = Damaged friable surfacing ACBM; 3 = Significantly damaged friable surfacing ACBM; 4 = Damaged or significantly damaged friable miscellaneous ACBM; 5 = ACBM with potential for damage; 6 = ACBM with potential for significant damage; 7 = Any remaining friable ACBM or friable suspected ACBM

Appendix C

Re-Inspection Form 2



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 1 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Black & Yellow 12" x 12" Floor Tile & associated Mastic

 Sample ID Number: Assumed



ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Gym Foyer, 1 st Floor Industrial Arts, Women's Lavatory Foyer Infilled in Senior Lounge, Rooms A16-A19, A31- A34, B16-B19 and C32- C35	NF	5,700 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? <u>(No)</u>					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 2 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Black 12" x 12" Floor Tile and Yellow 12" x 12" Floor Tile (checkered pattern) & associated Mastix Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
G67 Weight Room Hallway, Classroom A17A, A18, A32 Storage, Classrooms A31 - A34, 1st Floor Senior Lounge Commons, Classrooms C33, C34, C35, Infilled in Hallway by Rooms A16-A19	NF	7,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 3 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Black with white specks 12"x12" Floor Tile & associated Mastic

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
A25 Prep Room, Classrooms B27, B28 (including prep rooms)	NF	2,500 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 4 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Brown with Black and White Specks 12"x12" Floor Tile & associated Mastic

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Industrial Arts Corridor Mc214 Workroom, MC209 Book Storage, Room M21, Classrooms C15 - C17	NF	1,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 5 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Cream with Brown Specks 12" x 12" Floor Tile & associated Mastic

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Faculty Dining Room, Storage G14 Girls Locker Room, G6 Coach's Locker Room, M208 Storage, Classrooms A1, A16-A19, A21 - A28, A30-A34, B2 - B11, B16-B19, B21, B26, and Prep Rooms, B29 - B31, C3, C4, C10, C21 - C35, C201, M18, MC202, MC203B, MC208, MC209, MC213, MC220, MC224A, B29	NF	5,600 SF	5	ACBM with Potential for Damage	Repair 3 tiles cracked at room A31. Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? <u>(No)</u>					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 6 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Light Gray (multiple types) 12" x 12" Floor Tile & associated Mastic

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
1st Floor Senior Lounge Commons, M19, M19A, M20, Wood Shop, Wood Storage	NF	7,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 7 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Light Gray with Brown and White Specks 12"x12" Floor Tile & associated Mastic

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms M45, M55, M55 Storage, M55A	NF	2,800 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 8 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Peach with Brown Specks 12"x12" Floor Tile and associated Mastic

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
M45 Office	NF	120 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 9 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Tan 12"x12" Floor Tile & associated Mastic

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Classroom A13, C5 - C9	NF	3,800 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 10 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Tan with Brown Specks 12"x12" Floor Tile & associated Mastic

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Coach's Office, G51 Trainer's Office, G52, G52 Closet, Coach's Hallway, G6 Coach's Hallway, M24 - M27, M11 E, F, M11 A, M11 C, M11 H, AUD 14, AUD 12, AUD 17, AUD 24, AUD 25, AUD 22, Equipment Room Hallway, Practice Rooms M51 , M52, M54, M15A, M5, M5A, M5B, Rooms M12, 1st floor Custodial Closet, 1st floor Mechanical Room, M37, C1, C11	NF	14,500 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 11 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Tan with Cream Specks 12"x12" Floor Tile & associated Mastic

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
AUD16, Rooms A2 - 12, A15, A16, B1, B12 - B14	NF	13,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 12 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: White 12"x12" Floor Tile & associated Mastic

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Rooms M116, M117, M107 Conference Hallway, Work Room, M119, Nurse, M10A Office, M10 Storage, M9 Office, M9A Storage, M4 Sewing Room, M10, M7 Hallway, M8 Computer Lab, M9 Drafting, M3 Laundry Room, Hallway M3, Room M1, M3	NF	11,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 13 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: White with Gray and Yellow Specks 12"x12" Floor Tile & associated Mastic

Sample ID Number: Assumed



ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Room A16, A17A, A18, A19, 1st floor Wing A Hallway, B16 - B19	NF	7,200 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 14 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Grout and Thin-set Mortar associated with Black Ceramic Floor and Wall Tiles (various sizes) Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
1 st Floor B-Wing Bathrooms, Boy's Showers / Lockers / Bathroom, G11 Girls Showers, G21 Girls Locker Room, G6 Girls Bathroom, G25 Girls Showers, G52 Bathroom, 1 st Floor C-Wing Girls Bathroom	NF	2,600 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 15 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Grout and Thinset associated with Dark Gray 12"x12" Ceramic Floor Tile

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
M10 Bathroom, M104 Bathroom, M119 Bathroom, 1 st Floor Adim Wing Bathroom, M20A	NF	1,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 16 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Grout and Thinset associated with Gray 12"x12" Ceramic Floor Tile

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
1 st Floor Industrial Arts Bathrooms, 1 st Floor Maintenance Bathroom & Locker Room	NF	800 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 17 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Terrazzo Flooring

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
A-C Wing Hallways, M-Wing Hallway, Gym Girls and Boy Foyer, 1 st Floor C36, Cafeteria and Commons	NF	8,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 18 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Carpet Glue

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
M112 - M115, Hall to Dean's Office, M107, Main Office, M110, M104, B House Principal's Office, B House Conference Room, B106 Guidance, C-House Guidance, C103 - C109, AD26, 1 st Floor Industrial Arts Practice Rooms, M45, M2, M22, M23, B102, B104, B105, Media Center, C24, MC 209 A, MC 218, MC204, MC201, MC221 Office, MC216, MC223 - MC225, MC211, MC210B, MC210	NF	28,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 19 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Floor Underlayment Tar Paper

Sample ID Number: Assumed



ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Gym, Auxiliary Gym, M14	NF	3,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 20 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Black 4" Cove Base Molding and associated Glue Sample ID Number: Assumed



ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Senior Lounge, C36 Storage, G15, 1 st Floor Gym Wing Girls and Boys Foyer, Hallway G67, Gym Foyer, G21, Girls' Locker Room, G6, G25, Hallway A, M19, M20, Hallway B, Wood Shop, M13, M19A, 1 st Floor A-Wing Hallway, A16 - A19, B6, B7, B16 - B19, 1 st Floor C-Wing Hallway, A211, C201, A25, A26, B27, B28, B22, C32 - C35	NF	2,500 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 21 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Black 6" Cove Base Molding and associated Glue Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
G15, G67, 1 st Floor Industrial Arts Wing Hallway, A31 - A34, B24, B25	NF	1,500 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 22 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Gray 6" Cove Base Molding and associated Glue

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
M107, M112 - M114, M116, M117, B106, Faculty Dining Room, 1 st Floor Administration Work Room, C121, G35, G65, G51, G52, G6, G4, M4, M10, M24 - M27, M11 A, C, E, F, H, M7 - M9, AUD22, AUD 24, AUD25, AUD16, M51, M52, M54, M3, M10A, M20B, M15A, M9, M12, Custodian's Office, 1 st Floor Mechanical Office, M55, M45, M1 - M5, A1 - A13, A15, A16, B1 - B14, B-Wing House Rooms 102, 104, 105, C1 - C11, C15 - C17, Media Center, C23, C24, MC208 - MC214, MC201 - MC205, MC208, MC224 - MC225, A21 - A30, B21 - B30, C21 - C31	NF	17,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 23 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Tan 6" Cove Base Molding and associated Glue

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
C-House Guidance	NF	150 LF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 24 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Wall Panel Glue

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
M45, M45A	NF	2,400 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 25 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Wallboard & Joint Compound

 Sample ID Number: Assumed



ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
M112, PTSA Office, G14, 2 nd Floor Stairs Ceilings	NF	700 SF	5	ACBM with Potential for Damage	Repair 2 SF damaged at 2nd floor a wing stairs ceiling. Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 26 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Grout and Thin Set associated with Yellow and Pink Ceramic Wall Tiles Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
M Locker Room, G15, G52, G49, Boys Shower Room, G21, G11, G6, G25, M20A, 1 st Floor Wing B bathrooms, 2nd Floor C-Wing Girls Bathroom	NF	4,500 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 27 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: 2'x2' Suspended Ceiling Tiles (multiple types including short slots & pinholes, textured with pinholes, and pinholes)

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
M104, M107, M112 - M115, M119, M11, M7 Hallway, M9, 1 st Floor Industrial Arts Hallway, Industrial Arts Practice Room, M2, M55A, M45A, A17 Storage, Senior Lounge, M45, A16 - A19, A31 - A34, B16 - B19, C32 - C35, B House Principal's office, B House Conference Room, C House Guidance, C103 - C105, C107 - C109, Gym Foyer, A1 - A16, B2 - B11, B Wing Hallway by B6 & B7, C15 - C17, Media Center, C201, MC209, MC213, MC214, MC218, MC201 - MC205, MC210, MC211, MC216, MC223 - MC224	NF	68,000 SF	5	ACBM with Potential for Damage	16 Ceiling Tiles Stained at the 2nd Floor Hallway by Room A31. Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 28 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024



Homogeneous Material: 2'x4' Suspended Ceiling Tiles (multiple types including brown, flat white, slots & pinholes, white with bird tracks, pinholes)

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Media Center, Food Service Room, F7, G13, M37, M5A, M110 Lavatory, First Floor Maintenance Custodians Office, Mechanical Room Office, Bath Room Locker Room, M Locker, M107, M116, M117, M119, M10 A Office, M10 Storage, M19A Book Room, Women's Lavatory Hall, Ladies' Lavatory Foyer, Men's Lavatory, Women's Lavatory, Equipment Room, M4, M10, M24 - M27, Hallway A, M19, M20, M20 A, M11 E, F, M11 C, Hallway C, Commons Cafeteria, M7, M8, Hallway, AUD 22, AUD 16, Practice Rooms M51, M52, M54, M3 Laundry Room, M3 Hallway, Rooms M12, M55 Closet, M55 Storage, M45, M45 Office, M1, M2, M1 Closet, M5 B, M3, M22/M23 Storage, F9 Office, Faculty Dining Room, B106 Guidance Rooms 1-7, C121, C35 Office, G65 Office, G36 Storage, Coach's Office, G51 Trainers, G52, G52 Bathroom, Coach's Hallway, C6 Coach's, C6 Coach's Bathroom, G 6 Coaches Locker Room, G 4 Equipment Storage, G67, B12, B13, B102, B104, B105, B14, B1, C2- 12, A211, C23, C24, MC208, MC209, MC225, B 29, A21 - A30, B21, B24 - B31, C21 - C31, F13	NF	90,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going

Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

School: Trumbull High School Date of Re-Inspection: April 11, 2024

<p>Were additional samples of this ACBM collected? (<u>No</u>)</p>	<p>Date of Management Planner Review: _____</p>
<p>Inspector's Name: <u>Sandra Guzman</u></p> <p>Inspector Signature: <u></u></p> <p>Accreditation #/State: <u>000335</u></p> <p>Expiration Date: <u>08/31/2024</u></p>	<p>Management Planner Name: <u>Eduardo Miguel Marques</u></p> <p>Management Planner Signature: <u></u></p> <p>Accreditation #/State: <u>000201</u></p> <p>Expiration Date: <u>02/28/2025</u></p>
<p>I, the LEA's Designated Person, have read and understood the recommendations made above: _____</p> <p>Date: _____</p>	



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 30 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Plaster Ceiling Base & Skim Coat

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Boys' locker Room, Boys Showers, Locker Bathroom, Locker Shower, Boys Bath Rm, G11, G21, G6, M14, M15A, M15B, 1 st Floor Industrial Arts Men's' and Women's' Bathroom, M11A, AUD12, Generator Room, 1st Floor B-Wing Girls Bathroom	F	7,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____ _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 31 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Tectum Ceiling Panel

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Gym, Auxiliary Gym, Auto Shop, Wood Shop, M13, M14, M12A, Boiler Room	NF	32,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (<u>No</u>)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 32 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Chalkboard and Tackboard Adhesive

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
M9, M24, M9	NF	260 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 33 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Gray Sink Undercoat

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
B16, B18	NF	2 EA	5	ACBM with Potential for Damage	Not Regulated By AHERA; For Informational Purposes Only. Material Must Be Managed/Disposed of As ACBM Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? <u>(No)</u>					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 34 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Black Sink Undercoat

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
G52, M4, M7, M13, M3, MC205, MC209, MC213, MC220, B29, B22, B27/B28 Prep Room, C23, C24	NF	18 EA	5	ACBM with Potential for Damage	Not Regulated by AHERA; For Informational Purposes Only. Material Must be Managed/Disposed of as ACBM Maintain Under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? <u>(No)</u>					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 35 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Black Countertop

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
M25, B29, A21 - A28, B21 - B28	NF	4,000 SF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 36 of 38

 School: Trumbull High School Date of Re-Inspection: April 11, 2024

 Homogeneous Material: Door Frame Caulking

 Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
G49, Gym Wing Boys Foyer	NF	36 LF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 37 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Window Frame Caulking

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Gym, M14-3, M19, M0	NF	200 LF	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						



Re-Inspection Form 2. Re-Inspection of ACBM: Findings and Management Planner Recommendations

Page 38 of 38

School: Trumbull High School Date of Re-Inspection: April 11, 2024

Homogeneous Material: Pipe & Pipe Fitting Insulation

Sample ID Number: Assumed

ACBM RE-INSPECTION FINDINGS					MANAGEMENT PLANNER RECOMMENDATIONS	
ACBM Location(s) by Assessment Category	Friability	Estimated Quantity	Assessment Category	Physical Description	Recommended Response Action(s)	Date Action Completed
Behind Walls and Fixed Ceilings (Assumed to be present)	F	Unknown	5	ACBM with Potential for Damage	Maintain under O & M Plan. Recommend sampling to determine asbestos content prior to disturbance	On-going
Were additional samples of this ACBM collected? (No)					Date of Management Planner Review: _____	
Inspector's Name: <u>Sandra Guzman</u> Inspector Signature: <u></u> Accreditation #/State: <u>000335</u> Expiration Date: <u>08/31/2024</u>					Management Planner Name: <u>Eduardo Miguel Marques</u> Management Planner Signature: <u></u> Accreditation #/State: <u>000201</u> Expiration Date: <u>02/28/2025</u>	
I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____						

Appendix D

Sample 6-Month Periodic Surveillance Form

Sample 6- Month Periodic Surveillance Form

Local Education Agency (LEA): Trumbull Public Schools

Facility Address: Trumbull High School, 72 Strobel Road, Trumbull, CT

Date of Surveillance: _____

ACBM Damage Report

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
Black & yellow 12" x 12" floor tile & associated mastic	Gym Foyer, 1 st Floor Industrial Arts, Women's Lavatory Foyer Infilled in Senior Lounge, Rooms A16-A19, A31-A34, B16-B19, and C32-C35					
Black 12" x 12" floor tile and yellow 12" x 12" floor tile (checkered pattern) & associated Mastic	G67 Weight Room Hallway, Classroom A17A, A18, A32 Storage, Classrooms A31 - A34, 1 st Floor Senior Lounge Commons, Classrooms C33, C34, C35, Infilled in Hallway by Rooms A16-A19					
Black with white specks 12"x12" floor tile & associated mastic	A25 Prep Room, Classrooms B27, B28 (including prep rooms)					
Brown with black and white specks 12"x12" floor tile & associated mastic	Industrial Arts Corridor					
Cream 12"x12" floor tile & associated mastic	Mc214 Workroom, MC209 Book Storage, Room M21, Classrooms C15 - C17					
Cream with brown specks 12" x 12" floor tile & associated mastic	Faculty Dining Room, Storage G14 Girl's' Locker Room, G6 Coach's Locker Room, M208 Storage, Classrooms A1, A16-A19, A21 - A28, A30-A34, B2 - B11, B16-B19, B21, B26, and Prep Rooms, B29 - B31,					

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
	C3, C4, C10, C21 - C35, C201, M18, MC202, MC203B, MC208, MC209, MC213, MC220, MC224A, B29					
Light gray (multiple types) 12" x 12" floor tile & associated mastic	1 st Floor Senior Lounge Commons, M19, M19A, M20, Wood Shop, Wood Storage					
Light gray with brown and white specks 12"x12" floor tile & associated mastic	Rooms M45, M55, M55 Storage, M55A					
Peach with brown specks 12"x12" floor tile and associated mastic	M45 Office					
Tan 12"x12" floor tile & associated mastic	Classroom A13, C5 - C9					
Tan with brown specks 12"x12" floor tile & associated mastic	Coach's Office, G51 Trainer's Office, G52, G52 Closet, Coach's Hallway, G6 Coach's Hallway, M24 - M27, M11 E, F, M11 A, M11 C, M11 H, AUD 14, AUD 12, AUD 17, AUD 24, AUD 25, AUD 22, Equipment Room Hallway, Practice Rooms M51 , M52, M54, M15A, M5, M5A, M5B, Rooms M12, 1 st floor Custodial Closet, 1 st floor Mechanical Room, M37, C1, C11					
Tan with cream specks 12"x12" floor tile & associated mastic	AUD16, Rooms A2 - 12, A15, A16, B1, B12 - B14					
White 12"x12" floor tile & associated mastic	Rooms M116, M117, M107 Conference Hallway, Work Room, M119, Nurse, M10A Office, M10 Storage, M9 Office, M9A Storage, M4 Sewing Room, M10, M7 Hallway, M8 Computer Lab, M9					

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
	Drafting, M3 Laundry Room, Hallway M3, Room M1, M3					
White with gray and yellow specks 12"x12" floor tile & associated mastic	Room A16, A17A, A18, A19, 1 st floor Wing A Hallway, B16 - B19					
Grout and thin-set mortar associated with black ceramic floor and wall tiles (various sizes)	1 st Floor B-Wing Bathrooms, Boys Showers / Lockers / Bathroom, G11 Girls Showers, G21 Girls Locker Room, G6 Girls Bathroom, G25 Girls Showers, G52 Bathroom, 1 st Floor C-Wing Girls Bathroom					
Grout and thinset associated with dark gray 12"x12" ceramic floor tile	M10 Bathroom, M104 Bathroom, M119 Bathroom, 1 st Floor Adim Wing Bathroom, M20A					
Grout and thinset associated with gray 12"x12" ceramic floor tile	1 st Floor Industrial Arts Bathrooms, 1 st Floor Maintenance Bathroom & Locker room					
Terrazzo flooring	A-C Wing Hallways, M-Wing Hallway, Gym Girls' and Boys' Foyer, 1 st Floor C36, Cafeteria and Commons					
Carpet glue	M112 - M115, Hall to Dean's Office, M107, Main Office, M110, M104, B House Principal's Office, B House Conference Room, B106 Guidance, C-House Guidance, C103 - C109, AD26, 1 st Floor Industrial Arts Practice Rooms, M45, M2, M22, M23, B102, B104, B105, Media Center, C24, MC 209 A, MC 218,					

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
	MC204, MC201, MC221 Office, MC216, MC223 - MC225, MC211, MC210B, MC210					
Floor underlayment tar paper	Gym, Auxiliary Gym, M14					
Black 4" cove base molding and associated glue	Senior Lounge, C36 Storage, G15, 1st Floor Gym Wing Girls and Boys Foyer, Hallway G67, Gym Foyer, G21, Girls Locker Room, G6, G25, Hallway A, M19, M20, Hallway B, Wood Shop, M13, M19A, 1st Floor A-Wing Hallway, A16 - A19, B6, B7, B16 - B19, 1st Floor C-Wing Hallway, A211, C201, A25, A26, B27, B28, B22, C32 - C35					
Black 6" cove base molding and associated glue	G15, G67, 1st Floor Industrial Arts Wing Hallway, A31 - A34, B24, B25					
Gray 6" cove base molding and associated glue	M107, M112 - M114, M116, M117, B106, Faculty Dining Room, 1st Floor Administration Work Room, C121, G35, G65, G51, G52, G6, G4, M4, M10, M24 - M27, M11 A, C, E, F, H, M7 - M9, AUD22, AUD 24, AUD25, AUD16, M51, M52, M54, M3, M10A, M20B, M15A, M9, M12, Custodian's Office, 1st Floor Mechanical Office, M55, M45, M1 - M5, A1 - A13, A15, A16, B1 - B14, B-Wing House Rooms 102, 104, 105, C1 - C11, C15 - C17, Media Center, C23, C24, MC208 - MC214, MC201 - MC205,					

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
	MC208, MC224 - MC225, A21 - A30, B21 - B30, C21 - C31					
Tan 6" cove base molding and associated glue	C-House Guidance					
Wall panel glue	M45, M45A					
Wallboard & joint compound	M112, PTSA Office, G14, 2 nd Floor Stairs Ceilings					
Grout and thins Set associated with yellow and pink ceramic wall tiles	M Locker Room, G15, G52, G49, Boys Shower Room, G21, G11, G6, G25, M20A, 1st Floor Wing B bathrooms, 2nd Floor C-Wing Girls Bathroom					
2'x2' suspended ceiling tiles (multiple types including short slots & pinholes, textured with pinholes, and pinholes)	M104, M107, M112 - M115, M119, M11, M7 Hallway, M9, 1st Floor Industrial Arts Hallway, Industrial Arts Practice Room, M2, M55A, M45A, A17 Storage, Senior Lounge, M45, A16 - A19, A31 - A34, B16 - B19, C32 - C35, B House Principal's office, B House Conference Room, C House Guidance, C103 - C105, C107 - C109, Gym Foyer, A1 - A16, B2 - B11, B Wing Hallway by B6 & B7, C15 - C17, Media Center, C201, MC209, MC213, MC214, MC218, MC201 - MC205, MC210, MC211, MC216, MC223 - MC224					
2'x4' suspended ceiling tiles (multiple types including brown, flat white, slots & pinholes, white with bird tracks, pinholes)	Media Center, Food Service Room, F7, G13, M37, M5A, M110 Lavatory, First Floor Maintenance Custodians Office, Mechanical Room Office, Bath Room					

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
	Locker Room, M Locker, M107, M116, M117, M119, M10 A Office, M10 Storage, M19A Book Room, Women's Lavatory Hall, Ladies' Lavatory Foyer, Men's Lavatory, Women's Lavatory, Equipment Room, M4, M10, M24 - M27, Hallway A, M19, M20, M20 A, M11 E, F, M11 C, Hallway C, Commons Cafeteria, M7, M8, Hallway, AUD 22, AUD 16, Practice Rooms M51, M52, M54, M3 Laundry Room, M3 Hallway, Rooms M12, M55 Closet, M55 Storage, M45, M45 Office, M1, M2, M1 Closet, M5 B, M3, M22/M23 Storage, F9 Office, Faculty Dining Room, B106 Guidance Rooms 1-7, C121, C35 Office, G65 Office, G36 Storage, Coach's Office, G51 Trainers, G52, G52 Bathroom, Coach's Hallway, C6 Coach's, C6 Coach's Bathroom, G 6 Coach's Locker Room, G 4 Equipment Storage, G67, B12, B13, B102, B104, B105, B14, B1, C2- 12, A211, C23, C24, MC208, MC209, MC225, B 29, A21 - A30, B21, B24 - B31, C21 - C31, F13					
Plaster ceiling base & skim coat	Boys' locker Room, Boys Showers, Locker Bathroom, Locker Shower, Boys Bathroom, G11, G21, G6, M14, M15A, M15B, 1st Floor Industrial Arts Men's and Women's Bathroom, M11A, AUD12,					

Asbestos-Containing Building Material	Location	Previous Condition	Present Condition	Change in Condition (Yes/No)	Estimated Damaged Quantity	Comments
	Generator Room, 1 st Floor B-Wing Girls Bathroom					
Tectum ceiling panel	Gym, Auxiliary Gym, Auto Shop, Wood Shop, M13, M14, M12A, Boiler Room					
Chalkboard and tackboard adhesive	M9, M24, M9					
Gray sink undercoat	B16, B18					
Black sink undercoat	G52, M4, M7, M13, M3, MC205, MC209, MC213, MC220, B29, B22, B27/B28 Prep Room, C23, C24					
Black countertop	M25, B29, A21 - A28, B21 - B28					
Door frame caulking	G49, Gym Wing Boys Foyer					
Window frame caulking	Gym, M14-3, M19, M0					
Pipe & pipe fitting insulation	Behind Walls and Fixed Ceilings (Assumed to be present)					

Conditions: D = Damaged; F = Fair; G = Good; IA = Inaccessible; N/A = Not Applicable; SD = Significant Damage; SF = Square Feet

Surveillance conducted by: _____
 (print name) (signature)

I, the LEA's Designated Person, have read and understood the findings noted above: _____

Date: _____

Appendix E

Preventive Measures

Preventive Measures for Various Asbestos-Containing Building Materials

A. Surfacing Materials

“Surfacing Materials” means materials in a school building that are applied by spray, trowel, or otherwise applied to surfaces. These include sprayed-applied fireproofing materials on structural members, ceiling and wall plasters, or other materials applied to surfaces for acoustical, fireproofing, or other purposes.

Surfacing Materials are generally considered friable and can release asbestos fibers if damaged by impact, air erosion, vibration, and/or water intrusion. When properly implemented, the following procedures will reduce the potential for fiber release:

1. Sprayed-Applied Fireproofing

- a) Identify the materials and post warning signs on the laid-in or glued-in ceiling tile. If the decking is not covered, place the sign on the wall.
- b) Maintain the materials in intact state and undamaged condition. During winter, pigeons, squirrels, and other rodents tend to roost in boiler/machine rooms and dislodge sprayed-applied fireproofing on the decking. Prevent such possibilities.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, enclosure is a temporary solution. Encapsulation of damaged sprayed-on fireproofing material is not recommended.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Ceiling and Wall Plasters

- a) Identify the materials and post asbestos warning signs.
- b) Maintain the materials in intact state and undamaged condition. Avoid storing/stacking on/near the materials to reduce contact damage.
- c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, repair or enclosure is a temporary solution.
- d) Train the custodial people who are responsible for care and maintenance of surfacing materials.

B. Thermal System Insulation (TSI)

“Thermal System Insulation (TSI)” means insulating materials applied to pipes, pipe fittings, boilers, breechings, tanks, ducts, or other components to prevent process heat loss or gain, water condensation, or for other purposes (e.g., fire door insulation core).

TSI are generally considered friable ACBM. This means they can be easily damaged, increasing the potential for fiber release. When properly implemented, the following procedures will reduce the potential for fiber release:

1. Boiler and Breeching Insulation

- a) Identify the locations and label the boiler. Warning signs should be posted outside the boiler room.
- b) Reduce the likelihood of fiber release by ensuring that the insulation is not damaged. Avoid storing/stacking on/near the boiler to reduce contact damage.
- c) Maintain the insulation in an intact state and undamaged condition. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Pipe, Pipe Fitting, Tank, Duct & Breeching Insulations

- a) Identify the locations and label the materials. Warning signs should be posted outside of rooms that have TSI materials.
- b) Reduce the likelihood of fiber release by ensuring that the materials are not damaged. Avoid storing/stacking near the materials to reduce contact damage.
- c) Maintain all TSI materials in intact state and undamaged condition. Inspect the protective jackets for damage. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
- d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

C. Miscellaneous Materials

“Miscellaneous Materials” are the other ACBM in a school building that are not categorized as Surfacing Materials or TSI. These include floor tiles, floor tile and carpet mastics, gypsum wallboard and joint compound, ceiling tiles, glue daubs, asbestos cement panels, cove base and associated glue, window/door caulking and glazing compounds, etc. The following maintenance procedures are recommended for these materials:

1. Vinyl Asbestos Floor Tiles (VAT)

Vinyl Asbestos Floor Tiles (VAT) are considered non-friable, however routine maintenance procedures such as spray-buffing, burnishing, wet scrubbing, and stripping can generate asbestos fibers. Following procedures, when properly implemented, will reduce the potential of fiber release:

- a) Do not sand, grind, or abrade the tiles. Stripping of VAT should be done as infrequently as possible. When stripping becomes necessary, follow the appropriate work practices. Never perform dry stripping.
- b) During spray-buffing or burnishing the floor, operate the machine at the lowest workable speed and use the least abrasive pad. Use a wet mop for routine cleaning whenever possible.
- c) Routinely check whether chair and desk glides are in good condition and replace when necessary. Worn glides can gouge the floor and cause fiber release.

- d) Place carpets/floor mats in all entrances to reduce abrasion of floor tiles by sand and pebbles. During winter, have parking lots and walkways swept to the extent possible to avoid the tracking of salt and ice-melting compounds into the school by the students.
- e) Train the custodial people who are responsible for care and maintenance of VAT. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Wallboard and Joint Compound Assembly

- a) Since a number of different homogeneous assemblies may exist in a building, sheetrock/joint compound must be assumed to be ACM unless sample results prove otherwise. If any specific areas are going to be disturbed, samples of the material in that area should be collected and analyzed.
- b) Reduce the likelihood of fiber release by avoiding cutting or drilling holes through the sheetrock panels.

3. Ceiling Tile and Glue Daubs

- a) Reduce the likelihood of fiber release by limiting access to the space above the ceiling tiles. Maintain the ceiling tiles in undamaged condition. Replace any damaged or water-stained tile.
- b) If the ceiling tiles are non-asbestos, collect samples and analyze the glue daubs to identify asbestos-content before disturbing the tiles.

4. Asbestos Cement Panels, Window/Door Caulking and Glazing Compounds

- a) Maintain asbestos cement panels and window/door caulking and glazing compounds in undamaged condition.

5. Carpet Glue, Blackboard/Tack Board Glue, Floor Tile Mastic, Cove Base, and Mastic

- a) Reduce the likelihood of fiber release by leaving materials in place.
- b) Maintain materials in good condition. Collect samples and analyze to identify asbestos-content before disturbing.

Appendix F

Asbestos Inspector and Management Planner State Licenses and EPA Accreditations