

Chart B - Assessment of Asbestos-Containing Building Materials (ACBM)

All asbestos-containing events listed here are to be inspected during each six-month periodic surveillance for changes in condition. The Institute for Environmental assessment (IEA) highly recommends an in-depth "front end" inspection prior to any general renovation or remodeling to determine if those activities may disrupt building materials that may involve existing or undiscovered asbestos. Potentially inaccessible or exempt asbestos-containing materials not included in this plan may include: adhesives, caulking, putty, woven blankets, curtains, gloves and gaskets, electrical wiring insulation and heat shields above lights, paints and coatings, roofing felts, flashings and shingles, and mineral core fire doors.

Damaged materials which require corrective action to reduce a potential hazard are indicated on Chart A. All non-damaged ACBM identified in Chart B should be monitored through scheduled inspections and removed prior to renovation or demolition activities, or when their condition deteriorates.

District administration will direct another formal inspection by a federally-certified inspector within three (3) years, and will maintain an on-going file for each building. Specific recommendations on how to manage the different types of Asbestos-containing material are identified in the Asbestos Management Plan.

PLEASE NOTE: Based on EPA recommendations, materials analyzed utilizing PLM and found to contain between 0% and 10% should be assumed asbestos containing unless building owner wishes the laboratory to utilize "point counting." For samples analyzed prior to 1994 containing 1% or less (trace) of asbestos, resampling utilizing the 1993 EPA Test Method or point counting is strongly recommended for purposes of demolition or renovation before treating these materials as non-asbestos containing. Contact your local IEA office for questions or additional information.

EPA ASSESSMENT CATEGORIES:	1 = Damaged or significantly damaged TSI ACM	5 = ACBM with potential for damage
	2 = Damaged friable surfacing ACM	6 = ACBM with potential for significant damage
	3 = Significantly damaged friable surfacing ACM	7 = Remaining friable ACBM or friable suspect ACBM
	4 = Damaged or significantly damaged friable miscellaneous ACM	

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
10 CAD #:	D2A	Interior Boiler Insulation Interior Refractory	BOILER ROOM 1307	5 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
32 CAD #:	B1A	Air Cell Pipe Insulation 1921 Original Building	1921 ORIGINAL BUILDING GROUND FLOOR BOYS' RESTROOM	4 Lin Ft	Y	50 CH	1
Comments: ABOVE PLASTER CEILING. VISIBLE THROUGH CEILING HATCH. OPEN ENDS. INACCESSIBLE FOR REPAIR/REMOVAL.					Sample #:		
47 CAD #:	K2C	12" x 12" Vinyl Floor Tile & Mastic Beige w/Brown & White Smudges	GROUND FLOOR KITCHEN 1401	220 Sq Ft	N	10 CH (MASTIC ONLY)	5
Comments: INCLUDES PATCHED AREA NEAR SINK. MASTIC ASSUMED PRESENT UNDER PATCH. COMING UP AND CRACKING 5' IN FROM OVEN DOOR AND ALSO 2' IN FRONT OF SINK.					Sample #: 022409-MA-05		
49 CAD #:	V0A	Sink Undercoating White	GROUND FLOOR KITCHEN 1401	6 Sq Ft	N	10 CH	5
Comments: ONE (1) SINK.					Sample #: 022409-MA-20		
50 CAD #:	S0AA	Wood Floor Felt / Vapor Barrier 1921 Original Building (Elevated)	THROUGHOUT 1921 ORIGINAL BUILDING 1ST FLOOR ROOMS	3500 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
55 CAD #:	X0A	Miscellaneous Material Wood Frame Chalkboard Adhesive (1921)	ROOM 2315	15 Sq Ft	N	8 CH	5
Comments:					Sample #: 081511ML-01		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
59 CAD #:	X0A	Miscellaneous Material Wood Frame Chalkboard Adhesive (1921)	ROOM 2316	15 Sq Ft	N	8 CH	5
Comments:					Sample #:		
71 CAD #:	X0A	Miscellaneous Material Wood Frame Chalkboard Adhesive (1921)	ROOM 2304	10 Sq Ft	N	8 CH	5
Comments:					Sample #:		
76 CAD #:	S0AA	Wood Floor Felt / Vapor Barrier 1921 Original Building (Elevated)	THROUGHOUT 1921 ORIGINAL BUILDING 2ND FLOOR ROOMS	3500 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
83 CAD #:	X0A	Miscellaneous Material Wood Frame Chalkboard Adhesive (1921)	ROOM 3304	20 Sq Ft	N	8 CH	5
Comments: BEHIND NEW WHITEBOARDS.					Sample #:		
88 CAD #:	X0A	Miscellaneous Material Wood Frame Chalkboard Adhesive (1921)	ROOM 3305	20 Sq Ft	N	8 CH	5
Comments:					Sample #:		
98 CAD #:	X0A	Miscellaneous Material Wood Frame Chalkboard Adhesive (1921)	ROOM 3315	10 Sq Ft	N	8 CH	5
Comments: BEHIND NEW WHITEBOARDS.					Sample #:		
103 CAD #:	X0A	Miscellaneous Material Wood Frame Chalkboard Adhesive (1921)	ROOM 3316	20 Sq Ft	N	8 CH	5
Comments: BEHIND NEW WHITEBOARDS.					Sample #:		
110 CAD #:	W1C	1' x 1' Ceiling Tile Adhesive Associated w/I1C	1954 ADDITION HALLWAY 1107	95 Sq Ft	N	2 CH	5
Comments:					Sample #:		
125 CAD #:	W1C	1' x 1' Ceiling Tile Adhesive Associated w/I1C	HALLWAY 1208 BETWEEN SMALL KITCHEN 1206 & 1954 ADDITION GYMNASIUM 1122	40 Sq Ft	N	2 CH	5
Comments:					Sample #:		
131 CAD #:	S0B	Wood Floor Felt / Vapor Barrier 1954 Addition	1954 ADDITION STAGE 1202	600 Sq Ft	N	ASSUMED	5
Comments:					Sample #:		
132 CAD #:	A2B	Mudded Pipe Joints on Millboard Insulation 1954 Addition	WEST STAGE FAN ROOM	1 Joints	N	5 CH, 20 AM	5
Comments: ESTIMATED ABOVE PLASTER CEILING.					Sample #: 207D17A		
133 CAD #:	L0A	Flexible Duct Connector Coarse White	WEST STAGE FAN ROOM	4 Sq Ft	N	60 CH	5
Comments:					Sample #:		
134 CAD #:	L0A	Flexible Duct Connector Coarse White	EAST STAGE FAN ROOM	4 Sq Ft	N	60 CH	5
Comments:					Sample #: ACB450VV-H001		
136 CAD #:	W1C	1' x 1' Ceiling Tile Adhesive Associated w/I1C	ENTRY 1199A WEST OF 1954 ADDITION CAFETERIA	50 Sq Ft	N	2 CH	5
Comments:					Sample #:		
137 CAD #:	B2B	Millboard Pipe Insulation 1954 Addition	1954 ADDITION HALLWAY 1100	20 Lin Ft	N	5 CH	5
Comments: IN WALL FEEDING WATER FOUNTAINS. INACCESSIBLE.					Sample #: ACB450VV-H002		
139 CAD #:	W1C	1' x 1' Ceiling Tile Adhesive Associated w/I1C	1954 ADDITION HALLWAY 1100	300 Sq Ft	N	2 CH	5
Comments:					Sample #: 022409-MA-31		

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
145 CAD #:	W1C	1' x 1' Ceiling Tile Adhesive Associated w/IIC	WORK ROOM 1101	75 Sq Ft	N	2 CH	5
Comments: ACROSS FROM GIRLS' RESTROOM.							Sample #: 022409-MA-32
157 CAD #:	B2B	Millboard Pipe Insulation 1954 Addition	ROOM 1109	20 Lin Ft	N	5 CH	5
Comments: IN WALL FEEDING SINK. INACCESSIBLE.							Sample #:
161 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1954)	ROOM 1109	15 Sq Ft	N	3 CH	5
Comments:							Sample #: 042312MV-01
165 CAD #:	B2B	Millboard Pipe Insulation 1954 Addition	ROOM 1108	20 Lin Ft	N	5 CH	5
Comments: IN WALL FEEDING SINK. INACCESSIBLE.							Sample #:
170 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1954)	ROOM 1108	20 Sq Ft	N	3 CH	5
Comments:							Sample #:
172 CAD #:	B2B	Millboard Pipe Insulation 1954 Addition	ROOM 1110	20 Lin Ft	N	5 CH	5
Comments: IN WALL FEEDING SINK. INACCESSIBLE.							Sample #:
180 CAD #:	B2B	Millboard Pipe Insulation 1954 Addition	ROOM 1111	20 Lin Ft	N	5 CH	5
Comments: IN WALL FEEDING SINK. INACCESSIBLE.							Sample #:
184 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1954)	ROOM 1111	10 Sq Ft	N	3 CH	5
Comments: AT EAST WALL. BEHIND NEW WHITEBOARDS.							Sample #:
191 CAD #:	B2B	Millboard Pipe Insulation 1954 Addition	ROOM 1112	20 Lin Ft	N	5 CH	5
Comments: IN WALL FEEDING SINK. INACCESSIBLE.							Sample #:
195 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1954)	ROOM 1112	10 Sq Ft	N	3 CH	5
Comments: AT WEST WALL BEHIND WHITEBOARD.							Sample #:
199 CAD #:	B2B	Millboard Pipe Insulation 1954 Addition	ROOM 1113	20 Lin Ft	N	5 CH	5
Comments: IN WALL FEEDING SINK. INACCESSIBLE.							Sample #:
203 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1954)	ROOM 1113	10 Sq Ft	N	3 CH	5
Comments: AT WEST WALL BEHIND WHITEBOARD.							Sample #:
208 CAD #:	B2B	Millboard Pipe Insulation 1954 Addition	ROOM 1114	20 Lin Ft	N	5 CH	5
Comments: IN WALL FEEDING SINK. INACCESSIBLE.							Sample #:
212 CAD #:	X0C	Miscellaneous Material Wood Frame Chalkboard Adhesive (1954)	ROOM 1114	10 Sq Ft	N	3 CH	5
Comments: AT WEST WALL.							Sample #:
223 CAD #:	B1A	Air Cell Pipe Insulation 1921 Original Building	HALLWAY 1400 SOUTH OF REC CENTER GYMNASIUM	30 Lin Ft	Y	50 CH	1
Comments: ABOVE CEILING. VISIBLE FROM CEILING HATCH. DAMAGE W/DEBRIS. INACCESSIBLE FOR REPAIR/REMOVAL.							Sample #: 207D-10A
224 CAD #:	A1A	Mudded Pipe Joints on Air Cell Insulation 1921 Original Building	HALLWAY 1400 SOUTH OF REC CENTER GYMNASIUM	4 Joints	N	30 CH, 5 AM	5
Comments: ABOVE CEILING. VISIBLE FROM CEILING HATCH OUTSIDE KITCHEN. INACCESSIBLE FOR REMOVAL							Sample #: 207D-11A

IEA Event No.	Material Type	Material Description/Id	Location	Estimated Amount Total	Friability	% of Asbestos	EPA Assess Category
229 CAD #:	K2D	12" x 12" Vinyl Floor Tile & Mastic Light Gray w/Gray Smudges	REC CENTER GYMNASIUM (1402)	4800 Sq Ft	N	2 CH (TILE), 10 CH (MASTIC)	5
Comments: TILES CURLING & CRACKING IN NORTHWEST CORNER W/EXPOSED MASTIC. MISSING TILE PIECES W/EXPOSED MASTIC & CRACKING AROUND MID-COURT.						Sample #: 022409-MA-11	
233 CAD #:	K2E	12" x 12" Vinyl Floor Tile & Mastic Brown W/orange & Dark Brown Smudges	REC CENTER SOUTHEAST ENTRY 1403	120 Sq Ft	N	3 CH (TILE), 10 CH (MASTIC)	5
Comments: INCLUDES REPLACEMENT TILES AT EXTERIOR DOOR.						Sample #:	
234 CAD #:	K2E	12" x 12" Vinyl Floor Tile & Mastic Brown W/orange & Dark Brown Smudges	OFFICE 1406	140 Sq Ft	N	3 CH (TILE), 10 CH (MASTIC)	5
Comments: SOME TILES HAVE BEEN REPLACED.						Sample #: 022409-MA-12	