


**Midwest  
Environmental  
Consulting, L.L.C.**



 Printed on Recycled Paper

**East Consolidated  
Saint Paul Public Schools**

**Lead-Based Paint Inspection**

**Inspection Dates: 3/16/97, 3/17/97, 3/18/97, 3/31/97,  
4/1/97, 4/2/97, 4/3/97**

**submitted to:**

**Saint Paul Public Schools**

**MEC Project # 62/0197T**

## INTRODUCTION

At the request of Saint Paul Public Schools Environmental Safety Department, Midwest Environmental Consulting, L.L.C. (MEC), conducted a lead-based paint inspection at East Consolidated, 409 E. Case Avenue, St. Paul, MN. The purpose of this inspection was to identify lead-based painted, varnished, or otherwise coated building components on the interior and exterior of the school building.

The inspection protocol incorporated applicable portions of the U.S. Department of Housing and Urban Development (HUD) *Guidelines for the Evaluation and Control of Lead-based Paint Hazards in Housing* (HUD Guidelines, June 1995) and OSHA 1926.62 requirements (Lead in Construction). The HUD guidelines are formulated to guide agencies in conducting random sampling of the interiors and exteriors of dwellings and common areas in public housing. The OSHA requirement is designed to minimize worker exposure when working with material containing lead.

Confirmatory testing was conducted when inconclusive XRF results were encountered. Inconclusive refers to XRF readings less than 0.2 mg/cm<sup>2</sup> (milligrams per square centimeter). Inconclusive results were confirmed with laboratory analysis of paint chip samples (Appendix B). This report contains a list of such results.

The United States Environmental Protection Agency defines "lead-based paint" as a paint or other surface coating that contains lead equal to or in excess of 1.0 milligrams per square centimeter when analyzed by XRF or more than 0.5% by weight (5000 parts per million) by laboratory analysis of a bulk sample.

Minnesota Department of Labor and Industry (MN OSHA) adopted the EPA lead levels for the purpose of enforcing OSHA 1926.62 federal regulations. Detection of lead in dried paint film by XRF is a dependable indicator of levels of lead and is accepted by MN OSHA.

For this Saint Paul Public Schools Lead Inspection, all building components were tested on site using a Niton XL® X-ray Fluorescence Spectrum Analyzer<sup>(1)</sup>. Building components included walls, ceilings, floors, moldings, window and door components, door surfaces, and miscellaneous features such as shelves or bookcases. Only painted or glazed surfaces or surfaces which were varnished were tested. Suspended ceilings, structural steel, and corrugated decking were not included in the inspection. Neither anodized (e.g., window sashes) nor plastic (e.g., vinyl baseboard and vinyl mini-blinds) were included in the scope of this inspection.

---

<sup>(1)</sup> This is a portable hand held machine that can analyze building components instantly for lead concentrations.

Each building was divided into unique sites based on the year of construction or renovation. Portable classrooms, playgrounds, and other detached buildings were automatically designated as a unique site. Each site was inspected independently assuming differences in painting history and construction characteristics.

## SITE DESCRIPTION AND BUILDING HISTORY

According to information provided to MEC by Saint Paul Public Schools, East Consolidated was constructed in essentially one phase. This phase is 95,040 square-feet older and dates from 1971.

All room and area designations used in this report are depicted on sampling maps found in Appendix A.

## XRF SAMPLE RESULTS TABLE

The results of all samples analyzed are listed in the table at the end of this section. The following is a description of the column headings:

<b>Site</b>	Each school is divided into sites based on their unique construction characteristics. Each site has a unique date of construction or major renovation.
<b>Sample #</b>	Each sample taken was given a unique number to identify the type and location of the sample. The sampling date is an integral part of the sample number.
<b>Analysis</b>	This defines the type of analysis which can be categorized into two types:  1) XRF: This is an on-site analysis using a hand held Niton XL® X-ray Fluorescence Spectrum Analyzer; 2) Bulk or Chip: This is a bulk sample where paint is removed from the substrate and sent to a laboratory for analysis;
<b>Floor</b>	This is the level of the building in which the area tested was found, example, 1 (first floor), 0 (basement), etc.
<b>Area</b>	This further defines the specific functional space inspected such as a classroom, exterior, playground, gym, kitchen, etc.

<b>Room #</b>	This is typically the actual number on the room as identified at the building.
<b>Component</b>	Building "components" included walls, ceilings, floors, moldings, window and door components, door surfaces, and miscellaneous features such as shelves or bookcases.
<b>Feature</b>	Identifies more detailed information of the component.
<b>Condition</b>	This describes condition of the surface, whether it is intact, cracked, peeling, or chalking.
<b>Substrate</b>	This refers to the material the building component is made of (wood, concrete, drywall, metal, etc.).
<b>Result</b>	This is the analysis results for lead. Less than 1.0 mg/cm <sup>2</sup> or less than 0.5% by weight is considered to be non-lead and these building components are below the action levels of EPA and HUD. (All results are in mg/cm <sup>2</sup> except where noted.)

The table of results is designed for quick information on lead concentrations of tested building components. Generally, all repetitions of a test combination within a given room or area, may be assumed to contain similar concentrations of lead to that of the tested sample. For instance, the lead concentration of a tested wooden window sash was found to be above the action level of 1.0 mg/cm<sup>2</sup> in a given classroom. The classroom has five windows, all of wood, the same color and appearing to be of the same era. It can be assumed that the remaining four wooden window sashes each contain lead above the action limit.

Other columns identify the component and the component feature tested, condition of the component, type of substrate and the result of the analytical test.

As an example, the following illustration shows that the wooden door jamb in Room 123, first floor in the 1923 building section was in good, solid condition, and had an XRF test result of 0.3 mg/cm<sup>2</sup>, which is below the action level.

#### Illustration Only

Site	Sample #	Date	Analysis	Floor	Area	Room #	Component	Feature	Condition	Substrate	Results
1923 Bldg.	52		XRF	1	Room	123	Door	Jamb	Solid	Wood	0.3

In a similar manner, the table shows that the plaster walls in room 23, on the second floor has peeling paint with more than 1.0 mg/cm<sup>2</sup> (shaded).

#### ILLUSTRATION ONLY

Site	Sample #	Date	Analysis	Floor	Area	Room #	Component	Feature	Condition	Substrate	Results
1910 Bldg.	16		XRF	2	Room	23	Door	Jamb	Peeling	Wood	0.25
1910 Bldg.	17		XRF	2	Room	23	Wall	Wall	Peeling	Plaster	1.2
1910 Bldg.	18		XRF	2	Room	23	Ceiling	Peeling	Plaster	0.25	
1910 Bldg.	19		XRF	2	Room	23	Wall	Baseboard	Peeling	Wood	0.002

#### APPLICABLE REGULATIONS

When building components test above 1.0 mg/cm<sup>2</sup> of lead by XRF or 0.5% lead by weight from laboratory analysis all employees and contractors who will be working with these components in a construction related activity must be notified. The requirements of OSHA 1926.62, Lead in Construction are enforceable. This regulation defines construction work as "work for construction, alteration and/or repair, including painting and decorating." This regulation further defines monitoring requirements to minimize employee exposure to lead during construction activities.



When work is performed on external painted building structures (i.e. flashing, fire escapes, playground equipment, handrails, etc.), regulations of the Minnesota Pollution Control Agency (MPCA) may also be applicable. For removal of lead based paint from steel structures, MN Rules 7025.0200 - 7025.0380 apply to steel materials on the exterior of a building, or on the property when levels exceed 0.5 mg/cm<sup>2</sup> based on the average of three XRF spectrum results of the sample tested, or 5,000 ppm by laboratory analysis. If it is other than a steel surface, then MPCA regulates the painted surfaces under MN Rules 7025.010 - 7025.0080, when surfaces are to be disturbed using abrasive blasting methods.

Please contact MEC directly if you have questions about any portion of this report or the lead-based paint inspection itself.

# **APPENDIX A**

## **XRF TESTING DATA WITH LOCATION MAPS**

Drawing 1



Roof Top = Circle Sample #  
Building Exterior Assay #  
4-3-97

SITE ACTS  
SITE DEPS. IN FT.  
PAVING SA FT.  
FLAT SA FT.  
SITE SURVEY LIN FT.  
PUBLIC SURVEY LIN FT.  
FENCE LIN FT.  
WATER LIN FT.  
SITE TREES  
ROCKWORK TREES

NORTH  
EAST  
WEST  
SOUTH




INDEPENDENT SCHOOL DIST. #625  
360 COLBORNE STREET  
ST. PAUL, MINNESOTA 55102

EAST CONSOLIDATED ELEM.  
409 EAST CASE STREET  
ST. PAUL, MN 55101

CONSTRUCTED: 1971

PART  
1  
6

INTERIOR PLANS - EAST LIPPS ELEMENTARY - LOCATIONS




INDEPENDENT SCHOOL DIST. #625  
360 COLBORNE STREET  
ST. PAUL, MINNESOTA 55102

EAST CONSOLIDATED ELEM.  
409 EAST CASE ST.  
ST. PAUL, MN 55101


CONSTRUCTED 1971

2  
6



EAST  
CONSOLIDATED  
Elem.  
4/12/97

D Drawing 10




East Consolidated

313697 = O

41197 = no circle


41297 = " "

DRAWING 8



EAST  
CONSTRUCTED  
from 4/2/97

DRAWING 9




GIRLS Locker Room - 0160  
 BOYS Locker Room - 0070  
 Stairwell to Girls - 0150 - HALL#10  
 " " Boys - 0060 - HALL#11  
 Mechanical - 0140

EAST CONSOLIDATED

4/1/97


Drawing 6

B



GIRLS MECHANICAL

BOYS MECHANICAL




D

B


East Consolidated Elem  
3/30/92 - ○  
4/1/92 - # no circle  
neg. with 222

Drawing 7



B

EAST CONSOLIDATED  
3/3/97 - C  
DRAWING 5




D


C

3/31/97 = C

3/18/97

EAST CONSOLIDATED  
DRAWING 4





**INDEPENDANT SCHOOL DIST. #625**  
**360 COLBORNE STREET**  
**ST. PAUL, MN 55102**


**EAST CONSOLIDATE**  
**409 EAST CASE ST.**  
**ST. PAUL, MN 55101**

CASE CONSOLIDATED ELEM.

3/17/97 - Sampletts circled

3/18/97 - no circle

DRAwing 3



INDEPENDENT SCHOOL DIST. #625  
360 COLBORNE STREET  
ST. PAUL, MINNESOTA 55102


EAST CONSOLIDATED ELEM.  
409 EAST CASE ST.  
ST. PAUL, MN 55101

3/17/97 - Sample #1's circled


Drawing 2

3/16/97

3/17/97 - Sample #'s circled.



N +



Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
1	East Consolidated											
2												
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
4	1971 Bldg.	46	XRF	3/31/97	1	Bath	1211	Wall	Columns	Cracked	Concrete	0
5	1971 Bldg.	47	XRF	3/31/97	1	Bath	1211	Wall	Midle Wall	Solid	Concrete	0
6	1971 Bldg.	48	XRF	3/31/97	1	Bath	1211	Wall	Header	Solid	Wood	0
7	1971 Bldg.	49	XRF	3/31/97	1	Bath	1211	Window	Casing	Solid	Metal	0.34
8	1971 Bldg.	50	XRF	3/31/97	1	Bath	1211		Elec Panel	Solid	Metal	0
9	1971 Bldg.	51	XRF	3/31/97	1	Bath	1211	Wall	Wall	Chalking	Concrete	0.01
10	1971 Bldg.	52	XRF	3/31/97	1	Bath	1213	Wall	Columns	Solid	Concrete	0
11	1971 Bldg.	53	XRF	3/31/97	1	Bath	1213	Wall	Midle Wall	Solid	Concrete	0.01
12	1971 Bldg.	54	XRF	3/31/97	1	Bath	1213	Window	Casing	Solid	Metal	0.29
13	1971 Bldg.	55	XRF	3/31/97	1	Bath	1213		Elec Panel	Solid	Metal	0
14	1971 Bldg.	56	XRF	3/31/97	1	Bath	1213	Door	Door	Solid	Wood	0
15	1971 Bldg.	57	XRF	3/31/97	1	Bath	1213	Door	Casing	Solid	Metal	0.01
16	1971 Bldg.	58	XRF	3/31/97	1	Bath	1213	Ceiling		Solid	Concrete	0
17	1971 Bldg.	307	XRF	4/1/97	1	Bath	1521	Wall	Midle Wall	Solid	Concrete	0
18	1971 Bldg.	308	XRF	4/1/97	1	Bath	1521	Door	Door	Solid	Wood	0
19	1971 Bldg.	309	XRF	4/1/97	1	Bath	1521	Door	Casing	Solid	Metal	0.03
20	1971 Bldg.	246	XRF	4/1/97	1	Bath	1591	Wall	Midle Wall	Solid	Concrete	0
21	1971 Bldg.	247	XRF	4/1/97	1	Bath	1591	Door	Door	Solid	Wood	0
22	1971 Bldg.	248	XRF	4/1/97	1	Bath	1591	Door	Casing	Solid	Metal	0.03
23	1971 Bldg.	249	XRF	4/1/97	1	Bath	1591	Wall	Wall	Solid	Wood	0
24	1971 Bldg.	250	XRF	4/1/97	1	Bath	1591	Ceiling	Beam	Solid	Wood	0.11
25	1971 Bldg.	49	XRF	4/2/97	1	Bath	1711	Ceiling	Beam	Solid	Wood	0.07
26	1971 Bldg.	50	XRF	4/2/97	1	Bath	1711	Ceiling	Beam	Solid	Wood	0
27	1971 Bldg.	51	XRF	4/2/97	1	Bath	1711	Door	Door	Solid	Wood	0
28	1971 Bldg.	52	XRF	4/2/97	1	Bath	1711	Door	Casing	Solid	Metal	0.01
29	1971 Bldg.	53	XRF	4/2/97	1	Bath	1711	Wall	Midle Wall	Solid	Concrete	0.07
30	1971 Bldg.	54	XRF	4/2/97	1	Bath	1711	Wall	Midle Wall	Solid	Concrete	0.04
31	1971 Bldg.	42	XRF	4/2/97	1	Bath	1731	Door	Door	Solid	Wood	0
32	1971 Bldg.	43	XRF	4/2/97	1	Bath	1731	Door	Casing	Solid	Metal	0.02
33	1971 Bldg.	44	XRF	4/2/97	1	Bath	1731	Wall	Midle Wall	Solid	Concrete	0.01
34	1971 Bldg.	45	XRF	4/2/97	1	Bath	1731	Wall	Wall	Solid	Wood	0
35	1971 Bldg.	46	XRF	4/2/97	1	Bath	1731		Elec Panel	Solid	Metal	0.01
36	1971 Bldg.	47	XRF	4/2/97	1	Bath	1731	Window	Casing	Solid	Metal	0
37	1971 Bldg.	48	XRF	4/2/97	1	Bath	1731	Ceiling	Beam	Solid	Wood	0.1
38	1971 Bldg.	38	XRF	4/2/97	1	Bath	1733	Wall	Midle Wall	Solid	Concrete	0
39	1971 Bldg.	39	XRF	4/2/97	1	Bath	1733	Wall	Midle Wall	Solid	Concrete	0
40	1971 Bldg.	40	XRF	4/2/97	1	Bath	1733	Door	Door	Solid	Wood	0
41	1971 Bldg.	41	XRF	4/2/97	1	Bath	1733	Door	Casing	Solid	Metal	0.02
42	1971 Bldg.	86	XRF	4/2/97	1	Bath	1741	Wall	Wall	Solid	Wood	0
43	1971 Bldg.	87	XRF	4/2/97	1	Bath	1741	Wall	Midle Wall	Solid	Concrete	0.07
44	1971 Bldg.	88	XRF	4/2/97	1	Bath	1741	Window	Casing	Solid	Metal	0.33
45	1971 Bldg.	89	XRF	4/2/97	1	Bath	1741	Door	Door	Solid	Wood	0
46	1971 Bldg.	90	XRF	4/2/97	1	Bath	1741	Door	Casing	Solid	Metal	0.02
47	1971 Bldg.	91	XRF	4/2/97	1	Bath	1741	Door	Stall Door	Solid	Metal	0.01
48	1971 Bldg.	92	XRF	4/2/97	1	Bath	1742	Wall	Wall	Solid	Wood	0
49	1971 Bldg.	93	XRF	4/2/97	1	Bath	1742	Wall	Midle Wall	Solid	Concrete	0
50	1971 Bldg.	94	XRF	4/2/97	1	Bath	1742	Wall	Midle Wall	Solid	Concrete	0.08
51	1971 Bldg.	95	XRF	4/2/97	1	Bath	1742	Window	Casing	Solid	Metal	0.5
52	1971 Bldg.	96	XRF	4/2/97	1	Bath	1742	Door	Door	Solid	Wood	0
53	1971 Bldg.	97	XRF	4/2/97	1	Bath	1742	Door	Casing	Solid	Metal	0.01
54	1971 Bldg.	98	XRF	4/2/97	1	Bath	1742	Door	Stall Door	Solid	Metal	0.04
55	1971 Bldg.	190	XRF	4/2/97	1	Bath	1750	Wall	Wall	Solid	Wood	0
56	1971 Bldg.	191	XRF	4/2/97	1	Bath	1750	Wall	Wall	Solid	Concrete	0.05

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
57	1971 Bldg.	192	XRF	4/2/97	1	Bath	1750	Window	Casing	Solid	Metal	0.66
58	1971 Bldg.	193	XRF	4/2/97	1	Bath	1750	Door	Door	Solid	Wood	0
59	1971 Bldg.	194	XRF	4/2/97	1	Bath	1750	Door	Casing	Solid	Metal	0.01
60	1971 Bldg.	195	XRF	4/2/97	1	Bath	1750	Door	Stall Door	Solid	Metal	0.01
61	1971 Bldg.	186	XRF	4/2/97	1	Bath	1752	Wall	Midle Wall	Solid	Concrte	0
62	1971 Bldg.	187	XRF	4/2/97	1	Bath	1752	Wall	Wall	Solid	Wood	0
63	1971 Bldg.	188	XRF	4/2/97	1	Bath	1752	Window	Casing	Solid	Metal	0.54
64	1971 Bldg.	189	XRF	4/2/97	1	Bath	1752	Door	Stall Door	Solid	Metal	0.01
65	1971 Bldg.	59	XRF	3/31/97	1	Bath	1781	Wall	Columns	Solid	Concrte	0
66	1971 Bldg.	60	XRF	3/31/97	1	Bath	1781	Wall	Wall	Solid	Concrte	0.07
67	1971 Bldg.	61	XRF	3/31/97	1	Bath	1781	Window	Casing	Solid	Metal	0.66
68	1971 Bldg.	62	XRF	3/31/97	1	Bath	1781	Wall	Wall	Solid	Wood	0.02
69	1971 Bldg.	63	XRF	3/31/97	1	Bath	1781		Elec Panel	Solid	Metal	0
70	1971 Bldg.	64	XRF	3/31/97	1	Bath	1782	Wall	Columns	Solid	Concrte	0
71	1971 Bldg.	65	XRF	3/31/97	1	Bath	1782	Wall	Midle Wall	Solid	Concrte	0.01
72	1971 Bldg.	66	XRF	3/31/97	1	Bath	1782	Window	Casing	Solid	Metal	0.44
73	1971 Bldg.	67	XRF	3/31/97	1	Bath	1782	Wall	Wall	Solid	Wood	0
74	1971 Bldg.	68	XRF	3/31/97	1	Bath	1782		Elec Panel	Solid	Metal	0
75	1971 Bldg.	138	XRF	3/31/97	1	Bath	1792	Wall	Columns	Solid	Concrte	0
76	1971 Bldg.	139	XRF	3/31/97	1	Bath	1792	Wall	Midle Wall	Solid	Concrte	0
77	1971 Bldg.	140	XRF	3/31/97	1	Bath	1792	Window	Casing	Solid	Metal	0.42
78	1971 Bldg.	141	XRF	3/31/97	1	Bath	1792		Elec Panel	Solid	Metal	0
79	1971 Bldg.	142	XRF	3/31/97	1	Bath	1792	Door	Door	Solid	Wood	0
80	1971 Bldg.	143	XRF	3/31/97	1	Bath	1792	Door	Casing	Solid	Metal	0.02
81	1971 Bldg.	133	XRF	3/31/97	1	Bath	1794	Wall	Columns	Solid	Concrte	0
82	1971 Bldg.	134	XRF	3/31/97	1	Bath	1794	Wall	Midle Wall	Solid	Concrte	0.02
83	1971 Bldg.	135	XRF	3/31/97	1	Bath	1794	Window	Casing	Solid	Metal	0.35
84	1971 Bldg.	136	XRF	3/31/97	1	Bath	1794	Wall	Wall	Solid	Wood	0
85	1971 Bldg.	137	XRF	3/31/97	1	Bath	1794		Elec Panel	Solid	Metal	0
86	1971 Bldg.	36	XRF	3/31/97	1	Bath	1801	Wall	Chair rail	Solid	Concrte	0.01
87	1971 Bldg.	37	XRF	3/31/97	1	Bath	1801	Window	Casing	Solid	Metal	0.3
88	1971 Bldg.	38	XRF	3/31/97	1	Bath	1801	Wall	Header	Solid	Wood	0
89	1971 Bldg.	39	XRF	3/31/97	1	Bath	1801		Elec Panel	Solid	Metal	0.02
90	1971 Bldg.	40	XRF	3/31/97	1	Bath	1801	Wall	Columns	Solid	Concrte	0.02
91	1971 Bldg.	41	XRF	3/31/97	1	Bath	1802	Wall	Columns	Solid	Concrte	0
92	1971 Bldg.	42	XRF	3/31/97	1	Bath	1802	Wall	Wall	Solid	Concrte	0
93	1971 Bldg.	43	XRF	3/31/97	1	Bath	1802	Window	Casing	Solid	Metal	0.48
94	1971 Bldg.	44	XRF	3/31/97	1	Bath	1802	Door	Stall Door	Solid	Metal	0
95	1971 Bldg.	45	XRF	3/31/97	1	Bath	1802	Wall	Header	Solid	Wood	0.03
96	1971 Bldg.	40	XRF	3/16/97	1	Cafeteria	0	Wall	Midle Wall	Solid	Concrte	0
97	1971 Bldg.	41	XRF	3/16/97	1	Cafeteria	0	Wall	Midle Wall	Solid	Concrte	0
98	1971 Bldg.	42	XRF	3/16/97	1	Cafeteria	0	Wall	Wall	Solid	Concrte	0.01
99	1971 Bldg.	43	XRF	3/16/97	1	Cafeteria	0	Wall	Column	Solid	Concrte	0.01
100	1971 Bldg.	44	XRF	3/16/97	1	Cafeteria	0	Wall	Column	Solid	Concrte	0.04
101	1971 Bldg.	45	XRF	3/16/97	1	Cafeteria	0	Stairs	Hand rail	Solid	Wood	0.03
102	1971 Bldg.	46	XRF	3/16/97	1	Cafeteria	0	Stairs	Hand rail	Solid	Wood	0
103	1971 Bldg.	47	XRF	3/16/97	1	Cafeteria	0	Stairs	Newal pos	Solid	Wood	0.05
104	1971 Bldg.	48	XRF	3/16/97	1	Cafeteria	0	Stairs	Baseboar	Solid	Concrte	0.07
105	1971 Bldg.	49	XRF	3/16/97	1	Cafeteria	0	Ceiling	Beam Bra	Solid	Metal	0
106	1971 Bldg.	50	XRF	3/16/97	1	Cafeteria	0	Ceiling	Beam	Solid	Wood	0.03
107	1971 Bldg.	51	XRF	3/16/97	1	Cafeteria	0		Radiator	Solid	Metal	0.03
108	1971 Bldg.	52	XRF	3/16/97	1	Cafeteria	0	Floor	Flr Registr	Solid	Metal	0
109	1971 Bldg.	81	XRF	3/18/97	1	Classroom	1180	Door	Panel	Solid	Wood	0
110	1971 Bldg.	82	XRF	3/18/97	1	Classroom	1180	Ceiling	Beam Bra	Peeling	Metal	0
111	1971 Bldg.	83	XRF	3/18/97	1	Classroom	1180	Ceiling	Beam	Solid	Wood	0

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

3	A	B	C	D	E	F	G	H	I	J	K	L
	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
112	1971 Bldg.	84	XRF	3/18/97	1	Classroom	1180	Wall	Midle Wall	Solid	Drywall	0
113	1971 Bldg.	85	XRF	3/18/97	1	Classroom	1180	Door	Door	Solid	Wood	0
114	1971 Bldg.	86	XRF	3/18/97	1	Classroom	1180	Door	Casing	Solid	Metal	0
115	1971 Bldg.	87	XRF	3/18/97	1	Classroom	1180	Wall	Column	Solid	Concrete	0
116	1971 Bldg.	88	XRF	3/18/97	1	Classroom	1180	Wall	Column	Solid	Wood	0
117	1971 Bldg.	89	XRF	3/18/97	1	Classroom	1180	Wall	Wall	Solid	Concrte	0
118	1971 Bldg.	90	XRF	3/18/97	1	Classroom	1180	Wall	Column	Solid	Metal	0
119	1971 Bldg.	91	XRF	3/18/97	1	Classroom	1180		Radiator	Solid	Metal	0
120	1971 Bldg.	92	XRF	3/18/97	1	Classroom	1180	Wall	Mural	Solid	Concrte	0
121	1971 Bldg.	93	XRF	3/18/97	1	Classroom	1180	Wall	Mural	Solid	Concrte	0
122	1971 Bldg.	36	XRF	3/18/97	1	Classroom	1190	Wall	Panel	Solid	Wood	0
123	1971 Bldg.	37	XRF	3/18/97	1	Classroom	1190	Wall	Panel	Solid	Wood	0.05
124	1971 Bldg.	38	XRF	3/18/97	1	Classroom	1190	Wall	Midle Wall	Solid	Drywall	0.01
125	1971 Bldg.	39	XRF	3/18/97	1	Classroom	1190	Coat Rack		Solid	Wood	0
126	1971 Bldg.	40	XRF	3/18/97	1	Classroom	1190	Wall	Midle Wall	Solid	Drywall	0
127	1971 Bldg.	41	XRF	3/18/97	1	Classroom	1190	Door	Door	Solid	Wood	0
128	1971 Bldg.	42	XRF	3/18/97	1	Classroom	1190	Door	Casing	Solid	Metal	0.01
129	1971 Bldg.	43	XRF	3/18/97	1	Classroom	1190	Wall	Midle Wall	Solid	Concrte	0
130	1971 Bldg.	44	XRF	3/18/97	1	Classroom	1192	Wall	Midle Wall	Solid	Concrete	0.03
131	1971 Bldg.	45	XRF	3/18/97	1	Classroom	1192	Coat Rack		Solid	Wood	0
132	1971 Bldg.	46	XRF	3/18/97	1	Classroom	1192	Wall	Wall	Solid	Drywall	0
133	1971 Bldg.	47	XRF	3/18/97	1	Classroom	1192	Door	Door	Solid	Wood	0
134	1971 Bldg.	48	XRF	3/18/97	1	Classroom	1192	Door	Casing	Solid	Wood	0
135	1971 Bldg.	49	XRF	3/18/97	1	Classroom	1192	Door	Jamb	Solid	Wood	0
136	1971 Bldg.	50	XRF	3/18/97	1	Classroom	1192	Bookcase	Inside	Solid	Wood	0
137	1971 Bldg.	51	XRF	3/18/97	1	Classroom	1192	Bookcase	Inside	Solid	Wood	0.32
138	1971 Bldg.	52	XRF	3/18/97	1	Classroom	1192	Wall	Panel	Solid	Wood	0.05
139	1971 Bldg.	53	XRF	3/18/97	1	Classroom	1192	Wall	Panel	Solid	Wood	0
140	1971 Bldg.	29	XRF	3/18/97	1	Classroom	1193	Wall	Midle Wall	Solid	Concrte	0.01
141	1971 Bldg.	30	XRF	3/18/97	1	Classroom	1193	Wall	Midle Wall	Solid	Drywall	0
142	1971 Bldg.	31	XRF	3/18/97	1	Classroom	1193	Door	Door	Solid	Wood	0
143	1971 Bldg.	32	XRF	3/18/97	1	Classroom	1193	Door	Casing	Solid	Metal	0.02
144	1971 Bldg.	33	XRF	3/18/97	1	Classroom	1193	Ceiling	Beam	Solid	Wood	0.08
145	1971 Bldg.	34	XRF	3/18/97	1	Classroom	1193	Ceiling	Beam Bra	Solid	Metal	0
146	1971 Bldg.	35	XRF	3/18/97	1	Classroom	1193	Wall	Midle Wall	Solid	Drywall	0
147	1971 Bldg.	78	XRF	3/18/97	1	Classroom	1210	Ceiling	Beam Bra	Solid	Metal	0.07
148	1971 Bldg.	79	XRF	3/18/97	1	Classroom	1210	Door	Door	Solid	Wood	0
149	1971 Bldg.	80	XRF	3/18/97	1	Classroom	1210	Door	Casing	Solid	Metal	0.02
150	1971 Bldg.	104	XRF	3/16/97	1	Classroom	1220	Wall	Mural	Solid	Concrte	0.02
151	1971 Bldg.	105	XRF	3/16/97	1	Classroom	1220	Door	Door	Solid	Wood	0
152	1971 Bldg.	106	XRF	3/16/97	1	Classroom	1220	Wall	Wall	Solid	Drywall	0
153	1971 Bldg.	107	XRF	3/16/97	1	Classroom	1220	Door	Jamb	Solid	Metal	0.04
154	1971 Bldg.	108	XRF	3/16/97	1	Classroom	1220	Ceiling	Beam Bra	Solid	Metal	0.05
155	1971 Bldg.	109	XRF	3/16/97	1	Classroom	1220	Ceiling	Beam	Solid	Wood	0.07
156	1971 Bldg.	110	XRF	3/16/97	1	Classroom	1220	Ceiling	Beam	Solid	Wood	0.07
157	1971 Bldg.	111	XRF	3/16/97	1	Classroom	1220	Ceiling	Beam Bra	Solid	Metal	0.01
158	1971 Bldg.	112	XRF	3/16/97	1	Classroom	1220	Window	Casing	Solid	Metal	0.02
159	1971 Bldg.	113	XRF	3/16/97	1	Classroom	1220	Wall	Wall	Solid	Drywall	0.04
160	1971 Bldg.	114	XRF	3/16/97	1	Classroom	1220	Wall	Column	Solid	Metal	0.03
161	1971 Bldg.	92	XRF	3/16/97	1	Classroom	1230	Wall	Midle Wall	Solid	Drywall	0
162	1971 Bldg.	93	XRF	3/16/97	1	Classroom	1230	Window	Sash	Solid	Metal	0.01
163	1971 Bldg.	94	XRF	3/16/97	1	Classroom	1230		Radiator	Solid	Metal	0.03
164	1971 Bldg.	95	XRF	3/16/97	1	Classroom	1230		Radiator	Solid	Metal	0.01
165	1971 Bldg.	96	XRF	3/16/97	1	Classroom	1230	Wall	Wall	Solid	Concrte	0
166	1971 Bldg.	97	XRF	3/16/97	1	Classroom	1230	Ceiling	Beam Bra	Solid	Metal	0.03

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

3	A	B	C	D	E	F	G	H	I	J	K	L
	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
167	1971 Bldg.	98	XRF	3/16/97	1	Classroom	1230	Ceiling	Beam	Solid	Wood	0.11
168	1971 Bldg.	99	XRF	3/16/97	1	Classroom	1230	Wall	Column	Solid	Metal	0.05
169	1971 Bldg.	100	XRF	3/16/97	1	Classroom	1230	Wall	Column	Solid	Wood	0.01
170	1971 Bldg.	101	XRF	3/16/97	1	Classroom	1230	Wall	Wall	Solid	Drywall	0.05
171	1971 Bldg.	102	XRF	3/16/97	1	Classroom	1230	Door	Jamb	Solid	Metal	0.01
172	1971 Bldg.	103	XRF	3/16/97	1	Classroom	1230	Door	Door	Solid	Wood	0
173	1971 Bldg.	53	XRF	3/16/97	1	Classroom	1240	Wall	Wall	Solid	Concrte	0.07
174	1971 Bldg.	54	XRF	3/16/97	1	Classroom	1240	Wall	Midle Wall	Solid	Concrte	0
175	1971 Bldg.	55	XRF	3/16/97	1	Classroom	1240	Ceiling	Beam Bra	Solid	Metal	0.03
176	1971 Bldg.	56	XRF	3/16/97	1	Classroom	1240	Ceiling	Beam	Solid	Wood	0
177	1971 Bldg.	57	XRF	3/16/97	1	Classroom	1240	Window	Stool	Solid	Metal	0
178	1971 Bldg.	58	XRF	3/16/97	1	Classroom	1240	Window	Stool	Solid	Metal	0
179	1971 Bldg.	59	XRF	3/16/97	1	Classroom	1240	Window	Stool	Solid	Metal	0
180	1971 Bldg.	60	XRF	3/16/97	1	Classroom	1240	Stool	Seat	Solid	Wood	0.03
181	1971 Bldg.	61	XRF	3/16/97	1	Classroom	1240	Stool	Leg	Solid	Metal	0.03
182	1971 Bldg.	62	XRF	3/16/97	1	Classroom	1240	Wall	Midle Wall	Solid	Concrte	0
183	1971 Bldg.	63	XRF	3/16/97	1	Classroom	1240	Bookcase	Inside	Peeling	Wood	0.76
184	1971 Bldg.	64	XRF	3/16/97	1	Classroom	1240		Radiator	Solid	Metal	0.03
185	1971 Bldg.	65	XRF	3/16/97	1	Classroom	1240	Door	Door	Solid	Metal	0
186	1971 Bldg.	66	XRF	3/16/97	1	Classroom	1240	Door	Jamb	Solid	Metal	0
187	1971 Bldg.	67	XRF	3/16/97	1	Classroom	1240	Wall	Column	Solid	Metal	0.01
188	1971 Bldg.	68	XRF	3/16/97	1	Classroom	1240	Wall	Column	Solid	Wood	1.27
189	1971 Bldg.	69	XRF	3/16/97	1	Classroom	1240	Wall	Wall	Solid	Wood	0
190	1971 Bldg.	70	XRF	3/16/97	1	Classroom	1240	Wall	Midle Wall	Solid	Drywall	0.02
191	1971 Bldg.	71	XRF	3/16/97	1	Classroom	1240	Cabinet	Door	Solid	Wood	0
192	1971 Bldg.	72	XRF	3/16/97	1	Classroom	1240	Door	Header	Solid	Wood	0
193	1971 Bldg.	73	XRF	3/16/97	1	Classroom	1240	Door	Door	Solid	Wood	0
194	1971 Bldg.	74	XRF	3/16/97	1	Classroom	1240	Door	Jamb	Solid	Metal	0
195	1971 Bldg.	115	XRF	3/16/97	1	Classroom	1264	Wall	Midle Wall	Solid	Concrte	0
196	1971 Bldg.	116	XRF	3/16/97	1	Classroom	1264	Ceiling	Beam Bra	Solid	Metal	0.06
197	1971 Bldg.	117	XRF	3/16/97	1	Classroom	1264	Ceiling	Beam	Solid	Wood	0.04
198	1971 Bldg.	118	XRF	3/16/97	1	Classroom	1264	Wall	Column	Solid	Metal	0.05
199	1971 Bldg.	119	XRF	3/16/97	1	Classroom	1264	Door	Door	Solid	Metal	0
200	1971 Bldg.	120	XRF	3/16/97	1	Classroom	1264	Door	Jamb	Solid	Metal	0
201	1971 Bldg.	121	XRF	3/16/97	1	Classroom	1264		Radiator	Solid	Metal	0
202	1971 Bldg.	122	XRF	3/16/97	1	Classroom	1264	Window	Casing	Solid	Metal	0
203	1971 Bldg.	123	XRF	3/16/97	1	Classroom	1264	Door	Door	Solid	Wood	0
204	1971 Bldg.	124	XRF	3/16/97	1	Classroom	1264	Door	Casing	Solid	Metal	0.04
205	1971 Bldg.	125	XRF	3/16/97	1	Classroom	1264	Wall	Wall	Solid	Drywall	0
206	1971 Bldg.	97	XRF	3/17/97	1	Classroom	1275	Wall	Midle Wall	Solid	Concrte	0
207	1971 Bldg.	98	XRF	3/17/97	1	Classroom	1275	Window	Casing	Solid	Metal	0
208	1971 Bldg.	99	XRF	3/17/97	1	Classroom	1275		Radiator	Solid	Metal	0.01
209	1971 Bldg.	100	XRF	3/17/97	1	Classroom	1275	Wall	Midle Wall	Solid	Drywall	0.01
210	1971 Bldg.	102	XRF	3/17/97	1	Classroom	1275	Ceiling	Beam	Solid	Wood	0
211	1971 Bldg.	103	XRF	3/17/97	1	Classroom	1275	Ceiling	Beam Bra	Solid	Metal	0.03
212	1971 Bldg.	104	XRF	3/17/97	1	Classroom	1275	Ceiling	Beam	Solid	Wood	0.05
213	1971 Bldg.	105	XRF	3/17/97	1	Classroom	1275	Door	Door	Solid	Wood	0
214	1971 Bldg.	106	XRF	3/17/97	1	Classroom	1275	Door	Casing	Solid	Metal	0.04
215	1971 Bldg.	107	XRF	3/17/97	1	Classroom	1275	Wall	Mural	Solid	Drywall	0
216	1971 Bldg.	108	XRF	3/17/97	1	Classroom	1275	Wall	Midle Wall	Solid	Drywall	0
217	1971 Bldg.	109	XRF	3/17/97	1	Classroom	1275	Wall	Column	Solid	Metal	0.04
218	1971 Bldg.	110	XRF	3/17/97	1	Classroom	1275	Door	Door	Solid	Metal	0
219	1971 Bldg.	111	XRF	3/17/97	1	Classroom	1275	Door	Casing	Solid	Metal	0
220	1971 Bldg.	112	XRF	3/17/97	1	Classroom	1275	Window	Casing	Solid	Metal	0
221	1971 Bldg.	113	XRF	3/17/97	1	Classroom	1275	Window	Casing	Solid	Metal	0

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L	
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result	
222	1971 Bldg.	114	XRF	3/17/97	1	Classroom	1275	Ceiling	Beam	Solid	Wood	0	
223	1971 Bldg.	115	XRF	3/17/97	1	Classroom	1275	Ceiling	Beam Bra	Solid	Metal	0.05	
224	1971 Bldg.	116	XRF	3/17/97	1	Classroom	1275		Radiator	Solid	Metal	0	
225	1971 Bldg.	117	XRF	3/17/97	1	Classroom	1275	Wall	Midle Wall	Solid	Concrte	0.01	
226	1971 Bldg.	118	XRF	3/17/97	1	Classroom	1275	Door	Door	Solid	Wood	0	
227	1971 Bldg.	119	XRF	3/17/97	1	Classroom	1275	Door	Casing	Solid	Metal	0.02	
228	1971 Bldg.	120	XRF	3/17/97	1	Classroom	1275	Door	Header	Solid	Wood	0.08	
229	1971 Bldg.	128	XRF	3/17/97	1	Classroom	1280	Ceiling	Beam	Solid	Wood	0.05	
230	1971 Bldg.	129	XRF	3/17/97	1	Classroom	1280	Ceiling	Beam	Solid	Wood	0	
231	1971 Bldg.	130	XRF	3/17/97	1	Classroom	1280	Ceiling	Beam Bra	Solid	Metal	0.05	
232	1971 Bldg.	131	XRF	3/17/97	1	Classroom	1280	Wall	Midle Wall	Solid	Drywall	0.03	
233	1971 Bldg.	132	XRF	3/17/97	1	Classroom	1280	Wall	Midle Wall	Solid	Drywall	0	
234	1971 Bldg.	133	XRF	3/17/97	1	Classroom	1280	Cabinet	Floor	Solid	Wood	0	
235	1971 Bldg.	134	XRF	3/17/97	1	Classroom	1280	Cabinet	Door	Solid	Wood	0	
236	1971 Bldg.	135	XRF	3/17/97	1	Classroom	1280	Wall	Wall	Solid	Concrte	0.05	
237	1971 Bldg.	136	XRF	3/17/97	1	Classroom	1280		Radiator	Solid	Metal	0	
238	1971 Bldg.	137	XRF	3/17/97	1	Classroom	1280	Door	Door	Solid	Wood	0	
239	1971 Bldg.	138	XRF	3/17/97	1	Classroom	1280	Door	Casing	Solid	Metal	0	
240	1971 Bldg.	173	XRF	3/17/97	1	Classroom	1285	Door	Panel	Solid	Wood	0.07	
241	1971 Bldg.	174	XRF	3/17/97	1	Classroom	1285	Wall	Midle Wall	Solid	Concrte	0	
242	1971 Bldg.	175	XRF	3/17/97	1	Classroom	1285	Wall	Column	Solid	Metal	0.05	
243	1971 Bldg.	176	XRF	3/17/97	1	Classroom	1285	Column		Solid	Wood	0	
244	1971 Bldg.	177	XRF	3/17/97	1	Classroom	1285	Column	Bracket	Solid	Metal	0.03	
245	1971 Bldg.	178	XRF	3/17/97	1	Classroom	1285	Window	Casing	Solid	Metal	0	
246	1971 Bldg.	179	XRF	3/17/97	1	Classroom	1285		Radiator	Solid	Metal	0.01	
247	1971 Bldg.	180	XRF	3/17/97	1	Classroom	1285	Wall	Midle Wall	Solid	Drywall	0.02	
248	1971 Bldg.	181	XRF	3/17/97	1	Classroom	1285	Unlisted	Chair rail	Solid	Wood	0	
249	1971 Bldg.	182	XRF	3/17/97	1	Classroom	1285	Door	Door	Solid	Wood	0	
250	1971 Bldg.	183	XRF	3/17/97	1	Classroom	1285	Door	Casing	Solid	Metal	0.28	
251	1971 Bldg.	163	XRF	3/17/97	1	Classroom	1286	Wall	Midle Wall	Solid	Concrte	0	
252	1971 Bldg.	164	XRF	3/17/97	1	Classroom	1286	Ceiling	Beam	Solid	Wood	0	
253	1971 Bldg.	165	XRF	3/17/97	1	Classroom	1286	Ceiling	Beam Bra	Solid	Metal	0.05	
254	1971 Bldg.	166	XRF	3/17/97	1	Classroom	1286	Window	Casing	Solid	Metal	0	
255	1971 Bldg.	167	XRF	3/17/97	1	Classroom	1286	Wall	Column	Solid	Metal	0.03	
256	1971 Bldg.	168	XRF	3/17/97	1	Classroom	1286		Radiator	Solid	Metal	0.02	
257	1971 Bldg.	169	XRF	3/17/97	1	Classroom	1286	Wall	Midle Wall	Solid	Drywall	0.06	
258	1971 Bldg.	170	XRF	3/17/97	1	Classroom	1286	Door	Door	Solid	Wood	0	
259	1971 Bldg.	171	XRF	3/17/97	1	Classroom	1286	Door	Casing	Solid	Metal	0.01	
260	1971 Bldg.	172	XRF	3/17/97	1	Classroom	1286	Door	Panel	Solid	Wood	0.06	
261	1971 Bldg.	150	XRF	3/17/97	1	Classroom	1287	Ceiling	Beam Bra	Solid	Metal	0.06	
262	1971 Bldg.	151	XRF	3/17/97	1	Classroom	1287	Wall	Midle Wall	Solid	Drywall	0.01	
263	1971 Bldg.	152	XRF	3/17/97	1	Classroom	1287	Wall	Column	Solid	Metal	0.02	
264	1971 Bldg.	153	XRF	3/17/97	1	Classroom	1287	Door	Door	Solid	Metal	0.01	
265	1971 Bldg.	154	XRF	3/17/97	1	Classroom	1287	Door	Casing	Solid	Metal	0	
266	1971 Bldg.	155	XRF	3/17/97	1	Classroom	1287	Coat Rack		Solid	Wood	0	
267	1971 Bldg.	156	XRF	3/17/97	1	Classroom	1287	Door	Door	Solid	Wood	0	
268	1971 Bldg.	157	XRF	3/17/97	1	Classroom	1287	Door	Casing	Solid	Metal	0.03	
269	1971 Bldg.	158	XRF	3/17/97	1	Classroom	1287	Wall	Wall	Solid	Wood	0	
270	1971 Bldg.	159	XRF	3/17/97	1	Classroom	1287	Wall	Midle Wall	Solid	Metal	0.05	
271	1971 Bldg.	160	XRF	3/17/97	1	Classroom	1287	Wall	Midle Wall	Solid	Concrte	0.01	
272	1971 Bldg.	161	XRF	3/17/97	1	Classroom	1287	Window	Casing	Solid	Metal	0	
273	1971 Bldg.	162	XRF	3/17/97	1	Classroom	1287		Radiator	Solid	Metal	0.01	
274	1971 Bldg.	28	XRF	3/17/97	1	Hall		1	Door	Door	Solid	Wood	0
275	1971 Bldg.	29	XRF	3/17/97	1	Hall		1	Door	Casing	Solid	Metal	0.06
276	1971 Bldg.	30	XRF	3/17/97	1	Hall		1	Wall	Wall	Solid	Drywall	0

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
277	1971 Bldg.	31	XRF	3/17/97	1	Hall	1	Coat Rack		Solid	Wood	0
278	1971 Bldg.	32	XRF	3/17/97	1	Hall	1		Column	Solid	Metal	0.03
279	1971 Bldg.	33	XRF	3/17/97	1	Hall	1	Wall	Midle Wall	Solid	Concrete	0.01
280	1971 Bldg.	34	XRF	3/17/97	1	Hall	1	Wall	Wall	Solid	Drywall	0.03
281	1971 Bldg.	35	XRF	3/17/97	1	Hall	1	Wall	Midle Wall	Solid	Concrete	0.01
282	1971 Bldg.	36	XRF	3/17/97	1	Hall	1		Radiator	Solid	Metal	0.08
283	1971 Bldg.	37	XRF	3/17/97	1	Hall	1	Ceiling	Beam Bra	Solid	Metal	0.01
284	1971 Bldg.	38	XRF	3/17/97	1	Hall	1	Ceiling	Beam	Solid	Wood	0.05
285	1971 Bldg.	39	XRF	3/17/97	1	Hall	1	Wall	Header	Solid	Wood	0
286	1971 Bldg.	40	XRF	3/17/97	1	Hall	1		Header	Solid	Wood	0
287	1971 Bldg.	41	XRF	3/17/97	1	Hall	1	Wall	Column	Solid	Concrete	0
288	1971 Bldg.	57	XRF	3/17/97	1	Hall	2	Wall	Header	Solid	Wood	0.01
289	1971 Bldg.	58	XRF	3/17/97	1	Hall	2	Wall	Header	Solid	Wood	0
290	1971 Bldg.	59	XRF	3/17/97	1	Hall	2	Wall	Radiator	Solid	Metal	0.02
291	1971 Bldg.	60	XRF	3/17/97	1	Hall	2	Door	Header	Solid	Wood	0
292	1971 Bldg.	61	XRF	3/17/97	1	Hall	2	Door	Door	Solid	Wood	0
293	1971 Bldg.	62	XRF	3/17/97	1	Hall	2	Door	Jamb	Solid	Metal	0.02
294	1971 Bldg.	63	XRF	3/17/97	1	Hall	2	Wall	Wall	Solid	Concrete	0.03
295	1971 Bldg.	64	XRF	3/17/97	1	Hall	2	Wall	Column	Solid	Concrete	0.01
296	1971 Bldg.	65	XRF	3/17/97	1	Hall	2	Wall	Mural	Solid	Concrete	2.38
297	1971 Bldg.	66	XRF	3/17/97	1	Hall	2	Stairs	Hand rail	Solid	Wood	0
298	1971 Bldg.	67	XRF	3/17/97	1	Hall	2	Wall	Wall	Solid	Concrete	0.02
299	1971 Bldg.	68	XRF	3/17/97	1	Hall	2	Wall	Mural	Solid	Concrete	2.95
300	1971 Bldg.	69	XRF	3/17/97	1	Hall	2	Door	Casing	Solid	Metal	0.37
301	1971 Bldg.	70	XRF	3/17/97	1	Hall	2	Door	Door	Solid	Wood	0
302	1971 Bldg.	71	XRF	3/17/97	1	Hall	2	Door	Jamb	Solid	Metal	0.38
303	1971 Bldg.	6	XRF	3/18/97	1	Hall	3	Wall	Wall	Solid	Concrete	0
304	1971 Bldg.	7	XRF	3/18/97	1	Hall	3	Stairs	Hand rail	Solid	Wood	0
305	1971 Bldg.	8	XRF	3/18/97	1	Hall	3	Stairs	Newal pos	Solid	Metal	0.06
306	1971 Bldg.	9	XRF	3/18/97	1	Hall	3	Wall	Column	Solid	Concrete	0
307	1971 Bldg.	10	XRF	3/18/97	1	Hall	3	Door	Door	Solid	Wood	0
308	1971 Bldg.	11	XRF	3/18/97	1	Hall	3	Door	Casing	Solid	Metal	0
309	1971 Bldg.	12	XRF	3/18/97	1	Hall	3	Wall	Midle Wall	Solid	Drywall	0
310	1971 Bldg.	13	XRF	3/18/97	1	Hall	3	Wall	Wall	Solid	Wood	0
311	1971 Bldg.	14	XRF	3/18/97	1	Hall	3	Wall	Panel	Solid	Metal	0.03
312	1971 Bldg.	15	XRF	3/18/97	1	Hall	3	Window	Casing	Solid	Metal	0.01
313	1971 Bldg.	16	XRF	3/18/97	1	Hall	3	Ceiling	Beam	Solid	Wood	0.05
314	1971 Bldg.	54	XRF	3/18/97	1	Hall	4	Door	Door	Solid	Metal	0.02
315	1971 Bldg.	55	XRF	3/18/97	1	Hall	4	Door	Casing	Solid	Metal	0.02
316	1971 Bldg.	56	XRF	3/18/97	1	Hall	4	Door	Casing	Solid	Metal	0.01
317	1971 Bldg.	57	XRF	3/18/97	1	Hall	4	Wall	Midle Wall	Solid	Concrete	0.02
318	1971 Bldg.	58	XRF	3/18/97	1	Hall	4		Radiator	Solid	Metal	0.01
319	1971 Bldg.	59	XRF	3/18/97	1	Hall	4	Stairs	Hand rail	Solid	Wood	0
320	1971 Bldg.	60	XRF	3/18/97	1	Hall	4	Stairs	Baluster	Solid	Metal	0.06
321	1971 Bldg.	61	XRF	3/18/97	1	Hall	4	Stairs	Baluster	Solid	Metal	0.02
322	1971 Bldg.	62	XRF	3/18/97	1	Hall	4	Wall	Column	Solid	Concrete	0
323	1971 Bldg.	63	XRF	3/18/97	1	Hall	4	Door	Door	Solid	Wood	0
324	1971 Bldg.	64	XRF	3/18/97	1	Hall	4	Door	Casing	Solid	Wood	0
325	1971 Bldg.	65	XRF	3/18/97	1	Hall	4	Door	Jamb	Solid	Wood	0
326	1971 Bldg.	66	XRF	3/18/97	1	Hall	4	Window	Casing	Solid	Metal	0.01
327	1971 Bldg.	67	XRF	3/18/97	1	Hall	4	Wall	Midle Wall	Solid	Drywall	0
328	1971 Bldg.	68	XRF	3/18/97	1	Hall	4	Wall	Mural	Solid	Concrete	0.08
329	1971 Bldg.	17	XRF	3/31/97	1	Hall	5	Ceiling	Beam	Solid	Wood	0.04
330	1971 Bldg.	18	XRF	3/31/97	1	Hall	5	Wall	Midle Wall	Solid	Concrete	0
331	1971 Bldg.	19	XRF	3/31/97	1	Hall	5	Door	Door	Peeling	Metal	0.05

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
332	1971 Bldg.	20	XRF	3/31/97	1	Hall	5	Door	Casing	Solid	Metal	0.01
333	1971 Bldg.	21	XRF	3/31/97	1	Hall	5	Wall	Header	Solid	Wood	0
334	1971 Bldg.	22	XRF	3/31/97	1	Hall	5		Radiator	Solid	Metal	0.01
335	1971 Bldg.	23	XRF	3/31/97	1	Hall	5	Stairs	Hand rail	Solid	Wood	0
336	1971 Bldg.	24	XRF	3/31/97	1	Hall	5	Stairs	Newal pos	Solid	Metal	0.03
337	1971 Bldg.	25	XRF	3/31/97	1	Hall	5	Door	Door	Solid	Wood	0
338	1971 Bldg.	26	XRF	3/31/97	1	Hall	5	Door	Casing	Solid	Metal	0.61
339	1971 Bldg.	391	XRF	4/1/97	0	Hall	60	Wall	Midle Wall	Solid	Concrte	0
340	1971 Bldg.	392	XRF	4/1/97	0	Hall	60	Stairs	Hand rail	Peeling	Metal	0.01
341	1971 Bldg.	393	XRF	4/1/97	0	Hall	60	Door	Door	Solid	Wood	0
342	1971 Bldg.	394	XRF	4/1/97	0	Hall	60	Door	Casing	Solid	Metal	0.02
343	1971 Bldg.	395	XRF	4/1/97	0	Hall	60	Wall	Wall Rgstr	Solid	Metal	0.01
344	1971 Bldg.	396	XRF	4/1/97	0	Hall	60	Ceiling		Solid	Concrte	0.01
345	1971 Bldg.	382	XRF	4/1/97	0	Hall	150	Wall	Midle Wall	Solid	Concrte	0.03
346	1971 Bldg.	383	XRF	4/1/97	0	Hall	150	Door	Door	Solid	Wood	0
347	1971 Bldg.	384	XRF	4/1/97	0	Hall	150	Door	Casing	Solid	Metal	0.02
348	1971 Bldg.	385	XRF	4/1/97	0	Hall	150	Ceiling		Solid	Concrte	0.01
349	1971 Bldg.	386	XRF	4/1/97	0	Hall	150	Stairs	Baseboar	Solid	Metal	0
350	1971 Bldg.	387	XRF	4/1/97	0	Hall	150	Wall	Wall Rgstr	Solid	Metal	0.02
351	1971 Bldg.	388	XRF	4/1/97	0	Hall	150	Stairs	Hand rail	Chalking	Metal	0.04
352	1971 Bldg.	389	XRF	4/1/97	0	Hall	150	Door	Door	Solid	Wood	0
353	1971 Bldg.	390	XRF	4/1/97	0	Hall	150	Door	Casing	Peeling	Metal	0.03
354	1971 Bldg.	69	XRF	3/31/97	1	Hall	1030	Wall	Midle Wall	Solid	Concrte	0
355	1971 Bldg.	70	XRF	3/31/97	1	Hall	1030		Radiator	Solid	Metal	0.01
356	1971 Bldg.	71	XRF	3/31/97	1	Hall	1030	Wall	Columns	Peeling	Metal	0.04
357	1971 Bldg.	72	XRF	3/31/97	1	Hall	1030	Window	Casing	Solid	Metal	0.01
358	1971 Bldg.	73	XRF	3/31/97	1	Hall	1030	Wall	Wall	Solid	Wood	0
359	1971 Bldg.	74	XRF	3/31/97	1	Hall	1030	Ceiling	Beam	Solid	Wood	0.08
360	1971 Bldg.	75	XRF	3/31/97	1	Hall	1030	Ceiling	Beam Bra	Solid	Metal	0.04
361	1971 Bldg.	144	XRF	3/31/97	1	Hall	1291	Wall	Columns	Solid	Metal	0.01
362	1971 Bldg.	145	XRF	3/31/97	1	Hall	1291	Wall	Wall	Solid	Drywall	0.01
363	1971 Bldg.	146	XRF	3/31/97	1	Hall	1291	Wall	Wall	Solid	Concrte	0
364	1971 Bldg.	147	XRF	3/31/97	1	Hall	1291		Radiator	Solid	Metal	0
365	1971 Bldg.	148	XRF	3/31/97	1	Hall	1291	Window	Casing	Solid	Metal	0
366	1971 Bldg.	149	XRF	3/31/97	1	Hall	1291	Ceiling	Beam	Solid	Wood	0.04
367	1971 Bldg.	150	XRF	3/31/97	1	Hall	1291	Ceiling	Beam	Solid	Wood	0
368	1971 Bldg.	151	XRF	3/31/97	1	Hall	1291	Ceiling	Beam Bra	Cracked	Metal	0.04
369	1971 Bldg.	196	XRF	3/31/97	1	Hall	1320	Wall	Columns	Solid	Metal	0.01
370	1971 Bldg.	197	XRF	3/31/97	1	Hall	1320	Wall	Columns	Solid	Concrte	0
371	1971 Bldg.	198	XRF	3/31/97	1	Hall	1320	Wall	Wall	Solid	Concrte	0
372	1971 Bldg.	199	XRF	3/31/97	1	Hall	1320		Radiator	Solid	Metal	0.02
373	1971 Bldg.	200	XRF	3/31/97	1	Hall	1320	Window	Casing	Solid	Metal	0.02
374	1971 Bldg.	201	XRF	3/31/97	1	Hall	1320	Ceiling	Beam Bra	Solid	Metal	0.03
375	1971 Bldg.	202	XRF	3/31/97	1	Hall	1320	Ceiling	Beam	Solid	Wood	0
376	1971 Bldg.	203	XRF	3/31/97	1	Hall	1320	Ceiling	Beam	Solid	Wood	0.09
377	1971 Bldg.	284	XRF	4/1/97	1	Hall	1470	Door	Door	Solid	Wood	0
378	1971 Bldg.	285	XRF	4/1/97	1	Hall	1470	Door	Casing	Solid	Metal	0.02
379	1971 Bldg.	286	XRF	4/1/97	1	Hall	1470	Wall	Chair rail	Solid	Wood	0
380	1971 Bldg.	287	XRF	4/1/97	1	Hall	1470	Door	Door	Solid	Wood	0
381	1971 Bldg.	288	XRF	4/1/97	1	Hall	1470	Door	Casing	Solid	Metal	0.01
382	1971 Bldg.	289	XRF	4/1/97	1	Hall	1470	Wall	Midle Wall	Solid	Concrte	0.05
383	1971 Bldg.	290	XRF	4/1/97	1	Hall	1470	Stairs	Hand rail	Solid	Wood	0
384	1971 Bldg.	291	XRF	4/1/97	1	Hall	1470	Wall	Midle Wall	Solid	Concrte	0
385	1971 Bldg.	292	XRF	4/1/97	1	Hall	1470	Wall	Midle Wall	Solid	Concrte	0.02
386	1971 Bldg.	293	XRF	4/1/97	1	Hall	1470	Stairs	Tread	Solid	Metal	0.03

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

3	A Site	B Sample#	C Analysis	D Date	E Floor	F Area	G Room#	H Structure	I Feature	J Condition	K Substrate	L Result
387	1971 Bldg.	294	XRF	4/1/97	1	Hall	1470	Stairs	Hand rail	Solid	Metal	0.01
388	1971 Bldg.	196	XRF	4/2/97	1	Hall	1640	Wall	Midle Wall	Solid	Concrte	0
389	1971 Bldg.	197	XRF	4/2/97	1	Hall	1640	Door	Door	Solid	Wood	0
390	1971 Bldg.	198	XRF	4/2/97	1	Hall	1640	Door	Casing	Solid	Metal	0.02
391	1971 Bldg.	199	XRF	4/2/97	1	Hall	1640	Wall	Radiator	Solid	Metal	0
392	1971 Bldg.	200	XRF	4/2/97	1	Hall	1640	Window	Casing	Solid	Metal	0
393	1971 Bldg.	201	XRF	4/2/97	1	Hall	1640	Ceiling	Beam	Solid	Wood	0
394	1971 Bldg.	202	XRF	4/2/97	1	Hall	1640	Ceiling	Beam Bra	Solid	Metal	0.05
395	1971 Bldg.	203	XRF	4/2/97	1	Hall	1640	Ceiling	Beam	Solid	Wood	0.07
396	1971 Bldg.	204	XRF	4/2/97	1	Hall	1640	Door	Door	Solid	Wood	0
397	1971 Bldg.	205	XRF	4/2/97	1	Hall	1640	Door	Casing	Solid	Metal	0.62
398	1971 Bldg.	206	XRF	4/2/97	1	Hall	1640	Wall	Columns	Solid	Concrte	0.05
399	1971 Bldg.	99	XRF	4/2/97	1	Hall	1700	Wall	Midle Wall	Solid	Concrte	0.02
400	1971 Bldg.	100	XRF	4/2/97	1	Hall	1700	Wall	Midle Wall	Solid	Concrte	0
401	1971 Bldg.	101	XRF	4/2/97	1	Hall	1700	Wall	Midle Wall	Solid	Concrte	0.09
402	1971 Bldg.	102	XRF	4/2/97	1	Hall	1700	Stairs	Hand rail	Solid	Wood	0
403	1971 Bldg.	103	XRF	4/2/97	1	Hall	1700	Stairs	Newal pos	Solid	Metal	0.02
404	1971 Bldg.	104	XRF	4/2/97	1	Hall	1700	Door	Door	Solid	Wood	0.02
405	1971 Bldg.	105	XRF	4/2/97	1	Hall	1700	Door	Casing	Solid	Metal	0.01
406	1971 Bldg.	106	XRF	4/2/97	1	Hall	1700	Ceiling	Beam	Solid	Wood	0
407	1971 Bldg.	107	XRF	4/2/97	1	Hall	1700	Ceiling	Beam Bra	Solid	Metal	0.05
408	1971 Bldg.	108	XRF	4/2/97	1	Hall	1700	Ceiling	Beam	Solid	Wood	0.09
409	1971 Bldg.	109	XRF	4/2/97	1	Hall	1700	Wall	Columns	Solid	Concrte	0
410	1971 Bldg.	74	XRF	4/2/97	1	Hall	1720	Wall	Midle Wall	Solid	Concrte	0.04
411	1971 Bldg.	75	XRF	4/2/97	1	Hall	1720	Wall	Wall	Solid	Drywall	0
412	1971 Bldg.	79	XRF	4/2/97	1	Hall	1720	Ceiling	Beam	Solid	Wood	0
413	1971 Bldg.	80	XRF	4/2/97	1	Hall	1720	Ceiling	Beam Bra	Solid	Metal	0.02
414	1971 Bldg.	81	XRF	4/2/97	1	Hall	1720	Ceiling	Beam	Solid	Wood	0.06
415	1971 Bldg.	82	XRF	4/2/97	1	Hall	1720	Wall	Columns	Solid	Metal	0.04
416	1971 Bldg.	83	XRF	4/2/97	1	Hall	1720	Wall	Columns	Solid	Concrte	0.03
417	1971 Bldg.	84	XRF	4/2/97	1	Hall	1720	Door	Door	Solid	Wood	0
418	1971 Bldg.	85	XRF	4/2/97	1	Hall	1720	Door	Casing	Solid	Metal	0.52
419	1971 Bldg.	37	XRF	3/16/97	1	Kitchen	0	Cabinet		Solid	Wood	0
420	1971 Bldg.	38	XRF	3/16/97	1	Kitchen	0	Floor	Flr Registr	Solid	Metal	0.01
421	1971 Bldg.	39	XRF	3/16/97	1	Kitchen	0	Wall	Wall	Solid	Concrte	0.01
422	1971 Bldg.	6	XRF	3/16/97	1	Kitchen	1	Wall	Wall	Solid	Concrte	0.08
423	1971 Bldg.	7	XRF	3/16/97	1	Kitchen	1	Wall	Wall	Solid	Concrte	0
424	1971 Bldg.	8	XRF	3/16/97	1	Kitchen	1	Ceiling	Beam	Solid	Wood	0.12
425	1971 Bldg.	9	XRF	3/16/97	1	Kitchen	1	Wall	Midle Wall	Solid	Metal	0.27
426	1971 Bldg.	10	XRF	3/16/97	1	Kitchen	1	Door	Jamb	Solid	Metal	0.01
427	1971 Bldg.	11	XRF	3/16/97	1	Kitchen	1	Door	Door	Solid	Wood	0
428	1971 Bldg.	12	XRF	3/16/97	1	Kitchen	1	Door	Door	Solid	Wood	0.01
429	1971 Bldg.	13	XRF	3/16/97	1	Kitchen	1	Ceiling	Beam Bra	Solid	Metal	0.04
430	1971 Bldg.	14	XRF	3/16/97	1	Kitchen	1	Window	Casing	Solid	Metal	0.01
431	1971 Bldg.	15	XRF	3/16/97	1	Kitchen	1	Stairs	Hand rail	Solid	Wood	0
432	1971 Bldg.	16	XRF	3/16/97	1	Kitchen	1	Ceiling	Beam	Solid	Wood	0.03
433	1971 Bldg.	17	XRF	3/16/97	1	Kitchen	1	Wall	Wall	Solid	Concrte	0.03
434	1971 Bldg.	18	XRF	3/16/97	1	Kitchen	1		Radiator	Solid	Metal	0.02
435	1971 Bldg.	19	XRF	3/16/97	1	Kitchen	1	Wall	Wall	Solid	Concrte	0
436	1971 Bldg.	20	XRF	3/16/97	1	Kitchen	1	Wall	Wall	Solid	Concrte	0.04
437	1971 Bldg.	21	XRF	3/16/97	1	Kitchen	1	Wall	Midle Wall	Solid	Tile	0
438	1971 Bldg.	22	XRF	3/16/97	1	Kitchen	1	Wall	Wall	Solid	Concrte	0
439	1971 Bldg.	23	XRF	3/16/97	1	Kitchen	1	Wall	Wall	Solid	Concrte	0.01
440	1971 Bldg.	24	XRF	3/16/97	1	Kitchen	1	Wall	Wall	Solid	Concrte	0.03
441	1971 Bldg.	25	XRF	3/16/97	1	Kitchen	1	Door	Door	Solid	Wood	0.14

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

3	A Site	B Sample#	C Analysis	D Date	E Floor	F Area	G Room#	H Structure	I Feature	J Condition	K Substrate	L Result
442	1971 Bldg.	26	XRF	3/16/97	1	Kitchen	1	Door	Jamb	Solid	Metal	0.03
443	1971 Bldg.	27	XRF	3/16/97	1	Kitchen	1	Door	Door	Solid	Wood	0
444	1971 Bldg.	28	XRF	3/16/97	1	Kitchen	1	Wall	Wall	Solid	Concrete	0.02
445	1971 Bldg.	29	XRF	3/16/97	1	Kitchen	1	Wall	Midle Wall	Solid	Concrete	0
446	1971 Bldg.	30	XRF	3/16/97	1	Kitchen	1	Wall	Wall	Solid	Concrete	0
447	1971 Bldg.	217	XRF	4/3/97	1	Outside	1	Ext Wall	Trim	Solid	Metal	0.03
448	1971 Bldg.	218	XRF	4/3/97	1	Outside	1	Ext Wall	Light	Solid	Metal	0.01
449	1971 Bldg.	219	XRF	4/3/97	1	Outside	1	Roof	Vent	Solid	Metal	0.01
450	1971 Bldg.	220	XRF	4/3/97	1	Outside	1	Window	Sash	Solid	Metal	0
451	1971 Bldg.	221	XRF	4/3/97	1	Outside	1	Window	Downspou	Peeling	Metal	0.04
452	1971 Bldg.	222	XRF	4/3/97	1	Outside	1	Window	Sash	Solid	Metal	0.01
453	1971 Bldg.	223	XRF	4/3/97	1	Outside	1	Ext Wall	Trim	Peeling	Metal	0.02
454	1971 Bldg.	224	XRF	4/3/97	1	Outside	1	Roof	Vent	Solid	Metal	0
455	1971 Bldg.	225	XRF	4/3/97	1	Outside	1	Roof	Register	Peeling	Metal	0.05
456	1971 Bldg.	226	XRF	4/3/97	1	Outside	1	Roof	Casing	Solid	Metal	0.04
457	1971 Bldg.	227	XRF	4/3/97	1	Outside	1	Ext Wall	Trim	Peeling	Metal	0.04
458	1971 Bldg.	228	XRF	4/3/97	1	Outside	1	Roof	Vent	Solid	Metal	0.01
459	1971 Bldg.	229	XRF	4/3/97	1	Outside	1	Window	Header	Solid	Metal	0.04
460	1971 Bldg.	230	XRF	4/3/97	1	Outside	1	Roof	Vent	Peeling	Metal	0.03
461	1971 Bldg.	231	XRF	4/3/97	1	Outside	1	Ext Wall	Trim	Peeling	Metal	0.03
462	1971 Bldg.	232	XRF	4/3/97	1	Outside	1	Ext Wall	Downspou	Peeling	Metal	0.04
463	1971 Bldg.	233	XRF	4/3/97	1	Outside	1	Roof	Trim	Solid	Metal	0
464	1971 Bldg.	234	XRF	4/3/97	1	Outside	1	Roof	Register	Solid	Metal	0.03
465	1971 Bldg.	235	XRF	4/3/97	1	Outside	1	Roof	Header	Solid	Metal	0.02
466	1971 Bldg.	236	XRF	4/3/97	1	Outside	2	Roof	Downspou	Solid	Metal	0.05
467	1971 Bldg.	237	XRF	4/3/97	1	Outside	2	Door	Door	Solid	Metal	0.07
468	1971 Bldg.	238	XRF	4/3/97	1	Outside	2	Door	Casing	Solid	Metal	0
469	1971 Bldg.	239	XRF	4/3/97	1	Outside	2		Downspou	Peeling	Metal	0.02
470	1971 Bldg.	240	XRF	4/3/97	1	Outside	2	Ext Wall	Wall	Solid	Metal	0.03
471	1971 Bldg.	241	XRF	4/3/97	1	Outside	2	Door	Door	Solid	Metal	0.02
472	1971 Bldg.	242	XRF	4/3/97	1	Outside	2	Door	Jamb	Solid	Metal	0.02
473	1971 Bldg.	243	XRF	4/3/97	1	Outside	2	Ext Wall	Trim	Solid	Concrete	0
474	1971 Bldg.	244	XRF	4/3/97	1	Outside	2	Window	Sash	Solid	Metal	0
475	1971 Bldg.	245	XRF	4/3/97	1	Outside	2	Ext Wall	Trim	Peeling	Wood	0
476	1971 Bldg.	246	XRF	4/3/97	1	Outside	2	Ext Wall	Register	Peeling	Metal	0.04
477	1971 Bldg.	247	XRF	4/3/97	1	Outside	2	Ext Wall	Downspou	Peeling	Metal	0
478	1971 Bldg.	248	XRF	4/3/97	1	Outside	2	Window	Header	Solid	Metal	0.03
479	1971 Bldg.	249	XRF	4/3/97	1	Outside	2	Stairs	Hand rail	Peeling	Metal	0.02
480	1971 Bldg.	250	XRF	4/3/97	1	Outside	2	Door	Door	Cracked	Metal	0.02
481	1971 Bldg.	251	XRF	4/3/97	1	Outside	2	Door	Door	Solid	Metal	0.01
482	1971 Bldg.	252	XRF	4/3/97	1	Outside	2	Door	Jamb	Solid	Metal	0.01
483	1971 Bldg.	253	XRF	4/3/97	1	Outside	2	Stairs	Hand rail	Solid	Metal	0.03
484	1971 Bldg.	254	XRF	4/3/97	1	Outside	2	Window	Sash	Solid	Metal	0
485	1971 Bldg.	255	XRF	4/3/97	1	Outside	2	Ext Wall	Trim	Peeling	Wood	0
486	1971 Bldg.	256	XRF	4/3/97	1	Outside	2	Ext Wall	Trim	Solid	Metal	0.02
487	1971 Bldg.	257	XRF	4/3/97	1	Outside	2	Ext Wall	Downspou	Solid	Metal	0.04
488	1971 Bldg.	258	XRF	4/3/97	1	Outside	2	Ext Wall	Register	Peeling	Metal	0.05
489	1971 Bldg.	259	XRF	4/3/97	1	Outside	2	Window	Sash	Solid	Metal	0
490	1971 Bldg.	260	XRF	4/3/97	1	Outside	2	Door	Door	Cracked	Metal	0.02
491	1971 Bldg.	261	XRF	4/3/97	1	Outside	2	Door	Jamb	Solid	Metal	0.01
492	1971 Bldg.	262	XRF	4/3/97	1	Outside	3	Curb		Peeling	Concrete	2.44
493	1971 Bldg.	263	XRF	4/3/97	1	Outside	3	Curb		Peeling	Concrete	0.66
494	1971 Bldg.	264	XRF	4/3/97	1	Outside	3	Car Barrier		Solid	Metal	0.01
495	1971 Bldg.	265	XRF	4/3/97	1	Outside	3	Floor Striping		Chalking	Concrete	0.04
496	1971 Bldg.	27	XRF	3/31/97	1	Porch	5	Wall	Columns	Chalking	Concrete	0

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

A	B	C	D	E	F	G	H	I	J	K	L	
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
497	1971 Bldg.	28	XRF	3/31/97	1	Porch	5	Wall	Mural	Solid	Concrete	2.06
498	1971 Bldg.	29	XRF	3/31/97	1	Porch	5	Door	Door	Solid	Wood	0
499	1971 Bldg.	30	XRF	3/31/97	1	Porch	5	Door	Casing	Solid	Metal	0.03
500	1971 Bldg.	31	XRF	3/31/97	1	Porch	5	Wall	Mural	Solid	Concrete	2.63
501	1971 Bldg.	32	XRF	3/31/97	1	Porch	5	Window	Casing	Solid	Metal	0.44
502	1971 Bldg.	31	XRF	3/16/97	1	Restroom	1	Wall	Wall	Solid	Concrete	0.04
503	1971 Bldg.	32	XRF	3/16/97	1	Restroom	1	Wall	Wall	Solid	Concrete	0.05
504	1971 Bldg.	33	XRF	3/16/97	1	Restroom	1		Locker	Solid	Metal	0.51
505	1971 Bldg.	34	XRF	3/16/97	1	Restroom	1	Wall	Bthrm Stll	Solid	Metal	0.01
506	1971 Bldg.	35	XRF	3/16/97	1	Restroom	2		Locker	Solid	Metal	0.53
507	1971 Bldg.	36	XRF	3/16/97	1	Restroom	2	Wall	Midle Wall	Solid	Concrete	0.03
508	1971 Bldg.	45	XRF	3/17/97	1	Restroom	3	Wall	Header	Solid	Wood	0
509	1971 Bldg.	46	XRF	3/17/97	1	Restroom	3	Wall	Header	Solid	Wood	0
510	1971 Bldg.	47	XRF	3/17/97	1	Restroom	3	Wall	Midle Wall	Solid	Concrete	0.08
511	1971 Bldg.	48	XRF	3/17/97	1	Restroom	3	Wall	Wall	Solid	Concrete	0.01
512	1971 Bldg.	49	XRF	3/17/97	1	Restroom	3	Wall	Bthrm Stll	Solid	Metal	0.02
513	1971 Bldg.	50	XRF	3/17/97	1	Restroom	3	Wall	Column	Solid	Concrete	0.02
514	1971 Bldg.	51	XRF	3/17/97	1	Restroom	4	Wall	Header	Solid	Wood	0
515	1971 Bldg.	52	XRF	3/17/97	1	Restroom	4	Wall	Header	Solid	Wood	0
516	1971 Bldg.	53	XRF	3/17/97	1	Restroom	4	Wall	Midle Wall	Solid	Concrete	0.05
517	1971 Bldg.	54	XRF	3/17/97	1	Restroom	4	Door	Stall Door	Solid	Metal	0
518	1971 Bldg.	55	XRF	3/17/97	1	Restroom	4	Door	Door	Solid	Metal	0.03
519	1971 Bldg.	56	XRF	3/17/97	1	Restroom	4	Door	Casing	Solid	Metal	0.01
520	1971 Bldg.	17	XRF	3/18/97	1	Restroom	5	Wall	Midle Wall	Solid	Concrete	0.01
521	1971 Bldg.	18	XRF	3/18/97	1	Restroom	5	Wall	Wall	Solid	Wood	0
522	1971 Bldg.	19	XRF	3/18/97	1	Restroom	5	Wall	Header	Solid	Wood	0
523	1971 Bldg.	20	XRF	3/18/97	1	Restroom	5	Wall	Midle Wall	Solid	Concrete	0.01
524	1971 Bldg.	21	XRF	3/18/97	1	Restroom	5	Wall	Bthrm Stll	Solid	Metal	0.01
525	1971 Bldg.	22	XRF	3/18/97	1	Restroom	6	Wall	Wall	Solid	Wood	0
526	1971 Bldg.	23	XRF	3/18/97	1	Restroom	6	Wall	Header	Solid	Wood	0
527	1971 Bldg.	24	XRF	3/18/97	1	Restroom	6	Wall	Column	Solid	Concrete	0
528	1971 Bldg.	25	XRF	3/18/97	1	Restroom	6	Wall	Midle Wall	Solid	Concrete	0.04
529	1971 Bldg.	26	XRF	3/18/97	1	Restroom	6	Door	Door	Solid	Wood	0.01
530	1971 Bldg.	27	XRF	3/18/97	1	Restroom	6	Door	Casing	Solid	Metal	0.06
531	1971 Bldg.	28	XRF	3/18/97	1	Restroom	6	Door	Stall Door	Solid	Metal	0.03
532	1971 Bldg.	397	XRF	4/1/97	0	Room	70	Wall	Midle Wall	Solid	Concrete	0.01
533	1971 Bldg.	398	XRF	4/1/97	0	Room	70		Locker	Solid	Metal	0.02
534	1971 Bldg.	399	XRF	4/1/97	0	Room	70	Wall	Wall	Solid	Concrete	0
535	1971 Bldg.	400	XRF	4/1/97	0	Room	70	Ceiling		Solid	Concrete	0.01
536	1971 Bldg.	401	XRF	4/1/97	0	Room	70	Floor		Solid	Concrete	0.07
537	1971 Bldg.	402	XRF	4/1/97	0	Room	70	Wall	Midle Wall	Solid	Concrete	0
538	1971 Bldg.	403	XRF	4/1/97	0	Room	70	Wall	Midle Wall	Solid	Concrete	0
539	1971 Bldg.	404	XRF	4/1/97	0	Room	70	Wall	Midle Wall	Solid	Concrete	0
540	1971 Bldg.	405	XRF	4/1/97	0	Room	70	Ceiling		Solid	Metal	0.03
541	1971 Bldg.	406	XRF	4/1/97	0	Room	70	Wall	Midle Wall	Solid	Concrete	0.01
542	1971 Bldg.	407	XRF	4/1/97	0	Room	70	Wall	Midle Wall	Solid	Concrete	0
543	1971 Bldg.	408	XRF	4/1/97	0	Room	70	Door	Stall Door	Solid	Metal	0.03
544	1971 Bldg.	409	XRF	4/1/97	0	Room	140	Door	Door	Solid	Wood	0
545	1971 Bldg.	410	XRF	4/1/97	0	Room	140	Door	Casing	Solid	Metal	0.02
546	1971 Bldg.	411	XRF	4/1/97	0	Room	140	Stairs	Hand rail	Solid	Metal	0.02
547	1971 Bldg.	412	XRF	4/1/97	0	Room	140	Stairs	Tread	Solid	Metal	0.02
548	1971 Bldg.	368	XRF	4/1/97	0	Room	160		Locker	Solid	Metal	0.01
549	1971 Bldg.	369	XRF	4/1/97	0	Room	160	Door	Door	Solid	Wood	0
550	1971 Bldg.	370	XRF	4/1/97	0	Room	160	Door	Casing	Solid	Metal	0.02
551	1971 Bldg.	371	XRF	4/1/97	0	Room	160	Wall	Midle Wall	Solid	Concrete	0.01

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
552	1971 Bldg.	372	XRF	4/1/97	0	Room	160	Wall	Midle Wall	Solid	Concrte	0.03
553	1971 Bldg.	373	XRF	4/1/97	0	Room	160	Wall	Midle Wall	Solid	Concrte	0.01
554	1971 Bldg.	374	XRF	4/1/97	0	Room	160	Wall	Wall	Solid	Concrte	0.01
555	1971 Bldg.	375	XRF	4/1/97	0	Room	160	Ceiling		Solid	Plaster	0.01
556	1971 Bldg.	376	XRF	4/1/97	0	Room	160	Floor		Solid	Concrte	0.04
557	1971 Bldg.	377	XRF	4/1/97	0	Room	160	Wall	Bath Stall	Solid	Metal	0
558	1971 Bldg.	378	XRF	4/1/97	0	Room	160	Shower		Solid	Metal	0
559	1971 Bldg.	379	XRF	4/1/97	0	Room	160	Wall	Midle Wall	Solid	Concrte	0.01
560	1971 Bldg.	380	XRF	4/1/97	0	Room	160	Wall	Midle Wall	Solid	Concrte	0.02
561	1971 Bldg.	381	XRF	4/1/97	0	Room	160	Ceiling		Solid	Concrte	0.01
562	1971 Bldg.	76	XRF	3/31/97	1	Room	1000	Door	Door	Solid	Metal	0
563	1971 Bldg.	77	XRF	3/31/97	1	Room	1000	Door	Casing	Solid	Metal	0
564	1971 Bldg.	78	XRF	3/31/97	1	Room	1000	Wall	Midle Wall	Solid	Concrte	0
565	1971 Bldg.	79	XRF	3/31/97	1	Room	1000	Wall	Columns	Solid	Metal	0.03
566	1971 Bldg.	80	XRF	3/31/97	1	Room	1000		Radiator	Solid	Metal	0.01
567	1971 Bldg.	81	XRF	3/31/97	1	Room	1000	Wall	Wall	Solid	Wood	0
568	1971 Bldg.	82	XRF	3/31/97	1	Room	1000	Ceiling	Beam Bra	Solid	Metal	0.06
569	1971 Bldg.	83	XRF	3/31/97	1	Room	1000	Ceiling	Beam	Solid	Wood	0.03
570	1971 Bldg.	84	XRF	3/31/97	1	Room	1010	Ceiling	Beam	Solid	Wood	0.04
571	1971 Bldg.	85	XRF	3/31/97	1	Room	1010	Ceiling	Beam	Solid	Wood	0
572	1971 Bldg.	86	XRF	3/31/97	1	Room	1010	Ceiling	Beam Bra	Solid	Metal	0.06
573	1971 Bldg.	87	XRF	3/31/97	1	Room	1010	Wall	Columns	Solid	Metal	0.03
574	1971 Bldg.	88	XRF	3/31/97	1	Room	1010		Radiator	Solid	Metal	0.01
575	1971 Bldg.	89	XRF	3/31/97	1	Room	1010	Wall	Midle Wall	Solid	Concrte	0
576	1971 Bldg.	90	XRF	3/31/97	1	Room	1010	Window	Casing	Solid	Metal	0
577	1971 Bldg.	91	XRF	3/31/97	1	Room	1020	Wall	Columns	Solid	Metal	0.02
578	1971 Bldg.	92	XRF	3/31/97	1	Room	1020		Radiator	Solid	Metal	0.02
579	1971 Bldg.	93	XRF	3/31/97	1	Room	1020	Window	Casing	Solid	Metal	0.01
580	1971 Bldg.	94	XRF	3/31/97	1	Room	1020	Wall	Midle Wall	Solid	Concrte	0
581	1971 Bldg.	95	XRF	3/31/97	1	Room	1020	Ceiling	Beam	Solid	Wood	0.05
582	1971 Bldg.	96	XRF	3/31/97	1	Room	1020	Ceiling	Beam	Solid	Wood	0
583	1971 Bldg.	97	XRF	3/31/97	1	Room	1020	Ceiling	Beam Bra	Cracked	Metal	0.05
584	1971 Bldg.	98	XRF	3/31/97	1	Room	1020	Ceiling	Beam Bra	Cracked	Metal	0.03
585	1971 Bldg.	99	XRF	3/31/97	1	Room	1020	Ceiling	Beam Bra	Cracked	Metal	0.07
586	1971 Bldg.	100	XRF	3/31/97	1	Room	1040	Ceiling	Beam	Solid	Wood	0
587	1971 Bldg.	101	XRF	3/31/97	1	Room	1040	Ceiling	Beam Bra	Cracked	Metal	0.03
588	1971 Bldg.	102	XRF	3/31/97	1	Room	1040	Wall	Columns	Solid	Metal	0.04
589	1971 Bldg.	103	XRF	3/31/97	1	Room	1040	Wall	Columns	Solid		0.03
590	1971 Bldg.	104	XRF	3/31/97	1	Room	1040	Wall	Columns	Solid	Concrte	0.01
591	1971 Bldg.	105	XRF	3/31/97	1	Room	1040		Radiator	Solid	Metal	0.03
592	1971 Bldg.	106	XRF	3/31/97	1	Room	1040	Stairs	Hand rail	Solid	Wood	0
593	1971 Bldg.	107	XRF	3/31/97	1	Room	1040	Stairs	Newal pos	Solid	Metal	0.02
594	1971 Bldg.	108	XRF	3/31/97	1	Room	1040	Wall	Midle Wall	Solid	Concrte	0.01
595	1971 Bldg.	109	XRF	3/31/97	1	Room	1040	Door	Door	Solid	Metal	0
596	1971 Bldg.	110	XRF	3/31/97	1	Room	1040	Door	Casing	Solid	Metal	0.03
597	1971 Bldg.	111	XRF	3/31/97	1	Room	1040	Window	Casing	Solid	Metal	0
598	1971 Bldg.	112	XRF	3/31/97	1	Room	1040	Ceiling	Beam	Solid	Wood	0.09
599	1971 Bldg.	117	XRF	3/31/97	1	Room	1040	Wall	Midle Wall	Solid	Concrte	0.01
600	1971 Bldg.	118	XRF	3/31/97	1	Room	1040	Window	Casing	Solid	Metal	0
601	1971 Bldg.	131	XRF	3/31/97	1	Room	1051	Door	Door	Solid	Wood	0
602	1971 Bldg.	132	XRF	3/31/97	1	Room	1051	Door	Casing	Solid	Metal	0.01
603	1971 Bldg.	113	XRF	3/31/97	1	Room	1052	Stairs	Tread	Solid	Metal	0.01
604	1971 Bldg.	114	XRF	3/31/97	1	Room	1052	Stairs	Hand rail	Solid	Metal	0.03
605	1971 Bldg.	115	XRF	3/31/97	1	Room	1052	Door	Door	Solid	Wood	0
606	1971 Bldg.	116	XRF	3/31/97	1	Room	1052	Door	Casing	Solid	Metal	0.01

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

3	A	B	C	D	E	F	G	H	I	J	K	L
	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
607	1971 Bldg.	119	XRF	3/31/97	1	Room	1060	Radiator	Solid	Metal		0
608	1971 Bldg.	120	XRF	3/31/97	1	Room	1060	Door	Door	Solid	Metal	0
609	1971 Bldg.	121	XRF	3/31/97	1	Room	1060	Door	Casing	Solid	Metal	0
610	1971 Bldg.	122	XRF	3/31/97	1	Room	1060	Wall	Columns	Solid	Metal	0.02
611	1971 Bldg.	123	XRF	3/31/97	1	Room	1060	Wall	Columns	Solid	Concrete	0
612	1971 Bldg.	124	XRF	3/31/97	1	Room	1060	Wall	Columns	Peeling	Metal	0.06
613	1971 Bldg.	125	XRF	3/31/97	1	Room	1060	Ceiling	Beam	Solid	Wood	0
614	1971 Bldg.	126	XRF	3/31/97	1	Room	1060	Ceiling	Beam Bra	Solid	Metal	0.06
615	1971 Bldg.	127	XRF	3/31/97	1	Room	1060	Stairs	Hand rail	Solid	Wood	0
616	1971 Bldg.	128	XRF	3/31/97	1	Room	1060	Stairs	Newal pos	Solid	Metal	0.03
617	1971 Bldg.	129	XRF	3/31/97	1	Room	1060	Door	Door	Solid	Wood	0
618	1971 Bldg.	130	XRF	3/31/97	1	Room	1060	Door	Casing	Solid	Metal	0.03
619	1971 Bldg.	94	XRF	3/18/97	1	Room	1181	Wall	Column	Solid	Metal	0
620	1971 Bldg.	95	XRF	3/18/97	1	Room	1181	Radiator	Solid	Metal	0	
621	1971 Bldg.	96	XRF	3/18/97	1	Room	1181	Wall	Wall	Solid	Concrete	0
622	1971 Bldg.	97	XRF	3/18/97	1	Room	1181	Door	Door	Solid	Wood	0
623	1971 Bldg.	98	XRF	3/18/97	1	Room	1181	Door	Casing	Solid	Metal	0
624	1971 Bldg.	99	XRF	3/18/97	1	Room	1181	Wall	Midle Wall	Solid	Drywall	0
625	1971 Bldg.	100	XRF	3/18/97	1	Room	1181	Stairs	Hand rail	Solid	Wood	0
626	1971 Bldg.	101	XRF	3/18/97	1	Room	1181	Stairs	Newal pos	Solid	Metal	0
627	1971 Bldg.	102	XRF	3/18/97	1	Room	1181	Ceiling	Beam	Solid	Wood	0
628	1971 Bldg.	103	XRF	3/18/97	1	Room	1181	Ceiling	Beam	Solid	Wood	0
629	1971 Bldg.	104	XRF	3/18/97	1	Room	1181	Ceiling	Beam Bra	Peeling	Metal	0
630	1971 Bldg.	6	XRF	3/31/97	1	Room	1200	Wall	Midle Wall	Solid	Concrete	1.19
631	1971 Bldg.	7	XRF	3/31/97	1	Room	1200	Radiator	Solid	Metal	0.01	
632	1971 Bldg.	8	XRF	3/31/97	1	Room	1200	Stairs	Hand rail	Solid	Wood	0
633	1971 Bldg.	9	XRF	3/31/97	1	Room	1200	Stairs	Newal pos	Solid	Metal	0.02
634	1971 Bldg.	10	XRF	3/31/97	1	Room	1200	Door	Door	Solid	Wood	0
635	1971 Bldg.	11	XRF	3/31/97	1	Room	1200	Door	Casing	Solid	Metal	0.02
636	1971 Bldg.	12	XRF	3/31/97	1	Room	1200	Wall	Midle Wall	Solid	Concrete	0.02
637	1971 Bldg.	13	XRF	3/31/97	1	Room	1200		Elec Panel	Solid	Metal	0
638	1971 Bldg.	14	XRF	3/31/97	1	Room	1200	Ceiling	Beam	Solid	Wood	0
639	1971 Bldg.	15	XRF	3/31/97	1	Room	1200	Ceiling	Beam	Solid	Wood	0.06
640	1971 Bldg.	16	XRF	3/31/97	1	Room	1200	Ceiling	Beam Bra	Solid	Metal	0.02
641	1971 Bldg.	69	XRF	3/18/97	1	Room	1210	Wall	Wall	Solid	Concrete	0.09
642	1971 Bldg.	70	XRF	3/18/97	1	Room	1210	Wall	Bthrm Sttl	Solid	Metal	0.07
643	1971 Bldg.	71	XRF	3/18/97	1	Room	1210	Wall	Midle Wall	Solid	Concrete	0.01
644	1971 Bldg.	72	XRF	3/18/97	1	Room	1210	Door	Header	Solid	Wood	0
645	1971 Bldg.	74	XRF	3/18/97	1	Room	1210	Wall	Midle Wall	Solid	Concrete	0.02
646	1971 Bldg.	75	XRF	3/18/97	1	Room	1210		Radiator	Solid	Metal	0.02
647	1971 Bldg.	76	XRF	3/18/97	1	Room	1210	Wall	Panel	Solid	Wood	0.07
648	1971 Bldg.	77	XRF	3/18/97	1	Room	1210	Ceiling	Beam	Solid	Wood	0
649	1971 Bldg.	75	XRF	3/16/97	1	Room	1251	Wall	Wall	Solid	Drywall	0
650	1971 Bldg.	76	XRF	3/16/97	1	Room	1251	Wall	Vent	Solid	Metal	0.12
651	1971 Bldg.	77	XRF	3/16/97	1	Room	1251	Wall	Wall	Solid	Concrete	0.02
652	1971 Bldg.	78	XRF	3/16/97	1	Room	1251	Wall	Wall	Solid	Wood	0
653	1971 Bldg.	79	XRF	3/16/97	1	Room	1251	Wall	Wall	Solid	Wood	0.09
654	1971 Bldg.	80	XRF	3/16/97	1	Room	1251	Window	Header	Solid	Metal	0.07
655	1971 Bldg.	81	XRF	3/16/97	1	Room	1251	Window	Header	Solid	Metal	0.02
656	1971 Bldg.	82	XRF	3/16/97	1	Room	1251	Wall	Midle Wall	Solid	Concrete	0.05
657	1971 Bldg.	83	XRF	3/16/97	1	Room	1251		Radiator	Solid	Metal	0.02
658	1971 Bldg.	84	XRF	3/16/97	1	Room	1251	Door	Door	Solid	Wood	0
659	1971 Bldg.	85	XRF	3/16/97	1	Room	1251	Door	Jamb	Solid	Metal	0.06
660	1971 Bldg.	86	XRF	3/16/97	1	Room	1251	Wall	Diffuser	Solid	Metal	0
661	1971 Bldg.	87	XRF	3/16/97	1	Room	1251	Wall	Diffuser	Solid	Metal	0.01

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
662	1971 Bldg.	88	XRF	3/16/97	1	Room	1251	Wall	Diffuser	Solid	Metal	0.01
663	1971 Bldg.	19	XRF	3/17/97	1	Room	1260	Wall	Midle Wall	Solid	Wood	0.07
664	1971 Bldg.	20	XRF	3/17/97	1	Room	1260	Wall	Midle Wall	Solid	Metal	0.01
665	1971 Bldg.	21	XRF	3/17/97	1	Room	1260	Wall	Wall	Solid	Concrete	0
666	1971 Bldg.	22	XRF	3/17/97	1	Room	1260	Door	Door	Solid	Wood	0
667	1971 Bldg.	23	XRF	3/17/97	1	Room	1260	Door	Casing	Solid	Metal	0.1
668	1971 Bldg.	24	XRF	3/17/97	1	Room	1260	Wall	Midle Wall	Solid	Drywall	0.01
669	1971 Bldg.	25	XRF	3/17/97	1	Room	1260	Wall	Midle Wall	Solid	Drywall	0
670	1971 Bldg.	26	XRF	3/17/97	1	Room	1260	Stairs	Hand rail	Solid	Wood	0
671	1971 Bldg.	27	XRF	3/17/97	1	Room	1260	Stairs	Newal pos	Solid	Metal	0.02
672	1971 Bldg.	6	XRF	3/17/97	1	Room	1261	Wall	Midle Wall	Solid	Concrete	0
673	1971 Bldg.	7	XRF	3/17/97	1	Room	1261		Radiator	Solid	Metal	0
674	1971 Bldg.	8	XRF	3/17/97	1	Room	1261	Wall	Column	Solid	Metal	0.02
675	1971 Bldg.	9	XRF	3/17/97	1	Room	1261	Door	Door	Solid	Wood	0
676	1971 Bldg.	10	XRF	3/17/97	1	Room	1261	Door	Jamb	Solid	Metal	0.01
677	1971 Bldg.	11	XRF	3/17/97	1	Room	1261	Door	Door	Solid	Wood	0.04
678	1971 Bldg.	12	XRF	3/17/97	1	Room	1261	Wall	Wall	Solid	Wood	0
679	1971 Bldg.	13	XRF	3/17/97	1	Room	1261	Wall	Midle Wall	Solid	Wood	0
680	1971 Bldg.	14	XRF	3/17/97	1	Room	1261		Radiator	Solid	Metal	0
681	1971 Bldg.	15	XRF	3/17/97	1	Room	1261	Wall	Wall	Solid	Wood	0.05
682	1971 Bldg.	16	XRF	3/17/97	1	Room	1261	Wall	Wall	Solid	Concrete	0
683	1971 Bldg.	17	XRF	3/17/97	1	Room	1261	Wall	Midle Wall	Solid	Wood	0
684	1971 Bldg.	18	XRF	3/17/97	1	Room	1261	Wall	Midle Wall	Solid	Wood	0.06
685	1971 Bldg.	126	XRF	3/16/97	1	Room	1262	Wall	Midle Wall	Solid	Concrete	0.05
686	1971 Bldg.	127	XRF	3/16/97	1	Room	1262	Wall	Midle Wall	Solid	Drywall	0.04
687	1971 Bldg.	128	XRF	3/16/97	1	Room	1262		Radiator	Solid	Metal	0.01
688	1971 Bldg.	129	XRF	3/16/97	1	Room	1262		Radiator	Solid	Metal	0.33
689	1971 Bldg.	130	XRF	3/16/97	1	Room	1262	Door	Door	Solid	Wood	0
690	1971 Bldg.	131	XRF	3/16/97	1	Room	1262	Door	Panel	Solid	Wood	0.09
691	1971 Bldg.	1	XRF	3/17/97	1	Room	1262	Door	Casing	Solid	Metal	1.19
692	1971 Bldg.	92	XRF	3/17/97	1	Room	1272	Door	Door	Solid	Wood	0
693	1971 Bldg.	93	XRF	3/17/97	1	Room	1272	Door	Casing	Solid	Metal	0.02
694	1971 Bldg.	94	XRF	3/17/97	1	Room	1272	Stairs	Hand rail	Solid	Metal	0.03
695	1971 Bldg.	95	XRF	3/17/97	1	Room	1272	Stairs	Tread	Solid	Metal	0.02
696	1971 Bldg.	96	XRF	3/17/97	1	Room	1272	Stairs	Baseboar	Solid	Metal	0.02
697	1971 Bldg.	72	XRF	3/17/97	1	Room	1274	Wall	Midle Wall	Solid	Concrete	0.01
698	1971 Bldg.	73	XRF	3/17/97	1	Room	1274	Wall	Midle Wall	Solid	Drywall	0
699	1971 Bldg.	74	XRF	3/17/97	1	Room	1274	Wall	Column	Solid	Metal	0.01
700	1971 Bldg.	75	XRF	3/17/97	1	Room	1274	Cabinet	Floor	Solid	Wood	0.02
701	1971 Bldg.	76	XRF	3/17/97	1	Room	1274	Cabinet	Door	Solid	Wood	0
702	1971 Bldg.	77	XRF	3/17/97	1	Room	1274	Wall	Midle Wall	Solid	Drywall	0.03
703	1971 Bldg.	78	XRF	3/17/97	1	Room	1274	Cabinet	Outside	Solid	Wood	0.11
704	1971 Bldg.	79	XRF	3/17/97	1	Room	1274	Ceiling	Beam	Solid	Wood	0
705	1971 Bldg.	80	XRF	3/17/97	1	Room	1274	Ceiling	Beam Bra	Solid	Metal	0.04
706	1971 Bldg.	81	XRF	3/17/97	1	Room	1274	Ceiling	Beam	Solid	Wood	0.06
707	1971 Bldg.	82	XRF	3/17/97	1	Room	1274	Stairs	Hand rail	Solid	Wood	0
708	1971 Bldg.	83	XRF	3/17/97	1	Room	1274	Stairs	Newal pos	Solid	Metal	0.03
709	1971 Bldg.	84	XRF	3/17/97	1	Room	1274	Stairs	Column	Solid	Concrete	0.01
710	1971 Bldg.	85	XRF	3/17/97	1	Room	1274	Door	Door	Solid	Wood	0
711	1971 Bldg.	86	XRF	3/17/97	1	Room	1274	Door	Casing	Solid	Metal	0.02
712	1971 Bldg.	87	XRF	3/17/97	1	Room	1274	Door	Door	Solid	Metal	0.02
713	1971 Bldg.	88	XRF	3/17/97	1	Room	1274	Coat Rack		Solid	Wood	0.06
714	1971 Bldg.	89	XRF	3/17/97	1	Room	1274	Coat Rack		Solid	Wood	0
715	1971 Bldg.	121	XRF	3/17/97	1	Room	1280	Door	Door	Solid	Wood	0
716	1971 Bldg.	122	XRF	3/17/97	1	Room	1280	Door	Casing	Solid	Metal	0.01

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
717	1971 Bldg.	123	XRF	3/17/97	1	Room	1280	Wall	Midle Wall	Solid	Drywall	0.01
718	1971 Bldg.	124	XRF	3/17/97	1	Room	1280	Wall	Midle Wall	Solid	Drywall	0
719	1971 Bldg.	125	XRF	3/17/97	1	Room	1280	Ceiling	Beam Bra	Solid	Metal	0.06
720	1971 Bldg.	126	XRF	3/17/97	1	Room	1280	Ceiling	Beam	Solid	Wood	0
721	1971 Bldg.	127	XRF	3/17/97	1	Room	1280	Ceiling	Beam	Solid	Wood	0.04
722	1971 Bldg.	139	XRF	3/17/97	1	Room	1284	Door	Door	Solid	Wood	0
723	1971 Bldg.	140	XRF	3/17/97	1	Room	1284	Door	Casing	Solid	Metal	0
724	1971 Bldg.	141	XRF	3/17/97	1	Room	1284	Wall	Midle Wall	Solid	Drywall	0.01
725	1971 Bldg.	142	XRF	3/17/97	1	Room	1284		Radiator	Solid	Metal	0.18
726	1971 Bldg.	143	XRF	3/17/97	1	Room	1284	Wall	Wall	Solid	Wood	0
727	1971 Bldg.	144	XRF	3/17/97	1	Room	1284		Radiator	Solid	Metal	0
728	1971 Bldg.	145	XRF	3/17/97	1	Room	1284		Radiator	Solid	Metal	0.01
729	1971 Bldg.	146	XRF	3/17/97	1	Room	1284	Wall	Midle Wall	Solid	Concrte	0.02
730	1971 Bldg.	148	XRF	3/17/97	1	Room	1284	Window	Casing	Solid		0.01
731	1971 Bldg.	149	XRF	3/17/97	1	Room	1284	Ceiling	Beam	Solid	Wood	0.04
732	1971 Bldg.	152	XRF	3/31/97	1	Room	1290	Wall	Midle Wall	Solid	Concrte	0.01
733	1971 Bldg.	153	XRF	3/31/97	1	Room	1290		Radiator	Solid	Metal	0.01
734	1971 Bldg.	154	XRF	3/31/97	1	Room	1290	Window	Casing	Solid	Metal	0.02
735	1971 Bldg.	155	XRF	3/31/97	1	Room	1290	Ceiling	Beam	Chalking	Wood	0
736	1971 Bldg.	156	XRF	3/31/97	1	Room	1290	Ceiling	Beam Bra	Chalking	Metal	0.04
737	1971 Bldg.	157	XRF	3/31/97	1	Room	1290	Ceiling	Beam	Solid	Wood	0.11
738	1971 Bldg.	158	XRF	3/31/97	1	Room	1290	Door	Door	Solid	Metal	0
739	1971 Bldg.	159	XRF	3/31/97	1	Room	1290	Door	Casing	Solid	Metal	0
740	1971 Bldg.	160	XRF	3/31/97	1	Room	1290	Wall	Columns	Solid	Metal	0.04
741	1971 Bldg.	161	XRF	3/31/97	1	Room	1292	Wall	Columns	Solid		0.07
742	1971 Bldg.	162	XRF	3/31/97	1	Room	1292	Door	Door	Solid	Metal	0
743	1971 Bldg.	163	XRF	3/31/97	1	Room	1292	Door	Casing	Solid	Metal	0
744	1971 Bldg.	164	XRF	3/31/97	1	Room	1292		Radiator	Solid	Metal	0
745	1971 Bldg.	165	XRF	3/31/97	1	Room	1292	Window	Casing	Solid	Metal	0
746	1971 Bldg.	166	XRF	3/31/97	1	Room	1292	Wall	Midle Wall	Solid	Concrte	0
747	1971 Bldg.	167	XRF	3/31/97	1	Room	1292	Stairs	Hand rail	Solid	Wood	0
748	1971 Bldg.	168	XRF	3/31/97	1	Room	1292	Stairs	Newal pos	Solid	Metal	0.02
749	1971 Bldg.	169	XRF	3/31/97	1	Room	1292	Ceiling	Beam	Solid	Wood	0.09
750	1971 Bldg.	170	XRF	3/31/97	1	Room	1292	Ceiling	Beam	Solid	Wood	0
751	1971 Bldg.	171	XRF	3/31/97	1	Room	1292	Ceiling	Beam Bra	Solid	Metal	0.05
752	1971 Bldg.	172	XRF	3/31/97	1	Room	1292	Wall	Columns	Solid	Concrte	0.06
753	1971 Bldg.	180	XRF	3/31/97	1	Room	1301	Door	Door	Solid	Wood	0
754	1971 Bldg.	181	XRF	3/31/97	1	Room	1301	Door	Casing	Solid	Metal	0.03
755	1971 Bldg.	176	XRF	3/31/97	1	Room	1302	Stairs	Tread	Solid	Metal	0.01
756	1971 Bldg.	177	XRF	3/31/97	1	Room	1302	Stairs	Hand rail	Solid	Metal	0.03
757	1971 Bldg.	178	XRF	3/31/97	1	Room	1302	Door	Door	Solid	Wood	0
758	1971 Bldg.	179	XRF	3/31/97	1	Room	1302	Window	Casing	Solid	Metal	0.01
759	1971 Bldg.	182	XRF	3/31/97	1	Room	1310	Wall	Columns	Solid	Metal	0.04
760	1971 Bldg.	183	XRF	3/31/97	1	Room	1310	Wall	Columns	Solid	Concrte	0
761	1971 Bldg.	184	XRF	3/31/97	1	Room	1310	Wall	Columns	Solid	Metal	0.02
762	1971 Bldg.	185	XRF	3/31/97	1	Room	1310	Wall	Midle Wall	Solid	Concrte	0.08
763	1971 Bldg.	186	XRF	3/31/97	1	Room	1310	Door	Door	Solid	Metal	0
764	1971 Bldg.	187	XRF	3/31/97	1	Room	1310	Door	Casing	Solid		0
765	1971 Bldg.	188	XRF	3/31/97	1	Room	1310	Window	Casing	Solid	Metal	0
766	1971 Bldg.	189	XRF	3/31/97	1	Room	1310	Ceiling	Beam	Solid	Wood	0.06
767	1971 Bldg.	190	XRF	3/31/97	1	Room	1310	Ceiling	Beam	Solid	Wood	0
768	1971 Bldg.	191	XRF	3/31/97	1	Room	1310	Ceiling	Beam Bra	Solid	Metal	0.04
769	1971 Bldg.	192	XRF	3/31/97	1	Room	1310	Door	Door	Solid	Wood	0
770	1971 Bldg.	193	XRF	3/31/97	1	Room	1310	Door	Casing	Solid	Metal	0.03
771	1971 Bldg.	194	XRF	3/31/97	1	Room	1310	Stairs	Hand rail	Solid	Wood	0

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

A	B	C	D	E	F	G	H	I	J	K	L	
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
772	1971 Bldg.	195	XRF	3/31/97	1	Room	1310	Stairs	Newal pos	Solid	Metal	0.03
773	1971 Bldg.	229	XRF	4/1/97	1	Room	1330	Door	Door	Solid	Metal	0
774	1971 Bldg.	230	XRF	4/1/97	1	Room	1330	Door	Casing	Solid	Metal	0
775	1971 Bldg.	231	XRF	4/1/97	1	Room	1330	Wall	Midle Wall	Solid	Concrete	0
776	1971 Bldg.	232	XRF	4/1/97	1	Room	1330		Radiator	Solid	Metal	0.01
777	1971 Bldg.	233	XRF	4/1/97	1	Room	1330	Window	Casing	Solid	Metal	0
778	1971 Bldg.	234	XRF	4/1/97	1	Room	1330	Ceiling	Beam	Solid	Wood	0
779	1971 Bldg.	235	XRF	4/1/97	1	Room	1330	Ceiling	Beam Bra	Solid	Metal	0.04
780	1971 Bldg.	236	XRF	4/1/97	1	Room	1330	Ceiling	Beam	Solid	Wood	0.09
781	1971 Bldg.	237	XRF	4/1/97	1	Room	1330	Wall	Columns	Solid	Metal	0.07
782	1971 Bldg.	320	XRF	4/1/97	1	Room	1330	Wall	Midle Wall	Solid	Concrete	3.32
783	1971 Bldg.	321	XRF	4/1/97	1	Room	1330		Radiator	Solid	Metal	0.01
784	1971 Bldg.	322	XRF	4/1/97	1	Room	1330	Wall	Midle Wall	Solid	Concrete	0
785	1971 Bldg.	323	XRF	4/1/97	1	Room	1330	Door	Door	Solid	Wood	0
786	1971 Bldg.	324	XRF	4/1/97	1	Room	1330	Door	Casing	Solid	Metal	0.02
787	1971 Bldg.	325	XRF	4/1/97	1	Room	1330	Window	Casing	Solid	Metal	0
788	1971 Bldg.	326	XRF	4/1/97	1	Room	1330	Window	Panel	Solid	Metal	0
789	1971 Bldg.	327	XRF	4/1/97	1	Room	1330	Wall	Wall	Solid	Wood	0
790	1971 Bldg.	328	XRF	4/1/97	1	Room	1330	Ceiling	Beam	Solid	Wood	0.06
791	1971 Bldg.	329	XRF	4/1/97	1	Room	1330	Ceiling	Beam Bra	Solid	Metal	0.02
792	1971 Bldg.	222	XRF	4/1/97	1	Room	1340	Wall	Midle Wall	Solid	Concrete	0
793	1971 Bldg.	223	XRF	4/1/97	1	Room	1340	Window	Casing	Solid	Metal	0
794	1971 Bldg.	224	XRF	4/1/97	1	Room	1340		Radiator	Solid	Metal	0
795	1971 Bldg.	225	XRF	4/1/97	1	Room	1340	Wall	Columns	Solid	Metal	0.04
796	1971 Bldg.	226	XRF	4/1/97	1	Room	1340	Ceiling	Beam	Solid	Wood	0.09
797	1971 Bldg.	227	XRF	4/1/97	1	Room	1340	Ceiling	Beam	Solid	Wood	0
798	1971 Bldg.	228	XRF	4/1/97	1	Room	1340	Ceiling	Beam Bra	Solid	Metal	0.07
799	1971 Bldg.	204	XRF	3/31/97	1	Room	1350	Wall	Columns	Solid	Metal	0.03
800	1971 Bldg.	205	XRF	3/31/97	1	Room	1350		Radiator	Solid	Metal	0.01
801	1971 Bldg.	206	XRF	3/31/97	1	Room	1350	Window	Casing	Solid	Metal	0
802	1971 Bldg.	207	XRF	3/31/97	1	Room	1350	Wall	Midle Wall	Solid	Concrete	0.01
803	1971 Bldg.	208	XRF	3/31/97	1	Room	1350	Wall	Midle Wall	Solid	Concrete	0.01
804	1971 Bldg.	209	XRF	3/31/97	1	Room	1350	Ceiling	Beam	Solid	Wood	0.09
805	1971 Bldg.	210	XRF	3/31/97	1	Room	1350	Ceiling	Beam	Solid	Wood	0
806	1971 Bldg.	211	XRF	3/31/97	1	Room	1350	Ceiling	Beam Bra	Solid	Metal	0.06
807	1971 Bldg.	413	XRF	4/1/97	1	Room	1390	Door	Door	Solid	Wood	0
808	1971 Bldg.	414	XRF	4/1/97	1	Room	1390	Door	Casing	Solid	Metal	0
809	1971 Bldg.	415	XRF	4/1/97	1	Room	1390	Wall	Wall	Solid	Drywall	0.03
810	1971 Bldg.	416	XRF	4/1/97	1	Room	1390	Stairs	Hand rail	Solid	Wood	0
811	1971 Bldg.	417	XRF	4/1/97	1	Room	1390	Stairs	Newal pos	Solid	Metal	0.01
812	1971 Bldg.	418	XRF	4/1/97	1	Room	1390	Wall	Midle Wall	Solid	Concrete	0.01
813	1971 Bldg.	419	XRF	4/1/97	1	Room	1390		Radiator	Solid	Metal	0.02
814	1971 Bldg.	420	XRF	4/1/97	1	Room	1390	Wall	Midle Wall	Solid	Concrete	0.01
815	1971 Bldg.	421	XRF	4/1/97	1	Room	1390	Ceiling	Beam	Solid	Wood	0.07
816	1971 Bldg.	422	XRF	4/1/97	1	Room	1390	Ceiling	Beam	Solid	Wood	0
817	1971 Bldg.	423	XRF	4/1/97	1	Room	1390	Ceiling	Beam Bra	Solid	Metal	0.05
818	1971 Bldg.	20	XRF	4/2/97	1	Room	1394	Wall	Midle Wall	Solid	Concrete	0
819	1971 Bldg.	21	XRF	4/2/97	1	Room	1394	Wall	Wall	Solid	Concrete	0.02
820	1971 Bldg.	22	XRF	4/2/97	1	Room	1394		Radiator	Solid	Metal	0.01
821	1971 Bldg.	23	XRF	4/2/97	1	Room	1394	Wall	Midle Wall	Solid	Drywall	0
822	1971 Bldg.	24	XRF	4/2/97	1	Room	1394	Door	Door	Solid	Wood	0
823	1971 Bldg.	25	XRF	4/2/97	1	Room	1394	Door	Casing	Solid	Metal	0.05
824	1971 Bldg.	26	XRF	4/2/97	1	Room	1394	Ceiling	Beam	Solid	Wood	0.07
825	1971 Bldg.	424	XRF	4/1/97	1	Room	1395	Wall	Midle Wall	Solid	Concrete	0
826	1971 Bldg.	425	XRF	4/1/97	1	Room	1395	Wall	Midle Wall	Solid	Drywall	0

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

3	A Site	B Sample#	C Analysis	D Date	E Floor	F Area	G Room#	H Structure	I Feature	J Condition	K Substrate	L Result
827	1971 Bldg.	426	XRF	4/1/97	1	Room	1395	Door	Door	Solid	Wood	0
828	1971 Bldg.	427	XRF	4/1/97	1	Room	1395	Door	Casing	Solid	Metal	0.01
829	1971 Bldg.	428	XRF	4/1/97	1	Room	1395		Radiator	Solid	Metal	0.01
830	1971 Bldg.	358	XRF	4/1/97	1	Room	1400	Wall	Midle Wall	Solid	Wood	0.03
831	1971 Bldg.	359	XRF	4/1/97	1	Room	1400	Door	Door	Solid	Wood	0
832	1971 Bldg.	360	XRF	4/1/97	1	Room	1400	Door	Casing	Solid	Metal	0.04
833	1971 Bldg.	361	XRF	4/1/97	1	Room	1400	Wall	Midle Wall	Solid	Concrte	0.01
834	1971 Bldg.	362	XRF	4/1/97	1	Room	1400	Wall	Midle Wall	Solid	Drywall	0.03
835	1971 Bldg.	363	XRF	4/1/97	1	Room	1400		Radiator	Solid	Metal	0.02
836	1971 Bldg.	364	XRF	4/1/97	1	Room	1400		Elec Panel	Solid	Metal	0.07
837	1971 Bldg.	365	XRF	4/1/97	1	Room	1400	Ceiling	Beam	Solid	Wood	0.09
838	1971 Bldg.	366	XRF	4/1/97	1	Room	1400	Ceiling	Beam	Solid	Wood	0
839	1971 Bldg.	367	XRF	4/1/97	1	Room	1400	Ceiling	Beam Bra	Solid	Metal	0.03
840	1971 Bldg.	10	XRF	4/2/97	1	Room	1400	Door	Door	Solid	Wood	0
841	1971 Bldg.	11	XRF	4/2/97	1	Room	1400	Door	Casing	Solid	Metal	0
842	1971 Bldg.	12	XRF	4/2/97	1	Room	1400	Wall	Midle Wall	Solid	Drywall	0.04
843	1971 Bldg.	13	XRF	4/2/97	1	Room	1400	Wall	Diffuser	Solid	Metal	0
844	1971 Bldg.	14	XRF	4/2/97	1	Room	1400	Wall	Midle Wall	Solid	Drywall	0.03
845	1971 Bldg.	6	XRF	4/2/97	1	Room	1410	Wall	Midle Wall	Solid	Concrte	0.01
846	1971 Bldg.	7	XRF	4/2/97	1	Room	1410	Door	Door	Solid	Wood	0
847	1971 Bldg.	8	XRF	4/2/97	1	Room	1410	Door	Casing	Solid	Metal	0
848	1971 Bldg.	9	XRF	4/2/97	1	Room	1410		Radiator	Solid	Metal	0
849	1971 Bldg.	15	XRF	4/2/97	1	Room	1420	Wall	Midle Wall	Solid	Concrte	0.03
850	1971 Bldg.	16	XRF	4/2/97	1	Room	1420	Door	Door	Solid	Wood	0
851	1971 Bldg.	17	XRF	4/2/97	1	Room	1420	Door	Casing	Solid	Metal	0.01
852	1971 Bldg.	18	XRF	4/2/97	1	Room	1420		Radiator	Solid	Metal	0.02
853	1971 Bldg.	19	XRF	4/2/97	1	Room	1420	Wall	Wall	Solid	Concrte	0.04
854	1971 Bldg.	341	XRF	4/1/97	1	Room	1460	Door	Door	Solid	Wood	0
855	1971 Bldg.	342	XRF	4/1/97	1	Room	1460	Door	Casing	Solid	Metal	0.02
856	1971 Bldg.	343	XRF	4/1/97	1	Room	1460	Wall	Wall	Solid	Concrte	0.04
857	1971 Bldg.	344	XRF	4/1/97	1	Room	1460	Wall	Wall	Solid	Concrte	0
858	1971 Bldg.	345	XRF	4/1/97	1	Room	1460	Coat Rack		Solid	Wood	0
859	1971 Bldg.	346	XRF	4/1/97	1	Room	1460	Door	Door	Solid	Wood	0
860	1971 Bldg.	347	XRF	4/1/97	1	Room	1460	Door	Casing	Solid	Metal	0.01
861	1971 Bldg.	348	XRF	4/1/97	1	Room	1460	Floor		Solid	Tile	0
862	1971 Bldg.	349	XRF	4/1/97	1	Room	1460	Floor		Solid	Tile	0.2
863	1971 Bldg.	350	XRF	4/1/97	1	Room	1460	Floor		Peeling	Tile	0.31
864	1971 Bldg.	351	XRF	4/1/97	1	Room	1460	Wall	Wall	Solid	Wood	0
865	1971 Bldg.	352	XRF	4/1/97	1	Room	1460	Wall	Chair rail	Solid	Wood	0
866	1971 Bldg.	353	XRF	4/1/97	1	Room	1460	Wall	Midle Wall	Solid	Wood	0.05
867	1971 Bldg.	354	XRF	4/1/97	1	Room	1460	Wall	Wall	Solid	Concrte	0
868	1971 Bldg.	355	XRF	4/1/97	1	Room	1460	Wall	Wall	Solid	Concrte	0.04
869	1971 Bldg.	356	XRF	4/1/97	1	Room	1460	Wall	Wall Rgstr	Solid	Metal	0.03
870	1971 Bldg.	357	XRF	4/1/97	1	Room	1460	Wall	Wall Rgstr	Solid	Metal	0
871	1971 Bldg.	90	XRF	3/17/97	1	Room	1471	Door	Door	Solid	Wood	0
872	1971 Bldg.	91	XRF	3/17/97	1	Room	1471	Door	Casing	Solid	Metal	0.07
873	1971 Bldg.	295	XRF	4/1/97	1	Room	1500	Wall	Midle Wall	Solid	Concrte	0.02
874	1971 Bldg.	296	XRF	4/1/97	1	Room	1500	Window	Casing	Solid	Metal	0
875	1971 Bldg.	297	XRF	4/1/97	1	Room	1500		Radiator	Solid	Metal	0.02
876	1971 Bldg.	298	XRF	4/1/97	1	Room	1500	Wall	Chair rail	Solid	Wood	0
877	1971 Bldg.	299	XRF	4/1/97	1	Room	1500	Door	Door	Solid	Wood	0
878	1971 Bldg.	300	XRF	4/1/97	1	Room	1500	Door	Casing	Solid	Metal	0.02
879	1971 Bldg.	301	XRF	4/1/97	1	Room	1500	Wall	Midle Wall	Solid	Concrte	0.04
880	1971 Bldg.	302	XRF	4/1/97	1	Room	1500	Wall	Midle Wall	Solid	Concrte	0.01
881	1971 Bldg.	303	XRF	4/1/97	1	Room	1500	Wall	Midle Wall	Solid	Concrte	0

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
882	1971 Bldg.	304	XRF	4/1/97	1	Room	1500	Ceiling	Beam Bra	Solid	Metal	0.04
883	1971 Bldg.	305	XRF	4/1/97	1	Room	1500	Ceiling	Beam	Solid	Wood	0
884	1971 Bldg.	306	XRF	4/1/97	1	Room	1500	Ceiling	Beam	Solid	Wood	0.04
885	1971 Bldg.	330	XRF	4/1/97	1	Room	1540	Wall	Midle Wall	Solid	Concrte	0.06
886	1971 Bldg.	331	XRF	4/1/97	1	Room	1540	Wall	Midle Wall	Solid	Concrte	0.01
887	1971 Bldg.	332	XRF	4/1/97	1	Room	1540	Door	Door	Solid	Wood	0
888	1971 Bldg.	333	XRF	4/1/97	1	Room	1540	Door	Casing	Solid	Metal	0.01
889	1971 Bldg.	334	XRF	4/1/97	1	Room	1540	Window	Casing	Solid	Metal	0
890	1971 Bldg.	335	XRF	4/1/97	1	Room	1540	Window	Panel	Solid	Metal	0.02
891	1971 Bldg.	336	XRF	4/1/97	1	Room	1540		Radiator	Solid	Metal	0.01
892	1971 Bldg.	337	XRF	4/1/97	1	Room	1540	Ceiling	Beam Bra	Solid	Metal	0.04
893	1971 Bldg.	338	XRF	4/1/97	1	Room	1540	Ceiling	Beam	Solid	Wood	0
894	1971 Bldg.	339	XRF	4/1/97	1	Room	1540	Ceiling	Beam	Solid	Wood	0.08
895	1971 Bldg.	340	XRF	4/1/97	1	Room	1540	Wall	Midle Wall	Solid	Concrte	0
896	1971 Bldg.	310	XRF	4/1/97	1	Room	1560	Wall	Midle Wall	Solid	Concrte	3.13
897	1971 Bldg.	311	XRF	4/1/97	1	Room	1560	Wall	Midle Wall	Solid	Concrte	0.01
898	1971 Bldg.	312	XRF	4/1/97	1	Room	1560	Wall	Midle Wall	Solid	Concrte	0.04
899	1971 Bldg.	313	XRF	4/1/97	1	Room	1560	Window	Casing	Solid	Metal	0
900	1971 Bldg.	314	XRF	4/1/97	1	Room	1560		Radiator	Solid	Metal	0
901	1971 Bldg.	315	XRF	4/1/97	1	Room	1560	Door	Door	Solid	Wood	0
902	1971 Bldg.	316	XRF	4/1/97	1	Room	1560	Door	Casing	Solid	Metal	0.02
903	1971 Bldg.	317	XRF	4/1/97	1	Room	1560	Ceiling	Beam Bra	Solid	Metal	0.04
904	1971 Bldg.	318	XRF	4/1/97	1	Room	1560	Ceiling	Beam	Solid	Wood	0.07
905	1971 Bldg.	319	XRF	4/1/97	1	Room	1560	Ceiling	Beam	Solid	Wood	0
906	1971 Bldg.	262	XRF	4/1/97	1	Room	1570	Wall	Midle Wall	Solid	Concrte	0.06
907	1971 Bldg.	263	XRF	4/1/97	1	Room	1570	Window	Casing	Solid	Metal	0
908	1971 Bldg.	264	XRF	4/1/97	1	Room	1570		Radiator	Solid	Metal	0.07
909	1971 Bldg.	265	XRF	4/1/97	1	Room	1570	Wall	Midle Wall	Solid	Concrte	0.02
910	1971 Bldg.	266	XRF	4/1/97	1	Room	1570	Door	Door	Solid	Wood	0
911	1971 Bldg.	267	XRF	4/1/97	1	Room	1570	Door	Casing	Solid	Metal	0.02
912	1971 Bldg.	268	XRF	4/1/97	1	Room	1570	Ceiling	Beam	Solid	Wood	0.05
913	1971 Bldg.	269	XRF	4/1/97	1	Room	1570	Ceiling	Beam Bra	Solid	Metal	0.05
914	1971 Bldg.	270	XRF	4/1/97	1	Room	1570	Wall	Wall	Solid	Wood	0
915	1971 Bldg.	271	XRF	4/1/97	1	Room	1570	Wall	Midle Wall	Solid	Concrte	0.04
916	1971 Bldg.	272	XRF	4/1/97	1	Room	1570	Wall	Midle Wall	Solid	Concrte	0.01
917	1971 Bldg.	251	XRF	4/1/97	1	Room	1580	Ceiling	Beam	Solid	Wood	0.08
918	1971 Bldg.	252	XRF	4/1/97	1	Room	1580	Ceiling	Beam	Solid	Wood	0
919	1971 Bldg.	253	XRF	4/1/97	1	Room	1580	Ceiling	Beam Bra	Solid	Metal	0.06
920	1971 Bldg.	254	XRF	4/1/97	1	Room	1580	Wall	Midle Wall	Solid	Concrte	3.54
921	1971 Bldg.	255	XRF	4/1/97	1	Room	1580	Wall	Midle Wall	Solid	Concrte	0.01
922	1971 Bldg.	256	XRF	4/1/97	1	Room	1580	Door	Door	Solid	Wood	0
923	1971 Bldg.	257	XRF	4/1/97	1	Room	1580	Door	Casing	Solid	Metal	0.03
924	1971 Bldg.	258	XRF	4/1/97	1	Room	1580	Wall	Chair rail	Solid	Wood	0
925	1971 Bldg.	259	XRF	4/1/97	1	Room	1580	Window	Casing	Solid	Metal	0.02
926	1971 Bldg.	260	XRF	4/1/97	1	Room	1580		Radiator	Solid	Metal	0
927	1971 Bldg.	261	XRF	4/1/97	1	Room	1580	Wall	Midle Wall	Solid	Concrte	0.01
928	1971 Bldg.	238	XRF	4/1/97	1	Room	1590		Radiator	Solid	Metal	0.01
929	1971 Bldg.	239	XRF	4/1/97	1	Room	1590	Wall	Midle Wall	Solid	Concrte	0.02
930	1971 Bldg.	240	XRF	4/1/97	1	Room	1590	Door	Door	Solid	Wood	0
931	1971 Bldg.	241	XRF	4/1/97	1	Room	1590	Door	Casing	Solid	Metal	0.01
932	1971 Bldg.	242	XRF	4/1/97	1	Room	1590	Window	Casing	Solid	Metal	0
933	1971 Bldg.	243	XRF	4/1/97	1	Room	1590	Wall	Midle Wall	Solid	Concrte	0.01
934	1971 Bldg.	244	XRF	4/1/97	1	Room	1590	Ceiling	Beam	Solid	Wood	0.13
935	1971 Bldg.	245	XRF	4/1/97	1	Room	1590	Ceiling	Beam	Solid	Wood	0
936	1971 Bldg.	273	XRF	4/1/97	1	Room	1600	Window	Casing	Solid	Metal	0

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
937	1971 Bldg.	274	XRF	4/1/97	1	Room	1600	Wall	Midle Wall	Solid	Concrete	0.01
938	1971 Bldg.	275	XRF	4/1/97	1	Room	1600		Radiator	Solid	Metal	0
939	1971 Bldg.	276	XRF	4/1/97	1	Room	1600	Wall	Midle Wall	Solid	Concrete	3.03
940	1971 Bldg.	277	XRF	4/1/97	1	Room	1600	Door	Door	Solid	Wood	0
941	1971 Bldg.	278	XRF	4/1/97	1	Room	1600	Door	Casing	Solid	Metal	0.02
942	1971 Bldg.	279	XRF	4/1/97	1	Room	1600	Ceiling	Beam	Solid	Wood	0.07
943	1971 Bldg.	280	XRF	4/1/97	1	Room	1600	Ceiling	Beam Bra	Solid	Metal	0
944	1971 Bldg.	177	XRF	4/2/97	1	Room	1610	Wall	Midle Wall	Solid	Concrete	0
945	1971 Bldg.	178	XRF	4/2/97	1	Room	1610	Door	Door	Solid	Wood	0
946	1971 Bldg.	179	XRF	4/2/97	1	Room	1610	Door	Casing	Solid	Metal	0.02
947	1971 Bldg.	180	XRF	4/2/97	1	Room	1610	Window	Casing	Solid	Metal	0
948	1971 Bldg.	181	XRF	4/2/97	1	Room	1610		Radiator	Solid	Metal	0.03
949	1971 Bldg.	182	XRF	4/2/97	1	Room	1610	Ceiling	Beam	Solid	Wood	0
950	1971 Bldg.	183	XRF	4/2/97	1	Room	1610	Ceiling	Beam Bra	Solid	Metal	0.03
951	1971 Bldg.	184	XRF	4/2/97	1	Room	1610	Ceiling	Beam	Solid	Wood	0.06
952	1971 Bldg.	185	XRF	4/2/97	1	Room	1610	Wall	Columns	Solid	Metal	0.04
953	1971 Bldg.	169	XRF	4/2/97	1	Room	1620	Window	Casing	Solid	Metal	0
954	1971 Bldg.	170	XRF	4/2/97	1	Room	1620	Door	Door	Solid	Wood	0
955	1971 Bldg.	171	XRF	4/2/97	1	Room	1620	Door	Casing	Solid	Metal	0.01
956	1971 Bldg.	172	XRF	4/2/97	1	Room	1620	Wall	Midle Wall	Solid	Concrete	0.01
957	1971 Bldg.	173	XRF	4/2/97	1	Room	1620		Radiator	Solid	Metal	0.02
958	1971 Bldg.	174	XRF	4/2/97	1	Room	1620	Ceiling	Beam	Solid	Wood	0.03
959	1971 Bldg.	175	XRF	4/2/97	1	Room	1620	Ceiling	Beam	Solid	Wood	0
960	1971 Bldg.	176	XRF	4/2/97	1	Room	1620	Ceiling	Beam Bra	Solid	Metal	0.07
961	1971 Bldg.	159	XRF	4/2/97	1	Room	1630	Wall	Columns	Solid	Metal	0.02
962	1971 Bldg.	160	XRF	4/2/97	1	Room	1630	Door	Door	Solid	Metal	0
963	1971 Bldg.	161	XRF	4/2/97	1	Room	1630	Door	Casing	Solid	Metal	0
964	1971 Bldg.	162	XRF	4/2/97	1	Room	1630		Radiator	Solid	Metal	0.07
965	1971 Bldg.	163	XRF	4/2/97	1	Room	1630	Window	Casing	Solid	Metal	0
966	1971 Bldg.	164	XRF	4/2/97	1	Room	1630	Ceiling	Beam	Solid	Wood	0.04
967	1971 Bldg.	165	XRF	4/2/97	1	Room	1630	Ceiling	Beam	Solid	Wood	0
968	1971 Bldg.	166	XRF	4/2/97	1	Room	1630	Ceiling	Beam Bra	Solid	Metal	0.05
969	1971 Bldg.	167	XRF	4/2/97	1	Room	1630	Door	Door	Solid	Wood	0
970	1971 Bldg.	168	XRF	4/2/97	1	Room	1630	Door	Casing	Solid	Metal	0.01
971	1971 Bldg.	116	XRF	4/2/97	1	Room	1650	Wall	Midle Wall	Solid	Concrete	0
972	1971 Bldg.	117	XRF	4/2/97	1	Room	1650	Door	Door	Solid	Wood	0
973	1971 Bldg.	118	XRF	4/2/97	1	Room	1650	Door	Casing	Solid	Metal	0.01
974	1971 Bldg.	119	XRF	4/2/97	1	Room	1650	Ceiling	Beam	Solid	Wood	0
975	1971 Bldg.	120	XRF	4/2/97	1	Room	1650	Ceiling	Beam Bra	Solid	Metal	0.03
976	1971 Bldg.	121	XRF	4/2/97	1	Room	1650	Ceiling	Beam	Solid	Wood	0.1
977	1971 Bldg.	122	XRF	4/2/97	1	Room	1650		Radiator	Solid	Metal	0.06
978	1971 Bldg.	123	XRF	4/2/97	1	Room	1650	Wall	Midle Wall	Solid	Concrete	0
979	1971 Bldg.	124	XRF	4/2/97	1	Room	1650	Wall	Columns	Solid	Metal	0.05
980	1971 Bldg.	125	XRF	4/2/97	1	Room	1660	Wall	Midle Wall	Solid	Concrete	0
981	1971 Bldg.	126	XRF	4/2/97	1	Room	1660	Wall	Chair rail	Solid	Wood	0
982	1971 Bldg.	127	XRF	4/2/97	1	Room	1660	Window	Casing	Solid	Metal	0.02
983	1971 Bldg.	128	XRF	4/2/97	1	Room	1660	Door	Door	Solid	Wood	0
984	1971 Bldg.	129	XRF	4/2/97	1	Room	1660	Door	Casing	Solid	Metal	0.02
985	1971 Bldg.	130	XRF	4/2/97	1	Room	1660	Ceiling	Beam	Solid	Wood	0.05
986	1971 Bldg.	131	XRF	4/2/97	1	Room	1660	Ceiling	Beam	Solid	Wood	0
987	1971 Bldg.	132	XRF	4/2/97	1	Room	1670	Wall	Midle Wall	Solid	Concrete	0
988	1971 Bldg.	133	XRF	4/2/97	1	Room	1670	Door	Door	Solid	Wood	0
989	1971 Bldg.	134	XRF	4/2/97	1	Room	1670	Door	Casing	Solid	Metal	0.02
990	1971 Bldg.	135	XRF	4/2/97	1	Room	1670	Wall	Wall Rgstr	Solid	Metal	0.03
991	1971 Bldg.	136	XRF	4/2/97	1	Room	1670	Coat Rack		Solid	Wood	0

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
992	1971 Bldg.	137	XRF	4/2/97	1	Room	1670	Ceiling	Beam	Solid	Wood	0.06
993	1971 Bldg.	138	XRF	4/2/97	1	Room	1670	Ceiling	Beam	Solid	Wood	0
994	1971 Bldg.	139	XRF	4/2/97	1	Room	1680	Wall	Midle Wall	Solid	Concrete	0.01
995	1971 Bldg.	140	XRF	4/2/97	1	Room	1680	Wall	Chair rail	Solid	Wood	0
996	1971 Bldg.	141	XRF	4/2/97	1	Room	1680	Window	Casing	Solid	Metal	0.03
997	1971 Bldg.	142	XRF	4/2/97	1	Room	1680	Door	Door	Solid	Wood	0
998	1971 Bldg.	143	XRF	4/2/97	1	Room	1680	Door	Casing	Solid	Metal	0.03
999	1971 Bldg.	144	XRF	4/2/97	1	Room	1680	Wall	Wall Rgstr	Solid	Metal	0
1000	1971 Bldg.	145	XRF	4/2/97	1	Room	1680	Ceiling	Beam	Solid	Wood	0.04
1001	1971 Bldg.	146	XRF	4/2/97	1	Room	1680	Ceiling	Beam	Solid	Wood	0
1002	1971 Bldg.	147	XRF	4/2/97	1	Room	1690	Wall	Midle Wall	Solid	Concrete	0
1003	1971 Bldg.	148	XRF	4/2/97	1	Room	1690	Window	Casing	Solid	Metal	0
1004	1971 Bldg.	149	XRF	4/2/97	1	Room	1690		Radiator	Solid	Metal	0
1005	1971 Bldg.	150	XRF	4/2/97	1	Room	1690	Door	Door	Solid	Metal	0
1006	1971 Bldg.	151	XRF	4/2/97	1	Room	1690	Door	Casing	Solid	Metal	0
1007	1971 Bldg.	152	XRF	4/2/97	1	Room	1690	Wall	Chair rail	Solid	Wood	0
1008	1971 Bldg.	153	XRF	4/2/97	1	Room	1690	Door	Door	Solid	Wood	0.01
1009	1971 Bldg.	154	XRF	4/2/97	1	Room	1690	Door	Casing	Solid	Metal	0.01
1010	1971 Bldg.	155	XRF	4/2/97	1	Room	1690	Ceiling	Beam	Solid	Wood	0
1011	1971 Bldg.	156	XRF	4/2/97	1	Room	1690	Ceiling	Beam Bra	Solid	Metal	0.17
1012	1971 Bldg.	157	XRF	4/2/97	1	Room	1690	Ceiling	Beam	Solid	Wood	0.07
1013	1971 Bldg.	158	XRF	4/2/97	1	Room	1690	Wall	Columns	Solid	Metal	0.07
1014	1971 Bldg.	110	XRF	4/2/97	1	Room	1701	Door	Door	Solid	Wood	0
1015	1971 Bldg.	111	XRF	4/2/97	1	Room	1701	Door	Casing	Solid	Metal	0.03
1016	1971 Bldg.	112	XRF	4/2/97	1	Room	1704	Door	Door	Solid	Wood	0
1017	1971 Bldg.	113	XRF	4/2/97	1	Room	1704	Door	Casing	Solid	Metal	0.01
1018	1971 Bldg.	114	XRF	4/2/97	1	Room	1704	Stairs	Tread	Peeling	Metal	0.02
1019	1971 Bldg.	115	XRF	4/2/97	1	Room	1704	Stairs	Hand rail	Solid	Metal	0.03
1020	1971 Bldg.	55	XRF	4/2/97	1	Room	1710	Door	Door	Solid	Metal	0.02
1021	1971 Bldg.	56	XRF	4/2/97	1	Room	1710	Door	Casing	Solid	Metal	0
1022	1971 Bldg.	57	XRF	4/2/97	1	Room	1710	Wall	Mural	Solid	Concrete	0.02
1023	1971 Bldg.	58	XRF	4/2/97	1	Room	1710	Wall	Mural	Solid	Concrete	0
1024	1971 Bldg.	59	XRF	4/2/97	1	Room	1710	Window	Casing	Solid	Metal	0
1025	1971 Bldg.	60	XRF	4/2/97	1	Room	1710		Radiator	Solid	Metal	0.01
1026	1971 Bldg.	61	XRF	4/2/97	1	Room	1710	Door	Door	Solid	Wood	0
1027	1971 Bldg.	62	XRF	4/2/97	1	Room	1710	Door	Casing	Solid	Metal	0.02
1028	1971 Bldg.	63	XRF	4/2/97	1	Room	1710	Wall	Chair rail	Solid	Wood	0
1029	1971 Bldg.	64	XRF	4/2/97	1	Room	1710	Wall	Midle Wall	Solid	Concrete	0
1030	1971 Bldg.	65	XRF	4/2/97	1	Room	1710	Wall	Midle Wall	Solid	Drywall	0.02
1031	1971 Bldg.	66	XRF	4/2/97	1	Room	1710	Ceiling	Beam	Solid	Wood	0
1032	1971 Bldg.	67	XRF	4/2/97	1	Room	1710	Ceiling	Beam Bra	Solid	Metal	0.04
1033	1971 Bldg.	68	XRF	4/2/97	1	Room	1710	Ceiling	Beam	Solid	Wood	0.09
1034	1971 Bldg.	69	XRF	4/2/97	1	Room	1710	Wall	Columns	Solid	Metal	0.08
1035	1971 Bldg.	70	XRF	4/2/97	1	Room	1713	Wall	Midle Wall	Solid	Concrete	0.03
1036	1971 Bldg.	71	XRF	4/2/97	1	Room	1713	Door	Door	Solid	Wood	0
1037	1971 Bldg.	72	XRF	4/2/97	1	Room	1713	Door	Casing	Solid	Metal	0.01
1038	1971 Bldg.	73	XRF	4/2/97	1	Room	1713	Wall	Wall	Solid	Wood	0
1039	1971 Bldg.	27	XRF	4/2/97	1	Room	1730		Radiator	Solid	Metal	0.02
1040	1971 Bldg.	28	XRF	4/2/97	1	Room	1730	Wall	Midle Wall	Solid	Concrete	0
1041	1971 Bldg.	29	XRF	4/2/97	1	Room	1730	Window	Casing	Solid	Metal	0
1042	1971 Bldg.	30	XRF	4/2/97	1	Room	1730	Wall	Columns	Solid	Metal	0.03
1043	1971 Bldg.	31	XRF	4/2/97	1	Room	1730	Door	Door	Solid	Metal	0
1044	1971 Bldg.	32	XRF	4/2/97	1	Room	1730	Door	Casing	Solid	Metal	0.11
1045	1971 Bldg.	33	XRF	4/2/97	1	Room	1730	Wall	Midle Wall	Solid	Concrete	0
1046	1971 Bldg.	34	XRF	4/2/97	1	Room	1730	Wall	Midle Wall	Solid	Drywall	0

Saint Paul Public Schools  
 East Consolidated  
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Structure	Feature	Condition	Substrate	Result
1047	1971 Bldg.	35	XRF	4/2/97	1	Room	1730	Ceiling	Beam	Solid	Wood	0.06
1048	1971 Bldg.	36	XRF	4/2/97	1	Room	1730	Ceiling	Beam	Solid	Wood	0
1049	1971 Bldg.	37	XRF	4/2/97	1	Room	1730	Ceiling	Beam Bra	Solid	Metal	0.05

## **APPENDIX B**

### **LABORATORY SAMPLE ANALYSIS DATA**

**LABORATORY ANALYSIS REPORT****DATE:** April 21, 1997**PAGE:**

1 Of 3

**CLIENT:** Midwest Environmental Cons.  
5385 401st Ave. NW  
Dalbo, MN 55017

**PROJECT NO.:** 040797-200888  
**COLLECTION DATE:** 4/03/97  
**COLLECTED BY:** Client  
**RECEIVED DATE:** 4/07/97  
**PROJECT DESCRIPT.:** 62/0197T

**CONTACT:** Richard Cox

<u>ANALYSIS</u>		<u>Sample No.:</u>	L971869-1	<u>ANALYSIS</u>
		<u>Sample ID.:</u>	PC 1	
<u>UNITS</u>		<u>MDL</u>	<u>RESULT</u>	<u>DATE</u>
<u>ANALYSIS</u>				
Lead (6010A)	mg/kg	46	ND	4/21/97
<u>ANALYSIS</u>				
Lead (6010A)	mg/kg	200	ND	4/21/97
<u>ANALYSIS</u>				
Lead (6010A)	mg/kg	48	210	4/21/97
<u>ANALYSIS</u>				
Lead (6010A)	mg/kg	39	ND	4/21/97
<u>ANALYSIS</u>				
Lead (6010A)	mg/kg	27	ND	4/21/97
<u>ANALYSIS</u>				
Lead (6010A)	mg/kg	56	ND	4/21/97
<u>ANALYSIS</u>				
Lead (6010A)	mg/kg	80	1400	4/21/97

*As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.*

A member of The Marmon Group of Companies

**LABORATORY ANALYSIS REPORT****DATE:** April 21, 1997**PAGE:** 2 Of 3

**CLIENT:** Midwest Environmental Cons.  
5385 401st Ave. NW  
Dalbo, MN 55017

**PROJECT NO.:** 040797-200888  
**COLLECTION DATE:** 4/03/97  
**COLLECTED BY:** Client  
**RECEIVED DATE:** 4/07/97  
**PROJECT DESCRP.:** 62/0197T

**CONTACT:** Richard Cox

<u>ANALYSIS</u>		<u>Sample No.:</u>	L971869-8	<u>ANALYSIS</u>
		<u>Sample ID.:</u>	PC 8	
<u>UNITS</u>		<u>MDL</u>	<u>RESULT</u>	<u>DATE</u>
<u>ANALYSIS</u> Lead (6010A)	mg/kg	97	2800	4/21/97
<u>ANALYSIS</u> Lead (6010A)	mg/kg	190	280	4/18/97
<u>ANALYSIS</u> Lead (6010A)	mg/kg	19	21	4/18/97
<u>ANALYSIS</u> Lead (6010A)	ug/ft <sup>2</sup>	5.0	ND	4/18/97
<u>ANALYSIS</u> Lead (6010A)	ug/ft <sup>2</sup>	5.0	20	4/18/97
<u>ANALYSIS</u> Lead (6010A)	ug/ft <sup>2</sup>	5.0	ND	4/18/97
<u>ANALYSIS</u> Lead (7300)	mg	0.004	ND	4/18/97

*ND means Not Detected or below reported MDL*

*MDL means Method Detection Limit*

*mg/kg means Milligrams Per Kilogram which is equivalent to Parts Per Million (ppm)*

*As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.*



A member of The Marmon Group of Companies

**LABORATORY ANALYSIS REPORT**

<b>DATE:</b>	<i>April 21, 1997</i>	<b>PAGE:</b>	<i>3 Of 3</i>
<b>CLIENT:</b>	<i>Midwest Environmental Cons. 5385 401st Ave. NW Dalbo, MN 55017</i>	<b>PROJECT NO.:</b>	<i>040797-200888</i>
		<b>COLLECTION DATE:</b>	<i>4/03/97</i>
		<b>COLLECTED BY:</b>	<i>Client</i>
		<b>RECEIVED DATE:</b>	<i>4/07/97</i>
		<b>PROJECT DESCRIPT.:</b>	<i>62/0197T</i>
<b>CONTACT:</b>	<i>Richard Cox</i>		

*This report has been reviewed by me for technical accuracy and completeness. The analyses were performed using EPA or other approved methodologies and the results were reported on an "as received" basis unless otherwise noted. Organic soil analyses were reported on a dry weight basis. The results reported relate only to the items tested. Please contact me if you have any questions or comments regarding this report. Spectrum Labs, Inc. appreciates the opportunity to provide this analytical service for you.*

*Report Submitted By,*

*Thomas L. Halverson  
Laboratory Manager*

*TLH:wmc  
mec111-1*

*As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.*



A member of The Marmon Group of Companies



### Midwest Environmental Consulting, L.L.C.

5385 401st Ave. NW, Dalbo, MN 55017  
612-689-3612/612-757-5541/FAX-612-689-5209

Client Address 405 Case Ave

Contact \_\_\_\_\_

### CHAIN OF CUSTODY RECORD

Project Number 62-0197 T  
Client S.  
Project Pb Inspection  
Phone/Fax \_\_\_\_\_

Sample ID	Sample Description	Collection Date/Time	Matrix (Vol/Area)	Analysis Requested
PC 1	Kitchen - wood Beam-white	4/2/97 5:50pm	1 sq inch	Lead in ppm
PC 2	U - metal door casing	.. 5:60pm	1 sq inch	Lead in ppm
PC 3	U - wood Beam white	.. 6:00pm	1 sq inch	Lead in ppm
PC 4	Rm 1251 - metal - door - white	.. 6:05pm	1 sq inch	Lead in ppm
PC 5	Rm 1220 - doorway - metal - white	.. 6:20pm	1 sq inch	Lead in ppm
PC 6	Rm 1261 - wood + door - Brown	.. 6:25pm	1 sq inch	Lead in ppm
PC 7	Rm 1280A - metal - Beam - Black	.. 6:30pm	1 sq inch	Lead in ppm
PC 8	Rm 1274 - wood - Beam - Grey	.. 6:45pm	1 sq inch	Lead in ppm
V 9	Rm 1274 - metal - white	.. 7:05pm	1 sq ft	(spine 5) Lead in ppm
V 10	Rm 1270 - metal - white	.. 7:30pm	1 sq ft	Lead in ppm
W 11	Rm 1170 - white - floor	.. 7:45pm	1 sq ft	Lead mg / ft <sup>2</sup>
W 12	Rm 1270 - white - floor	.. 8:00pm	" "	Lead mg / ft <sup>2</sup>
W 13	Blank white			Lead mg / ft <sup>2</sup>
W 14	vac Blank			Lead off ppm

Sampled By: D. Thompson Date: 4-3-97 Time: \_\_\_\_\_

Received By: John O. R. Date: 4/7/97 Time: \_\_\_\_\_

Received By Lab: Midwest Enviro Date: 4/7/97 Time: 11:30am Disposition of Samples \_\_\_\_\_

Notes:

Delivered By: John O. R. Date: 9/6/07 Time: 11:30 am

Delivered By: John O. R. Date: \_\_\_\_\_ Time: \_\_\_\_\_

## **APPENDIX C**

## **INSPECTOR**

**Bob Hargrove**  
**MDH Lead Inspector # 416**