


Midwest
Environmental
Consulting, L.L.C.



Printed on Recycled Paper

**Chelsea Heights Elementary School
Saint Paul Public Schools**

Lead-Based Paint Inspection

**Inspection Dates: 2/5/97, 2/6/97, 2/12/97, 2/13/97, 2/14/97, 2/15/97,
2/16/97, 2/20/97, 5/18/98, 5/19/98**

submitted to:

Saint Paul Public Schools

MEC Project # 62/0197E

INTRODUCTION

At the request of Saint Paul Public Schools Environmental Safety Department, Midwest Environmental Consulting, L.L.C. (MEC), conducted a lead-based paint inspection at Chelsea Heights Elementary School, 1557 Huron Street, St. Paul, MN. The purpose of this inspection was to identify lead-based painted, varnished, or otherwise coated building components on the interior and exterior of the school building.

The inspection protocol incorporated applicable portions of the U.S. Department of Housing and Urban Development (HUD) *Guidelines for the Evaluation and Control of Lead-based Paint Hazards in Housing* (HUD Guidelines, June 1995) and OSHA 1926.62 requirements (Lead in Construction). The HUD guidelines are formulated to guide agencies in conducting random sampling of the interiors and exteriors of dwellings and common areas in public housing. The OSHA requirement is designed to minimize worker exposure when working with material containing lead.

Confirmatory testing was conducted when inconclusive XRF results were encountered. Inconclusive refers to XRF readings less than 0.2 mg/cm² (milligrams per square centimeter). Inconclusive results were confirmed with laboratory analysis of paint chip samples (Appendix B). This report contains a list of such results.

The United States Environmental Protection Agency defines "lead-based paint" as a paint or other surface coating that contains lead equal to or in excess of 1.0 milligrams per square centimeter when analyzed by XRF or more than 0.5% by weight (5000 parts per million) by laboratory analysis of a bulk sample.

Minnesota Department of Labor and Industry (MN OSHA) adopted the EPA lead levels for the purpose of enforcing OSHA 1926.62 federal regulations. Detection of lead in dried paint film by XRF is a dependable indicator of levels of lead and is accepted by MN OSHA.

For this Saint Paul Public Schools Lead Inspection, all building components were tested on site using a Niton XL® X-ray Fluorescence Spectrum Analyzer⁽¹⁾. Building components included walls, ceilings, floors, moldings, window and door components, door surfaces, and miscellaneous features such as shelves or bookcases. Only painted or glazed surfaces or surfaces which were varnished were tested. Suspended ceilings, structural steel, and corrugated decking were not included in the inspection. Neither anodized (e.g., window sashes) nor plastic (e.g., vinyl baseboard and vinyl mini-blinds) were included in the scope of this inspection.

⁽¹⁾ This is a portable hand held machine that can analyze building components instantly for lead concentrations.

Each building was divided into unique sites based on the year of construction or renovation. Portable classrooms, playgrounds, and other detached buildings were automatically designated as a unique site. Each site was inspected independently assuming differences in painting history and construction characteristics.

SITE DESCRIPTION AND BUILDING HISTORY

According to information provided to MEC by Saint Paul Public Schools, Chelsea Heights Elementary was constructed in essentially four phases. The initial phase includes the 11,013 square-foot older section of the building and dates from 1932. The second phase is a 9,113 square foot addition dating from 1939. The third phase is a 20,537 square foot addition from 1953. The fourth addition is 27,275 square feet dating from 1974.

The 1932 building and the 1939 addition are considered to be site 1 for the purpose of this inspection.

All room and area designations used in this report are depicted on sampling maps found in Appendix A.

XRF SAMPLE RESULTS TABLE

The results of all samples analyzed are listed in the table at the end of this section. The following is a description of the column headings:

Site	Each school is divided into sites based on their unique construction characteristics. Each site has a unique date of construction or major renovation.
Sample #	Each sample taken was given a unique number to identify the type and location of the sample. The sampling date is an integral part of the sample number.
Analysis	This defines the type of analysis which can be categorized into two types: 1) XRF: This is an on-site analysis using a hand held Niton XL® X-ray Fluorescence Spectrum Analyzer; 2) Bulk or Chip: This is a bulk sample where paint is removed from the substrate and sent to a laboratory for analysis;
Floor	This is the level of the building in which the area tested was found, example, 1 (first floor), 0 (basement), etc.

Area	This further defines the specific functional space inspected such as a classroom, exterior, playground, gym, kitchen, etc.
Room #	This is typically the actual number on the room as identified at the building.
Component	Building "components" included walls, ceilings, floors, moldings, window and door components, door surfaces, and miscellaneous features such as shelves or bookcases.
Feature	Identifies more detailed information of the component.
Condition	This describes condition of the surface, whether it is intact, cracked, peeling, or chalking.
Substrate	This refers to the material the building component is made of (wood, concrete, drywall, metal, etc.).
Result	This is the analysis results for lead. Less than 1.0 mg/cm ² or less than 0.5% by weight is considered to be non-lead and these building components are below the action levels of EPA and HUD. (All results are in mg/cm ² except where noted.)

The table of results is designed for quick information on lead concentrations of tested building components. Generally, all repetitions of a test combination within a given room or area, may be assumed to contain similar concentrations of lead to that of the tested sample. For instance, the lead concentration of a tested wooden window sash was found to be above the action level of 1.0 mg/cm² in a given classroom. The classroom has five windows, all of wood, the same color and appearing to be of the same era. It can be assumed that the remaining four wooden window sashes each contain lead above the action limit.

Other columns identify the component and the component feature tested, condition of the component, type of substrate and the result of the analytical test.

As an example, the following illustration shows that the wooden door jamb in Room 123, first floor in the 1923 building section was in good, solid condition, and had an XRF test result of 0.3 mg/cm², which is below the action level.

Illustration Only

Site	Sample #	Date	Analysis	Floor	Area	Room #	Component	Feature	Condition	Substrate	Results
1923 Bldg.	52		XRF	1	Room	123	Door	Jamb	Solid	Wood	0.3

In a similar manner, the table shows that the plaster walls in room 23, on the second floor has peeling paint with more than 1.0 mg/cm² (shaded).

ILLUSTRATION ONLY

Site	Sample #	Date	Analysis	Floor	Area	Room #	Component	Feature	Condition	Substrate	Results
1910 Bldg.	16		XRF	2	Room	23	Door	Jamb	Peeling	Wood	0.25
1910 Bldg.	17		XRF	2	Room	23	Wall	Wall	Peeling	Plaster	0.2
1910 Bldg.	18		XRF	2	Room	23		Ceiling	Peeling	Plaster	0.25
1910 Bldg.	19		XRF	2	Room	23	Wall	Baseboard	Peeling	Wood	0.002

APPLICABLE REGULATIONS

When building components test above 1.0 mg/cm² of lead by XRF or 0.5% lead by weight from laboratory analysis all employees and contractors who will be working with these components in a construction related activity must be notified. The requirements of OSHA 1926.62, Lead in Construction are enforceable. This regulation defines construction work as "work for construction, alteration and/or repair, including painting and decorating." This regulation further defines monitoring requirements to minimize employee exposure to lead during construction activities.

When work is performed on external painted building structures (i.e. flashing, fire escapes, playground equipment, handrails, etc.), regulations of the Minnesota Pollution Control Agency (MPCA) may also be applicable. For removal of lead based paint from steel structures, MN Rules 7025.0200 - 7025.0380 apply to steel materials on the exterior of a building, or on the property when levels exceed 0.5 mg/cm² based on the average of three XRF spectrum results of the sample tested, or 5,000 ppm by laboratory analysis. If it is other than a steel surface, then MPCA regulates the painted surfaces under MN Rules 7025.010 - 7025.0080, when surfaces are to be disturbed using abrasive blasting methods.

Please contact MEC directly if you have questions about any portion of this report or the lead-based paint inspection itself.


APPENDIX A

XRF TESTING DATA

WITH

LOCATION MAPS

SSL - CHG
100




5


CONSTRUCTED: 1922. \$3.73


A white rectangular label with black text, partially visible on the left edge. The text reads:

CHELSEA HEIGHTS ELEMENTARY SCHOOL
1557 HURON ST
ST. PAUL, MN 55108


INDUSTRIAL SCHOOL DIST. #62
380 COLBORNE STREET
ST. PAUL, MINNESOTA 55102








卷之三



卷之三



CONSTRUCTED: 1932. \$3,73

CHELSEA HERRICKS ELEM
1557 MURON ST
ST PAUL, MN 55106

INDIANAPOLIS SCHOOL DIST. #625
360 COLBORNE STREET
ST. PAUL, MINNESOTA 55102

SECOND FLOOR PLAN


卷之三

CONSTRUCTED: 1932, 53, 73

CHAPLEAU-THEATRE'S ELEM.

1557 HURON ST.
NEW YORK 10021

INDEPENDENT SCHOOL DIST. #625



It's not get into

203
205

for ceiling samples

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

A	B	C	D	E	F	G	H	I	J	K	L	
1	Chelsea Heights Elementary School											
2												
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result
4	1932 & 1939 Bldgs.	68	XRF	2/5/97	1	Bath		1 Wall	Wall	Solid	Plaster	0.09
5	1932 & 1939 Bldgs.	69	XRF	2/5/97	1	Bath		1 Wall	Wall	Solid	Plaster	0.02
6	1932 & 1939 Bldgs.	70	XRF	2/5/97	1	Bath		1 Door	Door	Solid	Wood	0.02
7	1932 & 1939 Bldgs.	71	XRF	2/5/97	1	Bath		1 Door	Casing	Solid	Wood	0.04
8	1932 & 1939 Bldgs.	85	XRF	2/5/97	1	Bath		2 Wall	Wall	Solid	Plaster	0.09
9	1932 & 1939 Bldgs.	86	XRF	2/5/97	1	Bath		2 Wall	Wall	Solid	Plaster	0.13
10	1932 & 1939 Bldgs.	87	XRF	2/5/97	1	Bath		2 Door	Door	Solid	Wood	0.03
11	1932 & 1939 Bldgs.	88	XRF	2/5/97	1	Bath		2 Door	Casing	Solid	Wood	0.06
12	1932 & 1939 Bldgs.	143	XRF	2/5/97	1	Bath		3 Wall	Wall	Solid	Plaster	0.11
13	1932 & 1939 Bldgs.	144	XRF	2/5/97	1	Bath		3 Wall	Wall	Solid	Plaster	0.1
14	1932 & 1939 Bldgs.	145	XRF	2/5/97	1	Bath		3 Wall	Chair rail	Solid	Metal	0.27
15	1932 & 1939 Bldgs.	146	XRF	2/5/97	1	Bath		3 Door	Casing	Solid	Wood	0.03
16	1932 & 1939 Bldgs.	147	XRF	2/5/97	1	Bath		3 Stall	Door	Solid	Metal	0.02
17	1932 & 1939 Bldgs.	148	XRF	2/5/97	1	Bath		3 Stall	Door	Solid	Wood	0.01
18	1932 & 1939 Bldgs.	149	XRF	2/5/97	1	Bath		3 Bath	Stall	Solid	Wood	0.06
19	1932 & 1939 Bldgs.	150	XRF	2/5/97	1	Bath		3 Bath	Stall	Solid	Wood	0.06
20	1932 & 1939 Bldgs.	151	XRF	2/5/97	1	Bath		3 Wall	Wall Rgstr	Solid	Metal	0.12
21	1932 & 1939 Bldgs.	300	XRF	2/16/97	1	Bath		3 Ceiling		Solid	Plaster	0.24
22	1932 & 1939 Bldgs.	301	XRF	2/16/97	1	Bath		3 Wall	Wall Rgstr	Solid	Metal	0.06
23	1932 & 1939 Bldgs.	180	XRF	2/6/97	1	Bath		4 Wall	Wall	Solid	Plaster	0.08
24	1932 & 1939 Bldgs.	181	XRF	2/6/97	1	Bath		4 Wall	Wall	Solid	Plaster	0.1
25	1932 & 1939 Bldgs.	182	XRF	2/6/97	1	Bath		4 Wall	Midle Wall	Solid	Drywall	0.02
26	1932 & 1939 Bldgs.	183	XRF	2/6/97	1	Bath		4 Ceiling		Solid	Drywall	0
27	1932 & 1939 Bldgs.	305	XRF	2/6/97	2	Bath		5 Wall	Wall	Solid	Plaster	0.2
28	1932 & 1939 Bldgs.	306	XRF	2/6/97	2	Bath		5 Wall	Wall	Solid	Plaster	0.35
29	1932 & 1939 Bldgs.	307	XRF	2/6/97	2	Bath		5 Wall	Midle Wall	Solid	Plaster	0.33
30	1932 & 1939 Bldgs.	308	XRF	2/6/97	2	Bath		5 Wall	Wall Rgstr	Solid	Metal	0.23
31	1932 & 1939 Bldgs.	309	XRF	2/6/97	2	Bath		5 Door	Door	Solid	Wood	0.04
32	1932 & 1939 Bldgs.	310	XRF	2/6/97	2	Bath		5 Door	Casing	Solid	Wood	0.05
33	1932 & 1939 Bldgs.	346	XRF	2/6/97	2	Bath		6 Wall	Wall	Solid	Plaster	0.34
34	1932 & 1939 Bldgs.	347	XRF	2/6/97	2	Bath		6 Wall	Wall	Solid	Plaster	0.28
35	1932 & 1939 Bldgs.	348	XRF	2/6/97	2	Bath		6 Wall	Midle Wall	Solid	Plaster	0.29
36	1932 & 1939 Bldgs.	349	XRF	2/6/97	2	Bath		6 Wall	Midle Wall	Solid	Plaster	0.23
37	1932 & 1939 Bldgs.	351	XRF	2/6/97	2	Bath		6 Door	Casing	Solid	Wood	0.05
38	1932 & 1939 Bldgs.	352	XRF	2/6/97	2	Bath		6 Door	Door	Solid	Wood	0.04
39	1932 & 1939 Bldgs.	353	XRF	2/6/97	2	Bath		6 Window	Stops	Solid	Wood	0.1
40	1932 & 1939 Bldgs.	354	XRF	2/6/97	2	Bath		6	Radiator	Cracked	Metal	0
41	1932 & 1939 Bldgs.	355	XRF	2/6/97	2	Bath		6 Floor		Cracked	Concrte	0.04
42	1932 & 1939 Bldgs.	305	XRF	2/16/97	2	Bath		6 Ceiling		Solid	Plaster	0.36
43	1932 & 1939 Bldgs.	306	XRF	2/16/97	2	Bath		6 Wall	Wall Rgstr	Solid	Metal	0.03
44	1932 & 1939 Bldgs.	356	XRF	2/6/97	2	Bath		7 Wall	Wall	Cracked	Concrte	0.15
45	1932 & 1939 Bldgs.	357	XRF	2/6/97	2	Bath		7 Wall	Wall	Solid	Plaster	0.17
46	1932 & 1939 Bldgs.	358	XRF	2/6/97	2	Bath		7 Wall	Midle Wall	Solid	Plaster	0.08
47	1932 & 1939 Bldgs.	359	XRF	2/6/97	2	Bath		7 Wall	Midle Wall	Solid	Plaster	0.1
48	1932 & 1939 Bldgs.	360	XRF	2/6/97	2	Bath		7 Wall	Chair rail	Solid	Metal	5.09
49	1932 & 1939 Bldgs.	6	XRF	2/12/97	2	Bath		7 Stall	Partition	Solid	Wood	0.03
50	1932 & 1939 Bldgs.	7	XRF	2/12/97	2	Bath		7 Window	Casing	Solid	Wood	0.04
51	1932 & 1939 Bldgs.	8	XRF	2/12/97	2	Bath		7 Window	Panel	Solid	Metal	1.82
52	1932 & 1939 Bldgs.	9	XRF	2/12/97	2	Bath		7 Door	Door	Solid	Wood	0.02
53	1932 & 1939 Bldgs.	10	XRF	2/12/97	2	Bath		7 Door	Casing	Solid	Wood	0.02
54	1932 & 1939 Bldgs.	11	XRF	2/12/97	2	Bath		7	Radiator	Cracked	Metal	0.2
55	1932 & 1939 Bldgs.	307	XRF	2/16/97	2	Bath		7 Wall	Wall Rgstr	Solid	Metal	0.1
56	1932 & 1939 Bldgs.	308	XRF	2/16/97	2	Bath		7 Ceiling		Solid	Plaster	0.58
57	1932 & 1939 Bldgs.	12	XRF	2/12/97	2	Bath		8 Wall	Wall	Solid	Plaster	0.21
58	1932 & 1939 Bldgs.	13	XRF	2/12/97	2	Bath		8 Wall	Wall	Solid	Plaster	0.14
59	1932 & 1939 Bldgs.	14	XRF	2/12/97	2	Bath		8 Door	Door	Solid	Wood	0.02
60	1932 & 1939 Bldgs.	15	XRF	2/12/97	2	Bath		8 Door	Casing	Solid	Wood	0.03
61	1932 & 1939 Bldgs.	6	XRF	2/5/97	1	Hall		1 Wall	Wall	Solid	Plaster	0.1
62	1932 & 1939 Bldgs.	7	XRF	2/5/97	1	Hall		1 Wall	Midle Wall	Solid	Metal	0.23
63	1932 & 1939 Bldgs.	8	XRF	2/5/97	1	Hall		1 Wall	Wall	Solid	Plaster	0.2
64	1932 & 1939 Bldgs.	9	XRF	2/5/97	1	Hall		1 Door	Door	Solid	Metal	0.26

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L	
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result	
65	1932 & 1939 Bldgs.	10	XRF	2/5/97	1	Hall		1	Door	Jamb	Metal	5.09	
66	1932 & 1939 Bldgs.	11	XRF	2/5/97	1	Hall		1	Door	Casing	Wood	0.04	
67	1932 & 1939 Bldgs.	12	XRF	2/5/97	1	Hall	1		Locker	Solid	Metal	0.09	
68	1932 & 1939 Bldgs.	13	XRF	2/5/97	1	Hall		1	Wall	Wall Rgstr	Solid	0.01	
69	1932 & 1939 Bldgs.	14	XRF	2/5/97	1	Hall		1	Elec Pane	Solid	Metal	0.01	
70	1932 & 1939 Bldgs.	15	XRF	2/5/97	1	Hall	1		Elec Pane	Solid	Metal	0.01	
71	1932 & 1939 Bldgs.	16	XRF	2/5/97	1	Hall		1	Door	Door	Wood	0.06	
72	1932 & 1939 Bldgs.	17	XRF	2/5/97	1	Hall		1	Door	Casing	Wood	0.05	
73	1932 & 1939 Bldgs.	18	XRF	2/5/97	1	Hall		1	Bulletin B	Trim	Wood	0.07	
74	1932 & 1939 Bldgs.	19	XRF	2/5/97	1	Hall	1		Locker	Solid	Metal	0.1	
75	1932 & 1939 Bldgs.	20	XRF	2/5/97	1	Hall		1	Wall	Midle Wall	Cracked	Plaster	0.69
76	1932 & 1939 Bldgs.	21	XRF	2/5/97	1	Hall		1	Closet	Wall	Solid	Wood	0
77	1932 & 1939 Bldgs.	22	XRF	2/5/97	1	Hall		1	Wall	Wall	Solid	Plaster	0.45
78	1932 & 1939 Bldgs.	152	XRF	2/5/97	1	Hall		1	Closet	Wall	Solid	Plaster	0.09
79	1932 & 1939 Bldgs.	153	XRF	2/5/97	1	Hall		1	Closet	Wall	Solid	Plaster	0.1
80	1932 & 1939 Bldgs.	154	XRF	2/5/97	1	Hall		1	Door	Casing	Solid	Wood	0.03
81	1932 & 1939 Bldgs.	155	XRF	2/5/97	1	Hall		1	Door	Casing	Solid	Wood	0.05
82	1932 & 1939 Bldgs.	156	XRF	2/5/97	1	Hall		1	Closet	Shelf	Solid	Wood	0.02
83	1932 & 1939 Bldgs.	157	XRF	2/5/97	1	Hall		1	Ceiling		Solid	Plaster	0.14
84	1932 & 1939 Bldgs.	271	XRF	2/16/97	1	Hall		1	Ceiling		Solid	Plaster	0.11
85	1932 & 1939 Bldgs.	302	XRF	2/16/97	2	Hall		1	Door	Crown mo	Solid	Wood	0.02
86	1932 & 1939 Bldgs.	222	XRF	2/6/97	2	Hall		2	Wall	Wall	Solid	Plaster	0.13
87	1932 & 1939 Bldgs.	223	XRF	2/6/97	2	Hall		2	Wall	Wall	Solid	Plaster	0.07
88	1932 & 1939 Bldgs.	224	XRF	2/6/97	2	Hall		2	Wall	Wall	Solid	Plaster	0.05
89	1932 & 1939 Bldgs.	225	XRF	2/6/97	2	Hall		2	Wall	Chair rail	Solid	Metal	0.2
90	1932 & 1939 Bldgs.	226	XRF	2/6/97	2	Hall		2	Door	Door	Solid	Metal	0.22
91	1932 & 1939 Bldgs.	227	XRF	2/6/97	2	Hall		2	Door	Jamb	Solid	Metal	5.09
92	1932 & 1939 Bldgs.	228	XRF	2/6/97	2	Hall		2	Door	Casing	Solid	Wood	0.08
93	1932 & 1939 Bldgs.	229	XRF	2/6/97	2	Hall		2	Door	Door	Solid	Wood	0.02
94	1932 & 1939 Bldgs.	230	XRF	2/6/97	2	Hall		2	Door	Casing	Solid	Wood	0.04
95	1932 & 1939 Bldgs.	231	XRF	2/6/97	2	Hall		2	Bulletin B	Trim	Solid	Wood	0.06
96	1932 & 1939 Bldgs.	232	XRF	2/6/97	2	Hall		2		Locker	Solid	Metal	0.1
97	1932 & 1939 Bldgs.	233	XRF	2/6/97	2	Hall		2		Elec Pane	Solid	Metal	0.01
98	1932 & 1939 Bldgs.	234	XRF	2/6/97	2	Hall		2	Cabinet	Inside	Solid	Metal	0
99	1932 & 1939 Bldgs.	235	XRF	2/6/97	2	Hall		2	Cabinet	Door	Solid	Metal	0.09
100	1932 & 1939 Bldgs.	236	XRF	2/6/97	2	Hall		2	Wall	Wall Rgstr	Solid	Metal	0.16
101	1932 & 1939 Bldgs.	237	XRF	2/6/97	2	Hall		2		Elec Pane	Solid	Metal	0
102	1932 & 1939 Bldgs.	238	XRF	2/6/97	2	Hall		2	Wire	Tray	Solid	Metal	0.1
103	1932 & 1939 Bldgs.	239	XRF	2/6/97	2	Hall		2	Cabinet	Door	Solid	Metal	0.07
104	1932 & 1939 Bldgs.	303	XRF	2/16/97	2	Hall		2	Wall	Wall Rgstr	Solid	Metal	0.11
105	1932 & 1939 Bldgs.	304	XRF	2/16/97	2	Hall		2	Ceiling		Solid	Plaster	0.02
106	1932 & 1939 Bldgs.	183	XRF	2/20/97	1	Outside		0	Door	Door	Solid	Wood	2.32
107	1932 & 1939 Bldgs.	184	XRF	2/20/97	1	Outside		0	Door	Jamb	Solid	Wood	1.83
108	1932 & 1939 Bldgs.	185	XRF	2/20/97	1	Outside		0	Window	Sash	Solid	Wood	5.09
109	1932 & 1939 Bldgs.	186	XRF	2/20/97	1	Outside		0	Ext Wall	Bulkhead	Peeling	Metal	0.07
110	1932 & 1939 Bldgs.	187	XRF	2/20/97	1	Outside		0	Flag	Pole	Peeling	Metal	4.01
111	1932 & 1939 Bldgs.	188	XRF	2/20/97	1	Outside		0	Fence	Pipe	Solid	Metal	5.09
112	1932 & 1939 Bldgs.	189	XRF	2/20/97	1	Outside		0	Wall	Wall Rgstr	Solid	Metal	0.05
113	1932 & 1939 Bldgs.	190	XRF	2/20/97	1	Outside		0	Window	Sash	Solid	Wood	0
114	1932 & 1939 Bldgs.	36	XRF	2/12/97	0	Room		1	Wall	Wall	Solid	Plaster	0.07
115	1932 & 1939 Bldgs.	37	XRF	2/12/97	0	Room		1	Wall	Midle Wall	Solid	Wood	0.04
116	1932 & 1939 Bldgs.	38	XRF	2/12/97	0	Room		1	Wall	Wall	Solid	Plaster	0.09
117	1932 & 1939 Bldgs.	39	XRF	2/12/97	0	Room		1	Door	Door	Solid	Wood	0.05
118	1932 & 1939 Bldgs.	40	XRF	2/12/97	0	Room		1	Door	Casing	Solid	Wood	0
119	1932 & 1939 Bldgs.	41	XRF	2/12/97	0	Room		1	Window	Stool	Solid	Wood	0.11
120	1932 & 1939 Bldgs.	42	XRF	2/12/97	0	Room		1	Door	Door	Solid	Wood	0.02
121	1932 & 1939 Bldgs.	43	XRF	2/12/97	0	Room		1	Door	Casing	Solid	Wood	0.01
122	1932 & 1939 Bldgs.	44	XRF	2/12/97	0	Room		1	Wall	Wall Rgstr	Solid	Metal	0.23
123	1932 & 1939 Bldgs.	45	XRF	2/12/97	0	Room		1	Cabinet	Door	Solid	Wood	0
124	1932 & 1939 Bldgs.	46	XRF	2/12/97	0	Room		1	Cabinet	Shelf	Solid	Wood	0
125	1932 & 1939 Bldgs.	47	XRF	2/12/97	0	Room		1	Window	Panel	Solid	Metal	1.6
126	1932 & 1939 Bldgs.	48	XRF	2/12/97	0	Room		1	Window	Mullion	Solid	Wood	0.07
127	1932 & 1939 Bldgs.	58	XRF	2/5/97	1	Room		1	Wall	Wall	Solid	Plaster	0.3

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result
128	1932 & 1939 Bldgs.	59	XRF	2/5/97	1	Room	1	Wall	Chair rail	Solid	Metal	5.09
129	1932 & 1939 Bldgs.	60	XRF	2/5/97	1	Room	1	Wall	Wall	Solid	Plaster	0.18
130	1932 & 1939 Bldgs.	61	XRF	2/5/97	1	Room	1	Door	Door	Solid	Wood	0.02
131	1932 & 1939 Bldgs.	62	XRF	2/5/97	1	Room	1	Door	Casing	Solid	Wood	0.03
132	1932 & 1939 Bldgs.	63	XRF	2/5/97	1	Room	1	Bulletin B	Trim	Solid	Wood	0
133	1932 & 1939 Bldgs.	64	XRF	2/5/97	1	Room	1	Cabinet	Outside	Solid	Wood	0.06
134	1932 & 1939 Bldgs.	65	XRF	2/5/97	1	Room	1	Window	Stool	Solid	Wood	0.07
135	1932 & 1939 Bldgs.	66	XRF	2/5/97	1	Room	1		Radiator	Solid	Metal	0.01
136	1932 & 1939 Bldgs.	67	XRF	2/5/97	1	Room	1	Wire	Tray	Solid	Metal	0
137	1932 & 1939 Bldgs.	28	XRF	2/12/97	3	Room	1	Wall	Wall	Solid	Plaster	0.14
138	1932 & 1939 Bldgs.	29	XRF	2/12/97	3	Room	1	Wall	Wall	Solid	Plaster	0.11
139	1932 & 1939 Bldgs.	30	XRF	2/12/97	3	Room	1	Door	Door	Solid	Wood	0.02
140	1932 & 1939 Bldgs.	31	XRF	2/12/97	3	Room	1	Door	Casing	Solid	Wood	0.04
141	1932 & 1939 Bldgs.	32	XRF	2/12/97	3	Room	1	Window	Stool	Solid	Wood	0.12
142	1932 & 1939 Bldgs.	33	XRF	2/12/97	3	Room	1	Window	Panel	Solid	Metal	2.01
143	1932 & 1939 Bldgs.	34	XRF	2/12/97	3	Room	1		Radiator	Cracked	Metal	0.09
144	1932 & 1939 Bldgs.	35	XRF	2/12/97	3	Room	1	Ceiling		Solid	Plaster	0.37
145	1932 & 1939 Bldgs.	50	XRF	2/12/97	0	Room	2	Wall	Wall	Peeling	Plaster	0.14
146	1932 & 1939 Bldgs.	51	XRF	2/12/97	0	Room	2	Wall	Wall	Peeling	Plaster	0.01
147	1932 & 1939 Bldgs.	52	XRF	2/12/97	0	Room	2	Wall	Wall	Solid	Drywall	0.01
148	1932 & 1939 Bldgs.	53	XRF	2/12/97	0	Room	2	Wall	Wall	Solid	Drywall	0.04
149	1932 & 1939 Bldgs.	54	XRF	2/12/97	0	Room	2	Wall	Wall	Peeling	Plaster	0.09
150	1932 & 1939 Bldgs.	55	XRF	2/12/97	0	Room	2	Door	Casing	Solid	Wood	0.05
151	1932 & 1939 Bldgs.	56	XRF	2/12/97	0	Room	2	Window	Stool	Solid	Wood	0.09
152	1932 & 1939 Bldgs.	57	XRF	2/12/97	0	Room	2	Window	Mullion	Solid	Wood	0.1
153	1932 & 1939 Bldgs.	58	XRF	2/12/97	0	Room	2	Cabinet	Outside	Solid	Wood	0
154	1932 & 1939 Bldgs.	59	XRF	2/12/97	0	Room	2		Radiator	Solid	Metal	0.09
155	1932 & 1939 Bldgs.	72	XRF	2/5/97	1	Room	2	Wall	Wall	Solid	Plaster	0.27
156	1932 & 1939 Bldgs.	73	XRF	2/5/97	1	Room	2	Wall	Wall	Solid	Plaster	0.22
157	1932 & 1939 Bldgs.	74	XRF	2/5/97	1	Room	2	Door	Door	Solid	Wood	0.04
158	1932 & 1939 Bldgs.	75	XRF	2/5/97	1	Room	2	Door	Casing	Solid	Wood	0.04
159	1932 & 1939 Bldgs.	76	XRF	2/5/97	1	Room	2	Cabinet	Door	Solid	Wood	0
160	1932 & 1939 Bldgs.	77	XRF	2/5/97	1	Room	2	Cabinet	Shelf	Solid	Wood	0
161	1932 & 1939 Bldgs.	78	XRF	2/5/97	1	Room	2	Bulletin B	Trim	Solid	Wood	0
162	1932 & 1939 Bldgs.	79	XRF	2/5/97	1	Room	2	Window	Stool	Solid	Wood	0.08
163	1932 & 1939 Bldgs.	80	XRF	2/5/97	1	Room	2		Radiator	Cracked	Metal	0.09
164	1932 & 1939 Bldgs.	81	XRF	2/5/97	1	Room	2	Wire	Tray	Solid	Metal	0.1
165	1932 & 1939 Bldgs.	82	XRF	2/5/97	1	Room	2	Wall	Baseboard	Solid	Metal	0.02
166	1932 & 1939 Bldgs.	83	XRF	2/5/97	1	Room	2	Closet	Wall	Solid	Metal	0.12
167	1932 & 1939 Bldgs.	84	XRF	2/5/97	1	Room	2	Cabinet	Shelf	Solid	Wood	0.01
168	1932 & 1939 Bldgs.	60	XRF	2/12/97	0	Room	3	Wall	Wall	Solid	Plaster	0.36
169	1932 & 1939 Bldgs.	61	XRF	2/12/97	0	Room	3	Wall	Wall	Solid	Plaster	0.21
170	1932 & 1939 Bldgs.	62	XRF	2/12/97	0	Room	3	Wall	Wall	Solid	Plaster	0.3
171	1932 & 1939 Bldgs.	63	XRF	2/12/97	0	Room	3	Door	Door	Solid	Wood	0.02
172	1932 & 1939 Bldgs.	64	XRF	2/12/97	0	Room	3	Door	Casing	Solid	Wood	0
173	1932 & 1939 Bldgs.	65	XRF	2/12/97	0	Room	3	Window	Casing	Solid	Wood	0.1
174	1932 & 1939 Bldgs.	66	XRF	2/12/97	0	Room	3		Radiator	Solid	Metal	0.13
175	1932 & 1939 Bldgs.	67	XRF	2/12/97	0	Room	3	Closet	Wall	Peeling	Plaster	0.31
176	1932 & 1939 Bldgs.	89	XRF	2/5/97	1	Room	3	Wall	Wall	Solid	Plaster	0.26
177	1932 & 1939 Bldgs.	90	XRF	2/5/97	1	Room	3	Wall	Wall	Solid	Plaster	0.28
178	1932 & 1939 Bldgs.	91	XRF	2/5/97	1	Room	3	Door	Casing	Solid	Metal	0.02
179	1932 & 1939 Bldgs.	92	XRF	2/5/97	1	Room	3	Window	Stool	Solid	Wood	0.12
180	1932 & 1939 Bldgs.	93	XRF	2/5/97	1	Room	3	Wall	Baseboard	Cracked	Metal	0.1
181	1932 & 1939 Bldgs.	94	XRF	2/5/97	1	Room	3	Cabinet	Door	Cracked	Wood	0
182	1932 & 1939 Bldgs.	95	XRF	2/5/97	1	Room	3	Cabinet	Door	Solid	Wood	0
183	1932 & 1939 Bldgs.	96	XRF	2/5/97	1	Room	3	Wire	Tray	Solid	Metal	0.01
184	1932 & 1939 Bldgs.	97	XRF	2/5/97	1	Room	3	Wall	Wall Rgstr	Solid	Metal	0.21
185	1932 & 1939 Bldgs.	68	XRF	2/12/97	0	Room	4	Wall	Wall	Peeling	Plaster	0.15
186	1932 & 1939 Bldgs.	69	XRF	2/12/97	0	Room	4	Wall	Wall	Peeling	Plaster	0.09
187	1932 & 1939 Bldgs.	70	XRF	2/12/97	0	Room	4	Door	Door	Solid	Wood	0.03
188	1932 & 1939 Bldgs.	71	XRF	2/12/97	0	Room	4	Door	Casing	Solid	Wood	0.04
189	1932 & 1939 Bldgs.	72	XRF	2/12/97	0	Room	4	Window	Stool	Solid	Wood	0.11
190	1932 & 1939 Bldgs.	73	XRF	2/12/97	0	Room	4	Window	Mullion	Solid	Wood	0.08

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result
191	1932 & 1939 Bldgs.	74	XRF	2/12/97	0	Room	4	Stairs	Hand rail	Solid	Wood	0.01
192	1932 & 1939 Bldgs.	98	XRF	2/5/97	1	Room	4	Wall	Wall	Solid	Plaster	0.12
193	1932 & 1939 Bldgs.	99	XRF	2/5/97	1	Room	4	Wall	Wall	Solid	Plaster	0.07
194	1932 & 1939 Bldgs.	100	XRF	2/5/97	1	Room	4	Wall	Midle Wall	Solid	Drywall	0
195	1932 & 1939 Bldgs.	101	XRF	2/5/97	1	Room	4	Door	Door	Solid	Wood	0.05
196	1932 & 1939 Bldgs.	102	XRF	2/5/97	1	Room	4	Door	Jamb	Solid	Wood	0.04
197	1932 & 1939 Bldgs.	103	XRF	2/5/97	1	Room	4	Door	Casing	Solid	Metal	0
198	1932 & 1939 Bldgs.	104	XRF	2/5/97	1	Room	4	Wall	Baseboar	Solid	Metal	0.09
199	1932 & 1939 Bldgs.	126	XRF	2/5/97	1	Room	4	Closet	Wall	Solid	Plaster	0.29
200	1932 & 1939 Bldgs.	127	XRF	2/5/97	1	Room	4	Closet	Wall	Solid	Drywall	0
201	1932 & 1939 Bldgs.	75	XRF	2/12/97	0	Room	5	Wall	Wall	Solid	Concrte	0.01
202	1932 & 1939 Bldgs.	76	XRF	2/12/97	0	Room	5	Wall	Wall	Solid	Concrte	0.01
203	1932 & 1939 Bldgs.	77	XRF	2/12/97	0	Room	5	Closet	Wall	Solid	Plaster	0.1
204	1932 & 1939 Bldgs.	78	XRF	2/12/97	0	Room	5	Cabinet	Door	Solid	Wood	0.04
205	1932 & 1939 Bldgs.	79	XRF	2/12/97	0	Room	5	Closet	Wall	Peeling	Plaster	0.12
206	1932 & 1939 Bldgs.	80	XRF	2/12/97	0	Room	5	Door	Door	Solid	Wood	0.04
207	1932 & 1939 Bldgs.	81	XRF	2/12/97	0	Room	5	Door	Jamb	Solid	Wood	0.04
208	1932 & 1939 Bldgs.	82	XRF	2/12/97	0	Room	5	Closet	Shelf	Solid	Wood	0.04
209	1932 & 1939 Bldgs.	83	XRF	2/12/97	0	Room	5	Floor		Cracked	Concre	0.02
210	1932 & 1939 Bldgs.	84	XRF	2/12/97	0	Room	5	Door	Door	Solid	Wood	0.06
211	1932 & 1939 Bldgs.	85	XRF	2/12/97	0	Room	5	Door	Casing	Solid	Wood	0.07
212	1932 & 1939 Bldgs.	86	XRF	2/12/97	0	Room	5	Wall	Midle Wall	Solid	Plaster	0.31
213	1932 & 1939 Bldgs.	105	XRF	2/5/97	1	Room	5	Wall	Wall	Solid	Plaster	0.06
214	1932 & 1939 Bldgs.	106	XRF	2/5/97	1	Room	5	Wall	Wall	Solid	Plaster	0.01
215	1932 & 1939 Bldgs.	107	XRF	2/5/97	1	Room	5	Wall	Midle Wall	Solid	Drywall	0.01
216	1932 & 1939 Bldgs.	108	XRF	2/5/97	1	Room	5	Door	Casing	Solid	Metal	0
217	1932 & 1939 Bldgs.	109	XRF	2/5/97	1	Room	5	Wall	Baseboar	Solid	Metal	5.09
218	1932 & 1939 Bldgs.	110	XRF	2/5/97	1	Room	5	Ceiling	Diffuser	Solid	Metal	0
219	1932 & 1939 Bldgs.	107	XRF	2/12/97	0	Room	6	Wall	Wall	Solid	Concrte	0.21
220	1932 & 1939 Bldgs.	108	XRF	2/12/97	0	Room	6	Wall	Wall	Solid	Concrte	0.1
221	1932 & 1939 Bldgs.	109	XRF	2/12/97	0	Room	6	Wall	Midle Wall	Solid	Brick	0.09
222	1932 & 1939 Bldgs.	110	XRF	2/12/97	0	Room	6	Door	Door	Solid	Metal	0.63
223	1932 & 1939 Bldgs.	111	XRF	2/12/97	0	Room	6	Door	Jamb	Solid	Metal	0.95
224	1932 & 1939 Bldgs.	112	XRF	2/12/97	0	Room	6	Floor		Cracked	Concrete	0.06
225	1932 & 1939 Bldgs.	113	XRF	2/12/97	0	Room	6	Stairs	Hand rail	Cracked	Metal	0.19
226	1932 & 1939 Bldgs.	114	XRF	2/12/97	0	Room	6	Cabinet	Door	Solid	Wood	0
227	1932 & 1939 Bldgs.	111	XRF	2/5/97	1	Room	6	Wall	Wall	Solid	Plaster	0.31
228	1932 & 1939 Bldgs.	113	XRF	2/5/97	1	Room	6	Wall	Wall	Solid	Plaster	0.25
229	1932 & 1939 Bldgs.	114	XRF	2/5/97	1	Room	6	Wall	Wall	Solid	Plaster	0.32
230	1932 & 1939 Bldgs.	115	XRF	2/5/97	1	Room	6	Wall	Midle Wall	Solid	Drywall	0.01
231	1932 & 1939 Bldgs.	116	XRF	2/5/97	1	Room	6	Door	Casing	Solid	Metal	0
232	1932 & 1939 Bldgs.	117	XRF	2/5/97	1	Room	6	Window	Stool	Solid	Wood	0.16
233	1932 & 1939 Bldgs.	118	XRF	2/5/97	1	Room	6	Wall	Baseboar	Cracked	Metal	0.13
234	1932 & 1939 Bldgs.	119	XRF	2/5/97	1	Room	6	Ceiling	Diffuser	Solid	Metal	0
235	1932 & 1939 Bldgs.	115	XRF	2/12/97	0	Room	7	Wall	Midle Wall	Solid	Concrte	0.03
236	1932 & 1939 Bldgs.	116	XRF	2/12/97	0	Room	7	Wall	Midle Wall	Solid	Wood	0
237	1932 & 1939 Bldgs.	117	XRF	2/12/97	0	Room	7	Wall	Midle Wall	Solid	Wood	0
238	1932 & 1939 Bldgs.	118	XRF	2/12/97	0	Room	7	Floor		Solid	Concre	0.07
239	1932 & 1939 Bldgs.	119	XRF	2/12/97	0	Room	7		Locker	Solid	Metal	0.08
240	1932 & 1939 Bldgs.	120	XRF	2/12/97	0	Room	7		Locker	Solid	Metal	0.22
241	1932 & 1939 Bldgs.	120	XRF	2/5/97	1	Room	7	Wall	Wall	Solid	Plaster	0.53
242	1932 & 1939 Bldgs.	121	XRF	2/5/97	1	Room	7	Wall	Wall	Solid	Plaster	0.37
243	1932 & 1939 Bldgs.	122	XRF	2/5/97	1	Room	7	Wall	Midle Wall	Solid	Drywall	0.01
244	1932 & 1939 Bldgs.	123	XRF	2/5/97	1	Room	7	Door	Casing	Solid	Metal	0
245	1932 & 1939 Bldgs.	124	XRF	2/5/97	1	Room	7	Wall	Baseboar	Cracked	Metal	0.17
246	1932 & 1939 Bldgs.	125	XRF	2/5/97	1	Room	7	Ceiling	Diffuser	Solid	Metal	0
247	1932 & 1939 Bldgs.	121	XRF	2/12/97	0	Room	8	Wall	Midle Wall	Solid	Concrte	0.01
248	1932 & 1939 Bldgs.	122	XRF	2/12/97	0	Room	8	Door	Door	Solid	Metal	0.58
249	1932 & 1939 Bldgs.	123	XRF	2/12/97	0	Room	8	Door	Jamb	Solid	Metal	0.55
250	1932 & 1939 Bldgs.	124	XRF	2/12/97	0	Room	8	Wall	Midle Wall	Solid	Wood	0
251	1932 & 1939 Bldgs.	128	XRF	2/5/97	1	Room	8	Wall	Wall	Solid	Plaster	0.28
252	1932 & 1939 Bldgs.	129	XRF	2/5/97	1	Room	8	Wall	Wall	Solid	Plaster	0.36
253	1932 & 1939 Bldgs.	130	XRF	2/5/97	1	Room	8	Wall	Midle Wall	Solid	Drywall	0.09

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result
254	1932 & 1939 Bldgs.	131	XRF	2/5/97	1	Room	8	Door	Casing	Solid	Metal	0
255	1932 & 1939 Bldgs.	132	XRF	2/5/97	1	Room	8	Wall	Baseboar	Cracked	Metal	0.15
256	1932 & 1939 Bldgs.	133	XRF	2/5/97	1	Room	8	Bulletin B	Trim	Solid	Wood	0.04
257	1932 & 1939 Bldgs.	134	XRF	2/5/97	1	Room	8	Ceiling	Diffuser	Solid	Metal	0
258	1932 & 1939 Bldgs.	135	XRF	2/5/97	1	Room	9	Wall	Wall	Solid	Plaster	0.23
259	1932 & 1939 Bldgs.	136	XRF	2/5/97	1	Room	9	Wall	Wall	Solid	Plaster	0.16
260	1932 & 1939 Bldgs.	137	XRF	2/5/97	1	Room	9	Wall	Midle Wall	Solid	Drywall	0.01
261	1932 & 1939 Bldgs.	138	XRF	2/5/97	1	Room	9	Door	Casing	Solid	Metal	0
262	1932 & 1939 Bldgs.	139	XRF	2/5/97	1	Room	9	Wall	Baseboar	Cracked	Metal	0.15
263	1932 & 1939 Bldgs.	140	XRF	2/5/97	1	Room	9	Wall	Baseboar	Cracked	Metal	0.42
264	1932 & 1939 Bldgs.	141	XRF	2/5/97	1	Room	9	Wall	Baseboar	Cracked	Metal	0.11
265	1932 & 1939 Bldgs.	142	XRF	2/5/97	1	Room	9	Ceiling	Diffuser	Solid	Metal	0
266	1932 & 1939 Bldgs.	168	XRF	2/6/97	1	Room	10	Wall	Wall	Solid	Plaster	0.26
267	1932 & 1939 Bldgs.	169	XRF	2/6/97	1	Room	10	Wall	Wall	Solid	Plaster	0.21
268	1932 & 1939 Bldgs.	170	XRF	2/6/97	1	Room	10	Wall	Midle Wall	Solid	Drywall	0
269	1932 & 1939 Bldgs.	171	XRF	2/6/97	1	Room	10	Door	Door	Solid	Wood	0.01
270	1932 & 1939 Bldgs.	172	XRF	2/6/97	1	Room	10	Door	Casing	Solid	Wood	0.03
271	1932 & 1939 Bldgs.	173	XRF	2/6/97	1	Room	10	Door	Jamb	Solid	Metal	0
272	1932 & 1939 Bldgs.	174	XRF	2/6/97	1	Room	10	Window	Stool	Solid	Wood	0.13
273	1932 & 1939 Bldgs.	175	XRF	2/6/97	1	Room	10	Door	Door	Solid	Wood	0
274	1932 & 1939 Bldgs.	176	XRF	2/6/97	1	Room	10	Radiator	Solid	Metal	0.02	
275	1932 & 1939 Bldgs.	177	XRF	2/6/97	1	Room	10	Window	Casing	Solid	Metal	0
276	1932 & 1939 Bldgs.	178	XRF	2/6/97	1	Room	10	Wall	Baseboar	Solid	Vinyl	0.86
277	1932 & 1939 Bldgs.	179	XRF	2/6/97	1	Room	10	Wire	Tray	Solid	Metal	0.05
278	1932 & 1939 Bldgs.	184	XRF	2/6/97	1	Room	11	Wall	Wall	Solid	Plaster	0.12
279	1932 & 1939 Bldgs.	185	XRF	2/6/97	1	Room	11	Wall	Wall	Solid	Plaster	0.23
280	1932 & 1939 Bldgs.	186	XRF	2/6/97	1	Room	11	Wall	Midle Wall	Solid	Drywall	0
281	1932 & 1939 Bldgs.	187	XRF	2/6/97	1	Room	11	Door	Door	Solid	Wood	0.02
282	1932 & 1939 Bldgs.	188	XRF	2/6/97	1	Room	11	Door	Casing	Solid	Wood	0.03
283	1932 & 1939 Bldgs.	189	XRF	2/6/97	1	Room	11	Window	Casing	Solid	Metal	0
284	1932 & 1939 Bldgs.	190	XRF	2/6/97	1	Room	11	Wire	Tray	Solid	Metal	0.16
285	1932 & 1939 Bldgs.	290	XRF	2/6/97	2	Room	20	Wall	Wall	Solid	Plaster	0.61
286	1932 & 1939 Bldgs.	291	XRF	2/6/97	2	Room	20	Wall	Wall	Solid	Plaster	0.07
287	1932 & 1939 Bldgs.	292	XRF	2/6/97	2	Room	20	Wall	Midle Wall	Solid	Plaster	0.56
288	1932 & 1939 Bldgs.	293	XRF	2/6/97	2	Room	20	Door	Door	Solid	Wood	0.06
289	1932 & 1939 Bldgs.	294	XRF	2/6/97	2	Room	20	Door	Casing	Solid	Wood	0.07
290	1932 & 1939 Bldgs.	295	XRF	2/6/97	2	Room	20	Window	Stool	Solid	Wood	0.09
291	1932 & 1939 Bldgs.	296	XRF	2/6/97	2	Room	20	Radiator	Solid	Metal	0.01	
292	1932 & 1939 Bldgs.	297	XRF	2/6/97	2	Room	20	Wall	Baseboar	Solid	Metal	0.14
293	1932 & 1939 Bldgs.	298	XRF	2/6/97	2	Room	20	Window	Panel	Solid	Metal	1.82
294	1932 & 1939 Bldgs.	299	XRF	2/6/97	2	Room	20	Window	Panel	Solid	Metal	0.55
295	1932 & 1939 Bldgs.	301	XRF	2/6/97	2	Room	20	Closest	Wall	Solid	Plaster	0.28
296	1932 & 1939 Bldgs.	302	XRF	2/6/97	2	Room	20	Closest	Casing	Solid	Wood	0.06
297	1932 & 1939 Bldgs.	303	XRF	2/6/97	2	Room	20	Closest	Wall	Solid	Plaster	0.22
298	1932 & 1939 Bldgs.	304	XRF	2/6/97	2	Room	20	Closest	Shelf	Solid	Wood	0
299	1932 & 1939 Bldgs.	23	XRF	2/5/97	1	Room	101	Wall	Wall	Cracked	Plaster	0.15
300	1932 & 1939 Bldgs.	24	XRF	2/5/97	1	Room	101	Wall	Wall	Cracked	Plaster	0.03
301	1932 & 1939 Bldgs.	25	XRF	2/5/97	1	Room	101	Wall	Wall	Solid	Plaster	0.2
302	1932 & 1939 Bldgs.	26	XRF	2/5/97	1	Room	101	Wall	Baseboar	Solid	Metal	5.09
303	1932 & 1939 Bldgs.	28	XRF	2/5/97	1	Room	101	Window	Stool	Solid	Wood	0.09
304	1932 & 1939 Bldgs.	29	XRF	2/5/97	1	Room	101	Door	Door	Solid	Wood	0.02
305	1932 & 1939 Bldgs.	30	XRF	2/5/97	1	Room	101	Door	Jamb	Solid	Wood	0.03
306	1932 & 1939 Bldgs.	31	XRF	2/5/97	1	Room	101	Radiator	Solid	Metal	0.16	
307	1932 & 1939 Bldgs.	32	XRF	2/5/97	1	Room	101	Ventilator	Solid	Metal	0.12	
308	1932 & 1939 Bldgs.	33	XRF	2/5/97	1	Room	101	Cabinet	Door	Solid	Wood	0
309	1932 & 1939 Bldgs.	34	XRF	2/5/97	1	Room	101	Cabinet	Door	Solid	Wood	0
310	1932 & 1939 Bldgs.	35	XRF	2/5/97	1	Room	101	Wire	Tray	Solid	Metal	0.02
311	1932 & 1939 Bldgs.	36	XRF	2/5/97	1	Room	101	Bulletin B	Trim	Solid	Wood	0.04
312	1932 & 1939 Bldgs.	37	XRF	2/5/97	1	Room	101	Cabinet	Shelf	Solid	Wood	0
313	1932 & 1939 Bldgs.	275	XRF	2/15/97	1	Room	101	Wall	Wall	Solid	Plaster	0.05
314	1932 & 1939 Bldgs.	38	XRF	2/5/97	1	Room	102	Wall	Wall	Solid	Plaster	0.26
315	1932 & 1939 Bldgs.	39	XRF	2/5/97	1	Room	102	Wall	Wall	Solid	Plaster	0.41
316	1932 & 1939 Bldgs.	40	XRF	2/5/97	1	Room	102	Wall	Midle Wall	Solid	Plaster	0.26

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Compon	Feature	Condition	Substrate	Result
317	1932 & 1939 Bldgs.	41	XRF	2/5/97	1	Room	102	Wall	Midle Wall	Solid	Plaster	0.17
318	1932 & 1939 Bldgs.	42	XRF	2/5/97	1	Room	102	Wall	Midle Wall	Solid	Plaster	0.19
319	1932 & 1939 Bldgs.	43	XRF	2/5/97	1	Room	102	Door	Door	Solid	Wood	0.03
320	1932 & 1939 Bldgs.	44	XRF	2/5/97	1	Room	102	Door	Jamb	Solid	Wood	0.02
321	1932 & 1939 Bldgs.	45	XRF	2/5/97	1	Room	102	Window	Stool	Solid	Wood	0.07
322	1932 & 1939 Bldgs.	46	XRF	2/5/97	1	Room	102		Radiator	Cracked	Metal	0.06
323	1932 & 1939 Bldgs.	47	XRF	2/5/97	1	Room	102		Ventilator	Sold	Metal	0.58
324	1932 & 1939 Bldgs.	48	XRF	2/5/97	1	Room	102	Wall	Baseboar	Solid	Metal	0.84
325	1932 & 1939 Bldgs.	49	XRF	2/5/97	1	Room	102	Chalkboar	Rail	Solid	Wood	0.03
326	1932 & 1939 Bldgs.	50	XRF	2/5/97	1	Room	102	Cabinet	Door	Solid	Wood	0.02
327	1932 & 1939 Bldgs.	51	XRF	2/5/97	1	Room	102	Cabinet	Door	Solid	Wood	0.02
328	1932 & 1939 Bldgs.	52	XRF	2/5/97	1	Room	102	Cabinet	Door	Solid	Wood	0.51
329	1932 & 1939 Bldgs.	53	XRF	2/5/97	1	Room	102	Cabinet	Door	Cracked	Wood	0
330	1932 & 1939 Bldgs.	54	XRF	2/5/97	1	Room	102	Wire	Tray	Cracked	Metal	0.15
331	1932 & 1939 Bldgs.	55	XRF	2/5/97	1	Room	102	Cabinet	Shelf	Solid	Wood	0
332	1932 & 1939 Bldgs.	56	XRF	2/5/97	1	Room	102	Wire	Tray	Solid	Metal	0.01
333	1932 & 1939 Bldgs.	273	XRF	2/15/97	1	Room	102	Celling		Solid	Plaster	0.09
334	1932 & 1939 Bldgs.	274	XRF	2/15/97	1	Room	102	Wall	Wall	Solid	Plaster	0.05
335	1932 & 1939 Bldgs.	191	XRF	2/6/97	1	Room	105	Wall	Wall	Solid	Plaster	0.37
336	1932 & 1939 Bldgs.	192	XRF	2/6/97	1	Room	105	Wall	Wall	Solid	Plaster	0.27
337	1932 & 1939 Bldgs.	193	XRF	2/6/97	1	Room	105	Wall	Midle Wall	Solid	Plaster	0.48
338	1932 & 1939 Bldgs.	194	XRF	2/6/97	1	Room	105	Door	Door	Solid	Wood	0.03
339	1932 & 1939 Bldgs.	195	XRF	2/6/97	1	Room	105	Door	Jamb	Solid	Wood	0.05
340	1932 & 1939 Bldgs.	196	XRF	2/6/97	1	Room	105	Window	Stool	Solid	Wood	0.1
341	1932 & 1939 Bldgs.	197	XRF	2/6/97	1	Room	105	Window	Casing	Solid	Wood	0.09
342	1932 & 1939 Bldgs.	198	XRF	2/6/97	1	Room	105	Chalkboar	Rail	Cracked	Wood	0.03
343	1932 & 1939 Bldgs.	199	XRF	2/6/97	1	Room	105	Chalkboar	Rail	Cracked	Wood	0.04
344	1932 & 1939 Bldgs.	200	XRF	2/6/97	1	Room	105	Bulletin B	Trim	Solid	Wood	0.02
345	1932 & 1939 Bldgs.	201	XRF	2/6/97	1	Room	105	Cablnet	Door	Solid	Wood	0.03
346	1932 & 1939 Bldgs.	202	XRF	2/6/97	1	Room	105		Radiator	Cracked	Metal	0.55
347	1932 & 1939 Bldgs.	203	XRF	2/6/97	1	Room	105		Ventilator	Solid	Metal	0.11
348	1932 & 1939 Bldgs.	204	XRF	2/6/97	1	Room	105	Wall	Wall Rgstr	Solid	Metal	0.26
349	1932 & 1939 Bldgs.	205	XRF	2/6/97	1	Room	105	Wire	Tray	Solid	Metal	0.28
350	1932 & 1939 Bldgs.	206	XRF	2/6/97	1	Room	105	Cabinet	Inside	Solid	Wood	0.01
351	1932 & 1939 Bldgs.	240	XRF	2/6/97	2	Room	201	Wall	Wall	Solid	Plaster	0.37
352	1932 & 1939 Bldgs.	241	XRF	2/6/97	2	Room	201	Wall	Wall	Solid	Plaster	0.14
353	1932 & 1939 Bldgs.	242	XRF	2/6/97	2	Room	201	Wall	Wall	Solid	Plaster	0.33
354	1932 & 1939 Bldgs.	243	XRF	2/6/97	2	Room	201	Door	Door	Solid	Wood	0.03
355	1932 & 1939 Bldgs.	244	XRF	2/6/97	2	Room	201	Door	Jamb	Solid	Wood	0.02
356	1932 & 1939 Bldgs.	245	XRF	2/6/97	2	Room	201	Bulletin B	Trim	Solid	Wood	0.06
357	1932 & 1939 Bldgs.	246	XRF	2/6/97	2	Room	201	Chalkboar	Rail	Solid	Wood	0.04
358	1932 & 1939 Bldgs.	247	XRF	2/6/97	2	Room	201	Window	Mullion	Solid	Wood	0.08
359	1932 & 1939 Bldgs.	248	XRF	2/6/97	2	Room	201		Radiator	Cracked	Metal	0.42
360	1932 & 1939 Bldgs.	249	XRF	2/6/97	2	Room	201		Ventilator	Cracked	Metal	0.14
361	1932 & 1939 Bldgs.	250	XRF	2/6/97	2	Room	201	Cabinet	Door	Solid	Wood	0.03
362	1932 & 1939 Bldgs.	251	XRF	2/6/97	2	Room	201	Cabinet	Shelf	Solid	Wood	0.01
363	1932 & 1939 Bldgs.	252	XRF	2/6/97	2	Room	201	Cabinet	Inside	Solid	Wood	0.01
364	1932 & 1939 Bldgs.	253	XRF	2/6/97	2	Room	201	Vent	Duct	Solid	Metal	0.3
365	1932 & 1939 Bldgs.	254	XRF	2/6/97	2	Room	201	Wire	Tray	Solid	Metal	0.08
366	1932 & 1939 Bldgs.	289	XRF	2/6/97	2	Room	201	Window	Panel	Solid	Metal	2.02
367	1932 & 1939 Bldgs.	309	XRF	2/16/97	2	Room	201	Wall	Wall	Solid	Plaster	0.04
368	1932 & 1939 Bldgs.	310	XRF	2/16/97	2	Room	201	Ceiling		Solid	Plaster	0.04
369	1932 & 1939 Bldgs.	255	XRF	2/6/97	2	Room	202	Wall	Wall	Solid	Plaster	0.09
370	1932 & 1939 Bldgs.	256	XRF	2/6/97	2	Room	202	Wall	Wall	Solid	Plaster	0.2
371	1932 & 1939 Bldgs.	257	XRF	2/6/97	2	Room	202	Wall	Midle Wall	Solid	Plaster	0.14
372	1932 & 1939 Bldgs.	258	XRF	2/6/97	2	Room	202	Door	Door	Solid	Wood	0.03
373	1932 & 1939 Bldgs.	259	XRF	2/6/97	2	Room	202	Door	Jamb	Solid	Wood	0.03
374	1932 & 1939 Bldgs.	260	XRF	2/6/97	2	Room	202	Window	Stool	Solid	Wood	0.06
375	1932 & 1939 Bldgs.	261	XRF	2/6/97	2	Room	202	Bulletin B	Trim	Solid	Wood	0.02
376	1932 & 1939 Bldgs.	262	XRF	2/6/97	2	Room	202		Radiator	Cracked	Metal	0.07
377	1932 & 1939 Bldgs.	263	XRF	2/6/97	2	Room	202		Ventilator	Cracked	Metal	0.2
378	1932 & 1939 Bldgs.	264	XRF	2/6/97	2	Room	202	Wire	Tray	Solid	Metal	0.01
379	1932 & 1939 Bldgs.	265	XRF	2/6/97	2	Room	202	Cabinet	Door	Solid	Wood	0.01

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result
380	1932 & 1939 Bldgs.	266	XRF	2/6/97	2	Room	202	Cabinet	Inside	Solid	Wood	0.01
381	1932 & 1939 Bldgs.	267	XRF	2/6/97	2	Room	202	Cabinet	Shelf	Solid	Wood	0
382	1932 & 1939 Bldgs.	268	XRF	2/6/97	2	Room	202	Vent	Duct	Solid	Metal	0.2
383	1932 & 1939 Bldgs.	269	XRF	2/6/97	2	Room	202	Chalkboar	Rail	Solid	Wood	0.03
384	1932 & 1939 Bldgs.	270	XRF	2/6/97	2	Room	202	Chalkboar	Rail	Solid	Wood	0.02
385	1932 & 1939 Bldgs.	288	XRF	2/6/97	2	Room	202	Window	Panel	Solid	Metal	1.64
386	1932 & 1939 Bldgs.	311	XRF	2/16/97	2	Room	202	Wall	Wall	Solid	Plaster	0.06
387	1932 & 1939 Bldgs.	312	XRF	2/16/97	2	Room	202	Ceiling		Solid	Plaster	0.09
388	1932 & 1939 Bldgs.	311	XRF	2/6/97	2	Room	203	Wall	Wall	Solid	Plaster	0.14
389	1932 & 1939 Bldgs.	312	XRF	2/6/97	2	Room	203	Wall	Wall	Solid	Plaster	0.07
390	1932 & 1939 Bldgs.	313	XRF	2/6/97	2	Room	203	Wall	Midle Wall	Solid	Plaster	0.12
391	1932 & 1939 Bldgs.	314	XRF	2/6/97	2	Room	203	Window	Stool	Solid	Wood	0.13
392	1932 & 1939 Bldgs.	315	XRF	2/6/97	2	Room	203	Window	Stops	Solid	Wood	0.06
393	1932 & 1939 Bldgs.	316	XRF	2/6/97	2	Room	203		Radiator	Cracked	Metal	0.28
394	1932 & 1939 Bldgs.	317	XRF	2/6/97	2	Room	203		Ventilator	Solid	Metal	0.22
395	1932 & 1939 Bldgs.	318	XRF	2/6/97	2	Room	203	Bulletin B	Trim	Solid	Wood	0.03
396	1932 & 1939 Bldgs.	319	XRF	2/6/97	2	Room	203	Chalkboar	Rail	Solid	Wood	0.03
397	1932 & 1939 Bldgs.	320	XRF	2/6/97	2	Room	203	Window	Panel	Solid	Metal	2.51
398	1932 & 1939 Bldgs.	321	XRF	2/6/97	2	Room	203	Cabinet	Door	Solid	Wood	0.01
399	1932 & 1939 Bldgs.	322	XRF	2/6/97	2	Room	203	Cabinet	Shelf	Solid	Wood	0.01
400	1932 & 1939 Bldgs.	323	XRF	2/6/97	2	Room	203	Wire	Tray	Solid	Metal	0.08
401	1932 & 1939 Bldgs.	324	XRF	2/6/97	2	Room	203	Vent	Duct	Solid	Metal	0.22
402	1932 & 1939 Bldgs.	325	XRF	2/6/97	2	Room	203	Door	Door	Solid	Wood	0.02
403	1932 & 1939 Bldgs.	326	XRF	2/6/97	2	Room	203	Door	Jamb	Solid	Wood	0.03
404	1932 & 1939 Bldgs.	314	XRF	2/16/97	1	Room	204	Ceiling		Solid	Plaster	0.07
405	1932 & 1939 Bldgs.	315	XRF	2/16/97	1	Room	204	Wall	Wall	Solid	Plaster	0.04
406	1932 & 1939 Bldgs.	272	XRF	2/6/97	2	Room	204	Wall	Wall	Solid	Plaster	0.09
407	1932 & 1939 Bldgs.	273	XRF	2/6/97	2	Room	204	Wall	Wall	Solid	Plaster	0.15
408	1932 & 1939 Bldgs.	274	XRF	2/6/97	2	Room	204	Wall	Midle Wall	Solid	Plaster	0.12
409	1932 & 1939 Bldgs.	275	XRF	2/6/97	2	Room	204	Door	Door	Solid	Wood	0.02
410	1932 & 1939 Bldgs.	276	XRF	2/6/97	2	Room	204	Door	Jamb	Solid	Wood	0.03
411	1932 & 1939 Bldgs.	277	XRF	2/6/97	2	Room	204	Window	Mullion	Solid	Wood	0.1
412	1932 & 1939 Bldgs.	278	XRF	2/6/97	2	Room	204	Window	Panel	Solid	Metal	2.41
413	1932 & 1939 Bldgs.	279	XRF	2/6/97	2	Room	204	Bulletin B	Trim	Solid	Wood	0.03
414	1932 & 1939 Bldgs.	280	XRF	2/6/97	2	Room	204	Chalkboar	Rail	Solid	Wood	0.03
415	1932 & 1939 Bldgs.	281	XRF	2/6/97	2	Room	204		Radiator	Cracked	Metal	0.25
416	1932 & 1939 Bldgs.	282	XRF	2/6/97	2	Room	204		Ventilator	Solid	Metal	0.13
417	1932 & 1939 Bldgs.	283	XRF	2/6/97	2	Room	204	Cabinet	Door	Solid	Wood	0.03
418	1932 & 1939 Bldgs.	284	XRF	2/6/97	2	Room	204	Cabinet	Inside	Solid	Wood	0
419	1932 & 1939 Bldgs.	285	XRF	2/6/97	2	Room	204	Cabinet	Shelf	Solid	Wood	0
420	1932 & 1939 Bldgs.	286	XRF	2/6/97	2	Room	204	Wire	Tray	Solid	Metal	0.08
421	1932 & 1939 Bldgs.	287	XRF	2/6/97	2	Room	204	Vent	Duct	Solid	Metal	0.17
422	1932 & 1939 Bldgs.	327	XRF	2/6/97	2	Room	205	Door	Jamb	Solid	Plaster	0.23
423	1932 & 1939 Bldgs.	328	XRF	2/6/97	2	Room	205	Wall	Wall	Solid	Plaster	0.26
424	1932 & 1939 Bldgs.	329	XRF	2/6/97	2	Room	205	Wall	Midle Wall	Solid	Plaster	0.28
425	1932 & 1939 Bldgs.	330	XRF	2/6/97	2	Room	205	Door	Door	Solid	Wood	0.04
426	1932 & 1939 Bldgs.	331	XRF	2/6/97	2	Room	205	Door	Jamb	Solid	Wood	0.02
427	1932 & 1939 Bldgs.	332	XRF	2/6/97	2	Room	205	Window	Mullion	Solid	Wood	0.1
428	1932 & 1939 Bldgs.	333	XRF	2/6/97	2	Room	205	Bulletin B	Trim	Solid	Wood	0.02
429	1932 & 1939 Bldgs.	334	XRF	2/6/97	2	Room	205	Chalkboar	Rail	Solid	Wood	0.05
430	1932 & 1939 Bldgs.	335	XRF	2/6/97	2	Room	205		Radiator	Cracked	Metal	0.53
431	1932 & 1939 Bldgs.	336	XRF	2/6/97	2	Room	205		Ventilator	Solid	Metal	0.56
432	1932 & 1939 Bldgs.	337	XRF	2/6/97	2	Room	205	Cabinet	Door	Solid	Wood	0
433	1932 & 1939 Bldgs.	338	XRF	2/6/97	2	Room	205	Cabinet	Outslide	Solid	Wood	0.07
434	1932 & 1939 Bldgs.	339	XRF	2/6/97	2	Room	205	Cabinet	Shelf	Solid	Wood	0
435	1932 & 1939 Bldgs.	340	XRF	2/6/97	2	Room	205	Wall	Baseboar	Solid	Metal	0.12
436	1932 & 1939 Bldgs.	341	XRF	2/6/97	2	Room	205	Window	Panel	Solid	Metal	2.04
437	1932 & 1939 Bldgs.	342	XRF	2/6/97	2	Room	205	Cabinet	Door	Solid	Wood	0.04
438	1932 & 1939 Bldgs.	343	XRF	2/6/97	2	Room	205	Cabinet	Inside	Solid	Wood	0
439	1932 & 1939 Bldgs.	344	XRF	2/6/97	2	Room	205	Wire	Tray	Solid	Metal	0.16
440	1932 & 1939 Bldgs.	345	XRF	2/6/97	2	Room	205	Vent	Duct	Solid	Metal	0.2
441	1932 & 1939 Bldgs.	16	XRF	2/12/97	2	Room	206	Wall	Wall	Cracked	Plaster	0.39
442	1932 & 1939 Bldgs.	17	XRF	2/12/97	2	Room	206	Wall	Wall	Cracked	Plaster	0.09

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result
443	1932 & 1939 Bldgs.	18	XRF	2/12/97	2	Room	206	Window	Stool	Solid	Wood	0.1
444	1932 & 1939 Bldgs.	19	XRF	2/12/97	2	Room	206	Window	Panel	Solid	Metal	1.92
445	1932 & 1939 Bldgs.	20	XRF	2/12/97	2	Room	206	Bulletin B	Trim	Solid	Wood	0.01
446	1932 & 1939 Bldgs.	21	XRF	2/12/97	2	Room	206	Cabinet	Door	Solid	Wood	0.06
447	1932 & 1939 Bldgs.	22	XRF	2/12/97	2	Room	206	Cabinet	Inside	Solid	Wood	0
448	1932 & 1939 Bldgs.	23	XRF	2/12/97	2	Room	206	Cabinet	Shelf	Solid	Wood	0
449	1932 & 1939 Bldgs.	24	XRF	2/12/97	2	Room	206	Wall	Baseboar	Peeling	Metal	0.18
450	1932 & 1939 Bldgs.	25	XRF	2/12/97	2	Room	206	Univent		Peeling	Metal	0.02
451	1932 & 1939 Bldgs.	26	XRF	2/12/97	2	Room	206	Univent		Peeling	Metal	0.21
452	1932 & 1939 Bldgs.	27	XRF	2/12/97	2	Room	206	Door	Jamb	Solid	Metal	0
453	1932 & 1939 Bldgs.	207	XRF	2/6/97	1	Stairwell	1	Wall	Wall	Solid	Plaster	0.11
454	1932 & 1939 Bldgs.	208	XRF	2/6/97	1	Stairwell	1	Wall	Wall	Solid	Plaster	0.06
455	1932 & 1939 Bldgs.	209	XRF	2/6/97	1	Stairwell	1	Wall	Wall	Solid	Plaster	0.07
456	1932 & 1939 Bldgs.	210	XRF	2/6/97	1	Stairwell	1	Wall	Midle Wall	Solid	Plaster	0.3
457	1932 & 1939 Bldgs.	211	XRF	2/6/97	1	Stairwell	1	Wall	Chair rail	Solid	Metal	0.5
458	1932 & 1939 Bldgs.	212	XRF	2/6/97	1	Stairwell	1	Door	Door	Cracked	Wood	0.16
459	1932 & 1939 Bldgs.	213	XRF	2/6/97	1	Stairwell	1	Door	Jamb	Cracked	Wood	0.12
460	1932 & 1939 Bldgs.	214	XRF	2/6/97	1	Stairwell	1	Door	Door	Solid	Metal	0.09
461	1932 & 1939 Bldgs.	215	XRF	2/6/97	1	Stairwell	1	Door	Jamb	Solid	Metal	5.09
462	1932 & 1939 Bldgs.	216	XRF	2/6/97	1	Stairwell	1	Door	Door	Solid	Metal	0.17
463	1932 & 1939 Bldgs.	217	XRF	2/6/97	1	Stairwell	1	Wall	Midle Wall	Solid	Plaster	0.26
464	1932 & 1939 Bldgs.	218	XRF	2/6/97	1	Stairwell	1	Stairs	Hand rail	Solid	Wood	0
465	1932 & 1939 Bldgs.	220	XRF	2/6/97	1	Stairwell	1	Radiator	Cracked	Metal	0.12	
466	1932 & 1939 Bldgs.	221	XRF	2/6/97	1	Stairwell	1	Window	Stool	Cracked	Wood	0.12
467	1932 & 1939 Bldgs.	313	XRF	2/16/97	1	Stairwell	1	Ceiling		Solid	Plaster	0.04
468	1932 & 1939 Bldgs.	87	XRF	2/12/97	0	Stairwell	2	Wall	Wall	Solid	Plaster	0.16
469	1932 & 1939 Bldgs.	88	XRF	2/12/97	0	Stairwell	2	Wall	Wall	Solid	Metal	0.14
470	1932 & 1939 Bldgs.	89	XRF	2/12/97	0	Stairwell	2	Wall	Midle Wall	Solid	Metal	0.36
471	1932 & 1939 Bldgs.	90	XRF	2/12/97	0	Stairwell	2	Door	Door	Solid	Wood	0.07
472	1932 & 1939 Bldgs.	91	XRF	2/12/97	0	Stairwell	2	Door	Casing	Solid	Wood	0.04
473	1932 & 1939 Bldgs.	92	XRF	2/12/97	0	Stairwell	2	Elec Pane	Solid	Metal	0.12	
474	1932 & 1939 Bldgs.	93	XRF	2/12/97	0	Stairwell	2	Cabinet	Outside	Solid	Metal	0.07
475	1932 & 1939 Bldgs.	94	XRF	2/12/97	0	Stairwell	2	Wall	Wall Rgstr	Solid	Metal	0
476	1932 & 1939 Bldgs.	95	XRF	2/12/97	0	Stairwell	2	Wall	Wall Rgstr	Solid	Metal	0.36
477	1932 & 1939 Bldgs.	96	XRF	2/12/97	0	Stairwell	2	Wall	Wall Rgstr	Solid	Metal	0.05
478	1932 & 1939 Bldgs.	97	XRF	2/12/97	0	Stairwell	2	Stairs	Wall	Solid	Plaster	0.13
479	1932 & 1939 Bldgs.	98	XRF	2/12/97	0	Stairwell	2	Stairs	Wall	Solid	Plaster	0.36
480	1932 & 1939 Bldgs.	99	XRF	2/12/97	0	Stairwell	2	Stairs	Hand rail	Solid	Wood	0
481	1932 & 1939 Bldgs.	100	XRF	2/12/97	0	Stairwell	2	Stairs	Wall	Solid	Plaster	0.95
482	1932 & 1939 Bldgs.	101	XRF	2/12/97	0	Stairwell	2	Stairs	Wall	Solid	Plaster	0.29
483	1932 & 1939 Bldgs.	102	XRF	2/12/97	0	Stairwell	2	Closest	Wall	Solid	Plaster	0.31
484	1932 & 1939 Bldgs.	103	XRF	2/12/97	0	Stairwell	2	Closest	Wall	Solid	Plaster	0.26
485	1932 & 1939 Bldgs.	104	XRF	2/12/97	0	Stairwell	2	Closest	Casing	Solid	Wood	0.03
486	1932 & 1939 Bldgs.	105	XRF	2/12/97	0	Stairwell	2	Closest	Shelf	Solid	Wood	0.19
487	1932 & 1939 Bldgs.	106	XRF	2/12/97	0	Stairwell	2	Ceiling		Solid	Plaster	0.16
488	1932 & 1939 Bldgs.	324	XRF	2/16/97	0	Stairwell	2	Ceiling		Solid	Plaster	0.2
489	1932 & 1939 Bldgs.	316	XRF	2/16/97	1	Stairwell	2	Ceiling		Solid	Plaster	0.09
490	1932 & 1939 Bldgs.	317	XRF	2/16/97	2	Stairwell	2	Door	Handle	Cracked	Metal	0.06
491	1932 & 1939 Bldgs.	318	XRF	2/16/97	2	Stairwell	2	Window	Stool	Solid	Wood	0.22
492	1932 & 1939 Bldgs.	319	XRF	2/16/97	2	Stairwell	2	Window	Casing	Solid	Wood	0.15
493	1932 & 1939 Bldgs.	320	XRF	2/16/97	2	Stairwell	2	Window	Sash	Solid	Wood	0.06
494	1932 & 1939 Bldgs.	321	XRF	2/16/97	2	Stairwell	2	Window	Mullion	Solid	Metal	0.04
495	1932 & 1939 Bldgs.	322	XRF	2/16/97	2	Stairwell	2	Pipe		Solid	Metal	0.12
496	1932 & 1939 Bldgs.	325	XRF	2/16/97	0	Stairwell	4	Window	Stool	Solid	Wood	0.09
497	1932 & 1939 Bldgs.	326	XRF	2/16/97	0	Stairwell	4	Window	Sash	Solid	Wood	0.09
498	1932 & 1939 Bldgs.	327	XRF	2/16/97	0	Stairwell	4	Wall	Wall	Solid	Plaster	0.13
499	1932 & 1939 Bldgs.	328	XRF	2/16/97	0	Stairwell	4	Wall	Midle Wall	Solid	Plaster	0.17
500	1932 & 1939 Bldgs.	329	XRF	2/16/97	0	Stairwell	4	Wall	Wall	Solid	Plaster	0.13
501	1932 & 1939 Bldgs.	330	XRF	2/16/97	0	Stairwell	4	Ceiling		Solid	Plaster	0.02
502	1932 & 1939 Bldgs.	331	XRF	2/16/97	0	Stairwell	4	Door	Door	Solid	Metal	0.02
503	1932 & 1939 Bldgs.	332	XRF	2/16/97	0	Stairwell	4	Door	Jamb	Solid	Metal	0
504	1932 & 1939 Bldgs.	333	XRF	2/16/97	0	Stairwell	4	Wall	Baseboar	Solid	Concrete	0.31
505	1932 & 1939 Bldgs.	334	XRF	2/16/97	0	Stairwell	4	Radiator	Solid	Metal	0.11	

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Compon	Feature	Condition	Substrate	Result
506	1953 Bldg.	170	XRF	2/12/97	1	Bath		1 Wall	Wall	Solid	Tile	3.15
507	1953 Bldg.	171	XRF	2/12/97	1	Bath		1 Door	Casing	Solid	Wood	0.01
508	1953 Bldg.	172	XRF	2/12/97	1	Bath		1 Window	Stool	Peeling	Wood	0.77
509	1953 Bldg.	173	XRF	2/12/97	1	Bath		1 Bath	Stall	Peeling	Wood	0
510	1953 Bldg.	174	XRF	2/12/97	1	Bath		1 Bath	Stall	Peeling	Wood	0.01
511	1953 Bldg.	175	XRF	2/12/97	1	Bath		1 Radiator	Cover	Solid	Metal	0.02
512	1953 Bldg.	176	XRF	2/12/97	1	Bath		1 Wall	Wall Rgstr	Solid	Metal	0
513	1953 Bldg.	177	XRF	2/12/97	1	Bath		1 Wall	Wall Rgstr	Solid	Metal	0
514	1953 Bldg.	280	XRF	2/15/97	1	Bath		1 Ceiling		Solid	Plaster	0.13
515	1953 Bldg.	281	XRF	2/15/97	1	Bath		1 Ceiling	Diffuser	Solid	Metal	0.05
516	1953 Bldg.	284	XRF	2/15/97	1	Bath		2 Ceiling		Solid	Plaster	0.08
517	1953 Bldg.	285	XRF	2/15/97	1	Bath		2 Ceiling		Solid	Plaster	0.25
518	1953 Bldg.	286	XRF	2/15/97	1	Bath		2 Ceiling	Diffuser	Solid	Metal	0.1
519	1953 Bldg.	262	XRF	2/15/97	1	Bath		5 Ceiling		Solid	Plaster	0.03
520	1953 Bldg.	263	XRF	2/15/97	1	Bath		5 Ceiling	Diffuser	Solid	Metal	0
521	1953 Bldg.	264	XRF	2/15/97	1	Bath		5 Ceiling	Diffuser	Solid	Metal	0.01
522	1953 Bldg.	265	XRF	2/15/97	1	Bath		5 Wall	Baseboar	Solid	Tile	2.72
523	1953 Bldg.	148	XRF	5/18/98	1	Cafeteria		8 Wall	Wall	Solid	Tile	2.73
524	1953 Bldg.	149	XRF	5/18/98	1	Cafeteria		8 Wall	Midle Wall	Solid	Concrete	0
525	1953 Bldg.	150	XRF	5/18/98	1	Cafeteria		8 Wall	Wall	Solid	Concrete	0
526	1953 Bldg.	151	XRF	5/18/98	1	Cafeteria		8 Lemtil		Solid	Metal	0.04
527	1953 Bldg.	152	XRF	5/18/98	1	Cafeteria		8 Table	Enclosure	Solid	Metal	0.01
528	1953 Bldg.	153	XRF	5/18/98	1	Cafeteria		8 Wall	Diffuser	Solid	Metal	0
529	1953 Bldg.	154	XRF	5/19/98	1	Cafeteria		8 Door	Door	Solid	Wood	0.01
530	1953 Bldg.	156	XRF	5/19/98	1	Cafeteria		8 Door	Casing	Solid	Wood	0.01
531	1953 Bldg.	157	XRF	5/19/98	1	Cafeteria		8 Door	Door	Solid	Wood	0
532	1953 Bldg.	158	XRF	5/19/98	1	Cafeteria		8 Door	Jamb	Solid	Metal	0
533	1953 Bldg.	159	XRF	5/19/98	1	Cafeteria		8	Radiator	Solid	Metal	0
534	1953 Bldg.	160	XRF	5/19/98	1	Cafeteria		8 Cabinet	Door	Solid	Wood	0
535	1953 Bldg.	161	XRF	5/19/98	1	Cafeteria		8 Cabinet	Door	Solid	Wood	0
536	1953 Bldg.	162	XRF	5/19/98	1	Cafeteria		8 Floor		Solid	Wood	0
537	1953 Bldg.	163	XRF	5/19/98	1	Cafeteria		8 Stairs	Tread	Solid	Wood	0
538	1953 Bldg.	164	XRF	5/19/98	1	Cafeteria		8 Wall	Midle Wall	Solid	Concrete	0.07
539	1953 Bldg.	165	XRF	5/19/98	1	Cafeteria		8 Door	Door	Solid	Wood	0
540	1953 Bldg.	166	XRF	5/19/98	1	Cafeteria		8 Door	Casing	Solid	Wood	0
541	1953 Bldg.	167	XRF	5/19/98	1	Cafeteria		8 Wall	Midle Wall	Solid	Wood	0
542	1953 Bldg.	168	XRF	5/19/98	1	Cafeteria		8 Wall	Baseboar	Solid	Wood	0
543	1953 Bldg.	169	XRF	5/19/98	1	Cafeteria		8 Elec Pane	Solid	Metal	0.59	
544	1953 Bldg.	170	XRF	5/19/98	1	Cafeteria		8 Rail	Cap	Solid	Wood	0
545	1953 Bldg.	171	XRF	5/19/98	1	Cafeteria		8 Stairs	Hand rail	Solid	Wood	0
546	1953 Bldg.	6	XRF	5/18/98	1	Classroo	107	Wall	Wall	Solid	Tile	2.52
547	1953 Bldg.	7	XRF	5/18/98	1	Classroo	107	Wall	Wall	Solid	Concrete	0.03
548	1953 Bldg.	8	XRF	5/18/98	1	Classroo	107	Door	Door	Solid	Wood	0.01
549	1953 Bldg.	9	XRF	5/18/98	1	Classroo	107	Door	Casing	Solid	Wood	0
550	1953 Bldg.	10	XRF	5/18/98	1	Classroo	107	Window	Mullion	Solid	Plaster	0.03
551	1953 Bldg.	11	XRF	5/18/98	1	Classroo	107	Cabinet	Outside	Solid	Wood	0.03
552	1953 Bldg.	12	XRF	5/18/98	1	Classroo	107	Cabinet	Inside	Solid	Wood	0.02
553	1953 Bldg.	13	XRF	5/18/98	1	Classroo	107	Cabinet	Shelf	Solid	Wood	0.04
554	1953 Bldg.	14	XRF	5/18/98	1	Classroo	107		Radiator	Solid	Metal	0.04
555	1953 Bldg.	15	XRF	5/18/98	1	Classroo	107		Radiator	Solid	Metal	0.02
556	1953 Bldg.	16	XRF	5/18/98	1	Classroo	107	Bookcase	Shelf	Solid	Wood	0.03
557	1953 Bldg.	17	XRF	5/18/98	1	Classroo	107	Chalkboar	Rail	Solid	Wood	0.03
558	1953 Bldg.	18	XRF	5/18/98	1	Classroo	107	Wall	Baseboar	Solid	Wood	0
559	1953 Bldg.	19	XRF	5/18/98	1	Classroo	107	Wall	Defuser	Solid	Metal	0.02
560	1953 Bldg.	37	XRF	5/18/98	1	Classroo	108	Wall	Midle Wall	Solid	Tile	3.35
561	1953 Bldg.	38	XRF	5/18/98	1	Classroo	108	Wall	Wall	Solid	Concrete	0.16
562	1953 Bldg.	39	XRF	5/18/98	1	Classroo	108	Door	Door	Solid	Wood	0.01
563	1953 Bldg.	40	XRF	5/18/98	1	Classroo	108	Door	Casing	Solid	Wood	0
564	1953 Bldg.	41	XRF	5/18/98	1	Classroo	108	Wall	Midle Wall	Solid	Metal	0.03
565	1953 Bldg.	42	XRF	5/18/98	1	Classroo	108	Window	Mullion	Solid	Plaster	0.06
566	1953 Bldg.	43	XRF	5/18/98	1	Classroo	108	Window	Panel	Solid	Metal	1.75
567	1953 Bldg.	44	XRF	5/18/98	1	Classroo	108		Radiator	Solid	Metal	0.04
568	1953 Bldg.	45	XRF	5/18/98	1	Classroo	108		Radiator	Solid	Metal	0.04

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result
569	1953 Bldg.	46	XRF	5/18/98	1	Classroo	108	Bookcase	Shelf	Solid	Wood	0.03
570	1953 Bldg.	47	XRF	5/18/98	1	Classroo	108	Bulletin B	Trim	Solid	Wood	0.03
571	1953 Bldg.	48	XRF	5/18/98	1	Classroo	108	Cabinet	Door	Solid	Wood	0
572	1953 Bldg.	49	XRF	5/18/98	1	Classroo	108	Cabinet	Shelf	Solid	Wood	0
573	1953 Bldg.	50	XRF	5/18/98	1	Classroo	108	Wall	Baseboar	Solid	Wood	0.01
574	1953 Bldg.	51	XRF	5/18/98	1	Classroo	109	Wall	Midle Wall	Solid	Concrete	0
575	1953 Bldg.	52	XRF	5/18/98	1	Classroo	109	Wall	Midle Wall	Solid	Tile	2.33
576	1953 Bldg.	54	XRF	5/18/98	1	Classroo	109	Door	Door	Solid	Wood	0.02
577	1953 Bldg.	55	XRF	5/18/98	1	Classroo	109	Door	Casing	Solid	Wood	0
578	1953 Bldg.	56	XRF	5/18/98	1	Classroo	109	Window	Mullion	Solid	Plaster	0.06
579	1953 Bldg.	57	XRF	5/18/98	1	Classroo	109		Radiator	Solid	Metal	0.07
580	1953 Bldg.	58	XRF	5/18/98	1	Classroo	109		Radiator	Solid	Metal	0.08
581	1953 Bldg.	59	XRF	5/18/98	1	Classroo	109	Bookcase	Inside	Solid	Wood	0.04
582	1953 Bldg.	60	XRF	5/18/98	1	Classroo	109	Chalkboar	Rail	Solid	Wood	0.01
583	1953 Bldg.	61	XRF	5/18/98	1	Classroo	109	Wall	Baseboar	Solid	Wood	0.03
584	1953 Bldg.	62	XRF	5/18/98	1	Classroo	109	Cabinet	Door	Solid	Wood	0
585	1953 Bldg.	63	XRF	5/18/98	1	Classroo	109	Cabinet	wall	Solid	Wood	0
586	1953 Bldg.	64	XRF	5/18/98	1	Classroo	109	Cabinet	Shelf	Solid	Wood	0.01
587	1953 Bldg.	65	XRF	5/18/98	1	Classroo	109	Cabinet	Shelf	Solid	Wood	0.01
588	1953 Bldg.	66	XRF	5/18/98	1	Classroo	109	Wall	Diffuser	Solid	Metal	0.02
589	1953 Bldg.	67	XRF	5/18/98	1	Classroo	110	Wall	Midle Wall	Solid	Tile	2.88
590	1953 Bldg.	68	XRF	5/18/98	1	Classroo	110	Wall	Midle Wall	Solid	Concrete	0.03
591	1953 Bldg.	69	XRF	5/18/98	1	Classroo	110	Door	Door	Solid	Wood	0.32
592	1953 Bldg.	70	XRF	5/18/98	1	Classroo	110	Door	Casing	Solid	Wood	1.55
593	1953 Bldg.	71	XRF	5/18/98	1	Classroo	110	Wall	Midle Wall	Solid	Wood	0.48
594	1953 Bldg.	72	XRF	5/18/98	1	Classroo	110	Door	Door	Solid	Wood	0.01
595	1953 Bldg.	73	XRF	5/18/98	1	Classroo	110	Door	Casing	Solid	Wood	0
596	1953 Bldg.	74	XRF	5/18/98	1	Classroo	110	Door	Header	Solid	Wood	0.01
597	1953 Bldg.	75	XRF	5/18/98	1	Classroo	110	Window	Mullion	Solid	Plaster	0.08
598	1953 Bldg.	76	XRF	5/18/98	1	Classroo	110		Radiator	Solid	Metal	0.05
599	1953 Bldg.	77	XRF	5/18/98	1	Classroo	110	Bookcase	Inside	Solid	Wood	0.04
600	1953 Bldg.	78	XRF	5/18/98	1	Classroo	110	Cabinet	Door	Solid	Wood	0
601	1953 Bldg.	79	XRF	5/18/98	1	Classroo	110	Cabinet	Outside	Solid	Wood	0.22
602	1953 Bldg.	80	XRF	5/18/98	1	Classroo	110	Chalkboar	Trim	Solid	Wood	0.01
603	1953 Bldg.	81	XRF	5/18/98	1	Classroo	110	Unlisted	Wall	Solid	Wood	0.01
604	1953 Bldg.	83	XRF	5/18/98	1	Classroo	110		Radiator	Solid	Metal	0.73
605	1953 Bldg.	84	XRF	5/18/98	1	Classroo	110	Floor		Solid	Tile	2.45
606	1953 Bldg.	85	XRF	5/18/98	1	Classroo	110	Coat	Rack	Solid	Wood	0
607	1953 Bldg.	97	XRF	5/18/98	1	Classroo	111	Wall	Midle Wall	Solid	Tile	2.91
608	1953 Bldg.	98	XRF	5/18/98	1	Classroo	111	Wall	Wall	Solid	Concrete	0.03
609	1953 Bldg.	99	XRF	5/18/98	1	Classroo	111	Door	Door	Solid	Wood	0
610	1953 Bldg.	100	XRF	5/18/98	1	Classroo	111	Door	Casing	Solid	Wood	0
611	1953 Bldg.	101	XRF	5/18/98	1	Classroo	111	Door	Door	Solid	Wood	0.25
612	1953 Bldg.	102	XRF	5/18/98	1	Classroo	111	Window	Mullion	Solid	Plaster	0.06
613	1953 Bldg.	103	XRF	5/18/98	1	Classroo	111	Window	Header	Solid	Wood	0.58
614	1953 Bldg.	104	XRF	5/18/98	1	Classroo	111		Radiator	Solid	Metal	0.04
615	1953 Bldg.	105	XRF	5/18/98	1	Classroo	111	Bookcase	Shelf	Solid	Wood	0.03
616	1953 Bldg.	106	XRF	5/18/98	1	Classroo	111	Cabinet	Inside	Solid	Wood	0.02
617	1953 Bldg.	107	XRF	5/18/98	1	Classroo	111	Chalkboar	Rail	Solid	Wood	0
618	1953 Bldg.	108	XRF	5/18/98	1	Classroo	111	Window	Header	Solid	Metal	1.87
619	1953 Bldg.	109	XRF	5/18/98	1	Classroo	111	Window	Panel	Solid	Wood	0
620	1953 Bldg.	110	XRF	5/18/98	1	Classroo	111	Window	Casing	Solid	Metal	0.06
621	1953 Bldg.	111	XRF	5/18/98	1	Classroo	111	Wall	Baseboar	Solid	Wood	0
622	1953 Bldg.	112	XRF	5/18/98	1	Classroo	111	Floor		Solid	Tile	2.84
623	1953 Bldg.	113	XRF	5/18/98	1	Classroo	111	Wall	Diffuser	Solid	Metal	0.02
624	1953 Bldg.	114	XRF	5/18/98	1	Classroo	111	Coat	Rack	Solid	Wood	0.02
625	1953 Bldg.	289	XRF	2/15/97	1	Hall	0	Ceiling		Solid	Plaster	0.16
626	1953 Bldg.	126	XRF	2/12/97	1	Hall	1	Wall	Wall	Solid	Plaster	0.93
627	1953 Bldg.	127	XRF	2/12/97	1	Hall	1	Wall	Midle Wall	Solid	Tile	3.06
628	1953 Bldg.	128	XRF	2/12/97	1	Hall	1	Wall	Wall	Solid	Plaster	0.92
629	1953 Bldg.	129	XRF	2/12/97	1	Hall	1	Wall	Wall	Solid	Plaster	0.8
630	1953 Bldg.	130	XRF	2/12/97	1	Hall	1	Wall	Wall	Solid	Plaster	0.87
631	1953 Bldg.	131	XRF	2/12/97	1	Hall	1	Wall	Wall	Solid	Tile	5.09

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Compon	Feature	Condition	Substrate	Result
632	1953 Bldg.	132	XRF	2/12/97	1	Hall		1	Door	Door	Solid	Wood 0.48
633	1953 Bldg.	133	XRF	2/12/97	1	Hall		1	Door	Casing	Solid	Wood 0
634	1953 Bldg.	134	XRF	2/12/97	1	Hall		1	Window	Mullion	Solid	Wood 0
635	1953 Bldg.	135	XRF	2/12/97	1	Hall		1	Door	Door	Solid	Wood 0.01
636	1953 Bldg.	136	XRF	2/12/97	1	Hall		1	Door	Casing	Solid	Wood 0.01
637	1953 Bldg.	137	XRF	2/12/97	1	Hall		1		Univent	Solid	Metal 0
638	1953 Bldg.	138	XRF	2/12/97	1	Hall		1		Locker	Solid	Metal 0.06
639	1953 Bldg.	139	XRF	2/12/97	1	Hall		1	Fire Ext.	Cabinet	Solid	Metal 0.02
640	1953 Bldg.	140	XRF	2/12/97	1	Hall		1		Elec Pane	Solid	Metal 0.02
641	1953 Bldg.	141	XRF	2/12/97	1	Hall		1		Univent	Solid	Metal 0
642	1953 Bldg.	142	XRF	2/12/97	1	Hall		1	Window	Panel	Solid	Metal 2
643	1953 Bldg.	143	XRF	2/12/97	1	Hall		1	Window	Mullion	Solid	Plaster 0.04
644	1953 Bldg.	252	XRF	2/15/97	1	Hall		1	Ceiling		Solid	Plaster 1.03
645	1953 Bldg.	191	XRF	2/20/97	1	Outside		0	Window	Sill	Solid	Wood 0.45
646	1953 Bldg.	192	XRF	2/20/97	1	Outside		0	Wall	Wall Rgstr	Solid	Metal 0.37
647	1953 Bldg.	193	XRF	2/20/97	1	Outside		0	Door	Door	Solid	Wood 0.8
648	1953 Bldg.	194	XRF	2/20/97	1	Outside		0	Door	Jamb	Solid	Wood 5.09
649	1953 Bldg.	195	XRF	2/20/97	1	Outside		0	Window	Sash	Solid	Wood 3.23
650	1953 Bldg.	196	XRF	2/20/97	1	Outside		0	Ext Wall	Siding	Solid	Wood 0
651	1953 Bldg.	197	XRF	2/20/97	1	Outside		0	Ext Wall	Dripboard	Solid	Wood 0.45
652	1953 Bldg.	198	XRF	2/20/97	1	Outside		0	Door	Door	Solid	Wood 0.15
653	1953 Bldg.	199	XRF	2/20/97	1	Outside		0	Door	Jamb	Solid	Wood 0.82
654	1953 Bldg.	200	XRF	2/20/97	1	Outside		0	Ext Wall	Siding	Solid	Wood 0
655	1953 Bldg.	201	XRF	2/20/97	1	Outside		0	Ext Wall	Dripboard	Solid	Metal 0.01
656	1953 Bldg.	202	XRF	2/20/97	1	Outside		0	Window	Sash	Peeling	Metal 3.47
657	1953 Bldg.	203	XRF	2/20/97	1	Outside		0	Window	Sill	Solid	Wood 1.14
658	1953 Bldg.	204	XRF	2/20/97	1	Outside		0	Window	Sash	Solid	Metal 0.01
659	1953 Bldg.	31	XRF	5/18/98	1	Restroom		2	Wall	Midle Wall	Solid	Tile 3.14
660	1953 Bldg.	32	XRF	5/18/98	1	Restroom		2	Door	Casing	Solid	Wood 0.01
661	1953 Bldg.	33	XRF	5/18/98	1	Restroom		2	Window	Casing	Solid	Metal 0
662	1953 Bldg.	34	XRF	5/18/98	1	Restroom		2		Radiator	Solid	Metal 0.02
663	1953 Bldg.	35	XRF	5/18/98	1	Restroom		2	Stall	Door	Solid	Wood 0.01
664	1953 Bldg.	36	XRF	5/18/98	1	Restroom		2	Wall	Diffuser	Solid	Metal 0.18
665	1953 Bldg.	86	XRF	5/18/98	1	Restroom		3	Door	Door	Solid	Wood 0.01
666	1953 Bldg.	87	XRF	5/18/98	1	Restroom		3	Wall	Midle Wall	Solid	Tile 3.3
667	1953 Bldg.	88	XRF	5/18/98	1	Restroom		3	Door	Door	Solid	Wood 0.01
668	1953 Bldg.	89	XRF	5/18/98	1	Restroom		3	Door	Casing	Solid	Wood 0
669	1953 Bldg.	90	XRF	5/18/98	1	Restroom		3		Radiator	Peeling	Metal 0.46
670	1953 Bldg.	91	XRF	5/18/98	1	Restroom		3	Ceiling		Solid	Plaster 0.01
671	1953 Bldg.	115	XRF	5/18/98	1	Restroom		4	Wall	Wall	Solid	Tile 3
672	1953 Bldg.	116	XRF	5/18/98	1	Restroom		4	Door	Door	Solid	Wood 0.01
673	1953 Bldg.	117	XRF	5/18/98	1	Restroom		4	Door	Casing	Solid	Wood 0
674	1953 Bldg.	118	XRF	5/18/98	1	Restroom		4	Ceiling		Solid	Plaster 0.01
675	1953 Bldg.	119	XRF	5/18/98	1	Restroom		4	Ceiling	Diffuser	Solid	Metal 0.07
676	1953 Bldg.	120	XRF	5/18/98	1	Restroom		4	Door	Grid	Solid	Wood 0
677	1953 Bldg.	142	XRF	5/18/98	1	Restroom		5	Wall	Wall	Solid	Plaster 0.34
678	1953 Bldg.	143	XRF	5/18/98	1	Restroom		5	Wall	Midle Wall	Solid	Concrete 0
679	1953 Bldg.	144	XRF	5/18/98	1	Restroom		5	Door	Jamb	Solid	Metal 0
680	1953 Bldg.	145	XRF	5/18/98	1	Restroom		5	Floor		Solid	Tile 0.04
681	1953 Bldg.	146	XRF	5/18/98	1	Restroom		5	Wall	Baseboar	Solid	Tile 2.43
682	1953 Bldg.	147	XRF	5/18/98	1	Restroom		5		Locker	Solid	Metal 1.25
683	1953 Bldg.	277	XRF	2/15/97	1	Room		0	Ceiling		Solid	Plaster 0.08
684	1953 Bldg.	278	XRF	2/15/97	1	Room		0	Wall	Wall	Solid	Plaster 0.07
685	1953 Bldg.	279	XRF	2/15/97	1	Room		0	Ceiling		Solid	Plaster 0.07
686	1953 Bldg.	20	XRF	5/18/98	1	Room		1		Lemtil	Solid	Metal 0
687	1953 Bldg.	21	XRF	5/18/98	1	Room		1	Door	Casing	Solid	Wood 0
688	1953 Bldg.	22	XRF	5/18/98	1	Room		1	Floor		Solid	Concrete 0.11
689	1953 Bldg.	23	XRF	5/18/98	1	Room		2	Wall	Wall	Solid	Plaster 0.02
690	1953 Bldg.	24	XRF	5/18/98	1	Room		2	Wall	Wall	Solid	Plaster 0.05
691	1953 Bldg.	25	XRF	5/18/98	1	Room		2	Door	Door	Solid	Wood 0
692	1953 Bldg.	26	XRF	5/18/98	1	Room		2	Door	Casing	Solid	Wood 0.01
693	1953 Bldg.	27	XRF	5/18/98	1	Room		2	Closet	Shelf	Solid	Wood 0
694	1953 Bldg.	28	XRF	5/18/98	1	Room		2	Closet	Shelf	Solid	Wood 0

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result
695	1953 Bldg.	29	XRF	5/18/98	1	Room	2	Hatch	Trim	Solid	Wood	0
696	1953 Bldg.	30	XRF	5/18/98	1	Room	2	Floor		Solid	Tile	0.04
697	1953 Bldg.	282	XRF	2/15/97	1	Room	2	Ceiling		Solid	Plaster	0.06
698	1953 Bldg.	283	XRF	2/15/97	1	Room	2	Ceiling		Solid	Plaster	0.02
699	1953 Bldg.	92	XRF	5/18/98	1	Room	3	Wall	Midle Wall	Solid	Concrete	0.01
700	1953 Bldg.	93	XRF	5/18/98	1	Room	3	Door	Casing	Solid	Wood	0.01
701	1953 Bldg.	94	XRF	5/18/98	1	Room	3	Wall	Cabinet	Solid	Wood	0
702	1953 Bldg.	95	XRF	5/18/98	1	Room	3	Cabinet	Shelf	Solid	Wood	0
703	1953 Bldg.	121	XRF	5/18/98	1	Room	4	Wall	Midle Wall	Solid	Concrete	0
704	1953 Bldg.	122	XRF	5/18/98	1	Room	4	Door	Casing	Solid	Wood	0
705	1953 Bldg.	123	XRF	5/18/98	1	Room	4	Cabinet	Door	Solid	Wood	0.01
706	1953 Bldg.	124	XRF	5/18/98	1	Room	4	Closet	Wall	Solid	Wood	0.36
707	1953 Bldg.	125	XRF	5/18/98	1	Room	4	Closet	Shelf	Solid	Wood	0.36
708	1953 Bldg.	126	XRF	5/18/98	1	Room	5	Wall	Wall	Solid	Plaster	0.16
709	1953 Bldg.	127	XRF	5/18/98	1	Room	5	Wall	Wall	Solid	Plaster	0.03
710	1953 Bldg.	128	XRF	5/18/98	1	Room	5	Ceiling		Solid	Plaster	0
711	1953 Bldg.	129	XRF	5/18/98	1	Room	5	Wall	Baseboar	Solid	Wood	0.02
712	1953 Bldg.	130	XRF	5/18/98	1	Room	5	Wall	Diffuser	Solid	Metal	0
713	1953 Bldg.	131	XRF	5/18/98	1	Room	6	Wall	Wall	Solid	Concrete	0
714	1953 Bldg.	132	XRF	5/18/98	1	Room	6	Wall	Wall	Solid	Plaster	0
715	1953 Bldg.	133	XRF	5/18/98	1	Room	6	Wall	Midle Wall	Solid	Tile	3.52
716	1953 Bldg.	134	XRF	5/18/98	1	Room	6	Door	Jamb	Solid	Metal	0.01
717	1953 Bldg.	135	XRF	5/18/98	1	Room	6	Door	Casing	Solid	Wood	0
718	1953 Bldg.	136	XRF	5/18/98	1	Room	6	Wall	Baseboar	Solid	Wood	0.27
719	1953 Bldg.	253	XRF	2/15/97	1	Room	6	Ceiling		Solid	Plaster	0.03
720	1953 Bldg.	137	XRF	5/18/98	1	Room	7	Wall	Wall	Solid	Concrete	0
721	1953 Bldg.	138	XRF	5/18/98	1	Room	7	Door	Door	Solid	Wood	0.03
722	1953 Bldg.	139	XRF	5/18/98	1	Room	7	Door	Casing	Solid	Wood	0.02
723	1953 Bldg.	140	XRF	5/18/98	1	Room	7		Elec Pane	Solid	Metal	0
724	1953 Bldg.	141	XRF	5/18/98	1	Room	7	Wall	Midle Wall	Solid	Plaster	0
725	1953 Bldg.	260	XRF	2/15/97	1	Room	7	Ceiling		Solid	Plaster	0.01
726	1953 Bldg.	261	XRF	2/15/97	1	Room	7	Ceiling	Diffuser	Solid	Metal	0.01
727	1953 Bldg.	269	XRF	2/15/97	1	Room	8	Ceiling		Solid	Plaster	0.42
728	1953 Bldg.	270	XRF	2/15/97	1	Room	8	Ceiling		Solid	Plaster	0.53
729	1953 Bldg.	266	XRF	2/15/97	1	Room	9	Ceiling		Solid	Plaster	0
730	1953 Bldg.	267	XRF	2/15/97	1	Room	9	Floor		Solid	Concrete	0.07
731	1953 Bldg.	268	XRF	2/15/97	1	Room	9	Floor	Hatch	Solid	Metal	0.02
732	1953 Bldg.	287	XRF	2/15/97	1	Room	10	Ceiling		Solid	Plaster	0.13
733	1953 Bldg.	288	XRF	2/15/97	1	Room	11	Ceiling		Solid	Plaster	0.25
734	1953 Bldg.	276	XRF	2/15/97	1	Room	101	Wall	Wall	Solid	Plaster	0.05
735	1953 Bldg.	144	XRF	2/12/97	1	Room	106	Wall	Wall	Solid	Concrete	0
736	1953 Bldg.	145	XRF	2/12/97	1	Room	106	Wall	Wall	Solid	Concrete	0.08
737	1953 Bldg.	146	XRF	2/12/97	1	Room	106	Wall	Midle Wall	Solid	Metal	0.05
738	1953 Bldg.	147	XRF	2/12/97	1	Room	106	Door	Door	Solid	Wood	0.01
739	1953 Bldg.	148	XRF	2/12/97	1	Room	106	Door	Casing	Solid	Wood	0.03
740	1953 Bldg.	149	XRF	2/12/97	1	Room	106	Window	Stool	Solid	Wood	0.03
741	1953 Bldg.	150	XRF	2/12/97	1	Room	106	Window	Mullion	Solid	Plaster	0.06
742	1953 Bldg.	151	XRF	2/12/97	1	Room	106		Univent	Solid	Metal	0.03
743	1953 Bldg.	152	XRF	2/12/97	1	Room	106	Bookcase	Shelf	Solid	Wood	0.03
744	1953 Bldg.	153	XRF	2/12/97	1	Room	106	Bookcase	Inside	Solid	Wood	0.01
745	1953 Bldg.	154	XRF	2/12/97	1	Room	106	Cabinet	Door	Solid	Wood	0.02
746	1953 Bldg.	155	XRF	2/12/97	1	Room	106	Cabinet	Inside	Solid	Wood	0
747	1953 Bldg.	156	XRF	2/12/97	1	Room	106	Cabinet	Shelf	Solid	Wood	0
748	1953 Bldg.	157	XRF	2/12/97	1	Room	106	Window	Panel	Solid	Metal	1.68
749	1953 Bldg.	158	XRF	2/12/97	1	Room	106	Ceiling		Solid	Plaster	0.03
750	1953 Bldg.	159	XRF	2/12/97	1	Room	106		Univent	Solid	Metal	0.02
751	1953 Bldg.	160	XRF	2/12/97	1	Room	106	Wall	Baseboar	Solid	Wood	0.01
752	1953 Bldg.	161	XRF	2/12/97	1	Room	106	Chalkboar	Rail	Solid	Wood	0.02
753	1953 Bldg.	162	XRF	2/12/97	1	Room	106	Wall	Wall Rgstr	Solid	Metal	0.04
754	1953 Bldg.	254	XRF	2/15/97	1	Room	107	Ceiling		Solid	Plaster	0.02
755	1953 Bldg.	255	XRF	2/15/97	1	Room	108	Ceiling		Solid	Plaster	0.02
756	1953 Bldg.	256	XRF	2/15/97	1	Room	109	Ceiling		Solid	Plaster	0.01
757	1953 Bldg.	257	XRF	2/15/97	1	Room	110	Ceiling		Solid	Plaster	0.01

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L	
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result	
758	1953 Bldg.	258	XRF	2/15/97	1	Room	111	Ceiling		Solid	Plaster	0.02	
759	1953 Bldg.	163	XRF	2/12/97	1	Room	112	Wall	Wall	Solid	Plaster	0.07	
760	1953 Bldg.	164	XRF	2/12/97	1	Room	112	Wall	Wall	Solid	Plaster	0.09	
761	1953 Bldg.	165	XRF	2/12/97	1	Room	112	Door	Door	Solid	Wood	0.01	
762	1953 Bldg.	166	XRF	2/12/97	1	Room	112	Door	Casing	Solid	Wood	0.03	
763	1953 Bldg.	167	XRF	2/12/97	1	Room	112	Window	Mullion	Solid	Plaster	0.09	
764	1953 Bldg.	168	XRF	2/12/97	1	Room	112		Univent	Solid	Metal	0.07	
765	1953 Bldg.	169	XRF	2/12/97	1	Room	112	Wall	Baseboar	Solid	Wood	0	
766	1953 Bldg.	259	XRF	2/15/97	1	Room	111A	Ceiling		Solid	Plaster	0.03	
767	1974 Bldg.	78	XRF	2/14/97	1	Bath		1	Wall	Wall	Tile	0.29	
768	1974 Bldg.	79	XRF	2/14/97	1	Bath		1	Wall	Wall	Concrte	0.02	
769	1974 Bldg.	80	XRF	2/14/97	1	Bath		1	Ceiling		Drywall	0	
770	1974 Bldg.	81	XRF	2/14/97	1	Bath		1	Floor		Tile	0.04	
771	1974 Bldg.	82	XRF	2/14/97	1	Bath		1	Bath	Stall	Solid	Metal	0.06
772	1974 Bldg.	83	XRF	2/14/97	1	Bath		2	Wall	Wall	Solid	Tile	0.46
773	1974 Bldg.	84	XRF	2/14/97	1	Bath		2	Wall	Wall	Solid	Concrte	0.05
774	1974 Bldg.	85	XRF	2/14/97	1	Bath		2	Bath	Stall	Solid	Metal	0
775	1974 Bldg.	86	XRF	2/14/97	1	Bath		2	Ceiling		Solid	Drywall	0
776	1974 Bldg.	87	XRF	2/14/97	1	Bath		2	Wall	Wall Rgstr	Solid	Drywall	0
777	1974 Bldg.	244	XRF	2/15/97	1	Bath		3	Wall	Wall	Solid	Tile	0.5
778	1974 Bldg.	245	XRF	2/15/97	1	Bath		3	Wall	Wall	Solid	Plaster	0.12
779	1974 Bldg.	246	XRF	2/15/97	1	Bath		3	Wall	Wall	Solid	Concrte	0.01
780	1974 Bldg.	247	XRF	2/15/97	1	Bath		3	Door	Jamb	Solid	Metal	0
781	1974 Bldg.	248	XRF	2/15/97	1	Bath		3	Door	Jamb	Solid	Metal	0.12
782	1974 Bldg.	249	XRF	2/15/97	1	Bath		3	Door	Jamb	Solid	Metal	0.22
783	1974 Bldg.	250	XRF	2/15/97	1	Bath		3	Wall	Wall Rgstr	Solid	Metal	0
784	1974 Bldg.	251	XRF	2/15/97	1	Bath		3	Wall	Wall Rgstr	Solid	Metal	3.67
785	1974 Bldg.	172	XRF	2/13/97	1	Hall		1	Wall	Wall	Solid	Concrte	0.01
786	1974 Bldg.	173	XRF	2/13/97	1	Hall		1	Wall	Wall	Solid	Plaster	0.26
787	1974 Bldg.	174	XRF	2/13/97	1	Hall		1	Wall	Baseboar	Solid	Tile	0.16
788	1974 Bldg.	175	XRF	2/13/97	1	Hall		1	Wall	Wall	Solid	Concrte	0.01
789	1974 Bldg.	176	XRF	2/13/97	1	Hall		1	Wall	Wall	Solid	Plaster	0.21
790	1974 Bldg.	177	XRF	2/13/97	1	Hall		1	Door	Door	Solid	Metal	0.01
791	1974 Bldg.	178	XRF	2/13/97	1	Hall		1	Door	Jamb	Solid	Metal	0
792	1974 Bldg.	179	XRF	2/13/97	1	Hall		1	Elevator	Door	Solid	Metal	0
793	1974 Bldg.	180	XRF	2/13/97	1	Hall		1	Door	Jamb	Solid	Metal	0.03
794	1974 Bldg.	181	XRF	2/13/97	1	Hall		1	Door	Door	Solid	Metal	0
795	1974 Bldg.	6	XRF	2/14/97	1	Hall		1	Door	Door	Solid	Metal	0
796	1974 Bldg.	7	XRF	2/14/97	1	Hall		1	Door	Casing	Solid	Metal	0
797	1974 Bldg.	8	XRF	2/14/97	1	Hall		1	Radiator	Solid	Metal	0.02	
798	1974 Bldg.	9	XRF	2/14/97	1	Hall		1	Door	Door	Solid	Wood	0
799	1974 Bldg.	10	XRF	2/14/97	1	Hall		1	Fire Ext.	Cabinet	Solid	Metal	0.34
800	1974 Bldg.	11	XRF	2/14/97	1	Hall		1	Wall	Wall Rgstr	Solid	Metal	0
801	1974 Bldg.	69	XRF	2/14/97	1	Hall		1	Closet	Wall	Solid	Concrte	0
802	1974 Bldg.	70	XRF	2/14/97	1	Hall		1	Ceiling		Solid	Concrte	0
803	1974 Bldg.	71	XRF	2/14/97	1	Hall		1	Closet	Shelf	Solid	Concrte	0
804	1974 Bldg.	72	XRF	2/14/97	1	Hall		1	Door	Jamb	Solid	Metal	0
805	1974 Bldg.	73	XRF	2/14/97	1	Hall		1	Door	Jamb	Solid	Metal	0.01
806	1974 Bldg.	205	XRF	2/20/97	1	Outside	0	0	Door	Door	Solid	Metal	0.01
807	1974 Bldg.	206	XRF	2/20/97	1	Outside	0	0	Door	Jamb	Solid	Metal	0
808	1974 Bldg.	207	XRF	2/20/97	1	Outside	0	0	Garage	Door	Solid	Metal	0.01
809	1974 Bldg.	208	XRF	2/20/97	1	Outside	0	0	Door	Jamb	Solid	Wood	0
810	1974 Bldg.	209	XRF	2/20/97	1	Outside	0	0	Soffit		Solid	Plaster	2.96
811	1974 Bldg.	210	XRF	2/20/97	1	Outside	0	0	Door	Door	Solid	Metal	0.01
812	1974 Bldg.	211	XRF	2/20/97	1	Outside	0	0	Door	Jamb	Solid	Metal	0
813	1974 Bldg.	212	XRF	2/20/97	1	Outside	0	0	Stairs	Hand rail	Solid	Metal	0.01
814	1974 Bldg.	94	XRF	2/14/97	2	Room	1	Wall	Midle Wall	Solid	Plaster	0.06	
815	1974 Bldg.	95	XRF	2/14/97	2	Room	1	Wall	Wall	Solid	Concrte	0.02	
816	1974 Bldg.	96	XRF	2/14/97	2	Room	1	Wall	Wall	Solid	Concrte	0.01	
817	1974 Bldg.	97	XRF	2/14/97	2	Room	1	Elevator	Door	Solid	Metal	0.01	
818	1974 Bldg.	98	XRF	2/14/97	2	Room	1	Elevator D	Jamb	Solid	Metal	0.01	
819	1974 Bldg.	99	XRF	2/14/97	2	Room	1	Door	Casing	Solid	Metal	0	
820	1974 Bldg.	100	XRF	2/14/97	2	Room	1	1	Radiator	Solid	Metal	0	

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result
821	1974 Bldg.	101	XRF	2/14/97	2	Room	1	Wall	Wall	Solid	Concrete	0.01
822	1974 Bldg.	102	XRF	2/14/97	2	Room	1	Wall	Baseboar	Solid	Tile	0.17
823	1974 Bldg.	103	XRF	2/14/97	2	Room	1	Fire Ext.	Cabinet	Solid	Metal	0.43
824	1974 Bldg.	104	XRF	2/14/97	2	Room	1	Floor		Solid	Tile	0.09
825	1974 Bldg.	105	XRF	2/14/97	2	Room	1	Elec Pane	Solid	Metal	0	
826	1974 Bldg.	106	XRF	2/14/97	2	Room	1	Wall	Wall Rgstr	Solid	Metal	0
827	1974 Bldg.	107	XRF	2/14/97	2	Room	1	Wall	Wall	Solid	Drywall	0.01
828	1974 Bldg.	64	XRF	2/14/97	1	Room	2	Wall	Midle Wall	Solid	Metal	0.01
829	1974 Bldg.	65	XRF	2/14/97	1	Room	2	Wall	Midle Wall	Solid	Metal	0.05
830	1974 Bldg.	66	XRF	2/14/97	1	Room	2	Door	Jamb	Solid	Metal	0.02
831	1974 Bldg.	67	XRF	2/14/97	1	Room	2	Wall	Baseboar	Solid	Tile	0.08
832	1974 Bldg.	68	XRF	2/14/97	1	Room	2	Wall	Wall Rgstr	Solid	Metal	0
833	1974 Bldg.	227	XRF	2/15/97	2	Room	2	Wall	Midle Wall	Solid	Concrete	0.04
834	1974 Bldg.	228	XRF	2/15/97	2	Room	2	Door	Jamb	Solid	Metal	0
835	1974 Bldg.	229	XRF	2/15/97	2	Room	2	Celling		Solid	Drywall	0.02
836	1974 Bldg.	74	XRF	2/14/97	1	Room	3	Wall	Midle Wall	Solid	Concrete	0
837	1974 Bldg.	75	XRF	2/14/97	1	Room	3	Door	Jamb	Solid	Metal	0
838	1974 Bldg.	76	XRF	2/14/97	1	Room	3	Wall	Wall Rgstr	Solid	Metal	0
839	1974 Bldg.	77	XRF	2/14/97	1	Room	3	Celing		Solid	Drywall	0.03
840	1974 Bldg.	230	XRF	2/15/97	2	Room	3	Wall	Midle Wall	Solid	Concrete	0
841	1974 Bldg.	231	XRF	2/15/97	2	Room	3	Door	Jamb	Solid	Metal	0
842	1974 Bldg.	232	XRF	2/15/97	2	Room	3	Wall	Baseboar	Solid	Tile	0.04
843	1974 Bldg.	233	XRF	2/15/97	2	Room	3	Cabinet	Door	Solid	Wood	0.03
844	1974 Bldg.	234	XRF	2/15/97	2	Room	3	Cabinet	Inside	Solid	Wood	0
845	1974 Bldg.	235	XRF	2/15/97	2	Room	4	Wall	Midle Wall	Solid	Concrete	0
846	1974 Bldg.	236	XRF	2/15/97	2	Room	4	Door	Jamb	Solid	Metal	0
847	1974 Bldg.	237	XRF	2/15/97	2	Room	4	Wall	Baseboar	Solid	Tile	0.13
848	1974 Bldg.	238	XRF	2/15/97	2	Room	5	Wall	Midle Wall	Solid	Concrete	0.02
849	1974 Bldg.	239	XRF	2/15/97	2	Room	5	Door	Jamb	Solid	Metal	0.05
850	1974 Bldg.	240	XRF	2/15/97	2	Room	5	Celling		Solid	Drywall	0
851	1974 Bldg.	12	XRF	2/14/97	1	Room	100	Wall	Wall	Solid	Concrete	0.02
852	1974 Bldg.	13	XRF	2/14/97	1	Room	100	Wall	Wall	Solid	Concrete	0.03
853	1974 Bldg.	14	XRF	2/14/97	1	Room	100	Cabinet	Door	Solid	Metal	0
854	1974 Bldg.	15	XRF	2/14/97	1	Room	100	Cabinet	Door	Solid	Metal	0
855	1974 Bldg.	16	XRF	2/14/97	1	Room	100	Univent	Solid	Metal	0	
856	1974 Bldg.	17	XRF	2/14/97	1	Room	100	Univent	Solid	Metal	0.01	
857	1974 Bldg.	18	XRF	2/14/97	1	Room	100	Door	Jamb	Solid	Metal	0
858	1974 Bldg.	19	XRF	2/14/97	1	Room	100	Cabinet	Door	Solid	Metal	0.01
859	1974 Bldg.	20	XRF	2/14/97	1	Room	100	Cabinet	Door	Solid	Wood	0
860	1974 Bldg.	21	XRF	2/14/97	1	Room	100	Cabinet	Door	Solid	Wood	0.03
861	1974 Bldg.	22	XRF	2/14/97	1	Room	100	Cabinet	Door	Solid	Wood	0
862	1974 Bldg.	23	XRF	2/14/97	1	Room	100	Cabinet	Shelf	Solid	Wood	0
863	1974 Bldg.	24	XRF	2/14/97	1	Room	100	Cabinet	Inside	Solid	Wood	0
864	1974 Bldg.	25	XRF	2/14/97	1	Room	100	Wall	Baseboar	Solid	Tile	0.2
865	1974 Bldg.	45	XRF	2/14/97	1	Room	130	Wall	Midle Wall	Solid	Tile	0
866	1974 Bldg.	46	XRF	2/14/97	1	Room	130	Door	Door	Solid	Metal	0.01
867	1974 Bldg.	47	XRF	2/14/97	1	Room	130	Door	Jamb	Solid	Metal	0
868	1974 Bldg.	48	XRF	2/14/97	1	Room	130	Door	Jamb	Solid	Metal	0
869	1974 Bldg.	49	XRF	2/14/97	1	Room	130	Window	Casing	Solid	Metal	0.01
870	1974 Bldg.	50	XRF	2/14/97	1	Room	130	Univent	Solid	Metal	0	
871	1974 Bldg.	51	XRF	2/14/97	1	Room	130	Univent	Solid	Metal	0.02	
872	1974 Bldg.	52	XRF	2/14/97	1	Room	130	Heat	Vent	Solid	Metal	0
873	1974 Bldg.	53	XRF	2/14/97	1	Room	130	Wall	Baseboar	Solid	Tile	0.21
874	1974 Bldg.	54	XRF	2/14/97	1	Room	130	Wall	Wall	Solid	Drywall	0.03
875	1974 Bldg.	55	XRF	2/14/97	1	Room	130	Wall	Wall Rgstr	Solid	Metal	0.02
876	1974 Bldg.	29	XRF	2/14/97	1	Room	131	Wall	Wall	Solid	Concrete	0.02
877	1974 Bldg.	30	XRF	2/14/97	1	Room	131	Wall	Midle Wall	Solid	Concrete	0
878	1974 Bldg.	31	XRF	2/14/97	1	Room	131	Wall	Wall	Solid	Drywall	0.01
879	1974 Bldg.	32	XRF	2/14/97	1	Room	131	Door	Door	Solid	Wood	0
880	1974 Bldg.	33	XRF	2/14/97	1	Room	131	Door	Jamb	Solid	Metal	0.01
881	1974 Bldg.	35	XRF	2/14/97	1	Room	131	Door	Jamb	Solid	Metal	0
882	1974 Bldg.	36	XRF	2/14/97	1	Room	131	Window	Casing	Solid	Metal	0.01
883	1974 Bldg.	37	XRF	2/14/97	1	Room	131	Univent	Solid	Metal	0	

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result
884	1974 Bldg.	38	XRF	2/14/97	1	Room	131	Univent	Solid	Metal		0
885	1974 Bldg.	39	XRF	2/14/97	1	Room	131	Radiator	Solid	Metal		0
886	1974 Bldg.	40	XRF	2/14/97	1	Room	131	Baseboar	Solid	Tile		0.08
887	1974 Bldg.	41	XRF	2/14/97	1	Room	131	Wall	Wall Rgstr	Solid	Metal	0
888	1974 Bldg.	335	XRF	2/16/97	1	Room	150	Wall	Wall	Solid	Concrte	0
889	1974 Bldg.	336	XRF	2/16/97	1	Room	150	Wall	Midle Wall	Solid	Concrte	0
890	1974 Bldg.	337	XRF	2/16/97	1	Room	150	Door	Door	Solid	Metal	0
891	1974 Bldg.	338	XRF	2/16/97	1	Room	150	Door	Jamb	Solid	Metal	0.01
892	1974 Bldg.	339	XRF	2/16/97	1	Room	150	Wall	Midle Wall	Solid	Concrte	0.01
893	1974 Bldg.	340	XRF	2/16/97	1	Room	150	Radiator	Solid	Metal		0.04
894	1974 Bldg.	341	XRF	2/16/97	1	Room	150	Casling	Solid	Wood		0
895	1974 Bldg.	342	XRF	2/16/97	1	Room	150	Wall	Baseboar	Solid	Tile	0.07
896	1974 Bldg.	343	XRF	2/16/97	1	Room	150	Basketball	Rim	Solid	Metal	1.58
897	1974 Bldg.	344	XRF	2/16/97	1	Room	150	Basketball	Backboar	Solid	Metal	0
898	1974 Bldg.	345	XRF	2/16/97	1	Room	150	Pipe		Solid	Metal	0.02
899	1974 Bldg.	346	XRF	2/16/97	1	Room	150	Bracket		Solid	Wood	0
900	1974 Bldg.	347	XRF	2/16/97	1	Room	150	Wall	Wall Rgstr	Solid	Metal	0
901	1974 Bldg.	108	XRF	2/14/97	2	Room	200	Wall	Wall	Solid	Concrte	0.01
902	1974 Bldg.	109	XRF	2/14/97	2	Room	200	Door	Jamb	Solid	Metal	0
903	1974 Bldg.	110	XRF	2/14/97	2	Room	200	Radiator	Solid	Metal		0.02
904	1974 Bldg.	111	XRF	2/14/97	2	Room	200	Wall	Baseboar	Solid	Tile	0.22
905	1974 Bldg.	112	XRF	2/14/97	2	Room	200	Wall	Midle Wall	Solid	Concrte	0.01
906	1974 Bldg.	113	XRF	2/14/97	2	Room	200	Ceiling		Solid	Drywall	0.01
907	1974 Bldg.	114	XRF	2/14/97	2	Room	200	Ceiling	Hatch	Solid	Metal	0
908	1974 Bldg.	115	XRF	2/14/97	2	Room	201	Wall	Wall	Solid	Concrte	0
909	1974 Bldg.	116	XRF	2/14/97	2	Room	201	Wall	Baseboar	Solid	Tile	0.1
910	1974 Bldg.	117	XRF	2/14/97	2	Room	201	Door	Jamb	Solid	Metal	0
911	1974 Bldg.	118	XRF	2/14/97	2	Room	202	Wall	Midle Wall	Solid	Plaster	0.14
912	1974 Bldg.	119	XRF	2/14/97	2	Room	202	Wall	Midle Wall	Solid	Concrte	0.02
913	1974 Bldg.	120	XRF	2/14/97	2	Room	202	Wall	Wall	Solid	Concrte	0.01
914	1974 Bldg.	121	XRF	2/14/97	2	Room	202	Wall	Midle Wall	Solid	Concrte	0
915	1974 Bldg.	122	XRF	2/14/97	2	Room	202	Ladder		Solid	Metal	0
916	1974 Bldg.	123	XRF	2/14/97	2	Room	202	Wall	Wall	Solid	Plaster	0.01
917	1974 Bldg.	124	XRF	2/14/97	2	Room	202	Ceiling		Solid	Plaster	0
918	1974 Bldg.	125	XRF	2/14/97	2	Room	202	Ceiling	Hatch	Solid	Metal	0.12
919	1974 Bldg.	174	XRF	2/15/97	2	Room	207	Wall	Midle Wall	Solid	Concrte	0
920	1974 Bldg.	175	XRF	2/15/97	2	Room	207	Door	Casing	Solid	Metal	0.01
921	1974 Bldg.	176	XRF	2/15/97	2	Room	207	Wall	Baseboar	Solid	Tile	0.13
922	1974 Bldg.	126	XRF	2/14/97	2	Room	208	Wall	Midle Wall	Solid	Concrte	0.05
923	1974 Bldg.	127	XRF	2/14/97	2	Room	208	Wall	Midle Wall	Solid	Concrte	0.03
924	1974 Bldg.	128	XRF	2/14/97	2	Room	208		Radiator	Solid	Metal	0
925	1974 Bldg.	129	XRF	2/14/97	2	Room	208		Radiator	Solid	Metal	0
926	1974 Bldg.	130	XRF	2/14/97	2	Room	208	Wall	Wall	Solid	Drywall	0.01
927	1974 Bldg.	131	XRF	2/14/97	2	Room	208	Cabinet	Door	Solid	Metal	0
928	1974 Bldg.	132	XRF	2/14/97	2	Room	208	Wall	Baseboar	Solid	Tile	0.09
929	1974 Bldg.	153	XRF	2/15/97	2	Room	208	Door	Door	Solid	Wood	0
930	1974 Bldg.	133	XRF	2/14/97	2	Room	209	Wall	Wall	Solid	Plaster	0.02
931	1974 Bldg.	134	XRF	2/14/97	2	Room	209	Wall	Midle Wall	Solid	Concrte	0.01
932	1974 Bldg.	135	XRF	2/14/97	2	Room	209	Wall	Wall	Solid	Drywall	0
933	1974 Bldg.	136	XRF	2/14/97	2	Room	209		Radiator	Solid	Metal	0.01
934	1974 Bldg.	137	XRF	2/14/97	2	Room	209		Univent	Solid	Metal	0
935	1974 Bldg.	148	XRF	2/15/97	2	Room	209	Cabinet	Door	Solid	Metal	0
936	1974 Bldg.	149	XRF	2/15/97	2	Room	209	Cabinet	Shelf	Solid	Metal	0.01
937	1974 Bldg.	150	XRF	2/15/97	2	Room	209	Wall	Baseboar	Solid	Tile	0.17
938	1974 Bldg.	151	XRF	2/15/97	2	Room	209	Door	Jamb	Solid	Metal	0
939	1974 Bldg.	152	XRF	2/15/97	2	Room	209	Door	Door	Solid	Wood	0
940	1974 Bldg.	154	XRF	2/15/97	2	Room	210	Wall	Wall	Solid	Concrte	0.01
941	1974 Bldg.	155	XRF	2/15/97	2	Room	210	Wall	Midle Wall	Solid	Drywall	0.03
942	1974 Bldg.	156	XRF	2/15/97	2	Room	210	Wall	Wall	Solid	Drywall	0.02
943	1974 Bldg.	157	XRF	2/15/97	2	Room	210	Door	Door	Solid	Wood	0
944	1974 Bldg.	158	XRF	2/15/97	2	Room	210	Door	Jamb	Solid	Metal	0
945	1974 Bldg.	159	XRF	2/15/97	2	Room	210		Univent	Solid	Metal	0
946	1974 Bldg.	160	XRF	2/15/97	2	Room	210		Univent	Solid	Metal	0

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result
947	1974 Bldg.	161	XRF	2/15/97	2	Room	210	Radiator	Solid	Metal		0.01
948	1974 Bldg.	162	XRF	2/15/97	2	Room	210	Baseboar	Solid	Tile		0.12
949	1974 Bldg.	163	XRF	2/15/97	2	Room	211	Wall	Solid	Concrte		0.01
950	1974 Bldg.	164	XRF	2/15/97	2	Room	211	Wall	Solid	Concrte		0
951	1974 Bldg.	165	XRF	2/15/97	2	Room	211	Wall	Solid	Drywall		0.01
952	1974 Bldg.	166	XRF	2/15/97	2	Room	211	Door	Solid	Wood		0
953	1974 Bldg.	167	XRF	2/15/97	2	Room	211	Door	Jamb	Solid	Metal	
954	1974 Bldg.	168	XRF	2/15/97	2	Room	211	Univent	Solid	Metal		0
955	1974 Bldg.	169	XRF	2/15/97	2	Room	211		Univent	Solid	Metal	
956	1974 Bldg.	170	XRF	2/15/97	2	Room	211	Wall	Baseboar	Solid	Tile	0.04
957	1974 Bldg.	171	XRF	2/15/97	2	Room	211	Cabinet	Door	Solid	Tile	
958	1974 Bldg.	172	XRF	2/15/97	2	Room	211	Cabinet	Shelf	Solid	Tile	
959	1974 Bldg.	180	XRF	2/15/97	2	Room	212	Wall	Wall	Solid	Concrte	0.01
960	1974 Bldg.	181	XRF	2/15/97	2	Room	212	Wall	Wall	Solid	Concrte	0
961	1974 Bldg.	182	XRF	2/15/97	2	Room	212	Wall	Wall	Solid	Drywall	0
962	1974 Bldg.	183	XRF	2/15/97	2	Room	212	Door	Door	Solid	Wood	
963	1974 Bldg.	184	XRF	2/15/97	2	Room	212	Door	Jamb	Solid	Metal	0.01
964	1974 Bldg.	185	XRF	2/15/97	2	Room	212		Univent	Solid	Metal	
965	1974 Bldg.	186	XRF	2/15/97	2	Room	212		Univent	Solid	Metal	
966	1974 Bldg.	187	XRF	2/15/97	2	Room	212	Cabinet	Door	Solid	Metal	
967	1974 Bldg.	188	XRF	2/15/97	2	Room	212	Cabinet	Shelf	Solid	Metal	
968	1974 Bldg.	189	XRF	2/15/97	2	Room	212	Wall	Baseboar	Solid	Tile	0.06
969	1974 Bldg.	190	XRF	2/15/97	2	Room	212	Wall	Midle Wall	Solid	Drywall	0.24
970	1974 Bldg.	191	XRF	2/15/97	2	Room	213	Wall	Wall	Solid	Concrte	0
971	1974 Bldg.	192	XRF	2/15/97	2	Room	213	Wall	Wall	Solid	Concrte	0.01
972	1974 Bldg.	193	XRF	2/15/97	2	Room	213	Wall	Midle Wall	Solid	Drywall	0.01
973	1974 Bldg.	194	XRF	2/15/97	2	Room	213	Wall	Wall	Solid	Drywall	0.01
974	1974 Bldg.	195	XRF	2/15/97	2	Room	213	Door	Door	Solid	Wood	0
975	1974 Bldg.	196	XRF	2/15/97	2	Room	213	Door	Jamb	Solid	Metal	0
976	1974 Bldg.	197	XRF	2/15/97	2	Room	213		Univent	Solid	Metal	0
977	1974 Bldg.	198	XRF	2/15/97	2	Room	213		Univent	Solid	Metal	0.01
978	1974 Bldg.	199	XRF	2/15/97	2	Room	213	Cabinet	Door	Solid	Metal	
979	1974 Bldg.	200	XRF	2/15/97	2	Room	213	Cabinet	Floor	Solid	Metal	0.03
980	1974 Bldg.	201	XRF	2/15/97	2	Room	213	Wall	Baseboar	Solid	Tile	0.08
981	1974 Bldg.	202	XRF	2/15/97	2	Room	213	Radiator	Solid	Metal		0
982	1974 Bldg.	216	XRF	2/15/97	2	Room	215	Wall	Midle Wall	Solid	Concrte	0.01
983	1974 Bldg.	217	XRF	2/15/97	2	Room	215	Wall	Wall	Solid	Concrte	0.02
984	1974 Bldg.	218	XRF	2/15/97	2	Room	215	Wall	Wall	Solid	Drywall	0
985	1974 Bldg.	219	XRF	2/15/97	2	Room	215	Wall	Wall	Solid	Drywall	0
986	1974 Bldg.	220	XRF	2/15/97	2	Room	215	Door	Door	Solid	Wood	0
987	1974 Bldg.	221	XRF	2/15/97	2	Room	215	Door	Jamb	Solid	Metal	0
988	1974 Bldg.	222	XRF	2/15/97	2	Room	215		Univent	Solid	Metal	0
989	1974 Bldg.	223	XRF	2/15/97	2	Room	215		Univent	Solid	Metal	0
990	1974 Bldg.	224	XRF	2/15/97	2	Room	215	Cabinet	Outside	Solid	Metal	0
991	1974 Bldg.	225	XRF	2/15/97	2	Room	215	Cabinet	Shelf	Solid	Metal	0
992	1974 Bldg.	226	XRF	2/15/97	2	Room	215	Wall	Baseboar	Solid	Tile	0.1
993	1974 Bldg.	203	XRF	2/15/97	2	Room	216	Wall	Wall	Solid	Drywall	0
994	1974 Bldg.	204	XRF	2/15/97	2	Room	216	Wall	Wall	Solid	Drywall	0
995	1974 Bldg.	205	XRF	2/15/97	2	Room	216	Wall	Wall	Solid	Concrte	0.01
996	1974 Bldg.	206	XRF	2/15/97	2	Room	216	Wall	Midle Wall	Solid	Concrte	0.01
997	1974 Bldg.	207	XRF	2/15/97	2	Room	216		Univent	Solid	Metal	0
998	1974 Bldg.	208	XRF	2/15/97	2	Room	216		Univent	Solid	Metal	0
999	1974 Bldg.	209	XRF	2/15/97	2	Room	216	Radiator	Solid	Metal		0
1000	1974 Bldg.	210	XRF	2/15/97	2	Room	216	Door	Door	Solid	Wood	0
1001	1974 Bldg.	211	XRF	2/15/97	2	Room	216	Door	Jamb	Solid	Metal	0
1002	1974 Bldg.	212	XRF	2/15/97	2	Room	216	Wall	Baseboar	Solid	Tile	0.31
1003	1974 Bldg.	213	XRF	2/15/97	2	Room	216	Cabinet	Door	Solid	Metal	0
1004	1974 Bldg.	214	XRF	2/15/97	2	Room	216	Cabinet	Floor	Solid	Metal	0
1005	1974 Bldg.	26	XRF	2/14/97	1	Room	100A	Wall	Midle Wall	Solid	Concrte	0
1006	1974 Bldg.	27	XRF	2/14/97	1	Room	100A	Wall	Baseboar	Solid	Tile	0.08
1007	1974 Bldg.	28	XRF	2/14/97	1	Room	100A	Door	Jamb	Solid	Metal	0
1008	1974 Bldg.	56	XRF	2/14/97	1	Room	130A	Wall	Midle Wall	Solid	Concrte	0.06
1009	1974 Bldg.	57	XRF	2/14/97	1	Room	130A	Door	Casing	Solid	Concrte	0

Saint Paul Public Schools
 Chelsea Heights Elementary
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L	
3	Site	Sample#	Analysis	Date	Floor	Area	Room#	Componen	Feature	Condition	Substrate	Result	
1010	1974 Bldg.	58	XRF	2/14/97	1	Room	130A	Wall	Baseboar	Solid	Tile	0.13	
1011	1974 Bldg.	42	XRF	2/14/97	1	Room	131A	Wall	Midle Wall	Solid	Concrte	0	
1012	1974 Bldg.	43	XRF	2/14/97	1	Room	131A	Door	Casing	Solid	Metal	0	
1013	1974 Bldg.	44	XRF	2/14/97	1	Room	131A	Wall	Baseboar	Solid	Tile	0.06	
1014	1974 Bldg.	59	XRF	2/14/97	1	Room	1A	Wall	Midle Wall	Solid	Concrte	0.02	
1015	1974 Bldg.	60	XRF	2/14/97	1	Room	1A	Wall	Wall	Solid	Concrte	0	
1016	1974 Bldg.	61	XRF	2/14/97	1	Room	1A	Door	Jamb	Solid	Metal	0	
1017	1974 Bldg.	62	XRF	2/14/97	1	Room	1A	Wall	Baseboar	Solid	Tile	0.05	
1018	1974 Bldg.	63	XRF	2/14/97	1	Room	1A	Wall	Panel	Solid	Metal	0	
1019	1974 Bldg.	177	XRF	2/15/97	2	Room	1A	Wall	Midle Wall	Solid	Concrte	0.01	
1020	1974 Bldg.	178	XRF	2/15/97	2	Room	1A	Ceiling		Solid	Drywall	0.06	
1021	1974 Bldg.	179	XRF	2/15/97	2	Room	1A	Door	Casing	Solid	Metal	0	
1022	1974 Bldg.	88	XRF	2/14/97	1	Stairwell		1	Wall	Wall	Solid	Concrete	0.01
1023	1974 Bldg.	89	XRF	2/14/97	1	Stairwell		1	Wall	Midle Wall	Solid	Concrte	0.01
1024	1974 Bldg.	90	XRF	2/14/97	1	Stairwell		1	Stairs	Stringer	Solid	Concrte	0.01
1025	1974 Bldg.	92	XRF	2/14/97	1	Stairwell		1	Wall	Baseboar	Solid	Wood	0.03
1026	1974 Bldg.	93	XRF	2/14/97	1	Stairwell		1	Stairs	Rail cap	Solid	Metal	0
1027	1974 Bldg.	241	XRF	2/15/97	2	Stairwell		2	Wall	Midle Wall	Solid	Concrte	0.01
1028	1974 Bldg.	242	XRF	2/15/97	2	Stairwell		2	Stairs	Rail cap	Solid	Metal	0.02
1029	1974 Bldg.	243	XRF	2/15/97	2	Stairwell		2	Stairs	Stringer	Solid	Metal	0.03

APPENDIX B

LABORATORY SAMPLE ANALYSIS DATA

LABORATORY ANALYSIS REPORT**DATE:** May 12, 1997**PAGE:** 1 Of 3**CLIENT:** Midwest Environmental Cons.
5385 401st Ave. NW
Dalbo, MN 55017**PROJECT NO.:** 041097-200888
COLLECTION DATE: 4/05/97
COLLECTED BY: Client
RECEIVED DATE: 4/10/97
PROJECT DESCRIPT.: 62/0196E**CONTACT:** Greg Myers/Richard Cox

<u>SAMPLE #</u>	<u>DESCP.</u>	<u>MDL</u>	LEAD (6010A)	<u>ANALYSIS</u>
			<u>RESULTS</u>	
			<u>Units=mg/kg</u>	<u>DATE</u>
L972035-1	E-150	20	1300	5/08/97
L972035-2	E-151	22	1300	5/08/97
L972035-3	E-153	27	800	5/08/97
L972035-4	E-157	22	1900	5/08/97
L972035-5	E-213	27	1900	5/08/97
L972035-6	E-214	19	2100	5/08/97
L972035-7	E-228	780	116,000	5/08/97
L972035-8	E-235	14	1600	5/08/97
L972035-9	E-239	34	4000	5/08/97
L972035-10	E-247	20	3300	5/08/97
L972035-11	E-257	14	1600	5/08/97
L972035-12	E-274	12	1500	5/08/97
L972035-13	E-295	45	1500	5/08/97
L972035-14	E-297	25	3100	5/08/97
L972035-15	E-6	15	1200	5/08/97
L972035-16	E-12	44	8200	5/08/97
L972035-17	E-19	26	830	5/08/97
L972035-18	E-28	22	2300	5/08/97
L972035-19	E-32	17	2100	5/08/97
L972035-20	E-41	12	3000	5/08/97
L972035-21	E-46	25	940	5/08/97
L972035-22	E-81	15	680	5/08/97
L972035-23	E-83	15	3100	5/08/97
L972035-24	E-86	13	260	5/08/97
L972035-25	E-93 2/05	27	3900	5/08/97
L972035-26	E-99	17	ND	5/08/97
L972035-27	E-130	24	ND	5/08/97
L972035-28	E-149	12	990	5/08/97
L972035-29	E-358	17	1500	5/08/97

ND means Not Detected or below reported MDL

MDL means Method Detection Limit

mg/kg means Milligrams Per Kilogram which is equivalent to Parts Per Million (ppm)

As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.



A member of The Marmon Group of Companies

LABORATORY ANALYSIS REPORT**DATE:** May 12, 1997**PAGE:** 2 Of 3**CLIENT:** Midwest Environmental Cons.
5385 401st Ave. NW
Dalbo, MN 55017**PROJECT NO.:** 041097-200888
COLLECTION DATE: 4/05/97
COLLECTED BY: Client
RECEIVED DATE: 4/10/97
PROJECT DESCRIPT.: 62/0196E**CONTACT:** Greg Myers/Richard Cox

<u>SAMPLE #</u>	<u>DESCP.</u>	<u>MDL</u>	<u>LEAD</u> (6010A)	<u>ANALYSIS</u>
			<u>RESULTS</u>	
L972035-30	E-359	29	260	5/08/97
L972035-31	E-36	20	610	5/08/97
L972035-32	E-48	18	2200	5/08/97
L972035-33	E-50	48	260	5/08/97
L972035-34	E-65	34	5000	5/08/97
L972035-35	E-92	21	1500	5/09/97
L972035-36	E-93 2/12	16	1300	5/09/97
L972035-37	E-97	16	2400	5/09/97
L972035-38	E-108	64	6000	5/09/97
L972035-39	E-109	45	2000	5/09/97
L972035-40	E-112	50	1600	5/09/97
L972035-41	E-119	76	22,600	5/09/97
L972035-42	E-286	15	150	5/09/97
L972035-43	E-317	610	4100	5/09/97
L972035-44	E-319	20	1900	5/09/97
L972035-45	E-320	15	1500	5/09/97
L972035-46	E-322	44	240	5/09/97
L972035-47	E-186	80	2900	5/09/97

*ND means Not Detected or below reported MDL**MDL means Method Detection Limit**mg/kg means Milligrams Per Kilogram which is equivalent to Parts Per Million (ppm)**As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.*

A member of The Marmon Group of Companies

LABORATORY ANALYSIS REPORT

DATE: May 12, 1997 **PAGE:** 3 Of 3

CLIENT: Midwest Environmental Cons.
5385 401st Ave. NW
Dalbo, MN 55017 **PROJECT NO.:** 041097-200888
COLLECTION DATE: 4/05/97
COLLECTED BY: Client
RECEIVED DATE: 4/10/97
PROJECT DESCRIPT.: 62/0196E

CONTACT: Greg Myers/Richard Cox

This report has been reviewed by me for technical accuracy and completeness. The analyses were performed using EPA or other approved methodologies and the results were reported on an "as received" basis unless otherwise noted. Organic soil analyses were reported on a dry weight basis. The results reported relate only to the items tested. Please contact me if you have any questions or comments regarding this report. Spectrum Labs, Inc. appreciates the opportunity to provide this analytical service for you.

Report Submitted By,



Thomas L. Halverson
Laboratory Manager

TLH:wmc
mec132-2

As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.



KAMON
A member of The Marmon Group of Companies



Midwest Environmental Consulting, L.L.C.

5385 401st Ave. NW, Duluth, MN 55017
612-689-3612/612-757-5541/FAX-612-689-5209

Client Address: 2544 Myrick Road Cok
Contact: Chris Myers / Richard Cox

CHAIN OF CUSTODY RECORD

Project Number: 62-0196E
ST. Paul School District

Project: Custer Heights
Phone/Fax:

Sample ID	Room #	Sample Description	Color	Collection Date/Time	Matrix (Vol/Area)	Analysis Requested
035-62-0196E 2159# 150	3	D Bath Partition	WHITE	4/5/97	-	Pb % wt. or ppm
62-0196E 459# 151	↓ B	Wash Register	WHITE	-	-	
62-0196E 2159# 153	↓ Wall	WALL	GRAY	-	-	
62-0196E 2159# 155	↓ -	CEILINGS	WHITE	-	-	
62-0196E 2161# 4213	A	Door Jams	DR. GRAY	-	-	
62-0196E 2161# 241	↓ D	Door	TAN	-	-	
62-0196E 2161# 228	Z	Door Casings	TAN	-	-	
62-0196E 2161# 235	↓ D	Cabinet Door	WHITE	-	-	
62-0196E 2161# 239	↓ B	Cabinet Door	BROWN	-	-	
62-0196E 2161# 247	201	B Windows Mould	DR. GRAY	-	-	
62-0196E 2161# 257	202	A MIDDLE WDW	BLUE	-	-	
62-0196E 2161# 274	204	A Middle Wdw	Yellow	-	-	
62-0196E 2161# 275	2-0	B Windows Stool	TAN	-	-	
62-0196E 2161# 277	↓ C	Baseboards	TAN	↓	-	

Sampled By: Chris Myers Date: 4/5/97 Time: _____

Delivered By: Chris Myers Date: 4/10/97 Time: 11:30 am

Received By: John Lunk Date: 4/10/97 Time: _____

Delivered By: _____ Date: _____ Time: _____

Received By Lab: John Lunk Date: 4/10/97 Time: 11:30

Disposition of Samples _____

Notes: Report in 10 pm

SITE #6

Midwest Environmental Consulting, L.L.C.



5385 401st Ave. NW, Duluth, MN 55017
612-689-3612/612-757-5541/FAX-612-689-5209

Client Address _____

Contact _____

CHAIN OF CUSTODY RECORD

Project Number 6210196E
Client ST. Paul School District
Project CHESEA HEIGHTS
Phone/Fax _____

Sample ID	Run #	Spec Sample	Description	Collection Date/Time	Matrix (Vol/Area)	Analysis Requested
5 6210196E 2 5 97-#6	1	D	Lower wall	WHITE 4/5/97	—	Pb or UR or PPM
6 6210196E 2 5 97-#7	1	B	Locker	BLUE	—	—
7 6210196E 2 5 97-#8	1	B	Locker	RED	—	—
8 6210196E 2 5 97-#28	101	B	Wardrobe Stool	DR. GREEN	—	—
9 6210196E 2 5 97-#32	102	B	Radiator-Vent.	WHITE	—	—
10 6210196E 2 5 97-#41	102	D	Middle wall	GREEN	—	—
11 6210196E 2 5 97-#44	102	D	Radiator	WHITE	—	—
12 6210196E 2 5 97-#81	2	C	Wire Tarn	WHITE	—	—
13 6210196E 2 5 97-#83	2	D	Wall	WHITE	—	—
14 6210196E 2 5 97-#86	2	C	Upper wall	WHITE	—	—
15 6210196E 2 5 97-#93	3	C	Baseboard	GRAY	—	—
16 6210196E 2 5 97-#99	4	A	Middle wall	WHITE	—	—
17 6210196E 2 5 97-#130	8	C	Middle wall	WHITE	—	—
18 6210196E 2 5 97-#149	3	D	Berry Plantain	BLUE	—	—

Sampled By: J. Ode Date: 4/5/97 Time: _____

Received By: J. Ode Date: _____ Time: _____

Received By Lab: 6/1/97 (Date: 4/10/97 Time: 11:30) Disposition of Samples _____

Notes:

SITE #6

Delivered By: G. M. Myers Date: 4/19/97 Time: 11:30 a.m.

Delivered By: _____ Date: _____ Time: _____

Midwest Environmental Consulting, L.L.C.

5385 401st Ave. NW, Dalbo, MN 55017
612-689-3612/612-757-5541/FAX-612-689-5209



CHAIN OF CUSTODY RECORD

Project Number 6210196E
Client St. Paul Sutton District
Project Cherry Heights
Phone/Fax (651) 481-1111

Client Address 1000 University Street / Minneapolis, MN

Contact John Langill Date: 4/10/97 Time: 11:30 AM

Sample ID	Room #	Size	Sample Description	Color	Collection Date/Time	Matrix (Vol/Area)	Analysis Requested
6210196E 216197 #358	Batt	C	Middle Ware	Red	4/5/97	—	Pb % wt. or PPM
6210196E 216197 #359	↓	C	MIDDLE Ware	Orange	—	—	—
6210196E 212197 #360	1	G	Lower Ware	Blue	—	—	—
6210196E 212197 #483	↓	B	Window Mulsion	White	—	—	—
6210196E 210197 #502	2	A	Lower Ware	Black	—	—	—
6210196E 210197 #653	3	B	Window Casting	Brown	—	—	—
6210196E 212197 #922	2	c	Frac. Panel	White	—	—	—
6210196E 212197 #933	1	c	Frac Ext. Panel	White	—	—	—
6210196E 210197 #977	↓	C	Ware	dk. grey	—	—	—
6210196E 210197 #1086	6	D	Upper Ware	White	—	—	—
6210196E 210197 #1097	1	D	Middle Ware	White	—	—	—
6210196E 210197 #112	↓	-	Floor	Red	—	—	—
6210196E 210197 #119	7	A	Lacons	Green	—	—	—
6210196E 210197 #120	↓	—	—	—	—	—	—

Sampled By: John Langill Date: 4/5/97 Time: 11:30 AM
Received By: John Langill Date: 4/10/97 Time: 11:30 AM

Delivered By: John Langill Date: 4/10/97 Time: 11:30 AM

Delivered By: John Langill Date: 4/10/97 Time: 11:30 AM

Received By Lab: LJ Date: 4/10/97 Time: 11:30 AM Disposition of Samples _____

Notes:

SITE #6



Midwest Environmental Consulting, L.L.C.

5385 401st Ave. NW, Dalbo, MN 55017
612-689-3612/612-757-5541/FAX-612-689-5209

Client Address _____

Client Address -

CHAIN OF CUSTODY RECORD

Project Number 62-0146-E
Client ST. PAUL SCHOOL DISTRICT

Project CHELSEA Heights

Address _____

Sample ID	Room #	Sample Description	Collection Date/Time	Matrix (Vol/Area)	Analysis Requested
	#	Source			
62 0196 E	2 15 97 #286	Bent - CEILING DIFFUSER	WHITE	4/6/97	Pb % wt. or ppm
62 0196 E	2 16 97 #317	Door Handle	Black	—	
62 0196 E	2 16 97 #319	D Window Casink	Black	—	
62 0196 E	2 16 97 #320	B Window Sash	Black	—	
62 0196 E	2 16 97 #322	B PIPE	Black	—	
62 0196 E	2 16 97 #326	Exterior A Door Knob	Orange	—	

Sampled By: S. Omer Received By: _____

Delivered By: Craig Mirek Date: 4/10/97 Time: 11:30 a.m.

Delivered By: _____ Date: _____ Time: _____

卷之三

Notes

Site #16



301 West County Road E2 • St. Paul, MN 55112
(612) 633-0101 • FAX (612) 633-1402

LABORATORY ANALYSIS REPORT

DATE: May 5, 1997

PAGE: 1 Of 1

CLIENT: Midwest Environmental Cons.
5385 401st Ave. NW
Dalbo, MN 55017

PROJECT NO.: 041097-200888
COLLECTION DATE: 4/06/97
COLLECTED BY: Client
RECEIVED DATE: 4/10/97
PROJECT DESCRIPT.: 62/0196E

CONTACT: Greg Myers

<u>ANALYSIS</u> Lead (6010A))	<u>UNITS</u> mg/kg	<u>Sample No.:</u> Sample ID.: E-56	<u>MDL</u> 19	<u>L972032-1</u> ANALYSIS	<u>RESULT</u> ND	<u>DATE</u> 5/05/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>Sample No.:</u> Sample ID.: E-82	<u>MDL</u> 40	<u>L972032-2</u> ANALYSIS	<u>RESULT</u> 14000	<u>DATE</u> 5/05/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>Sample No.:</u> Sample ID.: E-125	<u>MDL</u> 28	<u>L972032-3</u> ANALYSIS	<u>RESULT</u> 67	<u>DATE</u> 5/05/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>Sample No.:</u> Sample ID.: E-178	<u>MDL</u> 33	<u>L972032-4</u> ANALYSIS	<u>RESULT</u> 47	<u>DATE</u> 5/05/97

As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.



A member of The Marmon Group of Companies



301 West County Road E2 • St. Paul, MN 55112
(612) 633-0101 • FAX (612) 633-1402

LABORATORY ANALYSIS REPORT

DATE:	<i>May 5, 1997</i>	PAGE:	<i>1 Of 1</i>
CLIENT:	<i>Midwest Environmental Cons. 5385 401st Ave. NW Dalbo, MN 55017</i>	PROJECT NO.:	<i>041097-200888</i>
		COLLECTION DATE:	<i>4/06/97</i>
		COLLECTED BY:	<i>Client</i>
		RECEIVED DATE:	<i>4/10/97</i>
		PROJECT DESCRIPT.:	<i>62/0196E</i>
CONTACT:	<i>Greg Myers</i>		

<u>ANALYSIS</u>	<u>Sample No.:</u>	<u>Sample ID.:</u>	<u>L972032-5</u>	<u>ANALYSIS</u>
<i>Lead (6010A)</i>	<i>E-245</i>			
	<u>UNITS</u>	<u>MDL</u>	<u>RESULT</u>	<u>DATE</u>
	<i>mg/kg</i>	<i>24</i>	<i>ND</i>	<i>5/05/97</i>

ND means Not Detected or below reported MDL

MDL means Method Detection Limit

mg/kg means Milligrams Per Kilogram which is equivalent to Parts Per Million (ppm)

This report has been reviewed by me for technical accuracy and completeness. The analyses were performed using EPA or other approved methodologies and the results were reported on an "as received" basis unless otherwise noted. Organic soil analyses were reported on a dry weight basis. The results reported relate only to the items tested. Please contact me if you have any questions or comments regarding this report. Spectrum Labs, Inc. appreciates the opportunity to provide this analytical service for you.

Report Submitted By,

Thomas L. Halverson
Laboratory Manager

TLH:wmc
mec125-4

As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.



A member of The Marmon Group of Companies



Midwest Environmental Consulting, L.L.C.

5385 401st Ave NW Dallas MN 55017

613-689-3612/613-757-5541/EAY-613-6

Glossary

Chittenden
Vermont

Contact

CHAIN OF CUSTODY RECORD

Project Number 620196E

Client ST. PAUL SICKLE: District

SCHILLER'S "WIDMER-SCHMIDT" 11

Project Summary

Phone/Fax _____

Sample ID	Room #	Sample Size	Sample Description	Collection Date/Time	Matrix (Vol/Area)	Analysis Requested
62 096E 2 14 97 #56	13A	B	MIDDLE WALL BARTH. PARCEL	WHITE 4/6/97	—	Pb % WT. OR PPM
62 096E 2 14 97 #62	13A	C	CEILING HARSH	Yellow	—	
62 096E 2 14 97 #125	202	-	CEILING HARSH	Grey	—	
62 096E 2 15 97 #130	Rm 1 closet	-	CEILING	White	—	
62 096E - 15 97 #245	13A	3	UPPER WALL	White	—	

Sampled By: *John Cason* Date: *4/6/97* Time: _____

Received By: _____ Date: _____ Time: _____

Received By Lab: LMC Date: 4/10/97 Time: 1130

Notes

Delivered By: George Myers Date: 11/10/87 Time: 11:30 am
Delivered By: _____ Date: _____ Time: _____
Disposition of Samples _____

LABORATORY ANALYSIS REPORT**DATE:** May 5, 1997**PAGE:** 1 Of 3

CLIENT: Midwest Environmental Cons.
5385 401st Ave. NW
Dalbo, MN 55017

PROJECT NO.: 041097-200888
COLLECTION DATE: 4/06/97
COLLECTED BY: Client
RECEIVED DATE: 4/10/97
PROJECT DESCRP.: 62/0196E

CONTACT: Richard Cox

<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>MDL</u> 22	<u>Sample No.:</u> L972034-1 <u>Sample ID.:</u> E-138	<u>RESULT</u> 1500	<u>ANALYSIS</u> <u>DATE</u> 5/05/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>MDL</u> 14	<u>Sample No.:</u> L972034-2 <u>Sample ID.:</u> E-150	<u>RESULT</u> 740	<u>ANALYSIS</u> <u>DATE</u> 5/05/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>MDL</u> 13	<u>Sample No.:</u> L972034-3 <u>Sample ID.:</u> E-163	<u>RESULT</u> 660	<u>ANALYSIS</u> <u>DATE</u> 5/05/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>MDL</u> 13	<u>Sample No.:</u> L972034-4 <u>Sample ID.:</u> E-164	<u>RESULT</u> 660	<u>ANALYSIS</u> <u>DATE</u> 5/05/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>MDL</u> 22	<u>Sample No.:</u> L972034-5 <u>Sample ID.:</u> E-167	<u>RESULT</u> 1200	<u>ANALYSIS</u> <u>DATE</u> 5/05/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>MDL</u> 15	<u>Sample No.:</u> L972034-6 <u>Sample ID.:</u> E-168	<u>RESULT</u> 59	<u>ANALYSIS</u> <u>DATE</u> 5/05/97
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>MDL</u> 46	<u>Sample No.:</u> L972034-7 <u>Sample ID.:</u> E-15	<u>RESULT</u> 2000	<u>ANALYSIS</u> <u>DATE</u> 5/05/97

As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.



A member of The Marmon Group of Companies

LABORATORY ANALYSIS REPORT**DATE:** May 5, 1997**PAGE:**

2 Of 3

CLIENT: Midwest Environmental Cons.
5385 401st Ave. NW
Dalbo, MN 55017**PROJECT NO.:** 041097-200888
COLLECTION DATE: 4/06/97
COLLECTED BY: Client
RECEIVED DATE: 4/10/97
PROJECT DESCRIPT.: 62/0196E**CONTACT:** Richard Cox

<u>ANALYSIS</u>	<u>UNITS</u>	<u>Sample No.:</u> Sample ID.: MDL	<u>L972034-8</u> E-20 RESULT 6000	<u>ANALYSIS</u> <u>DATE</u>
Lead (6010A)	mg/kg	430		5/05/97
<u>ANALYSIS</u>	<u>UNITS</u>	<u>Sample No.:</u> Sample ID.: MDL	<u>L972034-9</u> E-38 RESULT ND	<u>ANALYSIS</u> <u>DATE</u>
Lead (6010A)	mg/kg	18		5/05/97
<u>ANALYSIS</u>	<u>UNITS</u>	<u>Sample No.:</u> Sample ID.: MDL	<u>L972034-10</u> E-66 RESULT 370	<u>ANALYSIS</u> <u>DATE</u>
Lead (6010A)	mg/kg	25		5/05/97
<u>ANALYSIS</u>	<u>UNITS</u>	<u>Sample No.:</u> Sample ID.: MDL	<u>L972034-11</u> E-77 RESULT 3300	<u>ANALYSIS</u> <u>DATE</u>
Lead (6010A)	mg/kg	21		5/05/97
<u>ANALYSIS</u>	<u>UNITS</u>	<u>Sample No.:</u> Sample ID.: MDL	<u>L972034-12</u> E-141 RESULT 14	<u>ANALYSIS</u> <u>DATE</u>
Lead (6010A)	mg/kg	13		5/05/97

As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.

A member of The Marmon Group of Companies

LABORATORY ANALYSIS REPORT**DATE:** May 5, 1997**PAGE:**

3 Of 3

CLIENT: Midwest Environmental Cons.
5385 401st Ave. NW
Dalbo, MN 55017**PROJECT NO.:** 041097-200888
COLLECTION DATE: 4/06/97
COLLECTED BY: Client
RECEIVED DATE: 4/10/97
PROJECT DESCRIPT.: 62/0196E**CONTACT:** Richard Cox

<u>ANALYSIS</u>	<u>UNITS</u>	<u>MDL</u>	<u>Sample No.:</u>	<u>Sample ID.:</u>	<u>L972034-13</u>	<u>ANALYSIS</u>
			E-169	4100	DATE	
<u>ANALYSIS</u> Lead (6010A)	<u>UNITS</u> mg/kg	<u>MDL</u> 100	<u>Sample No.:</u> E-198	<u>RESULT</u> 4100	<u>L972034-14</u>	<u>ANALYSIS</u>

*ND means Not Detected or below reported MDL**MDL means Method Detection Limit**mg/kg means Milligrams Per Kilogram which is equivalent to Parts Per Million (ppm)*

This report has been reviewed by me for technical accuracy and completeness. The analyses were performed using EPA or other approved methodologies and the results were reported on an "as received" basis unless otherwise noted. Organic soil analyses were reported on a dry weight basis. The results reported relate only to the items tested. Please contact me if you have any questions or comments regarding this report. Spectrum Labs, Inc. appreciates the opportunity to provide this analytical service for you.

Report Submitted By,

Thomas L. Halverson
Laboratory ManagerTLH:wmc
mec125-1*As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.*

A member of The Marmon Group of Companies



Midwest Environmental Consulting, L.L.C.

5385 401st Ave. NW, Dalbo, MN 55017

612-689-3612/612-757-5541/FAX-612-689-5209

Client Address

Contact

CHAIN OF CUSTODY RECORD

Project Number 62/0196

Client St. Paul School District

Project CHESEA HEIGHTS

Phone/Fax

Sample ID	Room #	Sample Description	Color	Collection Date/Time	Matrix (Vol/Area)	Analysis Requested
1 621096E 2/12/97 #138	Hall	B Locker	Blue	4/1/97	—	Pb% WT or ppm
2 621096E 2/12/97 #150	106	B Window Muntion	Black	—	—	—
3 621096E 2/12/97 #153	112	B Lower Wall	White	—	—	—
4 621096E 2/12/97 #154	C	Upper Wall	White	—	—	—
5 621096E 2/12/97 #157	D	Window Muntion	White	—	—	—
6 621096E 2/12/97 #168	D	Radiator Cover	White	—	—	—
7 621096E 2/13/97 #15	107	B Radiator Top	Tan	—	—	—
8 621096E 2/13/97 #20	1	B Steel Header	Black (Painted)	—	—	—
9 621096E 2/13/97 #38	100	A Upper Wall	White	—	—	—
10 621096E 2/13/97 #6	109	D Wall Diffuser	White	—	—	—
11 621096E 2/13/97 #11	116	C Bookcase	Tan	—	—	—
12 621096E 2/13/97 #14	7	A Middle Wall	White	—	—	—
13 621096E 2/13/97 #16	8	B Electrical Panel	Term Blue	—	—	—
14 621096E 2/20/97 #18	exterior	C Door	Orange	—	—	—

Sampled By: J. Ode Date: 4/6/97 Time: _____

Delivered By: J. Ode Date: 4/10/97 Time: 11:30 am

Received By: J. Ode Date: _____ Time: _____


Delivered By: _____ Date: _____ Time: _____

Received By Lab: MMLC Date: 4/10/97 Time: 11:30

Disposition of Samples _____

Notes:

SITE #7
FLOOR IN PLANE



APPENDIX C INSPECTORS

**Bill Sloan
MDH Lead Inspector # 476**

**Roger Jeremiah
MDH Lead Inspector #139**

**John Allen
MDH Lead Inspector #236**