


Midwest
Environmental
Consulting, L.L.C.



 Printed on Recycled Paper

**DSF - 1930 Como
Saint Paul Public Schools**

Lead-Based Paint Inspection

Inspection Dates: 7/7/98, 7/16/97, 7/20/97

submitted to:

Saint Paul Public Schools

MEC Project # 62/0197BI

INTRODUCTION

At the request of Saint Paul Public Schools Environmental Safety Department, Midwest Environmental Consulting, L.L.C. (MEC), conducted a lead-based paint inspection at DSF - 1930 Como, 1930 Como Avenue, St. Paul, MN. The purpose of this inspection was to identify lead-based painted, varnished, or otherwise coated building components on the interior and exterior of the school building.

The inspection protocol incorporated applicable portions of the U.S. Department of Housing and Urban Development (HUD) *Guidelines for the Evaluation and Control of Lead-based Paint Hazards in Housing* (HUD Guidelines, June 1995) and OSHA 1926.62 requirements (Lead in Construction). The HUD guidelines are formulated to guide agencies in conducting random sampling of the interiors and exteriors of dwellings and common areas in public housing. The OSHA requirement is designed to minimize worker exposure when working with material containing lead.

The United States Environmental Protection Agency defines "lead-based paint" as a paint or other surface coating that contains lead equal to or in excess of 1.0 milligrams per square centimeter when analyzed by XRF or more than 0.5% by weight (5000 parts per million) by laboratory analysis of a bulk sample.

Minnesota Department of Labor and Industry (MN OSHA) adopted the EPA lead levels for the purpose of enforcing OSHA 1926.62 federal regulations. Detection of lead in dried paint film by XRF is a dependable indicator of levels of lead and is accepted by MN OSHA.

For this Saint Paul Public Schools Lead Inspection, all building components were tested on site using a Niton XL® X-ray Fluorescence Spectrum Analyzer⁽¹⁾. Building components included walls, ceilings, floors, moldings, window and door components, door surfaces, and miscellaneous features such as shelves or bookcases. Only painted or glazed surfaces or surfaces which were varnished were tested. Suspended ceilings, structural steel, and corrugated decking were not included in the inspection. Neither anodized (e.g., window sashes) nor plastic (e.g., vinyl baseboard and vinyl mini-blinds) were included in the scope of this inspection.

No samples were collected for laboratory analysis.

⁽¹⁾ This is a portable hand held machine that can analyze building components instantly for lead concentrations.

Each building was divided into unique sites based on the year of construction or renovation. Portable classrooms, playgrounds, and other detached buildings were automatically designated as a unique site. Each site was inspected independently assuming differences in painting history and construction characteristics.

SITE DESCRIPTION AND BUILDING HISTORY

According to information provided to MEC by Saint Paul Public Schools, DSF - 1930 Como was constructed in essentially one phase. This phase is 224,698 square-feet and dates from 1954.

All room and area designations used in this report are depicted on sampling maps found in Appendix A.

XRF SAMPLE RESULTS TABLE

The results of all samples analyzed are listed in the table at the end of this section. The following is a description of the column headings:

Site	Each school is divided into sites based on their unique construction characteristics. Each site has a unique date of construction or major renovation.
Sample #	Each sample taken was given a unique number to identify the type and location of the sample. The sampling date is an integral part of the sample number.
Analysis	This defines the type of analysis which can be categorized into two types: 1) XRF: This is an on-site analysis using a hand held Niton XL® X-ray Fluorescence Spectrum Analyzer; 2) Bulk or Chip: This is a bulk sample where paint is removed from the substrate and sent to a laboratory for analysis;
Floor	This is the level of the building in which the area tested was found, example, 1 (first floor), 0 (basement), etc.
Area	This further defines the specific functional space inspected such as a classroom, exterior, playground, gym, kitchen, etc.

- Room #** This is typically the actual number on the room as identified at the building.
- Component** Building "components" included walls, ceilings, floors, moldings, window and door components, door surfaces, and miscellaneous features such as shelves or bookcases.
- Feature** Identifies more detailed information of the component.
- Condition** This describes condition of the surface, whether it is intact, cracked, peeling, or chalking.
- Substrate** This refers to the material the building component is made of (wood, concrete, drywall, metal, etc.).
- Result** This is the analysis results for lead. Less than 1.0 mg/cm² or less than 0.5% by weight is considered to be non-lead and these building components are below the action levels of EPA and HUD. (All results are in mg/cm² except where noted.)

The table of results is designed for quick information on lead concentrations of tested building components. Generally, all repetitions of a test combination within a given room or area, may be assumed to contain similar concentrations of lead to that of the tested sample. For instance, the lead concentration of a tested wooden window sash was found to be above the action level of 1.0 mg/cm² in a given classroom. The classroom has five windows, all of wood, the same color and appearing to be of the same era. It can be assumed that the remaining four wooden window sashes each contain lead above the action limit.

Other columns identify the component and the component feature tested, condition of the component, type of substrate and the result of the analytical test.

As an example, the following illustration shows that the wooden door jamb in Room 123, first floor in the 1923 building section was in good, solid condition, and had an XRF test result of 0.3 mg/cm², which is below the action level.

Illustration Only

Site	Sample #	Date	Analysis	Floor	Area	Room #	Component	Feature	Condition	Substrate	Results
1923 Bldg.	52		XRF	1	Room	123	Door	Jamb	Solid	Wood	0.3

In a similar manner, the table shows that the plaster walls in room 23, on the second floor has peeling paint with more than 1.0 mg/cm² (shaded).

ILLUSTRATION ONLY

Site	Sample #	Date	Analysis	Floor	Area	Room #	Component	Feature	Condition	Substrate	Results
1910 Bldg.	16		XRF	2	Room	23	Door	Jamb	Peeling	Wood	0.25
1910 Bldg.	17		XRF	2	Room	23	Wall	Wall	Peeling	Plaster	1.2
1910 Bldg.	18		XRF	2	Room	23	Ceiling	Peeling	Plaster		0.25
1910 Bldg.	19		XRF	2	Room	23	Wall	Baseboard	Peeling	Wood	0.002

APPLICABLE REGULATIONS


When building components test above 1.0 mg/cm² of lead by XRF or 0.5% lead by weight from laboratory analysis all employees and contractors who will be working with these components in a construction related activity must be notified. The requirements of OSHA 1926.62, Lead in Construction are enforceable. This regulation defines construction work as "work for construction, alteration and/or repair, including painting and decorating." This regulation further defines monitoring requirements to minimize employee exposure to lead during construction activities.

When work is performed on external painted building structures (i.e. flashing, fire escapes, playground equipment, handrails, etc.), regulations of the Minnesota Pollution Control Agency (MPCA) may also be applicable. For removal of lead based paint from steel structures, MN Rules 7025.0200 - 7025.0380 apply to steel materials on the exterior of a building, or on the property when levels exceed 0.5 mg/cm² based on the average of three XRF spectrum results of the sample tested, or 5,000 ppm by laboratory analysis. If it is other than a steel surface, then MPCA regulates the painted surfaces under MN Rules 7025.010 - 7025.0080, when surfaces are to be disturbed using abrasive blasting methods.

Please contact MEC directly if you have questions about any portion of this report or the lead-based paint inspection itself.

APPENDIX A

**XRF TESTING DATA
WITH
LOCATION MAPS**



FLOOR PLAN - SE

7/7/98


INDEPENDENT SCHOOL DIST. #625
360 COLBORNE STREET
ST. PAUL, MINNESOTA 55102


DISTRICT SERVICE FACILITY
1930 CONO AVENUE
ST. PAUL, MIN.

CONSTRUCTED:



7/7/98





FLOOR PLAN - SE

7/20/98

OUTSIDE - SITE 2

5th Dec


INDEPENDENT SCHOOL DIST. #625
360 COLBORNE STREET
ST. PAUL, MINNESOTA 55102


DISTRICT SERVICE FACILITY
1930 COMO AVENUE
ST. PAUL, MN

CONSTRUCTED

A black and white highway shield. The top half contains the number '5'. The bottom half contains the number '11'. A diagonal line runs from the top-left corner to the bottom-right corner.

Side C






LODGE FLOOR PLAN - SW

DISTRICT SERVICE FACILITY
1930 CONO AVENUE
ST. PAUL, MN

CONSTRUCTED

6
11



This

A

MICHAEL - SW


7/20/98

INDEPENDENT SCHOOL DISTRICT
300 COLEBINE STREET
ST. PAUL, MINNESOTA 55101

SCHOOL DISTRICT SERVICE FACILITY
350 COLEBINE AVENUE
ST. PAUL, MN

CONSTRUCTED

7
11



Side A


7-20-98
OUTSIDE - SITE 2

INDEPENDENT SCHOOL DIST. #625
380 COLBORNE STREET
ST. PAUL, MINNESOTA 55102


DISTRICT SERVICE FACILITY
1930 COMO AVENUE
ST. PAUL, MN

CONSTRUCTED:





FLOOR PLAN - NW



(A) (B)

7/16/98
7/20/98


↓ N

INDEPENDENT SCHOOL DIST. #25
380 COLBORNE STREET
ST. PAUL, MINNESOTA 55102

DISTRICT SERVICE FACILITY
2830 COMO AVENUE
ST. PAUL, MN

CONSTRUCTED:





Alpha - A


OUTSIDE - SITE 2



7/20/98

INDEPENDENT SCHOOL DIST #625
380 COLBORNE STREET
ST. PAUL, MINNESOTA 55102

DISTRICT SERVICE FACILITY
1930 COMO AVENUE
ST. PAUL, MN


CONSTRUCTED:





N
1

7/7/98
7/16/98



Saint Paul Public Schools

DSF Building

Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
1	DSF Bldg.											
2												
3	Site	Sample	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
4	1954 Bldg.	33	XRF	7/7/98	1	Garage	1	Door	Door	Solid	Metal	0
5	1954 Bldg.	34	XRF	7/7/98	1	Garage	1	Door	Casing	Solid	Metal	0
6	1954 Bldg.	35	XRF	7/7/98	1	Garage	1	Door	Door	Solid	Metal	0
7	1954 Bldg.	36	XRF	7/7/98	1	Garage	1	Door	Jamb	Solid	Metal	0
8	1954 Bldg.	37	XRF	7/7/98	1	Garage	1	Parking	Rail	Solid	Metal	0.07
9	1954 Bldg.	91	XRF	7/7/98	1	Hall	2	Wall	Wall	Solid	Drywall	0
10	1954 Bldg.	92	XRF	7/7/98	1	Hall	2	Wall	Wall	Solid	Wood	0
11	1954 Bldg.	93	XRF	7/7/98	1	Hall	2	Wall	Midle Wall	Solid	Concrte	0
12	1954 Bldg.	94	XRF	7/7/98	1	Hall	2	Door	Door	Solid	Metal	0
13	1954 Bldg.	95	XRF	7/7/98	1	Hall	2	Floor		Solid	Concrte	0.01
14	1954 Bldg.	51	XRF	7/7/98	1	Hall	490	Wall	Midle Wall	Solid	Plaster	0.08
15	1954 Bldg.	52	XRF	7/7/98	1	Hall	490	Door	Door	Solid	Metal	0.03
16	1954 Bldg.	53	XRF	7/7/98	1	Hall	490	Door	Casing	Solid	Metal	0.06
17	1954 Bldg.	54	XRF	7/7/98	1	Hall	490	Stairs	Hand rail	Peeling	Metal	0.07
18	1954 Bldg.	55	XRF	7/7/98	1	Hall	490	Door	Door	Cracked	Metal	0
19	1954 Bldg.	56	XRF	7/7/98	1	Hall	490	Door	Casing	Solid	Metal	0.01
20	1954 Bldg.	57	XRF	7/7/98	1	Hall	490	Door	Door	Solid	Wood	0.03
21	1954 Bldg.	58	XRF	7/7/98	1	Hall	490		Radiator	Solid	Metal	0.08
22	1954 Bldg.	59	XRF	7/7/98	1	Hall	490	Floor		Cracked	Concrte	0
23	1954 Bldg.	60	XRF	7/7/98	1	Hall	490	Ceiling		Solid	Plaster	0.08
24	1954 Bldg.	141	XRF	7/7/98	1	Hall	1050	Door	Door	Solid	Metal	0.15
25	1954 Bldg.	142	XRF	7/7/98	1	Hall	1050	Door	Casing	Cracked	Metal	0.12
26	1954 Bldg.	143	XRF	7/7/98	1	Hall	1050	Wall	Wall	Solid	Plaster	0.18
27	1954 Bldg.	144	XRF	7/7/98	1	Hall	1050	Window	Casing	Solid	Metal	0
28	1954 Bldg.	145	XRF	7/7/98	1	Hall	1050	Door	Door	Solid	Wood	0
29	1954 Bldg.	146	XRF	7/7/98	1	Hall	1050	Wall	Midle Wall	Solid	Concrte	0.06
30	1954 Bldg.	147	XRF	7/7/98	1	Hall	1050	Door	Door	Solid	Metal	0.84
31	1954 Bldg.	148	XRF	7/7/98	1	Hall	1050	Door	Casing	Solid	Metal	0
32	1954 Bldg.	149	XRF	7/7/98	1	Hall	1050	Door	Door	Solid	Metal	0
33	1954 Bldg.	150	XRF	7/7/98	1	Hall	1050	Window	Casing	Solid	Metal	0.01
34	1954 Bldg.	151	XRF	7/7/98	1	Hall	1050		Radiator	Cracked	Metal	0.03
35	1954 Bldg.	152	XRF	7/7/98	1	Hall	1050	Wall	Midle Wall	Solid	Plaster	0.07
36	1954 Bldg.	153	XRF	7/7/98	1	Hall	1050	Floor		Solid	Concrte	0
37	1954 Bldg.	247	XRF	7/7/98	1	Hall	1075	Door	Door	Solid	Metal	0.01
38	1954 Bldg.	248	XRF	7/7/98	1	Hall	1075	Door	Jamb	Solid	Metal	0
39	1954 Bldg.	249	XRF	7/7/98	1	Hall	1075	Door	Door	Solid	Wood	0
40	1954 Bldg.	250	XRF	7/7/98	1	Hall	1075	Wall	Wall	Solid	Concrte	0
41	1954 Bldg.	251	XRF	7/7/98	1	Hall	1075	Wall	Wall	Solid	Concrte	0
42	1954 Bldg.	17	XRF	7/16/98	1	Hall	1301	Wall	Midle Wall	Solid	Concrte	0.11
43	1954 Bldg.	18	XRF	7/16/98	1	Hall	1301	Wall	Midle Wall	Solid	Plaster	0.64
44	1954 Bldg.	19	XRF	7/16/98	1	Hall	1301		Radiator	Solid	Metal	0.65
45	1954 Bldg.	20	XRF	7/16/98	1	Hall	1301	Door	Door	Solid	Metal	0.37
46	1954 Bldg.	21	XRF	7/16/98	1	Hall	1301	Door	Casing	Solid	Metal	0.73
47	1954 Bldg.	22	XRF	7/16/98	1	Hall	1301	Wall	Wall	Solid	Plaster	0.58
48	1954 Bldg.	23	XRF	7/16/98	1	Hall	1301	Door	Door	Solid	Metal	0.02
49	1954 Bldg.	24	XRF	7/16/98	1	Hall	1301	Ceiling		Solid	Plaster	0.66
50	1954 Bldg.	6	XRF	7/20/98	1	Hall	1600	Door	Door	Solid	Wood	0
51	1954 Bldg.	7	XRF	7/20/98	1	Hall	1600	Door	Casing	Solid	Wood	0
52	1954 Bldg.	8	XRF	7/20/98	1	Hall	1600	Wall	Wall	Solid	Concrte	0
53	1954 Bldg.	9	XRF	7/20/98	1	Hall	1600	Wall	Wall	Solid	Concrte	0.02
54	1954 Bldg.	10	XRF	7/20/98	1	Hall	1600	Wall	Wall	Solid	Concrte	0
55	1954 Bldg.	11	XRF	7/20/98	1	Hall	1600	Guard	Post	Solid	Metal	0
56	1954 Bldg.	12	XRF	7/20/98	1	Hall	1600	Door	Door	Solid	Metal	0

Saint Paul Public Schools

DSF Building

Lead-Based Paint Inspection

3	A	B	C	D	E	F	G	H	I	J	K	L
	Site	Sample	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
57	1954 Bldg.	13	XRF	7/20/98	1	Hall	1600	Door	Casing	Solid	Metal	0
58	1954 Bldg.	110	XRF	7/20/98	1	Hall	2000	Wall	Midle Wall	Solid	Concrete	0
59	1954 Bldg.	111	XRF	7/20/98	1	Hall	2000	Door	Door	Solid	Metal	0.01
60	1954 Bldg.	112	XRF	7/20/98	1	Hall	2000	Door	Jamb	Cracked	Metal	0.02
61	1954 Bldg.	113	XRF	7/20/98	1	Hall	2000	Door	Door	Cracked	Metal	0
62	1954 Bldg.	114	XRF	7/20/98	1	Hall	2000	Door	Casing	Cracked	Metal	0
63	1954 Bldg.	115	XRF	7/20/98	1	Hall	2000	Door	Door	Solid	Metal	0.04
64	1954 Bldg.	116	XRF	7/20/98	1	Hall	2000	Door	Casing	Cracked	Metal	0.01
65	1954 Bldg.	117	XRF	7/20/98	1	Hall	2000	Window	Casing	Solid	Metal	0.01
66	1954 Bldg.	118	XRF	7/20/98	1	Hall	2000	Wall	Midle Wall	Solid	Drywall	0
67	1954 Bldg.	119	XRF	7/20/98	1	Hall	2000	Door	Door	Solid	Wood	0
68	1954 Bldg.	120	XRF	7/20/98	1	Hall	2000	Door	Casing	Solid	Wood	0.01
69	1954 Bldg.	121	XRF	7/20/98	1	Hall	2000	Stairs	Hand rail	Solid	Metal	0
70	1954 Bldg.	122	XRF	7/20/98	1	Hall	2000	Stairs	Column	Solid	Metal	0.04
71	1954 Bldg.	123	XRF	7/20/98	1	Hall	2000	Door	Door	Peeling	Wood	0
72	1954 Bldg.	124	XRF	7/20/98	1	Hall	2000	Door	Door	Solid	Wood	0.83
73	1954 Bldg.	125	XRF	7/20/98	1	Hall	2000	Window	Casing	Solid	Metal	0
74	1954 Bldg.	126	XRF	7/20/98	1	Hall	2000	Wall	Wall	Solid	Concrete	0
75	1954 Bldg.	127	XRF	7/20/98	1	Hall	2000	Door	Door	Solid	Wood	0.79
76	1954 Bldg.	128	XRF	7/20/98	1	Hall	2000		Radiator	Solid	Metal	0
77	1954 Bldg.	80	XRF	7/16/98	2	Hall	2255	Wall	Midle Wall	Solid	Plaster	0.38
78	1954 Bldg.	81	XRF	7/16/98	2	Hall	2255		Radiator	Solid	Metal	0.04
79	1954 Bldg.	82	XRF	7/16/98	2	Hall	2255	Door	Door	Solid	Wood	0
80	1954 Bldg.	83	XRF	7/16/98	2	Hall	2255	Door	Casing	Solid	Metal	0.31
81	1954 Bldg.	84	XRF	7/16/98	2	Hall	2255	Stairs	Tread	Solid	Concrete	0
82	1954 Bldg.	85	XRF	7/16/98	2	Hall	2255		Elec Panel	Solid	Metal	0.88
83	1954 Bldg.	108	XRF	7/7/98	1	Kitchen	200	Wall	Midle Wall	Solid	Concrete	0
84	1954 Bldg.	109	XRF	7/7/98	1	Kitchen	200	Door	Jamb	Solid	Metal	0
85	1954 Bldg.	110	XRF	7/7/98	1	Kitchen	200	Door	Door	Solid	Metal	0.01
86	1954 Bldg.	111	XRF	7/7/98	1	Kitchen	200	Door	Jamb	Solid	Metal	0.02
87	1954 Bldg.	112	XRF	7/7/98	1	Kitchen	200	Wall	Midle Wall	Solid	Concrete	0
88	1954 Bldg.	113	XRF	7/7/98	1	Kitchen	300	Wall	Wall	Solid	Concrete	0.01
89	1954 Bldg.	114	XRF	7/7/98	1	Kitchen	300	Window	Casing	Solid	Metal	0
90	1954 Bldg.	115	XRF	7/7/98	1	Kitchen	300	Door	Door	Solid	Metal	0.57
91	1954 Bldg.	116	XRF	7/7/98	1	Kitchen	300	Door	Jamb	Solid	Metal	0
92	1954 Bldg.	117	XRF	7/7/98	1	Kitchen	300	Wall	Wall	Solid	Concrete	0
93	1954 Bldg.	118	XRF	7/7/98	1	Kitchen	300	Wall	Midle Wall	Solid	Concrete	0.01
94	1954 Bldg.	119	XRF	7/7/98	1	Kitchen	300	Window	Casing	Peeling	Metal	0
95	1954 Bldg.	120	XRF	7/7/98	1	Kitchen	300	Door	Door	Solid	Metal	0
96	1954 Bldg.	121	XRF	7/7/98	1	Kitchen	300	Door	Jamb	Solid	Metal	0
97	1954 Bldg.	122	XRF	7/7/98	1	Kitchen	300	Wall	Midle Wall	Solid	Concrete	0.01
98	1954 Bldg.	123	XRF	7/7/98	1	Kitchen	300	Wall	Column	Peeling	Metal	0.03
99	1954 Bldg.	124	XRF	7/7/98	1	Kitchen	300	Wall	Column	Peeling	Metal	0.02
100	1954 Bldg.	125	XRF	7/7/98	1	Kitchen	400	Wall	Midle Wall	Solid	Concrete	0
101	1954 Bldg.	126	XRF	7/7/98	1	Kitchen	400	Wall	Midle Wall	Solid	Concrete	0
102	1954 Bldg.	127	XRF	7/7/98	1	Kitchen	500	Wall	Midle Wall	Solid	Concrete	0
103	1954 Bldg.	128	XRF	7/7/98	1	Kitchen	600	Wall	Midle Wall	Solid	Concrete	0
104	1954 Bldg.	129	XRF	7/7/98	1	Kitchen	600	Door	Door	Solid	Metal	0.02
105	1954 Bldg.	130	XRF	7/7/98	1	Kitchen	600	Wall	Midle Wall	Solid	Concrete	0.01
106	1954 Bldg.	131	XRF	7/7/98	1	Kitchen	600	Wall	Midle Wall	Solid	Concrete	0.03
107	1954 Bldg.	132	XRF	7/7/98	1	Kitchen	600	Floor		Solid	Concrete	0.01
108	1954 Bldg.	133	XRF	7/7/98	1	Kitchen	600	Wall	Midle Wall	Solid	Concrete	0.01
109	1954 Bldg.	134	XRF	7/7/98	1	Kitchen	700	Wall	Midle Wall	Solid	Concrete	0.01
110	1954 Bldg.	135	XRF	7/7/98	1	Kitchen	700	Door	Casing	Solid	Metal	0
111	1954 Bldg.	136	XRF	7/7/98	1	Kitchen	700	Door	Door	Solid	Metal	0

Saint Paul Public Schools

DSF Building

Lead-Based Paint Inspection

3	A	B	C	D	E	F	G	H	I	J	K	L
	Site	Sample	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
112	1954 Bldg.	137	XRF	7/7/98	1	Kitchen	700	Door	Door	Solid	Metal	0.66
113	1954 Bldg.	138	XRF	7/7/98	1	Kitchen	700	Window	Casing	Solid	Metal	0
114	1954 Bldg.	139	XRF	7/7/98	1	Kitchen	700	Door	Door	Solid	Wood	0
115	1954 Bldg.	140	XRF	7/7/98	1	Kitchen	700	Door	Jamb	Solid	Metal	0
116	1954 Bldg.	148	XRF	7/20/98	1	Outside	1	Door	Door	Solid	Metal	0
117	1954 Bldg.	149	XRF	7/20/98	1	Outside	1	Door	Casing	Solid	Metal	0
118	1954 Bldg.	150	XRF	7/20/98	1	Outside	1	Stairs	Hand rail	Cracked	Metal	0.02
119	1954 Bldg.	151	XRF	7/20/98	1	Outside	1	Door	Door	Solid	Metal	0.15
120	1954 Bldg.	152	XRF	7/20/98	1	Outside	1	Door	Casing	Solid	Metal	0.02
121	1954 Bldg.	153	XRF	7/20/98	1	Outside	1	Door	Door	Solid	Metal	0.06
122	1954 Bldg.	154	XRF	7/20/98	1	Outside	1	Door	Casing	Solid	Metal	2.16
123	1954 Bldg.	155	XRF	7/20/98	1	Outside	1	Ext Wall	Siding	Solid	Metal	0.04
124	1954 Bldg.	156	XRF	7/20/98	1	Outside	1	Door	Door	Solid	Metal	0
125	1954 Bldg.	157	XRF	7/20/98	1	Outside	1	Door	Casing	Solid	Metal	0.01
126	1954 Bldg.	158	XRF	7/20/98	1	Outside	1	Door	Header	Solid	Metal	0
127	1954 Bldg.	159	XRF	7/20/98	1	Outside	1	Ext Wall	Trim	Solid	Metal	0.05
128	1954 Bldg.	160	XRF	7/20/98	1	Outside	1	Door	Door	Solid	Metal	0.01
129	1954 Bldg.	161	XRF	7/20/98	1	Outside	1	Door	Casing	Solid	Metal	3.81
130	1954 Bldg.	162	XRF	7/20/98	1	Outside	1	Door	Door	Peeling	Wood	0
131	1954 Bldg.	163	XRF	7/20/98	1	Outside	1	Door	Casing	Cracked	Metal	0.34
132	1954 Bldg.	164	XRF	7/20/98	1	Outside	1	Door	Door	Cracked	Metal	0.25
133	1954 Bldg.	165	XRF	7/20/98	1	Outside	1	Stairs	Hand rail	Chalking	Metal	0.01
134	1954 Bldg.	27	XRF	7/7/98	1	Restroom	1	Wall	Midle Wall	Solid	Plaster	0.05
135	1954 Bldg.	28	XRF	7/7/98	1	Restroom	1	Wall	Bthrm Stll	Solid	Metal	0.2
136	1954 Bldg.	29	XRF	7/7/98	1	Restroom	1	Door	Casing	Peeling	Metal	0.01
137	1954 Bldg.	30	XRF	7/7/98	1	Restroom	1	Door	Door	Cracked	Wood	0.03
138	1954 Bldg.	31	XRF	7/7/98	1	Restroom	1	Floor		Cracked	Concrete	0
139	1954 Bldg.	32	XRF	7/7/98	1	Restroom	1	Ceiling		Solid	Plaster	0.07
140	1954 Bldg.	165	XRF	7/7/98	1	Restroom	2	Wall	Midle Wall	Solid	Plaster	0.04
141	1954 Bldg.	166	XRF	7/7/98	1	Restroom	2	Door	Stall Door	Solid	Metal	0.01
142	1954 Bldg.	167	XRF	7/7/98	1	Restroom	2	Door	Door	Cracked	Wood	0
143	1954 Bldg.	168	XRF	7/7/98	1	Restroom	2	Door	Casing	Solid	Metal	0.02
144	1954 Bldg.	169	XRF	7/7/98	1	Restroom	2	Wall	Midle Wall	Solid	Drywall	0
145	1954 Bldg.	170	XRF	7/7/98	1	Restroom	2	Wall	Column	Solid	Metal	5.09
146	1954 Bldg.	171	XRF	7/7/98	1	Restroom	2	Floor		Cracked	Concrete	0.01
147	1954 Bldg.	172	XRF	7/7/98	1	Restroom	2	Ceiling		Solid	Drywall	0
148	1954 Bldg.	173	XRF	7/7/98	1	Restroom	3	Wall	Midle Wall	Solid	Drywall	0
149	1954 Bldg.	174	XRF	7/7/98	1	Restroom	3	Door	Door	Solid	Wood	0
150	1954 Bldg.	175	XRF	7/7/98	1	Restroom	3	Door	Casing	Solid	Metal	0.03
151	1954 Bldg.	176	XRF	7/7/98	1	Restroom	3	Door	Stall Door	Solid	Metal	0.01
152	1954 Bldg.	177	XRF	7/7/98	1	Restroom	3	Wall	Midle Wall	Solid	Plaster	0.06
153	1954 Bldg.	178	XRF	7/7/98	1	Restroom	3	Floor		Cracked	Concrete	0.01
154	1954 Bldg.	179	XRF	7/7/98	1	Restroom	3	Ceiling		Solid	Plaster	0
155	1954 Bldg.	81	XRF	7/20/98	1	Restroom	100	Wall	Wall	Solid	Concrete	0.01
156	1954 Bldg.	82	XRF	7/20/98	1	Restroom	100	Door	Door	Solid	Wood	0.79
157	1954 Bldg.	83	XRF	7/20/98	1	Restroom	100	Door	Casing	Solid	Metal	0
158	1954 Bldg.	84	XRF	7/20/98	1	Restroom	100	Wall	Bthrm Stll	Solid	Metal	0.01
159	1954 Bldg.	85	XRF	7/20/98	1	Restroom	100	Floor		Cracked	Concrete	0.33
160	1954 Bldg.	86	XRF	7/20/98	1	Restroom	200	Wall	Midle Wall	Solid	Concrete	0
161	1954 Bldg.	87	XRF	7/20/98	1	Restroom	200	Door	Door	Solid	Wood	0.91
162	1954 Bldg.	88	XRF	7/20/98	1	Restroom	200	Door	Jamb	Solid	Metal	0
163	1954 Bldg.	89	XRF	7/20/98	1	Restroom	200	Wall	Bthrm Stll	Solid	Metal	0.11
164	1954 Bldg.	90	XRF	7/20/98	1	Restroom	200	Floor		Solid	Concrete	0.37
165	1954 Bldg.	73	XRF	7/16/98	2	Restroom	2250	Door	Door	Solid	Wood	0
166	1954 Bldg.	74	XRF	7/16/98	2	Restroom	2250	Door	Casing	Solid	Metal	0.06

Saint Paul Public Schools

DSF Building

Lead-Based Paint Inspection

3	A	B	C	D	E	F	G	H	I	J	K	L
	Site	Sample	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
167	1954 Bldg.	75	XRF	7/16/98	2	Restroom	2250	Wall	Wall	Solid	Drywall	0
168	1954 Bldg.	76	XRF	7/16/98	2	Restroom	2250		Radiator	Solid	Metal	0.05
169	1954 Bldg.	77	XRF	7/16/98	2	Restroom	2250	Door	Door	Solid	Metal	0.03
170	1954 Bldg.	78	XRF	7/16/98	2	Restroom	2250	Wall	Bthrm Stil	Solid	Metal	0.11
171	1954 Bldg.	79	XRF	7/16/98	2	Restroom	2250	Ceiling		Solid	Plaster	0.07
172	1954 Bldg.	135	XRF	7/20/98	1	Room	30	Wall	Midle Wall	Solid	Concrte	0.03
173	1954 Bldg.	136	XRF	7/20/98	1	Room	30	Door	Door	Solid	Metal	0
174	1954 Bldg.	137	XRF	7/20/98	1	Room	30	Door	Jamb	Solid	Metal	0.01
175	1954 Bldg.	138	XRF	7/20/98	1	Room	30	Ceiling		Solid	Concrte	0
176	1954 Bldg.	44	XRF	7/20/98	1	Room	46	Wall	Midle Wall	Solid	Concrte	0.03
177	1954 Bldg.	45	XRF	7/20/98	1	Room	46	Door	Door	Solid	Metal	0.01
178	1954 Bldg.	46	XRF	7/20/98	1	Room	46	Door	Casing	Solid	Metal	0
179	1954 Bldg.	47	XRF	7/20/98	1	Room	48	Wall	Midle Wall	Solid	Concrte	0
180	1954 Bldg.	48	XRF	7/20/98	1	Room	48	Cabinet	Shelf	Solid	Wood	0
181	1954 Bldg.	49	XRF	7/20/98	1	Room	48	Door	Door	Solid	Metal	0
182	1954 Bldg.	50	XRF	7/20/98	1	Room	48	Door	Jamb	Solid	Metal	0
183	1954 Bldg.	51	XRF	7/20/98	1	Room	48	Cabinet	Shelf	Solid	Wood	0
184	1954 Bldg.	52	XRF	7/20/98	1	Room	48	Wall	Midle Wall	Solid	Concrte	0
185	1954 Bldg.	53	XRF	7/20/98	1	Room	48	Ceiling		Solid	Concrte	0.01
186	1954 Bldg.	96	XRF	7/7/98	1	Room	50	Floor	Baseboard	Solid	Concrte	0.02
187	1954 Bldg.	97	XRF	7/7/98	1	Room	50	Door	Door	Cracked	Metal	0
188	1954 Bldg.	98	XRF	7/7/98	1	Room	50	Door	Jamb	Cracked	Metal	0.01
189	1954 Bldg.	99	XRF	7/7/98	1	Room	50	Stairs	Hand rail	Solid	Metal	0
190	1954 Bldg.	100	XRF	7/7/98	1	Room	50		Elec Panel	Solid	Metal	0.02
191	1954 Bldg.	101	XRF	7/7/98	1	Room	50	Floor		Cracked	Concrte	0.01
192	1954 Bldg.	102	XRF	7/7/98	1	Room	50	Ceiling		Solid	Plaster	0.14
193	1954 Bldg.	54	XRF	7/20/98	1	Room	54	Door	Door	Solid	Metal	0.01
194	1954 Bldg.	55	XRF	7/20/98	1	Room	54	Door	Jamb	Solid	Metal	0
195	1954 Bldg.	56	XRF	7/20/98	1	Room	54	Door	Door	Solid	Wood	0
196	1954 Bldg.	57	XRF	7/20/98	1	Room	54	Ceiling		Solid	Concrte	0
197	1954 Bldg.	58	XRF	7/20/98	1	Room	56	Wall	Midle Wall	Solid	Concrte	0.01
198	1954 Bldg.	59	XRF	7/20/98	1	Room	56	Door	Door	Solid	Wood	0
199	1954 Bldg.	60	XRF	7/20/98	1	Room	56	Door	Casing	Solid	Metal	0.08
200	1954 Bldg.	61	XRF	7/20/98	1	Room	56	Ceiling		Solid	Concrte	0.04
201	1954 Bldg.	62	XRF	7/20/98	1	Room	60	Wall	Midle Wall	Solid	Concrte	0
202	1954 Bldg.	63	XRF	7/20/98	1	Room	60	Door	Door	Solid	Wood	1.19
203	1954 Bldg.	64	XRF	7/20/98	1	Room	60	Door	Door	Solid	Metal	0
204	1954 Bldg.	65	XRF	7/20/98	1	Room	60	Door	Door	Solid	Metal	0
205	1954 Bldg.	66	XRF	7/20/98	1	Room	60	Door	Jamb	Solid	Metal	0
206	1954 Bldg.	67	XRF	7/20/98	1	Room	60	Wall	Midle Wall	Solid	Concrte	0.02
207	1954 Bldg.	68	XRF	7/20/98	1	Room	65	Wall	Midle Wall	Solid	Concrte	0
208	1954 Bldg.	69	XRF	7/20/98	1	Room	65	Door	Door	Solid	Metal	0
209	1954 Bldg.	70	XRF	7/20/98	1	Room	65	Door	Casing	Solid	Metal	0
210	1954 Bldg.	71	XRF	7/20/98	1	Room	65	Cabinet	Door	Solid	Wood	0.02
211	1954 Bldg.	72	XRF	7/20/98	1	Room	65	Cabinet	Door	Solid	Wood	0.01
212	1954 Bldg.	73	XRF	7/20/98	1	Room	65	Wall	Midle Wall	Solid	Concrte	0
213	1954 Bldg.	74	XRF	7/20/98	1	Room	65	Ceiling		Solid	Concrte	0.01
214	1954 Bldg.	75	XRF	7/20/98	1	Room	70	Wall	Midle Wall	Solid	Concrte	0
215	1954 Bldg.	76	XRF	7/20/98	1	Room	70	Door	Door	Solid	Metal	0.84
216	1954 Bldg.	77	XRF	7/20/98	1	Room	70	Window	Casing	Solid	Metal	0
217	1954 Bldg.	78	XRF	7/20/98	1	Room	70	Door	Casing	Solid	Metal	0.01
218	1954 Bldg.	79	XRF	7/20/98	1	Room	70		Radiator	Solid	Metal	0
219	1954 Bldg.	80	XRF	7/20/98	1	Room	70	Wall	Wall	Solid	Drywall	0
220	1954 Bldg.	103	XRF	7/7/98	1	Room	150	Wall	Wall	Solid	Concrte	0
221	1954 Bldg.	104	XRF	7/7/98	1	Room	150	Door	Door	Peeling	Metal	0

Saint Paul Public Schools

DSF Building

Lead-Based Paint Inspection

A	B	C	D	E	F	G	H	I	J	K	L	
3	Site	Sample	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
222	1954 Bldg.	105	XRF	7/7/98	1	Room	150	Door	Jamb	Cracked	Metal	0
223	1954 Bldg.	106	XRF	7/7/98	1	Room	150	Floor		Cracked	Concrete	0
224	1954 Bldg.	107	XRF	7/7/98	1	Room	150	Ceiling		Peeling	Concrete	0
225	1954 Bldg.	91	XRF	7/20/98	1	Room	210	Wall	Midle Wall	Solid	Concrete	0.01
226	1954 Bldg.	92	XRF	7/20/98	1	Room	210	Door	Casing	Solid	Metal	0
227	1954 Bldg.	93	XRF	7/20/98	1	Room	210	Wall	Chair rail	Solid	Wood	0
228	1954 Bldg.	94	XRF	7/20/98	1	Room	230	Wall	Midle Wall	Solid	Drywall	0
229	1954 Bldg.	95	XRF	7/20/98	1	Room	230	Window	Casing	Solid	Wood	0
230	1954 Bldg.	96	XRF	7/20/98	1	Room	230	Door	Door	Solid	Wood	0.02
231	1954 Bldg.	97	XRF	7/20/98	1	Room	230	Wall	Midle Wall	Solid	Concrete	0
232	1954 Bldg.	98	XRF	7/20/98	1	Room	260	Door	Door	Solid	Metal	0
233	1954 Bldg.	99	XRF	7/20/98	1	Room	260	Door	Casing	Solid	Metal	0
234	1954 Bldg.	100	XRF	7/20/98	1	Room	260	Door	Column	Solid	Metal	0.05
235	1954 Bldg.	101	XRF	7/20/98	1	Room	260	Door	Door	Solid	Metal	0.03
236	1954 Bldg.	102	XRF	7/20/98	1	Room	260	Stairs	Hand rail	Solid	Metal	0.01
237	1954 Bldg.	129	XRF	7/20/98	1	Room	270	Door	Door	Solid	Metal	0
238	1954 Bldg.	130	XRF	7/20/98	1	Room	270	Door	Casing	Solid	Metal	0
239	1954 Bldg.	131	XRF	7/20/98	1	Room	270	Door	Column	Solid	Metal	0.06
240	1954 Bldg.	132	XRF	7/20/98	1	Room	270	Wall	Midle Wall	Solid	Drywall	0
241	1954 Bldg.	133	XRF	7/20/98	1	Room	270	Door	Door	Solid	Wood	0
242	1954 Bldg.	134	XRF	7/20/98	1	Room	270	Door	Casing	Solid	Wood	0
243	1954 Bldg.	103	XRF	7/20/98	1	Room	280	Door	Door	Solid	Metal	0.01
244	1954 Bldg.	104	XRF	7/20/98	1	Room	280	Door	Casing	Solid	Metal	0.02
245	1954 Bldg.	105	XRF	7/20/98	1	Room	280	Wall	Midle Wall	Solid	Concrete	0
246	1954 Bldg.	106	XRF	7/20/98	1	Room	280	Window	Casing	Solid	Metal	0.02
247	1954 Bldg.	107	XRF	7/20/98	1	Room	280	Stairs	Tread	Cracked	Wood	0
248	1954 Bldg.	108	XRF	7/20/98	1	Room	280	Stairs	Hand rail	Cracked	Wood	0.01
249	1954 Bldg.	109	XRF	7/20/98	1	Room	280	Wall	Wall	Solid	Drywall	0
250	1954 Bldg.	38	XRF	7/7/98	1	Room	443	Wall	Wall	Solid	Wood	0
251	1954 Bldg.	39	XRF	7/7/98	1	Room	443		Radiator	Solid	Metal	0.06
252	1954 Bldg.	40	XRF	7/7/98	1	Room	443	Cabinet	Door	Solid	Wood	0.02
253	1954 Bldg.	41	XRF	7/7/98	1	Room	443	Window	Casing	Solid	Wood	0
254	1954 Bldg.	42	XRF	7/7/98	1	Room	443	Door	Door	Solid	Wood	0
255	1954 Bldg.	43	XRF	7/7/98	1	Room	443	Door	Jamb	Solid	Wood	0
256	1954 Bldg.	44	XRF	7/7/98	1	Room	443		Locker	Solid	Metal	0.39
257	1954 Bldg.	45	XRF	7/7/98	1	Room	443	Wall	Wall	Solid	Plaster	0
258	1954 Bldg.	46	XRF	7/7/98	1	Room	443	Wall	Wall	Solid	Plaster	0.05
259	1954 Bldg.	47	XRF	7/7/98	1	Room	443	Door	Door	Solid	Metal	0.01
260	1954 Bldg.	48	XRF	7/7/98	1	Room	443	Wall	Wall	Solid	Concrete	0.05
261	1954 Bldg.	49	XRF	7/7/98	1	Room	443	Window	Casing	Solid	Metal	0
262	1954 Bldg.	50	XRF	7/7/98	1	Room	443	Cabinet	Door	Solid	Wood	0
263	1954 Bldg.	61	XRF	7/7/98	1	Room	464	Wall	Wall	Solid	Concrete	0
264	1954 Bldg.	62	XRF	7/7/98	1	Room	464	Door	Casing	Cracked	Wood	0
265	1954 Bldg.	63	XRF	7/7/98	1	Room	464	Door	Door	Solid	Metal	0
266	1954 Bldg.	64	XRF	7/7/98	1	Room	464	Door	Casing	Solid	Metal	0
267	1954 Bldg.	65	XRF	7/7/98	1	Room	464	Storage	Rack	Solid	Metal	0.03
268	1954 Bldg.	66	XRF	7/7/98	1	Room	464	Floor		Cracked	Concrete	0
269	1954 Bldg.	67	XRF	7/7/98	1	Room	464	Ceiling		Solid	Concrete	0
270	1954 Bldg.	6	XRF	7/7/98	1	Room	490	Wall	Midle Wall	Solid	Concrete	0
271	1954 Bldg.	7	XRF	7/7/98	1	Room	490	Door	Door	Solid	Wood	0.03
272	1954 Bldg.	8	XRF	7/7/98	1	Room	490	Door	Casing	Solid	Wood	0
273	1954 Bldg.	9	XRF	7/7/98	1	Room	490	Wall	Wall	Solid	Plaster	0.03
274	1954 Bldg.	10	XRF	7/7/98	1	Room	490		Radiator	Solid	Metal	0.03
275	1954 Bldg.	11	XRF	7/7/98	1	Room	490	Door	Jamb	Solid	Metal	0.05
276	1954 Bldg.	12	XRF	7/7/98	1	Room	490	Wall	Wall	Solid	Plaster	0.01

Saint Paul Public Schools

DSF Building

Lead-Based Paint Inspection

A	B	C	D	E	F	G	H	I	J	K	L	
3	Site	Sample	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
277	1954 Bldg.	13	XRF	7/7/98	1	Room	490	Wall	Midle Wall	Solid	Concrete	0
278	1954 Bldg.	14	XRF	7/7/98	1	Room	490	Door	Door	Solid	Metal	0
279	1954 Bldg.	15	XRF	7/7/98	1	Room	490	Door	Jamb	Solid	Metal	0
280	1954 Bldg.	16	XRF	7/7/98	1	Room	490	Radiator	Solid	Metal	Metal	0.03
281	1954 Bldg.	17	XRF	7/7/98	1	Room	490	Floor		Cracked	Concrete	0
282	1954 Bldg.	18	XRF	7/7/98	1	Room	490	Ceiling		Solid	Plaster	0.04
283	1954 Bldg.	19	XRF	7/7/98	1	Room	490		Elec Panel	Solid	Metal	0.02
284	1954 Bldg.	68	XRF	7/7/98	1	Room	604	Wall	Wall	Solid	Concrete	0
285	1954 Bldg.	69	XRF	7/7/98	1	Room	604	Door	Jamb	Solid	Metal	0.01
286	1954 Bldg.	70	XRF	7/7/98	1	Room	604	Wall	Midle Wall	Solid	Concrete	0.08
287	1954 Bldg.	71	XRF	7/7/98	1	Room	604	Door	Door	Solid	Metal	0.01
288	1954 Bldg.	72	XRF	7/7/98	1	Room	604	Door	Casing	Solid	Metal	0
289	1954 Bldg.	73	XRF	7/7/98	1	Room	604	Door	Door	Solid	Metal	0
290	1954 Bldg.	74	XRF	7/7/98	1	Room	604	Stairs	Hand rail	Solid	Metal	0.02
291	1954 Bldg.	75	XRF	7/7/98	1	Room	604	Door	Door	Cracked	Metal	0
292	1954 Bldg.	76	XRF	7/7/98	1	Room	604	Door	Jamb	Cracked	Metal	0.01
293	1954 Bldg.	77	XRF	7/7/98	1	Room	604	Wall	Midle Wall	Solid	Concrete	0.04
294	1954 Bldg.	78	XRF	7/7/98	1	Room	604	Wall	Midle Wall	Solid	Concrete	0.01
295	1954 Bldg.	79	XRF	7/7/98	1	Room	604	Stairs	Hand rail	Cracked	Metal	0
296	1954 Bldg.	80	XRF	7/7/98	1	Room	604		Column	Cracked	Metal	2.9
297	1954 Bldg.	81	XRF	7/7/98	1	Room	604	Overhead	Door	Cracked	Wood	1.04
298	1954 Bldg.	82	XRF	7/7/98	1	Room	604	Wall	Midle Wall	Cracked	Wood	0
299	1954 Bldg.	83	XRF	7/7/98	1	Room	604	Door	Door	Solid	Wood	0.03
300	1954 Bldg.	84	XRF	7/7/98	1	Room	604	Door	Casing	Solid	Metal	0
301	1954 Bldg.	85	XRF	7/7/98	1	Room	604	Wall	Wall	Solid	Concrete	0
302	1954 Bldg.	86	XRF	7/7/98	1	Room	604		Locker	Solid	Metal	0.01
303	1954 Bldg.	87	XRF	7/7/98	1	Room	604	Wall	Wall	Solid	Concrete	0
304	1954 Bldg.	88	XRF	7/7/98	1	Room	604	Window	Casing	Solid	Metal	0
305	1954 Bldg.	89	XRF	7/7/98	1	Room	604	Door	Casing	Solid	Metal	0
306	1954 Bldg.	90	XRF	7/7/98	1	Room	604	Floor		Solid	Concrete	0
307	1954 Bldg.	20	XRF	7/7/98	1	Room	710	Wall	Transom	Solid	Wood	0.08
308	1954 Bldg.	21	XRF	7/7/98	1	Room	710	Door	Door	Cracked	Metal	0.44
309	1954 Bldg.	22	XRF	7/7/98	1	Room	710	Door	Casing	Solid	Metal	0.46
310	1954 Bldg.	23	XRF	7/7/98	1	Room	710	Stairs	Hand rail	Cracked	Metal	0.03
311	1954 Bldg.	24	XRF	7/7/98	1	Room	710	Window	Sash	Peeling	Metal	0
312	1954 Bldg.	25	XRF	7/7/98	1	Room	710	Door	Door	Solid	Metal	0.02
313	1954 Bldg.	26	XRF	7/7/98	1	Room	710	Floor		Cracked	Concrete	0
314	1954 Bldg.	154	XRF	7/7/98	1	Room	800		Radiator	Solid	Metal	0.01
315	1954 Bldg.	155	XRF	7/7/98	1	Room	800	Wall	Wall	Solid	Plaster	0.06
316	1954 Bldg.	156	XRF	7/7/98	1	Room	800	Wall	Midle Wall	Solid	Plaster	0.03
317	1954 Bldg.	157	XRF	7/7/98	1	Room	800	Door	Door	Solid	Metal	0
318	1954 Bldg.	158	XRF	7/7/98	1	Room	800	Door	Casing	Solid	Metal	0.03
319	1954 Bldg.	159	XRF	7/7/98	1	Room	800	Wall	Midle Wall	Solid	Drywall	0
320	1954 Bldg.	160	XRF	7/7/98	1	Room	900	Wall	Midle Wall	Solid	Drywall	0
321	1954 Bldg.	161	XRF	7/7/98	1	Room	900	Door	Casing	Solid	Metal	0.03
322	1954 Bldg.	162	XRF	7/7/98	1	Room	900	Wall	Wall	Solid	Drywall	0
323	1954 Bldg.	163	XRF	7/7/98	1	Room	900	Wall	Midle Wall	Solid	Drywall	0
324	1954 Bldg.	164	XRF	7/7/98	1	Room	900	Cabinet	Door	Solid	Wood	0
325	1954 Bldg.	180	XRF	7/7/98	1	Room	1100		Radiator	Solid	Metal	0.17
326	1954 Bldg.	181	XRF	7/7/98	1	Room	1100	Wall	Midle Wall	Solid	Plaster	0.09
327	1954 Bldg.	182	XRF	7/7/98	1	Room	1100	Window	Stool	Solid	Concrete	0
328	1954 Bldg.	183	XRF	7/7/98	1	Room	1100	Door	Door	Solid	Metal	0.01
329	1954 Bldg.	184	XRF	7/7/98	1	Room	1100	Door	Casing	Solid	Metal	0
330	1954 Bldg.	185	XRF	7/7/98	1	Room	1100	Door	Door	Solid	Wood	0.04
331	1954 Bldg.	186	XRF	7/7/98	1	Room	1100	Door	Casing	Solid	Metal	0.07

Saint Paul Public Schools
 DSF Building
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
332	1954 Bldg.	187	XRF	7/7/98	1	Room	1100	Cabinet	Door	Solid	Wood	0
333	1954 Bldg.	188	XRF	7/7/98	1	Room	1100	Ceiling		Solid	Plaster	0.05
334	1954 Bldg.	41	XRF	7/20/98	1	Room	1102	Door	Door	Solid	Metal	0.07
335	1954 Bldg.	42	XRF	7/20/98	1	Room	1102	Door	Casing	Solid	Metal	0.05
336	1954 Bldg.	43	XRF	7/20/98	1	Room	1102	Floor		Cracked	Concrte	0.01
337	1954 Bldg.	34	XRF	7/20/98	1	Room	1105	Door	Door	Solid	Metal	0.98
338	1954 Bldg.	35	XRF	7/20/98	1	Room	1105	Door	Door	Solid	Metal	0.05
339	1954 Bldg.	36	XRF	7/20/98	1	Room	1105	Door	Casing	Solid	Metal	0.03
340	1954 Bldg.	37	XRF	7/20/98	1	Room	1105	Wall	Midle Wall	Solid	Concrte	0
341	1954 Bldg.	38	XRF	7/20/98	1	Room	1105	Wall	Midle Wall	Solid	Concrte	0
342	1954 Bldg.	39	XRF	7/20/98	1	Room	1105	Door	Jamb	Solid	Metal	0.02
343	1954 Bldg.	40	XRF	7/20/98	1	Room	1105	Floor		Solid	Concrte	0
344	1954 Bldg.	30	XRF	7/20/98	1	Room	1110	Wall	Midle Wall	Solid	Concrte	0.03
345	1954 Bldg.	31	XRF	7/20/98	1	Room	1110	Window	Casing	Solid	Metal	0.03
346	1954 Bldg.	32	XRF	7/20/98	1	Room	1110	Door	Door	Solid	Metal	0.02
347	1954 Bldg.	33	XRF	7/20/98	1	Room	1110		Radiator	Solid	Metal	0
348	1954 Bldg.	145	XRF	7/16/98	1	Room	1149	Wall	Midle Wall	Solid	Concrte	0
349	1954 Bldg.	146	XRF	7/16/98	1	Room	1149	Wall	Midle Wall	Solid	Drywall	0.01
350	1954 Bldg.	147	XRF	7/16/98	1	Room	1149	Wall	Midle Wall	Solid	Concrte	0
351	1954 Bldg.	148	XRF	7/16/98	1	Room	1149	Floor		Peeling	Concrte	0
352	1954 Bldg.	149	XRF	7/16/98	1	Room	1149	Ceiling		Peeling	Concrte	0
353	1954 Bldg.	153	XRF	7/16/98	1	Room	1151	Floor	Column	Solid	Metal	0
354	1954 Bldg.	154	XRF	7/16/98	1	Room	1151	Floor		Cracked	Concrte	0
355	1954 Bldg.	140	XRF	7/16/98	1	Room	1153	Wall	Midle Wall	Solid	Drywall	0
356	1954 Bldg.	141	XRF	7/16/98	1	Room	1153	Wall	Midle Wall	Solid	Concrte	0
357	1954 Bldg.	142	XRF	7/16/98	1	Room	1153	Door	Door	Solid	Wood	0
358	1954 Bldg.	143	XRF	7/16/98	1	Room	1153	Door	Jamb	Solid	Wood	0
359	1954 Bldg.	144	XRF	7/16/98	1	Room	1153	Floor		Cracked	Concrte	0.01
360	1954 Bldg.	24	XRF	7/20/98	1	Room	1170	Door	Door	Solid	Metal	1.61
361	1954 Bldg.	25	XRF	7/20/98	1	Room	1170	Door	Jamb	Solid	Metal	3.49
362	1954 Bldg.	26	XRF	7/20/98	1	Room	1170	Wall	Transom	Solid	Wood	0.05
363	1954 Bldg.	27	XRF	7/20/98	1	Room	1170	Door	Door	Peeling	Metal	0.08
364	1954 Bldg.	28	XRF	7/20/98	1	Room	1170	Door	Jamb	Solid	Metal	5.09
365	1954 Bldg.	29	XRF	7/20/98	1	Room	1170	Floor		Cracked	Concrte	0.01
366	1954 Bldg.	150	XRF	7/16/98	1	Room	1190	Ceiling	Column	Solid	Metal	0
367	1954 Bldg.	151	XRF	7/16/98	1	Room	1200	Ceiling	Column	Solid	Metal	0.01
368	1954 Bldg.	152	XRF	7/16/98	1	Room	1200	Floor		Solid	Concrte	0.02
369	1954 Bldg.	155	XRF	7/16/98	1	Room	1210	Floor	Column	Solid	Metal	0
370	1954 Bldg.	14	XRF	7/20/98	1	Room	1220	Wall	Midle Wall	Solid	Concrte	0
371	1954 Bldg.	15	XRF	7/20/98	1	Room	1220	Door	Door	Solid	Metal	0
372	1954 Bldg.	16	XRF	7/20/98	1	Room	1220	Door	Jamb	Solid	Metal	0.01
373	1954 Bldg.	17	XRF	7/20/98	1	Room	1220	Door	Column	Solid	Metal	0.03
374	1954 Bldg.	18	XRF	7/20/98	1	Room	1220	Wall	Wall	Solid	Concrte	0
375	1954 Bldg.	19	XRF	7/20/98	1	Room	1220	Door	Door	Solid	Metal	0
376	1954 Bldg.	20	XRF	7/20/98	1	Room	1220	Door	Jamb	Solid	Metal	0.01
377	1954 Bldg.	21	XRF	7/20/98	1	Room	1220	Window	Casing	Solid	Metal	0.02
378	1954 Bldg.	22	XRF	7/20/98	1	Room	1220	Wall	Midle Wall	Solid	Concrte	0
379	1954 Bldg.	23	XRF	7/20/98	1	Room	1220	Floor		Solid	Concrte	0
380	1954 Bldg.	6	XRF	7/16/98	1	Room	1300	Wall	Midle Wall	Solid	Drywall	0
381	1954 Bldg.	7	XRF	7/16/98	1	Room	1300		Radiator	Solid	Metal	0.09
382	1954 Bldg.	8	XRF	7/16/98	1	Room	1300	Door	Casing	Solid	Metal	0.01
383	1954 Bldg.	9	XRF	7/16/98	1	Room	1300	Wall	Midle Wall	Solid	Concrte	0
384	1954 Bldg.	10	XRF	7/16/98	1	Room	1300	Door	Door	Solid	Wood	0
385	1954 Bldg.	11	XRF	7/16/98	1	Room	1300	Door	Casing	Solid	Metal	0
386	1954 Bldg.	12	XRF	7/16/98	1	Room	1300	Wall	Midle Wall	Solid	Drywall	0

Saint Paul Public Schools

DSF Building

Lead-Based Paint Inspection

A	B	C	D	E	F	G	H	I	J	K	L	
3	Site	Sample	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
387	1954 Bldg.	13	XRF	7/16/98	1	Room	1300	Door	Casing	Solid	Metal	0.02
388	1954 Bldg.	14	XRF	7/16/98	1	Room	1300	Wall	Midle Wall	Solid	Drywall	0.01
389	1954 Bldg.	15	XRF	7/16/98	1	Room	1300	Door	Door	Solid	Metal	0
390	1954 Bldg.	16	XRF	7/16/98	1	Room	1300	Door	Casing	Solid	Wood	0
391	1954 Bldg.	200	XRF	7/7/98	1	Room	1400	Wall	Midle Wall	Solid	Drywall	0
392	1954 Bldg.	201	XRF	7/7/98	1	Room	1400	Door	Door	Solid	Wood	0
393	1954 Bldg.	202	XRF	7/7/98	1	Room	1400	Door	Casing	Solid	Wood	0
394	1954 Bldg.	203	XRF	7/7/98	1	Room	1400	Wall	Midle Wall	Solid	Concrete	0
395	1954 Bldg.	204	XRF	7/7/98	1	Room	1400	Wall	Midle Wall	Solid	Drywall	0.01
396	1954 Bldg.	189	XRF	7/7/98	1	Room	1500	Wall	Midle Wall	Solid	Plaster	0
397	1954 Bldg.	190	XRF	7/7/98	1	Room	1500	Wall	Midle Wall	Solid	Drywall	0
398	1954 Bldg.	191	XRF	7/7/98	1	Room	1500	Window	Casing	Solid	Metal	0
399	1954 Bldg.	192	XRF	7/7/98	1	Room	1500	Door	Door	Solid	Metal	0.01
400	1954 Bldg.	193	XRF	7/7/98	1	Room	1500	Wall	Midle Wall	Solid	Concrete	0.01
401	1954 Bldg.	194	XRF	7/7/98	1	Room	1500	Door	Door	Solid	Wood	0
402	1954 Bldg.	195	XRF	7/7/98	1	Room	1500	Door	Casing	Solid	Metal	0.14
403	1954 Bldg.	196	XRF	7/7/98	1	Room	1500	Door	Door	Solid	Metal	0.06
404	1954 Bldg.	197	XRF	7/7/98	1	Room	1500	Door	Casing	Solid	Wood	0
405	1954 Bldg.	198	XRF	7/7/98	1	Room	1500	Floor		Solid	Concrete	0
406	1954 Bldg.	199	XRF	7/7/98	1	Room	1500	Ceiling		Solid	Concrete	0
407	1954 Bldg.	205	XRF	7/7/98	1	Room	1600	Wall	Midle Wall	Solid	Drywall	0
408	1954 Bldg.	206	XRF	7/7/98	1	Room	1600	Wall	Midle Wall	Solid	Drywall	0
409	1954 Bldg.	207	XRF	7/7/98	1	Room	1600	Wall	Midle Wall	Solid	Concrete	0
410	1954 Bldg.	208	XRF	7/7/98	1	Room	1600	Door	Door	Solid	Metal	0
411	1954 Bldg.	209	XRF	7/7/98	1	Room	1600	Door	Jamb	Solid	Wood	0
412	1954 Bldg.	210	XRF	7/7/98	1	Room	1700	Wall	Midle Wall	Solid	Concrete	0
413	1954 Bldg.	211	XRF	7/7/98	1	Room	1700	Door	Door	Solid	Metal	0.06
414	1954 Bldg.	212	XRF	7/7/98	1	Room	1700	Wall	Wall	Solid	Plaster	0
415	1954 Bldg.	213	XRF	7/7/98	1	Room	1700	Floor		Solid	Concrete	0.01
416	1954 Bldg.	214	XRF	7/7/98	1	Room	1700	Ceiling		Solid	Plaster	0
417	1954 Bldg.	215	XRF	7/7/98	1	Room	1800	Wall	Midle Wall	Solid	Concrete	0.04
418	1954 Bldg.	216	XRF	7/7/98	1	Room	1800	Door	Door	Solid	Metal	0
419	1954 Bldg.	217	XRF	7/7/98	1	Room	1800	Window	Casing	Solid	Metal	0.11
420	1954 Bldg.	218	XRF	7/7/98	1	Room	1800	Wall	Midle Wall	Solid	Drywall	0
421	1954 Bldg.	219	XRF	7/7/98	1	Room	1800	Door	Door	Solid	Metal	0
422	1954 Bldg.	220	XRF	7/7/98	1	Room	1900	Door	Door	Solid	Metal	0.01
423	1954 Bldg.	221	XRF	7/7/98	1	Room	1900	Window	Casing	Solid	Metal	0
424	1954 Bldg.	222	XRF	7/7/98	1	Room	1900	Wall	Midle Wall	Solid	Concrete	0
425	1954 Bldg.	223	XRF	7/7/98	1	Room	1900	Wall	Midle Wall	Solid	Concrete	0
426	1954 Bldg.	224	XRF	7/7/98	1	Room	1900	Wall	Midle Wall	Solid	Concrete	0
427	1954 Bldg.	225	XRF	7/7/98	1	Room	1900	Door	Casing	Solid	Metal	0
428	1954 Bldg.	226	XRF	7/7/98	1	Room	1900	Wall	Wall	Solid	Drywall	0
429	1954 Bldg.	227	XRF	7/7/98	1	Room	1900	Door	Jamb	Solid	Metal	0.01
430	1954 Bldg.	228	XRF	7/7/98	1	Room	1950	Wall	Midle Wall	Solid	Drywall	0
431	1954 Bldg.	229	XRF	7/7/98	1	Room	1950	Door	Door	Solid	Metal	0
432	1954 Bldg.	230	XRF	7/7/98	1	Room	1950	Door	Jamb	Solid	Metal	0.03
433	1954 Bldg.	231	XRF	7/7/98	1	Room	1950	Wall	Wall	Solid	Drywall	0.1
434	1954 Bldg.	232	XRF	7/7/98	1	Room	1950	Door	Jamb	Solid	Metal	0.2
435	1954 Bldg.	233	XRF	7/7/98	1	Room	1950	Wall	Wall	Solid	Drywall	0
436	1954 Bldg.	234	XRF	7/7/98	1	Room	1950	Wall	Midle Wall	Solid	Drywall	0.02
437	1954 Bldg.	235	XRF	7/7/98	1	Room	1950	Door	Door	Solid	Wood	0
438	1954 Bldg.	236	XRF	7/7/98	1	Room	1950	Door	Casing	Solid	Metal	0.19
439	1954 Bldg.	237	XRF	7/7/98	1	Room	1950	Wall	Wall	Solid	Drywall	0.04
440	1954 Bldg.	238	XRF	7/7/98	1	Room	1950	Door	Door	Solid	Wood	0.01
441	1954 Bldg.	239	XRF	7/7/98	1	Room	1950	Wall	Midle Wall	Solid	Drywall	0.01

Saint Paul Public Schools

DSF Building

Lead-Based Paint Inspection

A	B	C	D	E	F	G	H	I	J	K	L	
3	Site	Sample	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
442	1954 Bldg.	240	XRF	7/7/98	1	Room	1950	Door	Casing	Solid	Metal	0.02
443	1954 Bldg.	241	XRF	7/7/98	1	Room	1950	Door	Door	Solid	Wood	0
444	1954 Bldg.	242	XRF	7/7/98	1	Room	1950	Cabinet	Door	Solid	Wood	0
445	1954 Bldg.	243	XRF	7/7/98	1	Room	1950	Wall	Wall	Solid	Concrete	0
446	1954 Bldg.	244	XRF	7/7/98	1	Room	1950	Wall	Wall	Solid	Concrete	0
447	1954 Bldg.	245	XRF	7/7/98	1	Room	1950	Wall	Wall	Solid	Concrete	0.01
448	1954 Bldg.	246	XRF	7/7/98	1	Room	1950	Door	Door	Solid	Metal	0.01
449	1954 Bldg.	252	XRF	7/7/98	1	Room	1975	Door	Door	Solid	Metal	0
450	1954 Bldg.	253	XRF	7/7/98	1	Room	1975	Window	Casing	Solid	Metal	0
451	1954 Bldg.	254	XRF	7/7/98	1	Room	1975	Wall	Midle Wall	Solid	Concrete	0
452	1954 Bldg.	255	XRF	7/7/98	1	Room	1975	Wall	Midle Wall	Solid	Drywall	0
453	1954 Bldg.	256	XRF	7/7/98	1	Room	1975	Wall	Midle Wall	Solid	Drywall	0
454	1954 Bldg.	93	XRF	7/16/98	2	Room	2010	Wall	Midle Wall	Solid	Wood	0
455	1954 Bldg.	94	XRF	7/16/98	2	Room	2010	Door	Door	Solid	Wood	0.03
456	1954 Bldg.	95	XRF	7/16/98	2	Room	2010	Window	Casing	Solid	Metal	0.29
457	1954 Bldg.	96	XRF	7/16/98	2	Room	2010	Door	Casing	Solid	Metal	0.25
458	1954 Bldg.	97	XRF	7/16/98	2	Room	2010	Wall	Wall	Solid	Plaster	0.37
459	1954 Bldg.	98	XRF	7/16/98	2	Room	2050	Door	Door	Solid	Wood	0
460	1954 Bldg.	99	XRF	7/16/98	2	Room	2050	Door	Casing	Solid	Metal	0
461	1954 Bldg.	100	XRF	7/16/98	2	Room	2050	Wall	Wall	Solid	Plaster	0.72
462	1954 Bldg.	101	XRF	7/16/98	2	Room	2050		Radiator	Solid	Metal	0.34
463	1954 Bldg.	102	XRF	7/16/98	2	Room	2050		Elec Panel	Solid	Metal	0.43
464	1954 Bldg.	103	XRF	7/16/98	2	Room	2050	Door	Casing	Solid	Metal	0.31
465	1954 Bldg.	104	XRF	7/16/98	2	Room	2050	Window	Casing	Solid	Metal	0.14
466	1954 Bldg.	105	XRF	7/16/98	2	Room	2050	Wall	Midle Wall	Solid	Wood	0
467	1954 Bldg.	106	XRF	7/16/98	2	Room	2050		Radiator	Solid	Metal	0.3
468	1954 Bldg.	107	XRF	7/16/98	2	Room	2050	Wall	Wall	Solid	Plaster	0.29
469	1954 Bldg.	108	XRF	7/16/98	2	Room	2080	Wall	Wall	Solid	Plaster	0.58
470	1954 Bldg.	109	XRF	7/16/98	2	Room	2080		Radiator	Solid	Metal	0.67
471	1954 Bldg.	110	XRF	7/16/98	2	Room	2080	Door	Door	Solid	Wood	0.01
472	1954 Bldg.	111	XRF	7/16/98	2	Room	2080	Door	Casing	Solid	Metal	0.32
473	1954 Bldg.	112	XRF	7/16/98	2	Room	2080	Cabinet	Door	Solid	Wood	0
474	1954 Bldg.	113	XRF	7/16/98	2	Room	2090	Wall	Wall	Solid	Plaster	0.49
475	1954 Bldg.	114	XRF	7/16/98	2	Room	2090		Radiator	Solid	Metal	0.56
476	1954 Bldg.	115	XRF	7/16/98	2	Room	2090	Door	Door	Solid	Wood	0.01
477	1954 Bldg.	116	XRF	7/16/98	2	Room	2090	Door	Casing	Solid	Metal	0.22
478	1954 Bldg.	117	XRF	7/16/98	2	Room	2090	Door	Door	Solid	Wood	0.01
479	1954 Bldg.	118	XRF	7/16/98	2	Room	2100	Wall	Wall	Solid	Plaster	0.53
480	1954 Bldg.	119	XRF	7/16/98	2	Room	2100		Radiator	Solid	Metal	0.39
481	1954 Bldg.	120	XRF	7/16/98	2	Room	2100	Door	Door	Solid	Wood	0.01
482	1954 Bldg.	121	XRF	7/16/98	2	Room	2100	Door	Casing	Solid	Metal	0.25
483	1954 Bldg.	122	XRF	7/16/98	2	Room	2100	Wall	Baseboard	Solid	Wood	0.06
484	1954 Bldg.	62	XRF	7/16/98	2	Room	2120	Wall	Wall	Solid	Plaster	0.01
485	1954 Bldg.	63	XRF	7/16/98	2	Room	2120		Radiator	Solid	Metal	0.16
486	1954 Bldg.	64	XRF	7/16/98	2	Room	2120	Wall	Midle Wall	Solid	Plaster	0.19
487	1954 Bldg.	65	XRF	7/16/98	2	Room	2120	Door	Door	Solid	Wood	0.01
488	1954 Bldg.	66	XRF	7/16/98	2	Room	2120	Door	Jamb	Solid	Metal	0.09
489	1954 Bldg.	67	XRF	7/16/98	2	Room	2120	Wall	Baseboard	Solid	Wood	0.05
490	1954 Bldg.	27	XRF	7/16/98	2	Room	2130	Wall	Wall	Solid	Drywall	0.02
491	1954 Bldg.	28	XRF	7/16/98	2	Room	2130		Radiator	Solid	Metal	0.25
492	1954 Bldg.	29	XRF	7/16/98	2	Room	2130	Door	Door	Solid	Wood	0.01
493	1954 Bldg.	30	XRF	7/16/98	2	Room	2130	Door	Jamb	Solid	Wood	0.23
494	1954 Bldg.	31	XRF	7/16/98	2	Room	2130	Wall	Midle Wall	Solid	Plaster	0.14
495	1954 Bldg.	32	XRF	7/16/98	2	Room	2130	Wall	Baseboard	Solid	Wood	0.12
496	1954 Bldg.	33	XRF	7/16/98	2	Room	2140	Wall	Wall	Solid	Plaster	0.01

Saint Paul Public Schools

DSF Building

Lead-Based Paint Inspection

3	A	B	C	D	E	F	G	H	I	J	K	L
	Site	Sample	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
497	1954 Bldg.	34	XRF	7/16/98	2	Room	2140	Radiator	Solid	Metal	0.18	
498	1954 Bldg.	35	XRF	7/16/98	2	Room	2140	Cabinet	Door	Solid	Wood	0.01
499	1954 Bldg.	36	XRF	7/16/98	2	Room	2140	Cabinet	Door	Solid	Wood	0
500	1954 Bldg.	37	XRF	7/16/98	2	Room	2140	Door	Door	Solid	Wood	0.01
501	1954 Bldg.	38	XRF	7/16/98	2	Room	2140	Door	Jamb	Solid	Metal	0.14
502	1954 Bldg.	39	XRF	7/16/98	2	Room	2140	Wall	Midle Wall	Solid	Drywall	0
503	1954 Bldg.	40	XRF	7/16/98	2	Room	2150	Wall	Wall	Solid	Wood	0.03
504	1954 Bldg.	41	XRF	7/16/98	2	Room	2150	Wall	Wall Rgstr	Solid	Metal	0.42
505	1954 Bldg.	42	XRF	7/16/98	2	Room	2150	Door	Door	Solid	Wood	0
506	1954 Bldg.	43	XRF	7/16/98	2	Room	2150	Door	Jamb	Solid	Wood	0.2
507	1954 Bldg.	44	XRF	7/16/98	2	Room	2160	Wall	Wall	Solid	Wood	0.04
508	1954 Bldg.	45	XRF	7/16/98	2	Room	2160	Wall	Wall Rgstr	Solid	Metal	0.53
509	1954 Bldg.	46	XRF	7/16/98	2	Room	2160	Door	Casing	Solid	Metal	0.29
510	1954 Bldg.	47	XRF	7/16/98	2	Room	2160	Door	Jamb	Solid	Wood	0.24
511	1954 Bldg.	48	XRF	7/16/98	2	Room	2190	Wall	Wall	Solid	Drywall	0
512	1954 Bldg.	49	XRF	7/16/98	2	Room	2190	Wall	Wall	Solid	Plaster	0
513	1954 Bldg.	50	XRF	7/16/98	2	Room	2190	Wall	Wall Rgstr	Solid	Metal	0.19
514	1954 Bldg.	51	XRF	7/16/98	2	Room	2190	Door	Door	Solid	Wood	0
515	1954 Bldg.	52	XRF	7/16/98	2	Room	2190	Door	Jamb	Solid	Metal	0.15
516	1954 Bldg.	53	XRF	7/16/98	2	Room	2200	Wall	Midle Wall	Solid	Drywall	0
517	1954 Bldg.	54	XRF	7/16/98	2	Room	2200	Wall	Wall Rgstr	Solid	Metal	0.06
518	1954 Bldg.	55	XRF	7/16/98	2	Room	2200	Door	Door	Solid	Wood	0
519	1954 Bldg.	56	XRF	7/16/98	2	Room	2200	Door	Jamb	Solid	Metal	0.02
520	1954 Bldg.	86	XRF	7/16/98	2	Room	2200	Wall	Midle Wall	Solid	Plaster	0.4
521	1954 Bldg.	87	XRF	7/16/98	2	Room	2200	Wall	Baseboard	Solid	Wood	0
522	1954 Bldg.	88	XRF	7/16/98	2	Room	2200	Door	Door	Solid	Wood	0.06
523	1954 Bldg.	89	XRF	7/16/98	2	Room	2200	Door	Jamb	Solid	Wood	0
524	1954 Bldg.	90	XRF	7/16/98	2	Room	2200	Window	Casing	Solid	Metal	0.3
525	1954 Bldg.	91	XRF	7/16/98	2	Room	2200	Wall	Wall Rgstr	Solid	Metal	0.21
526	1954 Bldg.	92	XRF	7/16/98	2	Room	2200		Radiator	Solid	Metal	0
527	1954 Bldg.	57	XRF	7/16/98	2	Room	2210	Wall	Midle Wall	Solid	Drywall	0
528	1954 Bldg.	58	XRF	7/16/98	2	Room	2210		Radiator	Solid	Metal	0.21
529	1954 Bldg.	59	XRF	7/16/98	2	Room	2210	Wall	Wall	Solid	Plaster	0
530	1954 Bldg.	60	XRF	7/16/98	2	Room	2210	Door	Door	Solid	Wood	0
531	1954 Bldg.	61	XRF	7/16/98	2	Room	2210	Door	Jamb	Solid	Metal	0
532	1954 Bldg.	68	XRF	7/16/98	2	Room	2220	Wall	Wall	Solid	Plaster	0.04
533	1954 Bldg.	69	XRF	7/16/98	2	Room	2220	Wall	Wall	Solid	Plaster	0.04
534	1954 Bldg.	70	XRF	7/16/98	2	Room	2220		Radiator	Solid	Metal	0.16
535	1954 Bldg.	71	XRF	7/16/98	2	Room	2220	Door	Door	Solid	Wood	0.01
536	1954 Bldg.	72	XRF	7/16/98	2	Room	2220	Door	Jamb	Solid	Metal	0.17
537	1954 Bldg.	137	XRF	7/16/98	2	Room	2330	Wall	Wall	Solid	Plaster	0.07
538	1954 Bldg.	138	XRF	7/16/98	2	Room	2330	Door	Door	Solid	Wood	0
539	1954 Bldg.	139	XRF	7/16/98	2	Room	2330	Door	Casing	Solid	Metal	0.09
540	1954 Bldg.	123	XRF	7/16/98	2	Room	2400	Wall	Wall	Solid	Concrete	0.1
541	1954 Bldg.	124	XRF	7/16/98	2	Room	2400	Wall	Wall	Solid	Plaster	0.65
542	1954 Bldg.	125	XRF	7/16/98	2	Room	2400	Door	Door	Solid	Wood	0.01
543	1954 Bldg.	126	XRF	7/16/98	2	Room	2400	Wall	Baseboard	Solid	Wood	0.11
544	1954 Bldg.	127	XRF	7/16/98	2	Room	2400	Wall	Midle Wall	Solid	Plaster	0.17
545	1954 Bldg.	128	XRF	7/16/98	2	Room	2400		Radiator	Solid	Metal	0.21
546	1954 Bldg.	129	XRF	7/16/98	2	Room	2400	Window	Casing	Solid	Metal	0.13
547	1954 Bldg.	130	XRF	7/16/98	2	Room	2400	Wall	Wall	Solid	Plaster	0.14
548	1954 Bldg.	131	XRF	7/16/98	2	Room	2400	Wall	Midle Wall	Solid	Plaster	0.28
549	1954 Bldg.	132	XRF	7/16/98	2	Room	2410	Wall	Wall	Solid	Plaster	0.17
550	1954 Bldg.	133	XRF	7/16/98	2	Room	2410	Window	Casing	Solid	Metal	0.08
551	1954 Bldg.	134	XRF	7/16/98	2	Room	2410	Door	Door	Solid	Wood	0

Saint Paul Public Schools
 DSF Building
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	Sample	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Result
552	1954 Bldg.	135	XRF	7/16/98	2	Room	2410	Door	Jamb	Solid	Metal	0.07
553	1954 Bldg.	136	XRF	7/16/98	2	Room	2410		Radiator	Solid	Metal	0.13
554	1954 Bldg.	139	XRF	7/20/98	2	Room	2500	Wall	Midle Wall	Solid	Concrte	0
555	1954 Bldg.	140	XRF	7/20/98	2	Room	2500	Wall	Column	Solid	Metal	0.06
556	1954 Bldg.	141	XRF	7/20/98	2	Room	2500	Stairs	Hand rail	Solid	Metal	0.01
557	1954 Bldg.	142	XRF	7/20/98	2	Room	2500	Wall	Midle Wall	Solid	Drywall	0
558	1954 Bldg.	143	XRF	7/20/98	2	Room	2550	Door	Door	Solid	Metal	0
559	1954 Bldg.	144	XRF	7/20/98	2	Room	2550	Door	Jamb	Solid	Metal	0
560	1954 Bldg.	145	XRF	7/20/98	2	Room	2550	Stairs	Hand rail	Solid	Metal	0
561	1954 Bldg.	146	XRF	7/20/98	2	Room	2550	Stairs	Column	Solid	Metal	0.05
562	1954 Bldg.	147	XRF	7/20/98	2	Room	2550	Wall	Midle Wall	Solid	Concrte	0.01
563	1954 Bldg.	25	XRF	7/16/98	1	Stairwell	1301	Wall	Wall	Solid	Plaster	0.46
564	1954 Bldg.	26	XRF	7/16/98	1	Stairwell	1301	Ceiling		Solid	Plaster	0.05

APPENDIX B

INSPECTOR

William Sloan
MDH Lead Inspector # 476