


Midwest
Environmental
Consulting, L.L.C.



Printed on Recycled Paper

**Humboldt Secondary Complex SH
Saint Paul Public Schools**

Lead-Based Paint Inspection

Inspection Dates: 2/26/97, 2/27/97, 3/1/97, 3/2/97

submitted to:

Saint Paul Public Schools

MEC Project # 62/0197P

INTRODUCTION

At the request of Saint Paul Public Schools Environmental Safety Department, Midwest Environmental Consulting, L.L.C. (MEC), conducted a lead-based paint inspection at Humboldt Secondary Complex SH, 30 E. Baker St., St. Paul, MN. The purpose of this inspection was to identify lead-based painted, varnished, or otherwise coated building components on the interior and exterior of the school building.

The inspection protocol incorporated applicable portions of the U.S. Department of Housing and Urban Development (HUD) *Guidelines for the Evaluation and Control of Lead-based Paint Hazards in Housing* (HUD Guidelines, June 1995) and OSHA 1926.62 requirements (Lead in Construction). The HUD guidelines are formulated to guide agencies in conducting random sampling of the interiors and exteriors of dwellings and common areas in public housing. The OSHA requirement is designed to minimize worker exposure when working with material containing lead.

Confirmatory testing was conducted when inconclusive XRF results were encountered. Inconclusive refers to XRF readings less than 0.2 mg/cm² (milligrams per square centimeter). Inconclusive results were confirmed with laboratory analysis of paint chip samples (Appendix B). This report contains a list of such results.

The United States Environmental Protection Agency defines "lead-based paint" as a paint or other surface coating that contains lead equal to or in excess of 1.0 milligrams per square centimeter when analyzed by XRF or more than 0.5% by weight (5000 parts per million) by laboratory analysis of a bulk sample.

Minnesota Department of Labor and Industry (MN OSHA) adopted the EPA lead levels for the purpose of enforcing OSHA 1926.62 federal regulations. Detection of lead in dried paint film by XRF is a dependable indicator of levels of lead and is accepted by MN OSHA.

For this Saint Paul Public Schools Lead Inspection, all building components were tested on site using a Niton XL® X-ray Fluorescence Spectrum Analyzer⁽¹⁾. Building components included walls, ceilings, floors, moldings, window and door components, door surfaces, and miscellaneous features such as shelves or bookcases. Only painted or glazed surfaces or surfaces which were varnished were tested. Suspended ceilings, structural steel, and corrugated decking were not included in the inspection. Neither anodized (e.g., window sashes) nor plastic (e.g., vinyl baseboard and vinyl mini-blinds) were included in the scope of this inspection.

⁽¹⁾ This is a portable hand held machine that can analyze building components instantly for lead concentrations.

Each building was divided into unique sites based on the year of construction or renovation. Portable classrooms, playgrounds, and other detached buildings were automatically designated as a unique site. Each site was inspected independently assuming differences in painting history and construction characteristics.

SITE DESCRIPTION AND BUILDING HISTORY

According to information provided to MEC by Saint Paul Public Schools, Humboldt Secondary Complex SH was constructed in essentially one phase. This phase includes the 206,958 square-foot section of the building and dates from 1976.

All room and area designations used in this report are depicted on sampling maps found in Appendix A.

XRF SAMPLE RESULTS TABLE

The results of all samples analyzed are listed in the table at the end of this section. The following is a description of the column headings:

Site	Each school is divided into sites based on their unique construction characteristics. Each site has a unique date of construction or major renovation.
Sample #	Each sample taken was given a unique number to identify the type and location of the sample. The sampling date is an integral part of the sample number.
Analysis	This defines the type of analysis which can be categorized into two types: 1) XRF: This is an on-site analysis using a hand held Niton XL® X-ray Fluorescence Spectrum Analyzer; 2) Bulk or Chip: This is a bulk sample where paint is removed from the substrate and sent to a laboratory for analysis;
Floor	This is the level of the building in which the area tested was found, example, 1 (first floor), 0 (basement), etc.
Area	This further defines the specific functional space inspected such as a classroom, exterior, playground, gym, kitchen, etc.

Room #	This is typically the actual number on the room as identified at the building.
Component	Building "components" included walls, ceilings, floors, moldings, window and door components, door surfaces, and miscellaneous features such as shelves or bookcases.
Feature	Identifies more detailed information of the component.
Condition	This describes condition of the surface, whether it is intact, cracked, peeling, or chalking.
Substrate	This refers to the material the building component is made of (wood, concrete, drywall, metal, etc.).
Result	This is the analysis results for lead. Less than 1.0 mg/cm ² or less than 0.5% by weight is considered to be non-lead and these building components are below the action levels of EPA and HUD. (All results are in mg/cm ² except where noted.)

The table of results is designed for quick information on lead concentrations of tested building components. Generally, all repetitions of a test combination within a given room or area, may be assumed to contain similar concentrations of lead to that of the tested sample. For instance, the lead concentration of a tested wooden window sash was found to be above the action level of 1.0 mg/cm² in a given classroom. The classroom has five windows, all of wood, the same color and appearing to be of the same era. It can be assumed that the remaining four wooden window sashes each contain lead above the action limit.

Other columns identify the component and the component feature tested, condition of the component, type of substrate and the result of the analytical test.

As an example, the following illustration shows that the wooden door jamb in Room 123, first floor in the 1923 building section was in good, solid condition, and had an XRF test result of 0.3 mg/cm², which is below the action level.

Illustration Only

Site	Sample #	Date	Analysis	Floor	Area	Room #	Component	Feature	Condition	Substrate	Results
1923 Bldg.	52		XRF	1	Room	123	Door	Jamb	Solid	Wood	0.3

In a similar manner, the table shows that the plaster walls in room 23, on the second floor has peeling paint with more than 1.0 mg/cm² (shaded).

ILLUSTRATION ONLY

Site	Sample #	Date	Analysis	Floor	Area	Room #	Component	Feature	Condition	Substrate	Results
1910 Bldg.	16		XRF	2	Room	23	Door	Jamb	Peeling	Wood	0.25
1910 Bldg.	17		XRF	2	Room	23	Wall	Wall	Peeling	Plaster	1.2
1910 Bldg.	18		XRF	2	Room	23	Ceiling	Peeling	Plaster	0.25	
1910 Bldg.	19		XRF	2	Room	23	Wall	Baseboard	Peeling	Wood	0.002

APPLICABLE REGULATIONS

When building components test above 1.0 mg/cm² of lead by XRF or 0.5% lead by weight from laboratory analysis all employees and contractors who will be working with these components in a construction related activity must be notified. The requirements of OSHA 1926.62, Lead in Construction are enforceable. This regulation defines construction work as "work for construction, alteration and/or repair, including painting and decorating." This regulation further defines monitoring requirements to minimize employee exposure to lead during construction activities.

When work is performed on external painted building structures (i.e. flashing, fire escapes, playground equipment, handrails, etc.), regulations of the Minnesota Pollution Control Agency (MPCA) may also be applicable. For removal of lead based paint from steel structures, MN Rules 7025.0200 - 7025.0380 apply to steel materials on the exterior of a building, or on the property when levels exceed 0.5 mg/cm² based on the average of three XRF spectrum results of the sample tested, or 5,000 ppm by laboratory analysis. If it is other than a steel surface, then MPCA regulates the painted surfaces under MN Rules 7025.010 - 7025.0080, when surfaces are to be disturbed using abrasive blasting methods.

Please contact MEC directly if you have questions about any portion of this report or the lead-based paint inspection itself.


APPENDIX A


XRF TESTING DATA WITH LOCATION MAPS



STRUCTURE

2/21/97 - Break-in
3/1/97 - Break-in

FIRST FLOOR EAST







13
3
11

CONSTRUCTED: 1909, X. 38, '76

HUMBLELOT SR HIGH SCHOOL
610 HUMBLELOT AVE.
ST. PAUL, MINNESOTA

INGELENDET SCHOOL DIST. #625
380 COLBYNE STREET
ST. PAUL, MINNESOTA 55102

(3)



N

W


E


S


THIRD FLOOR


3/1/97

D1










FIRST FLOOR SOUTH

D

Site Z
C2/097P



INDEPENDENT SCHOOL DIST. #625
360 COLBORNE STREET
ST. PAUL, MINNESOTA 55102


HUMBOLDT SR. HIGH SCHOOL
640 HUMBOLDT AVE.
ST. PAUL, MINNESOTA


CONSTR

A

B


C







D
SECOND FLOOR SOUTH


3/1/97





10/10/1






INDEPENDENT SCHOOL DIST. #625
360 COLBORNE STREET
ST. PAUL, MINNESOTA 55102

HUMBOLDT SR. HIGH SCHOOL
640 HUMBOLDT AVE.
ST. PAUL, MINNESOTA

CONSTRUCTED: 1909, 24, 59, 78

WIT
6
12



INDEPENDENT SCHOOL DIST. #625
ST. PAUL, MINNESOTA 55102

HUMBOLDT SR. HIGH SCHOOL
640 HUMBOLDT AVE.
ST. PAUL, MINNESOTA

CONSTRUCTED: 1909-24, '59, '75

13

1

865


13


1


865

FIRST FLOOR EAST

48
47
4








INDEPENDENT SCHOOL DIST. #625
300 COLBORNE STREET
ST. PAUL, MINNESOTA 55102

HUMBOLDT SR. HIGH SCHOOL
640 HUMBOLDT AVE.
ST. PAUL, MINNESOTA

CONSTRUCTED: 1909, 24, 59, 76

411
4




SECOND FLOOR SOUTH

HUMBOLDT SR HIGH SCHOOL
640 HUMBOLDT AVE.
ST. PAUL, MINNESOTA

INDEPENDENT SCHOOL DIST. #625
380 COLBORNE STREET
ST. PAUL, MINNESOTA 55102

CONSTRUCTED: 1909, 2L 58, 78

13
2
1
1



Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
1	Humboldt Senior High School											
2												
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
4	1976 bldg	82	XRF	2/26/97	1	Auditoriu	0	Wall	Wall	Solid	Concrete	0.08
5	1976 bldg	83	XRF	2/26/97	1	Auditoriu	0	Wall	Baseboar	Solid	Concrete	0.03
6	1976 bldg	84	XRF	2/26/97	1	Auditoriu	0	Ceiling		Solid	Drywall	0
7	1976 bldg	85	XRF	2/26/97	1	Auditoriu	0	Stairs	Hand rail	Solid	Metal	0.01
8	1976 bldg	86	XRF	2/26/97	1	Auditoriu	0	Door	Casing	Solid	Metal	0.12
9	1976 bldg	87	XRF	2/26/97	1	Auditoriu	0	Door	Door	Solid	Wood	0
10	1976 bldg	88	XRF	2/26/97	1	Auditoriu	0	Door	Column	Solid	Concrete	0
11	1976 bldg	89	XRF	2/26/97	1	Auditoriu	0	Seat	Frame	Solid	Metal	0.69
12	1976 bldg	90	XRF	2/26/97	1	Auditoriu	0	Wall	Midle Wall	Solid	Drywall	0.01
13	1976 bldg	25	XRF	3/1/97	1	Classroo	0	Wall	Wall	Solid	Concrete	0.03
14	1976 bldg	26	XRF	3/1/97	1	Classroo	0	Wall	Wall	Solid	Drywall	0.01
15	1976 bldg	27	XRF	3/1/97	1	Classroo	0	Window	Sash	Solid	Metal	0
16	1976 bldg	28	XRF	3/1/97	1	Classroo	0	Door	Casing	Peeling	Metal	0.01
17	1976 bldg	29	XRF	3/1/97	1	Classroo	0	Door	Door	Solid	Metal	0
18	1976 bldg	30	XRF	3/1/97	1	Classroo	0	Closet	Wall	Solid	Drywall	0
19	1976 bldg	31	XRF	3/1/97	1	Classroo	0	Door	Door	Solid	Wood	0
20	1976 bldg	146	XRF	2/27/97	1	Classroo	92	Wall	Midle Wall	Solid	Concrete	0
21	1976 bldg	147	XRF	2/27/97	1	Classroo	92	Wall	Midle Wall	Solid	Drywall	0.01
22	1976 bldg	148	XRF	2/27/97	1	Classroo	92	Ceiling		Solid	Concrete	0
23	1976 bldg	149	XRF	2/27/97	1	Classroo	92	Wall	Chair rail	Peeling	Metal	0.02
24	1976 bldg	150	XRF	2/27/97	1	Classroo	92	Door	Door	Solid	Wood	0
25	1976 bldg	151	XRF	2/27/97	1	Classroo	92	Door	Jamb	Solid	Metal	0.07
26	1976 bldg	152	XRF	2/27/97	1	Classroo	92	Stairs	Hand rail	Peeling	Metal	0.07
27	1976 bldg	202	XRF	2/27/97	1	Classroo	111	Wall	Wall	Solid	Concrete	0.04
28	1976 bldg	203	XRF	2/27/97	1	Classroo	111	Floor		Peeling	Concrete	0.01
29	1976 bldg	204	XRF	2/27/97	1	Classroo	111	Wall	Wall	Solid	Concrete	0.01
30	1976 bldg	205	XRF	2/27/97	1	Classroo	111	Wall	Baseboar	Solid	Concrete	0
31	1976 bldg	206	XRF	2/27/97	1	Classroo	111	Ceiling		Solid	Concrete	0
32	1976 bldg	207	XRF	2/27/97	1	Classroo	111	Window	Sash	Solid	Metal	0.01
33	1976 bldg	208	XRF	2/27/97	1	Classroo	111	Door	Jamb	Solid	Metal	0.01
34	1976 bldg	209	XRF	2/27/97	1	Classroo	111	Door	Door	Solid	Wood	0
35	1976 bldg	211	XRF	2/27/97	1	Classroo	111	Closet	Wall	Solid	Concrete	0
36	1976 bldg	217	XRF	2/27/97	1	Classroo	117	Wall	Wall	Solid	Concrete	0
37	1976 bldg	218	XRF	2/27/97	1	Classroo	117	Wall	Midle Wall	Solid	Wood	1.03
38	1976 bldg	219	XRF	2/27/97	1	Classroo	117	Wall	Baseboar	Solid	Concrete	0
39	1976 bldg	220	XRF	2/27/97	1	Classroo	117	Window	Sash	Solid	Metal	0.16
40	1976 bldg	221	XRF	2/27/97	1	Classroo	117	Ceiling		Solid	Concrete	0.04
41	1976 bldg	222	XRF	2/27/97	1	Classroo	117	Door	Door	Solid	Metal	0
42	1976 bldg	223	XRF	2/27/97	1	Classroo	117	Door	Casing	Solid	Metal	0.01
43	1976 bldg	224	XRF	2/27/97	1	Classroo	118	Wall	Midle Wall	Solid	Concrete	0.07
44	1976 bldg	225	XRF	2/27/97	1	Classroo	118	Wall	Wall	Solid	Concrete	0
45	1976 bldg	226	XRF	2/27/97	1	Classroo	118	Wall	Wall	Solid	Wood	0.86
46	1976 bldg	227	XRF	2/27/97	1	Classroo	118	Wall	Baseboar	Solid	Concrete	0
47	1976 bldg	228	XRF	2/27/97	1	Classroo	118	Ceiling		Peeling	Concrete	0.01
48	1976 bldg	229	XRF	2/27/97	1	Classroo	118	Door	Casing	Solid	Metal	0.01
49	1976 bldg	230	XRF	2/27/97	1	Classroo	118	Door	Door	Solid	Wood	0
50	1976 bldg	10	XRF	3/1/97	1	Classroo	125	Wall	Wall	Solid	Concrete	0
51	1976 bldg	11	XRF	3/1/97	1	Classroo	125	Wall	Wall	Solid	Drywall	0.05
52	1976 bldg	12	XRF	3/1/97	1	Classroo	125	Wall	Midle Wall	Solid	Concrete	0
53	1976 bldg	13	XRF	3/1/97	1	Classroo	125	Wall	Wall	Solid	Concrete	0.12
54	1976 bldg	14	XRF	3/1/97	1	Classroo	125	Window	Sash	Solid	Metal	0.15
55	1976 bldg	15	XRF	3/1/97	1	Classroo	125	Wall	Wall	Solid	Wood	0
56	1976 bldg	16	XRF	3/1/97	1	Classroo	125	Closet	Wall	Solid	Concrete	0
57	1976 bldg	17	XRF	3/1/97	1	Classroo	125	Door	Door	Solid	Wood	0
58	1976 bldg	18	XRF	3/1/97	1	Classroo	125	Door	Casing	Solid	Concrete	0.05
59	1976 bldg	19	XRF	3/1/97	1	Classroo	126	Door	Casing	Solid	Drywall	0.01
60	1976 bldg	20	XRF	3/1/97	1	Classroo	126	Wall	Midle Wall	Solid	Concrete	0

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
61	1976 bldg	21	XRF	3/1/97	1	Classroo	126	Window	Sash	Solid	Metal	0.17
62	1976 bldg	22	XRF	3/1/97	1	Classroo	126	Door	Door	Solid	Wood	0
63	1976 bldg	23	XRF	3/1/97	1	Classroo	126	Door	Jamb	Solid	Metal	0.07
64	1976 bldg	24	XRF	3/1/97	1	Classroo	126	Wall	Wall	Solid	Wood	0
65	1976 bldg	40	XRF	3/1/97	1	Classroo	128	Wall	Midle Wall	Solid	Concrete	0
66	1976 bldg	41	XRF	3/1/97	1	Classroo	128	Wall	Wall	Solid	Drywall	0.01
67	1976 bldg	42	XRF	3/1/97	1	Classroo	128	Window	Sash	Solid	Metal	0.01
68	1976 bldg	43	XRF	3/1/97	1	Classroo	128	Window	Casing	Solid	Metal	0.03
69	1976 bldg	44	XRF	3/1/97	1	Classroo	128	Door	Jamb	Solid	Metal	0.04
70	1976 bldg	45	XRF	3/1/97	1	Classroo	128	Door	Door	Solid	Wood	0
71	1976 bldg	46	XRF	3/1/97	1	Classroo	128	Wall	Wall	Solid	Wood	0
72	1976 bldg	171	XRF	2/27/97	1	Classroo	131	Wall	Midle Wall	Solid	Concrete	0.01
73	1976 bldg	172	XRF	2/27/97	1	Classroo	131	Wall	Midle Wall	Solid	Drywall	0
74	1976 bldg	173	XRF	2/27/97	1	Classroo	131	Door	Door	Solid	Wood	0
75	1976 bldg	174	XRF	2/27/97	1	Classroo	131	Door	Jamb	Solid	Metal	0.02
76	1976 bldg	175	XRF	2/27/97	1	Classroo	134	Wall	Midle Wall	Solid	Drywall	0.05
77	1976 bldg	176	XRF	2/27/97	1	Classroo	134	Wall	Wall	Solid	Concrete	0.06
78	1976 bldg	177	XRF	2/27/97	1	Classroo	135	Window	Casing	Solid	Metal	0.01
79	1976 bldg	178	XRF	2/27/97	1	Classroo	135	Door	Door	Solid	Wood	0
80	1976 bldg	179	XRF	2/27/97	1	Classroo	135	Door	Jamb	Solid	Metal	0.02
81	1976 bldg	162	XRF	2/27/97	1	Classroo	139	Wall	Midle Wall	Solid	Concrete	0
82	1976 bldg	163	XRF	2/27/97	1	Classroo	139	Wall	Midle Wall	Solid	Drywall	0.07
83	1976 bldg	164	XRF	2/27/97	1	Classroo	139	Door	Door	Solid	Wood	0
84	1976 bldg	165	XRF	2/27/97	1	Classroo	139	Door	Jamb	Solid	Metal	0.03
85	1976 bldg	158	XRF	2/27/97	1	Classroo	142	Wall	Midle Wall	Solid	Drywall	0
86	1976 bldg	159	XRF	2/27/97	1	Classroo	142	Wall	Midle Wall	Solid	Concrete	0
87	1976 bldg	160	XRF	2/27/97	1	Classroo	142	Door	Door	Solid	Wood	0
88	1976 bldg	161	XRF	2/27/97	1	Classroo	142	Door	Jamb	Solid	Metal	0
89	1976 bldg	153	XRF	2/27/97	1	Classroo	143	Wall	Midle Wall	Solid	Drywall	0
90	1976 bldg	154	XRF	2/27/97	1	Classroo	143	Wall	Wall	Solid	Concrete	0.08
91	1976 bldg	155	XRF	2/27/97	1	Classroo	143	Window	Casing	Solid	Metal	0.01
92	1976 bldg	156	XRF	2/27/97	1	Classroo	143	Door	Door	Solid	Wood	0
93	1976 bldg	157	XRF	2/27/97	1	Classroo	143	Door	Jamb	Solid	Metal	0.01
94	1976 bldg	127	XRF	2/27/97	1	Classroo	144	Wall	Wall	Solid	Concrete	0.02
95	1976 bldg	128	XRF	2/27/97	1	Classroo	144	Wall	Midle Wall	Solid	Drywall	0
96	1976 bldg	129	XRF	2/27/97	1	Classroo	144	Window	Casing	Solid	Metal	0.05
97	1976 bldg	130	XRF	2/27/97	1	Classroo	144	Door	Door	Solid	Wood	0
98	1976 bldg	131	XRF	2/27/97	1	Classroo	144	Door	Jamb	Solid	Metal	0.03
99	1976 bldg	88	XRF	2/27/97	1	Classroo	155	Wall	Wall	Solid	Concrete	0.05
100	1976 bldg	89	XRF	2/27/97	1	Classroo	155	Wall	Baseboar	Solid	Concrete	0
101	1976 bldg	90	XRF	2/27/97	1	Classroo	155	Door	Door	Solid	Metal	0.01
102	1976 bldg	91	XRF	2/27/97	1	Classroo	155	Ceiling		Solid	Concrete	0
103	1976 bldg	92	XRF	2/27/97	1	Classroo	155	Door	Door	Solid	Wood	0
104	1976 bldg	93	XRF	2/27/97	1	Classroo	155	Door	Door	Solid		0.06
105	1976 bldg	68	XRF	2/27/97	1	Classroo	162	Wall	Wall	Solid	Concrete	0
106	1976 bldg	69	XRF	2/27/97	1	Classroo	162	Wall	Wall	Solid	Concrete	0.01
107	1976 bldg	70	XRF	2/27/97	1	Classroo	162	Wall	Baseboar	Solid	Concrete	0
108	1976 bldg	102	XRF	2/27/97	1	Classroo	162		Locker	Solid	Metal	0.03
109	1976 bldg	71	XRF	2/27/97	1	Classroo	162	Ceiling		Solid	Concrete	0
110	1976 bldg	80	XRF	2/27/97	1	Classroo	173	Wall	Wall	Solid	Drywall	0.03
111	1976 bldg	81	XRF	2/27/97	1	Classroo	173	Wall	Midle Wall	Solid	Concrete	0.02
112	1976 bldg	82	XRF	2/27/97	1	Classroo	173	Window	Sash	Solid	Metal	0
113	1976 bldg	83	XRF	2/27/97	1	Classroo	173	Door	Door	Solid	Wood	0
114	1976 bldg	84	XRF	2/27/97	1	Classroo	173	Door	Door	Solid	Wood	0
115	1976 bldg	85	XRF	2/27/97	1	Classroo	174	Wall	Wall	Solid	Drywall	0
116	1976 bldg	86	XRF	2/27/97	1	Classroo	174	Door	Door	Solid	Wood	0
117	1976 bldg	87	XRF	2/27/97	1	Classroo	174	Door	Jamb	Solid	Metal	0.03
118	1976 bldg	55	XRF	2/27/97	1	Classroo	182	Wall	Midle Wall	Solid	Drywall	0.02
119	1976 bldg	56	XRF	2/27/97	1	Classroo	182	Wall	Wall	Solid	Concrete	0

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
120	1976 bldg	57	XRF	2/27/97	1	Classroo	182	Wall	Baseboar	Solid	Drywall	0.01
121	1976 bldg	58	XRF	2/27/97	1	Classroo	182	Door	Door	Solid	Wood	0
122	1976 bldg	59	XRF	2/27/97	1	Classroo	182	Door	Jamb	Solid	Metal	0.04
123	1976 bldg	20	XRF	2/27/97	1	Classroo	197	Wall	Midle Wall	Solid	Concrete	0
124	1976 bldg	21	XRF	2/27/97	1	Classroo	197	Wall	Baseboar	Solid	Concrete	0.02
125	1976 bldg	22	XRF	2/27/97	1	Classroo	197	Wall	Wall	Solid	Drywall	0.02
126	1976 bldg	23	XRF	2/27/97	1	Classroo	197	Ceiling		Solid	Drywall	0.03
127	1976 bldg	24	XRF	2/27/97	1	Classroo	197	Window	Casing	Solid	Metal	0.03
128	1976 bldg	25	XRF	2/27/97	1	Classroo	197	Stairs	Hand rail	Peeling	Metal	0.01
129	1976 bldg	26	XRF	2/27/97	1	Classroo	197	Door	Door	Solid	Wood	0
130	1976 bldg	27	XRF	2/27/97	1	Classroo	197	Door	Jamb	Solid	Metal	0.03
131	1976 bldg	28	XRF	2/27/97	1	Classroo	197	Closet	Wall	Solid	Concrete	0.08
132	1976 bldg	29	XRF	2/27/97	1	Classroo	197	Ceiling		Solid	Stucco	0
133	1976 bldg	63	XRF	3/1/97	1	Classroo	211	Wall	Wall	Solid	Drywall	0
134	1976 bldg	64	XRF	3/1/97	1	Classroo	211	Window	Casing	Solid	Metal	0.01
135	1976 bldg	65	XRF	3/1/97	1	Classroo	211	Door	Jamb	Solid	Metal	0.03
136	1976 bldg	66	XRF	3/1/97	1	Classroo	211	Door	Door	Solid	Wood	0
137	1976 bldg	67	XRF	3/1/97	1	Classroo	212	Wall	Midle Wall	Solid	Drywall	0.04
138	1976 bldg	68	XRF	3/1/97	1	Classroo	212	Wall	Wall	Solid	Concrete	0.01
139	1976 bldg	69	XRF	3/1/97	1	Classroo	212	Window	Sash	Solid	Metal	0.19
140	1976 bldg	70	XRF	3/1/97	1	Classroo	212	Door	Jamb	Solid	Metal	0.1
141	1976 bldg	71	XRF	3/1/97	1	Classroo	212	Door	Door	Solid	Wood	0
142	1976 bldg	72	XRF	3/1/97	1	Classroo	212	Wall	Midle Wall	Solid	Drywall	0
143	1976 bldg	76	XRF	3/1/97	1	Classroo	217	Wall	Midle Wall	Solid	Drywall	0.05
144	1976 bldg	77	XRF	3/1/97	1	Classroo	217	Window	Sash	Solid	Metal	0
145	1976 bldg	78	XRF	3/1/97	1	Classroo	217	Door	Jamb	Solid	Metal	0.05
146	1976 bldg	79	XRF	3/1/97	1	Classroo	217	Wall	Wall	Solid	Drywall	0.01
147	1976 bldg	80	XRF	3/1/97	1	Classroo	217	Door	Jamb	Solid	Metal	0.06
148	1976 bldg	81	XRF	3/1/97	1	Classroo	217	Door	Door	Solid	Wood	0
149	1976 bldg	125	XRF	3/1/97	1	Classroo	221	Wall	Midle Wall	Solid	Drywall	0
150	1976 bldg	126	XRF	3/1/97	1	Classroo	221	Window	Casing	Solid	Metal	0.08
151	1976 bldg	127	XRF	3/1/97	1	Classroo	221	Window	Casing	Solid		0.11
152	1976 bldg	128	XRF	3/1/97	1	Classroo	221	Door	Casing	Solid	Metal	0.01
153	1976 bldg	129	XRF	3/1/97	1	Classroo	221	Door	Door	Solid	Wood	0
154	1976 bldg	130	XRF	3/1/97	1	Classroo	221	Closet	Wall	Solid	Wood	0.81
155	1976 bldg	131	XRF	3/1/97	1	Classroo	224	Wall	Wall	Solid	Drywall	0.07
156	1976 bldg	132	XRF	3/1/97	1	Classroo	224	Window	Casing	Solid	Metal	0.08
157	1976 bldg	133	XRF	3/1/97	1	Classroo	224	Wall	Wall	Solid	Concrete	0.03
158	1976 bldg	134	XRF	3/1/97	1	Classroo	224	Door	Door	Solid	Wood	0
159	1976 bldg	135	XRF	3/1/97	1	Classroo	224	Closet	Wall	Solid	Wood	0.75
160	1976 bldg	136	XRF	3/1/97	1	Classroo	224	Closet	Wall	Solid	Metal	0
161	1976 bldg	141	XRF	3/1/97	1	Classroo	226	Wall	Wall	Solid	Drywall	0.04
162	1976 bldg	142	XRF	3/1/97	1	Classroo	226	Wall	Midle Wall	Solid	Wood	0.91
163	1976 bldg	143	XRF	3/1/97	1	Classroo	226	Door	Jamb	Solid	Metal	0.04
164	1976 bldg	144	XRF	3/1/97	1	Classroo	226	Door	Door	Solid	Wood	0
165	1976 bldg	145	XRF	3/1/97	1	Classroo	231	Wall	Wall	Solid	Drywall	0
166	1976 bldg	146	XRF	3/1/97	1	Classroo	231	Wall	Wall	Solid	Drywall	0.03
167	1976 bldg	147	XRF	3/1/97	1	Classroo	231	Window	Sash	Solid	Metal	0.09
168	1976 bldg	148	XRF	3/1/97	1	Classroo	231	Chalkboard	Ledge	Solid	Wood	0
169	1976 bldg	149	XRF	3/1/97	1	Classroo	231	Door	Jamb	Solid	Metal	0.05
170	1976 bldg	150	XRF	3/1/97	1	Classroo	231	Door	Door	Solid	Wood	0
171	1976 bldg	151	XRF	3/1/97	1	Classroo	232	Wall	Wall	Solid	Drywall	0
172	1976 bldg	152	XRF	3/1/97	1	Classroo	232	Wall	Midle Wall	Solid	Concrete	0.07
173	1976 bldg	153	XRF	3/1/97	1	Classroo	232	Wall	Wall	Solid	Concrete	0
174	1976 bldg	154	XRF	3/1/97	1	Classroo	232	Window	Casing	Solid	Metal	0
175	1976 bldg	155	XRF	3/1/97	1	Classroo	232	Door	Jamb	Solid	Metal	0.02
176	1976 bldg	156	XRF	3/1/97	1	Classroo	232	Door	Door	Solid	Wood	0
177	1976 bldg	157	XRF	3/1/97	1	Classroo	233	Wall	Wall	Solid	Drywall	0
178	1976 bldg	158	XRF	3/1/97	1	Classroo	233	Door	Jamb	Solid	Metal	0.05

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
179	1976 bldg	159	XRF	3/1/97	1	Classroo	233	Door	Door	Solid	Wood	0
180	1976 bldg	160	XRF	3/1/97	1	Classroo	233	Wall	Midle Wall	Solid	Wood	1.06
181	1976 bldg	161	XRF	3/1/97	1	Classroo	233	Window	Sash	Solid	Metal	0
182	1976 bldg	162	XRF	3/1/97	1	Classroo	235	Wall	Wall	Solid	Drywall	0
183	1976 bldg	163	XRF	3/1/97	1	Classroo	235	Wall	Wall	Solid	Drywall	0
184	1976 bldg	164	XRF	3/1/97	1	Classroo	235	Door	Casing	Solid	Metal	0.01
185	1976 bldg	165	XRF	3/1/97	1	Classroo	235	Door	Door	Solid	Metal	0
186	1976 bldg	166	XRF	3/1/97	1	Classroo	235	Closet	Wall	Solid	Drywall	0
187	1976 bldg	167	XRF	3/1/97	1	Classroo	235	Window	Casing	Solid	Metal	0.01
188	1976 bldg	168	XRF	3/1/97	1	Classroo	236	Wall	Wall	Solid	Drywall	0.01
189	1976 bldg	169	XRF	3/1/97	1	Classroo	236	Wall	Wall	Solid	Wood	1.07
190	1976 bldg	170	XRF	3/1/97	1	Classroo	236	Window	Casing	Solid	Metal	0
191	1976 bldg	171	XRF	3/1/97	1	Classroo	236	Door	Casing	Solid	Metal	0.04
192	1976 bldg	172	XRF	3/1/97	2	Classroo	236	Door	Door	Solid	Wood	0
193	1976 bldg	173	XRF	3/1/97	2	Classroo	237	Wall	Midle Wall	Solid	Drywall	0.05
194	1976 bldg	174	XRF	3/1/97	2	Classroo	237	Wall	Wall	Solid	Wood	0.96
195	1976 bldg	175	XRF	3/1/97	2	Classroo	237	Window	Sash	Solid	Metal	0.13
196	1976 bldg	176	XRF	3/1/97	2	Classroo	237	Window	Column	Solid	Concrete	0
197	1976 bldg	177	XRF	3/1/97	2	Classroo	237	Door	Casing	Solid	Metal	0.06
198	1976 bldg	178	XRF	3/1/97	2	Classroo	237	Door	Door	Solid	Wood	0
199	1976 bldg	179	XRF	3/1/97	2	Classroo	238	Wall	Wall	Solid	Drywall	0
200	1976 bldg	180	XRF	3/1/97	2	Classroo	238	Wall	Column	Peeling	Concrete	0.02
201	1976 bldg	181	XRF	3/1/97	2	Classroo	238	Door	Door	Solid	Wood	0
202	1976 bldg	182	XRF	3/1/97	2	Classroo	238	Door	Casing	Solid	Metal	0.02
203	1976 bldg	183	XRF	3/1/97	2	Classroo	239	Wall	Midle Wall	Solid	Concrete	0
204	1976 bldg	184	XRF	3/1/97	2	Classroo	239	Wall	Wall	Solid	Drywall	0
205	1976 bldg	185	XRF	3/1/97	2	Classroo	239	Wall	Wall	Solid	Wood	0.73
206	1976 bldg	186	XRF	3/1/97	2	Classroo	239	Window	Sash	Solid	Metal	0.13
207	1976 bldg	187	XRF	3/1/97	2	Classroo	239	Door	Jamb	Solid	Metal	0.08
208	1976 bldg	188	XRF	3/1/97	2	Classroo	239	Door	Door	Solid	Wood	0
209	1976 bldg	103	XRF	3/1/97	1	Classroo	247	Wall	Midle Wall	Solid	Drywall	0.05
210	1976 bldg	104	XRF	3/1/97	1	Classroo	247	Wall	Wall	Solid	Concrete	0.04
211	1976 bldg	105	XRF	3/1/97	1	Classroo	247	Door	Door	Solid	Wood	0
212	1976 bldg	106	XRF	3/1/97	1	Classroo	247	Door	Jamb	Solid	Metal	0.01
213	1976 bldg	205	XRF	3/1/97	2	Classroo	262		Column	Solid	Concrete	0
214	1976 bldg	206	XRF	3/1/97	2	Classroo	262	Wall	Midle Wall	Solid	Drywall	0.04
215	1976 bldg	207	XRF	3/1/97	2	Classroo	262	Wall	Wall	Solid	Drywall	0
216	1976 bldg	208	XRF	3/1/97	2	Classroo	262	Window	Sash	Solid	Metal	0.11
217	1976 bldg	209	XRF	3/1/97	2	Classroo	262	Door	Casing	Solid	Metal	0.02
218	1976 bldg	210	XRF	3/1/97	2	Classroo	262	Door	Door	Solid	Wood	0
219	1976 bldg	211	XRF	3/1/97	2	Classroo	263	Wall	Midle Wall	Solid	Drywall	0
220	1976 bldg	212	XRF	3/1/97	2	Classroo	263	Wall	Wall	Solid	Wood	0.92
221	1976 bldg	213	XRF	3/1/97	2	Classroo	263	Window	Sash	Solid	Metal	0
222	1976 bldg	214	XRF	3/1/97	2	Classroo	263	Door	Jamb	Solid	Metal	0.01
223	1976 bldg	215	XRF	3/1/97	2	Classroo	263	Door	Door	Solid	Wood	0
224	1976 bldg	216	XRF	3/1/97	2	Classroo	264	Wall	Wall	Solid	Drywall	0.06
225	1976 bldg	217	XRF	3/1/97	2	Classroo	264	Wall	Column	Solid	Concrete	0
226	1976 bldg	218	XRF	3/1/97	2	Classroo	264	Door	Casing	Solid	Metal	0.09
227	1976 bldg	219	XRF	3/1/97	2	Classroo	264	Door	Door	Solid	Wood	0
228	1976 bldg	231	XRF	3/1/97	2	Classroo	265	Door	Column	Solid	Concrete	0.02
229	1976 bldg	232	XRF	3/1/97	2	Classroo	265	Wall	Wall	Solid	Wood	1.03
230	1976 bldg	233	XRF	3/1/97	2	Classroo	265	Window	Sash	Solid	Metal	0.14
231	1976 bldg	234	XRF	3/1/97	2	Classroo	265	Door	Jamb	Solid	Metal	0.13
232	1976 bldg	235	XRF	3/1/97	2	Classroo	265	Wall	Wall	Solid	Drywall	0
233	1976 bldg	236	XRF	3/1/97	2	Classroo	266	Wall	Wall	Solid	Drywall	0
234	1976 bldg	237	XRF	3/1/97	2	Classroo	266	Wall	Wall	Solid	Wood	1.06
235	1976 bldg	238	XRF	3/1/97	2	Classroo	266	Window	Sash	Solid	Metal	0
236	1976 bldg	239	XRF	3/1/97	2	Classroo	266	Door	Casing	Solid	Metal	0.08
237	1976 bldg	240	XRF	3/1/97	2	Classroo	266	Door	Door	Solid	Metal	0

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
238	1976 bldg	245	XRF	3/1/97	2	Classroo	269	Wall	Midle Wall	Solid	Wood	0.91
239	1976 bldg	246	XRF	3/1/97	2	Classroo	269	Wall	Wall	Solid	Drywall	0
240	1976 bldg	247	XRF	3/1/97	2	Classroo	269	Window	Sash	Solid	Metal	0.18
241	1976 bldg	248	XRF	3/1/97	2	Classroo	269	Window	Column	Solid	Concrete	0.05
242	1976 bldg	249	XRF	3/1/97	2	Classroo	269	Door	Door	Solid	Wood	0
243	1976 bldg	250	XRF	3/1/97	2	Classroo	269	Door	Jamb	Solid	Metal	0.01
244	1976 bldg	251	XRF	3/1/97	2	Classroo	269	Door	Mural	Solid	Drywall	0.12
245	1976 bldg	252	XRF	3/1/97	2	Classroo	269	Door	Mural	Solid		0.02
246	1976 bldg	257	XRF	3/1/97	2	Classroo	271	Wall	Wall	Solid	Drywall	0.02
247	1976 bldg	258	XRF	3/1/97	2	Classroo	271	Wall	Wall	Solid	Concrete	0
248	1976 bldg	259	XRF	3/1/97	2	Classroo	271	Wall	Wall	Solid	Wood	0.65
249	1976 bldg	260	XRF	3/1/97	2	Classroo	271	Window	Sash	Solid	Metal	0.12
250	1976 bldg	261	XRF	3/1/97	2	Classroo	271	Wall	Wall	Solid	Concrete	0.04
251	1976 bldg	262	XRF	3/1/97	2	Classroo	271	Door	Door	Solid	Wood	0
252	1976 bldg	263	XRF	3/1/97	2	Classroo	271	Door	Jamb	Solid	Metal	0.03
253	1976 bldg	353	XRF	3/1/97	3	Classroo	301	Door	Mural	Solid	Drywall	0
254	1976 bldg	354	XRF	3/1/97	3	Classroo	301	Door	Column	Solid	Concrete	0.01
255	1976 bldg	355	XRF	3/1/97	3	Classroo	301	Door	Mural	Solid	Drywall	0
256	1976 bldg	356	XRF	3/1/97	3	Classroo	301	Wall	Wall	Solid	Drywall	0
257	1976 bldg	357	XRF	3/1/97	3	Classroo	301	Window	Sash	Solid	Metal	0.1
258	1976 bldg	358	XRF	3/1/97	3	Classroo	301	Door	Door	Solid	Wood	0
259	1976 bldg	359	XRF	3/1/97	3	Classroo	301	Cabinet	Door	Solid	Wood	0
260	1976 bldg	360	XRF	3/1/97	3	Classroo	301	Bookcase	Shelf	Solid	Wood	0.1
261	1976 bldg	361	XRF	3/1/97	3	Classroo	301	Cabinet	Shelf	Solid	Wood	0
262	1976 bldg	366	XRF	3/1/97	3	Classroo	305	Wall	Mural	Solid	Drywall	0.08
263	1976 bldg	367	XRF	3/1/97	3	Classroo	305	Wall	Mural	Solid	Drywall	0
264	1976 bldg	368	XRF	3/1/97	3	Classroo	305	Window	Sash	Solid	Metal	0.11
265	1976 bldg	369	XRF	3/1/97	3	Classroo	305	Cabinet	Door	Solid	Wood	0
266	1976 bldg	370	XRF	3/1/97	3	Classroo	305	Bookcase	Shelf	Solid	Wood	0
267	1976 bldg	371	XRF	3/1/97	3	Classroo	305	Door	Door	Solid	Wood	0.02
268	1976 bldg	372	XRF	3/1/97	3	Classroo	305	Door	Casing	Solid	Metal	0.01
269	1976 bldg	373	XRF	3/1/97	3	Classroo	306	Wall	Wall	Solid	Drywall	0.05
270	1976 bldg	374	XRF	3/1/97	3	Classroo	306	Wall	Wall	Solid	Drywall	0
271	1976 bldg	375	XRF	3/1/97	3	Classroo	306	Wall	Column	Solid	Concrete	0
272	1976 bldg	376	XRF	3/1/97	3	Classroo	306	Window	Sash	Solid	Metal	0.11
273	1976 bldg	377	XRF	3/1/97	3	Classroo	306	Cabinet	Door	Solid	Wood	0
274	1976 bldg	378	XRF	3/1/97	3	Classroo	306	Door	Jamb	Solid	Metal	0.03
275	1976 bldg	379	XRF	3/1/97	3	Classroo	306	Window	Panel	Solid	Metal	0.26
276	1976 bldg	380	XRF	3/1/97	3	Classroo	306	Door	Door	Solid	Wood	0
277	1976 bldg	384	XRF	3/1/97	3	Classroo	312	Wall	Wall	Solid	Drywall	0
278	1976 bldg	385	XRF	3/1/97	3	Classroo	312	Wall	Wall	Solid	Concrete	0.01
279	1976 bldg	386	XRF	3/1/97	3	Classroo	312	Wall	Midle Wall	Solid	Drywall	0
280	1976 bldg	387	XRF	3/1/97	3	Classroo	312	Window	Sash	Solid	Metal	0.18
281	1976 bldg	388	XRF	3/1/97	3	Classroo	312	Door	Door	Solid	Wood	0
282	1976 bldg	389	XRF	3/1/97	3	Classroo	312	Door	Jamb	Solid	Metal	0.05
283	1976 bldg	390	XRF	3/1/97	3	Classroo	313	Wall	Wall	Solid	Drywall	0
284	1976 bldg	391	XRF	3/1/97	3	Classroo	313	Wall	Wall	Solid	Drywall	0.04
285	1976 bldg	392	XRF	3/1/97	3	Classroo	313	Window	Sash	Solid	Metal	0.14
286	1976 bldg	393	XRF	3/1/97	3	Classroo	313	Door	Jamb	Solid	Metal	0.02
287	1976 bldg	394	XRF	3/1/97	3	Classroo	313	Door	Door	Solid	Wood	0
288	1976 bldg	395	XRF	3/1/97	3	Classroo	313	Cabinet	Door	Solid	Wood	0
289	1976 bldg	403	XRF	3/1/97	3	Classroo	322	Wall	Wall	Solid	Drywall	0
290	1976 bldg	404	XRF	3/1/97	3	Classroo	322	Door	Casing	Solid	Metal	0.02
291	1976 bldg	405	XRF	3/1/97	3	Classroo	322	Door	Door	Solid	Wood	0
292	1976 bldg	349	XRF	3/1/97	3	Classroo	332	Wall	Wall	Solid	Drywall	0
293	1976 bldg	350	XRF	3/1/97	3	Classroo	332	Window	Sash	Solid	Metal	0.16
294	1976 bldg	351	XRF	3/1/97	3	Classroo	332	Door	Jamb	Solid	Metal	0.02
295	1976 bldg	352	XRF	3/1/97	3	Classroo	332	Door	Door	Solid	Wood	0
296	1976 bldg	345	XRF	3/1/97	3	Classroo	333	Wall	Wall	Solid	Drywall	0.01

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
297	1976 bldg	346	XRF	3/1/97	3	Classroo	333	Wall	Midle Wall	Solid	Drywall	0
298	1976 bldg	347	XRF	3/1/97	3	Classroo	333	Window	Casing	Solid	Metal	0.02
299	1976 bldg	348	XRF	3/1/97	3	Classroo	333	Door	Door	Solid	Wood	0
300	1976 bldg	340	XRF	3/1/97	3	Classroo	334	Wall	Wall	Solid	Drywall	0.01
301	1976 bldg	341	XRF	3/1/97	3	Classroo	334	Wall	Column	Solid	Concrte	0.03
302	1976 bldg	342	XRF	3/1/97	3	Classroo	334	Window	Sash	Solid	Metal	0.15
303	1976 bldg	343	XRF	3/1/97	3	Classroo	334	Door	Jamb	Solid	Metal	0.01
304	1976 bldg	344	XRF	3/1/97	3	Classroo	334	Door	Door	Solid	Wood	0
305	1976 bldg	335	XRF	3/1/97	3	Classroo	335	Wall	Midle Wall	Solid	Drywall	0.04
306	1976 bldg	336	XRF	3/1/97	3	Classroo	335	Wall	Column	Solid	Concrte	0
307	1976 bldg	337	XRF	3/1/97	3	Classroo	335	Window	Sash	Solid	Metal	0
308	1976 bldg	338	XRF	3/1/97	3	Classroo	335	Door	Door	Solid	Wood	0
309	1976 bldg	339	XRF	3/1/97	3	Classroo	335	Door	Jamb	Solid	Metal	0.07
310	1976 bldg	321	XRF	3/1/97	3	Classroo	338	Wall	Wall	Solid	Concrte	0
311	1976 bldg	322	XRF	3/1/97	3	Classroo	338	Wall	Wall	Solid	Drywall	0
312	1976 bldg	323	XRF	3/1/97	3	Classroo	338	Window	Sash	Solid	Metal	0.01
313	1976 bldg	324	XRF	3/1/97	3	Classroo	338	Door	Door	Solid	Wood	0
314	1976 bldg	325	XRF	3/1/97	3	Classroo	338	Door	Jamb	Solid	Metal	0.02
315	1976 bldg	326	XRF	3/1/97	3	Classroo	338	Wall	Wall	Solid	Wood	1.05
316	1976 bldg	302	XRF	3/1/97	3	Classroo	341	Wall	Wall	Solid	Concrte	0.07
317	1976 bldg	303	XRF	3/1/97	3	Classroo	341	Wall	Midle Wall	Solid	Drywall	0.09
318	1976 bldg	304	XRF	3/1/97	3	Classroo	341	Wall	Column	Solid	Concrte	0
319	1976 bldg	305	XRF	3/1/97	3	Classroo	341	Door	Casing	Solid	Metal	0.02
320	1976 bldg	306	XRF	3/1/97	3	Classroo	341	Door	Door	Solid	Wood	0
321	1976 bldg	297	XRF	3/1/97	3	Classroo	342	Wall	Wall	Solid	Drywall	0.03
322	1976 bldg	298	XRF	3/1/97	3	Classroo	342	Wall	Midle Wall	Solid	Drywall	0.02
323	1976 bldg	299	XRF	3/1/97	3	Classroo	342	Window	Sash	Solid	Metal	0.09
324	1976 bldg	300	XRF	3/1/97	3	Classroo	342	Door	Door	Solid	Wood	0
325	1976 bldg	301	XRF	3/1/97	3	Classroo	342	Door	Jamb	Solid	Metal	0.02
326	1976 bldg	287	XRF	3/1/97	3	Classroo	343	Wall	Wall	Solid	Drywall	0.01
327	1976 bldg	288	XRF	3/1/97	3	Classroo	343	Wall	Wall	Solid	Drywall	0.01
328	1976 bldg	289	XRF	3/1/97	3	Classroo	343	Window	Sash	Solid	Metal	0.16
329	1976 bldg	290	XRF	3/1/97	3	Classroo	343	Door	Jamb	Solid	Metal	0.03
330	1976 bldg	281	XRF	3/1/97	3	Classroo	344	Wall	Wall	Solid	Drywall	0.01
331	1976 bldg	282	XRF	3/1/97	3	Classroo	344	Wall	Wall	Solid	Drywall	0.01
332	1976 bldg	283	XRF	3/1/97	3	Classroo	344	Wall	Column	Solid	Concrte	0
333	1976 bldg	284	XRF	3/1/97	3	Classroo	344	Window	Casing	Solid	Metal	0.02
334	1976 bldg	285	XRF	3/1/97	3	Classroo	344	Door	Casing	Solid	Metal	0.03
335	1976 bldg	286	XRF	3/1/97	3	Classroo	344	Door	Door	Solid	Wood	0
336	1976 bldg	291	XRF	3/1/97	3	Classroo	344	Wall	Wall	Solid	Drywall	0
337	1976 bldg	292	XRF	3/1/97	3	Classroo	344	Wall	Column	Solid	Concrte	0
338	1976 bldg	293	XRF	3/1/97	3	Classroo	344	Wall	Wall	Solid	Drywall	0
339	1976 bldg	294	XRF	3/1/97	3	Classroo	344	Window	Sash	Solid	Metal	0.12
340	1976 bldg	295	XRF	3/1/97	3	Classroo	344	Door	Casing	Solid	Metal	0.02
341	1976 bldg	296	XRF	3/1/97	3	Classroo	344	Door	Door	Solid	Wood	0
342	1976 bldg	307	XRF	3/1/97	3	Classroo	347	Wall	Midle Wall	Solid	Drywall	0.03
343	1976 bldg	308	XRF	3/1/97	3	Classroo	347	Wall	Wall	Solid	Drywall	0.02
344	1976 bldg	309	XRF	3/1/97	3	Classroo	347	Window	Sash	Solid	Metal	0.17
345	1976 bldg	310	XRF	3/1/97	3	Classroo	347	Door	Jamb	Solid	Plaster	0.08
346	1976 bldg	311	XRF	3/1/97	3	Classroo	347	Door	Door	Solid	Wood	0
347	1976 bldg	312	XRF	3/1/97	3	Classroo	348	Wall	Wall	Solid	Drywall	0.02
348	1976 bldg	313	XRF	3/1/97	3	Classroo	348	Wall	Wall	Solid	Concrte	0.03
349	1976 bldg	314	XRF	3/1/97	3	Classroo	348	Door	Jamb	Solid	Metal	0.02
350	1976 bldg	315	XRF	3/1/97	3	Classroo	348	Door	Door	Solid	Wood	0
351	1976 bldg	40	XRF	3/2/97	1	Garage	0	Door	Door	Solid	Wood	0
352	1976 bldg	41	XRF	3/2/97	1	Garage	0	Door	Jamb	Peeling	Metal	0.04
353	1976 bldg	42	XRF	3/2/97	1	Garage	0	Door	Door	Solid	Metal	0.12
354	1976 bldg	43	XRF	3/2/97	1	Garage	0	Door	Door	Solid	Metal	0
355	1976 bldg	32	XRF	2/26/97	1	Gym	1	Floor		Solid	Wood	0

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
356	1976 bldg	33	XRF	2/26/97	1	Gym		1 Wall	Wall	Solid	Concrete	0.01
357	1976 bldg	34	XRF	2/26/97	1	Gym		1 Wall	Midle Wall	Solid	Concrete	0
358	1976 bldg	35	XRF	2/26/97	1	Gym		1 Wall	Wall	Solid	Concrete	0.02
359	1976 bldg	36	XRF	2/26/97	1	Gym		1 Door	Door	Solid	Wood	0
360	1976 bldg	37	XRF	2/26/97	1	Gym		1 Door	Casing	Solid	Metal	0.01
361	1976 bldg	38	XRF	2/26/97	1	Gym		1 Bleachers	Casing	Solid	Wood	0
362	1976 bldg	16	XRF	2/26/97	1	Hall		1 Wall	Wall	Solid	Concrete	0
363	1976 bldg	17	XRF	2/26/97	1	Hall		1 Wall	Baseboar	Solid	Concrete	0
364	1976 bldg	18	XRF	2/26/97	1	Hall		1 Door	Door	Peeling	Metal	0
365	1976 bldg	19	XRF	2/26/97	1	Hall		1 Door	Jamb	Solid	Metal	0.04
366	1976 bldg	20	XRF	2/26/97	1	Hall		1 Window	Panel	Solid	Metal	0.05
367	1976 bldg	65	XRF	2/26/97	1	Hall		2 Wall	Wall	Solid	Concrete	0.08
368	1976 bldg	66	XRF	2/26/97	1	Hall		2 Wall	Baseboar	Solid	Concrete	0
369	1976 bldg	67	XRF	2/26/97	1	Hall		2 Wall	Locker	Solid	Metal	0.36
370	1976 bldg	68	XRF	2/26/97	1	Hall		2 Wall	Locker	Solid		0.59
371	1976 bldg	69	XRF	2/26/97	1	Hall		2 Wall	Locker	Solid		0.61
372	1976 bldg	70	XRF	2/26/97	1	Hall		2 Wall	Midle Wall	Solid	Concrete	0.01
373	1976 bldg	71	XRF	2/26/97	1	Hall		2 Wall	Locker	Solid	Metal	0.06
374	1976 bldg	72	XRF	2/26/97	1	Hall		2 Window	Casing	Solid	Metal	0.04
375	1976 bldg	73	XRF	2/26/97	1	Hall		2 Window	Panel	Solid	Metal	0.01
376	1976 bldg	74	XRF	2/26/97	1	Hall		2 Door	Door	Peeling	Metal	0
377	1976 bldg	75	XRF	2/26/97	1	Hall		2 Door	Jamb	Peeling	Metal	0
378	1976 bldg	76	XRF	2/26/97	1	Hall		2 Door	Column	Solid	Concrete	0.02
379	1976 bldg	77	XRF	2/26/97	1	Hall		2 Door	Door	Solid	Metal	0.01
380	1976 bldg	78	XRF	2/26/97	1	Hall		2 Door	Jamb	Solid	Metal	0.02
381	1976 bldg	79	XRF	2/26/97	1	Hall		2 Wall	Wall	Solid	Concrete	0.01
382	1976 bldg	80	XRF	2/26/97	1	Hall		2 Ceiling		Solid	Concrete	0
383	1976 bldg	81	XRF	2/26/97	1	Hall		2	Column	Solid	Concrete	0.03
384	1976 bldg	6	XRF	2/27/97	1	Hall		3 Wall	Wall	Solid	Concrete	0.01
385	1976 bldg	7	XRF	2/27/97	1	Hall		3 Wall	Baseboar	Solid	Concrete	0
386	1976 bldg	8	XRF	2/27/97	1	Hall		3 Wall	Column	Peeling	Concrete	0.01
387	1976 bldg	9	XRF	2/27/97	1	Hall		3 Ceiling		Solid	Metal	0.01
388	1976 bldg	10	XRF	2/27/97	1	Hall		3 Wall	Wall	Solid	Concrete	0.05
389	1976 bldg	11	XRF	2/27/97	1	Hall		3 Window	Casing	Solid	Metal	0.11
390	1976 bldg	12	XRF	2/27/97	1	Hall		3 Window	Panel	Solid	Wood	0.01
391	1976 bldg	13	XRF	2/27/97	1	Hall		3 Door	Door	Solid	Metal	0.01
392	1976 bldg	14	XRF	2/27/97	1	Hall		3 Window	Casing	Solid	Metal	0
393	1976 bldg	15	XRF	2/27/97	1	Hall		3	Locker	Solid	Metal	0.84
394	1976 bldg	16	XRF	2/27/97	1	Hall		3	Locker	Solid		0.6
395	1976 bldg	17	XRF	2/27/97	1	Hall		3	Locker	Solid		0.44
396	1976 bldg	18	XRF	2/27/97	1	Hall		3	Locker	Solid		0.02
397	1976 bldg	19	XRF	2/27/97	1	Hall		3 Door	Door	Solid	Wood	0.06
398	1976 bldg	103	XRF	2/27/97	1	Hall		4 Wall	Midle Wall	Solid	Drywall	0
399	1976 bldg	104	XRF	2/27/97	1	Hall		4 Door	Door	Solid	Wood	0
400	1976 bldg	105	XRF	2/27/97	1	Hall		4 Door	Jamb	Solid	Metal	0.01
401	1976 bldg	106	XRF	2/27/97	1	Hall		4 Door	Door	Solid	Metal	0.01
402	1976 bldg	107	XRF	2/27/97	1	Hall		4 Door	Jamb	Solid	Metal	0
403	1976 bldg	108	XRF	2/27/97	1	Hall		4 Window	Panel	Solid	Wood	0.1
404	1976 bldg	109	XRF	2/27/97	1	Hall		4 Wall	Wall	Solid	Concrete	0
405	1976 bldg	110	XRF	2/27/97	1	Hall		4 Closet	Wall	Solid	Drywall	0.02
406	1976 bldg	111	XRF	2/27/97	1	Hall		4 Closet	Casing	Solid	Metal	0
407	1976 bldg	112	XRF	2/27/97	1	Hall		4 Grate		Solid	Metal	0.05
408	1976 bldg	113	XRF	2/27/97	1	Hall		4 Unlisted	Casing	Solid		0.01
409	1976 bldg	114	XRF	2/27/97	1	Hall		4 Door	Door	Solid	Metal	0.36
410	1976 bldg	115	XRF	2/27/97	1	Hall		4 Door	Jamb	Solid	Metal	0.13
411	1976 bldg	116	XRF	2/27/97	1	Hall		4 Wall	Wall	Solid	Concrete	0.01
412	1976 bldg	117	XRF	2/27/97	1	Hall		4 Wall	Wall	Solid	Concrete	0
413	1976 bldg	118	XRF	2/27/97	1	Hall		4 Wall	Wall	Solid	Concrete	0
414	1976 bldg	138	XRF	2/27/97	1	Hall		4 Door	Door	Solid	Metal	0.11

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
415	1976 bldg	139	XRF	2/27/97	1	Hall	4	Unlisted	Column	Solid	Concrete	0.01
416	1976 bldg	6	XRF	3/1/97	1	Hall	5	Wall	Wall	Solid	Drywall	0.01
417	1976 bldg	7	XRF	3/1/97	1	Hall	5	Wall	Midle Wall	Solid	Drywall	2.05
418	1976 bldg	8	XRF	3/1/97	1	Hall	5	Door	Casing	Solid	Metal	0.06
419	1976 bldg	9	XRF	3/1/97	1	Hall	5	Door	Door	Solid	Wood	0
420	1976 bldg	37	XRF	3/1/97	1	Hall	5	Door	Door	Solid	Metal	0.1
421	1976 bldg	38	XRF	3/1/97	1	Hall	5	Door	Jamb	Solid	Metal	0.02
422	1976 bldg	39	XRF	3/1/97	1	Hall	5	Wall	Baseboar	Solid	Concrete	0
423	1976 bldg	264	XRF	3/1/97	2	Hall	6	Wall	Wall	Solid	Drywall	0.3
424	1976 bldg	265	XRF	3/1/97	2	Hall	6	Wall	Midle Wall	Solid	Drywall	0.55
425	1976 bldg	266	XRF	3/1/97	2	Hall	6	Wall	Midle Wall	Solid	Drywall	1.44
426	1976 bldg	267	XRF	3/1/97	2	Hall	6	Door	Door	Solid	Metal	0.41
427	1976 bldg	268	XRF	3/1/97	2	Hall	6	Door	Jamb	Solid	Metal	0.1
428	1976 bldg	269	XRF	3/1/97	2	Hall	6	Closet	Floor	Peeling	Concrete	0
429	1976 bldg	270	XRF	3/1/97	2	Hall	6	Closet	Floor	Peeling	Concrete	0
430	1976 bldg	271	XRF	3/1/97	2	Hall	6	Closet	Column	Solid	Concrete	0.03
431	1976 bldg	272	XRF	3/1/97	2	Hall	6	Wall	Wall	Solid	Concrete	0.01
432	1976 bldg	273	XRF	3/1/97	2	Hall	6	Door	Door	Solid	Wood	0
433	1976 bldg	274	XRF	3/1/97	2	Hall	6	Door	Jamb	Solid	Metal	0.01
434	1976 bldg	13	XRF	3/2/97	3	Hall	7	Wall	Wall	Solid	Concrete	0.02
435	1976 bldg	14	XRF	3/2/97	3	Hall	7	Wall	Midle Wall	Solid	Drywall	0.41
436	1976 bldg	15	XRF	3/2/97	3	Hall	7	Wall	Midle Wall	Solid	Drywall	0.9
437	1976 bldg	16	XRF	3/2/97	3	Hall	7	Door	Door	Solid	Metal	0.42
438	1976 bldg	17	XRF	3/2/97	3	Hall	7	Door	Jamb	Solid	Metal	0.07
439	1976 bldg	26	XRF	3/2/97	3	Hall	7	Window	Casing	Solid	Metal	0.01
440	1976 bldg	27	XRF	3/2/97	3	Hall	7	Door	Door	Solid	Wood	0
441	1976 bldg	28	XRF	3/2/97	3	Hall	7	Door	Jamb	Solid	Metal	0.07
442	1976 bldg	39	XRF	2/26/97	1	Kitchen	1	Wall	Midle Wall	Solid	Concrete	0.01
443	1976 bldg	40	XRF	2/26/97	1	Kitchen	1	Wall	Baseboar	Solid	Concrete	0
444	1976 bldg	41	XRF	2/26/97	1	Kitchen	1	Wall	Wall	Solid	Concrete	0
445	1976 bldg	42	XRF	2/26/97	1	Kitchen	1	Window	Casing	Solid	Metal	0.02
446	1976 bldg	43	XRF	2/26/97	1	Kitchen	1	Door	Door	Solid	Metal	0.04
447	1976 bldg	44	XRF	2/26/97	1	Kitchen	1	Door	Casing	Solid	Metal	0.03
448	1976 bldg	45	XRF	2/26/97	1	Kitchen	1	Door	Door	Solid	Wood	0
449	1976 bldg	46	XRF	2/26/97	1	Kitchen	1	Wall	Midle Wall	Solid	Concrete	1.66
450	1976 bldg	47	XRF	2/26/97	1	Kitchen	1	Wall	Locker	Solid	Metal	0.76
451	1976 bldg	48	XRF	2/26/97	1	Kitchen	1	Wall	Locker	Solid		0.01
452	1976 bldg	90	XRF	3/1/97	1	Library	246	Wall	Wall	Solid	Drywall	0.01
453	1976 bldg	91	XRF	3/1/97	1	Library	246	Wall	Wall	Solid	Drywall	0.06
454	1976 bldg	92	XRF	3/1/97	1	Library	246	Ceiling		Solid	Concrete	0
455	1976 bldg	93	XRF	3/1/97	1	Library	246	Ceiling		Solid	Concrete	0.01
456	1976 bldg	94	XRF	3/1/97	1	Library	246	Window	Sash	Solid	Metal	0.22
457	1976 bldg	95	XRF	3/1/97	1	Library	246	Ceiling		Solid	Metal	0
458	1976 bldg	96	XRF	3/1/97	1	Library	246	Window	Panel	Solid	Wood	0.45
459	1976 bldg	97	XRF	3/1/97	1	Library	246	Door	Jamb	Solid	Metal	0.02
460	1976 bldg	134	XRF	2/26/97	1	Lounge	61	Wall	Midle Wall	Solid	Concrete	0
461	1976 bldg	135	XRF	2/26/97	1	Lounge	61	Wall	Mural	Solid	Concrete	0.05
462	1976 bldg	136	XRF	2/26/97	1	Lounge	61	Door	Door	Solid	Wood	0.11
463	1976 bldg	137	XRF	2/26/97	1	Lounge	61	Door	Door	Solid	Wood	0
464	1976 bldg	196	XRF	2/27/97	1	Lounge	99	Wall	Midle Wall	Solid	Concrete	0.04
465	1976 bldg	197	XRF	2/27/97	1	Lounge	99	Wall	Chair rail	Solid	Drywall	0.03
466	1976 bldg	198	XRF	2/27/97	1	Lounge	99	Door	Door	Solid	Wood	0
467	1976 bldg	199	XRF	2/27/97	1	Lounge	99	Door	Jamb	Solid	Metal	0.02
468	1976 bldg	32	XRF	3/1/97	1	Lounge	123	Wall	Midle Wall	Solid	Drywall	0.02
469	1976 bldg	33	XRF	3/1/97	1	Lounge	123	Wall	Midle Wall	Solid	Concrete	0.08
470	1976 bldg	34	XRF	3/1/97	1	Lounge	123	Wall	Wall	Solid	Wood	0.96
471	1976 bldg	35	XRF	3/1/97	1	Lounge	123	Door	Jamb	Solid	Metal	0
472	1976 bldg	36	XRF	3/1/97	1	Lounge	123	Door	Door	Solid	Wood	0
473	1976 bldg	396	XRF	3/1/97	3	Lounge	314	Wall	Column	Solid	Concrete	0

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

A	B	C	D	E	F	G	H	I	J	K	L	
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
474	1976 bldg	397	XRF	3/1/97	3	Lounge	314	Wall	Wall	Solid	Drywall	0
475	1976 bldg	398	XRF	3/1/97	3	Lounge	314	Window	Sash	Solid	Metal	0.18
476	1976 bldg	362	XRF	3/1/97	3	Other	0	Wall	Wall	Solid	Drywall	0.01
477	1976 bldg	363	XRF	3/1/97	3	Other	0	Wall	Midle Wall	Solid	Concrete	0
478	1976 bldg	364	XRF	3/1/97	3	Other	0	Closet	Wall	Solid	Concrete	0
479	1976 bldg	365	XRF	3/1/97	3	Other	0	Cabinet	Shelf	Solid	Wood	0
480	1976 bldg	21	XRF	2/26/97	1	Other	21	Wall	Wall	Solid	Concrete	0
481	1976 bldg	22	XRF	2/26/97	1	Other	21	Wall	Baseboar	Solid	Concrete	0.03
482	1976 bldg	23	XRF	2/26/97	1	Other	21	Window	Sash	Solid	Metal	0
483	1976 bldg	24	XRF	2/26/97	1	Other	21	Door	Casing	Solid	Metal	0.01
484	1976 bldg	25	XRF	2/26/97	1	Other	21	Door	Door	Solid	Wood	0
485	1976 bldg	14	XRF	2/26/97	1	Other	27	Door	Door		Metal	0.07
486	1976 bldg	15	XRF	2/26/97	1	Other	27	Door	Casing	Solid	Metal	0.02
487	1976 bldg	125	XRF	2/26/97	1	Other	59	Wall	Wall	Solid	Concrete	0
488	1976 bldg	126	XRF	2/26/97	1	Other	59	Door	Casing	Solid	Metal	0.02
489	1976 bldg	127	XRF	2/26/97	1	Other	59	Door	Door	Solid	Wood	0
490	1976 bldg	128	XRF	2/26/97	1	Other	59	Unlisted	Locker	Solid	Metal	0.04
491	1976 bldg	124	XRF	2/26/97	1	Other	69	Wall	Wall	Solid	Concrete	0
492	1976 bldg	56	XRF	2/26/97	1	Other	72	Wall	Midle Wall	Solid	Concrete	0.03
493	1976 bldg	57	XRF	2/26/97	1	Other	72	Door	Casing	Solid	Metal	0.01
494	1976 bldg	58	XRF	2/26/97	1	Other	72	Door	Door	Solid	Wood	0
495	1976 bldg	59	XRF	2/26/97	1	Other	72	Ceiling		Solid	Concrete	0.04
496	1976 bldg	60	XRF	2/26/97	1	Other	75	Wall	Wall	Solid	Concrete	0
497	1976 bldg	61	XRF	2/26/97	1	Other	75	Wall	Midle Wall	Solid	Concrete	0.01
498	1976 bldg	62	XRF	2/26/97	1	Other	75	Door	Door	Solid	Wood	0
499	1976 bldg	63	XRF	2/26/97	1	Other	75	Door	Jamb	Solid	Metal	0.09
500	1976 bldg	64	XRF	2/26/97	1	Other	75	Pipe		Peeling	Metal	0
501	1976 bldg	49	XRF	2/26/97	1	Other	77	Wall	Baseboar	Peeling	Concrete	0
502	1976 bldg	50	XRF	2/26/97	1	Other	77	Wall	Wall	Solid	Concrete	0
503	1976 bldg	51	XRF	2/26/97	1	Other	77	Wall	Midle Wall	Solid	Concrete	0
504	1976 bldg	52	XRF	2/26/97	1	Other	77	Wall	Wall	Solid	Concrete	0.03
505	1976 bldg	53	XRF	2/26/97	1	Other	77	Door	Casing	Solid	Metal	0.04
506	1976 bldg	54	XRF	2/26/97	1	Other	77	Unlisted	Casing	Solid	Metal	0.17
507	1976 bldg	55	XRF	2/26/97	1	Other	77	Door	Door	Solid	Wood	0
508	1976 bldg	160	XRF	2/26/97	1	Other	82	Wall	Wall	Solid	Concrete	0
509	1976 bldg	161	XRF	2/26/97	1	Other	82	Wall	Wall	Solid	Concrete	0
510	1976 bldg	162	XRF	2/26/97	1	Other	82	Ceiling		Solid	Concrete	0
511	1976 bldg	163	XRF	2/26/97	1	Other	82	Wall	Baseboar	Solid	Concrete	0
512	1976 bldg	164	XRF	2/26/97	1	Other	82	Door	Door	Solid	Wood	0.02
513	1976 bldg	165	XRF	2/26/97	1	Other	82	Door	Casing	Solid	Metal	0.02
514	1976 bldg	171	XRF	2/26/97	1	Other	87	Wall	Midle Wall	Solid	Concrete	0.04
515	1976 bldg	172	XRF	2/26/97	1	Other	87	Wall	Midle Wall	Solid	Drywall	0
516	1976 bldg	173	XRF	2/26/97	1	Other	87	Door	Casing	Solid	Metal	0
517	1976 bldg	174	XRF	2/26/97	1	Other	87	Door	Door	Solid	Wood	0
518	1976 bldg	175	XRF	2/26/97	1	Other	87	Wall	Midle Wall	Solid	Concrete	0.02
519	1976 bldg	140	XRF	2/27/97	1	Other	91	Wall	Midle Wall	Solid	Concrete	0
520	1976 bldg	141	XRF	2/27/97	1	Other	91	Wall	Baseboar	Solid	Concrete	0
521	1976 bldg	142	XRF	2/27/97	1	Other	91	Window	Sash	Solid	Metal	0.15
522	1976 bldg	143	XRF	2/27/97	1	Other	91	Window	Sash	Solid	Metal	0.02
523	1976 bldg	144	XRF	2/27/97	1	Other	91	Door	Jamb	Solid	Wood	0
524	1976 bldg	145	XRF	2/27/97	1	Other	91	Door	Jamb	Solid	Metal	0.02
525	1976 bldg	180	XRF	2/27/97	1	Other	94	Wall	Midle Wall	Solid	Concrete	0
526	1976 bldg	181	XRF	2/27/97	1	Other	94	Wall	Wall	Solid	Drywall	0.02
527	1976 bldg	182	XRF	2/27/97	1	Other	94	Window	Sash	Solid	Metal	0.01
528	1976 bldg	183	XRF	2/27/97	1	Other	94	Door	Door	Solid	Wood	0
529	1976 bldg	184	XRF	2/27/97	1	Other	94	Door	Jamb	Solid	Metal	0.03
530	1976 bldg	187	XRF	2/27/97	1	Other	101	Wall	Wall	Solid	Drywall	0.01
531	1976 bldg	188	XRF	2/27/97	1	Other	101	Wall	Wall	Solid	Concrete	0.02
532	1976 bldg	189	XRF	2/27/97	1	Other	101	Window	Casing	Peeling	Wood	0

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
533	1976 bldg	190	XRF	2/27/97	1	Other	101	Window	Casing	Solid	Metal	0.02
534	1976 bldg	191	XRF	2/27/97	1	Other	101	Window	Sash	Solid	Metal	0.13
535	1976 bldg	192	XRF	2/27/97	1	Other	101	Door	Door	Solid	Metal	0.04
536	1976 bldg	193	XRF	2/27/97	1	Other	101	Door	Jamb	Solid	Metal	0.01
537	1976 bldg	194	XRF	2/27/97	1	Other	101	Door	Door	Solid	Wood	0.01
538	1976 bldg	195	XRF	2/27/97	1	Other	101	Door	Column	Solid	Concrte	0
539	1976 bldg	210	XRF	2/27/97	1	Other	114	Wall	Wall	Solid	Concrte	0.01
540	1976 bldg	212	XRF	2/27/97	1	Other	116	Wall	Wall	Solid	Concrete	0.04
541	1976 bldg	213	XRF	2/27/97	1	Other	116	Wall	Baseboar	Solid	Concrte	0
542	1976 bldg	214	XRF	2/27/97	1	Other	116	Window	Casing	Solid	Metal	0.01
543	1976 bldg	215	XRF	2/27/97	1	Other	116	Door	Door	Solid	Wood	0
544	1976 bldg	216	XRF	2/27/97	1	Other	116	Door	Jamb	Solid	Metal	0.01
545	1976 bldg	166	XRF	2/27/97	1	Other	131	Wall	Midle Wall	Solid	Drywall	0
546	1976 bldg	167	XRF	2/27/97	1	Other	131	Wall	Wall	Solid	Concrte	0
547	1976 bldg	168	XRF	2/27/97	1	Other	131	Door	Door	Solid	Wood	0
548	1976 bldg	169	XRF	2/27/97	1	Other	131	Door	Jamb	Solid	Metal	0.01
549	1976 bldg	170	XRF	2/27/97	1	Other	131	Cabinet	Outside	Solid	Wood	0
550	1976 bldg	94	XRF	2/27/97	1	Other	152	Wall	Baseboar	Solid	Concrte	0
551	1976 bldg	95	XRF	2/27/97	1	Other	152	Wall	Wall	Solid	Concrte	0
552	1976 bldg	96	XRF	2/27/97	1	Other	152	Wall	Wall	Solid	Concrete	0
553	1976 bldg	97	XRF	2/27/97	1	Other	152	Door	Door	Solid	Wood	0.08
554	1976 bldg	98	XRF	2/27/97	1	Other	152	Door	Door	Solid	Wood	0
555	1976 bldg	99	XRF	2/27/97	1	Other	152	Door	Door	Solid	Wood	0
556	1976 bldg	100	XRF	2/27/97	1	Other	154	Wall	Wall	Solid	Metal	0.01
557	1976 bldg	101	XRF	2/27/97	1	Other	154	Ceiling		Solid	Concrte	0.08
558	1976 bldg	72	XRF	2/27/97	1	Other	162	Door	Door	Solid	Metal	0.03
559	1976 bldg	73	XRF	2/27/97	1	Other	162	Casing	Solid	Metal	0.02	
560	1976 bldg	74	XRF	2/27/97	1	Other	162	Door	Door	Solid	Wood	0
561	1976 bldg	75	XRF	2/27/97	1	Other	171	Wall	Wall	Solid	Concrte	0
562	1976 bldg	76	XRF	2/27/97	1	Other	171	Wall	Wall	Solid	Drywall	0
563	1976 bldg	77	XRF	2/27/97	1	Other	171	Window	Sash	Solid	Metal	0.15
564	1976 bldg	78	XRF	2/27/97	1	Other	171	Door	Jamb	Solid	Metal	0.09
565	1976 bldg	79	XRF	2/27/97	1	Other	171	Door	Door	Solid	Wood	0
566	1976 bldg	64	XRF	2/27/97	1	Other	175	Wall	Wall	Solid	Concrte	0.01
567	1976 bldg	65	XRF	2/27/97	1	Other	175	Wall	Midle Wall	Solid	Drywall	0
568	1976 bldg	66	XRF	2/27/97	1	Other	175	Door	Door	Solid	Wood	0
569	1976 bldg	67	XRF	2/27/97	1	Other	175	Door	Jamb	Solid	Metal	0.01
570	1976 bldg	60	XRF	2/27/97	1	Other	181	Wall	Wall	Solid	Drywall	0
571	1976 bldg	61	XRF	2/27/97	1	Other	181	Wall	Midle Wall	Solid	Drywall	0.01
572	1976 bldg	62	XRF	2/27/97	1	Other	181	Door	Door	Solid	Wood	0
573	1976 bldg	63	XRF	2/27/97	1	Other	181	Door	Jamb	Solid	Metal	0
574	1976 bldg	47	XRF	2/27/97	1	Other	192	Wall	Wall	Solid	Concrte	0.01
575	1976 bldg	48	XRF	2/27/97	1	Other	192	Door	Jamb	Solid	Metal	0.05
576	1976 bldg	49	XRF	2/27/97	1	Other	192	Door	Door	Solid	Wood	0.03
577	1976 bldg	50	XRF	2/27/97	1	Other	192	Closet	Wall	Solid	Concrete	0
578	1976 bldg	51	XRF	2/27/97	1	Other	193	Wall	Midle Wall	Solid	Concrte	0.01
579	1976 bldg	52	XRF	2/27/97	1	Other	193	Ceiling		Solid	Plaster	0.08
580	1976 bldg	53	XRF	2/27/97	1	Other	193	Door	Door	Solid	Wood	0
581	1976 bldg	54	XRF	2/27/97	1	Other	193	Door	Jamb	Solid	Metal	0.01
582	1976 bldg	34	XRF	2/27/97	1	Other	194	Wall	Midle Wall	Solid	Concrete	0.01
583	1976 bldg	35	XRF	2/27/97	1	Other	194	Wall	Midle Wall	Solid	Metal	0
584	1976 bldg	36	XRF	2/27/97	1	Other	194	Wall	Wood Stri	Solid	Wood	0
585	1976 bldg	37	XRF	2/27/97	1	Other	194	Wall	Baseboar	Solid	Concrete	0
586	1976 bldg	38	XRF	2/27/97	1	Other	194	Ceiling		Solid	Concrte	0
587	1976 bldg	39	XRF	2/27/97	1	Other	194		Baseboar	Solid	Drywall	0.01
588	1976 bldg	40	XRF	2/27/97	1	Other	194		Baseboar	Solid		0.02
589	1976 bldg	41	XRF	2/27/97	1	Other	194		Baseboar	Solid		0.01
590	1976 bldg	42	XRF	2/27/97	1	Other	194	Closet	Wall	Solid	Concrte	0
591	1976 bldg	43	XRF	2/27/97	1	Other	194	Window	Sash	Solid	Metal	0.15

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
592	1976 bldg	44	XRF	2/27/97	1	Other	194	Wall	Midle Wall	Solid	Plaster	0
593	1976 bldg	45	XRF	2/27/97	1	Other	194	Ceiling		Solid	Stucco	0
594	1976 bldg	46	XRF	2/27/97	1	Other	194	Closet	Wall	Solid	Concrete	0
595	1976 bldg	32	XRF	2/27/97	1	Other	195	Door	Jamb	Solid	Metal	0.03
596	1976 bldg	33	XRF	2/27/97	1	Other	195	Wall	Baseboar	Solid	Concrete	0
597	1976 bldg	30	XRF	2/27/97	1	Other	196	Window	Casing	Solid	Metal	0.14
598	1976 bldg	31	XRF	2/27/97	1	Other	196	Wall	Midle Wall	Solid	Concrete	0.03
599	1976 bldg	54	XRF	3/1/97	1	Other	201	Wall	Wall	Solid	Concrete	0
600	1976 bldg	55	XRF	3/1/97	1	Other	201	Wall	Wall	Solid	Drywall	0.03
601	1976 bldg	56	XRF	3/1/97	1	Other	201	Window	Sash	Solid	Metal	0.16
602	1976 bldg	57	XRF	3/1/97	1	Other	201	Door	Casing	Solid	Metal	0.06
603	1976 bldg	58	XRF	3/1/97	1	Other	201	Closet	Wall	Solid	Drywall	0.01
604	1976 bldg	59	XRF	3/1/97	1	Other	201	Door	Door	Solid	Wood	0
605	1976 bldg	86	XRF	3/1/97	1	Other	213	Wall	Midle Wall	Solid	Drywall	0.05
606	1976 bldg	87	XRF	3/1/97	1	Other	213	Window	Casing	Solid	Metal	0.1
607	1976 bldg	88	XRF	3/1/97	1	Other	213	Door	Door	Solid	Wood	0
608	1976 bldg	89	XRF	3/1/97	1	Other	213	Door	Jamb	Solid	Metal	0.13
609	1976 bldg	73	XRF	3/1/97	1	Other	214	Wall	Midle Wall	Solid	Drywall	0
610	1976 bldg	74	XRF	3/1/97	1	Other	214	Door	Door	Solid	Wood	0
611	1976 bldg	75	XRF	3/1/97	1	Other	214	Door	Jamb	Solid	Metal	0.05
612	1976 bldg	82	XRF	3/1/97	1	Other	218	Wall	Wall	Solid	Drywall	0
613	1976 bldg	83	XRF	3/1/97	1	Other	219	Wall	Midle Wall	Solid	Drywall	0
614	1976 bldg	84	XRF	3/1/97	1	Other	219	Door	Jamb	Solid	Metal	0.02
615	1976 bldg	85	XRF	3/1/97	1	Other	219	Door	Door	Solid	Wood	0
616	1976 bldg	137	XRF	3/1/97	1	Other	225	Wall	Wall	Solid	Drywall	0.02
617	1976 bldg	138	XRF	3/1/97	1	Other	225	Wall	Baseboar	Solid	Concrete	0.01
618	1976 bldg	139	XRF	3/1/97	1	Other	225	Door	Door	Solid	Wood	0
619	1976 bldg	140	XRF	3/1/97	1	Other	225	Door	Casing	Solid	Metal	0.12
620	1976 bldg	113	XRF	3/1/97	1	Other	242	Wall	Midle Wall	Solid	Concrete	0
621	1976 bldg	114	XRF	3/1/97	1	Other	242	Window	Sash	Solid	Metal	0.22
622	1976 bldg	115	XRF	3/1/97	1	Other	242	Door	Jamb	Solid	Metal	0.02
623	1976 bldg	116	XRF	3/1/97	1	Other	242	Door	Door	Solid	Wood	0
624	1976 bldg	107	XRF	3/1/97	1	Other	243	Wall	Wall	Solid	Drywall	0.06
625	1976 bldg	108	XRF	3/1/97	1	Other	243	Wall	Wall	Solid		0
626	1976 bldg	109	XRF	3/1/97	1	Other	243	Wall	Wall	Solid	Drywall	0
627	1976 bldg	110	XRF	3/1/97	1	Other	243	Door	Door	Solid	Wood	0
628	1976 bldg	111	XRF	3/1/97	1	Other	243	Door	Jamb	Solid	Metal	0.05
629	1976 bldg	112	XRF	3/1/97	1	Other	243	Door	Column	Solid	Tile	0.03
630	1976 bldg	121	XRF	3/1/97	1	Other	245	Wall	Wall	Solid	Drywall	0
631	1976 bldg	122	XRF	3/1/97	1	Other	245	Wall	Midle Wall	Solid	Concrete	0.02
632	1976 bldg	123	XRF	3/1/97	1	Other	245	Door	Jamb	Solid	Metal	0.11
633	1976 bldg	124	XRF	3/1/97	1	Other	245	Door	Door	Solid	Wood	0
634	1976 bldg	60	XRF	3/1/97	1	Other	248	Floor	Flr Registr	Peeling	Concrete	0
635	1976 bldg	61	XRF	3/1/97	1	Other	248	Door	Door	Solid	Metal	0.02
636	1976 bldg	62	XRF	3/1/97	1	Other	248	Door	Door	Solid	Metal	0.09
637	1976 bldg	102	XRF	3/1/97	1	Other	249	Floor		Peeling	Concrete	0
638	1976 bldg	98	XRF	3/1/97	1	Other	251	Wall	Wall	Solid	Concrete	0.01
639	1976 bldg	99	XRF	3/1/97	1	Other	251	Wall	Wall	Solid	Drywall	0.05
640	1976 bldg	100	XRF	3/1/97	1	Other	251	Closet	Wall	Solid	Drywall	0.02
641	1976 bldg	101	XRF	3/1/97	1	Other	251	Window	Sash	Solid	Metal	0
642	1976 bldg	117	XRF	3/1/97	1	Other	255	Wall	Wall	Solid	Concrete	0
643	1976 bldg	118	XRF	3/1/97	1	Other	255	Wall	Wall	Solid	Drywall	0
644	1976 bldg	119	XRF	3/1/97	1	Other	255	Door	Door	Solid	Wood	0
645	1976 bldg	120	XRF	3/1/97	1	Other	255	Door	Jamb	Solid	Metal	0.05
646	1976 bldg	199	XRF	3/1/97	2	Other	261	Wall	Baseboar	Solid	Concrete	0
647	1976 bldg	200	XRF	3/1/97	2	Other	261	Wall	Wall	Solid	Drywall	0
648	1976 bldg	201	XRF	3/1/97	2	Other	261	Window	Sash	Solid	Metal	0.15
649	1976 bldg	202	XRF	3/1/97	2	Other	261	Door	Casing	Solid	Metal	0.02
650	1976 bldg	203	XRF	3/1/97	2	Other	261	Door	Door	Solid	Wood	0

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

A	B	C	D	E	F	G	H	I	J	K	L	
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
651	1976 bldg	204	XRF	3/1/97	2	Other	261	Window	Sash	Solid	Metal	0.03
652	1976 bldg	228	XRF	3/1/97	1	Other	264	Wall	Wall	Solid	Drywall	0
653	1976 bldg	229	XRF	3/1/97	1	Other	264	Door	Door	Solid	Wood	0
654	1976 bldg	230	XRF	3/1/97	1	Other	264	Door	Jamb	Solid	Metal	0
655	1976 bldg	241	XRF	3/1/97	2	Other	267	Wall	Wall	Solid	Drywall	0.01
656	1976 bldg	242	XRF	3/1/97	2	Other	267	Wall	Column	Solid	Concrete	0.06
657	1976 bldg	243	XRF	3/1/97	2	Other	267	Door	Casing	Solid	Metal	0.01
658	1976 bldg	244	XRF	3/1/97	2	Other	267	Door	Door	Solid	Wood	0
659	1976 bldg	253	XRF	3/1/97	2	Other	271	Wall	Wall	Solid	Drywall	0.02
660	1976 bldg	254	XRF	3/1/97	2	Other	271	Wall	Wall	Solid	Wood	0.98
661	1976 bldg	255	XRF	3/1/97	2	Other	271	Door	Jamb	Solid	Metal	0.01
662	1976 bldg	256	XRF	3/1/97	2	Other	271	Door	Door	Solid	Wood	0
663	1976 bldg	381	XRF	3/1/97	3	Other	309	Wall	Midle Wall	Solid	Drywall	0
664	1976 bldg	382	XRF	3/1/97	3	Other	309	Door	Casing	Solid	Metal	0.01
665	1976 bldg	383	XRF	3/1/97	3	Other	309	Door	Door	Solid	Wood	0
666	1976 bldg	399	XRF	3/1/97	3	Other	315	Door	Casing	Solid	Metal	0.02
667	1976 bldg	400	XRF	3/1/97	3	Other	315	Door	Door	Solid	Wood	0
668	1976 bldg	401	XRF	3/1/97	3	Other	315	Bookcase	Shelf	Solid	Wood	0
669	1976 bldg	402	XRF	3/1/97	3	Other	315	Bookcase	Shelf	Solid	Wood	0
670	1976 bldg	330	XRF	3/1/97	3	Other	336	Wall	Wall	Solid	Drywall	0.06
671	1976 bldg	331	XRF	3/1/97	3	Other	336	Wall	Column	Solid	Concrete	0.03
672	1976 bldg	332	XRF	3/1/97	3	Other	336	Window	Sash	Solid	Metal	0.01
673	1976 bldg	333	XRF	3/1/97	3	Other	336	Door	Jamb	Solid	Metal	0.01
674	1976 bldg	334	XRF	3/1/97	3	Other	336	Door	Door	Solid	Wood	0
675	1976 bldg	327	XRF	3/1/97	3	Other	337	Wall	Midle Wall	Solid	Drywall	0
676	1976 bldg	328	XRF	3/1/97	3	Other	337	Door	Door	Solid	Wood	0
677	1976 bldg	329	XRF	3/1/97	3	Other	337	Door	Jamb	Solid	Metal	0.02
678	1976 bldg	316	XRF	3/1/97	3	Other	349	Wall	Midle Wall	Solid	Drywall	0
679	1976 bldg	317	XRF	3/1/97	3	Other	349	Wall	Wall	Solid	Concrete	0.01
680	1976 bldg	318	XRF	3/1/97	3	Other	349	Closet	Wall	Solid	Drywall	0
681	1976 bldg	319	XRF	3/1/97	3	Other	349	Door	Door	Solid	Wood	0
682	1976 bldg	320	XRF	3/1/97	3	Other	349	Door	Jamb	Solid	Metal	0.01
683	1976 bldg	34	XRF	3/2/97	1	Outside	0	Floor	Baseboar	Solid		0
684	1976 bldg	35	XRF	3/2/97	1	Outside	0	Door	Door	Peeling	Metal	0.01
685	1976 bldg	36	XRF	3/2/97	1	Outside	0	Door	Jamb	Solid	Metal	0.08
686	1976 bldg	37	XRF	3/2/97	1	Outside	0	Ceiling		Solid	Metal	0
687	1976 bldg	38	XRF	3/2/97	1	Outside	0	Ceiling		Solid	Stucco	0
688	1976 bldg	39	XRF	3/2/97	1	Outside	0	Ext Wall	Trim	Solid	Metal	0.04
689	1976 bldg	44	XRF	3/2/97	1	Outside	0	Window	Sill	Solid	Metal	0
690	1976 bldg	45	XRF	3/2/97	1	Outside	0	Window	Sash	Solid	Metal	0.16
691	1976 bldg	46	XRF	3/2/97	1	Outside	0	Unlisted		Solid	Metal	0.01
692	1976 bldg	47	XRF	3/2/97	1	Outside	0	Unlisted	Sash	Peeling	Concrete	0.11
693	1976 bldg	48	XRF	3/2/97	1	Outside	0	Unlisted	Sash	Peeling	Concrete	0
694	1976 bldg	49	XRF	3/2/97	1	Outside	0	Window	Panel	Chalking	Metal	0.59
695	1976 bldg	50	XRF	3/2/97	1	Outside	0	Unlisted	Sash	Cracked	Concrete	0.01
696	1976 bldg	26	XRF	2/26/97	1	Restroom	1	Wall	Midle Wall	Solid	Concrete	1.42
697	1976 bldg	27	XRF	2/26/97	1	Restroom	1	Wall	Midle Wall	Solid	Concrete	0
698	1976 bldg	28	XRF	2/26/97	1	Restroom	1	Door	Jamb	Solid	Metal	0.01
699	1976 bldg	29	XRF	2/26/97	1	Restroom	1	Door	Door	Solid	Wood	0
700	1976 bldg	30	XRF	2/26/97	1	Restroom	1	Door	Locker	Solid	Metal	0.54
701	1976 bldg	31	XRF	2/26/97	1	Restroom	1	Door	Locker	Solid		0.01
702	1976 bldg	114	XRF	2/26/97	1	Restroom	3	Wall	Wall	Solid	Concrete	0.05
703	1976 bldg	115	XRF	2/26/97	1	Restroom	3	Wall	Baseboar	Solid	Concrete	0
704	1976 bldg	116	XRF	2/26/97	1	Restroom	3	Ceiling		Solid	Concrete	0.01
705	1976 bldg	117	XRF	2/26/97	1	Restroom	3	Wall	Wall	Solid	Tile	0
706	1976 bldg	118	XRF	2/26/97	1	Restroom	3	Wall	Midle Wall	Solid	Tile	0.24
707	1976 bldg	119	XRF	2/26/97	1	Restroom	3	Door	Casing	Solid	Metal	0.02
708	1976 bldg	120	XRF	2/26/97	1	Restroom	3	Door	Door	Solid	Wood	0
709	1976 bldg	121	XRF	2/26/97	1	Restroom	3	Door	Locker	Solid	Metal	0.65

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

	A	B	C	D	E	F	G	H	I	J	K	L
3	Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
710	1976 bldg	122	XRF	2/26/97	1	Restroom	3	Door	Locker	Solid		0.91
711	1976 bldg	123	XRF	2/26/97	1	Restroom	3	Door	Locker	Solid		0.57
712	1976 bldg	129	XRF	2/26/97	1	Restroom	4	Wall	Wall	Solid	Concrete	0.01
713	1976 bldg	130	XRF	2/26/97	1	Restroom	4	Wall	Baseboar	Solid	Concrete	0
714	1976 bldg	131	XRF	2/26/97	1	Restroom	4	Ceiling		Solid	Concrete	0
715	1976 bldg	132	XRF	2/26/97	1	Restroom	4		Locker	Solid	Metal	0.51
716	1976 bldg	133	XRF	2/26/97	1	Restroom	4	Door	Casing	Solid	Metal	0.03
717	1976 bldg	138	XRF	2/26/97	1	Restroom	5	Wall	Midle Wall	Solid	Concrete	0.03
718	1976 bldg	139	XRF	2/26/97	1	Restroom	5	Wall	Baseboar	Solid	Concrete	0
719	1976 bldg	140	XRF	2/26/97	1	Restroom	5	Wall	Midle Wall	Solid	Tile	0
720	1976 bldg	141	XRF	2/26/97	1	Restroom	5	Wall	Midle Wall	Solid	Tile	0.18
721	1976 bldg	142	XRF	2/26/97	1	Restroom	5	Ceiling		Solid	Concrete	0
722	1976 bldg	143	XRF	2/26/97	1	Restroom	5	Door	Casing	Solid	Metal	0.01
723	1976 bldg	144	XRF	2/26/97	1	Restroom	5	Door	Door	Solid	Wood	0
724	1976 bldg	145	XRF	2/26/97	1	Restroom	5	Door	Locker	Solid	Metal	0.96
725	1976 bldg	146	XRF	2/26/97	1	Restroom	5	Door	Locker	Solid		0.5
726	1976 bldg	147	XRF	2/26/97	1	Restroom	5	Door	Locker	Solid		0.6
727	1976 bldg	148	XRF	2/26/97	1	Restroom	5	Door	Locker	Solid		0.02
728	1976 bldg	149	XRF	2/26/97	1	Restroom	6	Wall	Wall	Solid	Concrete	0.01
729	1976 bldg	150	XRF	2/26/97	1	Restroom	6	Ceiling		Solid	Concrete	0
730	1976 bldg	151	XRF	2/26/97	1	Restroom	6	Floor	Flr Registr	Solid	Tile	0.02
731	1976 bldg	152	XRF	2/26/97	1	Restroom	6		Locker	Solid	Metal	0.64
732	1976 bldg	153	XRF	2/26/97	1	Restroom	6	Door	Door	Solid	Wood	0
733	1976 bldg	154	XRF	2/26/97	1	Restroom	6	Door	Casing	Solid	Metal	0.01
734	1976 bldg	155	XRF	2/26/97	1	Restroom	7	Wall	Wall	Solid	Concrete	0.03
735	1976 bldg	156	XRF	2/26/97	1	Restroom	7	Wall	Wall	Solid	Concrete	0
736	1976 bldg	157	XRF	2/26/97	1	Restroom	7	Wall	Midle Wall	Solid	Concrete	0
737	1976 bldg	158	XRF	2/26/97	1	Restroom	7	Wall	Midle Wall	Solid	Concrete	0
738	1976 bldg	159	XRF	2/26/97	1	Restroom	7	Wall	Stall Door	Solid	Metal	0.38
739	1976 bldg	166	XRF	2/26/97	1	Restroom	8	Wall	Midle Wall	Solid	Concrete	1.65
740	1976 bldg	167	XRF	2/26/97	1	Restroom	8	Wall	Wall	Solid	Concrete	0
741	1976 bldg	168	XRF	2/26/97	1	Restroom	8	Ceiling		Solid	Concrete	0
742	1976 bldg	169	XRF	2/26/97	1	Restroom	8	Wall	Baseboar	Solid	Concrete	0
743	1976 bldg	170	XRF	2/26/97	1	Restroom	8	Wall	Stall Door	Solid	Metal	0.02
744	1976 bldg	176	XRF	2/26/97	1	Restroom	9	Wall	Wall	Solid	Concrete	0
745	1976 bldg	177	XRF	2/26/97	1	Restroom	9	Ceiling		Solid	Plaster	0
746	1976 bldg	178	XRF	2/26/97	1	Restroom	10	Wall	Midle Wall	Solid	Concrete	0
747	1976 bldg	179	XRF	2/26/97	1	Restroom	10	Wall	Midle Wall	Solid	Drywall	0
748	1976 bldg	180	XRF	2/26/97	1	Restroom	10	Wall	Midle Wall	Solid	Concrete	0
749	1976 bldg	181	XRF	2/26/97	1	Restroom	10	Ceiling		Solid	Plaster	0
750	1976 bldg	119	XRF	2/27/97	1	Restroom	11	Wall	Midle Wall	Solid	Concrete	2.98
751	1976 bldg	120	XRF	2/27/97	1	Restroom	11	Wall	Midle Wall	Solid	Concrete	0
752	1976 bldg	121	XRF	2/27/97	1	Restroom	11	Wall	Baseboar	Solid	Concrete	0
753	1976 bldg	122	XRF	2/27/97	1	Restroom	11	Ceiling		Solid	Stucco	0
754	1976 bldg	123	XRF	2/27/97	1	Restroom	12	Ceiling		Solid	Stucco	0.02
755	1976 bldg	124	XRF	2/27/97	1	Restroom	12	Wall	Midle Wall	Solid	Concrete	2.67
756	1976 bldg	125	XRF	2/27/97	1	Restroom	12	Wall	Midle Wall	Solid	Concrete	0.01
757	1976 bldg	126	XRF	2/27/97	1	Restroom	12	Wall	Baseboar	Solid	Concrete	0.01
758	1976 bldg	185	XRF	2/27/97	1	Restroom	13	Wall	Wall	Solid	Drywall	0.02
759	1976 bldg	186	XRF	2/27/97	1	Restroom	14	Wall	Wall	Solid	Drywall	0
760	1976 bldg	200	XRF	2/27/97	1	Restroom	15	Wall	Wall	Solid	Drywall	0
761	1976 bldg	201	XRF	2/27/97	1	Restroom	16	Wall	Wall	Solid	Drywall	0
762	1976 bldg	47	XRF	3/1/97	1	Restroom	17	Wall	Midle Wall	Solid	Drywall	0.06
763	1976 bldg	48	XRF	3/1/97	1	Restroom	17	Wall	Baseboar	Solid	Tile	0.23
764	1976 bldg	189	XRF	3/1/97	2	Restroom	18	Wall	Wall	Solid	Concrete	0.02
765	1976 bldg	190	XRF	3/1/97	2	Restroom	18	Wall	Wall	Solid	Concrete	0
766	1976 bldg	191	XRF	3/1/97	2	Restroom	18	Ceiling		Solid	Plaster	0.02
767	1976 bldg	192	XRF	3/1/97	2	Restroom	18			Solid	Wood	0
768	1976 bldg	193	XRF	3/1/97	2	Restroom	18	Wall	Baseboar	Solid	Concrete	0

Saint Paul Public Schools
 Humboldt Secondary Complex SH
 Lead-Based Paint Inspection

A	B	C	D	E	F	G	H	I	J	K	L
Site	No	Analysis	Date	Floor	Area	Room#	Component	Feature	Condition	Substrate	Results
3	1976 bldg	194 XRF	3/1/97	2	Restroom	19	Wall	Wall	Solid	Concrete	2.08
769	1976 bldg	195 XRF	3/1/97	2	Restroom	19	Wall	Wall	Solid	Concrete	0
770	1976 bldg	196 XRF	3/1/97	2	Restroom	19	Ceiling		Solid	Plaster	0
771	1976 bldg	197 XRF	3/1/97	2	Restroom	19	Wall	Baseboar	Solid	Concrete	0
772	1976 bldg	198 XRF	3/1/97	2	Restroom	19	Wall	Stall Door	Solid	Wood	0
773	1976 bldg	18 XRF	3/2/97	3	Restroom	20	Wall	Midle Wall	Solid	Concrete	2.58
774	1976 bldg	19 XRF	3/2/97	3	Restroom	20	Wall	Midle Wall	Solid	Concrete	0
775	1976 bldg	20 XRF	3/2/97	3	Restroom	20	Wall	Baseboar	Solid	Concrete	0
776	1976 bldg	21 XRF	3/2/97	3	Restroom	20	Ceiling		Solid	Plaster	0
777	1976 bldg	22 XRF	3/2/97	3	Restroom	21	Wall	Wall	Solid	Drywall	0.02
779	1976 bldg	23 XRF	3/2/97	3	Restroom	21	Wall	Wall	Solid	Concrete	0
780	1976 bldg	24 XRF	3/2/97	3	Restroom	21	Ceiling		Solid	Plaster	0
781	1976 bldg	25 XRF	3/2/97	3	Restroom	21	Wall	Baseboar	Solid	Concrete	0
782	1976 bldg	406 XRF	3/1/97	3	Room	323	Wall	Wall	Solid	Concrete	0
783	1976 bldg	91 XRF	2/26/97	1	Stage	0	Wall	Midle Wall	Solid	Wood	0
784	1976 bldg	92 XRF	2/26/97	1	Stage	0	Wall	Baseboar	Peeling	Concrete	0.01
785	1976 bldg	93 XRF	2/26/97	1	Stage	0	Wall	Midle Wall	Solid	Concrete	0
786	1976 bldg	94 XRF	2/26/97	1	Stage	0	Door	Door	Solid	Wood	0
787	1976 bldg	95 XRF	2/26/97	1	Stage	0	Door	Door	Solid	Metal	0.27
788	1976 bldg	96 XRF	2/26/97	1	Stage	0	Door	Casing	Solid	Metal	0.01
789	1976 bldg	97 XRF	2/26/97	1	Stage	0	Door	Casing	Solid	Metal	0.02
790	1976 bldg	98 XRF	2/26/97	1	Stage	0	Ceiling		Solid	Drywall	0.04
791	1976 bldg	99 XRF	2/26/97	1	Stage	0	Ceiling		Solid		0.01
792	1976 bldg	100 XRF	2/26/97	1	Stage	0	Stairs	Riser	Solid	Metal	0.01
793	1976 bldg	101 XRF	2/26/97	2	Stage	0	Wall	Midle Wall	Solid	Drywall	0.01
794	1976 bldg	102 XRF	2/26/97	2	Stage	0	Wall	Midle Wall	Solid	Wood	0
795	1976 bldg	103 XRF	2/26/97	2	Stage	0	Window	Casing	Solid	Metal	0.01
796	1976 bldg	104 XRF	2/26/97	2	Stage	0	Door	Jamb	Solid	Metal	0.02
797	1976 bldg	105 XRF	2/26/97	2	Stage	0	Door	Door	Solid	Wood	0
798	1976 bldg	106 XRF	2/26/97	2	Stage	0	Stairs	Hand rail	Solid	Metal	0.05
799	1976 bldg	107 XRF	2/26/97	2	Stage	0	Ceiling		Solid	Metal	0.06
800	1976 bldg	49 XRF	3/1/97	1	Stairwell	1	Stairs	Riser	Solid	Metal	0.01
801	1976 bldg	50 XRF	3/1/97	1	Stairwell	1	Stairs	Wall	Solid	Concrete	0.01
802	1976 bldg	51 XRF	3/1/97	1	Stairwell	1	Stairs	Hand rail	Solid	Metal	0.01
803	1976 bldg	52 XRF	3/1/97	1	Stairwell	1	Door	Door	Solid	Wood	0
804	1976 bldg	53 XRF	3/1/97	1	Stairwell	1	Door	Jamb	Solid	Metal	0
805	1976 bldg	275 XRF	3/1/97	2	Stairwell	2	Stairs	Wall	Solid	Concrete	0
806	1976 bldg	276 XRF	3/1/97	2	Stairwell	2	Stairs	Riser	Solid	Metal	0.01
807	1976 bldg	277 XRF	3/1/97	2	Stairwell	2	Stairs	Hand rail	Solid	Metal	0.01
808	1976 bldg	278 XRF	3/1/97	2	Stairwell	2	Stairs	Baseboar	Solid	Metal	0.02
809	1976 bldg	279 XRF	3/1/97	2	Stairwell	2	Door	Door	Solid	Wood	0
810	1976 bldg	280 XRF	3/1/97	2	Stairwell	2	Door	Header	Solid	Metal	0.02
811	1976 bldg	6 XRF	3/2/97	3	Stairwell	3	Stairs	Wall	Solid	Concrete	0
812	1976 bldg	7 XRF	3/2/97	3	Stairwell	3	Stairs	Riser	Solid	Metal	0.04
813	1976 bldg	8 XRF	3/2/97	3	Stairwell	3	Stairs	Hand rail	Solid	Metal	0.03
814	1976 bldg	9 XRF	3/2/97	3	Stairwell	3	Stairs	Baseboar	Solid	Metal	0.02
815	1976 bldg	10 XRF	3/2/97	3	Stairwell	3	Door	Door	Solid	Wood	0.01
816	1976 bldg	11 XRF	3/2/97	3	Stairwell	3	Door	Jamb	Solid	Metal	0.03
817	1976 bldg	12 XRF	3/2/97	3	Stairwell	3	Ceiling		Solid	Plaster	0
818	1976 bldg	29 XRF	3/2/97	3	Stairwell	4	Stairs	Riser	Solid	Metal	0.02
819	1976 bldg	30 XRF	3/2/97	3	Stairwell	4	Stairs	Wall	Solid	Concrete	0
820	1976 bldg	31 XRF	3/2/97	3	Stairwell	4	Stairs	Hand rail	Solid	Metal	0.01
821	1976 bldg	32 XRF	3/2/97	3	Stairwell	4	Stairs	Baseboar	Solid	Metal	0.03
822	1976 bldg	33 XRF	3/2/97	3	Stairwell	4	Window	Panel	Solid	Metal	0.43

APPENDIX B

LABORATORY SAMPLE ANALYSIS DATA

LABORATORY ANALYSIS REPORT**DATE:** March 11, 1997**PAGE:**

1 Of 1

CLIENT: Midwest Environmental Cons.
5385 401st Ave. NW
Dalbo, MN 55017**PROJECT NO.:** 030597-200888
COLLECTION DATE: 2/26/97-3/02/97
COLLECTED BY: Client
RECEIVED DATE: 3/05/97
PROJECT DESCRIPT.: 62/0197P Humboldt S.H.**CONTACT:** Greg Myers/Richard Cox

SAMPLE #	DESCP.	MDL	LEAD (6010A)	ANALYSIS
			RESULTS	
L971194-1	54	400	860	3/10/97
L971194-2	30	25	90	3/10/97
L971194-3	268	39	15,000	3/10/97
L971194-4	42	39	240	3/10/97

*ND means Not Detected or below reported MDL**MDL means Method Detection Limit**mg/kg means Milligrams Per Kilogram which is equivalent to Parts Per Million (ppm)*


This report has been reviewed by me for technical accuracy and completeness. The analyses were performed using EPA or other approved methodologies and the results were reported on an "as received" basis unless otherwise noted. Organic soil analyses were reported on a dry weight basis. The results reported relate only to the items tested. Please contact me if you have any questions or comments regarding this report. Spectrum Labs, Inc. appreciates the opportunity to provide this analytical service for you.

Report Submitted By,

Thomas L. Halverson (Robert Rossini)
Thomas L. Halverson
Laboratory Manager

TLH:wmc
mec070-2*As a mutual protection, all reports are submitted in confidentiality and may not be reproduced except in full without written authorization.*

A member of The Marmon Group of Companies



Midwest Environmental Consulting, L.L.C.

5385 401st Ave. NW, Dalbo, MN 55017
612-689-3612/612-757-5541/FAX-612-689-5209

Client Address _____

Contact _____

CHAIN OF CUSTODY RECORDProject Number 62/0197P

Client _____

Project _____

Phone/Fax _____

Sample ID**Sample Description****Collection Date/Time****Analysis Requested**

62/0197P-54	site 2 Floor Lvl D metal door " " glass broken	2/26/97	1" x 1"	1(a)4-(1)
62/0197P-30	" " Rm 196 ceiling metal door door frame	2/27/97	1.5" x 1.5"	2
62/0197P-268	" Acor 2 hall 6 " " brown	3/1/97	1" x 1"	3
62/0197P-42	Outside side B metal step garage door	3/2/97	2" x 2"	4

Sampled By: Bob Date: 3/2/97 Time: _____

Received By: _____ Date: _____ Time: _____

Received By Lab: Bob Date: 3/6/97 Time: 2:15 Disposition of Samples _____

Notes: _____

Delivered By: Bob Date: 3/6/97 Time: _____

Delivered By: _____ Date: _____ Time: _____

Disposition of Samples _____

APPENDIX C INSPECTORS

**Richard T. Cox
MDH Lead Inspector # 166**