

FACILITY CONDITION ASSESSMENT



**BUREAU
VERITAS**

prepared for

Alexandria City Public Schools
2000 North Beauregard Street
Alexandria, Virginia 22311
John Finnigan



George Mason Elementary
2601 Cameron Mills Road
Alexandria, Virginia 22302

PREPARED BY:

*Bureau Veritas
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.us.bureauveritas.com*

BV CONTACT:

*Tom Bart
Program Manager
800.733.0660 x7540
Tom.Bart@bureauveritas.com*

BV PROJECT #:

148303.21R000-007.354

DATE OF REPORT:

December 15, 2021

ON SITE DATE:

June 29, 2021

Bureau Veritas

10461 Mill Run Circle, Suite 1100 | Owings Mills, MD 21117 | www.us.bureauveritas.com | p 800.733.0660

TABLE OF CONTENTS

1. Executive Summary 1

Property Overview and Assessment Details 1

Significant/Systemic Findings and Deficiencies 2

Facility Condition Index (FCI) 3

Immediate Needs..... 4

Key Findings 5

Plan Types..... 7

2. Building and Site Information 8

3. Property Space Use and Observed Areas 10

4. Purpose and Scope 11

5. Opinions of Probable Costs 13

Methodology 13

Definitions 13

6. Certification..... 15

7. Appendices 16



1. Executive Summary

Property Overview and Assessment Details

| General Information | |
|-----------------------------------|---|
| Property Type | School |
| Main Address | 2601 Cameron Mills Road, Alexandria, Virginia 22302 |
| Site Developed | YOC 1939 Renovated in 1976, 2014, 2015 |
| Site Area | 3.50 acres (estimated) |
| Parking Spaces | Approximately ten spaces. No striping. |
| Building Area | 50,935 SF |
| Number of Stories | Two above grade |
| Outside Occupants / Leased Spaces | None |
| Date(s) of Visit | June 29, 2021 |
| Management Point of Contact | Alexandria City Public Schools, John Finnigan John.Finnigan@acps.k12.va.us |
| On-site Point of Contact (POC) | Vasean Gillis |
| Assessment and Report Prepared By | JT Ballway |
| Reviewed By | Tom Bart Program Manager Tom.Bart@bureauveritas.com 800.733.0660 x7540 |
| AssetCalc Link | Full dataset for this assessment can be found at: https://www.assetcalc.net/ |

Significant/Systemic Findings and Deficiencies

Historical Summary

The building was constructed in 1939. Not much remains from original construction outside the shell of the building after a major remodel in 1976. It has been renovated multiple times, most recently in 2014 and 2015. Some of the building appears to be historical.

Architectural

The school is a two-story CMU and reinforced concrete structure. Exterior façade consists of brick veneer with double-glazed vinyl framed windows. The brick work needs repointing in isolated areas. Wood trim, soffits, and fascia's need refinishing. Exterior doors are swinging steel or composite units with a small amount of glazing. Some older wood doors remain. The roof is primarily a TPO membrane, which was installed in recent years. The oldest portion of the building is covered with a slate tile, while the newest portion of the building is covered with asphalt shingles. There is also smaller standing seam metal roofs around the gymnasium. Interior finishes consist of vinyl tile, carpet, quarry tile, and ceramic tile on the floors. Interior walls are finished with glazed block and/or a painted finish. Ceilings are finished with acoustical ceiling tiles.

Mechanical, Electrical, Plumbing and Fire (MEPF)

The school is primarily condition by an air-cooled chiller and two boilers. Classrooms, hallways, and offices are primarily conditioned by ventilators. There is also a series of rooftop packaged units and split system units.

The electrical distribution system appears to be older for the most part with some components replaced as needed. Lighting appears to be T-8 fixtures in large part.

There are three water heaters supplying hot water to the restrooms and kitchen.

Fire protection includes an integrated fire alarm system which includes horn strobes, pull stations and smoke detectors, as well as addressable fire alarm control panel. Fire suppression is limited to a network of extinguishers throughout the building.

Site

The site consists of a small unstriped parking area, the school building, playground and landscaped area. The school shares a border with a city park.

Recommended Additional Studies

No additional studies recommended at this time.

Facility Condition Index (FCI)

One of the major goals of the FCA is to calculate each building's Facility Condition Index (FCI), which provides a theoretical objective indication of a building's overall condition. By definition, the FCI is defined as the ratio of the cost of current needs divided by current replacement value (CRV) of the facility. The chart below presents the industry standard ranges and cut-off points.

FCI Ranges and Description

| | |
|----------------------|---|
| 0 – 5% | In new or well-maintained condition, with little or no visual evidence of wear or deficiencies. |
| 5 – 10% | Subjected to wear but is still in a serviceable and functioning condition. |
| 10 – 30% | Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life. |
| 30% and above | Has reached the end of its useful or serviceable life. Renewal is now necessary. |

The deficiencies and lifecycle needs identified in this assessment provide the basis for a portfolio-wide capital improvement funding strategy. In addition to the current FCI, extended FCI's have been developed to provide owners the intelligence needed to plan and budget for the "keep-up costs" for their facilities. As such the 3-year, 5-year, and 10-year FCI's are calculated by dividing the anticipated needs of those respective time periods by current replacement value. As a final point, the FCI's ultimately provide more value when used to relatively compare facilities across a portfolio instead of being over-analyzed and scrutinized as stand-alone values. The table below summarizes the individual findings for this FCA:

FCI Analysis | George Mason Elementary School Campus(1939)

| | | | |
|---|---------------------------|--------------------------|---------------|
| <i>Replacement Value</i> \$ 15,280,500 | <i>Total SF</i> 50,935 | <i>Cost/SF</i> \$ 300 | |
| | Est Reserve Cost | | FCI |
| Current | \$ 240,100 | | 1.6 % |
| 3-Year | \$ 2,039,200 | | 13.3 % |
| 5-Year | \$ 3,135,200 | | 20.5 % |
| 10-Year | \$ 6,663,900 | | 43.6 % |

The vertical bars below represent the year-by-year needs identified for the site. The orange line in the graph below forecasts what would happen to the FCI (left Y axis) over time, assuming zero capital expenditures over the next ten years. The dollar amounts allocated for each year (blue bars) are associated with the values along the right Y axis.


Needs by Year with Unaddressed FCI Over Time

FCI Analysis: George Mason Elementary School Campus

Replacement Value: \$15,281,000

Inflation Rate: 3.0%

Average Needs per Year: \$605,900



Immediate Needs

| Facility/Building | Total Items | Total Cost |
|---------------------------------------|-------------|------------------|
| George Mason Elementary School Campus | 5 | \$240,000 |
| Total | 5 | \$240,000 |

George Mason Elementary School Campus

| ID | Location | Location Description | UF Code | Description | Condition | Plan Type | Cost |
|------------------------|---------------------------------------|----------------------|---------|---|-----------|-----------------------|------------------|
| 3460740 | George Mason Elementary School Campus | | P2030 | Engineering Study, Structural, General Design, Basement Mechanical Room | NA | Performance/Integrity | \$7,000 |
| 3046384 | George Mason Elementary School Campus | Parking lot | G2020 | Parking Lots, Pavement, Asphalt, Seal & Stripe | Failed | Performance/Integrity | \$8,300 |
| 3046374 | George Mason Elementary School Campus | Exterior wall | B2010 | Exterior Walls, Brick or Brick Veneer, 1-2 Story Building, Repair/Repaint | Poor | Performance/Integrity | \$13,200 |
| 3046432 | George Mason Elementary School Campus | Front stairs | B1080 | Stair Treads, Raised Rubber Tile, Replace | Failed | Performance/Integrity | \$9,000 |
| 3461117 | George Mason Elementary School Campus | | A2010 | Basement Wall, any type, Waterproofing of Exterior Face, Replace | NA | Performance/Integrity | \$202,500 |
| Total (5 items) | | | | | | | \$240,000 |

Key Findings



Exterior Walls in Poor condition.

Brick or Brick Veneer, 1-2 Story Building
George Mason Elementary School Campus
Exterior wall

Uniformat Code: B2011

Recommendation: **Repair/Repoint in 2021**

Priority Score: **89.9**

Plan Type:
Performance/Integrity

Cost Estimate: \$13,200

\$\$\$\$

Sections of the exterior walls were observed to be in poor condition. Many areas have experienced damage and there are holes within the facade which allow water infiltration. The property has experienced problems with rodent infestation through the facade. The brick veneer will require repair during the reserve term. - AssetCALC ID: 3046374



Exterior Walls in Poor condition.

Any painted surface, 1-2 Story Building
George Mason Elementary School Campus
Building exterior

Uniformat Code: B2011

Recommendation: **Prep & Paint in 2023**

Priority Score: **89.6**

Plan Type:
Performance/Integrity

Cost Estimate: \$7,000

\$\$\$\$

The painted finish on the wood trim was observed to be in poor condition. The fascia and soffits have experienced a significant amount of damage. the damaged wooden trim is believed to contribute to the water infiltration within the building. The wood trim will require replacement during the reserve term. - AssetCALC ID: 3046348



Parking Lots in Failed condition.

Pavement, Asphalt
George Mason Elementary School Campus
Parking lot

Uniformat Code: G2021

Recommendation: **Seal & Stripe in 2021**

Priority Score: **84.9**

Plan Type:
Performance/Integrity

Cost Estimate: \$8,300

\$\$\$\$

There is no striping. - AssetCALC ID: 3046384

Recommended Follow-up Study: Structural, General Design

Structural, General Design
George Mason Elementary School Campus

Uniformat Code: P2032
Recommendation: **Basement Mechanical
Room in 2021**


Priority Score: **81.9**

Plan Type:
Performance/Integrity

Cost Estimate: \$7,000

\$\$\$\$

Water intrusion into the basement mechanical room that need to be abated. - AssetCALC ID: 3460740



Stair Treads in Failed condition.

Raised Rubber Tile
George Mason Elementary School Campus
Front stairs

Uniformat Code: B1081
Recommendation: **Replace in 2021**

Priority Score: **81.9**

Plan Type:
Performance/Integrity

Cost Estimate: \$9,000

\$\$\$\$

The front two sets of stairs have a polished surface which is likely slippery when wet. Rubber treads or tape should be installed to ensure safe footing. - AssetCALC ID: 3046432



Exterior Door in Poor condition.

Wood, Solid-Core Decorative High-End w/
Glazing
George Mason Elementary School Campus
Building exterior

Uniformat Code: B2051
Recommendation: **Replace in 2023**

Priority Score: **81.7**

Plan Type:
Performance/Integrity

Cost Estimate: \$4,200

\$\$\$\$

Doors are badly deteriorated. - AssetCALC ID: 3147159


Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance.

Plan Type Descriptions

| | | |
|------------------------------|---|---|
| Safety | ■ | An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk. |
| Performance/Integrity | ■ | Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability. |
| Accessibility | ■ | Does not meet ADA, UFAS, and/or other accessibility requirements. |
| Environmental | ■ | Improvements to air or water quality, including removal of hazardous materials from the building or site. |
| Retrofit/Adaptation | ■ | Components, systems, or spaces recommended for upgrades in in order to meet current standards, facility usage, or client/occupant needs. |
| Lifecycle/Renewal | ■ | Any component or system that is not currently deficient or problematic but for which future replacement or repair is anticipated and budgeted. |

Plan Type Distribution (by Cost)



2. Building and Site Information



Systems Summary

| <i>System</i> | <i>Description</i> | <i>Condition</i> |
|--------------------------|---|------------------|
| Structure | Masonry bearing walls with light gauge metal roof decks | Good |
| Façade | Primary Wall Finish: Brick Windows: Vinyl | Fair |
| Roof | Primary: Flat construction with single-ply TPO/PVC membrane Secondary: Hip construction with asphalt shingle or slate tile | Fair |
| Interiors | Walls: Painted CMU, glazed brick Floors: Carpet, VCT, quarry tile, ceramic tile Ceilings: ACT | Fair |
| Elevators | Passenger: One hydraulic car serving both floors | Fair |
| Plumbing | Distribution: Copper distribution and PVC waste and venting Hot Water: Gas commercial heater and electric commercial water heater Fixtures: Toilets, urinals, and sinks in some restrooms | Fair |
| HVAC | Central System: Boilers and chiller feeding ventilators Non-Central System: Packaged units // Split-system heat pumps | Fair |
| Fire Suppression | Fire extinguishers only | Good |
| Electrical | Source and Distribution: Main switchboard with copper wiring Interior Lighting: linear fluorescent | Fair |
| Fire Alarm | Alarm panel with smoke detectors, heat detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs | Fair |
| Equipment/Special | Commercial kitchen equipment | Fair |

Systems Summary

| | | |
|-----------------------------------|--|------|
| Site Pavement | Asphalt lots with limited areas of concrete aprons and pavement and adjacent concrete sidewalks, curbs, ramps, and stairs | Fair |
| Site Development | Property entrance signage Playgrounds, fencing, and site lights Heavily furnished with park benches, picnic tables, trash receptacles | Fair |
| Landscaping and Topography | Limited landscaping features including lawns, trees, bushes, and planters Irrigation not present Low to moderate site slopes throughout | Fair |
| Utilities | Municipal water and sewer Local utility-provided electric and natural gas | Fair |
| Site Lighting | Building-mounted: LED | Fair |
| Ancillary Structures | None | -- |
| Key Issues and Findings | The front stairs have no tread surface, there is no striping in the parking lot, brick repointing needed, wood trim needs refinished, old, deteriorated wood doors need replacement. | |

Systems Expenditure Forecast

| System | Immediate | Short Term (1-2 yr) | Near Term (3-5 yr) | Med Term (6-10 yr) | Long Term (11-20 yr) | TOTAL |
|---------------------------------|------------------|------------------------|-----------------------|-----------------------|-------------------------|---------------------|
| Structure | \$211,500 | - | \$3,646 | - | \$20,488 | \$235,634 |
| Facade | \$13,200 | \$11,902 | - | - | \$21,801 | \$46,903 |
| Roofing | - | - | \$766,992 | - | \$141,737 | \$908,729 |
| Interiors | - | - | \$483,415 | \$142,687 | \$556,678 | \$1,182,780 |
| Conveying | - | - | \$74,304 | - | \$4,405 | \$78,709 |
| Plumbing | - | - | \$21,598 | \$114,228 | \$1,440,192 | \$1,576,018 |
| HVAC | - | - | \$550,397 | \$92,827 | \$541,322 | \$1,184,546 |
| Fire Protection | - | - | - | \$3,426 | \$4,604 | \$8,030 |
| Electrical | - | - | \$26,770 | \$2,108,423 | \$372,823 | \$2,508,016 |
| Fire Alarm & Electronic Systems | - | - | \$597,190 | \$277,092 | \$507,053 | \$1,381,335 |
| Equipment & Furnishings | - | - | \$119,807 | - | \$168,291 | \$288,098 |
| Special Construction & Demo | - | - | - | - | \$4,515 | \$4,515 |
| Site Development | - | - | \$134,427 | \$778,810 | \$734 | \$913,971 |
| Site Pavement | \$8,329 | - | \$89,283 | \$11,193 | \$28,019 | \$136,824 |
| Site Utilities | - | - | \$15,374 | - | \$7,048 | \$22,422 |
| Follow-up Studies | \$7,000 | - | - | - | - | \$7,000 |
| TOTALS | \$240,100 | \$12,000 | \$2,883,300 | \$3,528,700 | \$3,819,800 | \$10,483,900 |

3. Property Space Use and Observed Areas

Areas Observed

The interior spaces were observed in order to gain a clear understanding of the property's overall condition. Other areas accessed included the site within the property boundaries, the exterior of the property, and the roofs.

Key Spaces Not Observed

All key areas of the property were accessible and observed.

4. Purpose and Scope

Purpose

Bureau Veritas was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

| Condition Ratings | |
|-----------------------|---|
| Excellent | New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service. |
| Good | Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service. |
| Fair | Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life. |
| Poor | Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life. |
| Failed | Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required. |
| Not Applicable | Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present. |

Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.

5. Opinions of Probable Costs

Cost estimates are attached throughout this report, with the Replacement Reserves in the appendix.

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means*, *CBRE Whitestone*, and *Marshall and Swift*, Bureau Veritas's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, Bureau Veritas opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its *effective age*, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of Bureau Veritas's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

Definitions

Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with *Safety* or *Performance/Integrity* Plan Types, are considered Immediate Needs.

Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, Bureau Veritas's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

Bureau Veritas's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system's or component's respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.

Exceedingly Aged

A fairly common scenario encountered during the assessment process, and a frequent source of debate, occurs when classifying and describing "very old" systems or components that are still functioning adequately and do not appear nor were reported to be in any way deficient. To help provide some additional intelligence on these items, such components will be tagged in the database as Exceedingly Aged. This designation will be reserved for mechanical or electrical systems or components that have aged well beyond their industry standard lifecycles, typically at least 15 years beyond and/or twice their Estimated Useful Life (EUL). In tandem with this designation, these items will be assigned a Remaining Useful Life (RUL) not less than two years but not greater than 1/3 of their standard EUL. As such the recommended replacement time for these components will reside outside the typical Short Term window but will not be pushed 'irresponsibly' (too far) into the future.

6. Certification

Alexandria City Public Schools (the Client) retained Bureau Veritas to perform this Facility Condition Assessment in connection with its continued operation of George Mason Elementary, 2601 Cameron Mills Road, Alexandria, Virginia 22302, the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared for and is exclusively for the use and benefit of the Client identified on the cover page of this report. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and Bureau Veritas.

This report, or any of the information contained therein, is not for the use or benefit of, nor may it be relied upon by any other person or entity, for any purpose without the advance written consent of Bureau Veritas. Any reuse or distribution without such consent shall be at the client's or recipient's sole risk, without liability to Bureau Veritas.

Prepared by: JT Ballway,
Project Manager

Reviewed by:



Jose L Rolon,
Technical Report Reviewer for
Tom Bart,
Program Manager
Tom.Bart@bureauveritas.com
800.733.0660 x7540

7. Appendices

- Appendix A: Photographic Record
- Appendix B: Site Plan
- Appendix C: Pre-Survey Questionnaire
- Appendix D: Accessibility Review and Photos
- Appendix E: Component Condition Report
- Appendix F: Replacement Reserves
- Appendix G: Equipment Inventory List

Appendix A:

Photographic Record



1 FRONT ELEVATION



2 RIGHT ELEVATION



3 LEFT ELEVATION



4 REAR ELEVATION



5 BRICK FACADE



6 WINDOWS



| | |
|---|---------------|
| 7 | EXTERIOR DOOR |
|---|---------------|



| | |
|---|------------|
| 8 | METAL ROOF |
|---|------------|



| | |
|---|----------|
| 9 | TPO ROOF |
|---|----------|



| | |
|----|------------------|
| 10 | ASPHALT SHINGLES |
|----|------------------|



| | |
|----|------------|
| 11 | SLATE ROOF |
|----|------------|



| | |
|----|-----------|
| 12 | GYMNASIUM |
|----|-----------|



13

OFFICE




14

CAFETERIA



15

CLASSROOM



16

STAIRS



17

CORRIDOR



18

ELEVATOR CAB FINISHES



19

ELEVATOR MACHINE



20

WATER HEATER



21

BOILER ROOM




22

CHILLED WATER PUMPS



23

ELECTRICAL EQUIPMENT



24

CORRIDOR LIGHTING



25

KITCHEN LIGHTING



26

FIRE ALARM TERMINAL DEVICE



27

FIRE ALARM PANEL



28

GENERATOR



29

REFRIGERATORS



30

KITCHEN



31

PLAY STRUCTURE




32

PLAYGROUND



33

PARKING LOT




34

EXTERIOR WOOD DOOR



35

BROKEN CONCRETE WINDOW LINTEL



36

DETERIORATED WOOD TRIM

Appendix B:

Site Plan

Site Plan



Project Number

148303.21R000-007.354

Source

Google

Project Name

George Mason Elementary

On-Site Date

June 29, 2021



Appendix C:

Pre-Survey Questionnaire

**BUREAU VERITAS FACILITY CONDITION ASSESSMENT:
PRE-SURVEY QUESTIONNAIRE**

Building / Facility Name: George Mason Elementary

Name of person completing form: John Finnigan

Title / Association with property: Director of Educational Facilities

Length of time associated w/ property: 6 years

Date Completed: 11/01/21

Phone Number: 703.517.1807

Method of Completion: Choose an item.

Directions: Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses.

| DATA OVERVIEW | | RESPONSE | | |
|---------------|---------------------------------|--------------------------------------|------------------|--|
| 1 | Year/s constructed / renovated | 1939 / additions in 1949, 1977, 2015 | | |
| 2 | Building size in SF | 65,535 | | |
| 3 | Major Renovation/Rehabilitation | | Year | Additional Detail |
| | | Façade | 2016 | Window repairs, masonry tuck-pointing, caulking; painting |
| | | Roof | 2000; 2020 | Replacement; 2020 Repair (liquid applied membrane) |
| | | Interiors | 2016, 2018, 2019 | Wall repairs; Bathroom floor repair; Asbestos remediation / carpet removal, LVT installation |
| | | HVAC | 2018, 2019 | Office HVAC replacement; Chiller replacement |
| | | Electrical | | |
| | | Site Pavement | | |
| | | Accessibility | | |

| QUESTION | | RESPONSE |
|----------|--|--|
| 4 | List other significant capital improvements (focus on recent years; provide approximate date). | 2015 Modular addition; 2016 Playground resurfacing |
| 5 | List any major capital expenditures planned/requested for the next few years. Have they been budgeted? | |
| 6 | Describe any on-going extremely problematic, historically chronic, or immediate facility needs. | |

| Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any Yes responses. (NA indicates "Not Applicable", Unk indicates "Unknown") | | | | | | |
|--|---|----------|----|-----|----|---|
| QUESTION | | RESPONSE | | | | COMMENTS |
| | | Yes | No | Unk | NA | |
| 7 | Are there any problems with foundations or structures, like excessive settlement? | X | | | | |
| 8 | Are there any wall, window, basement or roof leaks? | | X | | | Addressed with phased window system, wall and building envelope repair projects. |
| 9 | Has any part of the facility ever contained visible suspect mold growth, or have there been any indoor air quality or mold related complaints from occupants? | X | | | | There were mold issues in 2016 due to water intrusion. Environmental contractor abated the mold and subsequent building envelope repairs, window repairs and interior wall reconstruction fixed the water intrusion issues. |
| 10 | Are your elevators unreliable, with frequent service calls? | | X | | | |
| 11 | Are there any plumbing leaks, water pressure, or clogging/back-up problems? | | X | | | |
| 12 | Have there been any leaks or pressure problems with natural gas, HVAC supply/return lines, or steam service? | | X | | | |
| 13 | Are any areas of the facility inadequately heated, cooled or ventilated? Any poorly insulated areas? | | X | | | |
| 14 | Is the electrical service outdated, undersized, or otherwise problematic? | | X | | | |
| 15 | Are there any problems or inadequacies with exterior lighting? | | X | | | |
| 16 | Is site/parking drainage inadequate, with excessive ponding or other problems? | | X | | | |
| 17 | Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified above? | | X | | | |

| Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any Yes responses. (NA indicates “ <i>Not Applicable</i> ”, Unk indicates “ <i>Unknown</i> ”) | | | | | | |
|--|---|----------|----|-----|----|----------|
| QUESTION | | RESPONSE | | | | COMMENTS |
| | | Yes | No | Unk | NA | |
| 18 | ADA: Has an accessibility study been performed at the site? If so, indicate when. | | X | | | |
| 19 | ADA: If a study has occurred, have the associated recommendations been addressed? In full or in part? | | | | X | |
| 20 | ADA: Have there been regular complaints about accessibility issues, or associated previous or pending litigation? | | X | | | |

Appendix D:

Accessibility Review and Photos

**THIS APPENDIX IS INTENTIONALLY LEFT
BLANK.**

Appendix E:

Component Condition Report

Component Condition Report | George Mason Elementary School Campus

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|------------|---------------------|-----------|---|-----------|-----|---------|
| Structure | | | | | | |
| A2010 | | NA | Basement Wall, any type, Waterproofing of Exterior Face | 7,500 SF | 0 | 3461117 |
| B1080 | Rear stairs | Fair | Stair Treads, Raised Rubber Tile | 300 SF | 3 | 3147170 |
| B1080 | Common areas | Good | Stair Treads, Raised Rubber Tile | 300 SF | 15 | 3046407 |
| B1080 | Site | Fair | Stair/Ramp Rails, Metal, Refinish | 225 LF | 3 | 3147197 |
| B1080 | Front stairs | Failed | Stair Treads, Raised Rubber Tile | 900 SF | 0 | 3046432 |
| Facade | | | | | | |
| B2010 | Building exterior | Poor | Exterior Walls, any painted surface, 1-2 Story Building, Prep & Paint | 2,340 SF | 2 | 3046348 |
| B2010 | Exterior wall | Poor | Exterior Walls, Brick or Brick Veneer, 1-2 Story Building, Repair/Repoint | 400 SF | 0 | 3046374 |
| B2020 | Exterior wall | Good | Window, Vinyl-Clad Double-Glazed, 16-25 SF | 149 | 23 | 3046370 |
| B2020 | Building exterior | Good | Window, Aluminum Double-Glazed, 16-25 SF | 30 | 23 | 3147154 |
| B2050 | Building exterior | Good | Exterior Door, Wood, Solid-Core Decorative High-End w/ Glazing | 8 | 23 | 3147165 |
| B2050 | Building exterior | Fair | Exterior Door, Steel, Standard | 4 | 19 | 3046376 |
| B2050 | Building exterior | Poor | Exterior Door, Wood, Solid-Core Decorative High-End w/ Glazing | 2 | 2 | 3147159 |
| B2050 | Building exterior | Good | Exterior Door, Wood, Solid-Core Decorative High-End w/ Glazing | 2 | 20 | 3046377 |
| B2050 | Building exterior | Good | Exterior Door, Steel, Standard | 16 | 33 | 3046375 |
| Roofing | | | | | | |
| B3010 | Roof | Good | Roofing, Asphalt Shingle, 30-Year Premium | 3,000 SF | 24 | 3046350 |
| B3010 | Gym roof | Fair | Roofing, Metal | 1,200 SF | 19 | 3046349 |
| B3010 | Roof | Fair | Roofing, Slate | 6,600 SF | 29 | 3046353 |
| B3010 | Roof | Fair | Roofing, Single-Ply Membrane, TPO/PVC | 41,000 SF | 3 | 3046352 |
| B3010 | Gym roof | Fair | Roofing, Single-Ply Membrane, TPO/PVC | 4,500 SF | 13 | 3046351 |
| B3020 | Roof | Fair | Roof Appurtenances, Gutters & Downspouts, Aluminum w/ Fittings | 514 LF | 5 | 3147137 |
| B3020 | Roof | Good | Roof Appurtenances, Gutters & Downspouts, Aluminum w/ Fittings | 150 LF | 14 | 3046436 |
| B3060 | Roof | Good | Roof Skylight, per unit, up to 20 SF | 24 | 23 | 3147156 |
| Interiors | | | | | | |
| C1030 | Throughout building | Fair | Interior Door, Wood, Solid-Core | 98 | 22 | 3147148 |
| C1030 | Throughout building | Good | Door Hardware, School, per Door | 98 | 20 | 3147186 |
| C1070 | Common areas | Fair | Suspended Ceilings, Acoustical Tile (ACT) | 35,700 SF | 4 | 3046429 |
| C1090 | Restrooms | Fair | Toilet Partitions, Metal | 22 | 10 | 3147178 |
| C1090 | Throughout building | Fair | Lockers, Steel-Baked Enamel, 12" W x 15" D x 72" H | 200 | 5 | 3147135 |

Component Condition Report | George Mason Elementary School Campus

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|------------|---------------------|-----------|--|-----------|-----|---------|
| C2010 | Throughout building | Fair | Wall Finishes, any surface, Prep & Paint | 53,481 SF | 5 | 3046423 |
| C2030 | Throughout building | Good | Flooring, Luxury Vinyl Tile (LVT) | 7,000 SF | 12 | 3147146 |
| C2030 | Gym | Fair | Flooring, Maple Sports Floor | 4,700 SF | 9 | 3046421 |
| C2030 | Throughout building | Fair | Flooring, Vinyl Tile (VCT) | 20,000 SF | 3 | 3147175 |
| C2030 | Restrooms | Fair | Flooring, Ceramic Tile | 750 SF | 19 | 3046419 |
| C2030 | Restrooms | Good | Flooring, Terrazzo | 1,200 SF | 35 | 3147172 |
| C2030 | Throughout building | Good | Flooring, Carpet, Commercial Tile | 5,500 SF | 7 | 3147162 |
| C2030 | kitchen | Good | Flooring, Quarry Tile | 1,200 SF | 44 | 3046418 |
| C2030 | Common areas | Fair | Flooring, Carpet, Commercial Standard | 3,000 SF | 3 | 3046420 |
| Conveying | | | | | | |
| D1010 | Elevator | Fair | Passenger Elevator, Hydraulic, 2 Floors, Renovate | 1 | 3 | 3147136 |
| D1010 | Elevator | Fair | Elevator Cab Finishes, Economy | 1 | 3 | 3046355 |
| D1010 | Elevator | Fair | Elevator Controls, Automatic, 1 Car | 1 | 3 | 3147160 |
| Plumbing | | | | | | |
| D2010 | Throughout building | Fair | Sink/Lavatory, Vanity Top, Stainless Steel | 2 | 15 | 3147152 |
| D2010 | Restrooms | Fair | Urinal, Waterless | 7 | 9 | 3046410 |
| D2010 | Throughout building | Fair | Drinking Fountain, Wall-Mounted, Single-Level | 6 | 5 | 3147183 |
| D2010 | Utility closet | Fair | Sink/Lavatory, Vanity Top, Solid Surface or Vitreous China | 1 | 15 | 3147177 |
| D2010 | Electrical Room | Good | Water Heater, Electric, Commercial (12 kW) | 1 | 16 | 3046357 |
| D2010 | Throughout building | Fair | Plumbing System, Supply & Sanitary, High Density (excludes fixtures) | 50,935 SF | 20 | 3147139 |
| D2010 | Boiler room | Good | Backflow Preventer, Domestic Water | 1 | 20 | 3147205 |
| D2010 | Boiler room | Fair | Water Heater, Gas, Commercial (200 MBH) | 1 | 11 | 3147181 |
| D2010 | Restrooms | Fair | Sink/Lavatory, Wall-Hung, Vitreous China | 19 | 12 | 3147182 |
| D2010 | Restrooms | Fair | Toilet, Commercial Water Closet | 38 | 9 | 3046409 |
| D2010 | Throughout building | Fair | Sink/Lavatory, Service Sink, Floor | 2 | 14 | 3147207 |
| D2010 | Electrical room | Good | Backflow Preventer, Domestic Water | 1 | 20 | 3147180 |
| D2010 | Kitchen | Good | Sink/Lavatory, Commercial Kitchen, 3-Bowl | 1 | 20 | 3147142 |
| D2010 | Restrooms | Fair | Sink/Lavatory, Trough Style, Solid Surface | 4 | 9 | 3046411 |
| D2010 | Kitchen | Fair | Water Heater, Gas, Commercial (125 MBH) | 1 | 13 | 3046356 |
| D2010 | Main corridor | Fair | Drinking Fountain, Floor-Mounted, Interior Basic | 1 | 3 | 3147184 |
| D2020 | Boiler room | Fair | Pump, Sewage Ejector | 1 | 5 | 3147149 |
| D2020 | Boiler room | Fair | Pump, Sewage Ejector | 1 | 5 | 3147201 |

Component Condition Report | George Mason Elementary School Campus

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|------------|---------------------|-----------|---|-----------|-----|---------|
| D2030 | Electrical room | Fair | Pump, Sump | 1 | 3 | 3147191 |
| D2030 | Roof | Fair | Plumbing System, Rain Water Drainage, Low Density | 46,500 SF | 10 | 3046435 |
| HVAC | | | | | | |
| D3010 | Site | Fair | Storage Tank, Fuel | 1 | 8 | 3147164 |
| D3020 | Boiler room | Fair | Boiler Supplemental Components, Shot Feed Tank | 1 | 12 | 3147195 |
| D3020 | Boiler Room | Fair | Boiler, Gas, HVAC | 1 | 12 | 3046413 |
| D3020 | Roof | Fair | Furnace, Gas [ERU-1] | 1 | 13 | 3046405 |
| D3020 | Boiler room | Fair | Boiler Supplemental Components, Expansion Tank | 1 | 22 | 3147151 |
| D3020 | Boiler Room | Fair | Boiler, Gas, HVAC | 1 | 12 | 3046414 |
| D3030 | Classrooms | Fair | Unit Ventilator, approx/nominal 2 Ton | 29 | 3 | 3046426 |
| D3030 | Storage closet | Fair | Split System, Fan Coil Unit, DX | 1 | 3 | 3147176 |
| D3030 | Roof | Good | Split System, Condensing Unit/Heat Pump | 1 | 12 | 3046391 |
| D3030 | Site | Fair | Split System, Condensing Unit/Heat Pump | 1 | 3 | 3147150 |
| D3030 | Building Exterior | Fair | Chiller, Air-Cooled | 1 | 3 | 3046415 |
| D3030 | Roof | Good | Split System, Condensing Unit/Heat Pump | 1 | 12 | 3046390 |
| D3030 | Roof | Fair | Split System, Condensing Unit/Heat Pump | 1 | 3 | 3147192 |
| D3030 | Roof | Fair | Heat Pump, Variable Refrigerant Volume (VRV), 12 TON | 1 | 7 | 3046394 |
| D3050 | Gymnasium Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted, 8 to 10 TON | 1 | 3 | 3046358 |
| D3050 | Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted, 6 to 7.5 TON | 1 | 3 | 3147166 |
| D3050 | Boiler room | Fair | Pump, Distribution, HVAC Heating Water | 1 | 7 | 3147198 |
| D3050 | Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted | 1 | 13 | 3046367 |
| D3050 | Gymnasium Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted, 8 to 10 TON | 1 | 3 | 3046368 |
| D3050 | Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted, 6 to 7.5 TON | 1 | 3 | 3046363 |
| D3050 | Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted, 6 to 7.5 TON | 1 | 3 | 3046359 |
| D3050 | Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted, 6 to 7.5 TON | 1 | 3 | 3147157 |
| D3050 | Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted | 1 | 13 | 3147202 |
| D3050 | Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted | 1 | 3 | 3046365 |
| D3050 | Electrical Room | Fair | Pump, Distribution, HVAC Chilled or Condenser Water | 1 | 7 | 3046412 |
| D3050 | Gymnasium Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted, 8 to 10 TON | 1 | 3 | 3046361 |
| D3050 | Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted, 4 TON | 1 | 3 | 3046362 |
| D3050 | Throughout building | Fair | HVAC System, Ductwork, Medium Density | 50,935 SF | 12 | 3147145 |
| D3050 | Electrical room | Fair | Pump, Distribution, HVAC Chilled or Condenser Water | 1 | 7 | 3147190 |

Component Condition Report | George Mason Elementary School Campus

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|---------------------------------|---------------------|-----------|---|-----------|-----|---------|
| D3050 | Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted | 1 | 3 | 3046360 |
| D3050 | Boiler Room | Fair | Pump, Distribution, HVAC Heating Water | 1 | 7 | 3046408 |
| D3050 | Gymnasium Roof | Fair | Packaged Unit, RTU, Pad or Roof-Mounted, 8 to 10 TON | 1 | 3 | 3046369 |
| D3060 | Roof | Fair | Exhaust Fan, Centrifugal, 12" Damper | 12 | 12 | 3046427 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 24" Damper | 4 | 13 | 3046428 |
| D3060 | Roof | Good | Exhaust Fan, Roof or Wall-Mounted, 24" Damper | 2 | 14 | 3147199 |
| Fire Protection | | | | | | |
| D4030 | Throughout building | Good | Fire Extinguisher, Type ABC, up to 20 LB | 15 | 10 | 3147189 |
| D4030 | Kitchen | Good | Fire Extinguisher, Wet Chemical/CO2 | 1 | 10 | 3147194 |
| Electrical | | | | | | |
| D5010 | Electrical Room | Fair | Automatic Transfer Switch, ATS | 1 | 7 | 3046343 |
| D5010 | Building Exterior | Fair | Generator, Diesel | 1 | 7 | 3046344 |
| D5020 | Electrical Room | Fair | Switchboard, 120/208 V | 1 | 22 | 3046399 |
| D5030 | Boiler room | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 1 | 3 | 3147158 |
| D5030 | Throughout building | Fair | Electrical System, Wiring & Switches, High Density/Complexity | 50,935 SF | 20 | 3147193 |
| D5030 | Boiler room | Fair | Variable Frequency Drive, VFD, by HP of Motor, Replace/Install | 1 | 3 | 3147188 |
| D5040 | Throughout building | Fair | Emergency & Exit Lighting, Exit Sign, LED | 15 | 3 | 3147140 |
| D5040 | Gymnasium | Fair | Special Fixture w/ Lamp, any type Interior High Bay, w/ LED Replacement | 24 | 3 | 3046402 |
| D5040 | Throughout building | Fair | Interior Lighting System, Full Upgrade, Very High Density or High-End Fixtures | 50,935 SF | 10 | 3147163 |
| D5040 | Throughout Building | Fair | Interior Lighting System, Full Upgrade, High Density & Standard Fixtures | 50,935 SF | 7 | 3046401 |
| Fire Alarm & Electronic Systems | | | | | | |
| D6060 | Throughout Building | Fair | Intercom/PA System, Public Address Upgrade, Facility-Wide | 50,935 SF | 4 | 3046378 |
| D7010 | Throughout Building | Fair | Intrusion Detection System, Full Alarm System Renovation/Upgrade, Upgrade/Install | 50,935 SF | 4 | 3046379 |
| D7030 | Throughout Building | Fair | Security/Surveillance System, Full System Installation, High Density, Install | 50,935 SF | 8 | 3046380 |
| D7050 | Throughout Building | Fair | Fire Alarm System, Full System Upgrade, Standard Addressable, Install | 50,935 SF | 5 | 3046381 |
| D7050 | Main Office | Fair | Fire Alarm Panel, Fully Addressable | 1 | 8 | 3046382 |
| D8010 | Throughout Building | Fair | BAS/HVAC Controls, Basic System or Legacy Upgrades, Upgrade/Install | 50,935 SF | 3 | 3046431 |
| Equipment & Furnishings | | | | | | |
| E1030 | Kitchen | Fair | Foodservice Equipment, Refrigerator, 2-Door Reach-In | 1 | 5 | 3147174 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Dairy Cooler/Wells | 1 | 3 | 3147185 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Tabletop Drawers (Set of 4) | 1 | 5 | 3147168 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Refrigerator, 2-Door Reach-In | 1 | 5 | 3147187 |

Component Condition Report | George Mason Elementary School Campus

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|--|-------------------|-----------|--|-----------|-----|---------|
| E1030 | Roof | Good | Foodservice Equipment, Walk-In, Condenser for Refrigerator/Freezer | 1 | 12 | 3046393 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Refrigerator, Undercounter 1-Door | 1 | 5 | 3147200 |
| E1030 | Roof | Good | Foodservice Equipment, Walk-In, Condenser for Refrigerator/Freezer | 1 | 12 | 3046392 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Convection Oven, Single | 1 | 3 | 3147196 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Steamer, Freestanding | 1 | 3 | 3147144 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels | 1 | 5 | 3147179 |
| E1030 | kitchen | Good | Foodservice Equipment, Walk-In, Freezer | 1 | 14 | 3046346 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Tabletop Drawers (Set of 4) | 1 | 5 | 3147138 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Dairy Cooler/Wells | 1 | 5 | 3147141 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels | 1 | 5 | 3147153 |
| E1030 | kitchen | Good | Foodservice Equipment, Walk-In, Refrigerator | 1 | 14 | 3046347 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Convection Oven, Single | 1 | 3 | 3147155 |
| E2010 | Classrooms | Fair | Casework, Cabinetry Economy | 308 LF | 3 | 3046416 |
| Special Construction & Demo | | | | | | |
| F1020 | Site | Good | Shed/Gazebo/Shade Structure, Wood or Metal-Framed, Basic/Minimal | 100 SF | 20 | 3147147 |
| Pedestrian Plazas & Walkways | | | | | | |
| G2020 | Parking lot | Failed | Parking Lots, Pavement, Asphalt, Seal & Stripe | 18,510 SF | 0 | 3046384 |
| G2020 | Parking lot | Fair | Parking Lots, Pavement, Asphalt, Mill & Overlay | 18,510 SF | 4 | 3046386 |
| G2030 | Site | Good | Sidewalk, Concrete, Large Areas | 685 SF | 43 | 3046388 |
| G2030 | Building exterior | Fair | Site Stairs & Ramps, Steps, Concrete (per LF of nosing) | 142 LF | 4 | 3046406 |
| Athletic, Recreational & Playfield Areas | | | | | | |
| G2050 | Site | Fair | Play Structure, Multipurpose, Small | 1 | 6 | 3147204 |
| G2050 | Site | Fair | Sports Apparatus, Basketball, Backboard/Rim/Pole | 2 | 10 | 3147171 |
| G2050 | Site | Fair | Play Structure, Multipurpose, Large | 1 | 6 | 3147161 |
| G2050 | Site | Fair | Play Structure, Swing Set, 4 Seats | 1 | 6 | 3147169 |
| G2050 | Site | Fair | Play Structure, Multipurpose, Large | 1 | 6 | 3147206 |
| G2050 | Site | Fair | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement, Mill & Overlay | 34,125 SF | 4 | 3046387 |
| G2050 | Site | Fair | Play Structure, Multipurpose, Small | 1 | 10 | 3147203 |
| G2050 | Site | Fair | Play Structure, Multipurpose, Very Small | 1 | 10 | 3147143 |
| G2050 | Site | Fair | Play Structure, Multipurpose, Large | 1 | 6 | 3147208 |
| G2050 | Site | Fair | Playfield Surfaces, Rubber, Small Areas | 10,000 SF | 6 | 3046439 |
| G2050 | Site | Fair | Playfield Surfaces, Rubber, Small Areas | 8,220 SF | 6 | 3046438 |

Component Condition Report | George Mason Elementary School Campus

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|-------------------|-------------------|-----------|---|----------|-----|---------|
| G2050 | Site | Fair | Play Structure, Swing Set, 4 Seats | 1 | 6 | 3046437 |
| G2050 | Site | Fair | Play Structure, Multipurpose, Small | 1 | 10 | 3147134 |
| Sitework | | | | | | |
| G2060 | Site | Fair | Park Bench, Metal Powder-Coated | 7 | 10 | 3147173 |
| G2060 | Site | Fair | Picnic Table, Metal Powder-Coated | 3 | 10 | 3147167 |
| G2060 | Parking lot | Fair | Signage, Exterior/Site, Guide & Directional Pole-Mounted, Replace/Install | 1 | 13 | 3046385 |
| G4050 | Building Exterior | Fair | Exterior Fixture w/ Lamp, any type, w/ LED Replacement | 15 | 4 | 3046400 |
| G4050 | Building Exterior | Fair | Exterior Fixture w/ Lamp, any type, w/ LED Replacement | 8 | 3 | 3046404 |
| G4050 | Building Exterior | Fair | Exterior Fixture w/ Lamp, any type, w/ LED Replacement | 8 | 13 | 3046403 |
| Follow-up Studies | | | | | | |
| P2030 | | NA | Engineering Study, Structural, General Design, Basement Mechanical Room | 1 | 0 | 3460740 |

Appendix F:

Replacement Reserves

Replacement Reserves Report

12/15/2021

| Location | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | Total Escalated Estimate |
|--|------------------|------------|-----------------|--------------------|------------------|------------------|------------------|--------------------|------------------|------------------|--------------------|-----------------|------------------|------------------|-----------------|------------------|-----------------|-----------------|------------------|------------------|--------------------|--------------------------|
| George Mason Elementary School Campus | \$240,030 | \$0 | \$11,903 | \$1,787,204 | \$645,725 | \$450,311 | \$708,933 | \$1,078,237 | \$280,387 | \$156,573 | \$1,304,573 | \$22,978 | \$563,004 | \$310,209 | \$74,041 | \$148,086 | \$19,898 | \$59,089 | \$432,771 | \$345,509 | \$1,844,165 | \$10,483,626 |
| George Mason Elementary School Campus / George Mason Elementary School | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Grand Total | \$240,030 | \$0 | \$11,903 | \$1,787,204 | \$645,725 | \$450,311 | \$708,933 | \$1,078,237 | \$280,387 | \$156,573 | \$1,304,573 | \$22,978 | \$563,004 | \$310,209 | \$74,041 | \$148,086 | \$19,898 | \$59,089 | \$432,771 | \$345,509 | \$1,844,165 | \$10,483,626 |

George Mason Elementary School Campus

| Uniformat Code | Location Description | ID | Cost Description | Lifespan (EUL) | EAge | RUL | Quantity | Unit | Unit Cost * | Subtotal | 2021 | 2022 | 2023 | 2024 | 2025 | 2026 | 2027 | 2028 | 2029 | 2030 | 2031 | 2032 | 2033 | 2034 | 2035 | 2036 | 2037 | 2038 | 2039 | 2040 | 2041 | Deficiency Repair Estimate |
|----------------|---------------------------------------|---------|---|----------------|------|-----|----------|-------|-------------|-------------|-----------|-----------|------|---------|-----------|-----------|-----------|------|----------|------|----------|------|----------|----------|---------|---------|----------|------|-----------|-----------|----------|----------------------------|
| A2010 | George Mason Elementary School Campus | 3461117 | Basement Wall, any type, Waterproofing of Exterior Face, Replace | | 0 | 0 | 0 | 7500 | SF | \$27.00 | \$202,500 | \$202,500 | | | | | | | | | | | | | | | | | | | | \$202,500 |
| B1080 | Front stairs | 3046432 | Stair Treads, Raised Rubber Tile, Replace | | 18 | 18 | 0 | 900 | SF | \$10.00 | \$9,000 | \$9,000 | | | | | | | | | | | | | | | | | | \$9,000 | | \$18,000 |
| B1080 | Rear stairs | 3147170 | Stair Treads, Raised Rubber Tile, Replace | | 18 | 15 | 3 | 300 | SF | \$10.00 | \$3,000 | | | | \$3,000 | | | | | | | | | | | | | | | | | \$3,000 |
| B1080 | Common areas | 3046407 | Stair Treads, Raised Rubber Tile, Replace | | 18 | 3 | 15 | 300 | SF | \$10.00 | \$3,000 | | | | | | | | | | | | | | | \$3,000 | | | | | | \$3,000 |
| B1080 | Site | 3147197 | Stair/Ramp Rails, Metal, Refinish | | 10 | 7 | 3 | 225 | LF | \$1.50 | \$338 | | | | | \$338 | | | | | | | | \$338 | | | | | | | | \$675 |
| B2010 | Exterior wall | 3046374 | Exterior Walls, Brick or Brick Veneer, 1-2 Story Building, Repair/Repoint | | 0 | 0 | 0 | 400 | SF | \$33.00 | \$13,200 | \$13,200 | | | | | | | | | | | | | | | | | | | | \$13,200 |
| B2010 | Building exterior | 3046348 | Exterior Walls, any painted surface, 1-2 Story Building, Prep & Paint | | 10 | 8 | 2 | 2340 | SF | \$3.00 | \$7,020 | | | \$7,020 | | | | | | | | | \$7,020 | | | | | | | | | \$14,040 |
| B2050 | Building exterior | 3147159 | Exterior Door, Wood, Solid-Core Decorative High-End w/ Glazing, Replace | | 25 | 23 | 2 | 2 | EA | \$2,100.00 | \$4,200 | | | \$4,200 | | | | | | | | | | | | | | | | | | \$4,200 |
| B2050 | Building exterior | 3046376 | Exterior Door, Steel, Standard, Replace | | 40 | 21 | 19 | 4 | EA | \$600.00 | \$2,400 | | | | | | | | | | | | | | | | | | | \$2,400 | | \$2,400 |
| B2050 | Building exterior | 3046377 | Exterior Door, Wood, Solid-Core Decorative High-End w/ Glazing, Replace | | 25 | 5 | 20 | 2 | EA | \$2,100.00 | \$4,200 | | | | | | | | | | | | | | | | | | | | \$4,200 | \$4,200 |
| B3010 | Gym roof | 3046349 | Roofing, Metal, Replace | | 40 | 21 | 19 | 1200 | SF | \$13.00 | \$15,600 | | | | | | | | | | | | | | | | | | | \$15,600 | | \$15,600 |
| B3010 | Roof | 3046352 | Roofing, Single-Ply Membrane, TPO/PVC, Replace | | 20 | 17 | 3 | 41000 | SF | \$17.00 | \$697,000 | | | | | \$697,000 | | | | | | | | | | | | | | | | \$697,000 |
| B3010 | Gym roof | 3046351 | Roofing, Single-Ply Membrane, TPO/PVC, Replace | | 20 | 7 | 13 | 4500 | SF | \$17.00 | \$76,500 | | | | | | | | | | | | | \$76,500 | | | | | | | | \$76,500 |
| B3020 | Roof | 3147137 | Roof Appurtenances, Gutters & Downspouts, Aluminum w/ Fittings, Replace | | 20 | 15 | 5 | 514 | LF | \$9.00 | \$4,626 | | | | | \$4,626 | | | | | | | | | | | | | | | | \$4,626 |
| B3020 | Roof | 3046436 | Roof Appurtenances, Gutters & Downspouts, Aluminum w/ Fittings, Replace | | 20 | 6 | 14 | 150 | LF | \$9.00 | \$1,350 | | | | | | | | | | | | | | \$1,350 | | | | | | | \$1,350 |
| C1030 | Throughout building | 3147186 | Door Hardware, School, per Door, Replace | | 30 | 10 | 20 | 98 | EA | \$400.00 | \$39,200 | | | | | | | | | | | | | | | | | | | | \$39,200 | \$39,200 |
| C1070 | Common areas | 3046429 | Suspended Ceilings, Acoustical Tile (ACT), Replace | | 25 | 21 | 4 | 35700 | SF | \$3.50 | \$124,950 | | | | | | \$124,950 | | | | | | | | | | | | | | | \$124,950 |
| C1090 | Restrooms | 3147178 | Toilet Partitions, Metal, Replace | | 20 | 10 | 10 | 22 | EA | \$850.00 | \$18,700 | | | | | | | | | | | | | | | | | | | | | \$18,700 |
| C1090 | Throughout building | 3147135 | Lockers, Steel-Baked Enamel, 12" W x 15" D x 72" H, Replace | | 20 | 15 | 5 | 200 | EA | \$500.00 | \$100,000 | | | | | \$100,000 | | | | | | | | | | | | | | | | \$100,000 |
| C2010 | Throughout building | 3046423 | Wall Finishes, any surface, Prep & Paint | | 10 | 5 | 5 | 53481 | SF | \$1.50 | \$80,222 | | | | | | \$80,222 | | | | | | | | | | \$80,222 | | | | | \$160,443 |
| C2030 | Restrooms | 3046419 | Flooring, Ceramic Tile, Replace | | 40 | 21 | 19 | 750 | SF | \$18.00 | \$13,500 | | | | | | | | | | | | | | | | | | | \$13,500 | | \$13,500 |
| C2030 | Throughout building | 3147175 | Flooring, Vinyl Tile (VCT), Replace | | 15 | 12 | 3 | 20000 | SF | \$5.00 | \$100,000 | | | | \$100,000 | | | | | | | | | | | | | | \$100,000 | | | \$200,000 |
| C2030 | Throughout building | 3147146 | Flooring, Luxury Vinyl Tile (LVT), Replace | | 15 | 3 | 12 | 7000 | SF | \$7.50 | \$52,500 | | | | | | | | | | | | | \$52,500 | | | | | | | | \$52,500 |
| C2030 | Common areas | 3046420 | Flooring, Carpet, Commercial Standard, Replace | | 10 | 7 | 3 | 3000 | SF | \$7.50 | \$22,500 | | | | \$22,500 | | | | | | | | | \$22,500 | | | | | | | | \$45,000 |
| C2030 | Throughout building | 3147162 | Flooring, Carpet, Commercial Tile, Replace | | 10 | 3 | 7 | 5500 | SF | \$6.50 | \$35,750 | | | | | | | | \$35,750 | | | | | | | | \$35,750 | | | | | \$71,500 |
| C2030 | Gym | 3046421 | Flooring, Maple Sports Floor, Replace | | 30 | 21 | 9 | 4700 | SF | \$12.00 | \$56,400 | | | | | | | | | | \$56,400 | | | | | | | | | | | \$56,400 |
| D1010 | Elevator | 3147136 | Passenger Elevator, Hydraulic, 2 Floors, Renovate | | 30 | 27 | 3 | 1 | EA | \$60,000.00 | \$60,000 | | | | \$60,000 | | | | | | | | | | | | | | | | | \$60,000 |
| D1010 | Elevator | 3046355 | Elevator Cab Finishes, Economy, Replace | | 10 | 7 | 3 | 1 | EA | \$3,000.00 | \$3,000 | | | | \$3,000 | | | | | | | | | \$3,000 | | | | | | | | \$6,000 |
| D1010 | Elevator | 3147160 | Elevator Controls, Automatic, 1 Car, Replace | | 20 | 17 | 3 | 1 | EA | \$5,000.00 | \$5,000 | | | | \$5,000 | | | | | | | | | | | | | | | | | \$5,000 |
| D2010 | Boiler room | 3147181 | Water Heater, Gas, Commercial (200 MBH), Replace | | 20 | 9 | 11 | 1 | EA | \$16,600.00 | \$16,600 | | | | | | | | | | | | \$16,600 | | | | | | | | | \$16,600 |
| D2010 | Kitchen | 3046356 | Water Heater, Gas, Commercial (125 MBH), Replace | | 20 | 7 | 13 | 1 | EA | \$12,400.00 | \$12,400 | | | | | | | | | | | | | \$12,400 | | | | | | | | \$12,400 |
| D2010 | Electrical Room | 3046357 | Water Heater, Electric, Commercial (12 kW), Replace | | 20 | 4 | 16 | 1 | EA | \$12,400.00 | \$12,400 | | | | | | | | | | | | | | | | \$12,400 | | | | | \$12,400 |
| D2010 | Throughout building | 3147139 | Plumbing System, Supply & Sanitary, High Density (excludes fixtures), Replace | | 40 | 20 | 20 | 50935 | SF | \$14.00 | \$713,090 | | | | | | | | | | | | | | | | | | | \$713,090 | | \$713,090 |
| D2010 | Boiler room | 3147205 | Backflow Preventer, Domestic Water, Replace | | 30 | 10 | 20 | 1 | EA | \$1,100.00 | \$1,100 | | | | | | | | | | | | | | | | | | | \$1,100 | | \$1,100 |
| D2010 | Electrical room | 3147180 | Backflow Preventer, Domestic Water, Replace | | 30 | 10 | 20 | 1 | EA | \$1,400.00 | \$1,400 | | | | | | | | | | | | | | | | | | | \$1,400 | | \$1,400 |
| D2010 | Main corridor | 3147184 | Drinking Fountain, Floor-Mounted, Interior Basic, Replace | | 15 | 12 | 3 | 1 | EA | \$900.00 | \$900 | | | | \$900 | | | | | | | | | | | | | | \$900 | | | \$1,800 |
| D2010 | Throughout building | 3147183 | Drinking Fountain, Wall-Mounted, Single-Level, Replace | | 15 | 10 | 5 | 6 | EA | \$1,200.00 | \$7,200 | | | | | \$7,200 | | | | | | | | | | | | | | \$7,200 | | \$14,400 |
| D2010 | Restrooms | 3046410 | Urinal, Waterless, Replace | | 30 | 21 | 9 | 7 | EA | \$600.00 | \$4,200 | | | | | | | | | | \$4,200 | | | | | | | | | | | \$4,200 |
| D2010 | Restrooms | 3046409 | Toilet, Commercial Water Closet, Replace | | 30 | 21 | 9 | 38 | EA | \$1,300.00 | \$49,400 | | | | | | | | | | \$49,400 | | | | | | | | | | | \$49,400 |
| D2010 | Restrooms | 3046411 | Sink/Lavatory, Trough Style, Solid Surface, Replace | | 30 | 21 | 9 | 4 | EA | \$2,500.00 | \$10,000 | | | | | | | | | | \$10,000 | | | | | | | | | | | \$10,000 |
| D2010 | Restrooms | 3147182 | Sink/Lavatory, Wall-Hung, Vitreous China, Replace | | 30 | 18 | 12 | 19 | EA | \$1,500.00 | \$28,500 | | | | | | | | | | | | \$28,500 | | | | | | | | | \$28,500 |
| D2010 | Throughout building | 3147207 | Sink/Lavatory, Service Sink, Floor, Replace | | 35 | 21 | 14 | 2 | EA | \$800.00 | \$1,600 | | | | | | | | | | | | | \$1,600 | | | | | | | | \$1,600 |
| D2010 | Throughout building | 3147152 | Sink/Lavatory, Vanity Top, Stainless Steel, Replace | | 30 | 15 | 15 | 2 | EA | \$1,200.00 | \$2,400 | | | | | | | | | | | | | | | \$2,400 | | | | | | \$2,400 |
| D2010 | Utility closet | 3147177 | Sink/Lavatory, Vanity Top, Solid Surface or Vitreous China, Replace | | 30 | 15 | 15 | 1 | EA | \$1,100.00 | \$1,100 | | | | | | | | | | | | | | | | \$1,100 | | | | | \$1,100 |
| D2010 | Kitchen | 3147142 | Sink/Lavatory, Commercial Kitchen, 3-Bowl, Replace | | 30 | 10 | 20 | 1 | EA | \$2,500.00 | \$2,500 | | | | | | | | | | | | | | | | | | | \$2,500 | | \$2,500 |
| D2020 | Boiler room | 3147149 | Pump, Sewage Ejector, Replace | | 15 | 10 | 5 | 1 | EA | \$3,280.00 | \$3,280 | | | | | \$3,280 | | | | | | | | | | | | | | \$3,280 | | \$6,560 |

Appendix G:

Equipment Inventory List

| | | | | | | | | | | | | | |
|---------------|---------|--------|--------------------------------|---|----------|---------------------------------------|-------------------|-----------------|----------------------|---------------|--------------|----------|-----|
| | | | | | | | | | | | | | |
| D10 Conveying | | | | | | | | | | | | | |
| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
| 1 | 3147160 | D1010 | Elevator Controls | Automatic, 1 Car | | George Mason Elementary School Campus | Elevator | Not found | Not found | Not found | 1977 | 01032587 | |
| 2 | 3147136 | D1010 | Passenger Elevator | Hydraulic, 2 Floors | 3500 LB | George Mason Elementary School Campus | Elevator | Not found | Not found | Not found | 1977 | 01032588 | |
| D20 Plumbing | | | | | | | | | | | | | |
| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
| 1 | 3046357 | D2010 | Water Heater | Electric, Commercial (12 kW) | 50 GAL | George Mason Elementary School Campus | Electrical Room | A. O. Smith | DRE 52 100 | 1751108634457 | 2017 | 01032585 | |
| 2 | 3046356 | D2010 | Water Heater | Gas, Commercial (125 MBH) | 80 GAL | George Mason Elementary School Campus | Kitchen | A. O. Smith | DRE 80 100 | 1413M001264 | 2014 | 01032603 | |
| 3 | 3147181 | D2010 | Water Heater | Gas, Commercial (200 MBH) | 118 GAL | George Mason Elementary School Campus | Boiler room | A. O. Smith | BTR 199 118 | 1131M000063 | 2012 | 01032607 | |
| 4 | 3147205 | D2010 | Backflow Preventer | Domestic Water | .75 IN | George Mason Elementary School Campus | Boiler room | Watts Regulator | Not found | 186791 | 2011 | 01032608 | |
| 5 | 3147180 | D2010 | Backflow Preventer | Domestic Water | 1 IN | George Mason Elementary School Campus | Electrical room | Watts Regulator | Not found | 28908 | 2011 | 01032582 | |
| 6 | 3147149 | D2020 | Pump | Sewage Ejector | 3 HP | George Mason Elementary School Campus | Boiler room | | | | 2011 | 01032606 | |
| 7 | 3147201 | D2020 | Pump | Sewage Ejector | 3 HP | George Mason Elementary School Campus | Boiler room | | | | 2011 | 01032605 | |
| 8 | 3147191 | D2030 | Pump | Sump | 3 HP | George Mason Elementary School Campus | Electrical room | Inaccessible | Inaccessible | Inaccessible | 2006 | 01032583 | |
| D30 HVAC | | | | | | | | | | | | | |
| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
| 1 | 3147164 | D3010 | Storage Tank | Fuel | 150 GAL | George Mason Elementary School Campus | Site | MGS | Not found | B494209 | 2004 | 01032578 | |
| 2 | 3046413 | D3020 | Boiler | Gas, HVAC | 1000 MBH | George Mason Elementary School Campus | Boiler Room | FULTON | PHW-1000 | 94246 | 2003 | 01032611 | |
| 3 | 3046414 | D3020 | Boiler | Gas, HVAC | 1000 MBH | George Mason Elementary School Campus | Boiler Room | FULTON | PHW-1000 | 94249 | 2003 | 01032610 | |
| 4 | 3046405 | D3020 | Furnace [ERU-1] | Gas | 100 MBH | George Mason Elementary School Campus | Roof | Greenheck | ERCH-20-30L-7P-16-01 | 135B2667 1403 | 2014 | 01032569 | |
| 5 | 3147151 | D3020 | Boiler Supplemental Components | Expansion Tank | 50 GAL | George Mason Elementary School Campus | Boiler room | Amtrol | Not found | 119825 | 2003 | 01032609 | |
| 6 | 3046415 | D3030 | Chiller | Air-Cooled | 90 TON | George Mason Elementary School Campus | Building Exterior | CARRIER | 30GB-090-550 | 1592F95217 | 1992 | 01032576 | |
| 7 | 3046394 | D3030 | Heat Pump | Variable Refrigerant Volume (VRV), 12 TON | 12 TON | George Mason Elementary School Campus | Roof | Mitsubishi | PURY-P144TKMU-A | 34W00738 | 2014 | 01032568 | |

| | | | | | | | | | | | | | |
|----|---------|-------|-----------------|---|----------|---------------------------------------|-----------------|--------------------|------------------|------------------|------|----------|----|
| 8 | 3046391 | D3030 | Split System | Condensing Unit/Heat Pump | 1.5 TON | George Mason Elementary School Campus | Roof | Goodman | GSX140181LC | 1807330841 | 2018 | 01032554 | |
| 9 | 3147150 | D3030 | Split System | Condensing Unit/Heat Pump | 2.5 TON | George Mason Elementary School Campus | Site | Carrier | 38YCC030300 | 2499E28020 | 2000 | 01032580 | |
| 10 | 3046390 | D3030 | Split System | Condensing Unit/Heat Pump | 1.5 TON | George Mason Elementary School Campus | Roof | Goodman | GSX140181LC | 1807330842 | 2018 | 01032560 | |
| 11 | 3147192 | D3030 | Split System | Condensing Unit/Heat Pump | 1 TON | George Mason Elementary School Campus | Roof | TRANE | TTB012C100A2 | 32150D05F | 2003 | 01032566 | |
| 12 | 3147176 | D3030 | Split System | Fan Coil Unit, DX | 2.5 TON | George Mason Elementary School Campus | Storage closet | Radco | FB4ANF030 | 4097A18829 | 1997 | 01032581 | |
| 13 | 3046426 | D3030 | Unit Ventilator | approx/nominal 2 Ton | 0 CFM | George Mason Elementary School Campus | Classrooms | undetermined | undetermined | undetermined | 1992 | | 29 |
| 14 | 3046412 | D3050 | Pump | Distribution, HVAC Chilled or Condenser Water | 15 HP | George Mason Elementary School Campus | Electrical Room | No tag/plate found | EM2333T | C0305300032 | 2003 | 01032613 | |
| 15 | 3147190 | D3050 | Pump | Distribution, HVAC Chilled or Condenser Water | 15 HP | George Mason Elementary School Campus | Electrical room | Baldor | EM2333T | C0305300027 | 2003 | 01032574 | |
| 16 | 3147198 | D3050 | Pump | Distribution, HVAC Heating Water | 0 HP | George Mason Elementary School Campus | Boiler room | No tag/plate found | M3774T | Illegible | 2003 | 01032616 | |
| 17 | 3046408 | D3050 | Pump | Distribution, HVAC Heating Water | 10 HP | George Mason Elementary School Campus | Boiler Room | BALDOR (motor) | M3774T | F0307076306 | 2003 | 01032575 | |
| 18 | 3046367 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted | 12.5 TON | George Mason Elementary School Campus | Roof | Trane | YSD150F3RHA0003D | 142210457D | 2014 | 01032557 | |
| 19 | 3147202 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted | 12.5 TON | George Mason Elementary School Campus | Roof | Trane | YSD150F3RHA0003D | 142310223D | 2014 | 01032559 | |
| 20 | 3046365 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted | 2 TON | George Mason Elementary School Campus | Roof | AAON | RK-02-2-E0-312 | 200307-AKGA50548 | 2003 | 01032562 | |
| 21 | 3046360 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted | 2 TON | George Mason Elementary School Campus | Roof | AAON | RK-02-2-E0-312 | 200307-AKGA50549 | 2003 | 01032563 | |
| 22 | 3046362 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted, 4 TON | 4 TON | George Mason Elementary School Campus | Roof | AAON | RK-04-2-E0-322 | 200307-AKGC50547 | 2003 | 01032567 | |
| 23 | 3147166 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted, 6 to 7.5 TON | 6 TON | George Mason Elementary School Campus | Roof | AAON, Inc. | RK-06-2-EO-322 | 200307-AKGE50546 | 2004 | 01032555 | |
| 24 | 3046363 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted, 6 to 7.5 TON | 6 TON | George Mason Elementary School Campus | Roof | AAON | RK-06-2-E0-322 | 200307-AKGC50543 | 2003 | 01032564 | |
| 25 | 3046359 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted, 6 to 7.5 TON | 6 TON | George Mason Elementary School Campus | Roof | AAON | RK-06-2-E0-322 | 200307-AKGC50544 | 2003 | 01032565 | |
| 26 | 3147157 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted, 6 to 7.5 TON | 6 TON | George Mason Elementary School Campus | Roof | AAON, Inc. | RK-06-2-EO-322 | 200307-AKGE50545 | 2003 | 01032561 | |
| 27 | 3046358 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted, 8 to 10 TON | 8 TON | George Mason Elementary School Campus | Gymnasium Roof | AAON | RK-08-2-E0-222 | 200208-AKG439609 | 2003 | 01032571 | |

| | | | | | | | | | | | | | |
|----------------------------------|---------|--------|---------------------------|--|----------|---------------------------------------|---------------------|--------------------|--------------------|--------------------|--------------|----------|-----|
| 28 | 3046368 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted, 8 to 10 TON | 8 TON | George Mason Elementary School Campus | Gymnasium Roof | AAON | RK-08-2-E0-222 | 200208-AKG439607 | 2003 | 01032570 | |
| 29 | 3046361 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted, 8 to 10 TON | 8 TON | George Mason Elementary School Campus | Gymnasium Roof | AAON | RK-08-2-E0-222 | 200208-AKG439610 | 2003 | 01032572 | |
| 30 | 3046369 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted, 8 to 10 TON | 8 TON | George Mason Elementary School Campus | Gymnasium Roof | AAON | RK-08-2-E0-222 | 200208-AKG439608 | 2003 | 01032573 | |
| 31 | 3046427 | D3060 | Exhaust Fan | Centrifugal, 12" Damper | 750 CFM | George Mason Elementary School Campus | Roof | No tag/plate found | No tag/plate found | No tag/plate found | 2008 | | 12 |
| 32 | 3046428 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 24" Damper | 3500 CFM | George Mason Elementary School Campus | Roof | No tag/plate found | No tag/plate found | No tag/plate found | 2014 | | 4 |
| 33 | 3147199 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 24" Damper | 2100 CFM | George Mason Elementary School Campus | Roof | | | | 2015 | | 2 |
| D40 Fire Protection | | | | | | | | | | | | | |
| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
| 1 | 3147189 | D4030 | Fire Extinguisher | Type ABC, up to 20 LB | | George Mason Elementary School Campus | Throughout building | | | | 2021 | | 15 |
| 2 | 3147194 | D4030 | Fire Extinguisher | Wet Chemical/CO2 | | George Mason Elementary School Campus | Kitchen | | | | 2021 | | |
| D50 Electrical | | | | | | | | | | | | | |
| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
| 1 | 3046344 | D5010 | Generator | Diesel | 150 KW | George Mason Elementary School Campus | Building Exterior | KOHLER | 150RE0ZJB | 766821 | 2003 | 01032577 | |
| 2 | 3046343 | D5010 | Automatic Transfer Switch | ATS | 600 AMP | George Mason Elementary School Campus | Electrical Room | Kohler | KCT-ACTA-0600S | K0766335 | 2003 | | |
| 3 | 3046399 | D5020 | Switchboard | 120/208 V | 2500 AMP | George Mason Elementary School Campus | Electrical Room | SIEMENS | N/A | 17-79715-A00020-01 | 2003 | 01032586 | |
| 4 | 3147158 | D5030 | Variable Frequency Drive | VFD, by HP of Motor | 10 HP | George Mason Elementary School Campus | Boiler room | Cutler-Hammer | HV9000 | Not found | 2003 | 01032614 | |
| 5 | 3147188 | D5030 | Variable Frequency Drive | VFD, by HP of Motor | 10 HP | George Mason Elementary School Campus | Boiler room | Cutler-Hammer | HV9000 | Not found | 2003 | 01032612 | |
| 6 | 3147140 | D5040 | Emergency & Exit Lighting | Exit Sign, LED | | George Mason Elementary School Campus | Throughout building | | | | 2011 | | 15 |
| 7 | 3046402 | D5040 | Special Fixture w/ Lamp | any type Interior High Bay, w/ LED Replacement | 0 W | George Mason Elementary School Campus | Gymnasium | | | | 1997 | | 24 |
| D70 Electronic Safety & Security | | | | | | | | | | | | | |
| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
| 1 | 3046382 | D7050 | Fire Alarm Panel | Fully Addressable | 0 | George Mason Elementary School Campus | Main Office | HONEYWELL | ESL 1500 | N/A | 2014 | 01032579 | |
| E10 Equipment | | | | | | | | | | | | | |
| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
| 1 | 3147196 | E1030 | Foodservice Equipment | Convection Oven, Single | | George Mason Elementary School Campus | Kitchen | Inaccessible | Inaccessible | Inaccessible | 2011 | 01032598 | |

