

FACILITY CONDITION ASSESSMENT

prepared for

Ann Arbor Public Schools
2555 South State Street
Ann Arbor, Michigan 48104
Jim Vibbart



PREPARED BY:

EMG

10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.emgcorp.com

EMG CONTACT:

Andrew Hupp
Program Manager
800.733.0660 x6632
ahupp@emgcorp.com

EMG PROJECT #:

129010.18R000-005.354

DATE OF REPORT:

March 19, 2018

ONSITE DATE:

March 19-20, 2018

FACILITY CONDITION ASSESSMENT

OF

ALLEN ELEMENTARY SCHOOL
2560 TOWNER BOULEVARD
ANN ARBOR, MICHIGAN 48104

Immediate Repairs Report

Allen Elementary

6/28/2018



EMG Renamed Item Number	Location Description	ID	Cost Description	Quantity	Unit	Unit Cost *	Subtotal	Repair Estimate *	Deficiency
7	Site	882645	Parking Lots, Asphalt Pavement, Cut & Patch	2500	SF	\$5.70	\$14,261	\$14,261	\$14,261
11	Restrooms	882586	ADA, Restroom, Lavatory Pipe Wraps, Install	1	EA	\$80.00	\$80	\$80	\$80
	Site	958679	Davis Bacon Prevailing Wages, Surcharge for Prevailing Wages, 10% surcharge for prevailing wages	40396.52	LS	\$1.15	\$46,456	\$46,456	\$46,456
Immediate Repairs Total									\$60,797

* Location Factor (1.0) included in totals.

EMG Renamed Item Number	Location Description	ID	Cost Description	Lifespan (EUL)	E	Age	RUL	Quantity	Unit	Unit Cost	w/ Markup	Subtotal	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	RRR_Row	GrandTotalLabel	
	Site	958679	Davis Bacon Prevailing Wages, Surcharge for Prevailing Wages, 10% surcharge for prevailing wages	1	1	0		40396.52	LS	\$1.00	\$1.15	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$46,456	\$929,120
Totals, Unescalated													\$60,797	\$479,549	\$780,896	\$122,079	\$129,857	\$337,805	\$88,443	\$269,856	\$118,434	\$112,307	\$614,352	\$398,070	\$872,218	\$249,929	\$1,132,646	\$723,072	\$104,009	\$81,392	\$67,114	\$369,464	\$7,112,287		
Totals, Escalated (3.0% inflation, compounded annually)													\$60,797	\$493,936	\$828,452	\$133,399	\$146,155	\$391,608	\$105,606	\$331,889	\$150,029	\$146,535	\$825,638	\$551,022	\$1,243,575	\$367,028	\$1,713,228	\$1,126,522	\$166,904	\$134,528	\$114,256	\$647,858	\$9,678,964		

* Markup/LocationFactor (1.0) has been included in unit costs. Markup includes a and 15% Ann Arbor Premium factors applied to the location adjusted unit cost.

TABLE OF CONTENTS

1. Executive Summary	1
1.1. Property Information and General Physical Condition	1
1.2. Key Findings	2
1.3. Facility Condition Index (FCI)	2
2. Building Structure	4
A10 Foundations	4
B10 Superstructure	4
3. Building Envelope	6
B20 Exterior Vertical Enclosures	6
4. Interiors	10
C10 Interior Construction	10
5. Services (MEPF)	12
D10 Conveying Systems	12
D20 Plumbing	13
D30 Building Heating, Ventilating, and Air Conditioning (HVAC)	14
D40 Fire Protection	17
D50 Electrical	18
D60 Communications	19
D70 Electronic Safety and Security	19
6. Equipment & Furnishings	20
E10 Equipment	20
7. Sitework	21
G20 Site Improvements	21
G30 Liquid & Gas Site Utilities	24
G40 Electrical Site Improvements	24
8. Ancillary Structures	26
9. Opinions of Probable Costs	27
9.1. Methodology	27
9.2. Immediate Repairs	27
9.3. Replacement Reserves	27
10. Purpose and Scope	28
10.1. Purpose	28
10.2. Scope	29
11. Accessibility and Property Research	30
11.1. ADA Accessibility	30
12. Certification	31
13. Appendices	32

1. Executive Summary

1.1. Property Information and General Physical Condition

The property information is summarized in the table below. More detailed descriptions may be found in the various sections of the report and in the Appendices.

Property Information	
Address:	2560 Towner Boulevard, Ann Arbor, Washtenaw County, Michigan 48104
Year Constructed/Renovated:	1961, Phase I Multiple reported additions to building; most recent Phase in 1991 Renovated 2016-2017 following significant flooding
Current Occupants:	Ann Arbor Public Schools
Percent Utilization:	100%
Management Point of Contact:	Mr. Jim Vibbart, Ann Arbor Public Schools vibbartj@aaps.k12.mi.us
Property Type:	Public School
Site Area:	10.5 acres
Building Area:	65,388 SF
Number of Buildings:	1
Number of Stories:	1 - 2
Parking Type and Number of Spaces:	73 spaces in open lots
Building Construction:	Masonry bearing walls and wood-framed roofs.
Roof Construction:	Hip and mansard roofs with standing seam metal and asphalt shingles. Flat roofs with single-ply EPDM membrane.
Exterior Finishes:	Brick Veneer
Heating, Ventilation and Air Conditioning:	Central system with boilers feeding hydronic fin tube radiators and cabinets, and classroom unit ventilators. Individual rooftop package units and condensing units. Supplemental components: ductless heat pump split-systems and ductless split system condensing units.
Fire and Life/Safety:	Limited fire sprinklers, hydrants, smoke detectors, alarms, strobes, extinguishers, pull stations, alarm panel, and exit signs.
ADA :	This building does not have any major ADA issues
All 65,388 square feet of the building are occupied by a single occupant, Ann Arbor Public Schools. The spaces are mostly classrooms and other academic rooms, and supporting restrooms, administrative offices, mechanical and other utility spaces.	

Assessment Information	
Dates of Visit:	3/19/2018 and 3/20/2018
On-Site Point of Contact (POC):	Kerry Beal, Principal, Allen Elementary School
Assessment and Report Prepared by:	Justin Dunn

Assessment Information	
Reviewed by:	Al Diefert Technical Report Reviewer For Andrew Hupp Program Manager ahupp@emgcorp.com 800.733.0660 x6632

1.2. Key Findings

Site : The property's site is generally in good to fair condition, with isolated areas of damage and deterioration at the parking lots and sidewalks. The majority of other site components are in sound condition.


Architectural : The property's architectural components are generally in sound condition, with no significant deficiencies or deterioration reported or observed.

MEPF : The property's MEPF components are in generally good condition, having been largely replaced in 2017 after extensive flooding in 2016. One of the two boilers is an original 1961 unit, but is reportedly still functional.

1.3. Facility Condition Index (FCI)

FCI Analysis: Allen Elementary

Replacement Value: \$ 13,077,600; Inflation rate: 3.0%



One of the major goals of the FCA is to calculate the FCI, which gives an indication of a building's overall condition. Two FCI ratios are calculated and presented, the Current Year and Ten-Year. The Current Year FCI is the ratio of Immediate Repair Costs to the building's Current Replacement Value. Similarly, the Ten-Year FCI is the ratio of anticipated Capital Reserve Needs over the next ten years to the Current Replacement Value.

FCI Rating	Definition	Percentage Value
Good	In new or well-maintained condition, with no visual evidence of wear, soiling or other deficiencies.	0 to .05
Fair	Subjected to wear and soiling but is still in a serviceable and functioning condition.	> than .05 to .10



FCI Rating	Definition	Percentage Value
Poor	Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life.	> than .10 to .60
Very Poor	Has reached the end of its useful or serviceable life. Renewal is now necessary.	> than .60

The graphs above and tables below represent summary-level findings for the FCA. The deficiencies identified in this assessment can be combined with potential new construction requirements to develop an overall strategy that can serve as the basis for a portfolio-wide capital improvement funding strategy. Key findings from the assessment include:

KEY FINDING	METRIC
Current Year Facility Condition Index (FCI) FCI = (IR)/(CRV):	0.10%
Current Year FCI Rating:	2018
10-Year Facility Condition Index (FCI) FCI = (RR)/(CRV):	9.46%
10-Year FCI Rating:	0.09
Current Replacement Value (CRV):	\$13,077,600
Year 0 (Current Year) - Immediate Repairs (IR):	\$12,481
Years 1-10 - Replacement Reserves (RR):	\$1,224,476
Total Capital Needs:	\$1,236,957

Further detail on the specific costs that make up the Immediate Repair Costs can be found in the cost tables at the beginning of this report.

2. Building Structure

A10 Foundations

Building Foundation		
Item	Description	Condition
Foundation	Slab on grade with integral footings	Good
Basement and Crawl Space	None	--

Anticipated Lifecycle Replacements

- No components of significance

Actions/Comments:

- The foundation systems are concealed. There are no significant signs of settlement, deflection, or movement. There is no evidence of movement or water infiltration.

B10 Superstructure

B1010 Floor Construction and B1020 Roof Construction		
Item	Description	Condition
Framing / Load-Bearing Walls	Masonry walls	Good
Ground Floor	Concrete slab	Good
Upper Floor Framing	Concrete beams	Good
Upper Floor Decking	Concrete, cast-in-place	Good
Balcony Framing	--	--
Balcony Decking	None	--
Balcony Deck Toppings	None	--
Balcony Guardrails	None	--
Roof Framing	Steel beams or girders	Good
Roof Decking	Plywood or OSB	Good

Maintenance Issues					
Observation	Location	Exists at Site	Observation	Location	Exists at Site
Caulk minor cracking		<input type="checkbox"/>	Monitor cracking for growth		<input type="checkbox"/>
Other		<input type="checkbox"/>	Other		<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- No components of significance

Actions/Comments:

- The superstructure is concealed. Walls and floors appear to be plumb, level, and stable. There are no significant signs of deflection or movement.

B1080 Stairs					
Type	Description	Riser	Handrail	Balusters	Condition
Building Exterior Stairs	Wood-framed	Closed	Metal	Metal	Good
Building Interior Stairs	Steel Framed With Vinyl treads	Closed	Metal	Metal	Good

Anticipated Lifecycle Replacements:

- No components of significance

Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended.

3. Building Envelope

B20 Exterior Vertical Enclosures

B2010 Exterior Walls		
Type	Location	Condition
Primary Finish	Brick veneer	Fair
Secondary Finish	Concrete	Fair
Accented with	Metal siding	Fair
Soffits	Concealed	Fair
Building sealants	Between dissimilar materials, at joints, around windows and doors	--

Maintenance Issues					
Observation	Location	Exists at Site	Observation	Location	Exists at Site
Graffiti		<input type="checkbox"/>	Efflorescence		<input type="checkbox"/>
Other		<input type="checkbox"/>	Other		<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- No components of significance

Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance, including patching repairs, graffiti removal, and re-caulking, is highly recommended.

B2020 Exterior Windows				
Window Framing	Glazing	Location	Window Screen	Condition
Aluminum framed, operable	Double glaze	Throughout exterior walls	<input type="checkbox"/>	Fair
Curtain wall	Double glaze	Throughout exterior walls	<input type="checkbox"/>	Fair
Aluminum framed storefront	Double glaze	Entry doors	<input type="checkbox"/>	Fair

B2050 Exterior Doors		
Main Entrance Doors	Door Type	Condition
	Fully glazed, metal framed	Fair
Secondary Entrance Doors	Metal, insulated	Fair
Service Doors	Metal, insulated	Fair
Overhead Doors	None	--



Anticipated Lifecycle Replacements:

- Windows
- Curtain wall glazing
- Storefront glazing
- Exterior doors

Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

B3010 Primary Roof			
Location	Majority of roof	Finish	Single-ply membrane
Type / Geometry	Flat	Roof Age	Unknown; est. 5+ Yrs
Flashing	Membrane	Warranties	Unknown
Parapet Copings	None	Roof Drains	Internal drains
Fascia	Metal Panel	Insulation	Rigid Board
Soffits	Concealed Soffits	Skylights	No
Attics	None	Ventilation Source-1	None
Roof Condition	Fair	Ventilation Source-2	--

B3010 Secondary Roof			
Location	Above library	Finish	Asphalt shingles
Type / Geometry	Hip Roof	Roof Age	Unknown; est. 15+ Yrs
Flashing	Sheet metal	Warranties	Unknown
Parapet Copings	None	Roof Drains	Edge drainage to ground
Fascia	None	Insulation	Unknown
Soffits	None	Skylights	No
Attics	None	Ventilation Source-1	Power Vents
Roof Condition	Fair	Ventilation Source-2	--

B3010 Tertiary Roof			
Location	Above gymnasium	Finish	Asphalt shingles
Type / Geometry	Mansard Roof	Roof Age	Unknown; est. 15+ Yrs
Flashing	Sheet metal	Warranties	Unknown; any assumed to be expired
Parapet Copings	None	Roof Drains	Edge drainage to ground
Fascia	None	Insulation	Unknown
Soffits	None	Skylights	No

B3010 Tertiary Roof			
Attics	None	Ventilation Source-1	None
Roof Condition	Fair	Ventilation Source-2	--

B3010 Quaternary Roof			
Location	Above elevator shaft	Finish	Standing seam metal
Type / Geometry	Hip Roof	Roof Age	Unknown; est. 26 Yrs
Flashing	Sheet metal	Warranties	Unknown
Parapet Copings	None	Roof Drains	Edge drainage to ground
Fascia	Metal Panel	Insulation	Rigid Board
Soffits	None	Skylights	No
Attics	None	Ventilation Source-1	None
Roof Condition	Good	Ventilation Source-2	--

Maintenance Issues					
Observation	Location	Exists at Site	Observation	Location	Exists at Site
Drainage components broken/missing		<input type="checkbox"/>	Vegetation/fungal growth		<input type="checkbox"/>
Blocked Drains		<input type="checkbox"/>	Debris		<input type="checkbox"/>
Missing shingles at mansard roof	Mansard roof, southeast elevation	<input checked="" type="checkbox"/>	Other		<input type="checkbox"/>

Degradation Issues			
Observation	Exists at Site	Observation	Exists at Site
Evidence of roof leaks	<input type="checkbox"/>	Significant ponding	<input type="checkbox"/>
Excessive patching or repairs	<input type="checkbox"/>	Blistering or ridging	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- Asphalt shingles
- EPDM roof membrane
- Metal roof

Actions/Comments:

- The roof finishes vary in age. Information regarding roof warranties or bonds was not available. The roofs are maintained by an outside contractor.
- According to the POC, there are no active roof leaks. There is no evidence of active roof leaks.



- There is no evidence of roof deck or insulation deterioration. The roof substrate and insulation should be inspected during any future roof repair or replacement work.
- Roof drainage appears to be adequate. Clearing and minor repair of drain system components should be performed regularly as part of the property management's routine maintenance and operations program.
- The attics are not accessible and it could not be determined if there is moisture, water intrusion, or excessive daylight in the attics.

4. Interiors

C10 Interior Construction

C1030 Interior Doors		
Item	Type	Condition
Interior Doors	Solid core wood	Good
Door Framing	Metal	Good
Fire Doors	Yes	Good
Closet Doors	N/A	--

Maintenance Issues					
Observation	Location	Exists at Site	Observation	Location	Exists at Site
Improperly adjusted door closures		<input type="checkbox"/>	Damaged/loose door hardware		<input type="checkbox"/>
Other		<input type="checkbox"/>	Other		<input type="checkbox"/>

The following table generally describes the locations and typical conditions of the interior finishes within the facility:

Interior Finishes - ALLEN ELEMENTARY SCHOOL

Location	Finish		Quantity (SF)	Condition	Action	RUL	Est. Cost
Restrooms	Ceiling	Gypsum Board/Plaster	750	Fair	Prep & Paint	9	1,452
Restrooms	Floor	Ceramic Tile	750	Good	Replace	23	11,816
Throughout building	Wall	Concrete/Masonry	90000	Fair	Prep & Paint	5	130,590
Throughout building	Wall	Clay Brick	2000	Fair	Repoint	15	24,816
Throughout building	Floor	Carpet Standard-Commercial Medium-Traffic	6500	Good	Replace	9	47,166
Throughout building	Floor	Vinyl Tile (VCT)	50000	Good	Replace	14	240,030
Throughout building	Ceiling	Suspended Acoustical Tile (ACT)	59000	Good	Replace	19	183,549

Maintenance Issues					
Observation	Location	Exists at Site	Observation	Location	Exists at Site
Loose carpeting/flooring		<input type="checkbox"/>	Minor areas of stained ceiling tiles		<input type="checkbox"/>
Minor paint touch-up		<input type="checkbox"/>	Areas of damaged/missing baseboard		<input type="checkbox"/>
Other		<input type="checkbox"/>	Other		<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- Carpet
- Vinyl tile
- Interior paint
- Suspended acoustic ceiling tile
- Interior doors and hardware

Actions/Comments:

- The interior areas were last renovated in 2017.
- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended.

5. Services (MEPF)

See the Mechanical Equipment List in the Appendices for the quantity, manufacturer's name, model number, capacity and year of manufacturer of the major mechanical equipment, if available.

D10 Conveying Systems

D1030 Vertical Conveying (Building Elevators) – Building 1			
Manufacturer	Otis	Machinery Location	Ground floor or basement adjacent to shaft
Safety Stops	Electronic	Emergency Communication Equipment	Yes
Cab Floor Finish	Vinyl-tiled	Cab Wall Finish	Plastic-laminated wood
Cab Finish Condition	Good	Elevator Cabin Lighting	F42T8
Hydraulic Elevators	1 car at 4000 LB		
Overhead Traction Elevators	None		
Freight Elevators	None		
Machinery Condition	--	Controls Condition	--
Other Conveyances	None	Other Conveyance Condition	NA

Maintenance Issues					
Observation	Location	Exists at Site	Observation	Location	Exists at Site
Inspection certificate not available		<input type="checkbox"/>	Inspection certificate expired		<input type="checkbox"/>
Service call needed		<input type="checkbox"/>	Minor cab finish repairs		<input type="checkbox"/>
Other		<input type="checkbox"/>	Other		<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- Elevator controls
- Elevator cab finishes

Actions/Comments:

- The POC was unable to provide a key to access the elevator mechanical room. Consequently, the elevator machinery was not observed during the on-site. The interior of the elevator cab was observed.
- The elevator is reported to provide adequate service. The elevator is reportedly serviced on a routine basis. The elevator machinery and controls appear to be more than 5 years old. The elevators will require continued periodic maintenance.
- The elevator is reportedly inspected on an annual basis by the municipality. A certificate of inspection was not on display in the elevator cab, and school personnel were unable to find a copy in the office. If the inspection certificate has expired, a new inspection should be scheduled as soon as possible.
- The emergency communication equipment in the elevator cabs appears to be functional. Equipment testing is not within the scope of the work.

D20 Plumbing

D2010 Domestic Water Distribution		
Type	Description	Condition
Water Supply Piping	Copper	Fair
Water Meter Location	Vault at site	

Domestic Water Heaters or Boilers	
Components	Water Heaters
Fuel	Natural gas
Boiler or Water Heater Condition	Fair
Supplementary Storage Tanks?	No
Adequacy of Hot Water	Adequate
Adequacy of Water Pressure	Adequate

D2020 Sanitary Drainage		
Type	Description	Condition
Waste/Sewer Piping	PVC	Fair
Vent Piping	PVC	Fair

Maintenance Issues					
Observation	Location	Exists at Site	Observation	Location	Exists at Site
Hot water temperature too hot or cold		<input type="checkbox"/>	Minor or isolated leaks		<input type="checkbox"/>
Other		<input type="checkbox"/>	Other		<input type="checkbox"/>

Plumbing Systems - ALLEN ELEMENTARY SCHOOL

Location	Component	Component Description	Quantity	Unit	Condition	RUL	Est. Cost
Boiler Room A	Water Heater	80 GAL	1	EA	Fair	8	10,699
Custodial Closet	Water Heater	50 GAL	1	EA	Good	8	2,349
Restrooms	Urinal	Vitreous China	2	EA	Fair	7	2,387
Restrooms	Toilet	Flush Tank (Water Closet)	36	EA	Fair	7	37,986
Restrooms	Sink	Enameled Steel	34	EA	Fair	7	20,945
Site	Backflow Preventer	2"	1	EA	Fair	10	2,603
Throughout building	Drinking Fountain	Refrigerated	4	EA	Fair	4	5,030
Throughout building	Service Sink	Floor	3	EA	Fair	11	4,799

Anticipated Lifecycle Replacements:

- Water heaters



- Backflow preventer
- Toilets
- Urinals
- Sinks
- Service floor sinks
- Drinking fountains
- Toilet partitions

Actions/Comments:

- The plumbing systems appear to be well maintained and functioning adequately. The water pressure appears to be sufficient. No significant repair actions or short term replacement costs are required. Routine and periodic maintenance is recommended. Future lifecycle replacements of the components or systems listed above will be required.

D30 Building Heating, Ventilating, and Air Conditioning (HVAC)

Building Central Heating System	
Primary Heating System Type	Hot water boilers
Heating Fuel	Natural gas
Location of Major Equipment	Mechanical rooms
Space Served by System	Entire building

Distribution System	
HVAC Water Distribution System	Two-pipe
Air Distribution System	Constant
Location of Air Handlers	Rooftop, penthouse
Terminal Units	Unit ventilators
Quantity and Capacity of Terminal Units	Approximately 25 unit ventilators at an estimated average of 1000 CFM each
Location of Terminal Units	Adjacent to windows

Packaged, Split and Individual Units	
Primary Components	Package Units (RTUs)
Cooling (if separate from above)	performed via components above
Heating Fuel	Natural gas
Location of Equipment	Rooftop
Space Served by System	Various larger spaces (gymnasium, library, etc.)

Supplemental/Secondary Components	
Supplemental Component #1	Ductless mini-split systems

Supplemental/Secondary Components	
Location / Space Served by Ductless mini-split systems	Electrical room; assumed elevator machine room
Ductless mini-split systems Condition	Good
Supplemental Component #2	Ductless mini-split heat pump systems
Location / Space Served by Ductless mini-split heat pumps	IT/data room
Ductless mini-split heat pumps Condition	Good
Supplemental Component #3	Split system condensing units
Location / Space Served by Split system condensing units	Classrooms (cooling for unit ventilators)
Split system condensing units Condition	Good

Controls and Ventilation	
HVAC Control System	BAS, hybrid pneumatic/electronic system
HVAC Control System Condition	Fair
Building Ventilation	Roof top exhaust fans
Ventilation System Condition	Fair

Maintenance Issues					
Observation	Location	Exists at Site	Observation	Location	Exists at Site
Ductwork/grills need cleaned		<input type="checkbox"/>	Minor control adjustments needed		<input type="checkbox"/>
Leaking condensate lines		<input type="checkbox"/>	Poor mechanical area access		<input type="checkbox"/>
Other		<input type="checkbox"/>	Other		<input type="checkbox"/>

Degradation Issues			
Observation	Exists at Site	Observation	Exists at Site
Heating, Cooling or Ventilation is not adequate	<input type="checkbox"/>	Major system inefficiencies	<input type="checkbox"/>
HVAC controls pneumatic or antiquated	<input type="checkbox"/>	Obsolete refrigerants : R11, R12, R22, R123, R502	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>



Mechanical Systems - ALLEN ELEMENTARY SCHOOL

Location	Component	Component Description	Quantity	Unit	Condition	RUL	Est. Cost
Boiler Room A	Expansion Tank	200 GAL	1	EA	Fair	5	4,697
Boiler Room A	Boiler (1)	2095 MBH	1	EA	Fair	3	54,195
Boiler Room B	Distribution Pump	5 HP	1	EA	Fair	4	5,519
Boiler Room B	Boiler	2092 MBH	1	EA	Fair	5	54,195
Boiler Room B	Expansion Tank	101 to 175 GAL	1	EA	Fair	5	3,999
Boiler Room B	Distribution Pump	5 HP	1	EA	Fair	5	5,519
Penthouse level mechanical room	Air Handler	17500 CFM	1	EA	Fair	5	9,414
Roof	Condensing Unit	3 Ton	1	EA	Good	14	3,579
Roof	Condensing Unit	3 Ton	1	EA	Good	14	3,579
Roof	Condensing Unit	2 Ton	1	EA	Good	14	3,122
Roof	Condensing Unit	2 Ton	1	EA	Good	14	3,122
Roof	Condensing Unit	2 Ton	1	EA	Good	14	3,122
Roof	Condensing Unit	3 Ton	1	EA	Good	14	3,579
Roof	Condensing Unit	2 Ton	1	EA	Good	14	3,122
Roof	Ductless Split System	1.5 Ton	1	EA	Good	12	4,473
Roof	Packaged Unit (RTU)	2 Ton	1	EA	Good	14	7,258
Roof	Condensing Unit	3 Ton	1	EA	Good	14	3,579
Roof	Ductless Split System	2 Ton	1	EA	Good	14	4,473
Roof	Condensing Unit/Heat Pump	3 Ton	1	EA	Good	14	3,579
Roof	Condensing Unit	2 Ton	1	EA	Good	14	3,122
Roof	Condensing Unit	2 Ton	1	EA	Good	14	3,122
Roof	Condensing Unit	2 Ton	1	EA	Good	14	3,122
Roof	Condensing Unit	3 Ton	1	EA	Good	14	3,579
Roof	Condensing Unit	2 Ton	1	EA	Good	14	3,122
Roof	Packaged Unit (RTU)	3 Ton	1	EA	Good	14	9,872
Roof	Packaged Unit (RTU)	4 Ton	1	EA	Good	14	10,581
Roof	Packaged Unit (RTU-8)	10 Ton	1	EA	Good	14	18,554
Roof	Condensing Unit	2 Ton	1	EA	Good	14	3,122
Roof	Packaged Unit (RTU-6)	7.5 Ton	1	EA	Good	14	14,396
Roof	Condensing Unit	3 Ton	1	EA	Good	14	3,579
Roof	Condensing Unit	2 Ton	1	EA	Good	14	3,122
Roof	Condensing Unit	2 Ton	1	EA	Good	14	3,122
Roof	Condensing Unit	2 Ton	1	EA	Good	14	3,122
Roof	Condensing Unit	3 Ton	1	EA	Good	14	3,579
Throughout building	Radiator	Hydronic, Fin Tube	175	LF	Fair	23	23,235
Throughout building	HVAC System Hydronic Piping	2-Pipe	65388	SF	Fair	15	425,022

Anticipated Lifecycle Replacements:

- Boilers
- Expansion tanks
- Air handling unit
- Distribution pumps
- Unit ventilators
- Package units
- Split system condensing units
- Ductless split system heat pumps
- Ductless split system condensing units
- Rooftop exhaust fans

Actions/Comments:

- The HVAC systems are maintained by an outside contractor. Details regarding the records of the installation, maintenance, upgrades, and replacement of the HVAC equipment at the property were not able to be verified.
- HVAC equipment varies in age.

- Boiler #1 is significantly past its EUL, as it is original the building's initial construction. However, the unit is reportedly still functional. The boiler will likely require replacement with a more modern unit within the term.
- Boiler #2 is past its EUL, but is reportedly still functional. The boiler appears to be leaking slightly, as water was observed on the floor of Mechanical Room B adjacent to the unit. The leak should be further investigated and repaired, and the boiler will likely require replacement within the term.
- The heating water distribution pumps appear to be past their EULs, but are reportedly still functional. Replacements will likely be required during the term.
- The facility HVAC appeared to be at least partially controlled using an outdated pneumatic system supplied by an air compressor. For modernization, reliability, and increased control, full conversion to a web-based direct digital control (DDC) platform is highly recommended.

D40 Fire Protection

Item	Description					
Type	Wet pipe, partial; Boiler Room B only					
Sprinkler System	None	<input type="checkbox"/>	Standpipes	<input type="checkbox"/>	Backflow Preventer	<input type="checkbox"/>
	Hose Cabinets	<input type="checkbox"/>	Fire Pumps	<input type="checkbox"/>	Siamese Connections	<input type="checkbox"/>
Sprinkler System Condition	Fair					
Fire Extinguishers	Last Service Date			Servicing Current?		
	August 2017			Yes		
Hydrant Location	Drive aisles adjacent to building					
Siamese Location	N/A					
Special Systems	Kitchen Suppression System		<input type="checkbox"/>	Computer Room Suppression System		<input type="checkbox"/>

Maintenance Issues					
Observation	Location	Exists at Site	Observation	Location	Exists at Site
Extinguisher tag expired		<input type="checkbox"/>	Riser tag expired (5 year)		<input type="checkbox"/>
Other		<input type="checkbox"/>	Other		<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- Sprinkler heads
- Fire extinguishers
- AED
- EXIT signs

Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.
- Sprinkler coverage was only observed in the mechanical space of Boiler Room B.



D50 Electrical

Distribution and Lighting			
Electrical Lines	Underground	Transformer	Pad-mounted
Main Service Size	800 Amps	Volts	277/480 Volt, three-phase
Meter and Panel Location	Main electrical room	Branch Wiring	Copper
Conduit	Metallic	Step-Down Transformers?	No
Security / Surveillance System?	Yes	Building Intercom System?	Yes
Lighting Fixtures	Generally LEDs		
Main Distribution Condition	Good		
Secondary Panel and Transformer Condition	Fair		
Lighting Condition	Good		

Building Emergency Systems			
Size	None	Fuel	--
Generator / UPS Serves	--	Tank Location	--
Testing Frequency	--	Tank Type	--
Generator / UPS Condition	--		

Maintenance Issues					
Observation	Location	Exists at Site	Observation	Location	Exists at Site
Improperly stored material		<input type="checkbox"/>	Unsecured high voltage area		<input type="checkbox"/>
Other		<input type="checkbox"/>	Other		<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- No components of significance

Actions/Comments:

- The onsite electrical systems up to the meters are owned and maintained by the respective utility company.
- The electrical service and capacity appear to be adequate for the property's demands.
- Much of the electrical equipment was reportedly replaced in 2017 after the 2016 flooding. The electrical service appears to be adequate for the facility's needs.



D60 Communications

D6060 Public Address Systems						
Item	Description					
Communication Equipment	Public Address System	<input checked="" type="checkbox"/>	Nurse Call System	<input type="checkbox"/>	Clock	<input checked="" type="checkbox"/>

D70 Electronic Safety and Security

D7010 Access Control and Intrusion Detection / D7050 Detection and Alarm						
Item	Description					
Access Control and Intrusion Detection	Exterior Camera	<input checked="" type="checkbox"/>	Interior Camera	<input checked="" type="checkbox"/>	Front Door Camera Only	<input type="checkbox"/>
	Cameras Monitored	<input checked="" type="checkbox"/>	Security Personnel On-Site	<input type="checkbox"/>	Intercom/Door Buzzer	<input checked="" type="checkbox"/>
Fire Alarm System	Central Alarm Panel	<input checked="" type="checkbox"/>	Battery-Operated Smoke Detectors	<input type="checkbox"/>	Alarm Horns	<input checked="" type="checkbox"/>
	Annunciator Panels	<input checked="" type="checkbox"/>	Hard-Wired Smoke Detectors	<input checked="" type="checkbox"/>	Strobe Light Alarms	<input checked="" type="checkbox"/>
	Pull Stations	<input checked="" type="checkbox"/>	Emergency Battery-Pack Lighting	<input checked="" type="checkbox"/>	Illuminated EXIT Signs	<input checked="" type="checkbox"/>
Fire Alarm System Condition	Fair					
Central Alarm Panel System	Location of Alarm Panel			Installation Date of Alarm Panel		
	General Office Closet			2017		

Anticipated Lifecycle Replacements:

- Central alarm panel
- Annunciator alarm panel

Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.



6. Equipment & Furnishings

E10 Equipment

The servery kitchen includes the following major appliances, fixtures, and equipment:

E1030 Commercial Kitchen Equipment		
Appliance	Comment	Condition
Refrigerators	Up-right	Fair
Freezers	Chest	Fair
Ranges	<input type="checkbox"/>	--
Ovens	Gas	Good
Griddles / Grills	<input type="checkbox"/>	--
Fryers	<input type="checkbox"/>	--
Hood	<input type="checkbox"/>	--
Dishwasher	<input type="checkbox"/>	--
Microwave	<input type="checkbox"/>	--
Ice Machines	<input type="checkbox"/>	--
Steam Tables	<input type="checkbox"/>	--

E1030 Commercial Laundry		
Equipment	Comment	Condition
Commercial Washing Machines	<input type="checkbox"/>	--
Commercial Dryers	<input type="checkbox"/>	--
Residential Washers	<input type="checkbox"/>	--
Residential Dryers	<input type="checkbox"/>	--

Anticipated Lifecycle Replacements:

- Convection oven
- Chest freezer
- Reach-in cooler

Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

7. Sitework

G20 Site Improvements

G2020 Parking Lots and G2030 Pedestrian Walkways		
Item	Material	Condition
Entrance Driveway Apron	Asphalt	Fair
Parking Lot	Asphalt	Fair
Drive Aisles	Asphalt	Fair
Service Aisles	None	--
Sidewalks	Concrete	Fair
Curbs	Concrete	Fair
Pedestrian Ramps	Cast-in-place concrete	Good
Ground Floor Patio or Terrace	Brick pavers	Fair

Parking Count				
Open Lot	Carport	Private Garage	Subterranean Garage	Freestanding Parking Structure
73	-	-	-	-
Total Number of ADA Compliant Spaces			3	
Number of ADA Compliant Spaces for Vans			1	
Total Parking Spaces			73	

Site Stairs			
Location	Material	Handrails	Condition
None	--	--	--

Maintenance Issues					
Observation	Location	Exists at Site	Observation	Location	Exists at Site
Pavement oil stains		<input type="checkbox"/>	Vegetation growth in joints		<input type="checkbox"/>
Stair/ramp rails loose		<input type="checkbox"/>	Stair/ramp rail needs scraped and painted		<input type="checkbox"/>
Other		<input type="checkbox"/>	Other		<input type="checkbox"/>

Degradation Issues			
Observation	Exists at Site	Observation	Exists at Site
Potholes/depressions	<input checked="" type="checkbox"/>	Alligator cracking	<input checked="" type="checkbox"/>
Concrete spalling	<input type="checkbox"/>	Trip hazards (settlement/heaving)	<input checked="" type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- Asphalt seal coating
- Asphalt pavement
- Sidewalks
- Curbs
- Patios

Actions/Comments:

- The asphalt pavement exhibits isolated areas of failure and deterioration, such as alligator cracking, and localized depressions, particularly along the main drive aisle. The most severely damaged areas of paving must be cut and patched in order to maintain the integrity of the overall pavement system. Complete milling and overlay of the entire lot is also recommended within the term.
- The concrete sidewalks and curbs have isolated areas of cracks, settlement and damage at the western elevation of the property and along the main drive aisle. The damaged areas of concrete pavement require replacement.

G2060 Site Development	
Property Signage	
Property Signage	Monument
Street Address Displayed?	Yes

Site Fencing		
Type	Location	Condition
Chain link with metal posts	Surrounding kindergarten playground, east elevation	Fair

Refuse Disposal				
Refuse Disposal	Common area dumpsters			
Dumpster Locations	Mounting	Enclosure	Contracted?	Condition
Northeast corner of property	Concrete pad	None	Yes	Fair



Other Site Amenities			
	Description	Location	Condition
Playground Equipment	Plastic and metal	Playgrounds at east and southeast sides of property	Fair
Tennis Courts	None	--	--
Basketball Court	None	--	--
Swimming Pool	None	--	--

The kindergarten playground is surrounded by a chain link fence.

Anticipated Lifecycle Replacements:

- Signage

Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

G2080 Landscaping		
Drainage System and Erosion Control		
System	Exists at Site	Condition
Surface Flow	<input checked="" type="checkbox"/>	Fair
Inlets	<input checked="" type="checkbox"/>	Fair
Swales	<input type="checkbox"/>	--
Detention pond	<input type="checkbox"/>	--
Lagoons	<input type="checkbox"/>	--
Ponds	<input type="checkbox"/>	--
Underground Piping	<input checked="" type="checkbox"/>	Fair
Pits	<input type="checkbox"/>	--
Municipal System	<input checked="" type="checkbox"/>	Fair
Dry Well	<input type="checkbox"/>	--

Anticipated Lifecycle Replacements:

- No components of significance

Actions/Comments:

- Ponding occurs in isolated areas. The affected areas must be graded to direct storm water toward the paved areas. This should be accomplished to maintain healthy vegetation.

Item	Description						
Site Topography	Slopes gently down from the west and south sides of the property toward the northeast and property line.						
Landscaping	Trees	Grass	Flower Beds	Planters	Drought Tolerant Plants	Decorative Stone	None
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>



Item	Description			
Landscaping Condition	Fair			
Irrigation	Automatic Underground	Drip	Hand Watering	None
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Irrigation Condition	--			

Retaining Walls		
Type	Location	Condition
CMU	Front elevation, adjacent to east parking lot	Good

Anticipated Lifecycle Replacements:

- No components of significance

Actions/Comments:

- The topography and adjacent uses do not appear to present conditions detrimental to the property. There are no significant areas of erosion.

G30 Liquid & Gas Site Utilities

G3060 Site Fuel Distribution	
Item	Description
Natural Gas	Gas service is supplied from the gas main on the adjacent public street. The gas meter and regulator are located adjacent to the grounds storage shed at the northwest corner of the building. The gas distribution piping within the building is malleable steel (black iron).

Anticipated Lifecycle Replacements:

- No components of significance

Actions/Comments:

- The pressure and quantity of gas appear to be adequate.
- The gas meter and regulator appear to be functioning adequately and will require routine maintenance.
- Only limited observation of the gas distribution piping can be made due to hidden conditions.

G40 Electrical Site Improvements

G4050 Site Lighting					
Site Lighting	None	Pole Mounted	Bollard Lights	Ground Mounted	Parking Lot Pole Type
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
	Fair				



G4050 Site Lighting			
Building Lighting	None	Wall Mounted	Recessed Soffit
	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	Good		

Maintenance Issues					
Observation	Location	Exists at Site	Observation	Location	Exists at Site
Isolated bulb/lamp replacement		<input type="checkbox"/>	Discolored/dirty lens cover		<input type="checkbox"/>
Other		<input type="checkbox"/>	Other		<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- Exterior light fixtures

Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

8. Ancillary Structures

Other Ancillary Structures			
Type	Grounds Storage Shed	Location	Northwest Corner of School
Item	Material	Item	Material
Exterior Siding	Pre-cast concrete	Roof Finishes	Concrete
Interior Finishes	Floor : Unfinished Concrete Ceiling : Exposed Walls : Pre-cast concrete	MEPF	N/A
Overall Building Condition			Fair

Anticipated Lifecycle Replacements:

- No components of significance

Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended.

9. Opinions of Probable Costs

Cost estimates are attached at the front of this report (following the cover page).

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means* and *Marshall & Swift*, EMG's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, and whether competitive pricing is solicited, etc. ASTM E2018-08 recognizes that certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

9.1. Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, EMG opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its effective age. Projections of Remaining Useful Life (RUL) are based on continued use of the Property similar to the reported past use. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be derived from an actual take-off, lump sum costs or allowances are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

9.2. Immediate Repairs

Immediate repairs are opinions of probable costs that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) material building or fire code violations, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

9.3. Replacement Reserves

Replacement Reserves are for recurring probable expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, EMG's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

EMG's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system's or component's respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined in the Immediate Repair Cost Estimate

10. Purpose and Scope

10.1. Purpose

EMG was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record at municipal offices, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

CONDITIONS:

The physical condition of building systems and related components are typically defined as being in one of five conditions: Excellent, Good, Fair, Poor, Failed or a combination thereof. For the purposes of this report, the following definitions are used:

Excellent	=	New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Good	=	Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Fair	=	Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.
Poor	=	Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life.
Failed	=	Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.
Not Applicable	=	Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.

FORMAT OF THE BODY OF THE REPORT:

Throughout sections 5 through 9 of this report, each report section will typically contain three subsections organized in the following sequence:

- A descriptive table (and/or narrative), which identifies the components assessed, their condition, and other key data points.
- A simple bulleted list of Anticipated Lifecycle Replacements, which lists components and assets typically in Excellent, Good, or Fair condition at the time of the assessment but that will require replacement or some other attention once aged past their estimated useful life. These listed components are typically included in the associated inventory database with costs identified and budgeted beyond the first several years.
- A bulleted cluster of Actions/Comments, which include more detailed narratives describing deficiencies, recommended repairs, and short term replacements. The assets and components associated with these bullets are/were typically problematic and in Poor or Failed condition at the time of the assessment, with corresponding costs included within the first few years.

PLAN TYPES:

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance. The following Plan Types are listed in general weighted order of importance:

Safety	=	An observed or reported unsafe condition that if left unaddressed could result in an injury; a system or component that presents a potential liability risk.
Performance/Integrity	=	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses a risk to overall system stability.
Accessibility	=	Does not meet ADA, UFAS, and/or other handicap accessibility requirements.
Environmental	=	Improvements to air or water quality, including removal of hazardous materials from the building or site.
Modernization/Adaptation	=	Conditions, systems, or spaces that need to be upgraded in appearance or function to meet current standards, facility usage, or client/occupant needs.
Lifecycle/Renewal	=	Any component or system in which future repair or replacement is anticipated beyond the next several years and/or is of minimal substantial early-term consequence.

10.2. Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a general statement of the subject Property’s compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Perform a limited assessment of accessible areas of the building(s) for the presence of fungal growth, conditions conducive to fungal growth, and/or evidence of moisture. EMG will also interview Project personnel regarding the presence of any known or suspected fungal growth, elevated relative humidity, water intrusion, or mildew-like odors. Potentially affected areas will be photographed. Sampling will not be considered in routine assessments.
- List the current utility service providers.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, in order to gain a clear understanding of the property’s overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report.
- Prepare a mechanical inventory list.

11. Accessibility and Property Research

11.1. ADA Accessibility

Generally, Title III of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of “areas of public accommodations” and “commercial facilities” on the basis of disability. Regardless of its age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

Buildings completed and occupied after January 26, 1992 are required to comply fully with the ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of compliance to the extent allowed by structural feasibility and the financial resources available. As an alternative, a reasonable accommodation pertaining to the deficiency must be made.

During the FCA, a limited visual observation for ADA accessibility compliance was conducted. The scope of the visual observation was limited to those areas set forth in *EMG’s Abbreviated Accessibility Table* below. It is understood by the Client that the limited observations described herein does not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of EMG’s undertaking. Only a representative sample of areas was observed and actual measurements were not taken to verify compliance.

The facility generally appears to be accessible as stated within the defined priorities of Title III of the Americans with Disabilities Act.

Under-sink pipe wrap was observed to be missing at the staff restroom, which is designated as accessible.

Accessibility Issues			
Component	Major Issue (ADA Study Recommended)	Moderate Issue (ADA Study Recommended)	Minor Issue
Parking	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Exterior Accessible Route	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Interior Accessible Route	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Restrooms	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Elevators	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

A full ADA Compliance Survey may reveal aspects of the property that are not in compliance.

Corrections of these conditions should be addressed from a liability standpoint, but are not necessarily code violations. The Americans with Disabilities Act Accessibility Guidelines concern civil rights issues as they pertain to the disabled and are not a construction code, although many local jurisdictions have adopted the Guidelines as such.

12. Certification

Ann Arbor Public Schools retained EMG to perform this Facility Condition Assessment in connection with its continued operation of Allen Elementary School, 2560 Towner Boulevard, Ann Arbor, MI, the "Property". It is our understanding that the primary interest of Ann Arbor Public Schools is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in depth studies were performed unless specifically required under Section 2 of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas were observed (See Section 4.2 for areas observed). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared on behalf of and exclusively for the use of the client for the purpose stated within Section 10 of this report. The report, or any excerpt thereof, shall not be used by any party other than the client or for any other purpose than that specifically stated in our agreement or within Section 10 of this report without the express written consent of EMG.

Any reuse or distribution of this report without such consent shall be at Ann Arbor Public Schools and the recipient's sole risk, without liability to EMG.

Prepared by: Justin Dunn,
Project Manager

Reviewed by:



Al Diefert
Technical Report Reviewer
For
Andrew Hupp
Program Manager

13. Appendices

Appendix A: Photographic Record

Appendix B: Site and Floor Plans

Appendix C: Supporting Documentation

Appendix D: Pre-Survey Questionnaire

Appendix A: Photographic Record



#1:	FRONT ELEVATION
-----	-----------------



#2:	LEFT ELEVATION
-----	----------------



#3:	RIGHT ELEVATION
-----	-----------------



#4:	REAR ELEVATION
-----	----------------



#5:	OVERALL SITE
-----	--------------



#6:	OVERALL ROOF
-----	--------------



#7: FLAT ROOF, EPDM SINGLE-PLY




#8: FLAT ROOF, ISOLATED MINOR PONDING



#9: HIP ROOF, ASPHALT SHINGLED



#10: MANSARD ROOF, ASPHALT SHINGLED



#11: MISSING ASPHALT ROOF SHINGLES AT MANSARD ROOF



#12: ROOF, METAL



#13:	EXTERIOR WALL TYPE
------	--------------------



#14:	EXTERIOR WALL TYPE
------	--------------------




#15:	EXTERIOR WALL TYPE
------	--------------------



#16:	WINDOW SYSTEM
------	---------------



#17:	MAIN ENTRANCE
------	---------------



#18:	ACCESSIBLE ENTRANCE DOOR
------	--------------------------



#19: MULTI-PURPOSE GREAT ROOM



#20: GYMNASIUM




#21: TYPICAL CLASSROOM



#22: COMPUTER LAB



#23: CENTRAL HALLWAY



#24: TYPICAL HALLWAY



#25: GENERAL OFFICE



#26: TYPICAL RESTROOM



#27: BOILER ROOM A



#28: BOILER ROOM B



#29: ELECTRICAL ROOM



#30: ELEVATOR



#31:	DOMESTIC WATER HEATER
------	-----------------------



#32:	PENTHOUSE AIR HANDLER
------	-----------------------



#33:	AIR-COOLED CONDENSING UNIT CONNECTED TO PENTHOUSE AHU
------	---



#34:	TYPICAL INDIVIDUAL CONDENSING UNITS
------	-------------------------------------



#35:	TYPICAL GAS-FIRED PACKAGE UNIT (RTU)
------	--------------------------------------



#36:	EXHAUST FANS
------	--------------



#37: BOILER #1 (ORIGINAL)



#38: BOILER #2 (NEWER)




#39: DISTRIBUTION PUMP, HEATING WATER



#40: BUILDING AUTOMATION SYSTEM



#41: TYPICAL CLASSROOM UNIT VENTILATOR



#42: RADIATORS AT HALLWAYS



#43: FIRE ALARM CONTROL PANEL



#44: TYPICAL FIRE ALARM COMPONENTS



#45: MAIN ELECTRICAL COMPONENTS



#46: EXTERIOR LIGHTING



#47: FRONT ASPHALT PAVED PARKING LOT



#48: REAR PARKING LOT WITH DUMPSTERS



#49:	CRACKED AND DAMAGED PAVING AT DRIVE AISLE
------	---



#50:	CONCRETE CURB DAMAGE
------	----------------------



#51:	TYPICAL CONCRETE SIDEWALK
------	---------------------------



#52:	CRACKED CONCRETE SIDEWALK
------	---------------------------

Appendix B: Site and Floor Plans

Site Plan



Project Name:

Allen Elementary School

Project Number:


129010.18R000-005.354

Source:

Google Earth

On-Site Date:

March 19, 2018



In Addition, provide (1) of each of the following:

- Boiler Room A
- Boiler Room B
- Electrical Room
- Elevator Machine Room
- Principal's Office
- Office
- PLTW Office

Locations TBD in the field

Appendix C: Supporting Documentation

**THIS APPENDIX IS INTENTIONALLY LEFT
BLANK.**

Appendix D: EMG Accessibility Checklist

Date Completed: March 19, 2018

Property Name: Allen Elementary School

EMG Project Number: 129010.18R000-005.354

Building History		Yes	No	Unk	Comments
1	Has an ADA survey previously been completed for this property?			✓	Informal review reportedly done as an activity with students on annual basis.
2	Have any ADA improvements been made to the property?	✓			
3	Does a Transition Plan / Barrier Removal Plan exist for the property?			✓	
4	Has building ownership or management received any ADA related complaints that have not been resolved?		✓		
5	Is any litigation pending related to ADA issues?		✓		
Parking		Yes	No	NA	Comments
1	Are there sufficient accessible parking spaces with respect to the total number of reported spaces?	✓			
2	Are there sufficient van-accessible parking spaces available?	✓			
3	Are accessible spaces marked with the International Symbol of Accessibility? Are there signs reading "Van Accessible" at van spaces?	✓			
4	Is there at least one accessible route provided within the boundary of the site from public transportation stops, accessible parking spaces, passenger loading zones, if provided, and public streets and sidewalks?	✓			
5	Do curbs on the accessible route have depressed, ramped curb cuts at drives, paths, and drop-offs?	✓			
6	If required does signage exist directing you to accessible parking and an accessible building entrance?	✓			
Ramps		Yes	No	NA	Comments
1*	Do all ramps along accessible path of travel appear to meet slope requirements? (1:12 or less)	✓			
2	Are ramps that appear longer than 6 ft complete with railings on both sides?	✓			
3	Does the width between railings appear at least 36 inches?	✓			

Ramps (cont.)		Yes	No	NA	Comments
4	Is there a level landing for approximately every 30 ft horizontal length of ramp, at the top and at the bottom of ramps and switchbacks?	✓			
Entrances/Exits		Yes	No	NA	Comments
1	Do all required accessible entrance doorways appear at least 32 inches wide and not a revolving door?	✓			
2	If the main entrance is inaccessible, are there alternate accessible entrances?			✓	Main entrance is accessible.
3	Is the door hardware easy to operate (lever/push type hardware, no twisting required and not higher than approximately 48 inches above the floor)?	✓			
Paths of Travel		Yes	No	NA	Comments
1	Are all paths of travel free of obstruction and wide enough for a wheelchair (appear at least 36 inches wide)?	✓			
2	Are wheelchair-accessible facilities (toilet rooms, exits, etc.) identified with signage?	✓			
3	Is there a path of travel that does not require the use of stairs?	✓			
Elevators		Yes	No	NA	Comments
1	Do the call buttons have visual and audible signals to indicate when a call is registered and answered when car arrives?	✓			
2	Are there visual and audible signals inside cars indicating floor change?	✓			
3	Are there standard raised and Braille marking on both jambs of each hoist way entrance as well as all cab/call buttons?	✓			
4	Do elevator doors have a reopening device that will stop and reopen a car door if an object or a person obstructs the door?	✓			
5	Are elevator controls low enough to be reached from a wheelchair (appears to be between 15 and 48 inches)?	✓			
6	If a two-way emergency communication system is provided within the elevator cab, is it usable without voice communication?	✓			

Toilet Rooms		Yes	No	NA	Comments
1	Are common area public restrooms located on an accessible route?	✓			
2	Are pull handles push/pull or lever type?	✓			
3	Are there audible and visual fire alarm devices in the toilet rooms?	✓			
4	Are toilet room access doors wheelchair-accessible (appear to be at least 32 inches wide)?	✓			
5	Are public restrooms large enough to accommodate a wheelchair turnaround (appear to have 60" turning diameter)?	✓			
6	In unisex toilet rooms, are there safety alarms with pull cords?			✓	Pull cord alarm system not in use at property.
7	Are toilet stall doors wheelchair accessible (appear to be at least 32" wide)?	✓			
8	Are grab bars provided in toilet stalls?	✓			
9	Are sinks provided with clearance for a wheelchair to roll under (appear to have 29" clearance)?	✓			
10	Are sink handles operable with one hand without grasping, pinching or twisting?	✓			
11	Are exposed pipes under sink sufficiently insulated against contact?		✓		
Guest Rooms		Yes	No	NA	Comments
1	How many total accessible sleeping rooms does the property management report to have? Provide specific number in comment field. Are there sufficient reported accessible sleeping rooms with respect to the total number of reported guestrooms? See attached hot sheet.			✓	

Guest Rooms (cont.)		Yes	No	NA	Comments
2	How many of the accessible sleeping rooms per property management have roll-in showers? Provide specific number in comment field. Are there sufficient reported accessible rooms with roll-in showers with respect to the total number of reported accessible guestrooms? See attached hot sheet.			✓	
3	How many assistive listening kits and/or rooms with communication features are available per property management? Provide specific number in comment field. Are there sufficient reported assistive listening devices with respect to the total number of rooms? See attached hot sheet.			✓	
Pools		Yes	No	NA	Comments
1	Are public access pools provided? If the answer is no, please disregard this section.			✓	
2	How many accessible access points are provided to each pool/spa? Provide number in comment field. Is at least one fixed lift or sloped entry to the pool provided?			✓	
Play Area		Yes	No	NA	Comments
1	Has the play area been reviewed for accessibility? All public playgrounds are subject to ADAAG standards.		✓		Playgrounds reportedly scheduled to be reviewed for accessibility and improvements added within the year.
Exercise Equipment		Yes	No	NA	Comments
1	Does there appear to be adequate clear floor space around the machines/equipment (30" by 48" minimum)?			✓	

**Based on visual observation only. The slope was not confirmed through measurements.*

Appendix E: Pre-Survey Questionnaire

EMG FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

Building / Facility Name: Allen Elementary
 Name of person completing form: Kerry Beal
 Title / Association with property: Principal
 Length of time associated w/ property: 4 years
 Date Completed: 3/19/2018
 Phone Number: 734-997-1210

Directions: Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any Yes responses.

DATA OVERVIEW		RESPONSE			
1	Year/s constructed	1961 ; numerous additions to original structure (multiple wings)			
2	Building size in SF	65,388			
3	Major Renovation Dates	Façade	unk; varies, numerous additions	HVAC	mix, all A/C 2017; boilers older
		Roof	unk	Electrical	2017 (most major components)
		Interiors	mostly 2017 due to flooding	Site Pavement	4+ years; old and deteriorating
		Accessibility	annual, involve the kids	other	
QUESTION		RESPONSE			
4	Provide additional detail about the scope of the MAJOR additions, renovations, or systemic rehabilitations since construction (referenced above in Question 3).	Flooded 2016 - 2016; renovated 2016/2017 new furniture pipe burst through floor got A/C → unit ventilators all new tile except gym; some drywall; RTUs Per spaces spaces (gym, offices) new window shades in great room			
5	List other significant but somewhat lesser capital improvements, focusing on recent years (provide approximate year completed).	ceiling changed (finishes) LED lighting throughout new water access installed			
6	List any major capital expenditures planned/requested for the next few years. Have they been budgeted?	playground additions parking lot resurfacing → surfacing at least 4 years old (but likely older)			
7	Describe any on-going extremely problematic, historically chronic, or immediate facility needs.	tweaking HVAC; getting balance throughout building some areas too warm/cool, but no major issues			

3-4 additions since built - 1991 most recent

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any Yes responses. (NA indicates "Not Applicable", Unk indicates "Unknown")

QUESTION		RESPONSE				COMMENTS
		Yes	No	Unk	NA	
8	Are there any problems with foundations or structures, like excessive settlement?		✓			
9	Has any part of the facility ever contained visible suspect mold growth, or have there been any indoor air quality or mold related complaints from occupants?		✓			
10	Are there any wall, window, basement or roof leaks?		✓			
11	Are there any plumbing leaks, water pressure, or clogging/back-up problems?		✓			
12	Have there been any leaks or pressure problems with natural gas, HVAC supply/return lines, or steam service?		✓			
13	Are any areas of the facility inadequately heated, cooled or ventilated? Any poorly insulated areas?	✓				HVAC balance issues; being worked on
14	Is the electrical service outdated, undersized, or otherwise problematic?		✓			
15	Are there any problems or inadequacies with exterior building-mounted lighting?		✓			
16	Is site/parking drainage inadequate, with excessive ponding or other problems?	✓	✓			blacktop @ playground gets web ponding behind basketball courts
17	Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified above?		✓			
18	ADA: Has an accessibility study been performed at the site? If so, indicate when.	✓	✓			annual assessment involving students formal/official assessment unknown
19	ADA: If a study has occurred, have the associated recommendations been addressed? In full or in part?	✓				mech door openers @ front doors
20	ADA: Have there been regular complaints about accessibility issues, or associated previous or pending litigation?		✓			

On the day of the site visit, provide EMG's Field Observer access to all of the available documents listed below. Provide copies if possible.

INFORMATION REQUIRED

1. All available construction documents (blueprints) for the original construction of the building or for any tenant improvement work or other recent construction work.
2. A site plan, preferably 8 1/2" X 11", which depicts the arrangement of buildings, roads, parking stalls, and other site features.
3. For commercial properties, provide a tenant list which identifies the names of each tenant, vacant tenant units, the floor area of each tenant space, and the gross and net leasable area of the building(s).
4. For apartment properties, provide a summary of the apartment unit types and apartment unit type quantities, including the floor area of each apartment unit as measured in square feet.
5. For hotel or nursing home properties, provide a summary of the room types and room type quantities.
6. Copies of Certificates of Occupancy, building permits, fire or health department inspection reports, elevator inspection certificates, roof or HVAC warranties, or any other similar, relevant documents.
7. The names of the local utility companies which serve the property, including the water, sewer, electric, gas, and phone companies.

8. The company name, phone number, and contact person of all outside vendors who serve the property, such as mechanical contractors, roof contractors, fire sprinkler or fire extinguisher testing contractors, and elevator contractors.
9. A summary of recent (over the last 5 years) capital improvement work which describes the scope of the work and the estimated cost of the improvements. Executed contracts or proposals for improvements. Historical costs for repairs, improvements, and replacements.
10. Records of system and material ages (roof, MEP, paving, finishes, furnishings).
11. Any brochures or marketing information.
12. Appraisal, either current or previously prepared.
13. Current occupancy percentage and typical turnover rate records (for commercial and apartment properties).
14. Previous reports pertaining to the physical condition of property.
15. ADA survey and status of improvements implemented.
16. Current / pending litigation related to property condition.

Your timely compliance with this request is greatly appreciated.

