

FACILITY CONDITION ASSESSMENT

Prepared for

Ann Arbor Public Schools
2555 South State Street
Ann Arbor, Michigan 48104
Jim Vibbart



PREPARED BY:

EMG

10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Andrew Hupp
Program Manager
800.733.0660 x6632
ahupp@emgcorp.com

EMG PROJECT #:

129010.18R000-020.354

DATE OF REPORT:

July 2, 2018

ONSITE DATE:

January 31, 2018

FACILITY CONDITION ASSESSMENT

OF

PATTENGILL ELEMENTARY
2100 CRESTLAND DRIVE
ANN ARBOR, MICHIGAN 48104



engineering | environmental | capital planning | project management

EMG Corporate Headquarters 10461 Mill Run Circle, Suite 1100, Owings Mills, MD 21117 www.EMGcorp.com p 800.733.0660

Immediate Repairs Report
Pattengill Elementary
7/2/2018



Location Name	EMG Renamed Item Number	ID	Cost Description	Quantity	Unit	Unit Cost *	Subtotal	Deficiency Repair Estimate *
Pattengill Elementary	D30	885577	Air Conditioning, Central, Install	52000	SF	\$11.50	\$598,000	\$598,000
Pattengill Elementary	B2020	834696	Window, Aluminum Double-Glazed 12 SF, 1-2 Stories, Replace	1	EA	\$584.21	\$584	\$584
Pattengill Elementary	B2050	834706	Exterior Door, Steel, Replace	16	EA	\$1,092.64	\$17,482	\$17,482
Pattengill Elementary	B30	845756	Roof, Modified Bituminous, Replace	37500	SF	\$10.35	\$387,978	\$387,978
Pattengill Elementary	C2010	834698	Interior Wall Finish, Gypsum Board/Plaster, Repair	200	SF	\$3.18	\$636	\$636
Pattengill Elementary	A10	834681	Interior Wall Finish, Concrete, Repair	77000	SF	\$34.78	\$2,678,443	\$2,678,443
Pattengill Elementary	C2050	834695	Interior Ceiling Finish, Gypsum Board/Plaster, Repair	1000	SF	\$8.42	\$8,417	\$8,417
Pattengill Elementary	C2050	834738	Interior Ceiling Finish, Suspended Acoustical Tile (ACT), Replace	2500	SF	\$3.58	\$8,944	\$8,944
Pattengill Elementary	D20	834679	Backflow Preventer, 2 Inch, Replace	1	EA	\$2,993.64	\$2,994	\$2,994
Pattengill Elementary	D30	834677	Building Automation System (HVAC Controls), , Upgrade	52000	SF	\$6.17	\$320,678	\$320,678
Pattengill Elementary	D70	834739	Fire Alarm Control Panel, Addressable, Replace	1	EA	\$23,342.23	\$23,342	\$23,342
Pattengill Elementary	D70	834702	Security/Surveillance System, Cameras and CCTV, Upgrade	52000	SF	\$5.00	\$259,963	\$259,963
Pattengill Elementary	D70	834742	Defibrillator, Cabinet Mounted, Replace	1	EA	\$1,620.93	\$1,621	\$1,621
Pattengill Elementary		958697	Davis Bacon Prevailing Wages, Surcharge for Prevailing Wages, 10% surcharge for prevailing wages	55445.46	LS	\$1.15	\$63,762	\$63,762
Pattengill Elementary	G2080	845760	Landscaping, Mature Tree, Remove/Trim	15	EA	\$1,425.66	\$21,385	\$21,385
Pattengill Elementary	A10	834719	Engineer, Structural, Superstructure, , Evaluate/Report	1	EA	\$11,500.00	\$11,500	\$11,500
Immediate Repairs Total								\$4,405,729

* Location Factor included in totals.

TABLE OF CONTENTS

1	Executive Summary	1
1.1	Property Information and General Physical Condition	1
1.2	Key Findings.....	2
1.3	Facility Condition Index (FCI)	2
2	Building Structure	4
	A10 Foundations.....	4
	B10 Superstructure.....	4
3	Building Envelope	6
	B20 Exterior Vertical Enclosures	6
	B30 Roofs	7
4	Interiors	9
	C10 Interior Construction.....	9
5	Services (MEPF)	11
	D10 Conveying Systems	11
	D20 Plumbing	11
	D30 Building Heating, Ventilating, and Air Conditioning (HVAC).....	12
	D40 Fire Protection.....	15
	D50 Electrical.....	16
	D60 Communications	16
	D70 Electronic Safety and Security	17
6	Equipment & Furnishings	18
	E10 Equipment	18
7	Sitework	19
	G20 Site Improvements.....	19
	G30 Liquid & Gas Site Utilities	22
	G40 Electrical Site Improvements	22
8	Ancillary Structures	24
9	Opinions of Probable Costs	25
	9.1 Methodology	25
	9.2 Immediate Repairs	25
	9.3 Replacement Reserves	25
10	Purpose and Scope	26
	10.1 Purpose	26
	10.2 Scope	27
11	Accessibility and Property Research	28
	11.1 ADA Accessibility	28
	11.2 Flood Zone	28
12	Certification	29
13	Appendices	30

1 Executive Summary

1.1 Property Information and General Physical Condition

The property information is summarized in the table below. More detailed descriptions may be found in the various sections of the report and in the Appendices.

Property Information		
Address:	2100 Crestland Drive, Ann Arbor, Washtenaw, Michigan 48104	
Year Constructed/Renovated:	1957	
Current Occupants:	Ann Arbor Public Schools	
Percent Utilization:	100	
Management Point of Contact:	Ann Arbor Public Schools, Jim Vibbart, Title 734.320.3613 phone vibbart.j@aaps.k12.mi.us email	
Property Type:	Elementary School	
Site Area:	11.33 acres	
Building Area:	52,000 SF	
Number of Buildings:	1	
Number of Stories:	1	
Parking Type and Number of Spaces:	38 spaces in open lots	
Building Construction:	Masonry bearing walls and concrete columns, beams, and decking	
Roof Construction:	Flat roofs with modified bituminous membrane Flat roof with EPDM membrane	
Exterior Finishes:	Concrete Masonry	
Heating, Ventilation & Air Conditioning:	Central system with boilers, air handlers, unit ventilators, and hydronic baseboard radiators and cabinets. Supplemental components: Ductless split-systems	
Fire and Life/Safety:	Hydrants, smoke detectors, alarms, strobes, extinguishers, pull stations, alarm panel, exit signs, and annunciator panel.	
ADA :	This building does not have any major ADA issues	
<p>All 52,000 square feet of the building are occupied by a single occupant, Pattengill Elementary/Ann Arbor Public Schools. The spaces are a combination of classrooms, offices, typical school spaces, supporting restrooms, mechanical room, and other utility/storage spaces.</p> <p>The following table identifies the unit types and mix at the subject property:</p>		
<p>Most of the interior spaces were observed in order to gain a clear understanding of the property's overall condition. Other areas accessed included the site within the property boundaries, exterior of the property, and the roof. Areas of note that were either inaccessible or not observed for other reasons are listed in the table below:</p>		
Key Spaces Not Observed		
Room Number	Area	Access Issues
--	Roof	Roof was not accessible due to snow and lack of roof access.
<p>A "down unit" or area is a term used to describe a unit or space that cannot be occupied due to poor conditions such as fire damage, water damage, missing equipment, damaged floor, wall or ceiling surfaces, or other significant deficiencies. There are no down units or areas.</p>		
Assessment Information		
Dates of Visit:	1/31/2018	
On-Site Point of Contact (POC):	Jim Vibbart	



Property Information	
Assessment and Report Prepared by:	James Cuellar
Reviewed by:	Andrew Hupp Program Manager ahupp@emgcorp.com 800.733.0660 x6632


1.2 Key Findings

Site : The site is in fair condition overall. Future lifecycle replacements are recommended.

Architectural : The CMU is in poor condition. The concrete block in Orchestra room, girls bathroom, computer lab, and vocal lab observed cracks throughout these rooms. Surveillance system is antiquated. Some ceiling repairs are required.

MEPF : Most of the mechanical and electrical components in the building are in fair condition. The building automation system utilizes an old pneumatic control system. It is recommended it be upgraded to a full DDC system.

1.3 Facility Condition Index (FCI)



One of the major goals of the FCA is to calculate the FCI, which gives an indication of a building’s overall condition. Two FCI ratios are calculated and presented, the Current Year and Ten-Year. The Current Year FCI is the ratio of Immediate Repair Costs to the building’s Current Replacement Value. Similarly, the Ten-Year FCI is the ratio of anticipated Capital Reserve Needs over the next ten years to the Current Replacement Value.

FCI Condition Rating	Definition	Percentage Value
Good	In new or well-maintained condition, with no visual evidence of wear, soiling or other deficiencies.	0 to .05
Fair	Subjected to wear and soiling but is still in a serviceable and functioning condition.	> than .05 to .10
Poor	Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life.	> than .10 to .60



FCI Condition Rating	Definition	Percentage Value
Very Poor	Has reached the end of its useful or serviceable life. Renewal is now necessary.	> than .60

The graphs above and tables below represent summary-level findings for the FCA. The deficiencies identified in this assessment can be combined with potential new construction requirements to develop an overall strategy that can serve as the basis for a portfolio-wide capital improvement funding strategy. Key findings from the assessment include:

Key Finding	Metric	
Current Year Facility Condition Index (FCI) $FCI = (IR)/(CRV)$	0.19	Poor
10-Year Facility Condition Index (FCI) $FCI = (RR)/(CRV)$	0.55	Poor
Current Replacement Value (CRV)	52,000 SF * 200 \$ / SF = \$10,400,000	
Year 0 (Current Year) - Immediate Repairs (IR)		\$1,955,127
Years 1-10 – Replacement Reserves (RR)		\$3,724,233
Total Capital Needs		\$5,679,360

Further detail on the specific costs that make up the Immediate Repair Costs can be found in the cost tables at the beginning of this report.

2 Building Structure

A10 Foundations

Building Foundation		
Item	Description	Condition
Foundation	Concrete spread footings	Poor
Basement and Crawl Space	None	--

Anticipated Lifecycle Replacements

- Structural study
- Structural repairs

Actions/Comments:

- The foundations and footings cannot be directly observed. However, there are isolated areas of cracking, movement, and vertically displaced slabs throughout the orchestra room, girls bathroom, computer lab, and vocal lab. This condition typically indicates excessive settlement or other potential problems with the foundation system. A Professional Engineer with specific expertise in structural design and construction in this geographical area must be retained to evaluate the structure and to provide remedial recommendations consistent with local regulatory and code requirements. Although the estimated cost of repair cannot be accurately determined without the recommended study, a budgetary cost allowance to repair the affected elements is also included.

B10 Superstructure

B1010 Floor Construction & B1020 Roof Construction		
Item	Description	Condition
Framing / Load-Bearing Walls	Masonry walls	Fair
Ground Floor	Concrete slab	Fair
Upper Floor Framing	None	--
Upper Floor Decking	None	--
Balcony Framing	None	--
Balcony Decking	None	--
Balcony Deck Toppings	None	--
Balcony Guardrails	None	--
Roof Framing	Steel beams or girders	Good
Roof Decking	Metal decking	Good

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Caulk minor cracking	<input type="checkbox"/>	Monitor cracking for growth	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- No components of significance

Actions/Comments:

- The superstructure is exposed in some locations, which allows for limited observation. Walls and floors appear to be plumb, level, and stable. There are no significant signs of deflection or movement.

B1080 Stairs					
Type	Description	Riser	Handrail	Balusters	Condition
Building Exterior Stairs	None	None	None	None	--
Building Interior Stairs/Ramp	Concrete ramp	None	Metal	None	Fair

Anticipated Lifecycle Replacements:

- Rail refinishing

Actions/Comments:

- The superstructure is exposed in some locations, which allows for limited observation. Walls and floors appear to be plumb, level, and stable. There are no significant signs of deflection or movement.

3 Building Envelope

B20 Exterior Vertical Enclosures

B2010 Exterior Walls		
Type	Location	Condition
Primary Finish	Brick veneer	Fair
Secondary Finish	None	--
Accented with	None	--
Soffits	Not Applicable	--
Building sealants	Between dissimilar materials, at joints, around windows and doors	Fair

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Graffiti	<input type="checkbox"/>	Efflorescence	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- Masonry re-pointing

Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance, including patching repairs, graffiti removal, and re-caulking, is highly recommended. Future lifecycle replacements of the components listed above will be required.

B2020 Exterior Windows				
Window Framing	Glazing	Location	Window Screen	Condition
Aluminum framed, operable	Double glaze	Surrounding building	<input type="checkbox"/>	Fair

B2050 Exterior Doors		
Main Entrance Doors	Door Type	Condition
	Solid core with glazing	Fair
Secondary Entrance Doors	Solid core with glazing	Fair
Service Doors	Metal, insulated	Fair
Overhead Doors	None	--

Anticipated Lifecycle Replacements:

- Windows
- Exterior entrance doors
- Exterior service doors

Actions/Comments:

- The windows display significant evidence of leaks, condensation throughout the entire building. The damaged windows must be replaced.
- There are a significant number of damaged, delaminated, deteriorated, rusted doors and door frames. The damaged doors and frames must be replaced.

B30 Roofs

B3010 Primary Roof			
Location	East Roof	Finish	Modified bitumen
Type / Geometry	Flat	Roof Age	27 Yrs
Flashing	Sheet metal	Warranties	None reported
Parapet Copings	None	Roof Drains	Internal drains
Fascia	None	Insulation	Rigid Board
Soffits	None	Skylights	No
Attics	Steel beams	Ventilation Source-1	Power Vents
Roof Condition	Poor	Ventilation Source-2	None

B3010 Secondary Roof			
Type / Geometry	Flat	Finish	EPDM
		Roof Age	17 Yrs
Flashing	Sheet metal	Warranties	None reported
Parapet Copings	None	Roof Drains	Internal drains
Fascia	None	Insulation	Rigid Board
Soffits	None	Skylights	No
Attics	Steel beams	Ventilation Source-1	Power Vents
Roof Condition	Fair	Roof Location	West Roof

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Drainage components broken/missing	<input type="checkbox"/>	Vegetation/fungal growth	<input type="checkbox"/>
Blocked Drains	<input checked="" type="checkbox"/>	Debris	<input type="checkbox"/>



Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Degradation Issues			
Observation	Exists At Site	Observation	Exists At Site
Evidence of roof leaks	<input checked="" type="checkbox"/>	Significant ponding	<input checked="" type="checkbox"/>
Excessive patching or repairs	<input type="checkbox"/>	Blistering or ridging	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- EPDM roof
- Modified bituminous roof
- Hanging tree limbs near roof

Actions/Comments:

- The roof finishes appear to be more than 17 years old. Information regarding roof warranties or bonds was not available. The roofs are maintained by an outside contractor.
- The modified bituminous roofs have significant areas of heavy membrane wear on the east roof. Replacement is recommended. A cost allowance for this work is included.
- Roof leaks have occurred within the past year, and some of these leaks remain active. The leaks occur throughout the building. All active leaks must be repaired.
- There are ponding stains and build-up of debris at some of the drain locations throughout the entire roof. The affected drains must be cleaned and cleared and debris must be removed from the roof surfaces. Overhanging tree branches must be cleared from the perimeter of the roof.



4 Interiors

C10 Interior Construction

C1030 Interior Doors		
Item	Type	Condition
Interior Doors	Solid core wood	Fair
Door Framing	Metal	Fair
Fire Doors	Yes	Fair
Closet Doors	Solid core wood	Fair

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Improperly adjusted door closures	<input type="checkbox"/>	Damaged/loose door hardware	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

C2010 Wall Finishes; C2030 Floor Finishes; C2050 Ceiling Finishes: The following table generally describes the locations and typical conditions of the interior finishes within the facility:

Interior Finishes - PATTENGILL ELEMENTARY

Location / Space	Finish	Quantity (SF)	Condition	Action	RUL t	Est. Cost
Throughout building	Wall	Concrete/Masonry	3,600	Fair	Prep & Paint	3 \$5,224
Middle Wing	Wall	Concrete	34,000	Poor	Repair	0 \$1,028,425
Throughout building	Ceiling	Suspended Acoustical Tile (ACT)	36,500	Fair	Replace	2 \$113,552
Gym	Floor	Wood Strip	1,000	Fair	Sand & Refinish	3 \$3,678
Media room	Ceiling	Gypsum Board/Plaster	1,000	Poor	Repair	0 \$7,319
Hallway in middle wing	Wall	Gypsum Board/Plaster	200	Poor	Repair	0 \$636
Restrooms	Wall	Ceramic Tile	8,000	Fair	Replace	3 \$132,432
Middle wing	Wall	Concrete/Masonry	3,600	Fair	Prep & Paint	3 \$5,224
Middle wing	Floor	Carpet Standard-Commercial Medium-Traffic	12,000	Fair	Replace	3 \$87,076
Throughout building	Floor	Vinyl Tile (VCT)	24,000	Fair	Replace	2 \$115,214
Throughout building	Floor	Ceramic Tile	4,000	Good	Replace	32 \$63,020
Throughout building	Ceiling	Suspended Acoustical Tile (ACT)	2,500	Poor	Replace	0 \$7,778

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Loose carpeting/flooring	<input type="checkbox"/>	Minor areas of stained ceiling tiles	<input type="checkbox"/>
Minor paint touch-up	<input type="checkbox"/>	Areas of damaged/missing baseboard	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- Vinyl tile
- Ceramic tile
- Carpet
- Interior painting
- Suspended acoustic ceiling tile
- Gym floor refinishing
- Interior doors
- Basketball backboards
- Kitchen cabinets
- Time clocks
- Toilet partitions

Actions/Comments:

- It appears that the interior finishes are original.
- The ceiling tiles have isolated areas of water-damaged ceilings throughout the property. The damaged ceiling tiles need to be replaced. A cost allowance for this work is included.
- There are isolated areas of faded wall finishes throughout the property. The damaged wall areas need to be repainted. A cost allowance for this work is included.

5 Services (MEPF)

D10 Conveying Systems

Not applicable. There are no elevators or conveying systems.

D20 Plumbing

D2010 Domestic Water Distribution		
Type	Description	Condition
Water Supply Piping	Copper	Fair
Water Meter Location	Mechanical Room	

Domestic Water Heaters or Boilers	
Components	Water Heaters
Fuel	Natural gas
Boiler or Water Heater Condition	Good
Supplementary Storage Tanks?	No
Adequacy of Hot Water	Adequate
Adequacy of Water Pressure	Adequate

D2020 Sanitary Drainage		
Type	Description	Condition
Waste/Sewer Piping	Cast iron	Fair
Vent Piping	Cast iron	Fair

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Hot water temperature too hot or cold	<input type="checkbox"/>	Minor or isolated leaks	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Plumbing System - PATTENGILL ELEMENTARY

Location / Space	Component	Component Description	Quantity	Unit	Condition	Action	RUL	Est. Cost
Boiler room	Backflow Preventer	2"	1	EA	NA	Replace	0	\$2,603
Classroom restroom	Lavatory	Vitreous China	35	EA	Fair	Replace	2	\$20,043
Boiler room	Water Heater	Gas, Commercial, 60 to 120 GAL	1	EA	Good	Replace	10	\$10,699
Restroom	Urinal	Vitreous China	2	EA	Fair	Replace	2	\$2,387
Custodian	Service Sink	Floor	4	EA	Fair	Replace	17	\$6,398
Restrooms	Toilet	Tankless (Water Closet)	32	EA	Fair	Replace	2	\$26,975
Art room	Sink	Pot, Multi-compartment	22	LF	Fair	Replace	3	\$27,775
Boiler room	Sump Pump	3 HP	1	EA	Fair	Replace	3	\$2,063
Classrooms	Sink	Stainless Steel	25	EA	Fair	Replace	3	\$26,351
Hallway	Drinking Fountain	Refrigerated	3	EA	Fair	Replace	3	\$3,773
Mechanical closet	Sink	Porcelain Enamel, Cast Iron	1	EA	Fair	Replace	3	\$1,167

Anticipated Lifecycle Replacements:

- Water heaters
- Toilets
- Urinals
- Sinks
- Sump pumps
- Drinking fountain

Actions/Comments:

- The plumbing systems appear to be well maintained and functioning adequately. The water pressure appears to be sufficient. No significant repair actions or short term replacement costs are required. Routine and periodic maintenance is recommended. Future lifecycle replacements of the components or systems listed above will be required.
- A backflow preventer was not observed on the domestic water pune. A backflow preventer is typically installed on new construction. It reduces the risk of contaminating the municipal water supply.

D30 Building Heating, Ventilating, and Air Conditioning (HVAC)

Building Central Heating System	
Primary Heating System Type	Hot water boilers
Heating Fuel	Natural gas
Location of Major Equipment	Mechanical rooms
Space Served by System	Entire building

Distribution System	
HVAC Water Distribution System	Two-pipe
Air Distribution System	Constant Volume
Location of Air Handlers	Rooftop, exterior
Terminal Units	Unit Ventilators



Distribution System	
----------------------------	--

Quantity and Capacity of Terminal Units	Quantity and capacity difficult to determine without construction drawings
Location of Terminal Units	Classrooms

Packaged, Split & Individual Units	
---	--

Primary Components	Package units
Cooling (if separate from above)	performed via components above
Heating Fuel	Natural gas
Location of Equipment	Rooftop
Space Served by System	East Wing

Supplemental/Secondary Components	
--	--

Supplemental Component #1	Ductless mini-split systems
Location / Space Served by ductless mini-split	Data rooms
ductless mini-split Condition	Fair
Supplemental Component #2	Wall heaters
Location / Space Served by wall heaters	Hallways
Wall heaters Condition	Fair
Supplemental Component #3	Hydronic Cabinet Unit Heaters
Location / Space Served by Hydronic Cabinet Unit	Class rooms
Hydronic Cabinet Unit Heaters Condition	Fair

Controls and Ventilation	
---------------------------------	--

HVAC Control System	BAS, hybrid pneumatic/electronic system
HVAC Control System Condition	Poor
Building Ventilation	Roof top exhaust fans
Ventilation System Condition	Fair

Maintenance Issues			
---------------------------	--	--	--

Observation	Exists At Site	Observation	Exists At Site
Ductwork/grills need cleaned	<input type="checkbox"/>	Minor control adjustments needed	<input type="checkbox"/>
Leaking condensate lines	<input type="checkbox"/>	Poor mechanical area access	<input type="checkbox"/>



Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Degradation Issues			
Observation	Exists At Site	Observation	Exists At Site
Heating, Cooling or Ventilation is not adequate	<input checked="" type="checkbox"/>	Major system inefficiencies	<input checked="" type="checkbox"/>
HVAC controls pneumatic or antiquated	<input checked="" type="checkbox"/>	Obsolete refrigerants : R11, R12, R22, R123, R502	<input checked="" type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Mechanical Systems - PATTENGILL ELEMENTARY

Location / Space	Component	Component Description	Quantity	Unit	Condition	Action	RUL	Subtotal
Mechanical room	Building Automation System	HVAC Controls	52,000	SF	Poor	Upgrade	0	\$278,850
Boiler room	Distribution Pump	Heating Water, 5 HP	1	EA	Fair	Replace	3	\$5,519
Boiler room	Boiler	Gas, 1,001 to 2,000 MBH	1	EA	Fair	Replace	6	\$46,465
Hallway	Cabinet Heater	Hydronic	2	EA	Fair	Replace	3	\$6,360
Cafeteria	Ceiling Fan	Ceiling Fan	2	EA	Fair	Replace	3	\$1,416
Boiler room	Distribution Pump	Heating Water, 5 HP	1	EA	Fair	Replace	3	\$5,519
Mechanical room	Hydronic Wall Unit	Hydronic Baseboard	150	LF	Fair	Replace	23	\$19,916
Classrooms	Unit Ventilator	300 to 750 CFM (approx. 2 Ton)	30	EA	Fair	Replace	4	\$202,488
Boiler room	Boiler	Gas, 1,001 to 2,000 MBH	1	EA	Fair	Replace	6	\$46,465
Boiler room	Boiler	Gas, 1,001 to 2,000 MBH	1	EA	Fair	Replace	6	\$46,465
Boiler room	Air Compressor	2 HP	1	EA	Good	Replace	15	\$6,612
Mechanical room	Ductless Split System	Single Zone, 1.5 to 2 Ton	1	EA	Fair	Replace	2	\$4,473
Throughout building	Cabinet Heater	Hydronic	13	EA	Fair	Replace	2	\$41,339
Throughout	Air Conditioner	Window/Thru-Wall, 1.5 to 2 Ton	20	EA	Fair	Replace	1	\$51,770
Roof	Exhaust Fan	Centrifugal, 801 to 2,000 CFM	30	EA	Fair	Replace	3	\$79,925
Roof	Air Handler	Exterior, 6,001 to 8,000 CFM	1	EA	Good	Replace	10	\$37,803

Anticipated Lifecycle Replacements:

- Boilers
- Distribution pumps and motors
- Hydronic cabinet unit heaters
- Unit ventilators
- Electric wall heaters
- Mini-split system
- Hydronic baseboard heaters
- Through-wall air conditioners
- Rooftop exhaust fans
- Building automation system
- Ceiling fans



Actions/Comments:

- The HVAC systems are maintained by an outside contractor. Records of the installation, maintenance, upgrades, and replacement of the HVAC equipment at the property have been maintained since the property was first occupied.
- HVAC equipment varies in age. HVAC equipment is replaced on an "as needed" basis.
- The HVAC equipment appears to be functioning adequately overall. The property management staff was interviewed about the historical and recent performance of the equipment and systems. No chronic problems were reported and an overall sense of satisfaction with the systems was conveyed. However, due to the inevitable failure of parts and components over time, some of the equipment will require replacement.
- The facility HVAC is controlled using an outdated pneumatic system supplied by an air compressor. For modernization, reliability, and increased control, full conversion to a web-based direct digital control (DDC) platform is highly recommended.

D40 Fire Protection

Item	Description					
Type	None					
Sprinkler System	None	<input checked="" type="checkbox"/>	Standpipes	<input type="checkbox"/>	Backflow Preventer	<input type="checkbox"/>
	Hose Cabinets	<input type="checkbox"/>	Fire Pumps	<input type="checkbox"/>	Siamese Connections	<input type="checkbox"/>
Sprinkler System Condition	--					
Fire Extinguishers	Last Service Date			Servicing Current?		
	July, 2017					
Hydrant Location	None listed					
Siamese Location	None listed					
Special Systems	Kitchen Suppression System		<input type="checkbox"/>	Computer Room Suppression System		<input type="checkbox"/>

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Extinguisher tag expired	<input type="checkbox"/>	Riser tag expired (5 year)	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- Fire extinguishers

Actions/Comments:

- The vast majority of the building is not protected by fire suppression. Due to its construction date, the facility is most likely "grandfathered" by code and the installation of fire sprinklers not required until major renovations are performed. Regardless of when or if installation of facility-wide fire suppression is required by the governing municipality, EMG recommends a retrofit be performed. A budgetary cost is included.

D50 Electrical

Distribution & Lighting			
Electrical Lines	Underground	Transformer	Pole-mounted
Main Service Size	1,200 Amps	Volts	120/208 Volt, three-phase
Meter Location	Electrical room	Branch Wiring	Copper
Conduit	Metallic	Step-Down Transformers?	No
Lighting Fixtures	T-8		
Main Distribution Condition	Fair		
Secondary Panel and Transformer Condition	Fair		
Lighting Condition	Fair		

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Improperly stored material	<input type="checkbox"/>	Unsecured high voltage area	<input type="checkbox"/>
Loose cables or improper use of conduit	<input type="checkbox"/>	Poor electrical room ventilation	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- Circuit breaker panels
- Main switchboard
- Interior light fixtures

Actions/Comments:

- The onsite electrical systems up to the meters are owned and maintained by the respective utility company.
- The electrical service and capacity appear to be adequate for the property's demands.
- The panels, switchboards and lighting vary in age. The electrical service appears to be adequate for the facility's needs. However, due to the age of the panels, switchboards and lighting and increasing difficulty of obtaining replacement parts over time, lifecycle replacements are recommended per above.

D60 Communications

D6060 Public Address Systems					
Item	Description				
Communication Equipment	Public Address System	<input checked="" type="checkbox"/>	Nurse Call System	<input type="checkbox"/>	Clock <input type="checkbox"/>

D70 Electronic Safety and Security

D7010 Access Control and Intrusion Detection / D7050 Detection and Alarm						
Item	Description					
Access Control and Intrusion Detection	Exterior Camera	<input checked="" type="checkbox"/>	Interior Camera	<input checked="" type="checkbox"/>	Front Door Camera Only	<input type="checkbox"/>
	Cameras monitored	<input type="checkbox"/>	Security Personnel On-Site	<input type="checkbox"/>	Intercom/Door Buzzer	<input type="checkbox"/>
Fire Alarm System	Central Alarm Panel	<input checked="" type="checkbox"/>	Battery-Operated Smoke Detectors	<input type="checkbox"/>	Alarm Horns	<input checked="" type="checkbox"/>
	Annunciator Panels	<input type="checkbox"/>	Hard-Wired Smoke Detectors	<input checked="" type="checkbox"/>	Strobe Light Alarms	<input checked="" type="checkbox"/>
	Pull Stations	<input checked="" type="checkbox"/>	Emergency Battery-Pack Lighting	<input type="checkbox"/>	Illuminated EXIT Signs	<input checked="" type="checkbox"/>
Fire Alarm System Condition	Fair					
Central Alarm Panel System	Location of Alarm Panel			Installation Date of Alarm Panel		
	Office			Unknown		

Anticipated Lifecycle Replacements:

- Central alarm panel
- Alarm devices and system
- Public address speakers
- Exit signs
- Defibrillators
- Security system

Actions/Comments:

- The fire alarm systems appear somewhat antiquated and not up to current standards. Due to the age of the components and apparent shortcomings, a full modernization project is recommended. A budgetary cost is included.

6 Equipment & Furnishings

E10 Equipment

The cafeteria kitchen includes the following major appliances, fixtures, and equipment:

E1030 Commercial Kitchen Equipment		
Appliance	Comment	Condition
Refrigerators	Up-right	Fair
Freezers	Up-right	Fair
Ranges	--	--
Ovens	Food warmers	Fair
Griddles / Grills	--	--
Fryers	--	--
Hood	--	--
Dishwasher	--	--
Microwave	<input type="checkbox"/>	--
Ice Machines	<input type="checkbox"/>	--
Steam Tables	<input type="checkbox"/>	--
Work Tables	<input type="checkbox"/>	--
Shelving	<input type="checkbox"/>	--

Anticipated Lifecycle Replacements:

- Food Warmer
- Reach-in freezer
- Reach-in cooler
- Kiln

Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

7 Sitework

G20 Site Improvements

G2020 Parking Lots & G2030 Pedestrian Walkways		
Item	Material	Condition
Entrance Driveway Apron	Asphalt	Good
Parking Lot	Asphalt	Good
Drive Aisles	Asphalt	Good
Service Aisles	Asphalt	Good
Sidewalks	Concrete	Good
Curbs	Concrete	Good
Pedestrian Ramps	None	--
Ground Floor Patio or Terrace	None	--

Parking Count				
Open Lot	Carport	Private Garage	Subterranean Garage	Freestanding Parking Structure
37	-	-	-	-
Total Number of ADA Compliant Spaces			1	
Number of ADA Compliant Spaces for Vans			1	
Total Parking Spaces			37	

Site Stairs			
Location	Material	Handrails	Condition
None	None	None	--

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Pavement oil stains	<input type="checkbox"/>	Vegetation growth in joints	<input type="checkbox"/>
Stair/ramp rails loose	<input type="checkbox"/>	Stair/ramp rail needs scraped and painted	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Degradation Issues			
Observation	Exists At Site	Observation	Exists At Site
Potholes/depressions	<input type="checkbox"/>	Alligator cracking	<input type="checkbox"/>
Concrete spalling	<input type="checkbox"/>	Trip hazards (settlement/heaving)	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- Asphalt seal coating
- Asphalt pavement
- Concrete pavement
- Sidewalks
- Curbs

Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

G2060 Site Development	
Property Signage	
Property Signage	Monument
Street Address Displayed?	Yes

Refuse Disposal				
Refuse Disposal	Common area dumpsters			
Dumpster Locations	Mounting	Enclosure	Contracted?	Condition
North West	Asphalt paving	None	Yes	Fair

Other Site Amenities			
	Description	Location	Condition
Playground Equipment	Plastic and metal	South West	Fair
Tennis Courts	None	--	--
Basketball Court	Asphalt	South West	Fair
Swimming Pool	None	--	--

Anticipated Lifecycle Replacements:

- Signage
- Playground equipment
- Basketball backstops



Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

G2080 Landscaping		
Drainage System and Erosion Control		
System	Exists At Site	Condition
Surface Flow	<input checked="" type="checkbox"/>	Fair
Inlets	<input checked="" type="checkbox"/>	Fair
Swales	<input type="checkbox"/>	--
Detention pond	<input type="checkbox"/>	--
Lagoons	<input type="checkbox"/>	--
Ponds	<input type="checkbox"/>	--
Underground Piping	<input type="checkbox"/>	--
Pits	<input type="checkbox"/>	--
Municipal System	<input type="checkbox"/>	--
Dry Well	<input type="checkbox"/>	--

Anticipated Lifecycle Replacements:

- No components of significance

Actions/Comments:

- There is no evidence of storm water runoff from adjacent properties. The storm water system appears to provide adequate runoff capacity. There is no evidence of major ponding or erosion.

Item	Description						
Site Topography	Slopes down away from the building down to the property lines.						
Landscaping	Trees	Grass	Flower Beds	Planters	Drought Tolerant Plants	Decorative Stone	None
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Landscaping Condition	Fair						
Irrigation	Automatic Underground		Drip		Hand Watering		None
	<input type="checkbox"/>		<input type="checkbox"/>		<input type="checkbox"/>		<input checked="" type="checkbox"/>
Irrigation Condition	--						

Retaining Walls		
Type	Location	Condition
None	--	--

Anticipated Lifecycle Replacements:

- Tree trimming

Actions/Comments:

- Observed hanging limbs that protrude onto the roof. These must be cleared..

G30 Liquid & Gas Site Utilities

G3060 Site Fuel Distribution	
Item	Description
Natural Gas	Gas service is supplied from the gas main on the adjacent public street. The gas meters and regulators are located along the exterior walls of the buildings. The gas distribution piping within the building is malleable steel (black iron).

Anticipated Lifecycle Replacements:

- No components of significance

Actions/Comments:

- The pressure and quantity of gas appear to be adequate.
- The gas meters and regulators appear to be functioning adequately and will require routine maintenance.
- Only limited observation of the gas distribution piping can be made due to hidden conditions.

G40 Electrical Site Improvements

G4050 Site Lighting					
Site Lighting	None	Pole Mounted	Bollard Lights	Ground Mounted	Parking Lot Pole Type
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
--					
Building Lighting	None		Wall Mounted	Recessed Soffit	
	<input type="checkbox"/>		<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Good					

Maintenance Issues			
Observation	Exists At Site	Observation	Exists At Site
Isolated bulb/lamp replacement	<input type="checkbox"/>	Discolored/dirty lens cover	<input type="checkbox"/>
Other	<input type="checkbox"/>	Other	<input type="checkbox"/>

Anticipated Lifecycle Replacements:

- Exterior lighting



Actions/Comments:

- No significant actions are identified at the present time. On-going periodic maintenance is highly recommended. Future lifecycle replacements of the components listed above will be required.

8 Ancillary Structures

Not applicable. There are no major accessory structures.

9 Opinions of Probable Costs

Cost estimates are attached at the front of this report (following the cover page).

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means* and *Marshall & Swift*, EMG's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, and whether competitive pricing is solicited, etc. ASTM E2018-08 recognizes that certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

9.1 Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, EMG opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its effective age. Projections of Remaining Useful Life (RUL) are based on continued use of the Property similar to the reported past use. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be derived from an actual take-off, lump sum costs or allowances are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

9.2 Immediate Repairs

Immediate repairs are opinions of probable costs that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) material building or fire code violations, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

9.3 Replacement Reserves

Replacement Reserves are for recurring probable expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, EMG's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

EMG's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system's or component's respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined in the Immediate Repair Cost Estimate

10 Purpose and Scope

10.1 Purpose

EMG was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record at municipal offices, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

CONDITIONS:

The physical condition of building systems and related components are typically defined as being in one of five conditions: Excellent, Good, Fair, Poor, Failed or a combination thereof. For the purposes of this report, the following definitions are used:

Excellent	=	New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Good	=	Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Fair	=	Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.
Poor	=	Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life.
Failed	=	Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.
Not Applicable	=	Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.

Throughout sections 5 through 9 of this report, each report section will typically contain three subsections organized in the following sequence:

- A descriptive table (and/or narrative), which identifies the components assessed, their condition, and other key data points.
- A simple bulleted list of Anticipated Lifecycle Replacements, which lists components and assets typically in Excellent, Good, or Fair condition at the time of the assessment but that will require replacement or some other attention once aged past their estimated useful life. These listed components are typically included in the associated inventory database with costs identified and budgeted beyond the first several years.
- A bulleted cluster of Actions/Comments, which include more detailed narratives describing deficiencies, recommended repairs, and short term replacements. The assets and components associated with these bullets are/were typically problematic and in Poor or Failed condition at the time of the assessment, with corresponding costs included within the first few years.

PLAN TYPES:

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance. The following Plan Types are listed in general weighted order of importance:

Safety	=	An observed or reported unsafe condition that if left unaddressed could result in an injury; a system or component that presents a potential liability risk.
Performance/Integrity	=	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses a risk to overall system stability.
Accessibility	=	Does not meet ADA, UFAS, and/or other handicap accessibility requirements.
Environmental	=	Improvements to air or water quality, including removal of hazardous materials from the building or site.
Modernization/Adaptation	=	Conditions, systems, or spaces that need to be upgraded in appearance or function to meet current standards, facility usage, or client/occupant needs.
Lifecycle/Renewal	=	Any component or system in which future repair or replacement is anticipated beyond the next several years and/or is of minimal substantial early-term consequence.

10.2 Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a general statement of the subject Property’s compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Perform a limited assessment of accessible areas of the building(s) for the presence of fungal growth, conditions conducive to fungal growth, and/or evidence of moisture. EMG will also interview Project personnel regarding the presence of any known or suspected fungal growth, elevated relative humidity, water intrusion, or mildew-like odors. Potentially affected areas will be photographed. Sampling will not be considered in routine assessments.
- List the current utility service providers.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, in order to gain a clear understanding of the property’s overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report.
- Prepare a mechanical inventory list.

11 Accessibility and Property Research

11.1 ADA Accessibility

Generally, Title III of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of “areas of public accommodations” and “commercial facilities” on the basis of disability. Regardless of its age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

Buildings completed and occupied after January 26, 1992 are required to comply fully with the ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of compliance to the extent allowed by structural feasibility and the financial resources available. As an alternative, a reasonable accommodation pertaining to the deficiency must be made.

During the FCA, a limited visual observation for ADA accessibility compliance was conducted. The scope of the visual observation was limited to those areas set forth in *EMG's Abbreviated Accessibility Checklist* provided in Appendix D of this report. It is understood by the Client that the limited observations described herein does not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of EMG's undertaking. Only a representative sample of areas was observed and, other than as shown on the Abbreviated Accessibility Checklist, actual measurements were not taken to verify compliance.

At a school property, the areas considered as a public accommodation besides the site itself and parking, are the exterior accessible route, the interior accessible route up to the tenant lease lines and the interior common areas, including the common area restrooms.

The facility generally appears to be accessible as stated within the defined priorities of Title III of the Americans with Disabilities Act.

A full ADA Compliance Survey may reveal aspects of the property that are not in compliance.

Corrections of these conditions should be addressed from a liability standpoint but are not necessarily code violations. The Americans with Disabilities Act Accessibility Guidelines concern civil rights issues as they pertain to the disabled and are not a construction code, although many local jurisdictions have adopted the Guidelines as such.

11.2 Flood Zone

According to the Flood Insurance Rate Map, published by the Federal Emergency Management Agency (FEMA) and dated April 3, 2012, the property is located in Zone X, defined as an area outside the 500-year flood plain with less than 0.2% annual probability of flooding. Annual Probability of Flooding of Less than one percent.

12 Certification

Ann Arbor Schools retained EMG to perform this Facility Condition Assessment in connection with its continued operation of Pattengill Elementary, 2100 Crestland Drive, Ann Arbor, Michigan, the "Property". It is our understanding that the primary interest of Ann Arbor Schools is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in depth studies were performed unless specifically required under Section 10 of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas were observed (See Section 4.2 for areas observed). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared on behalf of and exclusively for the use of Ann Arbor Schools for the purpose stated within Section 10 of this report. The report, or any excerpt thereof, shall not be used by any party other than Ann Arbor Schools or for any other purpose than that specifically stated in our agreement or within Section 10 of this report without the express written consent of EMG.

Any reuse or distribution of this report without such consent shall be at Ann Arbor Schools and the recipient's sole risk, without liability to EMG.

Prepared by: James Cuellar,
Project Manager

Reviewed by:



Paul Prusa P.E., LEED AP,
Technical Report Reviewer for
Andrew Hupp
Program Manager
arhupp@emgcorp.com
800.733.0660 x6632

13 Appendices

- Appendix A: Photographic Record
- Appendix B: Site Plan
- Appendix C: Supporting Documentation
- Appendix D: Pre-Survey Questionnaire

Appendix A: Photographic Record



#1:	FRONT ELEVATION
-----	-----------------



#2:	SIDE ELEVATION
-----	----------------



#3:	SIGNAGE
-----	---------



#4:	CRACKED WALL
-----	--------------



#5:	CLASSROOM
-----	-----------



#6:	HALLWAYS
-----	----------



#7:	CLASSROOM
-----	-----------



#8:	MECHANICAL ROOM
-----	-----------------



#9:	WINDOWS
-----	---------




#10:	CLAY BRICK
------	------------



#11:	ROOF
------	------



#12:	ROOF
------	------



#13:	DOORS
------	-------



#14:	DOORS
------	-------




#15:	WOOD FLOORING
------	---------------



#16:	CMU WALLS
------	-----------



#17:	TOILET PARTITIONS
------	-------------------



#18:	CARPET
------	--------



#19:	CERAMIC TILE
------	--------------



#20:	SUSPENDED ACOUSTICAL TILE (ACT)
------	---------------------------------



#21:	VINYL TILE (VCT)
------	------------------



#22:	WATER HEATER
------	--------------



#23:	SINKS
------	-------



#24:	TOILETS
------	---------



#25:	DISTRIBUTION PUMP
------	-------------------



#26:	DUCTLESS SPLIT SYSTEM
------	-----------------------



#27:	BOILERS
------	---------



#28:	AIR COMPRESSOR
------	----------------



#29:	DUCTLESS SPLIT SYSTEM
------	-----------------------



#30:	BUILDING AUTOMATION SYSTEM (HVAC CONTROLS)
------	--



#31:	BASEBOARD HEATER
------	------------------



#32:	BUILDING AUTOMATION SYSTEM (HVAC CONTROLS)
------	--



#33:	BOILERS
------	---------



#34:	FANS
------	------



#35:	CABINET UNITS
------	---------------



#36:	WALL HEATERS
------	--------------



#37: FIRE ALARM CONTROL PANEL



#38: FIRE ALARM SYSTEM, SCHOOL



#39: SWITCHBOARD



#40: SWITCHBOARD




#41: DISTRIBUTION PANEL



#42: LIGHTING SYSTEM

Appendix B: Site Plan

Site Plan



Project Name:
Pattengill Elementary

Project Number:
129010.18R000-020.354

Source:
Google Earth

On-Site Date:
January 31, 2018

Appendix C: Supporting Documentation


Flood Map

National Flood Hazard Layer FIRMeta



42°15'35.08"N

83°43'29.05"W



Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

- SPECIAL FLOOD HAZARD AREAS**
 - Without Base Flood Elevation (BFE) Zone A, V, A99
 - With BFE or Depth
 - Regulatory Floodway Zone AE, AO, AH, VE, AR
- OTHER AREAS OF FLOOD HAZARD**
 - 0.2% Annual Chance Flood Hazard. Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile Zone X
 - Future Conditions 1% Annual Chance Flood Hazard Zone X
 - Area with Reduced Flood Risk due to Levee. See Notes, Zone X
 - Area with Flood Risk due to Levee Zone D
- OTHER AREAS**
 - NO SCREEN Area of Minimal Flood Hazard Zone X
 - Effective LOMRs
 - Area of Undetermined Flood Hazard Zone D
- GENERAL STRUCTURES**
 - Channel, Culvert, or Storm Sewer
 - Levee, Dike, or Floodwall
- CROSS SECTIONS**
 - 20.2 Cross Sections with 1% Annual Chance Water Surface Elevation
 - 17.5 Coastal Transect
 - Base Flood Elevation Line (BFE)
 - Limit of Study
 - Jurisdiction Boundary
- OTHER FEATURES**
 - Coastal Transect Baseline
 - Profile Baseline
 - Hydrographic Feature
- MAP PANELS**
 - Digital Data Available
 - No Digital Data Available
 - Unmapped

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The base map shown complies with FEMA's base map accuracy standards.

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 2/23/2018 at 9:25:49 AM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: base map imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community

Feet 1:6,000 42°15'35.08"N 83°43'29.05"W

	Project Name: Pattengill Elementary	Project Number: 129010.18R000-020.354
	Source: FEMA Map Number: 26161C0263E Dated: April 3, 2012	On-Site Date: January 31, 2018

Appendix D: Pre-Survey Questionnaire

**THIS APPENDIX IS INTENTIONALLY LEFT
BLANK.**

On the day of the site visit, provide EMG's Field Observer access to all of the available documents listed below. Provide copies if possible.

<p>INFORMATION REQUIRED</p> <ol style="list-style-type: none"> 1. All available construction documents (blueprints) for the original construction of the building or for any tenant improvement work or other recent construction work. 2. A site plan, preferably 8 1/2" X 11", which depicts the arrangement of buildings, roads, parking stalls, and other site features. 3. For commercial properties, provide a tenant list which identifies the names of each tenant, vacant tenant units, the floor area of each tenant space, and the gross and net leasable area of the building(s). 4. For apartment properties, provide a summary of the apartment unit types and apartment unit type quantities, including the floor area of each apartment unit as measured in square feet. 5. For hotel or nursing home properties, provide a summary of the room types and room type quantities. 6. Copies of Certificates of Occupancy, building permits, fire or health department inspection reports, elevator inspection certificates, roof or HVAC warranties, or any other similar, relevant documents. 7. The names of the local utility companies which serve the property, including the water, sewer, electric, gas, and phone companies. 	<ol style="list-style-type: none"> 8. The company name, phone number, and contact person of all outside vendors who serve the property, such as mechanical contractors, roof contractors, fire sprinkler or fire extinguisher testing contractors, and elevator contractors. 9. A summary of recent (over the last 5 years) capital improvement work which describes the scope of the work and the estimated cost of the improvements. Executed contracts or proposals for improvements. Historical costs for repairs, improvements, and replacements. 10. Records of system & material ages (roof, MEP, paving, finishes, furnishings). 11. Any brochures or marketing information. 12. Appraisal, either current or previously prepared. 13. Current occupancy percentage and typical turnover rate records (for commercial and apartment properties). 14. Previous reports pertaining to the physical condition of property. 15. ADA survey and status of improvements implemented. 16. Current / pending litigation related to property condition.
--	---

Your timely compliance with this request is greatly appreciated.