

January 15, 2021

Mr. Mike Williams
Facilities Supervisor
Kyrene School District No. 28
8700 South Kyrene Road
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection
Asbestos-Containing Building Materials
Kyrene de los Lagos Elementary School
17001 South 34th Way, Phoenix
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: None.

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC



Michael Hall
Environmental Division Manager

*Attachments: 3-Year Reinspection Tables
3-Year Reinspection Forms*

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-STU-03	S	Stucco, Gray, Cementitious	Storage 79A	Assumed	NF	G	7,000	SF	09/22/21
			Courtyard						
			Exterior						
			Roof						
M-MRT-08	M	Mortar (Glass Block), White, Cementitious	Reception 02	Assumed	NF	G	150	SF	09/22/21
			Treatment 06						
			Kindergarten 23						
			Kindergarten 26						
			1 st Grade 28						
			1 st Grade 29						
			1 st Grade 31						
			2 nd Grade 32						
			2 nd Grade 39						
			2 nd Grade 40						
			3 rd Grade 44						
			3 rd Grade 45						
			3 rd Grade 46						
			Gifted 47						
			Foyer 42						
			Computer 50						
			Special Ed. 75						
			Special Ed. 76						
			Special Ed. 77						
			Multi-Purpose 91						
			6 th Grade 70						
			6 th Grade 71						
			Art 79						
			6 th Grade 80						
			4 th Grade 63						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			5 th Grade 64						
			5 th Grade 68						
			5 th Grade 69						
			Corridor 01						
			Corridor 25						
			Corridor 30						
			Corridor 43						
			Corridor 48						
			Corridor 60						
			Corridor 67						
			Corridor 78						
			Corridor 81						
			Exterior						
M-QPT-09	M	Quarry/Paver Tile, 4'x6', Red, Cementitious	Exterior	Assumed	NF	G	150	SF	09/22/21
M-BUR-10	M	Built-Up Roofing, Black, Asphaltic, Gray Gravel Cap	Roof	Assumed	NF	G	55,000	SF	09/22/21
M-MAS-11	M	Mastic (Penetrations and Flashings), Black, Tar-Like, Silver Coating	Roof	Assumed	NF	G	100	SF	09/22/21
M-SLT-12	M	Sealant (Windows), Black, Pliable	Roof	Assumed	NF	G	4	SF	09/22/21
M-FDI-20	M	Fire Door Insulation, Metal Cladding	Reception 02	Assumed	NF	G	819	SF	09/22/21
			Treatment 06						
			Kindergarten 23						
			Kindergarten 26						
			Room 35B						
			Boy's Restroom 38						
			Storage 101						
			Room 47A						
			Room 83A						
			Wings 88						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Multi-Purpose 91						
			Kitchen 94						
			Art 79						
			Storage 79a						
			Room 107						
			Corridor 01						
			Corridor 25						
			Corridor 30						
			Corridor 43						
			Corridor 48						
			Corridor 59						
			Corridor 60						
			Corridor 67						
			Corridor 78						
			Corridor 81						
			Corridor 102						
			Courtyard						
			Equipment Pad						
			Exterior						
M-FDI-21	M	Fire Door Insulation, Wood Cladding	Reception 02	Assumed	NF	G	1,743	SF	09/22/21
			Principal 04						
			Room 04A						
			Storage 09						
			Faculty Lounge 16						
			Storage 19						
			Hall 20						
			Men's Restroom 21						
			Women's Restroom 22						
			Janitor 49						
			Kindergarten 23						
			Kindergarten 26						
			1 st Grade 28						
			1 st Grade 29						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			1 st Grade 31						
			2 nd Grade 32						
			Hall 33						
			Girl's Restroom 35						
			Room 35A						
			Room 35B						
			2 nd Grade 39						
			2 nd Grade 40						
			3 rd Grade 44						
			3 rd Grade 45						
			3 rd Grade 46						
			Gifted 47						
			Foyer 42						
			Computer 50						
			Library 51						
			Work 53						
			A/V 54						
			Speech 56						
			Girl's Restroom 83						
			Room 83A						
			Room 83B						
			Hall 82						
			Boy's Restroom 86						
			Special Ed. 75						
			Special Ed. 76						
			Special Ed. 77						
			Psychology 100						
			Music 87						
			Room 87A						
			Wings 90						
			Multi-Purpose 91						
			Men's Restroom 92A						
			Women's Restroom 93A						
			Kitchen 94						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 95						
			Room 95A						
			P.E. Storage 96						
			6 th Grade 70						
			6 th Grade 71						
			Art 79						
			6 th Grade 80						
			Foyer 66						
			4 th Grade 63						
			5 th Grade 64						
			5 th Grade 68						
			5 th Grade 69						
			4 th Grade 61						
			4 th Grade 62						
			Classroom 103						
			Classroom 104						
			Room 105						
			Room 106						
			Toilet 108						
			Classroom 109						
			Classroom 110						
			Electrical 112						
			Corridor 01						
			Corridor 03						
			Corridor 25						
			Corridor 30						
			Corridor 43						
			Corridor 48						
			Corridor 59						
			Corridor 60						
			Corridor 67						
			Corridor 72						
			Corridor 78						
			Corridor 81						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 102						
M·SLT·24	M	Sealant, Black, Tar-Like	Treatment 06	2-5% Chrysotile	NF	G	20	SF	09/22/21
			Nurse 11						
			Foyer 42						
			Library 51						
			Work 53						
			Speech 56						
			Room 56A						
			Room 56B						
			Foyer 66						
			Special Ed. 75						
			Room 75A						
			Corridor 03						
M·ADH·35	M	Adhesive (FRP), Brown, Brittle	Janitor 49	Assumed	NF	G	50	SF	09/22/21
			Kitchen 94						
M·GWT·38	M	Glazed Wall Tile, 4"X4", White, Smooth, Black and Pink Pattern	Girl's Restroom 35	Assumed	NF	G	5,000	SF	09/22/21
			Room 35B						
			Boy's Restroom 38						
			Girl's Restroom 83						
			Room 83A						
			Boy's Restroom 86						
			Men's Restroom 92A						
			Women's Restroom 93A						
M·GRT·39	M	Grout, Gray, Cementitious	Girl's Restroom 35	Assumed	NF	G	500	SF	09/22/21
			Room 35B						
			Boy's Restroom 38						
			Girl's Restroom 83						
			Room 83A						
			Boy's Restroom 86						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Men's Restroom 92A						
			Women's Restroom 93A						
M-CMT-40	M	Ceramic Mosaic Tile, 2"X2", Pink, Smooth	Girl's Restroom 35	Assumed	NF	G	2,500	SF	09/22/21
			Room 35B						
			Boy's Restroom 38						
			Girl's Restroom 83						
			Room 83A						
			Boy's Restroom 86						
			Men's Restroom 92A						
			Women's Restroom 93A						
M-GRT-41	M	Grout, Gray, Cementitious, Associated with Ceramic	Girl's Restroom 35	Assumed	NF	G	250	SF	09/22/21
			Room 35B						
			Boy's Restroom 38						
			Girl's Restroom 83						
			Room 83A						
			Boy's Restroom 86						
			Men's Restroom 92A						
			Women's Restroom 93A						
M-VST-48	M	Vinyl Stair Tread, 12"X36", Brown, Textured, Circle Pattern	Wings 90	Assumed	NF	G	20	SF	09/22/21
M-ADH-49	M	Adhesive, Brown, Brittle	Wings 90	Assumed	NF	G	20	SF	09/22/21
M-VCT-53	M	Vinyl Composition Tile, 12"X12", White, Smooth, Cream Mottles	Multi-Purpose 91	Assumed	NF	G	5,000	SF	09/22/21
M-VCT-54	M	Vinyl Composition Tile (Strip), 2", Black, Smooth	Multi-Purpose 91	Assumed	NF	G	50	SF	09/22/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-VCT-55	M	Vinyl Composition Tile (Strip), 1", Green, Smooth	Multi-Purpose 91	Assumed	NF	G	50	SF	09/22/21
M-VCT-56	M	Vinyl Composition Tile (Strip), 1", Yellow, Smooth	Multi-Purpose 91	Assumed	NF	G	50	SF	09/22/21
M-VCT-57	M	Vinyl Composition Tile, 12"X12", Green, Smooth	Multi-Purpose 91	Assumed	NF	G	50	SF	09/22/21
M-VCT-58	M	Vinyl Composition Tile, 12"X12", Yellow, Smooth	Multi-Purpose 91	Assumed	NF	G	50	SF	09/22/21
M-VCT-59	M	Vinyl Composition Tile, 12"X12", Red, Smooth	Multi-Purpose 91	Assumed	NF	G	50	SF	09/22/21
M-MAS-60	M	Mastic, Yellow, Tacky	Multi-Purpose 91	Assumed	NF	G	5,000	SF	09/22/21
M-APL-63	M	Acoustical Ceiling Panel, 2'x4', White, Chalky, Vinyl Cover	Kitchen 94	Assumed	NF	G	1,000	SF	09/22/21
M-GWT-71	M	Glazed Wall Tile, 6"X6", White, Smooth	Room 105	Assumed	NF	G	1,500	SF	09/22/21
			Room 106						
			Toilet 108						
M-GRT-72	M	Grout, White, Cementitious	Room 105	Assumed	NF	G	150	SF	09/22/21
			Room 106						
			Toilet 108						
M-QPT-73	M	Quarry/Paver Tile, 8"X8", Tan, Smooth, Peppered	Room 105	Assumed	NF	G	1,200	SF	09/22/21
			Room 106						
			Toilet 108						
M-GRT-74	M	Grout, Gray, Cementitious	Room 105	Assumed	NF	G	120	SF	09/22/21
			Room 106						
			Toilet 108						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-PES-76	M	Pipe End Sealant, White, Pliable	Electrical 112	Assumed	NF	G	20	SF	09/22/21
			Equipment Pad						
M-CON-77	M	Concrete, Gray, Cementitious	Equipment Pad	Assumed	NF	G	6,300	SF	09/22/21
M-GAS-78	M	Gasket, 4"-6", Green, Paper-Like	Equipment Pad	Assumed	NF	G	5	SF	09/22/21
M-SLT-79	M	Sealant, Gray, Pliable	Equipment Pad	Assumed	NF	G	5	SF	09/22/21
S-TOT-80	M	Troweled-On Texture, White, Chalky	Room 107	Assumed	NF	G	250	SF	09/22/21
M-GWB-81	M	Gypsum Wallboard, White, Chalky	Room 107	Assumed	NF	G	250	SF	09/22/21
S-JTC-82	M	Joint Compound, White, Chalky	Room 107	Assumed	NF	G	25	SF	09/22/21
M-GAS-83	M	Gasket, 10"-12", Red, Paper-Like	Room 107	Assumed	NF	G	2	SF	09/22/21
M-GWB-84	M	Gypsum Wallboard, White, Chalky	Room 47A	Assumed	NF	G	260	SF	09/22/21
S-JTC-85	M	Joint Compound, White, Chalky	Room 47A	Assumed	NF	G	26	SF	09/22/21
M-SLT-205	M	Sealant (Duct), Gray, Pliable	A1 Storage 111	Assumed	NF	G	5	SF	09/22/21
			A1 Staff Restroom 112						
			A1 Storage 113						
			A1 Classroom 115						
			A1 Classroom 116						
			A1 Classroom 117						
			A1 Girl's Restroom 118						
			A1 Boy's Restroom 119						
			A1 Classroom 120						
			A1 Classroom 121						
			A1 Corridor 114						
			A1 Corridor 122						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-FDI-227	M	Fire Door Insulation, Metal/Wood Cladding	A1 Staff Restroom 112	Assumed	NF	G	378	SF	
			A1 Storage 113						
			A1 Classroom 115						
			A1 Classroom 116						
			A1 Classroom 117						
			A1 Girl's Restroom 118						
			A1 Boy's Restroom 119						
			A1 Classroom 120						
			A1 Classroom 121						
			A1 Corridor 114						
			A1 Corridor 122						
			Exterior						
M-SLT-305	M	Sealant (Duct), Gray, Pliable	A2 Classroom 123	Assumed	NF	G	5	SF	09/22/21
			Room A2 123A						
			A2 Classroom 124						
			Room A2 124a						
			A2 Corridor 125						



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4301261 4369 Signature of Inspector: Carbyn Hall

*Material Reinspected: S-STU-03, Stucco, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 430 1261 12314 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-MRT-08, Mortar (Glass Block), White, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4370 12501 12316 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-QPT-09, Quarry/Paver Tile, 4'x6', Red, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Han
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4370 4501 12345 Signature of Inspector: Carbyn Han

*Material Reinspected: M-BUR-10, Built-Up Roofing, Black, Asphaltic, Gray Gravel Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carlynn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 430125112316A Signature of Inspector: Carlynn Hall

*Material Reinspected: M-MAS-11, Mastic (Penetrations and Flashings), Black, Tar-Like, Silver Coating

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low 1
Degree of Activity Near the Material: High _____ Medium _____ Low 1
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: ~~435120120164~~ Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-12, Sealant (Windows), Black, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____
Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4310 1252 12362 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-20, Fire Door Insulation, Metal Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: ~~4370 1251 1314~~ Signature of Inspector: Carbyn Hall

*Material Reinspected: M-FDI-21, Fire Door Insulation, Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 4/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4312 1221 1213 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-24, Sealant, Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 43761261123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-ADH-35, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: ~~4370 1261 123164~~ Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GWT-38, Glazed Wall Tile, 4"X4", White, Smooth, Black and Pink Pattern

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: ~~4370 1260 1236~~ Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-39, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4320 1261 12314 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-CMT-40, Ceramic Mosaic Tile, 2"X2", Pink, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4320 1250 12304 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-41, Grout, Gray, Cementitious, Associated with Ceramic

Type of Asbestos-Containing Material: 1. Surf. 2. TSI Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4370 1201 123169 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-VST-48, Vinyl Stair Tread, 12"X36", Brown, Textured, Circle Pattern

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4310 1251 2304 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-ADH-49, Adhesive, Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: ~~439-129-1234~~ Signature of Inspector: Corbyn Hall

*Material Reinspected: M-VCT-53, Vinyl Composition Tile, 12"X12", White, Smooth, Cream Mottles

Type of Asbestos-Containing Material: 1. Surf. 2. TSI **(3)** Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No
Evidence of Water Damage: _____ Yes No
Evidence of Delamination or Other Damage: _____ Yes No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4370 1261 12345 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-VCT-54, Vinyl Composition Tile (Strip), 2", Black, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI **3** Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4370 1451 123169 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-VCT-55, Vinyl Composition Tile (Strip), 1", Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4370 1201 1234 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-VCT-56, Vinyl Composition Tile (Strip), 1", Yellow, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 43812011234 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-VCT-57, Vinyl Composition Tile, 12"X12", Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI **3** Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / **No**
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / **No**
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / **No**
Evidence of Water Damage: _____ Yes / **No**
Evidence of Delamination or Other Damage: _____ Yes / **No**
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / **No**
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / **No**

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / **No**
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4370 1261 0004 Signature of Inspector: Coryn Hall

*Material Reinspected: M-VCT-58, Vinyl Composition Tile, 12"X12", Yellow, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: ~~4387 1202 12364~~ Signature of Inspector: Carbyn Hall

*Material Reinspected: M-VCT-59, Vinyl Composition Tile, 12"X12", Red, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4376 P01 0364 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-MAS-60, Mastic, Yellow, Tacky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4370 D001 0364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-APL-63, Acoustical Ceiling Panel, 2'x4', White, Chalky, Vinyl Cover

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High _____ Medium ✓ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carson Hall

Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 43701280122067 Signature of Inspector: Carson Hall

*Material Reinspected: M-GWT-71, Glazed Wall Tile, 6"X6", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4370 12501 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-72, Grout, White, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4310 1231 12314 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-QPT-73, Quarry/Paver Tile, 8"X8", Tan, Smooth, Peppered

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 435005012364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-74, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4316 1201 123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PES-76, Pipe End Sealant, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4380125012316A Signature of Inspector: Carbyn Hall

*Material Reinspected: M-CON-77, Concrete, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 430125012304 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GAS-78, Gasket, 4"-6", Green, Paper-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main
AHERA certification number: 438 1251 12344 Signature of Inspector: Carbyn Hall
*Material Reinspected: M-SLT-79, Sealant, Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbor Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 430 1201 12316 Signature of Inspector: Carbor Hall

*Material Reinspected: S-TOT-80, Troweled-On Texture, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: ~~1310 1321 1331~~ Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GWB-81, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: ~~43101250112316~~ Signature of Inspector: Carbyn Hall

*Material Reinspected: S-JTC-82, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4596125012316 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GAS-83, Gasket, 10"-12", Red, Paper-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

• G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Lagos\FORMS\Main\83.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4370 1251 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWB-84, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 43612511236 Signature of Inspector: Carbyn Hall

*Material Reinspected: S-JTC-85, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Ham
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4390 1281 123164 Signature of Inspector: Corbyn Ham

*Material Reinspected: M-SLT-205, Sealant (Duct), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbon Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 4380125d 123169 Signature of Inspector: Carbon Hall

*Material Reinspected: M-FDI-227, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Lagos Elementary School Building Name/Number: Main

AHERA certification number: 430 1201 123164 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-SLT-305, Sealant (Duct), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI **3** Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-STU-03	S	Stucco, Gray, Cementitious	Storage 79A	Assumed	NF	G	7,000	SF	09/22/21
			Courtyard						
			Exterior						
			Roof						
M-MRT-08	M	Mortar (Glass Block), White, Cementitious	Reception 02	Assumed	NF	G	150	SF	09/22/21
			Treatment 06						
			Kindergarten 23						
			Kindergarten 26						
			1 st Grade 28						
			1 st Grade 29						
			1 st Grade 31						
			2 nd Grade 32						
			2 nd Grade 39						
			2 nd Grade 40						
			3 rd Grade 44						
			3 rd Grade 45						
			3 rd Grade 46						
			Gifted 47						
			Foyer 42						
			Computer 50						
			Special Ed. 75						
			Special Ed. 76						
			Special Ed. 77						
			Multi-Purpose 91						
			6 th Grade 70						
			6 th Grade 71						
			Art 79						
			6 th Grade 80						
			4 th Grade 63						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			5 th Grade 64						
			5 th Grade 68						
			5 th Grade 69						
			Corridor 01						
			Corridor 25						
			Corridor 30						
			Corridor 43						
			Corridor 48						
			Corridor 60						
			Corridor 67						
			Corridor 78						
			Corridor 81						
			Exterior						
M-QPT-09	M	Quarry/Paver Tile, 4'x6', Red, Cementitious	Exterior	Assumed	NF	G	150	SF	09/22/21
M-BUR-10	M	Built-Up Roofing, Black, Asphaltic, Gray Gravel Cap	Roof	Assumed	NF	G	55,000	SF	09/22/21
M-MAS-11	M	Mastic (Penetrations and Flashings), Black, Tar-Like, Silver Coating	Roof	Assumed	NF	G	100	SF	09/22/21
M-SLT-12	M	Sealant (Windows), Black, Pliable	Roof	Assumed	NF	G	4	SF	09/22/21
M-FDI-20	M	Fire Door Insulation, Metal Cladding	Reception 02	Assumed	NF	G	819	SF	09/22/21
			Treatment 06						
			Kindergarten 23						
			Kindergarten 26						
			Room 35B						
			Boy's Restroom 38						
			Storage 101						
			Room 47A						
			Room 83A						
			Wings 88						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Multi-Purpose 91						
			Kitchen 94						
			Art 79						
			Storage 79a						
			Room 107						
			Corridor 01						
			Corridor 25						
			Corridor 30						
			Corridor 43						
			Corridor 48						
			Corridor 59						
			Corridor 60						
			Corridor 67						
			Corridor 78						
			Corridor 81						
			Corridor 102						
			Courtyard						
			Equipment Pad						
			Exterior						
M-FDI-21	M	Fire Door Insulation, Wood Cladding	Reception 02	Assumed	NF	G	1,743	SF	09/22/21
			Principal 04						
			Room 04A						
			Storage 09						
			Faculty Lounge 16						
			Storage 19						
			Hall 20						
			Men's Restroom 21						
			Women's Restroom 22						
			Janitor 49						
			Kindergarten 23						
			Kindergarten 26						
			1 st Grade 28						
			1 st Grade 29						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			1 st Grade 31						
			2 nd Grade 32						
			Hall 33						
			Girl's Restroom 35						
			Room 35A						
			Room 35B						
			2 nd Grade 39						
			2 nd Grade 40						
			3 rd Grade 44						
			3 rd Grade 45						
			3 rd Grade 46						
			Gifted 47						
			Foyer 42						
			Computer 50						
			Library 51						
			Work 53						
			A/V 54						
			Speech 56						
			Girl's Restroom 83						
			Room 83A						
			Room 83B						
			Hall 82						
			Boy's Restroom 86						
			Special Ed. 75						
			Special Ed. 76						
			Special Ed. 77						
			Psychology 100						
			Music 87						
			Room 87A						
			Wings 90						
			Multi-Purpose 91						
			Men's Restroom 92A						
			Women's Restroom 93A						
			Kitchen 94						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 95						
			Room 95A						
			P.E. Storage 96						
			6 th Grade 70						
			6 th Grade 71						
			Art 79						
			6 th Grade 80						
			Foyer 66						
			4 th Grade 63						
			5 th Grade 64						
			5 th Grade 68						
			5 th Grade 69						
			4 th Grade 61						
			4 th Grade 62						
			Classroom 103						
			Classroom 104						
			Room 105						
			Room 106						
			Toilet 108						
			Classroom 109						
			Classroom 110						
			Electrical 112						
			Corridor 01						
			Corridor 03						
			Corridor 25						
			Corridor 30						
			Corridor 43						
			Corridor 48						
			Corridor 59						
			Corridor 60						
			Corridor 67						
			Corridor 72						
			Corridor 78						
			Corridor 81						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 102						
M·SLT·24	M	Sealant, Black, Tar-Like	Treatment 06	2-5% Chrysotile	NF	G	20	SF	09/22/21
			Nurse 11						
			Foyer 42						
			Library 51						
			Work 53						
			Speech 56						
			Room 56A						
			Room 56B						
			Foyer 66						
			Special Ed. 75						
			Room 75A						
			Corridor 03						
M·ADH·35	M	Adhesive (FRP), Brown, Brittle	Janitor 49	Assumed	NF	G	50	SF	09/22/21
			Kitchen 94						
M·GWT·38	M	Glazed Wall Tile, 4"X4", White, Smooth, Black and Pink Pattern	Girl's Restroom 35	Assumed	NF	G	5,000	SF	09/22/21
			Room 35B						
			Boy's Restroom 38						
			Girl's Restroom 83						
			Room 83A						
			Boy's Restroom 86						
			Men's Restroom 92A						
			Women's Restroom 93A						
M·GRT·39	M	Grout, Gray, Cementitious	Girl's Restroom 35	Assumed	NF	G	500	SF	09/22/21
			Room 35B						
			Boy's Restroom 38						
			Girl's Restroom 83						
			Room 83A						
			Boy's Restroom 86						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Men's Restroom 92A						
			Women's Restroom 93A						
M-CMT-40	M	Ceramic Mosaic Tile, 2"X2", Pink, Smooth	Girl's Restroom 35	Assumed	NF	G	2,500	SF	09/22/21
			Room 35B						
			Boy's Restroom 38						
			Girl's Restroom 83						
			Room 83A						
			Boy's Restroom 86						
			Men's Restroom 92A						
			Women's Restroom 93A						
M-GRT-41	M	Grout, Gray, Cementitious, Associated with Ceramic	Girl's Restroom 35	Assumed	NF	G	250	SF	09/22/21
			Room 35B						
			Boy's Restroom 38						
			Girl's Restroom 83						
			Room 83A						
			Boy's Restroom 86						
			Men's Restroom 92A						
			Women's Restroom 93A						
M-VST-48	M	Vinyl Stair Tread, 12"X36", Brown, Textured, Circle Pattern	Wings 90	Assumed	NF	G	20	SF	09/22/21
M-ADH-49	M	Adhesive, Brown, Brittle	Wings 90	Assumed	NF	G	20	SF	09/22/21
M-VCT-53	M	Vinyl Composition Tile, 12"X12", White, Smooth, Cream Mottles	Multi-Purpose 91	Assumed	NF	G	5,000	SF	09/22/21
M-VCT-54	M	Vinyl Composition Tile (Strip), 2", Black, Smooth	Multi-Purpose 91	Assumed	NF	G	50	SF	09/22/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-VCT-55	M	Vinyl Composition Tile (Strip), 1", Green, Smooth	Multi-Purpose 91	Assumed	NF	G	50	SF	09/22/21
M-VCT-56	M	Vinyl Composition Tile (Strip), 1", Yellow, Smooth	Multi-Purpose 91	Assumed	NF	G	50	SF	09/22/21
M-VCT-57	M	Vinyl Composition Tile, 12"x12", Green, Smooth	Multi-Purpose 91	Assumed	NF	G	50	SF	09/22/21
M-VCT-58	M	Vinyl Composition Tile, 12"x12", Yellow, Smooth	Multi-Purpose 91	Assumed	NF	G	50	SF	09/22/21
M-VCT-59	M	Vinyl Composition Tile, 12"x12", Red, Smooth	Multi-Purpose 91	Assumed	NF	G	50	SF	09/22/21
M-MAS-60	M	Mastic, Yellow, Tacky	Multi-Purpose 91	Assumed	NF	G	5,000	SF	09/22/21
M-APL-63	M	Acoustical Ceiling Panel, 2'x4', White, Chalky, Vinyl Cover	Kitchen 94	Assumed	NF	G	1,000	SF	09/22/21
M-GWT-71	M	Glazed Wall Tile, 6"x6", White, Smooth	Room 105	Assumed	NF	G	1,500	SF	09/22/21
			Room 106						
			Toilet 108						
M-GRT-72	M	Grout, White, Cementitious	Room 105	Assumed	NF	G	150	SF	09/22/21
			Room 106						
			Toilet 108						
M-QPT-73	M	Quarry/Paver Tile, 8"x8", Tan, Smooth, Peppered	Room 105	Assumed	NF	G	1,200	SF	09/22/21
			Room 106						
			Toilet 108						
M-GRT-74	M	Grout, Gray, Cementitious	Room 105	Assumed	NF	G	120	SF	09/22/21
			Room 106						
			Toilet 108						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-PES-76	M	Pipe End Sealant, White, Pliable	Electrical 112	Assumed	NF	G	20	SF	09/22/21
			Equipment Pad						
M-CON-77	M	Concrete, Gray, Cementitious	Equipment Pad	Assumed	NF	G	6,300	SF	09/22/21
M-GAS-78	M	Gasket, 4"-6", Green, Paper-Like	Equipment Pad	Assumed	NF	G	5	SF	09/22/21
M-SLT-79	M	Sealant, Gray, Pliable	Equipment Pad	Assumed	NF	G	5	SF	09/22/21
S-TOT-80	M	Troweled-On Texture, White, Chalky	Room 107	Assumed	NF	G	250	SF	09/22/21
M-GWB-81	M	Gypsum Wallboard, White, Chalky	Room 107	Assumed	NF	G	250	SF	09/22/21
S-JTC-82	M	Joint Compound, White, Chalky	Room 107	Assumed	NF	G	25	SF	09/22/21
M-GAS-83	M	Gasket, 10"-12", Red, Paper-Like	Room 107	Assumed	NF	G	2	SF	09/22/21
M-GWB-84	M	Gypsum Wallboard, White, Chalky	Room 47A	Assumed	NF	G	260	SF	09/22/21
S-JTC-85	M	Joint Compound, White, Chalky	Room 47A	Assumed	NF	G	26	SF	09/22/21
M-SLT-205	M	Sealant (Duct), Gray, Pliable	A1 Storage 111	Assumed	NF	G	5	SF	09/22/21
			A1 Staff Restroom 112						
			A1 Storage 113						
			A1 Classroom 115						
			A1 Classroom 116						
			A1 Classroom 117						
			A1 Girl's Restroom 118						
			A1 Boy's Restroom 119						
			A1 Classroom 120						
			A1 Classroom 121						
			A1 Corridor 114						
			A1 Corridor 122						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-FDI-227	M	Fire Door Insulation, Metal/Wood Cladding	A1 Staff Restroom 112	Assumed	NF	G	378	SF	
			A1 Storage 113						
			A1 Classroom 115						
			A1 Classroom 116						
			A1 Classroom 117						
			A1 Girl's Restroom 118						
			A1 Boy's Restroom 119						
			A1 Classroom 120						
			A1 Classroom 121						
			A1 Corridor 114						
			A1 Corridor 122						
			Exterior						
M-SLT-305	M	Sealant (Duct), Gray, Pliable	A2 Classroom 123	Assumed	NF	G	5	SF	09/22/21
			Room A2 123A						
			A2 Classroom 124						
			Room A2 124a						
			A2 Corridor 125						

**3-YEAR REINSPECTION
 IN-PLACE ASBESTOS-CONTAINING MATERIALS**

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Lagos\R5,R6-Tbl.doc

3YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Lagos\R7,R8-Tbl.doc

3-YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Lagos\R9,R12-Tbl.doc

3-YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Lagos\RR-Tbl.doc