

November 5, 2021

Mr. Mike Williams
Facilities Supervisor
Kyrene School District No. 28
8700 South Kyrene Road
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection
Asbestos-Containing Building Materials
Kyrene Akimel A-al Middle School
2720 East Liberty Lane, Phoenix
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: none.

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC



Michael Hall
Environmental Division Manager

Attachments: *3-Year Reinspection Tables*
3-Year Reinspection Forms

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-VCT-10	M	Vinyl Composition Tile, 12"X12", White, Smooth, Gray Mottles	Athletic Storage	Assumed	NF	G	10,000	SF	10/04/21
			Storage 17						
			Work Room						
			Supply Room 1						
			Supply Room 2						
			Mail Room						
			Faculty Lounge						
			Water Heater						
			Storage 16						
			Room D-12 Time Out						
			Room D-12 Restroom						
			Electrical 6						
			Storage 18						
			Health Restroom						
			Treatment						
			Teacher Workroom						
			Storage 20						
			Classroom D-8						
			Classroom D-9						
			Storage 19						
			Room D-9 Restroom						
			Room D-9 Time Out						
			Classroom A-1						
			Classroom A-2						
			Classroom A-3						
			Classroom A-4						
			Classroom A-5						
			Classroom A-6						
			Classroom A-7						
			Classroom A-8						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom A-11						
			Classroom A-12						
			Classroom A-13						
			Classroom A-14						
			Classroom A-15						
			Special Ed A-9						
			Special Ed A-10						
			Custodial 4						
			Workroom 1						
			Storage 13						
			Electrical 5						
			Storage 12						
			Custodial 3						
			Storage 9						
			Storage 10						
			Electrical 04						
			Storage 11						
			Classroom B-5						
			Classroom B-7						
			Classroom B-8						
			Classroom B-11						
			Classroom B-12						
			Classroom B-13						
			Classroom B-14						
			Classroom B-15						
			Classroom B-16						
			Classroom B-17						
			Classroom B-18						
			Special Ed B-9						
			Special Ed B-10						
			Electrical 03						
			Storage 7						
			Computer Lab 2						
			Storage 8						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Custodian 2						
			Storage 6						
			Classroom C-1						
			Classroom C-2						
			Classroom C-3						
			Classroom C-4						
			Storage 2						
			Classroom C-5						
			Classroom C-6						
			Classroom C-7						
			Science Classroom C-8						
			Riser Room						
			Science Classroom C-11						
			Classroom C-12						
			Classroom C-13						
			Classroom C-14						
			Classroom C-15						
			Classroom C-16						
			Classroom C-17						
			Classroom C-18						
			Special Ed C-9						
			Special Ed C-10						
			Electrical 02						
			Storage 4						
			Storage 5						
			Computer Lab 1						
			Custodian 1						
			Storage 3						
			Corridor 1-2						
M-VCT-11	M	Vinyl Composition Tile (Pattern), 12"X12", Blue, Smooth, Dark Blue Specks	Treatment	Assumed	NF	G	500	SF	10/04/21
			Classroom D-8						
			Classroom D-9						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom A-1						
			Classroom A-2						
			Classroom A-3						
			Classroom A-6						
			Classroom A-7						
			Classroom A-8						
			Classroom A-11						
			Classroom A-12						
			Classroom A-13						
			Classroom A-14						
			Classroom A-15						
			Special Ed A-9						
			Special Ed A-10						
			Classroom B-5						
			Classroom B-7						
			Classroom B-8						
			Classroom B-11						
			Classroom B-12						
			Classroom B-13						
			Classroom B-14						
			Classroom B-15						
			Classroom B-16						
			Classroom B-17						
			Classroom B-18						
			Special Ed B-9						
			Special Ed B-10						
			Classroom C-1						
			Classroom C-2						
			Classroom C-3						
			Classroom C-4						
			Classroom C-6						
			Classroom C-7						
			Science Classroom C-8						
			Science Classroom C-11						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom C-12						
			Classroom C-13						
			Classroom C-14						
			Classroom C-15						
			Classroom C-16						
			Classroom C-17						
			Classroom C-18						
			Special Ed C-9						
			Special Ed C-10						
M-VCT-12	M	Vinyl Composition Tile (Pattern), 12"X12", Tan, Smooth, Gray Mottles	Faculty Lounge	Assumed	NF	G	500	SF	10/04/21
			Treatment						
			Teacher Workroom						
			Classroom D-8						
			Classroom D-9						
			Classroom A-1						
			Classroom A-2						
			Classroom A-3						
			Classroom A-6						
			Classroom A-7						
			Classroom A-8						
			Classroom A-11						
			Classroom A-12						
			Classroom A-13						
			Classroom A-14						
			Classroom A-15						
			Special Ed A-9						
			Special Ed A-10						
			Classroom B-5						
			Classroom B-7						
			Classroom B-8						
			Classroom B-11						
			Classroom B-12						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom B-13						
			Classroom B-14						
			Classroom B-15						
			Classroom B-16						
			Classroom B-17						
			Classroom B-18						
			Special Ed B-9						
			Special Ed B-10						
			Classroom C-1						
			Classroom C-2						
			Classroom C-3						
			Classroom C-4						
			Classroom C-6						
			Classroom C-7						
			Science Classroom C-8						
			Science Classroom C-11						
			Classroom C-12						
			Classroom C-13						
			Classroom C-14						
			Classroom C-15						
			Classroom C-16						
			Classroom C-17						
			Classroom C-18						
			Special Ed C-9						
			Special Ed C-10						
M-VCT-13	M	Vinyl Composition Tile (Pattern), 12"X12", Tan, Smooth, Black Specks	Faculty Lounge	Assumed	NF	G	500	SF	10/04/21
			Treatment						
			Teacher Workroom						
			Classroom D-8						
			Classroom D-9						
			Classroom A-1						
			Classroom A-2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom A-3						
			Classroom A-6						
			Classroom A-7						
			Classroom A-8						
			Classroom A-11						
			Classroom A-12						
			Classroom A-13						
			Classroom A-14						
			Classroom A-15						
			Special Ed A-9						
			Special Ed A-10						
			Classroom B-5						
			Classroom B-7						
			Classroom B-8						
			Classroom B-11						
			Classroom B-12						
			Classroom B-13						
			Classroom B-14						
			Classroom B-15						
			Classroom B-16						
			Classroom B-17						
			Classroom B-18						
			Special Ed B-9						
			Special Ed B-10						
			Classroom C-1						
			Classroom C-2						
			Classroom C-3						
			Classroom C-4						
			Classroom C-6						
			Classroom C-7						
			Science Classroom C-8						
			Science Classroom C-11						
			Classroom C-12						
			Classroom C-13						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom C-14						
			Classroom C-15						
			Classroom C-16						
			Classroom C-17						
			Classroom C-18						
			Special Ed C-9						
			Special Ed C-10						
M-MAS-14	M	Mastic, Black, Brittle	Athletic Storage	Assumed	NF	G	11,500	SF	10/04/21
			Storage 17						
			Work Room						
			Supply Room 1						
			Supply Room 2						
			Mail Room						
			Faculty Lounge						
			Water Heater						
			Storage 16						
			Room D-12 Time Out						
			Room D-12 Restroom						
			Electrical 6						
			Storage 18						
			Health Restroom						
			Treatment						
			Teacher Workroom						
			Storage 20						
			Classroom D-8						
			Classroom D-9						
			Storage 19						
			Room D-9 Restroom						
			Room D-9 Time Out						
			Classroom A-1						
			Classroom A-2						
			Classroom A-3						
			Classroom A-4						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom A-5						
			Classroom A-6						
			Classroom A-7						
			Classroom A-8						
			Classroom A-11						
			Classroom A-12						
			Classroom A-13						
			Classroom A-14						
			Classroom A-15						
			Special Ed A-9						
			Special Ed A-10						
			Custodial 4						
			Workroom 1						
			Storage 13						
			Electrical 5						
			Storage 12						
			Custodial 3						
			Storage 9						
			Storage 10						
			Electrical 04						
			Storage 11						
			Classroom B-5						
			Classroom B-6						
			Classroom B-7						
			Classroom B-8						
			Classroom B-11						
			Classroom B-12						
			Classroom B-13						
			Classroom B-14						
			Classroom B-15						
			Classroom B-16						
			Classroom B-17						
			Classroom B-18						
			Electrical 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 7						
			Computer Lab 2						
			Storage 8						
			Custodian 2						
			Storage 6						
			Special Ed B-9						
			Special Ed B-10						
			Classroom C-1						
			Classroom C-2						
			Classroom C-3						
			Classroom C-4						
			Storage 2						
			Classroom C-5						
			Classroom C-6						
			Classroom C-7						
			Science Classroom C-8						
			Riser Room						
			Science Classroom C-11						
			Classroom C-12						
			Classroom C-13						
			Classroom C-14						
			Classroom C-15						
			Classroom C-16						
			Classroom C-17						
			Classroom C-18						
			Special Ed C-9						
			Special Ed C-10						
			Electrical 2						
			Storage 4						
			Storage 5						
			Computer Lab 1						
			Custodian 1						
			Storage 3						
			Corridor 1-2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-FDI-18	M	Fire Door Insulation, Metal/Wood Cladding	Office	Assumed	NF	G	3,780	SF	10/04/21
			Assistant Principal						
			Principal						
			Secretary						
			Athletic Storage						
			Storage 17						
			Work Room						
			Supply Room 1						
			Supply Room 2						
			Tele 1						
			Tele 2						
			Mail Room						
			Faculty Lounge						
			Conference 2						
			Water Heater						
			Men's Restroom 4						
			Custodial 5						
			Women's Restroom 4						
			Storage 16						
			Stairs						
			Room D-12						
			Room D-12 Time Out						
			Room D-12 Restroom						
			Electrical 6						
			Cot Room						
			Storage 18						
			Health						
			Custodial 6						
			Boy's Restroom 9						
			Girl's Restroom 9						
			Women's Restroom 5						
			Men's Restroom 5						
			Storage 20						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Teacher Workroom						
			Classroom D-8						
			Classroom D-9						
			Storage 19						
			Corridor 1-1						
			Corridor 2-1						
			Corridor 3-1						
			Corridor 4-1						
			Classroom A-1						
			Classroom A-2						
			Classroom A-3						
			Classroom A-4						
			Classroom A-5						
			Classroom A-6						
			Classroom A-7						
			Classroom A-8						
			Classroom A-11						
			Classroom A-12						
			Classroom A-13						
			Classroom A-14						
			Classroom A-15						
			Classroom A-16						
			Classroom A-17						
			Classroom A-18						
			Special Ed A-9						
			Special Ed A-10						
			Custodial 4						
			Storage 14						
			Workroom 1						
			Men's Restroom 3						
			Storage 13						
			Electrical 5						
			Women's Restroom 3						
			Storage 12						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom B-1						
			Classroom B-2						
			Classroom B-3						
			Classroom B-4						
			Custodial 3						
			Girl's Restroom 6						
			Break Out 2						
			Break Out 3						
			Boy's Restroom 6						
			Electrical 04						
			Storage 11						
			Classroom B-5						
			Classroom B-6						
			Classroom B-7						
			Classroom B-8						
			Storage 1						
			Classroom B-11						
			Classroom B-12						
			Classroom B-13						
			Classroom B-14						
			Classroom B-15						
			Classroom B-16						
			Classroom B-17						
			Classroom B-18						
			Special Ed B-9						
			Special Ed B-10						
			Storage 8						
			Computer Lab 2						
			Women's Restroom 2						
			Storage 7						
			Men's Restroom 2						
			Storage 6						
			Classroom C-1						
			Classroom C-2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom C-3						
			Classroom C-4						
			Girl's Restroom 1						
			Electrical 1						
			Boy's Restroom 1						
			Classroom C-5						
			Classroom C-6						
			Classroom C-7						
			Science Classroom C-8						
			Science Storage						
			Riser Room						
			Science Classroom C-11						
			Classroom C-12						
			Classroom C-13						
			Classroom C-14						
			Classroom C-15						
			Classroom C-16						
			Classroom C-17						
			Classroom C-18						
			Special Ed C-9						
			Special Ed C-10						
			Electrical 2						
			Storage 5						
			Computer Lab 1						
			Men's Restroom 1						
			Storage 4						
			Custodial 1						
			Women's Restroom 1						
			Storage 3						
			Storage 15						
			Office						
			Library Office						
			Library Storage						
			Media Classroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Computer Lab 3						
			Media Center						
			Corridor 1-2						
			Corridor 2-2						
			Corridor 3-2						
			Corridor 4-2						
			Corridor 5-2						
			Corridor 6-2						
			Corridor 7-2						
			Corridor 8-2						
			Corridor 9-2						
			Corridor 10-2						
			Corridor 11-2						
			Corridor 12-2						
			Exterior						
M-PSL-20	M	Pipe End Sealant (Fire Sprinklers), White, Pliable	Office	Assumed	NF	G	200	SF	10/04/21
			Server Room						
			Assistant Principal						
			Assistant Principal Closet						
			Principal						
			Office 4						
			Counselor						
			Psychology						
			Office 3						
			Office 2						
			Conference 1						
			Secretary						
			Athletic Storage						
			Storage 17						
			Work Room						
			Supply Room 1						
			Supply Room 2						
			Tele 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Tele 2						
			Mail Room						
			Faculty Lounge						
			Conference 2						
			Water Heater						
			Men's Restroom 4						
			Custodial 5						
			Women's Restroom 4						
			Storage 16						
			Stairs						
			Room D-12						
			Room D-12 Time Out						
			Room D-12 Restroom						
			Electrical 6						
			Cot Room						
			Storage 18						
			Health Restroom						
			Nurse						
			Health						
			Treatment						
			Hearing						
			Custodial 6						
			Boy's Restroom 9						
			Girl's Restroom 9						
			Women's Restroom 5						
			Men's Restroom 5						
			Storage 20						
			Teacher Workroom						
			Classroom D-8						
			Classroom D-9						
			Storage 19						
			Room D-9 Restroom						
			Room D-9 Shower						
			Room D-9 Time Out						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 1-1						
			Corridor 2-1						
			Corridor 3-1						
			Corridor 4-1						
			Classroom A-1						
			Classroom A-2						
			Classroom A-3						
			Classroom A-4						
			Classroom A-5						
			Classroom A-6						
			Classroom A-7						
			Classroom A-8						
			Classroom A-11						
			Classroom A-12						
			Classroom A-13						
			Classroom A-14						
			Classroom A-15						
			Classroom A-16						
			Classroom A-17						
			Classroom A-18						
			Special Ed A-9						
			Special Ed A-10						
			Custodial 4						
			Boy's Restroom 8						
			Girl's Restroom 8						
			Storage 14						
			Workroom 1						
			Men's Restroom 3						
			Storage 13						
			Electrical 5						
			Women's Restroom 3						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Storage 12						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom B-1						
			Classroom B-2						
			Classroom B-3						
			Classroom B-4						
			Custodial 3						
			Girl's Restroom 6						
			Storage 9						
			Storage 10						
			Break Out 2						
			Break Out 3						
			Boy's Restroom 6						
			Electrical 04						
			Storage 11						
			Classroom B-5						
			Classroom B-6						
			Classroom B-7						
			Classroom B-8						
			Storage 1						
			Classroom B-11						
			Classroom B-12						
			Classroom B-13						
			Classroom B-14						
			Classroom B-15						
			Classroom B-16						
			Classroom B-17						
			Classroom B-18						
			Special Ed B-9						
			Special Ed B-10						
			Electrical 3						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Storage 8						
			Computer Lab 2						
			Women's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 7						
			Custodial 2						
			Men's Restroom 2						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Storage 6						
			Classroom C-1						
			Classroom C-2						
			Classroom C-3						
			Classroom C-4						
			Girl's Restroom 1						
			Break Out 1						
			Storage 2						
			Electrical 1						
			Boy's Restroom 1						
			Classroom C-5						
			Classroom C-6						
			Classroom C-7						
			Science Classroom C-8						
			Science Storage						
			Riser Room						
			Science Classroom C-11						
			Classroom C-12						
			Classroom C-13						
			Classroom C-14						
			Classroom C-15						
			Classroom C-16						
			Classroom C-17						
			Classroom C-18						
			Special Ed C-9						
			Special Ed C-10						
			Electrical 2						
			Boy's Restroom 3						
			Girl's Restroom 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 5						
			Computer Lab 1						
			Men's Restroom 1						
			Storage 4						
			Custodial 1						
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Storage 3						
			Storage 15						
			Office						
			Library Office						
			Library Storage						
			Media Classroom						
			Computer Lab 3						
			Media Center						
			Corridor 1-2						
			Corridor 2-2						
			Corridor 3-2						
			Corridor 4-2						
			Corridor 5-2						
			Corridor 6-2						
			Corridor 7-2						
			Corridor 8-2						
			Corridor 9-2						
			Corridor 10-2						
			Corridor 11-2						
			Corridor 12-2						
M-SLT-21	M	Sealant (Duct), Gray, Pliable	Office	Assumed	NF	G	150	SF	10/04/21
			Server Room						
			Assistant Principal						
			Assistant Principal Closet						
			Principal						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Office 4						
			Counselor						
			Psychology						
			Office 3						
			Office 2						
			Conference 1						
			Secretary						
			Athletic Storage						
			Storage 17						
			Work Room						
			Supply Room 1						
			Supply Room 2						
			Tele 1						
			Tele 2						
			Mail Room						
			Faculty Lounge						
			Conference 2						
			Water Heater						
			Men's Restroom 4						
			Custodial 5						
			Women's Restroom 4						
			Storage 16						
			Stairs						
			Room D-12						
			Room D-12 Time Out						
			Room D-12 Restroom						
			Electrical 6						
			Cot Room						
			Storage 18						
			Health Restroom						
			Nurse						
			Health						
			Treatment						
			Hearing						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Custodial 6						
			Boy's Restroom 9						
			Girl's Restroom 9						
			Women's Restroom 5						
			Men's Restroom 5						
			Storage 20						
			Teacher Workroom						
			Classroom D-8						
			Classroom D-9						
			Storage 19						
			Room D-9 Restroom						
			Room D-9 Shower						
			Room D-9 Time Out						
			Corridor 1-1						
			Corridor 2-1						
			Corridor 3-1						
			Corridor 4-1						
			Classroom A-1						
			Classroom A-2						
			Classroom A-3						
			Classroom A-4						
			Classroom A-5						
			Classroom A-6						
			Classroom A-7						
			Classroom A-8						
			Classroom A-11						
			Classroom A-12						
			Classroom A-13						
			Classroom A-14						
			Classroom A-15						
			Classroom A-16						
			Classroom A-17						
			Classroom A-18						
			Special Ed A-9						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Special Ed A-10						
			Custodial 4						
			Boy's Restroom 8						
			Girl's Restroom 8						
			Storage 14						
			Workroom 1						
			Men's Restroom 3						
			Storage 13						
			Electrical 5						
			Women's Restroom 3						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Storage 12						
			Classroom B-1						
			Classroom B-2						
			Classroom B-3						
			Classroom B-4						
			Custodial 3						
			Girl's Restroom 6						
			Storage 9						
			Storage 10						
			Break Out 2						
			Break Out 3						
			Boy's Restroom 6						
			Electrical 04						
			Storage 11						
			Classroom B-5						
			Classroom B-6						
			Classroom B-7						
			Classroom B-8						
			Storage 1						
			Classroom B-11						
			Classroom B-12						
			Classroom B-13						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom B-14						
			Classroom B-15						
			Classroom B-16						
			Classroom B-17						
			Classroom B-18						
			Special Ed B-9						
			Special Ed B-10						
			Electrical 3						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Storage 8						
			Computer Lab 2						
			Women's Restroom 2						
			Storage 7						
			Custodial 2						
			Men's Restroom 2						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Storage 6						
			Classroom C-1						
			Classroom C-2						
			Classroom C-3						
			Classroom C-4						
			Girl's Restroom 1						
			Break Out 1						
			Storage 2						
			Electrical 1						
			Boy's Restroom 1						
			Classroom C-5						
			Classroom C-6						
			Classroom C-7						
			Science Classroom C-8						
			Science Storage						
			Riser Room						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Science Classroom C-11						
			Classroom C-12						
			Classroom C-13						
			Classroom C-14						
			Classroom C-15						
			Classroom C-16						
			Classroom C-17						
			Classroom C-18						
			Special Ed C-9						
			Special Ed C-10						
			Electrical 2						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Storage 5						
			Computer Lab 1						
			Men's Restroom 1						
			Storage 4						
			Custodial 1						
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Storage 3						
			Storage 15						
			Office						
			Library Office						
			Library Storage						
			Media Classroom						
			Computer Lab 3						
			Media Center						
			Corridor 1-2						
			Corridor 2-2						
			Corridor 3-2						
			Corridor 4-2						
			Corridor 5-2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 6-2						
			Corridor 7-2						
			Corridor 8-2						
			Corridor 9-2						
			Corridor 10-2						
			Corridor 11-2						
			Corridor 12-2						
M-SAC-22	M	Sink Acoustical Coating, Gray, Rough	Classroom A-14	Assumed	NF	G	10	SF	10/04/21
			Classroom A-15						
			Classroom B-5						
			Classroom C-13						
			Classroom C-14						
M-TWP-23	M	Tackable Wall Panel, White, Chalky, Vinyl Cover	Classroom A-14	Assumed	NF	G	250	SF	10/04/21
			Classroom A-15						
			Break Out 2						
			Break Out 3						
S-SAT-25	S	Spray-Applied Texture, White, Chalky	Water Heater	Assumed	NF	G	6,500	SF	10/04/21
			Men's Restroom 4						
			Custodial 5						
			Women's Restroom 4						
			Storage 16						
			Room D-12 Restroom						
			Health Restroom						
			Women's Restroom 5						
			Men's Restroom 5						
			Room D-9 Restroom						
			Room D-9 Shower						
			Custodial 4						
			Boy's Restroom 8						
			Girl's Restroom 8						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Men's Restroom 3						
			Women's Restroom 3						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Women's Restroom 2						
			Custodial 2						
			Men's Restroom 2						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Men's Restroom 1						
			Custodial 1						
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWB-26	M	Gypsum Wallboard, White, Chalky	Water Heater	Assumed	NF	G	6,500	SF	10/04/21
			Men's Restroom 4						
			Custodial 5						
			Women's Restroom 4						
			Storage 16						
			Room D-12 Restroom						
			Health Restroom						
			Women's Restroom 5						
			Men's Restroom 5						
			Room D-9 Restroom						
			Room D-9 Shower						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Custodial 4						
			Boy's Restroom 8						
			Girl's Restroom 8						
			Men's Restroom 3						
			Women's Restroom 3						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Women's Restroom 2						
			Custodial 2						
			Men's Restroom 2						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Men's Restroom 1						
			Custodial 1						
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
S-JTC-27	S	Joint Compound, White, Chalky	Water Heater	Assumed	NF	G	650	SF	10/04/21
			Men's Restroom 4						
			Custodial 5						
			Women's Restroom 4						
			Storage 16						
			Room D-12 Restroom						
			Health Restroom						
			Women's Restroom 5						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Men's Restroom 5						
			Room D-9 Restroom						
			Room D-9 Shower						
			Custodial 4						
			Boy's Restroom 8						
			Girl's Restroom 8						
			Men's Restroom 3						
			Women's Restroom 3						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Women's Restroom 2						
			Custodial 2						
			Men's Restroom 2						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Men's Restroom 1						
			Custodial 1						
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-28	M	Glazed Wall Tile, 4"X4", White, Smooth	Boy's Restroom 9	Assumed	NF	G	5,000	SF	10/04/21
			Girl's Restroom 9						
			Room D-9 Shower						
			Boy's Restroom 8						
			Girl's Restroom 8						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 7						
			Girl's Restroom 7						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-29	M	Glazed Wall Tile (Pattern), 2"X2", Tan, Smooth	Boy's Restroom 9	Assumed	NF	G	500	SF	10/04/21
			Girl's Restroom 9						
			Room D-9 Shower						
			Boy's Restroom 8						
			Girl's Restroom 8						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 2						
			Girl's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GWT-30	M	Glazed Wall Tile (Pattern), 2"X2", Blue, Smooth	Boy's Restroom 9	Assumed	NF	G	500	SF	10/04/21
			Girl's Restroom 9						
			Room D-9 Shower						
			Boy's Restroom 8						
			Girl's Restroom 8						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GRT-31	M	Grout, Gray, Cementitious	Boy's Restroom 9	Assumed	NF	G	600	SF	10/04/21
			Girl's Restroom 9						
			Room D-9 Shower						
			Boy's Restroom 8						
			Girl's Restroom 8						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 4						
			Girl's Restroom 4						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 1						
			Boy's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-32	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth	Girl's Restroom 6	Assumed	NF	G	800	SF	10/04/21
			Boy's Restroom 6						
			Girl's Restroom 1						
			Boy's Restroom 1						
M-CMT-33	M	Ceramic Mosaic Tile (Pattern), 2"X2", Tan, Smooth, White, Specks	Girl's Restroom 6	Assumed	NF	G	100	SF	10/04/21
			Boy's Restroom 6						
			Girl's Restroom 1						
			Boy's Restroom 1						
M-CMT-34	M	Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth, White Specks	Girl's Restroom 6	Assumed	NF	G	100	SF	10/04/21
			Boy's Restroom 6						
			Girl's Restroom 1						
			Boy's Restroom 1						
M-GRT-35	M	Grout, Gray, Cementitious	Girl's Restroom 6	Assumed	NF	G	100	SF	10/04/21
			Boy's Restroom 6						
			Girl's Restroom 1						
			Boy's Restroom 1						
S-SAT-36	S	Spray-Applied Texture, White, Chalky	Office	Assumed	NF	G	7,000	SF	10/04/21
			Electrical 6						
			Custodial 6						
			Corridor 1-2						
			Corridor 2-2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 3-2						
			Corridor 4-2						
			Corridor 5-2						
			Corridor 6-2						
			Corridor 7-2						
			Corridor 8-2						
			Corridor 9-2						
			Corridor 10-2						
			Corridor 11-2						
			Corridor 12-2						
M-GWB-37	M	Gypsum Wallboard, White, Chalky	Office	Assumed	NF	G	7,000	SF	10/04/21
			Electrical 6						
			Custodial 6						
			Corridor 1-2						
			Corridor 2-2						
			Corridor 3-2						
			Corridor 4-2						
			Corridor 5-2						
			Corridor 6-2						
			Corridor 7-2						
			Corridor 8-2						
			Corridor 9-2						
			Corridor 10-2						
			Corridor 11-2						
			Corridor 12-2						
S-JTC-38	S	Joint Compound, White, Chalky	Office	Assumed	NF	G	700	SF	10/04/21
			Electrical 6						
			Custodial 6						
			Corridor 1-2						
			Corridor 2-2						
			Corridor 3-2						
			Corridor 4-2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 5-2						
			Corridor 6-2						
			Corridor 7-2						
			Corridor 8-2						
			Corridor 9-2						
			Corridor 10-2						
			Corridor 11-2						
			Corridor 12-2						
M-CMT-39	M	Ceramic Mosaic Tile, 2"X2", White, Smooth, Peppered	Men's Restroom 4	Assumed	NF	G	3,500	SF	10/04/21
			Women's Restroom 4						
			Boy's Restroom 9						
			Girl's Restroom 9						
			Women's Restroom 5						
			Men's Restroom 5						
			Room D-9 Shower						
			Boy's Restroom 8						
			Girl's Restroom 8						
			Men's Restroom 3						
			Women's Restroom 3						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Men's Restroom 2						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Men's Restroom 1						
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMT-40	M	Ceramic Mosaic Tile (Pattern), 2"X2", Tan, Smooth, Brown Specks	Men's Restroom 4	Assumed	NF	G	250	SF	10/04/21
			Women's Restroom 4						
			Boy's Restroom 9						
			Girl's Restroom 9						
			Women's Restroom 5						
			Men's Restroom 5						
			Room D-9 Shower						
			Boy's Restroom 8						
			Girl's Restroom 8						
			Men's Restroom 3						
			Women's Restroom 3						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Men's Restroom 2						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Men's Restroom 1						
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-41	M	Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth, Brown Specks	Men's Restroom 4	Assumed	NF	G	250	SF	10/04/21
			Women's Restroom 4						
			Boy's Restroom 9						
			Girl's Restroom 9						
			Women's Restroom 5						
			Men's Restroom 5						
			Room D-9 Shower						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 8						
			Girl's Restroom 8						
			Men's Restroom 3						
			Women's Restroom 3						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Men's Restroom 2						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Men's Restroom 1						
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GRT-42	M	Grout, Gray, Cementitious	Men's Restroom 4	Assumed	NF	G	400	SF	10/04/21
			Women's Restroom 4						
			Boy's Restroom 9						
			Girl's Restroom 9						
			Women's Restroom 5						
			Men's Restroom 5						
			Room D-9 Shower						
			Boy's Restroom 8						
			Girl's Restroom 8						
			Men's Restroom 3						
			Women's Restroom 3						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Men's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 4						
			Girl's Restroom 4						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Men's Restroom 1						
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-43	M	Glazed Wall Tile (Coved), 4"X6", White, Smooth	Men's Restroom 4	Assumed	NF	G	500	SF	10/04/21
			Women's Restroom 4						
			Men's Restroom 3						
			Women's Restroom 3						
			Women's Restroom 2						
			Men's Restroom 2						
			Men's Restroom 1						
			Women's Restroom 1						
M-GRT-44	M	Grout, Gray, Cementitious	Men's Restroom 4	Assumed	NF	G	50	SF	10/04/21
			Women's Restroom 4						
			Men's Restroom 3						
			Women's Restroom 3						
			Women's Restroom 2						
			Men's Restroom 2						
			Men's Restroom 1						
			Women's Restroom 1						
S-TOT-52	S	Troweled-On Texture, White, Chalky	Custodial 3	Assumed	NF	G	200	SF	10/04/21
M-GWB-53	M	Gypsum Wallboard, White, Chalky	Custodial 3	Assumed	NF	G	200	SF	10/04/21
S-JTC-54	S	Joint Compound, White, Chalky	Custodial 3	Assumed	NF	G	20	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S·TOT·55	S	Troweled-On Texture, White, Chalky	Electrical 04	Assumed	NF	G	150	SF	10/04/21
M·GWB·56	M	Gypsum Wallboard, White, Chalky	Electrical 04	Assumed	NF	G	150	SF	10/04/21
S·JTC·57	S	Joint Compound, White, Chalky	Electrical 04	Assumed	NF	G	15	SF	10/04/21
M·CON·58	M	Concrete (Equipment Pad), Gray, Cementitious	Electrical 04	Assumed	NF	G	10	SF	10/04/21
M·VCT·59	M	Vinyl Composition Tile, 24"X24", Blue, Textured, Circle Pattern	Stairs	Assumed	NF	G	200	SF	10/04/21
M·MAS·60	M	Mastic, Yellow, Tacky	Stairs	Assumed	NF	G	200	SF	10/04/21
M·VST·61	M	Vinyl Stair Tread, 12"X36", Blue, Textured, Circle Pattern	Stairs	Assumed	NF	G	200	SF	
M·MAS·62	M	Mastic, Yellow, Tacky	Stairs	Assumed	NF	G	200	SF	10/04/21
M·GWB·67	M	Gypsum Wallboard, White, Chalky, Vinyl Cover	Office	Assumed	NF	G	18,000	SF	10/04/21
			Cot Room						
			Health						
			Treatment						
			Hearing						
			Corridor 1-1						
			Corridor 2-1						
			Corridor 3-1						
			Corridor 1-2						
			Corridor 2-2						
			Corridor 3-2						
			Corridor 4-2						
			Corridor 5-2						
			Corridor 6-2						
			Corridor 7-2						
			Corridor 8-2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 9-2						
			Corridor 10-2						
			Corridor 11-2						
			Corridor 12-2						
S-JTC-68	S	Joint Compound, White, Chalky	Office	Assumed	NF	G	1,800	SF	10/04/21
			Cot Room						
			Health						
			Treatment						
			Hearing						
			Corridor 1-1						
			Corridor 2-1						
			Corridor 3-1						
			Corridor 1-2						
			Corridor 2-2						
			Corridor 3-2						
			Corridor 4-2						
			Corridor 5-2						
			Corridor 6-2						
			Corridor 7-2						
			Corridor 8-2						
			Corridor 9-2						
			Corridor 10-2						
			Corridor 11-2						
			Corridor 12-2						
M-MRT-69	M	Mortar (Glass Block And GWT), Gray, Cementitious	Exterior	Assumed	NF	G	100	SF	10/04/21
M-GWT-72	M	Glazed Wall Tile, 12"X12", Brown, Smooth	Corridor 2-2	Assumed	NF	G	100	SF	10/04/21
			Corridor 11-2						
			Corridor 12-2						
M-GRT-73	M	Grout, Gray, Cementitious	Corridor 2-2	Assumed	NF	G	15	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 11-2						
			Corridor 12-2						
M-GWT-74	M	Glazed Wall Tile, 8"X8", Brown, Smooth	Corridor 2-2	Assumed	NF	G	50	SF	10/04/21
			Corridor 11-2						
			Corridor 12-2						
M-QPT-75	M	Quarry/Paver Tile, 12"X12", White, Smooth	Office	Assumed	NF	G	100	SF	10/04/21
M-GRT-76	M	Grout, Gray, Cementitious	Office	Assumed	NF	G	10	SF	10/04/21
M-QPT-77	M	Quarry/Paver Tile, 12"X12", Blue, Smooth	Office	Assumed	NF	G	20	SF	10/04/21
M-CON-78	M	Concrete (Foundation), Gray, Cementitious	Office	Assumed	NF	G	115,000	SF	10/04/21
			Server Room						
			Assistant Principal						
			Assistant Principal Closet						
			Principal						
			Office 4						
			Counselor						
			Psychology						
			Office 3						
			Office 2						
			Conference 1						
			Secretary						
			Athletic Storage						
			Storage 17						
			Work Room						
			Supply Room 1						
			Supply Room 2						
			Tele 1						
			Tele 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Mail Room						
			Faculty Lounge						
			Conference 2						
			Water Heater						
			Men's Restroom 4						
			Custodial 5						
			Women's Restroom 4						
			Storage 16						
			Stairs						
			Room D-12						
			Room D-12 Time Out						
			Room D-12 Restroom						
			Electrical 6						
			Cot Room						
			Storage 18						
			Health Restroom						
			Nurse						
			Health						
			Treatment						
			Hearing						
			Custodial 6						
			Boy's Restroom 9						
			Girl's Restroom 9						
			Women's Restroom 5						
			Men's Restroom 5						
			Storage 20						
			Teacher Workroom						
			Classroom D-8						
			Classroom D-9						
			Storage 19						
			Room D-9 Restroom						
			Room D-9 Shower						
			Room D-9 Time Out						
			Corridor 1-1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 2-1						
			Corridor 3-1						
			Corridor 4-1						
			Elevator 1						
			Classroom A-1						
			Classroom A-2						
			Classroom A-3						
			Classroom A-4						
			Classroom A-5						
			Classroom A-6						
			Classroom A-7						
			Classroom A-8						
			Classroom A-11						
			Classroom A-12						
			Classroom A-13						
			Classroom A-14						
			Classroom A-15						
			Classroom A-16						
			Classroom A-17						
			Classroom A-18						
			Special Ed A-9						
			Special Ed A-10						
			Custodial 4						
			Boy's Restroom 8						
			Girl's Restroom 8						
			Storage 14						
			Workroom 1						
			Men's Restroom 3						
			Storage 13						
			Electrical 5						
			Women's Restroom 3						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Storage 12						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom B-1						
			Classroom B-2						
			Classroom B-3						
			Classroom B-4						
			Custodial 3						
			Girl's Restroom 6						
			Storage 9						
			Storage 10						
			Break Out 2						
			Break Out 3						
			Boy's Restroom 6						
			Electrical 04						
			Storage 11						
			Classroom B-5						
			Classroom B-6						
			Classroom B-7						
			Classroom B-8						
			Storage 1						
			Classroom B-11						
			Classroom B-12						
			Classroom B-13						
			Classroom B-14						
			Classroom B-15						
			Classroom B-16						
			Classroom B-17						
			Classroom B-18						
			Special Ed B-9						
			Special Ed B-10						
			Electrical 3						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Storage 8						
			Computer Lab 2						
			Women's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 7						
			Custodial 2						
			Men's Restroom 2						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Storage 6						
			Classroom C-1						
			Classroom C-2						
			Classroom C-3						
			Classroom C-4						
			Girl's Restroom 1						
			Break Out 1						
			Storage 2						
			Electrical 1						
			Boy's Restroom 1						
			Classroom C-5						
			Classroom C-6						
			Classroom C-7						
			Science Classroom C-8						
			Science Storage						
			Riser Room						
			Science Classroom C-11						
			Classroom C-12						
			Classroom C-13						
			Classroom C-14						
			Classroom C-15						
			Classroom C-16						
			Classroom C-17						
			Classroom C-18						
			Special Ed C-9						
			Special Ed C-10						
			Electrical 2						
			Boy's Restroom 3						
			Girl's Restroom 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 5						
			Computer Lab 1						
			Men's Restroom 1						
			Storage 4						
			Custodial 1						
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Storage 3						
			Storage 15						
			Office						
			Library Office						
			Library Storage						
			Media Classroom						
			Computer Lab 3						
			Media Center						
			Elevator 2						
			Corridor 1-2						
			Corridor 2-2						
			Corridor 3-2						
			Corridor 4-2						
			Corridor 5-2						
			Corridor 6-2						
			Corridor 7-2						
			Corridor 8-2						
			Corridor 9-2						
			Corridor 10-2						
			Corridor 11-2						
			Corridor 12-2						
			Exterior						
M-GWB-79	M	Gypsum Wallboard, White, Chalky	Boy's Restroom 9	Assumed	NF	G	400	SF	10/04/21
			Girl's Restroom 9						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-JTC-80	S	Joint, Compound, White, Chalky	Boy's Restroom 9	Assumed	NF	G	20	SF	10/04/21
			Girl's Restroom 9						
M-MRT-86	M	Mortar (Glass Block), Gray, Cementitious	Roof	Assumed	NF	G	10	SF	10/04/21
M-SLT-88	M	Sealant (Flashings), Tan, Pliable	Exterior	Assumed	NF	G	25	SF	10/04/21
M-SLT-89	M	Sealant (Flashings), White, Brittle	Roof	Assumed	NF	G	15	SF	10/04/21
M-SLT-91	M	Sealant (Doors, Windows), Brown, Pliable	Exterior	Assumed	NF	G	5	SF	10/04/21
M-CON-92	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	3,000	SF	10/04/21
M-EXJ-93	M	Expansion Joint, Gray, Pliable	Exterior	Assumed	NF	G	25	SF	10/04/21
M-CON-94	M	Concrete, Gray, Cementitious	Exterior	Assumed	NF	G	250	SF	10/04/21
M-EXJ-95	M	Expansion Joint, Brown, Pliable	Stairs	Assumed	NF	G	250	SF	10/04/21
			Elevator 1						
			Custodial 3						
			Electrical 04						
			Electrical 1						
			Elevator 2						
			Corridor 2-2						
			Corridor 11-2						
			Corridor 12-2						
			Exterior						
M-GWT-96	M	Glazed Wall Tile, 8"X8", Brown, Smooth	Exterior	Assumed	NF	G	100	SF	10/04/21
M-GWT-97	M	Glazed Wall Tile, 4"X8", Brown, Smooth	Exterior	Assumed	NF	G	100	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GRT-98	M	Grout, Gray, Cementitious	Exterior	Assumed	NF	G	10	SF	10/04/21
M-CMT-99	M	Ceramic Mosaic Tile (Mosaic), Various Sizes, White, Smooth, Various Colors	Exterior	Assumed	NF	G	10	SF	10/04/21
M-GRT-100	M	Grout, Gray, Cementitious	Exterior	Assumed	NF	G	1	SF	10/04/21

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Main-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-VCT-10	M	Vinyl Composition Tile, 12"X12", White, Smooth, Gray Mottles	Classroom D-1	Assumed	NF	G	6,000	SF	10/04/21
			Storage 15						
			Storage 16						
			Storage 17						
			Office 1						
			Office 1 Restroom						
			Office 2 Restroom						
			Office 2						
			Storage 14						
			Kitchen Restroom						
			Locker						
			Kitchen Office						
			Custodian						
			Multi-Purpose						
			Music						
			Band Room						
			Band Restroom						
			Storage 9						
			Storage 10						
			Storage 11						
			Storage 12						
			Storage 13						
			Storage 7						
			Storage 6						
			Home Economics						
			Laundry						
			Home Ec Restroom						
			Art						
			Art Hall						
			Electrical 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 5						
			Storage 4						
			Storage 1						
			Storage 2						
			Corridor 1						
			Corridor 2						
			Corridor 4						
M-VCT-11	M	Vinyl Composition Tile (Pattern), 12"X12", Blue, Smooth, Dark Blue Specks	Classroom D-1	Assumed	NF	G	200	SF	10/04/21
			Office 1						
			Office 1 Restroom						
			Office 2 Restroom						
			Office 2						
			Home Economics						
			Art						
			Art Hall						
M-VCT-12	M	Vinyl Composition Tile (Pattern), 12"X12", Tan, Smooth, Gray Mottles	Classroom D-1	Assumed	NF	G	200	SF	10/04/21
			Office 1						
			Office 1 Restroom						
			Office 2 Restroom						
			Office 2						
			Home Economics						
			Art						
			Art Hall						
M-VCT-13	M	Vinyl Composition Tile (Pattern), 12"X12", Tan, Smooth, Black Specks	Classroom D-1	Assumed	NF	G	50	SF	10/04/21
			Office 1						
			Office 1 Restroom						
			Office 2 Restroom						
			Office 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Home Economics						
			Art						
			Art Hall						
M-MAS-14	M	Mastic, Yellow, Tacky	Classroom D-1	Assumed	NF	G	6,000	SF	10/04/21
			Storage 15						
			Storage 16						
			Storage 17						
			Office 1						
			Office 1 Restroom						
			Office 2 Restroom						
			Office 2						
			Storage 14						
			Kitchen Restroom						
			Locker						
			Kitchen Office						
			Custodian						
			Multi-Purpose						
			Music						
			Band Room						
			Band Restroom						
			Storage 9						
			Storage 10						
			Storage 11						
			Storage 12						
			Storage 13						
			Storage 7						
			Storage 6						
			Home Economics						
			Laundry						
			Home Economics Restroom						
			Art						
			Art Hall						
			Electrical 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 5						
			Storage 4						
			Storage 1						
			Storage 2						
			Corridor 1						
			Corridor 2						
			Corridor 4						
M-SAC-15	M	Sink Acoustical Coating, Black, Rough	Classroom D-1	Assumed	NF	G	24	SF	10/04/21
			Band Room						
			Home Economics						
			Art						
M-PSL-18	M	Pipe End Sealant (Fire Sprinklers), White, Pliable	Lobby	Assumed	NF	G	25	SF	10/04/21
			Storage 18						
			Classroom D-1						
			Gymnasium						
			Storage 15						
			Boy's Locker Room						
			Storage 16						
			Storage 17						
			Office 1						
			Office 1 Restroom						
			Office 2 Restroom						
			Office 2						
			Girl's Locker Room						
			Electrical 2						
			Water/Heater						
			Men's Restroom 1						
			Women's Restroom 1						
			Kitchen						
			Freezer						
			Storage 14						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Kitchen Restroom						
			Locker						
			Kitchen Office						
			Maintenance						
			Cafeteria						
			Custodian						
			Service Room						
			Multi-Purpose						
			Music						
			Band Room						
			Storage 8						
			Band Restroom						
			Band Office						
			Practice						
			Storage 9						
			Storage 10						
			Storage 11						
			Storage 12						
			Storage 13						
			Storage 7						
			Storage 6						
			Home Economics						
			Laundry						
			Home Economics Restroom						
			Art						
			Art Hall						
			Electrical 1						
			Storage 5						
			Storage 4						
			Storage 1						
			Storage 2						
			Storage 3						
			Computer Lab						
			Corridor 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
M-FDI-19	M	Fire Door Insulation, Metal/Wood Cladding	Lobby	Assumed	NF	G	2,520	SF	10/04/21
			Storage 18						
			Classroom D-1						
			Gymnasium						
			Storage 15						
			Boy's Locker Room						
			Storage 16						
			Storage 17						
			Office 1						
			Office 2						
			Girl's Locker Room						
			Electrical 2						
			Water/Heater						
			Kitchen						
			Storage 14						
			Kitchen Service Yard						
			Locker						
			Maintenance						
			Cafeteria						
			Custodian						
			Service Room						
			Multi-Purpose						
			Music						
			Band Room						
			Storage 8						
			Band Restroom						
			Band Office						
			Storage 9						
			Storage 10						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 11						
			Storage 12						
			Storage 13						
			Storage 7						
			Storage 6						
			Home Economics						
			Home Economics Service Yard						
			Art						
			Art Hall						
			Art Service Yard						
			Electrical 1						
			Storage 5						
			Storage 4						
			Weight Room						
			Storage 2						
			Storage 3						
			Service Yard						
			Computer Lab						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Exterior						
M-CON-21	M	Concrete (Foundation), Gray, Cementitious	Lobby	Assumed	NF	G	45,000	SF	10/04/21
			Storage 18						
			Classroom D-1						
			Gymnasium						
			Storage 15						
			Boy's Locker Room						
			Storage 16						
			Storage 17						
			Office 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Office 1 Restroom						
			Office 2 Restroom						
			Office 2						
			Girl's Locker Room						
			Electrical 2						
			Water/Heater						
			Men's Restroom 1						
			Women's Restroom 1						
			Kitchen						
			Freezer						
			Storage 14						
			Kitchen Service Yard						
			Kitchen Restroom						
			Locker						
			Kitchen Office						
			Maintenance						
			Cafeteria						
			Custodian						
			Service Room						
			Multi-Purpose						
			Music						
			Band Room						
			Storage 8						
			Band Restroom						
			Band Office						
			Practice						
			Storage 9						
			Storage 10						
			Storage 11						
			Storage 12						
			Storage 13						
			Mechanical Yard						
			Storage 7						
			Storage 6						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Home Economics						
			Laundry						
			Home Economics Restroom						
			Home Economics Service Yard						
			Art						
			Art Hall						
			Art Service Yard						
			Electrical 1						
			Storage 5						
			Storage 4						
			Weight Room						
			Storage 1						
			Storage 2						
			Storage 3						
			Service Yard						
			Computer Lab						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Exterior						
M-WDB-22	M	Woven Duct Boot, 4", Black, Canvas	Storage 15	Assumed	NF	G	10	SF	10/04/21
			Weight Room						
S-SAT-31	S	Spray-Applied Texture, White, Chalky	Lobby	Assumed	NF	G	7,000	SF	10/04/21
			Boy's Locker Room						
			Office 1 Restroom						
			Office 2 Restroom						
			Girl's Locker Room						
			Men's Restroom 1						
			Women's Restroom 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Kitchen						
			Kitchen Restroom						
			Custodian						
			Service Room						
			Band Restroom						
			Home Economics Restroom						
			Laundry						
			Storage 1						
M-GWB-32	M	Gypsum Wallboard, White, Chalky	Lobby	Assumed	NF	G	7,000	SF	10/04/21
			Boy's Locker Room						
			Office 1 Restroom						
			Office 2 Restroom						
			Girl's Locker Room						
			Men's Restroom 1						
			Women's Restroom 1						
			Kitchen						
			Kitchen Restroom						
			Custodian						
			Service Room						
			Band Restroom						
			Home Economics Restroom						
			Laundry						
			Storage 1						
S-JTC-33	S	Joint Compound, White, Chalky	Lobby	Assumed	NF	G	700	SF	10/04/21
			Boy's Locker Room						
			Office 1 Restroom						
			Office 2 Restroom						
			Girl's Locker Room						
			Men's Restroom 1						
			Women's Restroom 1						
			Kitchen						
			Kitchen Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Custodian						
			Service Room						
			Band Restroom						
			Home Economics Restroom						
			Laundry						
			Storage 1						
M-PES-34	M	Pipe End Sealant, White, Pliable	Weight Room	Assumed	NF	G	20	SF	10/04/21
M-GWB-35	M	Gypsum Wallboard, White, Chalky, Vinyl Cover	Band Restroom	Assumed	NF	G	4,000	SF	10/04/21
			Home Economics						
			Art						
			Art Hall						
S-JTC-36	S	Joint Compound, White, Chalky	Band Restroom	Assumed	NF	G	400	SF	10/04/21
			Home Economics						
			Art						
			Art Hall						
M-VCT-37	M	Vinyl Composition Tile (Pattern), 12"X12", Gray, Smooth, Dark Gray Mottles	Art	Assumed	NF	G	50	SF	10/04/21
M-WAB-38	M	Wallbase (Coved), 4", Blue, Vinyl-Like	Music	Assumed	NF	G	15	SF	10/04/21
M-ADH-39	M	Adhesive, Cream, Pliable	Music	Assumed	NF	G	15	SF	10/04/21
M-QPT-42	M	Quarry/Paver Tile, 12"X12", Tan, Smooth, Blue Specks	Lobby	Assumed	NF	G	450	SF	10/04/21
M-QPT-43	M	Quarry/Paver Tile, 12"X12", Blue, Smooth, Blue Specks	Lobby	Assumed	NF	G	50	SF	10/04/21
M-GRT-44	M	Grout, Gray, Cementitious	Lobby	Assumed	NF	G	500	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GWT-45	M	Glazed Wall Tile (Coved), 4"X6", Tan, Smooth, Blue Specks	Kitchen	Assumed	NF	G	150	SF	10/04/21
			Kitchen Restroom						
			Locker						
			Kitchen Office						
			Cafeteria						
M-GRT-46	M	Grout, Gray, Cementitious	Kitchen	Assumed	NF	G	150	SF	10/04/21
			Kitchen Restroom						
			Locker						
			Kitchen Office						
			Cafeteria						
M-ADH-47	M	Adhesive (FRP), Black, Brittle	Kitchen	Assumed	NF	G	800	SF	10/04/21
			Custodian						
			Multi-Purpose						
M-SLT-49	M	Sealant (Duct), Gray, Pliable	Lobby	Assumed	NF	G	50	SF	10/04/21
			Storage 18						
			Classroom D-1						
			Gymnasium						
			Storage 15						
			Boy's Locker Room						
			Storage 16						
			Storage 17						
			Office 1						
			Office 1 Restroom						
			Office 2 Restroom						
			Office 2						
			Girl's Locker Room						
			Electrical 2						
			Water/Heater						
			Men's Restroom 1						
			Women's Restroom 1						
			Kitchen						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Freezer						
			Storage 14						
			Kitchen Restroom						
			Locker						
			Kitchen Office						
			Maintenance						
			Cafeteria						
			Custodian						
			Service Room						
			Multi-Purpose						
			Music						
			Band Room						
			Storage 8						
			Band Restroom						
			Band Office						
			Practice						
			Storage 9						
			Storage 10						
			Storage 11						
			Storage 12						
			Storage 13						
			Storage 7						
			Storage 6						
			Home Economics						
			Laundry						
			Home Economics Restroom						
			Art						
			Art Hall						
			Electrical 1						
			Storage 5						
			Storage 4						
			Weight Room						
			Storage 1						
			Storage 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 3						
			Computer Lab						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
M·SLT·53	M	Sealant (Flashings), White, Brittle	Roof	Assumed	NF	G	200	SF	10/04/21
M·PES·54	M	Pipe End Sealant, Gray, Pliable	Roof	Assumed	NF	G	15	SF	10/04/21
M·MAS·56	M	Mastic (Penetrations and Flashings), Black, Tar-Like	Roof	Assumed	NF	G	60	SF	10/04/21
M·SLT·57	M	Sealant (Flashings), White, Pliable	Roof	Assumed	NF	G	5	SF	10/04/21
M·SLT·58	M	Sealant (Duct), Gray, Pliable	Roof	Assumed	NF	G	50	SF	10/04/21
M·APR·59	M	Asphalt Prepared Roofing (Rolled), Black, Asphaltic, White Coating	Roof	Assumed	NF	G	100	SF	10/04/21
M·SLT·60	M	Sealant (Flashings), Black, Pliable	Roof	Assumed	NF	G	10	SF	10/04/21
M·WDB·61	M	Woven Duct Boot, 4", Gray, Cloth-Like	Roof	Assumed	NF	G	1	SF	10/04/21
M·SLT·62	M	Sealant (Skylights), Gray, Pliable	Roof	Assumed	NF	G	25	SF	10/04/21
M·VST·63	M	Vinyl Stair Tread, 12"X36", Blue, Textured, Circle Pattern	Multi-Purpose	Assumed	NF	G	30	SF	10/04/21
			Corridor 1						
M·MAS·64	M	Mastic, Black, Brittle	Multi-Purpose	Assumed	NF	G	30	SF	10/04/21
			Corridor 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S·SAT·65	S	Spray-Applied Texture, White, Chalky	Lobby	Assumed	NF	G	2,500	SF	10/04/21
			Corridor 1						
			Corridor 2						
M·GWB·66	M	Gypsum Wallboard, White, Chalky	Lobby	Assumed	NF	G	2,500	SF	10/04/21
			Corridor 1						
			Corridor 2						
S·JTC·67	S	Joint Compound, White, Chalky	Lobby	Assumed	NF	G	250	SF	10/04/21
			Corridor 1						
			Corridor 2						
M·GWT·68	M	Glazed Wall Tile, 12"X12", Red, Smooth	Lobby	Assumed	NF	G	20	SF	10/04/21
M·MRT·69	M	Mortar (GWT And Glass Block), Gray, Cementitious	Lobby	Assumed	NF	G	45	SF	10/04/21
M·SLT·70	M	Sealant (Doors), Black, Pliable	Lobby	Assumed	NF	G	20	SF	10/04/21
			Storage 18						
			Classroom D-1						
			Gymnasium						
			Storage 15						
			Electrical 2						
			Water/Heater						
			Corridor 4						
			Exterior						
M·CPT·71	M	Carpet (Pattern), Blue, Fibrous	Lobby	Assumed	NF	G	50	SF	10/04/21
M·GWB·72	M	Gypsum Wallboard, White, Chalky	Lobby	Assumed	NF	G	175	SF	10/04/21
S·JTC·73	S	Joint Compound, White, Chalky	Lobby	Assumed	NF	G	20	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GWT-74	M	Glazed Wall Tile, 4"X4", White, Smooth	Boy's Locker Room	Assumed	NF	G	4,000	SF	10/04/21
			Girl's Locker Room						
			Men's Restroom 1						
			Women's Restroom 1						
			Corridor 3						
			Corridor 5						
M-GWT-75	M	Glazed Wall Tile (Pattern), 2"X2", Blue, Smooth	Boy's Locker Room	Assumed	NF	G	500	SF	10/04/21
			Girl's Locker Room						
			Men's Restroom 1						
			Women's Restroom 1						
			Corridor 3						
			Corridor 5						
M-GWT-76	M	Glazed Wall Tile (Pattern), 2"X2", Tan, Smooth	Boy's Locker Room	Assumed	NF	G	500	SF	10/04/21
			Girl's Locker Room						
			Men's Restroom 1						
			Women's Restroom 1						
			Corridor 3						
			Corridor 5						
M-GRT-77	M	Grout, Gray, Cementitious	Boy's Locker Room	Assumed	NF	G	500	SF	10/04/21
			Girl's Locker Room						
			Men's Restroom 1						
			Women's Restroom 1						
			Corridor 3						
			Corridor 5						
M-CMT-78	M	Ceramic Mosaic Tile, 2"X2", White, Smooth, Peppered	Men's Restroom 1	Assumed	NF	G	400	SF	10/04/21
			Women's Restroom 1						
M-CMT-79	M	Ceramic Mosaic Tile (Pattern), 2"X2", Tan, Smooth, Peppered	Men's Restroom 1	Assumed	NF	G	50	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Women's Restroom 1						
M-CMT-80	M	Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth, Peppered	Men's Restroom 1	Assumed	NF	G	50	SF	10/04/21
			Women's Restroom 1						
M-GRT-81	M	Grout, Gray, Cementitious	Men's Restroom 1	Assumed	NF	G	40	SF	10/04/21
			Women's Restroom 1						
M-WAB-82	M	Wallbase (L-Shaped), 4", Black, Vinyl-Like	Gymnasium	Assumed	NF	G	100	SF	10/04/21
M-ADH-83	M	Adhesive, Cream, Pliable -Like	Gymnasium	Assumed	NF	G	100	SF	10/04/21
M-ADH-84	M	Adhesive (FRP), Black, Brittle	Corridor 3	Assumed	NF	G	750	SF	10/04/21
			Corridor 5						
M-QPT-85	M	Quarry/Paver Tile, 12"X12", White, Textured	Boy's Locker Room	Assumed	NF	G	3,000	SF	10/04/21
			Girls' Locker Room						
			Corridor 3						
			Corridor 5						
M-GRT-86	M	Grout, Gray, Cementitious	Boy's Locker Room	Assumed	NF	G	300	SF	10/04/21
			Girls' Locker Room						
			Corridor 3						
			Corridor 5						
M-GWT-87	M	Glazed Wall Tile (Coved), 4"X6", White, Textured	Boy's Locker Room	Assumed	NF	G	15	SF	10/04/21
			Girls' Locker Room						
M-GRT-88	M	Grout, Gray, Cementitious	Boy's Locker Room	Assumed	NF	G	2	SF	10/04/21
			Girls' Locker Room						
M-GWB-89	M	Gypsum Wallboard, White, Chalky	Boy's Locker Room	Assumed	NF	G	3,000	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girls' Locker Room						
S-JTC-90	S	Joint Compound, White, Chalky	Boy's Locker Room	Assumed	NF	G	300	SF	10/04/21
			Girls' Locker Room						
M-EXJ-91	M	Expansion Joint, Brown, Pliable	Mechanical Yard	Assumed	NF	G	100	SF	10/04/21
			Home Economics Service Yard						
			Art Service Yard						
			Storage 3						
			Service Yard						
			Exterior						
M-SLT-92	M	Sealant (Doors, Windows), Brown, Pliable	Kitchen Service Yard	Assumed	NF	G	40	SF	10/04/21
			Home Economics Service Yard						
			Art Service Yard						
			Service Yard						
			Exterior						
M-CON-93	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	10,000	SF	10/04/21
M-EXJ-94	M	Expansion Joint, Gray, Pliable	Exterior	Assumed	NF	G	50	SF	10/04/21
M-CMU-96	M	Concrete Masonry Unit, 8"X8", Gray, Cementitious, Cross Cut Pattern	Exterior	Assumed	NF	G	150	SF	10/04/21

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-SAT-01	S	Spray-Applied Texture, White, Chalky	Concession	Assumed	NF	G	900	SF	10/04/21
			Women's Restroom						
			Men's Restroom						
M-GWB-02	M	Gypsum Wallboard, White, Chalky	Concession	Assumed	NF	G	900	SF	10/04/21
			Women's Restroom						
			Men's Restroom						
S-JTC-03	S	Joint Compound, White, Chalky	Concession	Assumed	NF	G	90	SF	10/04/21
			Women's Restroom						
			Men's Restroom						
M-GWT-04	M	Glazed Wall Tile, 4"X4", White, Smooth	Women's Restroom	Assumed	NF	G	1,200	SF	10/04/21
			Men's Restroom						
M-GWT-05	M	Glazed Wall Tile (Pattern), 2"X2", Blue Smooth	Women's Restroom	Assumed	NF	G	150	SF	10/04/21
			Men's Restroom						
M-GWT-06	M	Glazed Wall Tile (Pattern), 2"X2", Tan, Smooth	Women's Restroom	Assumed	NF	G	150	SF	10/04/21
			Men's Restroom						
M-GRT-07	M	Grout, Gray, Cementitious	Women's Restroom	Assumed	NF	G	150	SF	10/04/21
			Men's Restroom						
M-CMT-08	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth	Women's Restroom	Assumed	NF	G	400	SF	10/04/21
			Men's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMT-09	M	Ceramic Mosaic Tile (Pattern), 2"X2", Tan, Smooth, White Specks	Women's Restroom	Assumed	NF	G	50	SF	10/04/21
			Men's Restroom						
M-CMT-10	M	Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth, White Specks	Women's Restroom	Assumed	NF	G	50	SF	10/04/21
			Men's Restroom						
M-GRT-11	M	Grout, Gray, Cementitious	Women's Restroom	Assumed	NF	G	50	SF	10/04/21
			Men's Restroom						
M-SLT-12	M	Sealant (Doors, Millwork, Fixtures), White, Pliable	Concession	Assumed	NF	G	15	SF	10/04/21
			Storage 1						
			Storage 2						
			Electrical						
			Women's Restroom						
			Men's Restroom						
S-SAT-13	M	Spray-Applied Texture, White, Chalky	Storage 1	Assumed	NF	G	700	SF	10/04/21
			Storage 2						
M-GWB-14	M	Gypsum Wallboard, White, Chalky	Storage 1	Assumed	NF	G	700	SF	10/04/21
			Storage 2						
S-JTC-15	S	Joint Compound, White, Chalky	Storage 1	Assumed	NF	G	70	SF	10/04/21
M-WAB-16	M	Wallbase (Coved), 4", Blue, Vinyl- Like	Concession	Assumed	NF	G	40	SF	10/04/21
			Storage 1						
			Storage 2						
M-ADH-17	M	Adhesive, Cream, Pliable	Concession	Assumed	NF	G	40	SF	10/04/21
			Storage 1						
			Storage 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CON-18	M	Concrete (Foundation), Gray, Cementitious	Concession	Assumed	NF	G	1,500	SF	10/04/21
			Storage 1						
			Storage 2						
			Electrical						
			Maintenance						
			Equipment Yard						
			Women's Restroom						
			Men's Restroom						
			Exterior						
M-FDI-19	M	Fire Door Insulation, Metal/Wood Cladding	Concession	Assumed	NF	G	126	SF	10/04/21
			Storage 1						
			Storage 2						
			Electrical						
			Women's Restroom						
			Men's Restroom						
M-CMU-20	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious, Smooth	Concession	Assumed	NF	G	800	SF	10/04/21
			Storage 1						
			Storage 2						
			Electrical						
			Maintenance						
			Equipment Yard						
			Exterior						
M-CMU-21	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Smooth	Concession	Assumed	NF	G	800	SF	10/04/21
			Storage 1						
			Storage 2						
			Electrical						
			Maintenance						
			Equipment Yard						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Exterior						
M-CMU-22	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Rough	Concession	Assumed	NF	G	400	SF	10/04/21
			Storage 1						
			Storage 2						
			Electrical						
			Maintenance						
			Equipment Yard						
			Exterior						
M-CMU-23	M	Concrete Masonry Unit, 8"X8", Gray, Cementitious, Smooth	Concession	Assumed	NF	G	800	SF	10/04/21
			Storage 1						
			Storage 2						
			Electrical						
			Maintenance						
			Equipment Yard						
			Exterior						
M-CMU-24	M	Concrete Masonry Unit, 4"X8", Gray, Cementitious, Smooth	Concession	Assumed	NF	G	800	SF	10/04/21
			Storage 1						
			Storage 2						
			Electrical						
			Maintenance						
			Equipment Yard						
			Exterior						
M-CMU-25	M	Concrete Masonry Unit, 4"X8", Gray, Cementitious, Rough	Concession	Assumed	NF	G	400	SF	10/04/21
			Storage 1						
			Storage 2						
			Electrical						
			Maintenance						
			Equipment Yard						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Exterior						
M·MRT·26	M	Mortar, Gray, Cementitious	Concession	Assumed	NF	G	100	SF	10/04/21
			Storage 1						
			Storage 2						
			Electrical						
			Maintenance						
			Equipment Yard						
			Exterior						
M·SAC·27	M	Sink Acoustical Coating, Gray, Rough	Concession	Assumed	NF	G	8	SF	10/04/21
M·GWB·28	M	Gypsum Wallboard, White, Chalky	Electrical	Assumed	NF	G	200	SF	10/04/21
S·JTC·29	S	Joint Compound, White, Chalky	Electrical	Assumed	NF	G	20	SF	10/04/21
S·STU·30	S	Stucco, Gray, Cementitious	Exterior	Assumed	NF	G	100	SF	10/04/21
M·SLT·31	M	Sealant (Fixtures), Black, Gummy	Exterior	Assumed	NF	G	2	SF	10/04/21
M·SLT·32	M	Sealant (Doors, Walls), Brown, Pliable	Exterior	Assumed	NF	G	10	SF	10/04/21
M·CON·33	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	2,000	SF	10/04/21
M·GWT·34	M	Glazed Wall Tile, 12"X12", Brown, Smooth	Exterior	Assumed	NF	G	4	SF	10/04/21
M·SLT·35	M	Sealant (Fire Stop), Red, Brittle	Maintenance	Assumed	NF	G	1	SF	10/04/21
M·GAS·36	M	Gasket, 4"-6", Black, Vinyl-Like	Equipment Yard	Assumed	NF	G	7	SF	10/04/21
M·BUR·37	M	Built-Up Roofing, Black, Asphaltic, Silver Coating	Roof	Assumed	NF	G	1,400	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-MAS-38	M	Mastic (Penetrations and Flashings), Black, Asphaltic	Roof	Assumed	NF	G	140	SF	10/04/21
M-SLT-39	M	Sealant (Flashings), White, Pliable	Roof	Assumed	NF	G	15	SF	10/04/21
M-SLT-40	M	Sealant (Flashings), Black, Tar-Like	Roof	Assumed	NF	G	15	SF	10/04/21
M-SLT-41	M	Sealant (Duct), White, Pliable	Roof	Assumed	NF	G	10	SF	10/04/21

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Conc-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M·CMU·01	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious, Smooth	Storage 1	Assumed	NF	G	1,600	SF	10/04/21
			Exterior						
M·MRT·02	M	Mortar, Gray, Cementitious	Storage 1	Assumed	NF	G	160	SF	10/04/21
			Exterior						
M·CON·03	M	Concrete (Foundation), Gray, Cementitious	Storage 1	Assumed	NF	G	400	SF	10/04/21
			Exterior						
M·APR·04	M	Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Brown Mineral Cap	Roof	Assumed	NF	G	400	SF	10/04/21
M·VBF·05	M	Vapor Barrier Felt, Black, Asphaltic	Roof	Assumed	NF	G	400	SF	10/04/21

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Stor 1-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-APR-01	M	Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Tan Mineral Cap	Roof	Assumed	NF	G	100	SF	10/04/21
M-VBF-02	M	Vapor Barrier Felt, Black, Asphaltic	Roof	Assumed	NF	G	100	SF	10/04/21
M-CON-03	M	Concrete (Foundation), Gray, Cementitious	Storage 2	Assumed	NF	G	100	SF	10/04/21
			Exterior						

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Stor 2-Tbl.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4580/250/1236 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-VCT-10, Vinyl Composition Tile, 12"X12", White, Smooth, Gray Mottles

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Main\10.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-ai Middle School Building Name/Number: Main

AHERA certification number: 4380123164 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-VCT-11, Vinyl Composition Tile (Pattern), 12"X12", Blue, Smooth, Dark Blue Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No

Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\11.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carmyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4380 4501/2364 Signature of Inspector: Carmyn Hall

*Material Reinspected: M-VCT-12, Vinyl Composition Tile (Pattern), 12"X12", Tan, Smooth, Gray Mottles

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/14/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 130025710369 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-VCT-13, Vinyl Composition Tile (Pattern), 12"X12", Tan, Smooth, Black Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 1380 5001236 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-MAS-14, Mastic, Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\14.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 430022212016 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-FDI-18, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\18.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/24/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43012001236 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PSL-20, Pipe End Sealant (Fire Sprinklers), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\20.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4370125012364 Signature of Inspector: Carson Hall

*Material Reinspected: M-SLT-21, Sealant (Duct), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\21.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 45801200123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SAC-22, Sink Acoustical Coating, Gray, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\22.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 10/4/21 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-TWP-23, Tackable Wall Panel, White, Chalky, Vinyl Cover

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\23.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/24/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-ol Middle School Building Name/Number: Main

AHERA certification number: 437012012304 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-SAT-25, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Main\25.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 1130012-011234 Signature of Inspector: Carson Hall

*Material Reinspected: M-GWB-26, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Main\26.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43812501236 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-JTC-27, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place / 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High / Medium _____ Low _____
Degree of Activity Near the Material: High / Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\27.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 437012501234 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-GWT-28, Glazed Wall Tile, 4"X4", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Main\28.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/21/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4380 62010226 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GWT-29, Glazed Wall Tile (Pattern), 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\29.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbony Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4350125912364 Signature of Inspector: Carbony Hall

*Material Reinspected: M-GWT-30, Glazed Wall Tile (Pattern), 2"X2", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Main\30.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/24/21 Person performing reinspection: Carbryn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43606501231 Signature of Inspector: Carbryn Hall

*Material Reinspected: M-GRT-31, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Main\31.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carly Hgll
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43012012361 Signature of Inspector: Carly Hgll

*Material Reinspected: M-CMT-32, Ceramic Mosaic Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\32.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4320125012364 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-CMT-33, Ceramic Mosaic Tile (Pattern), 2"X2", Tan, Smooth, White, Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\33.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 430012369 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-CMT-34, Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth, White Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\34.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbza Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43801251123 Signature of Inspector: Carbza Hall

*Material Reinspected: M-GRT-35, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\35.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbenhall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43865164 Signature of Inspector: Carbenhall

*Material Reinspected: S-SAT-36, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\36.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 1370610102 Signature of Inspector: Carson Hall

*Material Reinspected: M-GWB-37, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\37.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4380/250/1234 Signature of Inspector: Carbyn Hall

*Material Reinspected: S-JTC-38, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\38.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4380125124 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-CMT-39, Ceramic Mosaic Tile, 2"X2", White, Smooth, Peppered

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\39.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/2/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43801250113 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CMT-40, Ceramic Mosaic Tile (Pattern), 2"X2", Tan, Smooth, Brown Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\40.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/21/21 Person performing reinspection: Corbin Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 458012910324 Signature of Inspector: Corbin Hall

*Material Reinspected: M-CMT-41, Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth, Brown Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\41.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlynn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4370/2521234 Signature of Inspector: Carlynn Hall

*Material Reinspected: M-GRT-42, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\42.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4380 650236 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-43, Glazed Wall Tile (Coved), 4"X6", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\43.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/21/21 Person performing reinspection: Conan Hall
Facility: Kyrene Akimel A-ol Middle School Building Name/Number: Main
AHERA certification number: 43012510369 Signature of Inspector: Conan Hall

*Material Reinspected: M-GRT-44, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\44.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carly Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 438012501236 Signature of Inspector: Carly Hall

*Material Reinspected: S-TOT-52, Troweled-On Texture, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\52.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4350 b21 b364 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-GWB-53, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\53.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbryn Hall
Facility: Kyrene Akimel A-ai Middle School Building Name/Number: Main

AHERA certification number: 4360125212364 Signature of Inspector: Carbryn Hall

*Material Reinspected: S-JTC-54, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\54.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/12/21 Person performing reinspection: Ceryn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main
AHERA certification number: 4380 12501206 Signature of Inspector: Ceryn Hall
*Material Reinspected: S-TOT-55, Troweled-On Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\55.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4300 125011231 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-GWB-56, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\56.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4360125012364 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-JTC-57, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\57.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/21/21 Person performing reinspection: Corbin Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main
AHERA certification number: 438012501236 Signature of Inspector: Corbin Hall
*Material Reinspected: M-CON-58, Concrete (Equipment Pad), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\58.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbzn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 438631636 Signature of Inspector: Carbzn Hall

*Material Reinspected: M-VCT-59, Vinyl Composition Tile, 24"X24", Blue, Textured, Circle Pattern

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\59.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/11/21 Person performing reinspection: Corbin Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 1380 12512345 Signature of Inspector: Corbin Hall

*Material Reinspected: M-MAS-60, Mastic, Yellow, Tacky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\60.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cambryn Heath
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43861206061 Signature of Inspector: Cambryn Heath

*Material Reinspected: M-VST-61, Vinyl Stair Tread, 12"X36", Blue, Textured, Circle Pattern

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\61.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbon Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main
AHERA certification number: 40012501369 Signature of Inspector: Carbon Hall
*Material Reinspected: M-MAS-62, Mastic, Yellow, Tacky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ☒ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\62.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4500127212364 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GWB-67, Gypsum Wallboard, White, Chalky, Vinyl Cover

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\67.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43801250112369 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-JTC-68, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\68.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43002021206 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-MRT-69, Mortar (Glass Block And GWT), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\69.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Caron Hill
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4380251236 Signature of Inspector: Caron Hill

*Material Reinspected: M-GWT-72, Glazed Wall Tile, 12"X12", Brown, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\72.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/24/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43802011206 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GRT-73, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\73.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43602501234 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-GWT-74, Glazed Wall Tile, 8"X8", Brown, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\74.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 438012512364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-QPT-75, Quarry/Paver Tile, 12"X12", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\75.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4380 1201 b364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-76, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\76.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carly Hall
Facility: Kyrene Akimel A-1 Middle School Building Name/Number: Main

AHERA certification number: 4380 125011236 Signature of Inspector: Carly Hall

*Material Reinspected: M-QPT-77, Quarry/Paver Tile, 12"X12", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc. (3)

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\77.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 438012512361 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-CON-78, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\78.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Ceryn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4381281236 Signature of Inspector: Ceryn Hall

*Material Reinspected: M-GWB-79, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\79.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbonte
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 43001201236 Signature of Inspector: Carbonte

*Material Reinspected: S-JTC-80, Joint, Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\80.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 432065012364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MRT-86, Mortar (Glass Block), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\86.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 45802201236 Signature of Inspector: Carson Hall

*Material Reinspected: M-SLT-88, Sealant (Flashings), Tan, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc. 3.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\88.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Coryn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number: 4582222222 Signature of Inspector: Coryn Hall

*Material Reinspected: M-SLT-89, Sealant (Flashings), White, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\89.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main
AHERA certification number: 4350125012264 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-SLT-91, Sealant (Doors, Windows), Brown, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\91.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbin Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main

AHERA certification number 4380120112369 Signature of Inspector: Corbin Hall

*Material Reinspected: M-CON-92, Concrete (Entries), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\92.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main
AHERA certification number: 4380250236 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-EXJ-93, Expansion Joint, Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Main\93.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 01/21/21 Person performing reinspection: Cecy Hall
Facility: Kyrene Akimel A-ai Middle School Building Name/Number: Main
AHERA certification number: 438012501246 Signature of Inspector: Cecy Hall
*Material Reinspected: M-CON-94, Concrete, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\94.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/24/21 Person performing reinspection: Corbin Hall
Facility: Kyrene Akimel A-l Middle School Building Name/Number: Main
AHERA certification number: 43001200234 Signature of Inspector: Corbin Hall
*Material Reinspected: M-EXJ-95, Expansion Joint, Brown, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\95.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 09/14/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-1 Middle School Building Name/Number: Main
AHERA certification number: 4388 12501236 Signature of Inspector: Cerbyn Hall
*Material Reinspected: M-GWT-96, Glazed Wall Tile, 8"X8", Brown, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\96.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Cordyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Main
AHERA certification number: 4380125011234 Signature of Inspector: Cordyn Hall
*Material Reinspected: M-GWT-97, Glazed Wall Tile, 4"X8", Brown, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Main\97.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: Cerbyn Hall Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-VCT-10, Vinyl Composition Tile, 12"X12", White, Smooth, Gray Mottles

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\10.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbya Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 438012501206 Signature of Inspector: Cerbya Hall

*Material Reinspected: M-VCT-11, Vinyl Composition Tile (Pattern), 12"X12", Blue, Smooth, Dark Blue Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\11.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/14/21 Person performing reinspection: Corby Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4360 6521 1234 Signature of Inspector: Corby Hall

*Material Reinspected: M-VCT-12, Vinyl Composition Tile (Pattern), 12"X12", Tan, Smooth, Gray Mottles

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conby Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 43001250112314 Signature of Inspector: Conby Hall

*Material Reinspected: M-VCT-13, Vinyl Composition Tile (Pattern), 12"X12", Tan, Smooth, Black Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carben Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 1310150112365 Signature of Inspector: Carben Hall

*Material Reinspected: M-MAS-14, Mastic, Yellow, Tacky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium ✓ Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\14.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4380125012369 Signature of Inspector: [Signature]

*Material Reinspected: M-SAC-15, Sink Acoustical Coating, Black, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium ✓ Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/21/21 Person performing reinspection: Corbin Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4380125012369 Signature of Inspector: Corbin Hall

*Material Reinspected: M-PSL-18, Pipe End Sealant (Fire Sprinklers), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\18.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/9/21 Person performing reinspection: Cameron Hall
Facility: Kyrene Akimel A-ai Middle School Building Name/Number: Gym

AHERA certification number: 130025012361 Signature of Inspector: Cameron Hall

*Material Reinspected: M-FDI-19, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\19.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4380/2524 Signature of Inspector: [Signature]

*Material Reinspected: M-CON-21, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\21.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/14/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 438012369 Signature of Inspector: Carson Hall

*Material Reinspected: M-WDB-22, Woven Duct Boot, 4", Black, Canvas

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\22.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-ai Middle School Building Name/Number: Gym

AHERA certification number: 435012501123 Signature of Inspector: Cerbyn Hall

*Material Reinspected: S-SAT-31, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Gym\31.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbun Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 43101251036 Signature of Inspector: Carbun Hall

*Material Reinspected: M-GWB-32, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\32.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carmen Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4130012811206 Signature of Inspector: Carmen Hall

*Material Reinspected: S-JTC-33, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\33.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-1 Middle School Building Name/Number: Gym

AHERA certification number: 4382 D011236 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PES-34, Pipe End Sealant, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\34.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 43802581236 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWB-35, Gypsum Wallboard, White, Chalky, Vinyl Cover

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\35.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4380120012364 Signature of Inspector: Carson Hall

*Material Reinspected: S-JTC-36, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\36.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4380129211256 Signature of Inspector: Carson Hall

*Material Reinspected: M-VCT-37, Vinyl Composition Tile (Pattern), 12"X12", Gray, Smooth, Dark Gray Mottles

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\37.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 43601250136 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-WAB-38, Wallbase (Coved), 4", Blue, Vinyl-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\38.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbin Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4350125011236 Signature of Inspector: Corbin Hall

*Material Reinspected: M-ADH-39, Adhesive, Cream, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\39.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-ai Middle School Building Name/Number: Gym

AHERA certification number: 4580 6001 12364 Signature of Inspector: Cornel Pire

*Material Reinspected: M-QPT-42, Quarry/Paver Tile, 12"X12", Tan, Smooth, Blue Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\42.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cordyn Hull
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 430125017236 Signature of Inspector: Cordyn Hull

*Material Reinspected: M-QPT-43, Quarry/Paver Tile, 12"X12", Blue, Smooth, Blue Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\43.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/21/21 Person performing reinspection: Candace Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 4380125912369 Signature of Inspector: Candace Hall
*Material Reinspected: M-GRT-44, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Gym\44.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/21/21 Person performing reinspection: Cerbm Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4380250112361 Signature of Inspector: Cerbm Hall

*Material Reinspected: M-GWT-45, Glazed Wall Tile (Coved), 4"X6", Tan, Smooth, Blue Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\45.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 4380 1201636 Signature of Inspector: Carbyn Hall
*Material Reinspected: M-GRT-46, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes ☐ No ☒
Evidence of Water Damage: _____ Yes ☐ No ☒
Evidence of Delamination or Other Damage: _____ Yes ☐ No ☒
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes ☐ No ☒

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes ☐ No ☒
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\46.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 43802501234 Signature of Inspector: Carson Hall
*Material Reinspected: M-ADH-47, Adhesive (FRP), Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\47.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/11/21 Person performing reinspection: Conby, J. Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 143801234123149 Signature of Inspector: Conby, J. Hall
*Material Reinspected: M-SLT-49, Sealant (Duct), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Gym\49.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 43802211236 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-53, Sealant (Flashings), White, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\53.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4386201269 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PES-54, Pipe End Sealant, Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\54.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 43012501236 Signature of Inspector: Carlyn Hall
*Material Reinspected: M-MAS-56, Mastic (Penetrations and Flashings), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\56.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corby Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 430125189 Signature of Inspector: Corby Hall

*Material Reinspected: M-SLT-57, Sealant (Flashings), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\57.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbontally
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 138012411316 Signature of Inspector: Carbontally

*Material Reinspected: M-SLT-58, Sealant (Duct), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No ☒
Evidence of Water Damage: _____ Yes / No ☒
Evidence of Delamination or Other Damage: _____ Yes / No ☒
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes ☐ No ☒

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes ☐ No ☒
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\58.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbin Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 4380125012369 Signature of Inspector: Corbin Hall

*Material Reinspected: M-APR-59, Asphalt Prepared Roofing (Rolled), Black, Asphaltic, White Coating

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\59.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 438012369 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-SLT-60, Sealant (Flashings), Black, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\60.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 458125121616 Signature of Inspector: Cerbyn Hall
*Material Reinspected: M-WDB-61, Woven Duct Boot, 4", Gray, Cloth-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\61.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbin Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4300125123104 Signature of Inspector: Corbin Hall

*Material Reinspected: M-SLT-62, Sealant (Skylights), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\62.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 4360125012329 Signature of Inspector: Cerbyn Hall
*Material Reinspected: M-VST-63, Vinyl Stair Tread, 12"X36", Blue, Textured, Circle Pattern

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\63.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corby Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 4380145115364 Signature of Inspector: Cowan Fred

*Material Reinspected: M-MAS-64, Mastic, Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\64.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/14/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 4380600123164 Signature of Inspector: Corbyn Hall
*Material Reinspected: S-SAT-65, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\65.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 4380 25212361 Signature of Inspector: Carson Hall
*Material Reinspected: M-GWB-66, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Gym\66.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbry Hurl
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 43801234 1234 Signature of Inspector: Carbry Hurl
*Material Reinspected: S-JTC-67, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\67.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 4380 6511236 Signature of Inspector: Carbyn Hall
*Material Reinspected: M-GWT-68, Glazed Wall Tile, 12"X12", Red, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\68.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 437012912316 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-MRT-69, Mortar (GWT And Glass Block), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\69.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/14/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 437024124 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-SLT-70, Sealant (Doors), Black, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\70.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4302501236 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-CPT-71, Carpet (Pattern), Blue, Fibrous

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\71.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4580125012367 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWB-72, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\72.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 138125012361 Signature of Inspector: Carson Hall

*Material Reinspected: S-JTC-73, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: ① Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes ☐ No ☒

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\73.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 438012821/23169 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-GWT-76, Glazed Wall Tile (Pattern), 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\76.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4386 65211216 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-75, Glazed Wall Tile (Pattern), 2"X2", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\75.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corsyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 458812312316 Signature of Inspector: Corsyn Hall

*Material Reinspected: M-GWT-74, Glazed Wall Tile, 4"X4", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\74.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cordyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym
AHERA certification number: 4301224256 Signature of Inspector: Cordyn Hall
*Material Reinspected: M-GRT-77, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\77.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 430125124 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-CMT-78, Ceramic Mosaic Tile, 2"X2", White, Smooth, Peppered

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\78.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/21/21 Person performing reinspection: Cerbya Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 1180025712366 Signature of Inspector: Cerbya Hall

*Material Reinspected: M-CMT-79, Ceramic Mosaic Tile (Pattern), 2"X2", Tan, Smooth, Peppered

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ☒ 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes ☐ No ☒
Evidence of Water Damage: _____ Yes ☐ No ☒
Evidence of Delamination or Other Damage: _____ Yes ☐ No ☒
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes ☐ No ☒

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes ☐ No ☒
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\79.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbm Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4380 / 2581256 Signature of Inspector: Carbm Hall

*Material Reinspected: M-CMT-80, Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth, Peppered

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place / 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High / Medium _____ Low _____
Degree of Activity Near the Material: High / Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\80.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 438012511236 Signature of Inspector: Carson Hall

*Material Reinspected: M-GRT-81, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ☒ 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\81.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbon Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 43012511236 Signature of Inspector: Cerbon Hall

*Material Reinspected: M-WAB-82, Wallbase (L-Shaped), 4", Black, Vinyl-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\82.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4360122123169 Signature of Inspector: Carson Hall

*Material Reinspected: M-ADH-83, Adhesive, Cream, Pliable -Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\83.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4380122112364 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-ADH-84, Adhesive (FRP), Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☐ Medium ☒ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\84.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 43812811284 Signature of Inspector: Conbyn Hall

*Material Reinspected: M-QPT-85, Quarry/Paver Tile, 12"X12", White, Textured

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\85.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4370123112364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-86, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 6 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\86.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carben Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 439128236 Signature of Inspector: Carben Hall

*Material Reinspected: M-GWT-87, Glazed Wall Tile (Coved), 4"X6", White, Textured

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\87.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corsyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4581210246 Signature of Inspector: Corsyn Hall

*Material Reinspected: M-GRT-88, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\88.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 1370175123 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GWB-89, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\89.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4301251234 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-JTC-90, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: (1) Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\90.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlynn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4001211236 Signature of Inspector: Carlynn Hall

*Material Reinspected: M-EXJ-91, Expansion Joint, Brown, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. ☒ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No

Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\91.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 437012011236 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-92, Sealant (Doors, Windows), Brown, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ☒ 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☒ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\92.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/17/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 43801201106 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-CON-93, Concrete (Entries), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\93.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 4370 1289 1006 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-EXJ-94, Expansion Joint, Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes (No)
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / (No)
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / (No)
Evidence of Water Damage: _____ Yes / (No)
Evidence of Delamination or Other Damage: _____ Yes / (No)
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / (No)
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes (No)

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes (No)
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Gym\94.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Gym

AHERA certification number: 45812011216 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-CMU-96, Concrete Masonry Unit, 8"X8", Gray, Cementitious, Cross Cut Pattern

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Gym\96.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10-4-21 Person performing reinspection: Candyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 438012369 Signature of Inspector: Candyn Hall

*Material Reinspected: S-SAT-01, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: (1) Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 1510125112314 Signature of Inspector: Conyn Hall

*Material Reinspected: M-GWB-02, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession
AHERA certification number: 4300 D012364 Signature of Inspector: Carbyn Hall

*Material Reinspected: S-JTC-03, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: (1) Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Concl03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Ceryn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4350120112014 Signature of Inspector: Ceryn Hall

*Material Reinspected: M-GWT-04, Glazed Wall Tile, 4"X4", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ☒ 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4380125012364 Signature of Inspector: Conyn Hall

*Material Reinspected: M-GWT-05, Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Conc\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10-4-21 Person performing reinspection: Conbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4360125-11236 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-06, Glazed Wall Tile (Pattern), 4"X4", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\06.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn H. H.
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession
AHERA certification number: 43012501236 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-07, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\07.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 9380 125412345 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CMT-08, Ceramic Mosaic Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\08.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carson Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 43612511236 Signature of Inspector: Carson Hall

*Material Reinspected: M-CMT-09, Ceramic Mosaic Tile (Pattern), 2"X2", Tan, Smooth, White Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\09.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Coryn Hall
Facility: Kyrene Akimel A-ai Middle School Building Name/Number: Concession

AHERA certification number: 4376125012366 signature of Inspector: Coryn Hall

*Material Reinspected: M-CMT-10, Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth, White Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\10.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbin Hall

Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4580-12061 Signature of Inspector: Corbin Hall

*Material Reinspected: M-GRT-11, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Conc\11.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Cecilia Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 430120112364 Signature of Inspector: Cecilia Hall

*Material Reinspected: M-SLT-12, Sealant (Doors, Millwork, Fixtures), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ☒ 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium ☒ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Concl12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 618301260112 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-SAT-13, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 1301201231 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWB-14, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\14.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4510120112369 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-JTC-15, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4386120412361 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-WAB-16, Wallbase (Coved), 4", Blue, Vinyl-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Concl\16.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 45012701236 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-ADH-17, Adhesive, Cream, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☒ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☒ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\17.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Caryn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession
AHERA certification number: 43012501236 Signature of Inspector: Caryn Hall
*Material Reinspected: M-CON-18, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\18.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4380 12521231 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-FDI-19, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ☒ 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium ☒ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Concl19.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4320129012265 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-CMU-20, Concrete Masonry Unit, 8"X16", Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\20.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4380 D-12-1266 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-CMU-21, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Concl\21.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene Akimel A-1 Middle School Building Name/Number: Concession

AHERA certification number: 4370 125611236 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CMU-22, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\22.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbya Hall

Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4370 12561236 Signature of Inspector: Corbya Hall

*Material Reinspected: M-CMU-23, Concrete Masonry Unit, 8"X8", Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Concl\23.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 436 12-1236 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CMU-24, Concrete Masonry Unit, 4"X8", Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 408 1241236 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-CMU-25, Concrete Masonry Unit, 4"X8", Gray, Cementitious, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ☒ 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\25.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall

Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4350 1234 1234 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-MRT-26, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\26.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Ceryn Hall

Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 437012511236 Signature of Inspector: Ceryn Hall

*Material Reinspected: M-SAC-27, Sink Acoustical Coating, Gray, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\27.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carben Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4376 1256112467 Signature of Inspector: Carben Hall

*Material Reinspected: M-GWB-28, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Concl\28.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carly H. H. 11
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession
AHERA certification number: 4350 2521 12345 signature of Inspector: [Signature]
*Material Reinspected: S-JTC-29, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ☒ 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes ☐ No ☒
Evidence of Water Damage: _____ Yes ☐ No ☒
Evidence of Delamination or Other Damage: _____ Yes ☐ No ☒
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☐ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes ☐ No ☒

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes ☐ No ☒
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\29.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corby Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 430126012369 Signature of Inspector: Corby Hall

*Material Reinspected: S-STU-30, Stucco, Gray, Cementitious

Type of Asbestos-Containing Material: ☒ Surf. ☐ 2. TSI ☐ 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Concl30.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hull
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 468012512367 Signature of Inspector: Corbyn Hull

*Material Reinspected: M-SLT-31, Sealant (Fixtures), Black, Gummy

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Conc\31.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession
AHERA certification number: 438517012169 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-SLT-32, Sealant (Doors, Walls), Brown, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\32.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbony Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 430120010329 Signature of Inspector: Carbony Hall

*Material Reinspected: M-CON-33, Concrete (Entries), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Concl33.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 137012501034 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GWT-34, Glazed Wall Tile, 12"X12", Brown, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ☒ 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☐ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Concl34.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cordyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession
AHERA certification number: 41590125012365 Signature of Inspector: Cordyn Hall

*Material Reinspected: M-SLT-35, Sealant (Fire Stop), Red, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Concl\35.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/14/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession
AHERA certification number: 438125-112369 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GAS-36, Gasket, 4"-6", Black, Vinyl-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carmyn Hall

Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4380 DSD/236 Signature of Inspector: Carmyn Hall

*Material Reinspected: M-BUR-37, Built-Up Roofing, Black, Asphaltic, Silver Coating

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Concl\37.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4310 1211234 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MAS-38, Mastic (Penetrations and Flashings), Black, Asphaltic

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\38.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conryn Hall

Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4386120412365 Signature of Inspector: Conryn Hall

*Material Reinspected: M-SLT-39, Sealant (Flashings), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High _____ Medium _____ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\39.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession

AHERA certification number: 4390/281/2364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-40, Sealant (Flashings), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\40.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Concession
AHERA certification number: 45003012360 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-SLT-41, Sealant (Duct), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Conc\41.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 04/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Storage 1

AHERA certification number: 138012316 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-CMU-01, Concrete Masonry Unit, 8"X16", Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Stor 1\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Storage 1

AHERA certification number: 4360125211234 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-MRT-02, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Stor 1\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/11 Person performing reinspection: Cornelia Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Storage 1

AHERA certification number: 430125012364 Signature of Inspector: Cornelia Hall

*Material Reinspected: M-CON-03, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Stor 1\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbya Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Storage 1

AHERA certification number: 43701230123164 Signature of Inspector: Carbya Hall

*Material Reinspected: M-APR-04, Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Brown Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Stor 1\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Coryn Hall
Facility: Kyrene Akimel A-ai Middle School Building Name/Number: Storage 1

AHERA certification number: 4380125011226 Signature of Inspector: Coryn Hall

*Material Reinspected: M-VBF-05, Vapor Barrier Felt, Black, Asphaltic

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Stor 1\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carmen Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Storage 2

AHERA certification number: 4360/2501/2366 Signature of Inspector: Carmen Hall

*Material Reinspected: M-VBF-02, Vapor Barrier Felt, Black, Asphaltic

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Stor 2\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carly Hall
Facility: Kyrene Akime Middle School Building Name/Number: Storage 2

AHERA certification number: 4360 1234/1234 Signature of Inspector: Carly Hall

*Material Reinspected: M-APR-01, Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Tan Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akime\Forms\Stor 2\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/24/21 Person performing reinspection: Candyn Hall
Facility: Kyrene Akimel A-al Middle School Building Name/Number: Storage 2

AHERA certification number: 4350 L2501 0316 Signature of Inspector: Candyn Hall

*Material Reinspected: M-CON-03, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Akimel\Forms\Stor 2\03.doc