



November 5, 2021

Mr. Giacomo Musella  
Facilities Supervisor  
Kyrene School District No. 28  
8700 South Kyrene Road  
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection  
Asbestos-Containing Building Materials  
Kyrene Altadena Middle School  
14620 South Desert Foothills Parkway, Phoenix  
FM Project 18-259**

Dear Mr. Musella:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

**Items of significance are: None.**

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

**FM GROUP INC**

A handwritten signature in black ink, appearing to read 'Cliff Rolle', with a long horizontal line extending to the right.

Cliff Rolle  
Environmental Project Manager

A handwritten signature in black ink, appearing to read 'Paul Anger', with a stylized 'P' and 'A'.

Paul Anger  
Environmental Division Manager

*Attachments: 3-Year Reinspection Tables  
3-Year Reinspection Forms*

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Altadena\Cvr Ltr.doc

### 3-YEAR REINSPECTION TABLE IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	70,000	SF	09/16/21
M-MAS-02	M	Mastic (Penetrations And Flashings), Black, Tar-Like, Silver	Roof	Assumed	NF	G	300	SF	09/16/21
M-BUR-03	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	10,000	SF	09/16/21
M-MAS-04	M	Mastic (Penetrations And Flashings), Black, Tar-Like, Silver	Roof	Assumed	NF	G	100	SF	09/16/21
M-SLT-05	M	Sealant (Flashings), Black, Tar- Like	Roof	Assumed	NF	G	10	SF	09/16/21
M-SLT-06	M	Sealant (Doors, Windows, Walls, Flashings), Tan, Pliable	Courtyard	Assumed	NF	G	80	SF	09/16/21
			Exterior						
			Roof						
S-STU-07	S	Stucco, Gray, Cementitious	Courtyard	Assumed	NF	G	6,000	SF	09/16/21
			Exterior						
			Roof						
M-CMU-08	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	Stair 02	Assumed	NF	G	20,000	SF	09/16/21
			Courtyard						
			Exterior						
			Roof						
M-MRT-09	M	Mortar, Gray, Cementitious	Stair 02	Assumed	NF	G	2,680	SF	09/16/21
			Courtyard						
			Exterior						
			Roof						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-SLT-10	M	Sealant (Windows, Roof), Black, Pliable	Exterior	Assumed	NF	G	20	SF	09/16/21
			Roof						
M-SLT-11	M	Sealant (Roof), Gray, Pliable	Roof	Assumed	NF	G	25	SF	09/16/21
M-CMU-12	M	Concrete Masonry Unit, 8"X16", Pink, Cementitious, Rough	Stair 02	Assumed	NF	G	4,500	SF	09/16/21
			Courtyard						
			Exterior						
			Roof						
M-BRK-13	M	Brick, 4"X16", Red, Cementitious	Stair 02	Assumed	NF	G	2,300	SF	09/16/21
			Courtyard						
			Exterior						
			Roof						
M-CON-16	M	Concrete (Columns), Gray, Cementitious	Courtyard	Assumed	NF	G	300	SF	09/16/21
M-FDI-17	M	Fire Door Insulation, Metal/Wood Cladding	Waiting Lobby	Assumed	NF	G	2,625	SF	09/16/21
			Reception						
			Hall 01						
			Stair 01						
			Health						
			Student Services						
			Elev/Equipment Storage Room						
			Cadd						
			Tech Room						
			Tech Yard						
			Art Yard						
			Table Storage						
			Hall 02						
			Food/Child Dev Lab						
			Art Room						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 02						
			Corridor 04						
			Courtyard						
			Classroom 100						
			Classroom 101						
			Classroom 102						
			Classroom 103						
			Classroom 104						
			Classroom 105						
			Classroom 106						
			Science Classroom 107						
			Staff Lounge 04						
			Storage 11						
			Janitor 04						
			Science Classroom 108						
			Classroom 109						
			Classroom 110						
			Classroom 111						
			Classroom 112						
			Classroom 113						
			Classroom 114						
			Classroom 115						
			Computer Classroom 116						
			Special Ed 117						
			Electrical 04						
			Men's Staff Restroom 4						
			Women's Staff Restroom 4						
			Boy's Restroom 6						
			Girl's Restroom 6						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Lobby 4						
			Classroom 200						
			Classroom 201						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 202						
			Classroom 203						
			Boy's Restroom 5						
			Staff Lounge 03						
			Girl's Restroom 5						
			Lobby 3						
			Classroom 204						
			Classroom 205						
			Classroom 206						
			Science Classroom 207						
			Staff Lounge 02						
			Storage 10						
			Science Classroom 208						
			Classroom 209						
			Classroom 210						
			Classroom 211						
			Classroom 212						
			Classroom 213						
			Classroom 214						
			Classroom 215						
			Computer Classroom 216						
			Special Ed 217						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Women's Staff Restroom 3						
			Electrical 03						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Men's Staff Restroom 3						
			Janitor 03						
			Classroom 300						
			Classroom 301						
			Classroom 302						
			Classroom 303						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 304						
			Classroom 305						
			Classroom 306						
			Science Classroom 307						
			Staff Lounge 01						
			Storage 09						
			Science Classroom 308						
			Classroom 309						
			Classroom 310						
			Classroom 311						
			Classroom 312						
			Classroom 313						
			Classroom 314						
			Classroom 315						
			Special Ed 317						
			Computer Classroom 316						
			Men's Staff Restroom 2						
			Electrical 02						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Janitor 02						
			Women's Staff Restroom 2						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Lobby 1						
			Corridor 05						
			Corridor 06						
			Corridor 07						
			Corridor 08						
			Corridor 09						
			Corridor 10						
			Corridor 11						
			Corridor 12						
			Corridor 13						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 14						
			Corridor 15						
			Corridor 16						
			Corridor 17						
			Corridor 18						
			Corridor 19						
			Corridor 20						
			Corridor 21						
			Corridor 22						
			Exterior						
M-SLT-19	M	Sealant (Doors, Windows), Black, Gummy	Courtyard	Assumed	NF	G	50	SF	09/16/21
			Corridor 05						
			Corridor 06						
			Corridor 07						
			Corridor 09						
			Corridor 10						
			Corridor 11						
			Corridor 13						
			Corridor 16						
			Corridor 17						
			Corridor 19						
			Exterior						
M-SAC-39	M	Sink Acoustical Coating, Gray, Rough	Treatment	Assumed	NF	G	126	SF	09/16/21
			Health						
			Food/Child Dev Lab						
			Art Room						
			Classroom 100						
			Classroom 101						
			Classroom 102						
			Classroom 103						
			Classroom 104						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 105						
			Classroom 106						
			Staff Lounge O4						
			Classroom 109						
			Classroom 110						
			Classroom 111						
			Classroom 112						
			Classroom 113						
			Classroom 114						
			Classroom 115						
			Special Ed 117						
			Classroom 200						
			Classroom 201						
			Classroom 202						
			Classroom 203						
			Classroom 204						
			Classroom 205						
			Classroom 206						
			Staff Lounge 02						
			Classroom 209						
			Classroom 210						
			Classroom 211						
			Classroom 212						
			Classroom 213						
			Classroom 214						
			Classroom 215						
			Special Ed 217						
			Classroom 300						
			Classroom 301						
			Classroom 302						
			Classroom 303						
			Classroom 304						
			Classroom 305						
			Classroom 306						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Lounge 01						
			Classroom 309						
			Classroom 310						
			Classroom 311						
			Classroom 312						
			Classroom 313						
			Classroom 314						
			Classroom 315						
			Special Ed 317						
M-VST-46	M	Vinyl Stair Tread, 12"X36", Blue, Vinyl-Like, Circle Pattern	Stair 01	Assumed	NF	G	300	SF	09/16/21
M-MAS-47	M	Mastic, White, Pliable	Stair 01	Assumed	NF	G	300	SF	09/16/21
M-VCT-48	M	Vinyl Composition Tile, 18"X18", Blue, Textured, Circle Pattern	Stair 01	Assumed	NF	G	300	SF	09/16/21
M-MAS-49	M	Mastic, White, Brittle	Stair 01	Assumed	NF	G	300	SF	09/16/21
M-SLT-52	M	Sealant (Duct), White, Pliable	Waiting Lobby	Assumed	NF	G	300	SF	09/16/21
			Reception						
			A/V						
			Mail						
			Principal						
			Office 01						
			Office 02						
			Office 03						
			Office 04						
			Office 05						
			Electrical 01						
			Janitor 01						
			Hall 01						
			Stair 01						
			Staff Men's Restroom 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Women's Restroom 1						
			Conference Room						
			Conference Room Closet						
			Assistant Principal						
			Assistant Principal Closet						
			Storage 01						
			Cots						
			Treatment						
			Test						
			Health						
			Nurse						
			Nurse Restroom						
			Student Services						
			Cadd						
			Tech Room						
			Storage 07						
			Storage 08						
			Car Storage						
			Hall 02						
			H.E. Restroom						
			Laundry						
			Food/Child Dev Lab						
			Art Storage 02						
			Storage 04						
			Art Storage 01						
			Art Room						
			Corridor 01						
			Corridor 02						
			Corridor 03						
			Corridor 04						
			Classroom 100						
			Classroom 101						
			Classroom 102						
			Classroom 103						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 104						
			Classroom 105						
			Classroom 106						
			Science Classroom 107						
			Staff Lounge 04						
			Storage 11						
			Janitor 04						
			Science Classroom 108						
			Classroom 109						
			Classroom 110						
			Classroom 111						
			Classroom 112						
			Classroom 113						
			Classroom 114						
			Classroom 115						
			Computer Classroom 116						
			Special Ed 117						
			Electrical 04						
			Men's Staff Restroom 4						
			Women's Staff Restroom 4						
			Boy's Restroom 6						
			Girl's Restroom 6						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Lobby 4						
			Classroom 200						
			Classroom 201						
			Classroom 202						
			Classroom 203						
			Storage 14						
			Storage 15						
			Boy's Restroom 5						
			Storage 12						
			Staff Lounge 03						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 13						
			Girl's Restroom 5						
			Storage 16						
			Lobby 3						
			Classroom 204						
			Classroom 205						
			Room 205a						
			Classroom 206						
			Science Classroom 207						
			Staff Lounge 02						
			Storage 10						
			Science Classroom 208						
			Classroom 209						
			Classroom 210						
			Classroom 211						
			Classroom 212						
			Classroom 213						
			Classroom 214						
			Classroom 215						
			Computer Classroom 216						
			Special Ed 217						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Women's Staff Restroom 3						
			Electrical 03						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Men's Staff Restroom 3						
			Janitor 03						
			Lobby 2						
			Classroom 300						
			Classroom 301						
			Classroom 302						
			Classroom 303						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 304						
			Bedroom 1						
			Bedroom 1 Closet						
			Living Room						
			Kitchen						
			Bedroom 2						
			Apt Restroom						
			Classroom 305						
			Classroom 306						
			Science Classroom 307						
			Staff Lounge 01						
			Storage 09						
			Science Classroom 308						
			Classroom 309						
			Classroom 310						
			Classroom 311						
			Classroom 312						
			Classroom 313						
			Classroom 314						
			Classroom 315						
			Computer Classroom 316						
			Special Ed 317						
			Men's Staff Restroom 2						
			Electrical 02						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Janitor 02						
			Women's Staff Restroom 2						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Lobby 1						
			Corridor 05						
			Corridor 06						
			Corridor 07						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 08						
			Corridor 09						
			Corridor 10						
			Corridor 11						
			Corridor 12						
			Corridor 13						
			Corridor 14						
			Corridor 15						
			Corridor 16						
			Corridor 17						
			Corridor 18						
			Corridor 19						
			Corridor 20						
			Corridor 21						
			Corridor 22						
M-WDB-53	M	Woven Duct Boot, 2", Black, Rubber-Like	Waiting Lobby	Assumed	NF	G	150	SF	09/16/21
			Reception						
			A/V						
			Mail						
			Principal						
			Office 01						
			Office 02						
			Office 03						
			Office 04						
			Office 05						
			Electrical 01						
			Janitor 01						
			Hall 01						
			Stair 01						
			Staff Men's Restroom 1						
			Staff Women's Restroom 1						
			Conference Room						
			Conference Room Closet						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Assistant Principal						
			Assistant Principal Closet						
			Storage 01						
			Cots						
			Treatment						
			Test						
			Health						
			Nurse						
			Nurse Restroom						
			Student Services						
			Elev/Equipment Storage Room						
			Cadd						
			Tech Room						
			Storage 07						
			Storage 08						
			Car Storage						
			Hall 02						
			H.E. Restroom						
			Laundry						
			Food/Child Dev Lab						
			Art Storage 02						
			Storage 04						
			Art Storage 01						
			Art Room						
			Corridor 01						
			Corridor 02						
			Corridor 03						
			Corridor 04						
			Classroom 100						
			Classroom 101						
			Classroom 102						
			Classroom 103						
			Classroom 104						
			Classroom 105						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 106						
			Science Classroom 107						
			Staff Lounge 04						
			Storage 11						
			Janitor 04						
			Science Classroom 108						
			Classroom 109						
			Classroom 110						
			Classroom 111						
			Classroom 112						
			Classroom 113						
			Classroom 114						
			Classroom 115						
			Computer Classroom 116						
			Special Ed 117						
			Electrical 04						
			Men's Staff Restroom 4						
			Women's Staff Restroom 4						
			Boy's Restroom 6						
			Girl's Restroom 6						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Lobby 4						
			Classroom 200						
			Classroom 201						
			Classroom 202						
			Classroom 203						
			Storage 14						
			Storage 15						
			Boy's Restroom 5						
			Storage 12						
			Staff Lounge 03						
			Storage 13						
			Girl's Restroom 5						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 16						
			Lobby 3						
			Classroom 204						
			Classroom 205						
			Room 205a						
			Classroom 206						
			Science Classroom 207						
			Staff Lounge 02						
			Storage 10						
			Science Classroom 208						
			Classroom 209						
			Classroom 210						
			Classroom 211						
			Classroom 212						
			Classroom 213						
			Classroom 214						
			Classroom 215						
			Computer Classroom 216						
			Special Ed 217						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Women's Staff Restroom 3						
			Electrical 03						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Men's Staff Restroom 3						
			Janitor 03						
			Lobby 2						
			Classroom 300						
			Classroom 301						
			Classroom 302						
			Classroom 303						
			Classroom 304						
			Bedroom 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Bedroom 1 Closet						
			Living Room						
			Kitchen						
			Bedroom 2						
			Apt Restroom						
			Classroom 305						
			Classroom 306						
			Science Classroom 307						
			Staff Lounge 01						
			Storage 09						
			Science Classroom 308						
			Classroom 309						
			Classroom 310						
			Classroom 311						
			Classroom 312						
			Classroom 313						
			Classroom 314						
			Classroom 315						
			Computer Classroom 316						
			Special Ed 317						
			Men's Staff Restroom 2						
			Electrical 02						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Janitor 02						
			Women's Staff Restroom 2						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Lobby 1						
			Corridor 05						
			Corridor 06						
			Corridor 07						
			Corridor 08						
			Corridor 09						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 10						
			Corridor 11						
			Corridor 12						
			Corridor 13						
			Corridor 14						
			Corridor 15						
			Corridor 16						
			Corridor 17						
			Corridor 18						
			Corridor 19						
			Corridor 20						
			Corridor 21						
			Corridor 22						
M-PES-54	M	Pipe End Sealant (Sprinklers), White, Pliable	Waiting Lobby	Assumed	NF	G	150	SF	09/16/21
			Reception						
			A/V						
			Mail						
			Principal						
			Office 01						
			Office 02						
			Office 03						
			Office 04						
			Office 05						
			Electrical 01						
			Janitor 01						
			Hall 01						
			Stair 01						
			Staff Men's Restroom 1						
			Staff Women's Restroom 1						
			Conference Room						
			Conference Room Closet						
			Assistant Principal						
			Assistant Principal Closet						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 01						
			Cots						
			Treatment						
			Test						
			Health						
			Nurse						
			Nurse Restroom						
			Student Services						
			Elev/Equipment Storage Room						
			Cadd						
			Tech Room						
			Storage 07						
			Storage 08						
			Car Storage						
			Hall 02						
			H.E. Restroom						
			Laundry						
			Food/Child Dev Lab						
			Art Storage 02						
			Storage 04						
			Art Storage 01						
			Art Room						
			Corridor 01						
			Corridor 02						
			Corridor 03						
			Corridor 04						
			Classroom 100						
			Classroom 101						
			Classroom 102						
			Classroom 103						
			Classroom 104						
			Classroom 105						
			Classroom 106						
			Science Classroom 107						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Lounge 04						
			Storage 11						
			Janitor 04						
			Science Classroom 108						
			Classroom 109						
			Classroom 110						
			Classroom 111						
			Classroom 112						
			Classroom 113						
			Classroom 114						
			Classroom 115						
			Computer Classroom 116						
			Special Ed 117						
			Electrical 04						
			Men's Staff Restroom 4						
			Women's Staff Restroom 4						
			Boy's Restroom 6						
			Girl's Restroom 6						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Lobby 4						
			Classroom 200						
			Classroom 201						
			Classroom 202						
			Classroom 203						
			Storage 14						
			Storage 15						
			Boy's Restroom 5						
			Storage 12						
			Staff Lounge 03						
			Storage 13						
			Girl's Restroom 5						
			Storage 16						
			Lobby 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 204						
			Classroom 205						
			Room 205a						
			Classroom 206						
			Science Classroom 207						
			Staff Lounge 02						
			Storage 10						
			Science Classroom 208						
			Classroom 209						
			Classroom 210						
			Classroom 211						
			Classroom 212						
			Classroom 213						
			Classroom 214						
			Classroom 215						
			Computer Classroom 216						
			Special Ed 217						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Women's Staff Restroom 3						
			Electrical 03						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Men's Staff Restroom 3						
			Janitor 03						
			Lobby 2						
			Classroom 300						
			Classroom 301						
			Classroom 302						
			Classroom 303						
			Classroom 304						
			Bedroom 1						
			Bedroom 1 Closet						
			Living Room						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Kitchen						
			Bedroom 2						
			Apt Restroom						
			Classroom 305						
			Classroom 306						
			Science Classroom 307						
			Staff Lounge 01						
			Storage 09						
			Science Classroom 308						
			Classroom 309						
			Classroom 310						
			Classroom 311						
			Classroom 312						
			Classroom 313						
			Classroom 314						
			Classroom 315						
			Computer Classroom 316						
			Special Ed 317						
			Men's Staff Restroom 2						
			Electrical 02						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Janitor 02						
			Women's Staff Restroom 2						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Lobby 1						
			Corridor 05						
			Corridor 06						
			Corridor 07						
			Corridor 08						
			Corridor 09						
			Corridor 10						
			Corridor 11						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 12						
			Corridor 13						
			Corridor 14						
			Corridor 15						
			Corridor 16						
			Corridor 17						
			Corridor 18						
			Corridor 19						
			Corridor 20						
			Corridor 21						
			Corridor 22						
M-GWT-56	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Men's Staff Restroom 4	Assumed	NF	G	10,000	SF	09/16/21
			Women's Staff Restroom 4						
			Boy's Restroom 6						
			Girl's Restroom 6						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Women's Staff Restroom 3						
			Apt Restroom						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Men's Staff Restroom 3						
			Men's Staff Restroom 2						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Women's Staff Restroom 2						
			Girl's Restroom 2						
			Boy's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GWT-57	M	Glazed Wall Tile (Pattern), 4"x4", Light Gray, Smooth	Men's Staff Restroom 4	Assumed	NF	G	1,000	SF	09/16/21
			Women's Staff Restroom 4						
			Boy's Restroom 6						
			Girl's Restroom 6						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Women's Staff Restroom 3						
			Apt Restroom						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Men's Staff Restroom 3						
			Men's Staff Restroom 2						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Women's Staff Restroom 2						
			Girl's Restroom 2						
			Boy's Restroom 2						
M-GWT-58	M	Glazed Wall Tile (Pattern), 4"x4", Black, Smooth	Men's Staff Restroom 4	Assumed	NF	G	500	SF	09/16/21
			Women's Staff Restroom 4						
			Boy's Restroom 6						
			Girl's Restroom 6						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Women's Staff Restroom 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Apt Restroom						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Men's Staff Restroom 3						
			Men's Staff Restroom 2						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Women's Staff Restroom 2						
			Girl's Restroom 2						
			Boy's Restroom 2						
M-GWT-59	M	Glazed Wall Tile (Coved), 4"X4", Blue, Smooth	Men's Staff Restroom 4	Assumed	NF	G	1,000	SF	09/16/21
			Women's Staff Restroom 4						
			Boy's Restroom 6						
			Girl's Restroom 6						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Women's Staff Restroom 3						
			Apt Restroom						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Men's Staff Restroom 3						
			Men's Staff Restroom 2						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Women's Staff Restroom 2						
			Girl's Restroom 2						
			Boy's Restroom 2						
M-GRT-60	M	Grout, Gray, Cementitious	Men's Staff Restroom 4	Assumed	NF	G	1,500	SF	09/16/21



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Women's Staff Restroom 4						
			Boy's Restroom 6						
			Girl's Restroom 6						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Women's Staff Restroom 3						
			Apt Restroom						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Men's Staff Restroom 3						
			Men's Staff Restroom 2						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Women's Staff Restroom 2						
			Girl's Restroom 2						
			Boy's Restroom 2						
M-CMT-61	M	Ceramic Mosaic Tile, 2"X2", Gray, Smooth	Women's Staff Restroom 3	Assumed	NF	G	300	SF	09/16/21
			Men's Staff Restroom 3						
			Men's Staff Restroom 2						
			Women's Staff Restroom 2						
M-CMT-62	M	Ceramic Mosaic Tile (Pattern), 2"X2", Gray, Smooth, White Specks	Women's Staff Restroom 3	Assumed	NF	G	30	SF	09/16/21
			Men's Staff Restroom 3						
			Men's Staff Restroom 2						
			Women's Staff Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMT-63	M	Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth, Brown Specks	Men's Staff Restroom 4	Assumed	NF	G	500	SF	09/16/21
			Women's Staff Restroom 4						
			Women's Staff Restroom 3						
			Men's Staff Restroom 3						
			Men's Staff Restroom 2						
			Women's Staff Restroom 2						
			Girl's Restroom 2						
			Boy's Restroom 2						
M-GRT-64	M	Grout, Gray, Cementitious	Men's Staff Restroom 4	Assumed	NF	G	1,000	SF	09/16/21
			Women's Staff Restroom 4						
			Boy's Restroom 6						
			Girl's Restroom 6						
			Boy's Restroom 7						
			Girl's Restroom 7						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Women's Staff Restroom 3						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Men's Staff Restroom 3						
			Men's Staff Restroom 2						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Women's Staff Restroom 2						
			Girl's Restroom 2						
			Boy's Restroom 2						
M-ADH-65	M	Adhesive (TWP), Brown, Brittle	Principal	Assumed	NF	G	4,500	SF	09/16/21
			Office 04						
			Student Services						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Cadd						
			Food/Child Dev Lab						
			Art Room						
			Classroom 100						
			Classroom 101						
			Classroom 102						
			Classroom 103						
			Classroom 104						
			Classroom 105						
			Classroom 106						
			Science Classroom 107						
			Science Classroom 108						
			Classroom 109						
			Classroom 110						
			Classroom 111						
			Classroom 112						
			Classroom 113						
			Classroom 114						
			Classroom 115						
			Computer Classroom 116						
			Special Ed 117						
			Classroom 200						
			Classroom 201						
			Classroom 202						
			Classroom 203						
			Classroom 204						
			Classroom 205						
			Classroom 206						
			Science Classroom 207						
			Science Classroom 208						
			Classroom 209						
			Classroom 210						
			Classroom 211						
			Classroom 212						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 213						
			Classroom 214						
			Classroom 215						
			Computer Classroom 216						
			Special Ed 217						
			Classroom 300						
			Classroom 301						
			Classroom 302						
			Classroom 303						
			Classroom 304						
			Classroom 305						
			Classroom 306						
			Science Classroom 307						
			Science Classroom 308						
			Classroom 309						
			Classroom 310						
			Classroom 312						
			Classroom 313						
			Classroom 314						
			Classroom 315						
			Computer Classroom 316						
			Special Ed 317						

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	40,000	SF	09/16/21
M-MAS-02	M	Mastic (Penetrations And Flashings), Black, Tar-Like	Roof	Assumed	NF	G	2,000	SF	09/16/21
M-SLT-03	M	Sealant (Flashings), Tan, Pliable	Roof	Assumed	NF	G	200	SF	09/16/21
M-SLT-04	M	Sealant (Flashings), Black, Pliable	Roof	Assumed	NF	G	200	SF	09/16/21
M-SLT-10	M	Sealant (Duct), Gray, Pliable	Lobby	Assumed	NF	G	200	SF	09/16/21
			Chorus						
			Multi-Purpose						
			Table Storage						
			Stage						
			Foyer 3						
			Electrical 1						
			Sound Room						
			Dressing Room 1						
			Unisex Restroom 1						
			Dressing Room 2						
			Band						
			Band Office						
			Freezer						
			Unisex Restroom 2						
			Foyer 2						
			Electrical 4						
			Office 01						
			Food Storage						
			Kitchen						
			Serving Room						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Women's Restroom						
			Men's Restroom						
			Foyer 1						
			Gym						
			Storage 1						
			P.E. Storage						
			Janitor						
			Girl's Coach						
			Girl's Coach Restroom						
			Girl's Locker Room 1						
			Girl's Storage						
			Girl's Shower						
			Girl's Restroom						
			Girl's Locker Room 2						
			Boy's Coach						
			Boy's Coach Restroom						
			Boy's Locker Room 1						
			Boy's Storage						
			Boy's Shower						
			Boy's Restroom						
			Boy's Locker Room 2						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Roof						
M-SLT-11	M	Sealant (Roof), Gray, Pliable Associated With Paneling (Metal), Factory Finish	Roof	Assumed	NF	G	10	SF	09/16/21
M-CMU-13	M	Concrete Masonry Unit (Pattern), 12"X12", Gray, Cementitious	Mechanical 2	Assumed	NF	G	300	SF	09/16/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CON-17	M	Concrete (Walls), Gray, Cementitious	Mechanical 2	Assumed	NF	G	400	SF	09/16/21
M-SLT-21	M	Sealant (Fire Stop), Red, Pliable	Electrical 3	Assumed	NF	G	10	SF	09/16/21
M-SLT-22	M	Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable	Lobby	Assumed	NF	G	50	SF	09/16/21
			Multi-Purpose						
			Stage						
			Foyer 3						
			Electrical 1						
			Dressing Room 1						
			Unisex Restroom 1						
			Dressing Room 2						
			Band						
			Band Office						
			Freezer						
			Unisex Restroom 2						
			Foyer 2						
			Office 01						
			Kitchen						
			Serving Room						
			Women's Restroom						
			Men's Restroom						
			Foyer 1						
			Storage 1						
			P.E. Storage						
			Janitor						
			Girl's Coach						
			Girl's Coach Restroom						
			Girl's Locker Room 1						
			Girl's Restroom						
			Mechanical Office						
			Electrical 3						
			Boy's Coach						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Coach Restroom						
			Boy's Locker Room 1						
			Boy's Storage						
			Boy's Restroom						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
S-SAT-28	S	Spray-Applied Texture, White, Chalky	Lobby	Assumed	NF	G	36,000	SF	09/16/21
			Chorus						
			Multi-Purpose						
			Stage						
			Foyer 3						
			Electrical 1						
			P.E. Storage						
			Janitor						
			Girl's Coach						
			Girl's Storage						
			Boy's Coach						
			Boy's Storage						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
M-GWB-29	M	Gypsum Wallboard, White, Chalky	Lobby	Assumed	NF	G	36,000	SF	09/16/21
			Chorus						
			Multi-Purpose						
			Stage						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Foyer 3						
			Electrical 1						
			P.E. Storage						
			Janitor						
			Girl's Coach						
			Girl's Storage						
			Boy's Coach						
			Boy's Storage						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
S-JTC-30	S	Joint Compound, White, Chalky	Lobby	Assumed	NF	G	3,600	SF	09/16/21
			Chorus						
			Multi-Purpose						
			Stage						
			Foyer 3						
			Electrical 1						
			P.E. Storage						
			Janitor						
			Girl's Coach						
			Girl's Storage						
			Boy's Coach						
			Boy's Storage						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-VCT-32	M	Vinyl Composition Tile (Pattern), 12"X12", White, Smooth, Brown Mottles	Lobby	Assumed	NF	G	300	SF	09/16/21
			Multi-Purpose						
M-VCT-33	M	Vinyl Composition Tile (Pattern), 12"X12", Light Blue, Smooth, Blue Mottles	Lobby	Assumed	NF	G	300	SF	09/16/21
			Multi-Purpose						
M-FDI-34	M	Fire Door Insulation, Metal/Wood Cladding	Lobby	Assumed	NF	G	1,701	SF	09/16/21
			Chorus						
			Multi-Purpose						
			Stage						
			Foyer 3						
			Electrical 1						
			Dressing Room 1						
			Unisex Restroom 1						
			Dressing Room 2						
			Band						
			Foyer 1						
			Serving Room						
			Kitchen Yard						
			Gym						
			Storage 1						
			P.E. Storage						
			Girl's Locker Room 1						
			Girl's Storage						
			Girl's Locker Room 2						
			Mechanical 1						
			Mechanical Office						
			Mechanical 2						
			Electrical 2						
			Electrical 3						
			Boy's Locker Room 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Storage						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Exterior						
M-GWT-35	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Kitchen	Assumed	NF	G	7,000	SF	09/16/21
			Serving Room						
			Women's Restroom						
			Men's Restroom						
			Foyer 1						
			Girl's Coach Restroom						
			Girl's Locker Room 1						
			Girl's Shower						
			Girl's Restroom						
			Girl's Locker Room 2						
			Boy's Coach Restroom						
			Boy's Locker Room 1						
			Boy's Shower						
			Boy's Restroom						
			Boy's Locker Room 2						
M-GWT-36	M	Glazed Wall Tile (Pattern), 4"X4", Light Gray, Smooth	Serving Room	Assumed	NF	G	500	SF	09/16/21
			Women's Restroom						
			Men's Restroom						
			Foyer 1						
			Girl's Coach Restroom						
			Girl's Locker Room 1						
			Girl's Shower						
			Girl's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Locker Room 2						
			Boy's Coach Restroom						
			Boy's Locker Room 1						
			Boy's Shower						
			Boy's Restroom						
			Boy's Locker Room 2						
M-GWT-37	M	Glazed Wall Tile (Pattern), 4"X4", Black, Smooth	Serving Room	Assumed	NF	G	500	SF	09/16/21
			Women's Restroom						
			Men's Restroom						
			Foyer 1						
			Girl's Coach Restroom						
			Girl's Locker Room 1						
			Girl's Shower						
			Girl's Restroom						
			Girl's Locker Room 2						
			Boy's Coach Restroom						
			Boy's Locker Room 1						
			Boy's Shower						
			Boy's Restroom						
			Boy's Locker Room 2						
M-GWT-38	M	Glazed Wall Tile (Coved), 4"X4", Blue, Smooth	Women's Restroom	Assumed	NF	G	400	SF	09/16/21
			Men's Restroom						
			Foyer 1						
			Girl's Coach Restroom						
			Girl's Locker Room 1						
			Girl's Shower						
			Girl's Restroom						
			Girl's Locker Room 2						
			Boy's Coach Restroom						
			Boy's Locker Room 1						
			Boy's Shower						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom						
			Boy's Locker Room 2						
M-GRT-39	M	Grout, Gray, Cementitious	Kitchen	Assumed	NF	G	700	SF	09/16/21
			Serving Room						
			Women's Restroom						
			Men's Restroom						
			Foyer 1						
			Girl's Coach Restroom						
			Girl's Locker Room 1						
			Girl's Shower						
			Girl's Restroom						
			Girl's Locker Room 2						
			Boy's Coach Restroom						
			Boy's Locker Room 1						
			Boy's Shower						
			Boy's Restroom						
			Boy's Locker Room 2						
M-CMT-40	M	Ceramic Mosaic Tile, 2"X2", Gray, Smooth	Women's Restroom	Assumed	NF	G	3,000	SF	09/16/21
			Men's Restroom						
			Girl's Locker Room 1						
			Girl's Restroom						
			Girl's Shower						
			Boy's Locker Room 1						
			Boy's Restroom						
			Boy's Shower						
M-CMT-41	M	Ceramic Mosaic Tile (Pattern), 2"X2", Gray, Smooth, White Specks	Women's Restroom	Assumed	NF	G	1,000	SF	09/16/21
			Men's Restroom						
			Girl's Locker Room 1						
			Girl's Restroom						
			Girl's Shower						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Locker Room 1						
			Boy's Restroom						
			Boy's Shower						
M-CMT-42	M	Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth, Brown Specks	Women's Restroom	Assumed	NF	G	1,000	SF	09/16/21
			Men's Restroom						
			Girl's Locker Room 1						
			Girl's Restroom						
			Girl's Shower						
			Boy's Locker Room 1						
			Boy's Restroom						
			Boy's Shower						
M-GRT-43	M	Grout, Gray, Cementitious	Women's Restroom	Assumed	NF	G	300	SF	09/16/21
			Men's Restroom						
			Girl's Locker Room 1						
			Girl's Restroom						
			Girl's Shower						
			Boy's Locker Room 1						
			Boy's Restroom						
			Boy's Shower						
S-SAT-44	S	Spray-Applied Texture, White, Chalky	Table Storage	Assumed	NF	G	7,000	SF	09/16/21
			Unisex Restroom 1						
			Unisex Restroom 2						
			Kitchen						
			Women's Restroom						
			Men's Restroom						
			Foyer 1						
			Girl's Coach Restroom						
			Girl's Locker Room 1						
			Girl's Shower						
			Girl's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Locker Room 2						
			Boy's Coach Restroom						
			Boy's Locker Room 1						
			Boy's Shower						
			Boy's Restroom						
			Boy's Locker Room 2						
M-GWB-45	M	Gypsum Wallboard, White, Chalky	Table Storage	Assumed	NF	G	7,000	SF	09/16/21
			Unisex Restroom 1						
			Unisex Restroom 2						
			Kitchen						
			Women's Restroom						
			Men's Restroom						
			Foyer 1						
			Girl's Coach Restroom						
			Girl's Locker Room 1						
			Girl's Shower						
			Girl's Restroom						
			Girl's Locker Room 2						
			Boy's Coach Restroom						
			Boy's Locker Room 1						
			Boy's Shower						
			Boy's Restroom						
			Boy's Locker Room 2						
S-JTC-46	S	Joint Compound, White, Chalky	Table Storage	Assumed	NF	G	700	SF	09/16/21
			Unisex Restroom 1						
			Unisex Restroom 2						
			Kitchen						
			Women's Restroom						
			Men's Restroom						
			Foyer 1						
			Girl's Coach Restroom						
			Girl's Locker Room 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Shower						
			Girl's Restroom						
			Girl's Locker Room 2						
			Boy's Coach Restroom						
			Boy's Locker Room 1						
			Boy's Shower						
			Boy's Restroom						
			Boy's Locker Room 2						
M-QPT-47	M	Quarry/Paver Tile, 12"X12", Gray, Smooth, Multi-Colored Specks	Kitchen	Assumed	NF	G	7,000	SF	09/16/21
			Serving Room						
			Girl's Locker Room 1						
			Girl's Locker Room 2						
			Boy's Locker Room 1						
			Boy's Locker Room 2						
M-GRT-48	M	Grout, Gray, Cementitious	Kitchen	Assumed	NF	G	700	SF	09/16/21
			Serving Room						
			Girl's Locker Room 1						
			Girl's Locker Room 2						
			Boy's Locker Room 1						
			Boy's Locker Room 2						
M-GWT-49	M	Glazed Wall Tile (Pattern), 4"X6", Gray, Smooth, Multi-Colored Specks	Table Storage	Assumed	NF	G	500	SF	09/16/21
			Kitchen						
			Serving Room						
			Girl's Locker Room 1						
			Girl's Shower						
			Girl's Restroom						
			Girl's Locker Room 2						
			Boy's Locker Room 1						
			Boy's Shower						
			Boy's Restroom						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Locker Room 2						
M-GRT-50	M	Grout, Gray, Cementitious	Table Storage	Assumed	NF	G	50	SF	09/16/21
			Kitchen						
			Serving Room						
			Girl's Locker Room 1						
			Girl's Shower						
			Girl's Restroom						
			Girl's Locker Room 2						
			Boy's Locker Room 1						
			Boy's Shower						
			Boy's Restroom						
			Boy's Locker Room 2						
M-VST-52	M	Vinyl Stair Tread, 12"X48", Blue, Vinyl-Like, Circle Pattern	Multi-Purpose	Assumed	NF	G	50	SF	09/16/21
			Corridor 2						
M-MAS-53	M	Mastic, Brown, Brittle	Multi-Purpose	Assumed	NF	G	50	SF	09/16/21
			Corridor 2						
M-ADH-58	M	Adhesive (FRP), Brown, Brittle	Kitchen	Assumed	NF	G	10	SF	09/16/21
M-SAC-59	M	Sink Acoustical Coating, Gray, Rough	Chorus	Assumed	NF	G	2	SF	09/16/21
M-WAB-60	M	Wallbase (Coved), 4", Black, Vinyl-Like	Gym	Assumed	NF	G	120	SF	09/16/21
M-ADH-61	M	Adhesive, Cream, Pliable	Gym	Assumed	NF	G	120	SF	09/16/21
M-PES-62	M	Pipe End Sealant (Sprinklers), White, Pliable	Lobby	Assumed	NF	G	100	SF	09/16/21
			Chorus						
			Multi-Purpose						
			Table Storage						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Stage						
			Foyer 3						
			Electrical 1						
			Sound Room						
			Dressing Room 1						
			Unisex Restroom 1						
			Dressing Room 2						
			Band						
			Band Office						
			Kitchen Yard						
			Freezer						
			Unisex Restroom 2						
			Foyer 2						
			Electrical 4						
			Office 01						
			Food Storage						
			Kitchen						
			Serving Room						
			Women's Restroom						
			Men's Restroom						
			Foyer 1						
			Gym						
			Storage 1						
			P.E. Storage						
			Janitor						
			Girl's Coach						
			Girl's Coach Restroom						
			Girl's Locker Room 1						
			Girl's Storage						
			Girl's Shower						
			Girl's Restroom						
			Girl's Locker Room 2						
			Mechanical Office						
			Boy's Coach						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Coach Restroom						
			Boy's Locker Room 1						
			Boy's Storage						
			Boy's Shower						
			Boy's Restroom						
			Boy's Locker Room 2						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
M-SLT-83	M	Sealant (Mechanical), Black, Brittle	Mechanical 2	4% Chrysotile	NF	G	15	SF	09/16/21

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap, Silver	Roof	Assumed	NF	G	25,000	SF	09/16/21
M-MAS-02	M	Mastic (Penetrations And Flashings), Black, Tar-Like	Roof	Assumed	NF	G	250	SF	09/16/21
M-SLT-03	M	Sealant (Flashings), Black, Pliable	Roof	Assumed	NF	G	100	SF	09/16/21
M-SLT-04	M	Sealant (Flashings), Gray, Pliable	Roof	Assumed	NF	G	100	SF	09/16/21
M-SLT-05	M	Sealant (Flashings), Tan, Pliable	Roof	Assumed	NF	G	25	SF	09/16/21
M-SLT-06	M	Sealant (Sky Light), Black, Brittle	Roof	Assumed	NF	G	5	SF	09/16/21
M-CMU-07	M	Concrete Masonry Unit, 8"x16", Gray, Cementitious, Smooth	Storage 1	Assumed	NF	G	15,000	SF	09/16/21
			Exterior						
M-CMU-08	M	Concrete Masonry Unit, 8"x16", Gray, Cementitious, Rough	Storage 1	Assumed	NF	G	1,500	SF	09/16/21
			Exterior						
M-CMU-09	M	Concrete Masonry Unit, 4"x16", Gray, Cementitious, Smooth	Storage 1	Assumed	NF	G	750	SF	09/16/21
			Exterior						
M-MRT-10	M	Mortar, Gray, Cementitious	Storage 1	Assumed	NF	G	1,500	SF	09/16/21
			Exterior						
M-EXJ-11	M	Expansion Joint, Gray, Pliable	Exterior	Assumed	NF	G	50	SF	09/16/21
M-SLT-12	M	Sealant (Doors, Windows, Fixtures), Gray, Pliable	Exterior	Assumed	NF	G	25	SF	09/16/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-STU-13	S	Stucco, Gray, Cementitious	Exterior	Assumed	NF	G	6,000	SF	09/16/21
M-CON-14	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	10,000	SF	09/16/21
M-MRT-15	M	Mortar (Glass Block), Gray, Cementitious	Exterior	Assumed	NF	G	25	SF	09/16/21
M-CON-16	M	Concrete (Columns), Gray, Cementitious	Exterior	Assumed	NF	G	300	SF	09/16/21
M-SLT-17	M	Sealant (Windows), Black, Tar-Like	Exterior	Assumed	NF	G	15	SF	09/16/21
M-EXJ-18	M	Expansion Joint (Entries), Gray, Pliable	Exterior	Assumed	NF	G	100	SF	09/16/21
M-APL-19	M	Acoustical Ceiling Panel, 2'x2', Gray, Pinholes And Fissures, White	Library	Assumed	F	G	15,500	SF	09/16/21
			Room 401						
			South Mountain						
			San Tan Mountain						
			Estrella Mountain						
			Camelback Mountain						
			Squaw Peak						
			Superstition Mountain						
			Cataloguing						
			A/V Storage						
			Staff Lounge						
			Telephone						
			Storage 02						
			Storage 03						
			Work Room 1						
			Work Room 2						
			Computer Lab 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Computer Lab 2						
			Conference						
			Receiving						
			Room 404						
			Vestibule						
			Multimedia						
			Studio						
M-ACT-20	M	Acoustical Ceiling Tile, 1'x1', Gray, Pinholes And Fissures, White	Library	Assumed	F	G	75	SF	09/16/21
M-ADH-21	M	Adhesive, Brown, Brittle	Library	Assumed	NF	G	75	SF	09/16/21
S-SAT-23	S	Spray-Applied Texture, White, Chalky	Library	Assumed	NF	G	35,000	SF	09/16/21
			Room 401						
			South Mountain						
			San Tan Mountain						
			Estrella Mountain						
			Camelback Mountain						
			Squaw Peak						
			Superstition Mountain						
			Cataloguing						
			A/V Storage						
			Staff Lounge						
			Telephone						
			Storage 02						
			Storage 03						
			Work Room 1						
			Work Room 2						
			Computer Lab 1						
			Computer Lab 2						
			Conference						
			Conference Storage						
			Receiving						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 404						
			Vestibule						
			Multimedia						
			Studio						
M·GWB·24	M	Gypsum Wallboard, White, Chalky	Library	Assumed	NF	G	35,000	SF	09/16/21
			Room 401						
			South Mountain						
			San Tan Mountain						
			Estrella Mountain						
			Camelback Mountain						
			Squaw Peak						
			Superstition Mountain						
			Cataloguing						
			A/V Storage						
			Staff Lounge						
			Telephone						
			Storage 02						
			Storage 03						
			Work Room 1						
			Work Room 2						
			Computer Lab 1						
			Computer Lab 2						
			Conference						
			Conference Storage						
			Receiving						
			Room 404						
			Vestibule						
			Multimedia						
			Studio						
S·JTC·25	S	Joint Compound, White, Chalky	Library	Assumed	NF	G	3,500	SF	09/16/21
			Room 401						
			South Mountain						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			San Tan Mountain						
			Estrella Mountain						
			Camelback Mountain						
			Squaw Peak						
			Superstition Mountain						
			Cataloguing						
			A/V Storage						
			Staff Lounge						
			Telephone						
			Storage 02						
			Storage 03						
			Work Room 1						
			Work Room 2						
			Computer Lab 1						
			Computer Lab 2						
			Conference						
			Conference Storage						
			Receiving						
			Room 404						
			Vestibule						
			Multimedia						
			Studio						
M-GWB-26	M	Gypsum Wallboard, White, Chalky, Vinyl Cover	Library	Assumed	NF	G	350	SF	09/16/21
S-JTC-27	S	Joint Compound, White, Chalky	Library	Assumed	NF	G	35	SF	09/16/21
M-TWP-28	M	Tackable Wall Panel, Brown, Fibrous, Vinyl Cover	Library	Assumed	NF	G	1,000	SF	09/16/21
			South Mountain						
			San Tan Mountain						
			Staff Lounge						
			Computer Lab 2						
			Multimedia						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-SLT-29	M	Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable	Library	Assumed	NF	G	50	SF	09/16/21
			Room 401						
			Men's Restroom 01						
			Women's Restroom 01						
			South Mountain						
			San Tan Mountain						
			Estrella Mountain						
			Camelback Mountain						
			Squaw Peak						
			Superstition Mountain						
			Cataloguing						
			A/V Storage						
			Staff Lounge						
			Telephone						
			Storage 01						
			Storage 02						
			Storage 03						
			Work Room 1						
			Work Room 2						
			Men's Restroom 02						
			Women's Restroom 02						
			Computer Lab 1						
			Computer Lab 2						
			Conference						
			Conference Storage						
			Receiving						
			Room 404						
			Vestibule						
			Multimedia						
			Studio						
M-QPT-34	M	Quarry/Paver Tile, 12"X12", Gray, Smooth, Peppered	Library	Assumed	NF	G	275	SF	09/16/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GRT-35	M	Grout, Gray, Cementitious	Library	Assumed	NF	G	30	SF	09/16/21
M-VCT-36	M	Vinyl Composition Tile, 12"X12", Tan, Smooth, Brown Mottles	Room 401	Assumed	NF	G	1,500	SF	09/16/21
M-VCT-37	M	Vinyl Composition Tile (Pattern), 12"X12", White, Smooth, Gray Mottles	Men's Restroom 01	Assumed	NF	G	75	SF	09/16/21
M-VCT-38	M	Vinyl Composition Tile (Pattern), 12"X12", Blue, Smooth, Dark Blue Mottles	Men's Restroom 01	Assumed	NF	G	75	SF	09/16/21
M-MAS-39	M	Mastic, Yellow, Tacky	Library	Assumed	NF	G	1,500	SF	09/16/21
			Room 401						
			Men's Restroom 01						
			Women's Restroom 02						
			Cataloguing						
			Storage 02						
			Storage 03						
			Work Room 1						
			Work Room 2						
			Men's Restroom 02						
			Women's Restroom 02						
			Multi-Media						
S-SAT-40	S	Spray-Applied Texture, White, Chalky	Men's Restroom 01	Assumed	NF	G	3,500	SF	09/16/21
			Women's Restroom 01						
			Men's Restroom 02						
			Women's Restroom 02						
M-GWB-41	M	Gypsum Wallboard, White, Chalky	Men's Restroom 01	Assumed	NF	G	3,500	SF	09/16/21
			Women's Restroom 01						
			Men's Restroom 02						
			Women's Restroom 02						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-JTC-42	S	Joint Compound, White, Chalky	Men's Restroom 01	Assumed	NF	G	350	SF	09/16/21
			Women's Restroom 01						
			Men's Restroom 02						
			Women's Restroom 02						
M-FDI-43	M	Fire Door Insulation, Wood/Metal Cladding	Library	Assumed	NF	G	861	SF	09/16/21
			Room 401						
			Men's Restroom 01						
			Women's Restroom 01						
			South Mountain						
			San Tan Mountain						
			Estrella Mountain						
			Camelback Mountain						
			Squaw Peak						
			Superstition Mountain						
			Cataloguing						
			A/V Storage						
			Staff Lounge						
			Telephone						
			Storage 01						
			Storage 02						
			Storage 03						
			Work Room 1						
			Work Room 2						
			Men's Restroom 02						
			Women's Restroom 02						
			Computer Lab 1						
			Computer Lab 2						
			Conference						
			Receiving						
			Room 404						
			Vestibule						
			Multimedia						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Exterior						
M-PSL-45	M	Pipe Sealant, White, Pliable	Library	Assumed	NF	G	25	SF	09/16/21
			Room 401						
			Men's Restroom 01						
			Women's Restroom 01						
			South Mountain						
			San Tan Mountain						
			Estrella Mountain						
			Camelback Mountain						
			Squaw Peak						
			Superstition Mountain						
			Cataloguing						
			A/V Storage						
			Staff Lounge						
			Telephone						
			Storage 01						
			Storage 02						
			Storage 03						
			Work Room 1						
			Work Room 2						
			Men's Restroom 02						
			Women's Restroom 02						
			Computer Lab 1						
			Computer Lab 2						
			Conference						
			Conference Storage						
			Receiving						
			Room 404						
			Vestibule						
			Multimedia						
			Studio						
M-SAC-46	M	Sink Acoustical Coating, Gray, Rough	Cataloguing	Assumed	NF	G	12	SF	09/16/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Lounge						
			Work Room 1						
			Work Room 2						
			Conference						
			Multimedia						
S·TOT·47	S	Troweled-On Texture, White, Chalky	Storage 01	Assumed	NF	G	85	SF	09/16/21
M·GWB·48	M	Gypsum Wallboard, White, Chalky	Storage 01	Assumed	NF	G	85	SF	09/16/21
S·JTC·49	S	Joint Compound, White, Chalky	Storage 01	Assumed	NF	G	10	SF	09/16/21
M·CON·50	M	Concrete (Foundation), Gray, Cementitious	Library	Assumed	NF	G	25,000	SF	09/16/21
			Room 401						
			Men's Restroom 01						
			Women's Restroom 01						
			South Mountain						
			San Tan Mountain						
			Estrella Mountain						
			Camelback Mountain						
			Squaw Peak						
			Superstition Mountain						
			Cataloguing						
			A/V Storage						
			Staff Lounge						
			Telephone						
			Storage 01						
			Storage 02						
			Storage 03						
			Work Room 1						
			Work Room 2						
			Men's Restroom 02						
			Women's Restroom 02						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Computer Lab 1						
			Computer Lab 2						
			Conference						
			Conference Storage						
			Receiving						
			Room 404						
			Vestibule						
			Multimedia						
			Studio						



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHRA certification number: 4370 1250 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\01.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHRA certification number: 4326 1261 128169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-02, Mastic (Penetrations And Flashings), Black, Tar-Like, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\02.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4370 1261 123124 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BUR-03, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\03.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2

AHERA certification number: 436126012364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-04, Mastic (Penetrations And Flashings), Black, Tar-Like, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\04.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 12601 123 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-SLT-05, Sealant (Flashings), Black, Tar-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\05.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHRA certification number: 4310 12601 123162 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-06, Sealant (Doors, Windows, Walls, Flashings), Tan, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\06.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 1250 128169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-STU-07, Stucco, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\07.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHRA certification number: 4380 12501 12345 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-08, Concrete Masonry Unit, 8"X16", Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\08.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHRA certification number: 4370 10501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-09, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\09.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 12501 123<sup>69</sup> Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-SLT-10, Sealant (Windows, Roof), Black, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\10.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4320 12601 12316A Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-11, Sealant (Roof), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\11.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHRA certification number: 4380125d 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BRK-13, Brick, 4"X16", Red, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\13.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Coby Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
ASHERA certification number: 4380 12501 123164 Signature of Inspector: Coby Hall

\*Material Reinspected: M-CMU-12, Concrete Masonry Unit, 8"X16", Pink, Cementitious, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\12.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4320 12601 1234567 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-16, Concrete (Columns), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\16.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2

AHERA certification number: 4380 12501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-FDI-17, Fire Door Insulation, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\17.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-19, Sealant (Doors, Windows), Black, Gummy

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\19.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbin Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2

AHERA certification number: 4380 12501 12316 Signature of Inspector: Corbin Hall

\*Material Reinspected: M-SAC-39, Sink Acoustical Coating, Gray, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\39.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4370 12821 23161 Signature of Inspector: cmh hall

\*Material Reinspected: M-VST-46, Vinyl Stair Tread, 12"X36", Blue, Vinyl-Like, Circle Pattern

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

#### Assessment:

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

#### Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\46.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4370 1251 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-47, Mastic, White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\47.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHRA certification number: 4380 12501 123167 Signature of Inspector: cmgn hall

\*Material Reinspected: M-VCT-48, Vinyl Composition Tile, 18"X18", Blue, Textured, Circle Pattern

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\48.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 12601 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-49, Mastic, White, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\49.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 1251 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-52, Sealant (Duct), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\52.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/18/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-WDB-53, Woven Duct Boot, 2", Black, Rubber-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\53.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 12501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-PES-54, Pipe End Sealant (Sprinklers), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\54.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 12501 123167 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-56, Glazed Wall Tile, 4"X4", Tan, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\56.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 1281 123161 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-57, Glazed Wall Tile (Pattern), 4"X4", Light Gray, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\57.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHRA certification number: 4380 1251 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-58, Glazed Wall Tile (Pattern), 4"X4", Black, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\58.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 281123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-59, Glazed Wall Tile (Coved), 4"X4", Blue, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\59.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 12501 123167 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-60, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\60.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2

AHERA certification number: 4380 1250 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMT-61, Ceramic Mosaic Tile, 2"X2", Gray, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\61.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHRA certification number: 4340 12501 12269 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-CMT-62, Ceramic Mosaic Tile (Pattern), 2"X2", Gray, Smooth, White Specks

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\62.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carlyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 12501 123169 Signature of Inspector: Carlyn Hall

\*Material Reinspected: M-CMT-63, Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth, Brown Specks

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\63.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4380 1250 123<sup>164</sup> Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-64, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\64.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 2  
AHERA certification number: 4370 1229 123/CA Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-ADH-65, Adhesive (TWP), Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 2\65.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carlyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3

AHERA certification number: 4380 1251 123169 Signature of Inspector: Carlyn Hall

\*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\01.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4310 1250 123164 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-MAS-02, Mastic (Penetrations And Flashings), Black, Tar-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\02.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-03, Sealant (Flashings), Tan, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\03.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3

AHERA certification number: 4376-125169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-04, Sealant (Flashings), Black, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\04.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Caryn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHERA certification number: 4380 1261 123161 Signature of Inspector: Caryn Hall

\*Material Reinspected: M-SLT-10, Sealant (Duct), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc. 3.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\10.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 438012501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-11, Sealant (Roof), Gray, Pliable Associated With Paneling (Metal), Factory Finish

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\11.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380 12nd 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-13, Concrete Masonry Unit (Pattern), 12"X12", Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\13.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4390 12551 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-17, Concrete (Walls), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\17.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHERA certification number: 4370-12521-123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-21, Sealant (Fire Stop), Red, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc. 3.

**Material Status:** 1. In-Place ✓ 2. Did Not Find ✓

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\21.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380 12501 12368 Signature of Inspector: Cornelia Heile

\*Material Reinspected: M-SLT-22, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\22.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380 12501 03169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-SAT-28, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\28.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWB-29, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\29.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380-1281 <sup>123164</sup> Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-30, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\30.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4320 12501 123167 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VCT-32, Vinyl Composition Tile (Pattern), 12"X12", White, Smooth, Brown Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc. 3

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\32.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380 1289 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VCT-33, Vinyl Composition Tile (Pattern), 12"X12", Light Blue, Smooth, Blue Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\33.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHERA certification number: 4370 12501 123169 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-FDI-34, Fire Door Insulation, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\34.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380 12601 1231601 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-35, Glazed Wall Tile, 4"X4", Tan, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\35.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: Building 3  
AHRA certification number: 4380-12001-123167 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-GWT-36, Glazed Wall Tile (Pattern), 4"X4", Light Gray, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\36.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380 1201 1231 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-37, Glazed Wall Tile (Pattern), 4"X4", Black, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\37.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Certyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 43801251 123164 Signature of Inspector: Certyn Hall

\*Material Reinspected: M-GWT-38, Glazed Wall Tile (Coved), 4"X4", Blue, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\38.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHERA certification number: 4380 1251 03164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-39, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\39.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380 12501 <sup>123164</sup> Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMT-40, Ceramic Mosaic Tile, 2"X2", Gray, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\40.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380 12501 123169 Signature of Inspector: 80 Corbyn Hall

\*Material Reinspected: M-CMT-41, Ceramic Mosaic Tile (Pattern), 2"X2", Gray, Smooth, White Specks

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\41.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4370 12501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMT-42, Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth, Brown Specks

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\42.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380 12501 123164 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-GRT-43, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\43.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carson Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHERA certification number: 43701251123164 Signature of Inspector: Carson Hall

\*Material Reinspected: S-SAT-44, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** ① Surf.    2. TSI    3. Misc.

**Material Status:**    1. In-Place ✓    2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection?    Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection?    Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material:    High ✓    Medium \_\_\_\_\_    Low \_\_\_\_\_  
Degree of Activity Near the Material:    High ✓    Medium \_\_\_\_\_    Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\44.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Cortyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHRA certification number: 4380 12801 123169 Signature of Inspector: Cortyn Hall

\*Material Reinspected: M-GWB-45, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\45.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hull  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHERA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hull  
\*Material Reinspected: S-JTC-46, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ☒ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium ☒ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\46.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3

AHERA certification number: 43801250173169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-QPT-47, Quarry/Paver Tile, 12"X12", Gray, Smooth, Multi-Colored Specks

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\47.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3

AHERA certification number: 438128112369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-48, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\48.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Candyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3

AHERA certification number: 4380 12501 12316 Signature of Inspector: Candyn Hall

\*Material Reinspected: M-GWT-49, Glazed Wall Tile (Pattern), 4"X6", Gray, Smooth, Multi-Colored Specks

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

#### Assessment:

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

#### Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\49.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3

AHERA certification number: 432012501123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-50, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\50.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Cordyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3

AHERA certification number: 4380 12561 123169 Signature of Inspector: Cordyn Hall

\*Material Reinspected: M-VST-52, Vinyl Stair Tread, 12"X48", Blue, Vinyl-Like, Circle Pattern

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\52.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHERA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-53, Mastic, Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\53.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3

AHERA certification number: 4380 12501 12316 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-ADH-58, Adhesive (FRP), Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☐ Medium ☒ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\58.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHERA certification number: 4380 1209 123164 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-SAC-59, Sink Acoustical Coating, Gray, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\59.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3

AHERA certification number: 4370 1250 12364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-WAB-60, Wallbase (Coved), 4", Black, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\60.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3

AHERA certification number: 4380 12501 12469 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-ADH-61, Adhesive, Cream, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\61.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHERA certification number: 4870 12601 <sup>123169</sup> Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-PES-62, Pipe End Sealant (Sprinklers), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\62.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 3  
AHERA certification number: 4380 12601 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-83, Sealant (Mechanical), Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 3\83.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4  
AHERA certification number: 4370 12601 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\01.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4370 12501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-02, Mastic (Penetrations And Flashings), Black, Tar-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\02.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4  
AHERA certification number: 4380 12501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-03, Sealant (Flashings), Black, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\03.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4  
AHERA certification number: 43801251123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-04, Sealant (Flashings), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\04.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4380 12501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-05, Sealant (Flashings), Tan, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\05.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4  
AHERA certification number: 4370 12501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-06, Sealant (Sky Light), Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\06.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4  
AHERA certification number: 4320 12501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-07, Concrete Masonry Unit, 8"X16", Gray, Cementitious, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\07.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4  
AHERA certification number: 4380 12501 125164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-08, Concrete Masonry Unit, 8"X16", Gray, Cementitious, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\08.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4  
AHERA certification number: 4370 12501 0369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-09, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Frms\Bldg 4\09.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4370 1250 12316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-10, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place \_\_\_\_\_ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

#### Assessment:

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

#### Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\10.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 437012521123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-EXJ-11, Expansion Joint, Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place \_\_\_\_\_ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\11.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4370 DSD 12369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-12, Sealant (Doors, Windows, Fixtures), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\12.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 438012801 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-STU-13, Stucco, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\13.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4300 12501 122169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-14, Concrete (Entries), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\14.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Cordyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4388 1268 12304 Signature of Inspector: Cordyn Hall

\*Material Reinspected: M-MRT-15, Mortar (Glass Block), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\15.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4316 1201 12369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-16, Concrete (Columns), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Frms\Bldg 4\16.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4380120112364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-17, Sealant (Windows), Black, Tar-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\17.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 43701251 0316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-EXJ-18, Expansion Joint (Entries), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\18.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4306 12501123K9 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-APL-19, Acoustical Ceiling Panel, 2'x2', Gray, Pinholes and Fissures, White

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\19.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4  
AHERA certification number: 4380 12501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-ACT-20, Acoustical Ceiling Tile, 1'x1', Gray, Pinholes And Fissures, White

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\20.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/14/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 43612512314 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-ADH-21, Adhesive, Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\21.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 486126112364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-SAT-23, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\23.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 43701200112364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWB-24, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**  
Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\24.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4386 1281 123161 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-25, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\25.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 43702012222 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWB-26, Gypsum Wallboard, White, Chalky, Vinyl Cover

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\26.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 43801260123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-27, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\27.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4  
AHERA certification number: 4380 12061 12169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-TWP-28, Tackable Wall Panel, Brown, Fibrous, Vinyl Cover

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc. 3

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\28.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4380 12671 12344 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-29, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\29.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carlynn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 43701250112316 Signature of Inspector: Carlynn Hall

\*Material Reinspected: M-QPT-34, Quarry/Paver Tile, 12"X12", Gray, Smooth, Peppered

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\34.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/24 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4301250122861 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-35, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\35.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4370-12011236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VCT-36, Vinyl Composition Tile, 12"X12", Tan, Smooth, Brown Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\36.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4370126212364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VCT-37, Vinyl Composition Tile (Pattern), 12"X12", White, Smooth, Gray Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\37.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4380 1254 1254 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VCT-38, Vinyl Composition Tile (Pattern), 12"X12", Blue, Smooth, Dark Blue Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\38.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hale  
Facility: Kyrene Altadena Middle School Building Name/Number: 4  
AHERA certification number: 43012012014 Signature of Inspector: Corbyn Hale

\*Material Reinspected: M-MAS-39, Mastic, Yellow, Tacky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\39.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4380 12501 12314 Signature of Inspector: Carbyn Hall

\*Material Reinspected: S-SAT-40, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\40.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 43012611234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWB-41, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place 1 2. Did Not Find 2

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High 1 Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High 1 Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\41.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carlyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4382 1281 0365 Signature of Inspector: Carlyn Hall

\*Material Reinspected: S-JTC-42, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\42.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Healy  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 438012501234 Signature of Inspector: Corbyn Healy

\*Material Reinspected: M-FDI-43, Fire Door Insulation, Wood/Metal Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\43.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/24 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4380 12601 12364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-PSL-45, Pipe Sealant, White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\45.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carlyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4380 12501 12316 Signature of Inspector: Craig Reall

\*Material Reinspected: M-SAC-46, Sink Acoustical Coating, Gray, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\46.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4370126123124 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-TOT-47, Troweled-On Texture, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\47.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/10/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4  
AHRA certification number: 4386 12501 123161 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWB-48, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? Yes No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? Yes No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\48.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hagg  
Facility: Kyrene Altadena Middle School Building Name/Number: 4  
AHRA certification number: 438012601 123164 Signature of Inspector: Corbyn Hagg

\*Material Reinspected: S-JTC-49, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc. 3

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

#### Assessment:

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

#### Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\49.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Altadena Middle School Building Name/Number: 4

AHERA certification number: 4370 12501 12314 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-CON-50, Concrete (Foundation), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Altadena\Forms\Bldg 4\50.doc