

November 2, 2021

Mr. Mike Williams  
Facilities Supervisor  
Kyrene School District No. 28  
8700 South Kyrene Road  
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection  
Asbestos-Containing Building Materials  
Kyrene Aprende Middle School  
777 North Desert Breeze Boulevard – East #2, Chandler  
FM Project 21-343**

Dear Mr. Musella:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

**Items of significance are: None.**

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

**FM GROUP INC**



Michael Hall  
Environmental Division Manager

*Attachments: 3-Year Reinspection Tables  
3-Year Reinspection Forms*

*G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Cvr Ltr.doc*

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap, Silver	Roof	Assumed	NF	G	105,000	SF	09/30/21
M-MAS-02	M	Mastic (Penetrations And Flashings), Black, Tar-Like, Silver	Roof	Assumed	NF	G	1,500	SF	09/30/21
M-SLT-03	M	Sealant (Flashings), Gray, Pliable	Roof	Assumed	NF	G	20	SF	09/30/21
M-SLT-04	M	Sealant (Flashings), Black, Gummy	Roof	Assumed	NF	G	30	SF	09/30/21
M-SLT-05	M	Sealant (Flashings), Tan, Pliable	Roof	Assumed	NF	G	100	SF	09/30/21
M-SLT-06	M	Sealant (Windows), White, Brittle	Roof	Assumed	NF	G	36	SF	09/30/21
M-CMU-07	M	Concrete Masonry Unit, 8"X16", Pink, Cementitious, Rough	Exterior	Assumed	NF	G	10,000	SF	09/30/21
M-CMU-08	M	Concrete Masonry Unit, 4"X16", Pink, Cementitious, Rough	Exterior	Assumed	NF	G	3,000	SF	09/30/21
M-CMU-09	M	Concrete Masonry Unit, 8"X16", Pink, Cementitious	Exterior	Assumed	NF	G	17,000	SF	09/30/21
M-CMU-10	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	Exterior	Assumed	NF	G	1,000	SF	09/30/21
M-MRT-11	M	Mortar, Gray, Cementitious	Exterior	Assumed	NF	G	3,000	SF	09/30/21
S-STU-12	M	Stucco, Gray, Cementitious	Exterior	Assumed	NF	G	6,000	SF	09/30/21
M-CON-16	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	5,000	SF	09/30/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CON-17	M	Concrete (Foundation), Gray, Cementitious	Secretary/Reception	Assumed	NF	G	105,000	SF	09/30/21
			Office 1						
			Office 2						
			Office 3						
			Office 4						
			Student Services						
			Staff Women's Restroom						
			Electrical 4						
			Office 5						
			Office 6						
			Conference Room						
			Office 7						
			Office 8						
			Staff Men's Restroom						
			Break						
			Nurse Restroom						
			Test						
			Cots						
			Cots Closet						
			Treatment						
			Principal						
			Wait						
			Nurse's Office						
			Classroom 100						
			Classroom 101						
			Classroom 102						
			Classroom 103						
			Classroom 104						
			Classroom 105						
			Classroom 106						
			Science Classroom 107						
			Storage 09						
			Staff Lounge 04						
			Science Classroom 108						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 109						
			Classroom 110						
			Classroom 111						
			Boy's Restroom 5						
			Storage 07						
			Storage 08						
			Lobby 04						
			Classroom 112						
			Classroom 113						
			Classroom 114						
			Classroom 115						
			Lobby 05						
			Computer Classroom 116						
			Special Ed 117						
			Special Ed 118						
			Staff Women's Restroom 4						
			Janitor 3						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						
			Electrical 3						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Classroom 200						
			Classroom 201						
			Classroom 202						
			Classroom 203						
			Girl's Restroom 5						
			Classroom 204						
			Classroom 205						
			Classroom 206						
			Science Classroom 207						
			Storage 06						
			Staff Lounge 03						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 05						
			Science Classroom 208						
			Classroom 209						
			Classroom 210						
			Classroom 211						
			Storage 04						
			Staff Women's Restroom 2						
			Staff Lounge 02						
			Staff Men's Restroom 2						
			Storage 03						
			Storage 02						
			Lobby 02						
			Classroom 212						
			Classroom 213						
			Classroom 214						
			Classroom 215						
			Lobby 03						
			Computer Classroom 216						
			Special Ed 217						
			Special Ed 218						
			Staff Men's Restroom 3						
			Janitor 2						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Staff Women's Restroom 3						
			Electrical 2						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Classroom 300						
			Classroom 301						
			Classroom 302						
			Classroom 303						
			Classroom 304						
			Classroom 305						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 306						
			Science Classroom 307						
			Storage 01						
			Staff Lounge 01						
			Science Classroom 308						
			Classroom 309						
			Classroom 310						
			Classroom 311						
			Classroom 312						
			Classroom 313						
			Classroom 314						
			Classroom 315						
			Lobby 01						
			Computer Classroom 316						
			Special Ed 317						
			Special Ed 318						
			Staff Women's Restroom 1						
			Janitor 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						
			Electrical 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Corridor 01						
			Corridor 02						
			Corridor 03						
			Corridor 04						
			Corridor 05						
			Corridor 06						
			Corridor 07						
			Corridor 08						
			Corridor 09						
			Corridor 10						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 11						
			Corridor 12						
			Corridor 13						
			Corridor 14						
			Corridor 15						
			Corridor 16						
			Corridor 17						
			Corridor 18						
			Corridor 19						
			Corridor 20						
			Exterior						
M-CON-18	M	Concrete (Columns), Gray, Cementitious	Exterior	Assumed	NF	G	400	SF	09/30/21
M-MRT-20	M	Mortar (Glass Block), White, Cementitious	Secretary/Reception	Assumed	NF	G	50	SF	09/30/21
			Lobby 02						
			Corridor 03						
			Corridor 06						
			Corridor 17						
			Exterior						
M-FDI-31	M	Fire Door Insulation, Metal/Wood Cladding	Secretary/Reception	Assumed	NF	G	3,087	SF	09/30/21
			Office 1						
			Office 2						
			Student Services						
			Electrical 4						
			Conference Room						
			Break						
			Principal						
			Wait						
			Classroom 100						
			Classroom 101						
			Classroom 102						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 103						
			Classroom 104						
			Classroom 106						
			Science Classroom 107						
			Staff Lounge 04						
			Science Classroom 108						
			Classroom 109						
			Classroom 110						
			Classroom 111						
			Boy's Restroom 5						
			Storage 07						
			Lobby 04						
			Classroom 112						
			Classroom 113						
			Classroom 114						
			Classroom 115						
			Computer Classroom 116						
			Special Ed 117						
			Special Ed 118						
			Staff Women's Restroom 4						
			Janitor 3						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						
			Electrical 3						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Classroom 200						
			Classroom 201						
			Classroom 202						
			Classroom 203						
			Girl's Restroom 5						
			Classroom 204						
			Classroom 205						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 206						
			Science Classroom 207						
			Staff Lounge 03						
			Science Classroom 208						
			Classroom 209						
			Classroom 210						
			Storage 04						
			Staff Women's Restroom 2						
			Staff Lounge 02						
			Staff Men's Restroom 2						
			Lobby 02						
			Classroom 211						
			Classroom 212						
			Classroom 213						
			Classroom 214						
			Classroom 215						
			Computer Classroom 216						
			Special Ed 217						
			Special Ed 218						
			Staff Men's Restroom 3						
			Janitor 2						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Staff Women's Restroom 3						
			Electrical 2						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Classroom 300						
			Classroom 301						
			Classroom 302						
			Classroom 303						
			Classroom 304						
			Classroom 305						
			Classroom 306						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Science Classroom 307						
			Staff Lounge 01						
			Science Classroom 308						
			Classroom 309						
			Classroom 311						
			Classroom 312						
			Classroom 313						
			Classroom 314						
			Classroom 315						
			Computer Classroom 316						
			Special Ed 317						
			Special Ed 318						
			Staff Women's Restroom 1						
			Janitor 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						
			Electrical 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Corridor 01						
			Corridor 02						
			Corridor 03						
			Corridor 04						
			Corridor 05						
			Corridor 06						
			Corridor 07						
			Corridor 08						
			Corridor 09						
			Corridor 10						
			Corridor 11						
			Corridor 12						
			Corridor 13						
			Corridor 14						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 15						
			Corridor 16						
			Corridor 17						
			Corridor 18						
			Corridor 19						
			Corridor 20						
M-SAC-32	M	Sink Acoustical Coating, Gray, Rough	Break	Assumed	NF	G	108	SF	09/30/21
			Cots						
			Treatment						
			Classroom 100						
			Classroom 101						
			Classroom 102						
			Classroom 103						
			Classroom 104						
			Classroom 105						
			Classroom 106						
			Staff Lounge 04						
			Classroom 109						
			Classroom 110						
			Classroom 111						
			Classroom 112						
			Classroom 113						
			Classroom 114						
			Classroom 115						
			Special Ed 117						
			Special Ed 118						
			Classroom 200						
			Classroom 201						
			Classroom 202						
			Classroom 203						
			Classroom 204						
			Classroom 205						
			Classroom 206						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Lounge 03						
			Classroom 209						
			Classroom 210						
			Classroom 211						
			Classroom 212						
			Classroom 213						
			Classroom 214						
			Classroom 215						
			Classroom 217						
			Classroom 218						
			Classroom 300						
			Classroom 301						
			Classroom 302						
			Classroom 303						
			Classroom 304						
			Classroom 305						
			Classroom 306						
			Staff Lounge 01						
			Classroom 309						
			Classroom 310						
			Classroom 311						
			Classroom 312						
			Classroom 313						
			Classroom 314						
			Classroom 315						
M-SLT-33	M	Sealant (Duct), Light Gray, Pliable	Secretary/Reception	Assumed	NF	G	1,000	SF	09/30/21
			Office 1						
			Office 2						
			Office 3						
			Office 4						
			Student Services						
			Staff Women's Restroom						
			Electrical 4						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Office 5						
			Office 6						
			Conference Room						
			Office 7						
			Office 8						
			Staff Men's Restroom						
			Break						
			Nurse Restroom						
			Test						
			Cots						
			Cots Closet						
			Treatment						
			Principal						
			Wait						
			Nurse's Office						
			Classroom 100						
			Classroom 101						
			Classroom 102						
			Classroom 103						
			Classroom 104						
			Classroom 105						
			Classroom 106						
			Science Classroom 107						
			Storage 09						
			Staff Lounge 04						
			Science Classroom 108						
			Classroom 109						
			Classroom 110						
			Classroom 111						
			Boy's Restroom 5						
			Storage 07						
			Storage 08						
			Lobby 04						
			Classroom 112						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 113						
			Classroom 114						
			Classroom 115						
			Lobby 05						
			Computer Classroom 116						
			Special Ed 117						
			Special Ed 118						
			Staff Women's Restroom 4						
			Janitor 3						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						
			Electrical 3						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Classroom 200						
			Classroom 201						
			Classroom 202						
			Classroom 203						
			Girl's Restroom 5						
			Classroom 204						
			Classroom 205						
			Classroom 206						
			Science Classroom 207						
			Storage 06						
			Staff Lounge 03						
			Storage 05						
			Science Classroom 208						
			Classroom 209						
			Classroom 210						
			Storage 04						
			Staff Women's Restroom 2						
			Staff Lounge 02						
			Staff Men's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 03						
			Storage 02						
			Lobby 02						
			Classroom 211						
			Classroom 212						
			Classroom 213						
			Classroom 214						
			Classroom 215						
			Lobby 03						
			Computer Classroom 216						
			Special Ed 217						
			Special Ed 218						
			Staff Men's Restroom 3						
			Janitor 2						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Staff Women's Restroom 3						
			Electrical 2						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Classroom 300						
			Classroom 301						
			Classroom 302						
			Classroom 303						
			Classroom 304						
			Classroom 305						
			Classroom 306						
			Science Classroom 307						
			Storage 01						
			Staff Lounge 01						
			Science Classroom 308						
			Classroom 309						
			Classroom 310						
			Classroom 311						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 312						
			Classroom 313						
			Classroom 314						
			Classroom 315						
			Lobby 01						
			Computer Classroom 316						
			Special Ed 317						
			Special Ed 318						
			Staff Women's Restroom 1						
			Janitor 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						
			Electrical 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Corridor 01						
			Corridor 02						
			Corridor 03						
			Corridor 04						
			Corridor 05						
			Corridor 06						
			Corridor 07						
			Corridor 08						
			Corridor 09						
			Corridor 10						
			Corridor 11						
			Corridor 12						
			Corridor 13						
			Corridor 14						
			Corridor 15						
			Corridor 16						
			Corridor 17						
			Corridor 18						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 19						
			Corridor 20						
S-SAT-35	S	Spray-Applied Texture, White, Chalky	Staff Women's Restroom	Assumed	NF	G	20,000	SF	09/30/21
			Staff Men's Restroom						
			Nurse's Restroom						
			Staff Women's Restroom 4						
			Janitor 3						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Staff Women's Restroom 2						
			Staff Men's Restroom 2						
			Staff Men's Restroom 3						
			Janitor 2						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Staff Women's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Staff Women's Restroom 1						
			Janitor 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
M-GWB-36	M	Gypsum Wallboard, White, Chalky	Staff Women's Restroom	Assumed	NF	G	20,000	SF	09/30/21
			Staff Men's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Nurse's Restroom						
			Staff Women's Restroom 4						
			Janitor 3						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Staff Women's Restroom 2						
			Staff Men's Restroom 2						
			Staff Men's Restroom 3						
			Janitor 2						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Staff Women's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Staff Women's Restroom 1						
			Janitor 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
S-JTC-37	S	Joint Compound, White, Chalky	Staff Women's Restroom	Assumed	NF	G	2,000	SF	09/30/21
			Staff Men's Restroom						
			Nurse's Restroom						
			Staff Women's Restroom 4						
			Janitor 3						
			Girl's Restroom 7						
			Boy's Restroom 7						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Men's Restroom 4						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Staff Women's Restroom 2						
			Staff Men's Restroom 2						
			Staff Men's Restroom 3						
			Janitor 2						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Staff Women's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Staff Women's Restroom 1						
			Janitor 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
M-GWT-38	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Staff Women's Restroom	Assumed	NF	G	20,000	SF	09/30/21
			Staff Men's Restroom						
			Nurse's Restroom						
			Staff Women's Restroom 4						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Staff Women's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Men's Restroom 2						
			Staff Men's Restroom 3						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Staff Women's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Staff Women's Restroom 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
M-GRT-39	M	Grout, Gray, Cementitious	Staff Women's Restroom	Assumed	NF	G	2,000	SF	09/30/21
			Staff Men's Restroom						
			Nurse's Restroom						
			Staff Women's Restroom 4						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Staff Women's Restroom 2						
			Staff Men's Restroom 2						
			Staff Men's Restroom 3						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Staff Women's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Staff Women's Restroom 1						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
M-CMT-40	M	Ceramic Mosaic Tile, 2"X2", Gray, Smooth, Multi-Colored Spots	Staff Women's Restroom	Assumed	NF	G	7,000	SF	09/30/21
			Staff Men's Restroom						
			Nurse's Restroom						
			Staff Women's Restroom 4						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Staff Women's Restroom 2						
			Staff Men's Restroom 2						
			Staff Men's Restroom 3						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Staff Women's Restroom 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
M-GRT-41	M	Grout, Gray, Cementitious	Staff Women's Restroom	Assumed	NF	G	700	SF	09/30/21
			Staff Men's Restroom						
			Nurse's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Women's Restroom 4						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Staff Women's Restroom 2						
			Staff Men's Restroom 2						
			Staff Men's Restroom 3						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Staff Women's Restroom 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
M-WAB-45	M	Wallbase (Coved), 4", Gray, Vinyl-Like	Electrical 3	Assumed	NF	G	100	SF	09/30/21
			Electrical 2						
			Electrical 1						
			Corridor 08						
			Corridor 09						
M-ADH-46	M	Adhesive, Cream, Pliable	Electrical 3	Assumed	NF	G	100	SF	09/30/21
			Electrical 2						
			Electrical 1						
			Corridor 08						
			Corridor 09						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-QPT-47	M	Quarry/Paver Tile, 12"X12", Gray, Smooth, Multi-Colored Spots	Janitor 3	Assumed	NF	G	400	SF	09/30/21
			Janitor 1						
M-GRT-48	M	Grout, Gray, Cementitious	Janitor 3	Assumed	NF	G	40	SF	09/30/21
			Janitor 1						
M-TWP-53	M	Tackable Wall Panel (Moveable), Brown, Fibrous, Vinyl Cover	Special Ed 117	Assumed	NF	G	1,000	SF	09/30/21
			Special Ed 118						
			Special Ed 217						
			Special Ed 218						
			Special Ed 317						
			Special Ed 318						
M-SLT-54	M	Sealant (Duct), Dark Gray, Pliable	Secretary/Reception	Assumed	NF	G	1,000	SF	09/30/21
			Office 1						
			Office 2						
			Office 3						
			Office 4						
			Student Services						
			Staff Women's Restroom						
			Electrical 4						
			Office 5						
			Office 6						
			Conference Room						
			Office 7						
			Office 8						
			Staff Men's Restroom						
			Break						
			Nurse Restroom						
			Test						
			Cots						
			Cots Closet						
			Treatment						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Principal						
			Wait						
			Nurse's Office						
			Classroom 100						
			Classroom 101						
			Classroom 102						
			Classroom 103						
			Classroom 104						
			Classroom 105						
			Classroom 106						
			Science Classroom 107						
			Storage 09						
			Staff Lounge 04						
			Science Classroom 108						
			Classroom 109						
			Classroom 110						
			Classroom 111						
			Boy's Restroom 5						
			Storage 07						
			Storage 08						
			Lobby 04						
			Classroom 112						
			Classroom 113						
			Classroom 114						
			Classroom 115						
			Lobby 05						
			Computer Classroom 116						
			Special Ed 117						
			Special Ed 118						
			Staff Women's Restroom 4						
			Janitor 3						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Electrical 3						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Classroom 200						
			Classroom 201						
			Classroom 202						
			Classroom 203						
			Girl's Restroom 5						
			Classroom 204						
			Classroom 205						
			Classroom 206						
			Science Classroom 207						
			Storage 06						
			Staff Lounge 03						
			Storage 05						
			Science Classroom 208						
			Classroom 209						
			Classroom 210						
			Storage 04						
			Staff Women's Restroom 2						
			Staff Lounge 02						
			Staff Men's Restroom 2						
			Storage 03						
			Storage 02						
			Lobby 02						
			Classroom 211						
			Classroom 212						
			Classroom 213						
			Classroom 214						
			Classroom 215						
			Lobby 03						
			Computer Classroom 216						
			Special Ed 217						
			Special Ed 218						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Men's Restroom 3						
			Janitor 2						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Staff Women's Restroom 3						
			Electrical 2						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Classroom 300						
			Classroom 301						
			Classroom 302						
			Classroom 303						
			Classroom 304						
			Classroom 305						
			Classroom 306						
			Science Classroom 307						
			Storage 01						
			Staff Lounge 01						
			Science Classroom 308						
			Classroom 309						
			Classroom 310						
			Classroom 311						
			Classroom 312						
			Classroom 313						
			Classroom 314						
			Classroom 315						
			Lobby 01						
			Computer Classroom 316						
			Special Ed 317						
			Special Ed 318						
			Staff Women's Restroom 1						
			Janitor 1						
			Girl's Restroom 2						
			Boy's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Men's Restroom 1						
			Electrical 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Corridor 01						
			Corridor 02						
			Corridor 03						
			Corridor 04						
			Corridor 05						
			Corridor 06						
			Corridor 07						
			Corridor 08						
			Corridor 09						
			Corridor 10						
			Corridor 11						
			Corridor 12						
			Corridor 13						
			Corridor 14						
			Corridor 15						
			Corridor 16						
			Corridor 17						
			Corridor 18						
			Corridor 19						
			Corridor 20						
M-GWT-55	M	Glazed Wall Tile (Pattern), 4"X4", Gray, Smooth	Staff Women's Restroom	Assumed	NF	G	1,000	SF	09/30/21
			Staff Men's Restroom						
			Nurse's Restroom						
			Staff Women's Restroom 4						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						
			Girl's Restroom 6						
			Boy's Restroom 6						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 5						
			Girl's Restroom 5						
			Staff Women's Restroom 2						
			Staff Men's Restroom 2						
			Staff Men's Restroom 3						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Staff Women's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Staff Women's Restroom 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
M-GWT-56	M	Glazed Wall Tile (Pattern), 4"X4", Black, Smooth	Staff Women's Restroom	Assumed	NF	G	1,000	SF	09/30/21
			Staff Men's Restroom						
			Nurse's Restroom						
			Staff Women's Restroom 4						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Staff Women's Restroom 2						
			Staff Men's Restroom 2						
			Staff Men's Restroom 3						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Staff Women's Restroom 3						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 3						
			Boy's Restroom 3						
			Staff Women's Restroom 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
M-GWT-57	M	Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth	Staff Women's Restroom	Assumed	NF	G	1,000	SF	09/30/21
			Staff Men's Restroom						
			Nurse's Restroom						
			Staff Women's Restroom 4						
			Girl's Restroom 7						
			Boy's Restroom 7						
			Staff Men's Restroom 4						
			Girl's Restroom 6						
			Boy's Restroom 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Staff Women's Restroom 2						
			Staff Men's Restroom 2						
			Staff Men's Restroom 3						
			Girl's Restroom 4						
			Boy's Restroom 4						
			Staff Women's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Staff Women's Restroom 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Staff Men's Restroom 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 1						
			Boy's Restroom 1						

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\AprendeMain-Tbl.doc

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	46,000	SF	09/30/21
M-MAS-02	M	Mastic (Penetrations And Flashing), Black, Tar-Like, Silver	Roof	Assumed	NF	G	1,000	SF	09/30/21
M-SLT-03	M	Sealant (Flashings), Gray, Pliable	Roof	Assumed	NF	G	250	SF	09/30/21
M-SLT-04	M	Sealant (Doors, Windows, Flashings), White, Pliable	Child Dev Service Yard	Assumed	NF	G	300	SF	09/30/21
			Tech Service Yard						
			Exterior Storage						
			Art Storage 01						
			Art Service Yard						
			Exterior						
			Roof						
M-CMU-05	M	Concrete Masonry Unit, 8"X16", Pink, Cementitious, Rough	Child Dev Service Yard	Assumed	NF	G	25,000	SF	09/30/21
			Tech Service Yard						
			Exterior Storage						
			Art Storage 01						
			Art Service Yard						
			Exterior						
			Roof						
M-CMU-06	M	Concrete Masonry Unit, 4"X16", Pink, Cementitious, Rough	Child Dev Service Yard	Assumed	NF	G	1,000	SF	09/30/21
			Tech Service Yard						
			Exterior Storage						
			Art Storage 01						
			Art Service Yard						
			Exterior						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Roof						
M-CMU-07	M	Concrete Masonry Unit, 8"X16", Pink, Cementitious	Child Dev Service Yard	Assumed	NF	G	1,000	SF	09/30/21
			Tech Service Yard						
			Exterior Storage						
			Art Storage 01						
			Art Service Yard						
			Exterior						
			Roof						
M-MRT-08	M	Mortar, Gray, Cementitious	Child Dev Service Yard	Assumed	NF	G	2,600	SF	09/30/21
			Tech Service Yard						
			Exterior Storage						
			Art Storage 01						
			Art Service Yard						
			Exterior						
			Roof						
M-CON-09	M	Concrete (Entries), Gray, Cementitious	Child Dev Service Yard	Assumed	NF	G	6,000	SF	09/30/21
			Tech Service Yard						
			Exterior Storage						
			Art Storage 01						
			Art Service Yard						
			Exterior						
M-CON-10	M	Concrete (Foundation), Gray, Cementitious	Library	Assumed	NF	G	43,000	SF	09/30/21
			Break Out 01						
			Break Out 02						
			Library Storage 02						
			Men's Restroom						
			Women's Restroom						
			Break Out 03						
			Break Out 04						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Break Out 05						
			Break Out 06						
			Work Room						
			Library Storage 01						
			Staff Lounge						
			N.W. Storage						
			Electrical 2						
			Work Room 426						
			T.O.						
			Unisex Restroom						
			Staff Restroom						
			426 Storage						
			Library Storage 03						
			Multi Media						
			Receiving Storage						
			Receiving						
			Conference						
			Cadd Classroom						
			Food Child Dev Lab						
			Food Storage						
			Cart Storage						
			H.E. Restroom						
			W/D						
			Room 429						
			429 Storage						
			Dark Room						
			424 Art						
			Art Storage 03						
			Electrical 1						
			Art Storage 02						
			Corridor 01						
			Corridor 02						
			Exterior						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CON-11	M	Concrete (Columns), Gray, Cementitious	Exterior	Assumed	NF	G	500	SF	09/30/21
S-STU-12	S	Stucco, Gray, Cementitious	Exterior	Assumed	NF	G	4,400	SF	09/30/21
M-FDI-13	M	Fire Door Insulation, Metal/Wood Cladding	Library	Assumed	NF	G	1,029	SF	09/30/21
			Men's Restroom						
			Women's Restroom						
			Break Out 03						
			Staff Lounge						
			N.W. Storage						
			Electrical 2						
			Work Room 426						
			Unisex Restroom						
			Staff Restroom						
			426 Storage						
			Receiving Storage						
			Receiving						
			Conference						
			Cadd Classroom						
			Food Child Dev Lab						
			Child Dev Service Yard						
			H.E. Restroom						
			Room 429						
			Tech Service Yard						
			Exterior Storage						
			429 Storage						
			424 Art						
			Art Storage 01						
			Art Service Yard						
			Corridor 01						
			Corridor 02						
M-MRT-14	M	Mortar (Glass Block), White, Cementitious	Library	Assumed	NF	G	50	SF	09/30/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 01						
			Exterior						
S-SAT-29	S	Spray-Applied Texture, White, Chalky	Men's Restroom	Assumed	NF	G	3,000	SF	09/30/21
			Women's Restroom						
			Unisex Restroom						
			Staff Restroom						
			H.E. Restroom						
			W/D						
M-GWB-30	M	Gypsum Wallboard, White, Chalky	Men's Restroom	Assumed	NF	G	3,000	SF	09/30/21
			Women's Restroom						
			Unisex Restroom						
			Staff Restroom						
			H.E. Restroom						
			W/D						
S-JTC-31	S	Joint Compound, White, Chalky	Men's Restroom	Assumed	NF	G	300	SF	09/30/21
			Women's Restroom						
			Unisex Restroom						
			Staff Restroom						
			H.E. Restroom						
			W/D						
M-SAC-32	M	Sink Acoustical Coating, Gray, Rough	Staff Lounge	Assumed	NF	G	18	SF	09/30/21
			Work Room 426						
			Multi Media						
			Receiving						
			Conference						
			424 Art						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-WDB-33	M	Woven Duct Boot, 2", Black, Rubber-Like	Library	Assumed	NF	G	100	SF	09/30/21
			Break Out 01						
			Break Out 02						
			Library Storage 02						
			Men's Restroom						
			Women's Restroom						
			Break Out 03						
			Break Out 04						
			Break Out 05						
			Break Out 06						
			Work Room						
			Library Storage 01						
			Staff Lounge						
			N.W. Storage						
			Electrical 2						
			Work Room 426						
			T.O.						
			Unisex Restroom						
			Staff Restroom						
			426 Storage						
			Library Storage 03						
			Multi Media						
			Receiving Storage						
			Receiving						
			Conference						
			Cadd Classroom						
			Food Child Dev Lab						
			Food Storage						
			Cart Storage						
			H.E. Restroom						
			W/D						
			Room 429						
			429 Storage						
			Dark Room						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			424 Art						
			Art Storage 03						
			Electrical 1						
			Art Storage 02						
			Corridor 01						
			Corridor 02						
M-GWT-35	M	Glazed Wall Tile, 4"x4", Tan, Smooth	Men's Restroom	Assumed	NF	G	3,000	SF	09/30/21
			Women's Restroom						
			Unisex Restroom						
			Staff Restroom						
			H.E. Restroom						
M-GRT-36	M	Grout, Gray, Cementitious	Men's Restroom	Assumed	NF	G	300	SF	09/30/21
			Women's Restroom						
			Unisex Restroom						
			Staff Restroom						
			H.E. Restroom						
M-CMT-37	M	Ceramic Mosaic Tile, 2"x2", Gray, Smooth, Multi-Colored Spots	Men's Restroom	Assumed	NF	G	1,600	SF	09/30/21
			Women's Restroom						
			Unisex Restroom						
			Staff Restroom						
			H.E. Restroom						
M-GRT-38	M	Grout, Gray, Cementitious	Men's Restroom	Assumed	NF	G	160	SF	09/30/21
			Women's Restroom						
			Unisex Restroom						
			Staff Restroom						
			H.E. Restroom						
M-APL-39	M	Acoustical Ceiling Panel, 2'x2', Yellow, Fibrous Glass, Cloth Cover	Library	Assumed	NF	G	3,600	SF	09/30/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-TWP-40	M	Tackable Wall Panel, White, Chalky, Vinyl Cover	Break Out 03	Assumed	NF	G	300	SF	09/30/21
			Break Out 04						
M-SLT-41	M	Sealant (Duct), Gray, Pliable	Library	Assumed	NF	G	150	SF	09/30/21
			Break Out 01						
			Break Out 02						
			Library Storage 02						
			Men's Restroom						
			Women's Restroom						
			Break Out 03						
			Break Out 04						
			Break Out 05						
			Break Out 06						
			Work Room						
			Library Storage 01						
			Staff Lounge						
			N.W. Storage						
			Electrical 2						
			Work Room 426						
			T.O.						
			Unisex Restroom						
			Staff Restroom						
			426 Storage						
			Library Storage 03						
			Multi Media						
			Receiving Storage						
			Receiving						
			Conference						
			Cadd Classroom						
			Food Child Dev Lab						
			Food Storage						
			Cart Storage						
			H.E. Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			W/D						
			Room 429						
			429 Storage						
			Dark Room						
			424 Art						
			Art Storage 03						
			Electrical 1						
			Art Storage 02						
			Corridor 01						
			Corridor 02						
M-GWT-42	M	Glazed Wall Tile (Pattern), 4"X4", Gray, Smooth	Men's Restroom	Assumed	NF	G	250	SF	09/30/21
			Women's Restroom						
			Unisex Restroom						
			Staff Restroom						
			H.E. Restroom						
M-GWT-43	M	Glazed Wall Tile (Pattern), 4"X4", Black, Smooth	Men's Restroom	Assumed	NF	G	250	SF	09/30/21
			Women's Restroom						
			Unisex Restroom						
			Staff Restroom						
			H.E. Restroom						
M-GWT-44	M	Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth	Men's Restroom	Assumed	NF	G	250	SF	09/30/21
			Women's Restroom						
			Unisex Restroom						
			Staff Restroom						
			H.E. Restroom						

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	30,000	SF	09/30/21
M-MAS-02	M	Mastic (Penetrations And Flashings), Black, Tar-Like, Silver	Roof	Assumed	NF	G	1,500	SF	09/30/21
M-SLT-03	M	Sealant (Flashings), Gray, Pliable	Roof	Assumed	NF	G	125	SF	09/30/21
M-CMU-05	M	Concrete Masonry Unit, 8"X16", Pink, Cementitious, Rough	Lobby	Assumed	NF	G	20,000	SF	09/30/21
			Gymnasium						
			Kitchen Service Yard						
			Exterior						
			Roof						
M-CMU-06	M	Concrete Masonry Unit, 4"X16", Pink, Cementitious, Rough	Lobby	Assumed	NF	G	10,000	SF	09/30/21
			Gymnasium						
			Kitchen Service Yard						
			Exterior						
			Roof						
M-SLT-10	M	Sealant (Duct), Gray, Pliable	Roof	Assumed	NF	G	50	SF	09/30/21
M-SLT-11	M	Sealant (Duct), White, Pliable	Roof	Assumed	NF	G	50	SF	09/30/21
M-PES-12	M	Pipe End Sealant, Gray, Pliable	Roof	Assumed	NF	G	20	SF	09/30/21
M-WDB-13	M	Woven Duct Boot, 2", Black, Rubber-Like	Roof	Assumed	NF	G	20	SF	09/30/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CON-16	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	1,000	SF	09/30/21
M-CON-18	M	Concrete (Columns), Gray, Cementitious	Exterior	Assumed	NF	G	200	SF	09/30/21
S-STU-19	S	Stucco, Gray, Cementitious	Exterior	Assumed	NF	G	3,300	SF	09/30/21
M-MRT-20	M	Mortar (Glass Block), White, Cementitious	Multi-Purpose	Assumed	NF	G	5	SF	09/30/21
			Exterior						
M-CMU-21	M	Concrete Masonry Unit (Pattern), 12"X12", Gray, Cementitious	Mechanical 02	Assumed	NF	G	800	SF	09/30/21
			Exterior						
M-TWP-26	M	Tackable Wall Panel, Yellow, Fibrous Glass, Cloth Cover	Band Room 353	Assumed	NF	G	1,200	SF	09/30/21
M-SAC-30	M	Sink Acoustical Coating, Gray, Rough	Strings 401	Assumed	NF	G	6	SF	09/30/21
			Stage						
			Band Room 353						
M-FDI-32	M	Fire Door Insulation, Metal/Wood Cladding	Lobby	Assumed	NF	G	2,484	SF	09/30/21
			Strings 401						
			Gymnasium						
			Gym Storage						
			Boy's Lockers 01						
			Boy's Storage						
			Boy's Lockers 02						
			Boy's Coach Office						
			Mechanical 01						
			Mechanical 02						
			Electrical 03						
			Water/Heater Room						
			P.E. Storage						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Janitor 01						
			Girl's Lockers 01						
			Girl's Storage						
			Girl's Lockers 02						
			Girl's Coach Office						
			Boy's Restroom 01						
			Girl's Restroom 01						
			Serving Area						
			Electrical 02						
			Chemical Room						
			Unisex Restroom 01						
			Kitchen Service Yard						
			Food Storage						
			Multi-Purpose						
			Snack Bar						
			Stage						
			Dress 01						
			Unisex Restroom 02						
			Dress 02						
			Sound Room						
			Electrical 01						
			Band Room 353						
			Girl's Restroom						
			Boy's Restroom						
			Living Room						
			Kitchen						
			Corridor 01						
			Corridor 02						
			Corridor 03						
			Corridor 04						
			Corridor 05						
			Corridor 06						
			Corridor 07						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-SAT-36	S	Spray-Applied Texture, White, Chalky	Boy's Lockers 01	Assumed	NF	G	14,000	SF	09/30/21
			Boy's Shower						
			Boy's Restroom 02						
			Boy's Lockers 02						
			Boy's Coach Restroom						
			Janitor 01						
			Girl's Lockers 01						
			Girl's Shower						
			Girl's Restroom 02						
			Girl's Lockers 02						
			Girl's Coach Restroom						
			Boy's Restroom 01						
			Girl's Restroom 01						
			Kitchen						
			Serving Area						
			Snack Bar						
			Unisex Restroom 02						
			Girl's Restroom						
			Boy's Restroom						
			Corridor 03						
			Corridor 04						
M-GWB-37	M	Gypsum Wallboard, White, Chalky	Boy's Lockers 01	Assumed	NF	G	14,000	SF	09/30/21
			Boy's Shower						
			Boy's Restroom 02						
			Boy's Lockers 02						
			Boy's Coach Restroom						
			Janitor 01						
			Girl's Lockers 01						
			Girl's Shower						
			Girl's Restroom 02						
			Girl's Lockers 02						
			Girl's Coach Restroom						
			Boy's Restroom 01						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 01						
			Kitchen						
			Serving Area						
			Snack Bar						
			Unisex Restroom 02						
			Girl's Restroom						
			Boy's Restroom						
			Corridor 03						
			Corridor 04						
S-JTC-38	S	Joint Compound, White, Chalky	Boy's Lockers 01	Assumed	NF	G	1,400	SF	09/30/21
			Boy's Shower						
			Boy's Restroom 02						
			Boy's Lockers 02						
			Boy's Coach Restroom						
			Janitor 01						
			Girl's Lockers 01						
			Girl's Shower						
			Girl's Restroom 02						
			Girl's Lockers 02						
			Girl's Coach Restroom						
			Boy's Restroom 01						
			Girl's Restroom 01						
			Kitchen						
			Serving Area						
			Snack Bar						
			Unisex Restroom 02						
			Girl's Restroom						
			Boy's Restroom						
			Corridor 03						
			Corridor 04						
M-GWT-39	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Boy's Locker 01	Assumed	NF	G	7,000	SF	09/30/21
			Boy's Shower						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 02						
			Boy's Lockers 02						
			Girl's Lockers 01						
			Girl's Shower						
			Girl's Restroom 02						
			Girl's Lockers 02						
			Boy's Restroom 01						
			Girl's Restroom 01						
			Unisex Restroom 01						
			Girl's Restroom						
			Boy's Restroom						
M-GRT-40	M	Grout, Gray, Cementitious	Boy's Locker 01	Assumed	NF	G	700	SF	09/30/21
			Boy's Shower						
			Boy's Restroom 02						
			Boy's Lockers 02						
			Girl's Lockers 01						
			Girl's Shower						
			Girl's Restroom 02						
			Girl's Lockers 02						
			Boy's Restroom 01						
			Girl's Restroom 01						
			Unisex Restroom 01						
			Girl's Restroom						
			Boy's Restroom						
M-CMT-41	M	Ceramic Mosaic Tile, 2"X2". Gray, Smooth, Multi-Colored Spots	Boy's Restroom 01	Assumed	NF	G	2,000	SF	09/30/21
			Girl's Restroom 01						
			Unisex Restroom 02						
			Girl's Restroom						
			Boy's Restroom						
M-GRT-42	M	Grout, Gray, Cementitious	Boy's Restroom 01	Assumed	NF	G	200	SF	09/30/21
			Girl's Restroom 01						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Unisex Restroom 02						
			Girl's Restroom						
			Boy's Restroom						
M-GWT-44	M	Glazed Wall Tile (Coved), 4"X8", Gray, Smooth, Multi-Colored	Kitchen	Assumed	NF	G	2,000	SF	09/30/21
			Serving Area						
			Snack Bar						
			Corridor 04						
			Corridor 05						
			Corridor 06						
			Corridor 07						
M-GRT-45	M	Grout, Gray, Cementitious	Kitchen	Assumed	NF	G	200	SF	09/30/21
			Serving Area						
			Snack Bar						
			Corridor 04						
			Corridor 05						
			Corridor 06						
			Corridor 07						
M-QPT-46	M	Quarry/Paver Tile, 12"X12", Gray, Smooth, Multi-Colored Spots	Kitchen	Assumed	NF	G	2,500	SF	09/30/21
			Serving Area						
			Corridor 04						
M-GRT-47	M	Grout, Gray, Cementitious	Kitchen	Assumed	NF	G	250	SF	09/30/21
			Serving Area						
			Corridor 04						
M-ADH-49	M	Adhesive (FRP), Brown, Brittle	Boy's Lockers 01	Assumed	NF	G	20	SF	09/30/21
			Kitchen						
M-QPT-50	M	Quarry/Paver Tile, 12"X12", Gray, Textured, Black Streaks	Boy's Lockers 01	Assumed	NF	G	6,000	SF	09/30/21
			Boy's Shower						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 02						
			Boy's Lockers 02						
			Girl's Lockers 01						
			Girl's Shower						
			Girl's Restroom 02						
			Girl's Lockers 02						
			Food Storage						
			Snack Bar						
M-GRT-51	M	Grout, Gray, Cementitious	Boy's Lockers 01	Assumed	NF	G	600	SF	09/30/21
			Boy's Shower						
			Boy's Restroom 02						
			Boy's Lockers 02						
			Girl's Lockers 01						
			Girl's Shower						
			Girl's Restroom 02						
			Girl's Lockers 02						
			Food Storage						
			Snack Bar						
M-VST-52	M	Vinyl Stair Tread, 12"X48", Gray, Vinyl-Like, Circle Pattern	Multi-Purpose	Assumed	NF	G	50	SF	09/30/21
M-MAS-53	M	Mastic, Brown, Brittle	Multi-Purpose	Assumed	NF	G	50	SF	09/30/21
M-SLT-59	M	Sealant (Fire Stop), Red, Pliable	Electrical 03	Assumed	NF	G	10	SF	09/30/21
			Water/Heater Room						
M-SLT-61	M	Sealant (Equipment), Gray, Pliable	Lobby	Assumed	NF	G	50	SF	09/30/21
			Strings 401						
			Gymnasium						
			Gym Storage						
			Boy's Lockers 01						
			Boy's Storage						
			Boy's Shower						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 02						
			Boy's Lockers 02						
			Boy's Coach Office						
			Boy's Coach Restroom						
			Electrical 03						
			Water/Heater Room						
			P.E. Storage						
			Janitor 01						
			Girl's Lockers 01						
			Girl's Storage						
			Girl's Shower						
			Girl's Restroom 02						
			Girl's Lockers 02						
			Girl's Coach Office						
			Girl's Coach Restroom						
			Boy's Restroom 01						
			Girl's Restroom 01						
			Kitchen						
			Serving Area						
			Electrical 02						
			Office 01						
			Chemical Room						
			Unisex Restroom 01						
			Food Storage						
			Freezer 1						
			Freezer 2						
			Multi-Purpose						
			Snack Bar						
			Stage						
			Dress 01						
			Unisex Restroom 02						
			Dress 02						
			Sound Room						
			Electrical 01						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Band Room 353						
			Girl's Restroom						
			Boy's Restroom						
			Corridor 01						
			Corridor 02						
			Corridor 03						
			Corridor 04						
			Corridor 05						
			Corridor 06						
			Corridor 07						
M-GWT-69	M	Glazed Wall Tile (Pattern), 4"X4", Gray, Smooth	Boy's Locker 01	Assumed	NF	G	300	SF	09/30/21
			Boy's Restroom 02						
			Boy's Lockers 02						
			Girl's Lockers 01						
			Girl's Shower						
			Girl's Restroom 02						
			Girl's Lockers 02						
			Boy's Restroom 01						
			Girl's Restroom 01						
			Unisex Restroom 01						
			Girl's Restroom						
			Boy's Restroom						
M-GWT-70	M	Glazed Wall Tile (Pattern), 4"X4", Black, Smooth	Boy's Locker 01	Assumed	NF	G	300	SF	09/30/21
			Boy's Restroom 02						
			Boy's Lockers 02						
			Girl's Lockers 01						
			Girl's Shower						
			Girl's Restroom 02						
			Girl's Lockers 02						
			Boy's Restroom 01						
			Girl's Restroom 01						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Unisex Restroom 01						
			Girl's Restroom						
			Boy's Restroom						
M-GWT-71	M	Glazed Wall Tile, 4"X4", Blue, Smooth	Boy's Locker 01	Assumed	NF	G	300	SF	09/30/21
			Boy's Restroom 02						
			Boy's Lockers 02						
			Girl's Lockers 01						
			Girl's Shower						
			Girl's Restroom 02						
			Girl's Lockers 02						
			Boy's Restroom 01						
			Girl's Restroom 01						
			Unisex Restroom 01						
			Girl's Restroom						
			Boy's Restroom						
M-BUR-99	M	Built-Up Roofing, Black Asphaltic, White Gravel Cap	Roof	Assumed	NF	G	1,500	SF	09/30/21

\*The following materials were sampled and analytically identified to be non asbestos-containing: M-CPT-62, M-MAS-63, M-QPT-64, M-GRT-64, M-GWT-67 and M-GRT-68.



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380 1281 12816 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\01.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 438025d123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-02, Mastic (Penetrations And Flashings), Black, Tar-Like, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\02.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 45801280112365 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-03, Sealant (Flashings), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\03.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Haril  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 438012501123169 Signature of Inspector: Corbyn Haril

\*Material Reinspected: M-SLT-04, Sealant (Flashings), Black, Gummy

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\04.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380 12501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-05, Sealant (Flashings), Tan, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\05.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 43801290123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-06, Sealant (Windows), White, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\06.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380 125d 12316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-07, Concrete Masonry Unit, 8"X16", Pink, Cementitious, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\07.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4378 12501 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-08, Concrete Masonry Unit, 4"X16", Pink, Cementitious, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\08.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380125412345 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-09, Concrete Masonry Unit, 8"X16", Pink, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\09.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: \_\_\_\_\_ Person performing reinspection: \_\_\_\_\_  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: \_\_\_\_\_ Signature of Inspector: \_\_\_\_\_

\*Material Reinspected: M-CMU-10, Concrete Masonry Unit, 8"X16", Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place \_\_\_\_\_ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\10.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 438012501123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-11, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\11.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380 125012316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-STU-12, Stucco, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\12.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 43001250123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-16, Concrete (Entries), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\16.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380 1200 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-17, Concrete (Foundation), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\17.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 43801254123164 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-CON-18, Concrete (Columns), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\18.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380 1250 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-20, Mortar (Glass Block), White, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\20.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380 12521 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-FDI-31, Fire Door Insulation, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\31.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 43001252128164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SAC-32, Sink Acoustical Coating, Gray, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\32.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 43801250112364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-33, Sealant (Duct), Light Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\33.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

ASHERA certification number: 4380 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-SAT-35, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\35.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 438012501123165 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWB-36, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\36.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380125-1123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-37, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\37.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380125d123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-38, Glazed Wall Tile, 4"X4", Tan, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\38.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-39, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\39.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380650123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMT-40, Ceramic Mosaic Tile, 2"X2", Gray, Smooth, Multi-Colored Spots

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place \_\_\_\_\_ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\40.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4386 12001 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-41, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3.) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\41.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 438012501123104 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-WAB-45, Wallbase (Coved), 4", Gray, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\45.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 438012501123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-ADH-46, Adhesive, Cream, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\46.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380125012314 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-QPT-47, Quarry/Paver Tile, 12"X12", Gray, Smooth, Multi-Colored Spots

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\47.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main  
AHERA certification number: 4300125012344 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-GRT-48, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\48.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4380250123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-TWP-53, Tackable Wall Panel (Moveable), Brown, Fibrous, Vinyl Cover

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\53.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Coby Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 438012501123164 Signature of Inspector: Coby Hall

\*Material Reinspected: M-SLT-54, Sealant (Duct), Dark Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\54.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 4390 1250123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-55, Glazed Wall Tile (Pattern), 4"X4", Gray, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\55.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main  
AHERA certification number: 43801250103164 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-GWT-56, Glazed Wall Tile (Pattern), 4"X4", Black, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\56.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Main

AHERA certification number: 43801250123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-57, Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Main\57.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media  
AHERA certification number: 4350 12501123456 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\01.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 43801250123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-02, Mastic (Penetrations And Flashing), Black, Tar-Like, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\02.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4380 1252 12345 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-03, Sealant (Flashings), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\03.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 43801250112364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-04, Sealant (Doors, Windows, Flashings), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\04.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4370 12021 00166 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-05, Concrete Masonry Unit, 8"X16", Pink, Cementitious, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\05.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4310 12501 12544 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-06, Concrete Masonry Unit, 4"X16", Pink, Cementitious, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\06.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4350 12581123161 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-07, Concrete Masonry Unit, 8"X16", Pink, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\07.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4376 1254 12365 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-08, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\08.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4586 1201 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-09, Concrete (Entries), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\09.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4380125011234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-10, Concrete (Foundation), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\10.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4320120012369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-11, Concrete (Columns), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\11.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hull  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4370 12501 12814 Signature of Inspector: Corbyn Hull

\*Material Reinspected: S-STU-12, Stucco, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\12.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4380 12501 13164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-FDI-13, Fire Door Insulation, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\13.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4376 US01 031621 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-14, Mortar (Glass Block), White, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\14.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4380 12501 12369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-SAT-29, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\29.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media  
AHERA certification number: 4380 DSD 123164 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-GWB-30, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\30.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4380 125010000 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-31, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\31.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4380 1250123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SAC-32, Sink Acoustical Coating, Gray, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\32.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4380 D501 D3164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-WDB-33, Woven Duct Boot, 2", Black, Rubber-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\33.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4380125012364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-35, Glazed Wall Tile, 4"X4", Tan, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\35.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 435012501/2266 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-36, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\36.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 43701250112316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMT-37, Ceramic Mosaic Tile, 2"X2", Gray, Smooth, Multi-Colored Spots

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\37.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 43801280123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-38, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\38.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 438012501123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-APL-39, Acoustical Ceiling Panel, 2'x2', Yellow, Fibrous Glass, Cloth Cover

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\39.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 435012501123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-TWP-40, Tackable Wall Panel, White, Chalky, Vinyl Cover

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\40.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4380 12501 123469 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-41, Sealant (Duct), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\41.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-42, Glazed Wall Tile (Pattern), 4"X4", Gray, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\42.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 43801250112316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-43, Glazed Wall Tile (Pattern), 4"X4", Black, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\43.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Media

AHERA certification number: 42801250123164 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-GWT-44, Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Media\44.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 438012501234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\01.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 43801250112364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-02, Mastic (Penetrations And Flashings), Black, Tar-Like, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\02.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 4380 12521 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-03, Sealant (Flashings), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

#### Assessment:

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

#### Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\03.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 438012501122169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-05, Concrete Masonry Unit, 8"X16", Pink, Cementitious, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\05.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 43801250123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-06, Concrete Masonry Unit, 4"X16", Pink, Cementitious, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\06.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 4300 050123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-10, Sealant (Duct), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\10.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 43801250123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-11, Sealant (Duct), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\11.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 43701250112314 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-PES-12, Pipe End Sealant, Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\12.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 438025012501 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-WDB-13, Woven Duct Boot, 2", Black, Rubber-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\13.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 4380 1250 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-16, Concrete (Entries), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\16.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 4380 1261 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-18, Concrete (Columns), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\18.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 13801250123164 Signature of Inspector: Carbyn Hall

\*Material Reinspected: S-STU-19, Stucco, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\19.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 430125812364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-20, Mortar (Glass Block), White, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\20.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 4386 1262 12316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-21, Concrete Masonry Unit (Pattern), 12"X12", Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\21.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 43001201123161 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-TWP-26, Tackable Wall Panel, Yellow, Fibrous Glass, Cloth Cover

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\26.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 438012521286 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SAC-30, Sink Acoustical Coating, Gray, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\30.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 9301250123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-FDI-32, Fire Door Insulation, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\32.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 4370450112864 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-SAT-36, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** (1) Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

#### Assessment:

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

#### Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\36.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Conbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 43801280122169 Signature of Inspector: Conbyn Hall

\*Material Reinspected: M-GWB-37, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\37.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 4370 0201 122169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-38, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

#### Assessment:

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

#### Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\38.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 43801250123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-39, Glazed Wall Tile, 4"X4", Tan, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\39.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 438012501123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-40, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

#### Assessment:

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

#### Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\40.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 4370 1250123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMT-41, Ceramic Mosaic Tile, 2"X2", Gray, Smooth, Multi-Colored Spots

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\41.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 43801250123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-42, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

#### Assessment:

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

#### Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\42.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 4381250128169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-44, Glazed Wall Tile (Coved), 4"X8", Gray, Smooth, Multi-Colored

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\44.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corby Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 438612501123169 Signature of Inspector: Corby Hall

\*Material Reinspected: M-GRT-45, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\45.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 43802512046 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-QPT-46, Quarry/Paver Tile, 12"X12", Gray, Smooth, Multi-Colored Spots

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\46.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 4380 DSD D364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-47, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\47.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 4380 12501 123164 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-ADH-49, Adhesive (FRP), Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ☒ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\49.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 4/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 4380 D5X12364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-QPT-50, Quarry/Paver Tile, 12"X12", Gray, Textured, Black Streaks

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\50.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 4380 1254123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-51, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\51.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 4/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 4370 12501 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VST-52, Vinyl Stair Tread, 12"X48", Gray, Vinyl-Like, Circle Pattern

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\52.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 438012501123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-53, Mastic, Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☒ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\53.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 4380 1204 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-59, Sealant (Fire Stop), Red, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\59.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHRA certification number: 4380 WSA 1234 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-SLT-61, Sealant (Equipment), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\61.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 43801250123464 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CPT-62, Carpet, Brown, Fibrous

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place 2. Did Not Find ✓

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\62.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 4380 1250 12846 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-QPT-63, Quarry/Paver Tile, 12"X12", Gray, Smooth, Multi-Colored Specks

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc. (3)

**Material Status:** 1. In-Place 2. Did Not Find ✓

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\63.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 4380125010314 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-64, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place \_\_\_\_\_ 2. Did Not Find ✓

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\64.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose

AHERA certification number: 43801250123184 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-67, Glazed Wall Tile, 4"X4", White, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place 2. Did Not Find ✓

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\67.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 4380125112365 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-68, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place 2. Did Not Find ☒

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\68.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 437612501123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-69, Glazed Wall Tile (Pattern), 4"X4", Gray, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\69.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 4380 12501 12369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-70, Glazed Wall Tile (Pattern), 4"X4", Black, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\70.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 4380 12-501 12345 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-71, Glazed Wall Tile, 4"X4", Blue, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\71.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene Aprende Middle School Building Name/Number: Multi-Purpose  
AHERA certification number: 437012501 02369 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-BUR-99, Built-Up Roofing, Black Asphaltic, White Gravel Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Aprende\Forms\Multi-Purpose\99.doc