

November 2, 2021

Mr. Mike Williams
Facilities Supervisor
Kyrene School District No. 28
8700 South Kyrene Road
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection
Asbestos-Containing Building Materials
Kyrene de la Mariposa Elementary School
50 East Knox Road, Tempe
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: None.

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC



Michael Hall
Environmental Division Manager

Attachments: *3-Year Reinspection Tables*
3-Year Reinspection Forms

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Cvr Ltr.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-ADH-07	M	Adhesive (TWP), Brown, Brittle	Room 1	Assumed	NF	G	740	SF	09/30/21
			Room 2						
			Room 3						
			Room 4						
			Room 5						
			Room 6						
			Room 7						
			Room 8						
			Room 9						
			Room 10						
			Room 11						
			Room 12						
			Reception						
			School Office						
			Conference Room						
			Faculty Workroom						
			Faculty Lounge						
			Room 19						
			Room 20						
			Room 21						
			Room 22						
			Room 23						
			Room 26						
			Room 27						
			Room 28						
			Room 29						
			Room 30						
			Room 31						
			Room 32						
			Room 33						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 34						
			Room 38						
			Room 39						
			Music						
M-FDI-08	M	Fire Door Insulation, Metal Cladding	Room 1	Assumed	NF	G	840	SF	09/30/21
			Room 2						
			Room 26						
			Girl's West Foyer						
			Boy's West Restroom						
			Electrical No. 2						
			Reception						
			Health Office						
			Girl's North Foyer						
			Boy's North Restroom						
			Ramp						
			Multi-Purpose						
			Kitchen						
			Corridor No. 1						
			Corridor No. 2						
			Corridor No. 3						
			Corridor No. 4						
			Corridor No. 5						
			Corridor No. 7						
			Corridor No. 11						
M-FDI-09	M	Fire Door Insulation, Wood Cladding	Room 1	Assumed	NF	G	1,554	SF	09/30/21
			Room 2						
			Room 3						
			Room 4						
			Room 5						
			Room 6						
			Girl's West Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom West Hall						
			Boy's West Restroom						
			Water Heater Closet No. 1						
			Room 7						
			Room 8						
			Room 9						
			Room 10						
			Room 11						
			Room 12						
			Reception						
			Office Storage No. 2						
			Hall No. 2						
			Faculty Lounge						
			Janitor						
			Electrical No. 1						
			Library						
			Library Workroom						
			Audio Visual						
			Computer Room						
			Room 19						
			Room 20						
			Room 21						
			Room 22						
			Room 23						
			Water Heater Closet No. 2						
			Girl's North Foyer						
			Girl's North Restroom						
			Girls' North Restroom Hall						
			Boy's North Restroom						
			Room 26						
			Room 27						
			Room 28						
			Room 29						
			Room 30						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 31						
			Room 32						
			Room 33						
			Room 34						
			Room 35						
			Room 36						
			Room 37						
			Room 38						
			Room 39						
			Music						
			Music Storage						
			Multi-Purpose						
			Multi-Use Storage						
			Water Heater Closet No. 3						
			P.E. Storage						
			Kitchen						
			Girl's East Restroom						
			Boy's East Restroom						
			Corridor No. 1						
			Corridor No. 2						
			Corridor No. 3						
			Corridor No. 4						
			Corridor No. 5						
			Corridor No. 6						
			Corridor No. 7						
			Corridor No. 8						
			Corridor No. 9						
			Corridor No. 10						
			Corridor No. 11						
			Corridor No. 12						
M-SLT-15	M	Sealant, White, Pliable	Room 1	Assumed	NF	G	130	SF	09/30/21
			Room 2						
			Room 2 Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 3						
			Room 4						
			Room 5						
			Room 6						
			Girl's West Foyer						
			Girl's West Restroom						
			Girl's Restroom West Hall						
			Boy's West Restroom						
			Water Heater Closet No. 1						
			Room 7						
			Room 8						
			Room 9						
			Room 10						
			Room 11						
			Room 12						
			Electrical No. 2						
			Reception						
			School Office						
			Health Office						
			Treatment						
			Hall No. 1						
			Office Storage Room No. 1						
			Fire Riser Room						
			Staff Restroom						
			Principal						
			Hall No. 2						
			Conference Room						
			Conference Room Closet						
			Staff Women's Restroom						
			Staff Men's Restroom						
			Office Storage No. 2						
			Faculty Workroom						
			Faculty Lounge						
			Phone Room						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Janitor						
			Electrical No. 1						
			Library						
			Library Work Room						
			Audio Visual						
			Computer Room						
			Room 19						
			Room 20						
			Vestibule						
			Speech Office						
			Test						
			Room 21						
			Timeout						
			Room 22						
			Room 23						
			Girl's North Restroom Hall						
			Boy's North Restroom						
			Room 26						
			Room 27						
			Room 28						
			Room 29						
			Room 30						
			Room 31						
			Room 32						
			Room 33						
			Room 34						
			Room 35						
			Room 36						
			Room 37						
			Room 38						
			Room 39						
			Music						
			Music Storage						
			Ramp						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Multi-Purpose						
			Multi-Use Storage						
			Water Heater Closet No. 3						
			P.E. Storage						
			Office						
			Corridor No. 1						
			Corridor No. 2						
			Corridor No. 3						
			Corridor No. 4						
			Corridor No. 5						
			Corridor No. 7						
			Corridor No. 8						
			Corridor No. 9						
			Corridor No. 10						
			Corridor No. 11						
			Corridor No. 12						
M-MRT-16	M	Mortar (Glass Block), Gray, Cementitious	Room 1	Assumed	NF	G	200	SF	09/30/21
			Room 2						
			Room 3						
			Room 4						
			Room 5						
			Room 6						
			Room 7						
			Room 8						
			Room 9						
			Room 10						
			Room 11						
			Room 12						
			Reception						
			Health Office						
			Fire Riser Room						
			Principal						
			Faculty Workroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Computer Room						
			Room 21						
			Room 22						
			Room 23						
			Room 26						
			Room 27						
			Room 28						
			Room 29						
			Room 30						
			Room 31						
			Room 32						
			Room 33						
			Room 34						
			Room 35						
			Room 36						
			Room 37						
			Room 38						
			Room 39						
			Multi-Purpose Room						
			Corridor No. 1						
			Corridor No. 2						
			Corridor No. 3						
			Corridor No. 4						
			Corridor No. 5						
			Corridor No. 7						
			Corridor No. 8						
			Corridor No. 9						
			Corridor No. 10						
			Corridor No. 12						
M-PES-23	M	Pipe End Sealant, White, Pliable	Room 1	Assumed	NF	G	200	SF	09/30/21
			Room 1 Restroom						
			Room 2						
			Room 2 Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 3						
			Room 4						
			Room 5						
			Room 6						
			Girl's West Foyer						
			Girl's West Restroom						
			Girl's Restroom West Hall						
			Boy's West Restroom						
			Water Heater Closet No. 1						
			Room 7						
			Room 8						
			Room 9						
			Room 10						
			Room 11						
			Room 12						
			Electrical No. 2						
			Reception						
			School Office						
			Health Office						
			Treatment						
			Hall No. 1						
			Office Storage Room No. 1						
			Fire Riser Room						
			Staff Restroom						
			Office No. 1						
			Principal						
			Hall No. 2						
			Conference Room						
			Conference Room Closet						
			Staff Women's Restroom						
			Staff Men's Restroom						
			Office Storage No. 2						
			Faculty Workroom						
			Faculty Lounge						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Phone Room						
			Janitor						
			Electrical No. 1						
			Library						
			Library Workroom						
			Audio Visual						
			Computer Room						
			Room 19						
			Room 20						
			Vestibule						
			Speech Office						
			Test						
			Room 21						
			Timeout						
			Room 22						
			Room 23						
			Water Heater Closet No. 2						
			Girl's North Foyer						
			Girl's North Restroom						
			Girl's North Restroom Hall						
			Boy's North Restroom						
			Room 26						
			Room 27						
			Room 28						
			Room 29						
			Room 30						
			Room 31						
			Room 32						
			Room 33						
			Room 34						
			Room 35						
			Room 36						
			Room 37						
			Room 38						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 39						
			Music						
			Music Storage						
			Stage						
			Stage Wing						
			Ramp						
			Multi-Purpose						
			Multi-Use Storage						
			Water Heater Closet No. 3						
			P.E. Storage						
			Office						
			Kitchen						
			Girl's East Restroom						
			Boy's East Restroom						
			Corridor No. 1						
			Corridor No. 2						
			Corridor No. 3						
			Corridor No. 4						
			Corridor No. 5						
			Corridor No. 6						
			Corridor No. 7						
			Corridor No. 8						
			Corridor No. 9						
			Corridor No. 10						
			Corridor No. 11						
			Corridor No. 12						
M-SAC-26	M	Sink Acoustical Coating, White, Rough	Room 1	Assumed	NF	G	165	SF	09/30/21
			Room 2						
			Room 3						
			Room 4						
			Room 5						
			Room 6						
			Room 7						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 8						
			Room 9						
			Room 10						
			Room 11						
			Room 12						
			Room 20						
			Room 21						
			Room 22						
			Room 23						
			Room 26						
			Room 27						
			Room 28						
			Room 29						
			Room 30						
			Room 31						
			Room 32						
			Room 33						
			Room 34						
			Room 35						
			Faculty Lounge						
			Computer Room						
			Library Workroom						
			Music						
M-SLT-30	M	Sealant (Duct), Gray, Brittle	Room 1	Assumed	NF	G	500	SF	09/30/21
			Room 1 Restroom						
			Room 2						
			Room 2 Restroom						
			Room 3						
			Room 4						
			Room 5						
			Room 6						
			Girl's West Foyer						
			Girl's West Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom West Hall						
			Boy's West Restroom						
			Water Heater Closet No. 1						
			Room 7						
			Room 8						
			Room 9						
			Room 10						
			Room 11						
			Room 12						
			Electrical No. 2						
			Reception						
			School Office						
			Health Office						
			Treatment						
			Hall No. 1						
			Office Storage Room No. 1						
			Fire Riser Room						
			Staff Restroom						
			Office No. 1						
			Principal						
			Hall No. 2						
			Conference Room						
			Conference Room Closet						
			Staff Women's Restroom						
			Staff Men's Restroom						
			Office Storage No. 2						
			Faculty Workroom						
			Faculty Lounge						
			Phone Room						
			Janitor						
			Electrical No. 1						
			Library						
			Library Workroom						
			Audio Visual						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Computer Room						
			Room 19						
			Room 20						
			Vestibule						
			Speech Office						
			Test						
			Room 21						
			Timeout						
			Room 22						
			Room 23						
			Water Heater Closet No. 2						
			Girl's North Foyer						
			Girl's North Restroom						
			Girl's North Restroom Hall						
			Boy's North Restroom						
			Room 26						
			Room 27						
			Room 28						
			Room 29						
			Room 30						
			Room 31						
			Room 32						
			Room 33						
			Room 34						
			Room 35						
			Room 36						
			Room 37						
			Room 38						
			Room 39						
			Music						
			Music Storage						
			Stage						
			Stage Wing						
			Ramp						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Multi-Purpose						
			Multi-Use Storage						
			Water Heater Closet No. 3						
			P.E. Storage						
			Office						
			Kitchen						
			Girl's East Restroom						
			Boy's East Restroom						
			Corridor No. 1						
			Corridor No. 2						
			Corridor No. 3						
			Corridor No. 4						
			Corridor No. 5						
			Corridor No. 6						
			Corridor No. 7						
			Corridor No. 8						
			Corridor No. 9						
			Corridor No. 10						
			Corridor No. 11						
			Corridor No. 12						
M-SLT-33	M	Sealant (Fire Stop), Red, Pliable	Room 1	Assumed	NF	G	5	SF	09/30/21
			Room 1 Restroom						
			Room 2						
			Room 2 Restroom						
			Room 3						
			Room 4						
			Room 5						
			Room 6						
			Girl's West Foyer						
			Girl's West Restroom						
			Girl's Restroom West Hall						
			Boy's West Restroom						
			Water Heater Closet No. 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 7						
			Room 8						
			Room 9						
			Room 10						
			Room 11						
			Room 12						
			Electrical No. 2						
			Reception						
			School Office						
			Health Office						
			Treatment						
			Hall No. 1						
			Office Storage Room No. 1						
			Fire Riser Room						
			Staff Restroom						
			Office No. 1						
			Principal						
			Hall No. 2						
			Conference Room						
			Conference Room Closet						
			Staff Women's Restroom						
			Staff Men's Restroom						
			Office Storage No. 2						
			Faculty Workroom						
			Faculty Lounge						
			Phone Room						
			Janitor						
			Electrical No. 1						
			Library						
			Library Workroom						
			Audio Visual						
			Computer Room						
			Room 19						
			Room 20						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Vestibule						
			Speech Office						
			Test						
			Room 21						
			Timeout						
			Room 22						
			Room 23						
			Water Heater Closet No. 2						
			Girl's North Foyer						
			Girl's North Restroom						
			Girl's North Restroom Hall						
			Boy's North Restroom						
			Room 26						
			Room 27						
			Room 28						
			Room 29						
			Room 30						
			Room 31						
			Room 32						
			Room 33						
			Room 34						
			Room 35						
			Room 36						
			Room 37						
			Room 38						
			Room 39						
			Music						
			Music Storage						
			Stage						
			Stage Wing						
			Ramp						
			Multi-Purpose						
			Multi-Use Storage						
			Water Heater Closet No. 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			P.E. Storage						
			Office						
			Kitchen						
			Girl's East Restroom						
			Boy's East Restroom						
			Corridor No. 1						
			Corridor No. 2						
			Corridor No. 3						
			Corridor No. 4						
			Corridor No. 5						
			Corridor No. 6						
			Corridor No. 7						
			Corridor No. 8						
			Corridor No. 9						
			Corridor No. 10						
			Corridor No. 11						
			Corridor No. 12						
M-GWT-34	M	Glazed Wall Tile, 4"X6", Gray, Smooth	Girl's West Foyer	Assumed	NF	G	2,000	SF	09/30/21
			Girl's West Restroom						
			Boy's West Restroom						
			Girl's North Foyer						
			Girl's North Restroom						
			Boy's North Restroom						
M-GWT-35	M	Glazed Wall Tile, 4"X6", Blue, Smooth	Girl's West Foyer	Assumed	NF	G	100	SF	09/30/21
			Girl's West Restroom						
			Boy's West Restroom						
			Girl's North Foyer						
			Girl's North Restroom						
			Boy's North Restroom						
M-GWT-36	M	Glazed Wall Tile, 4"X6", Pink, Smooth	Girl's West Foyer	Assumed	NF	G	100	SF	09/30/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's West Restroom						
			Boy's West Restroom						
			Girl's North Foyer						
			Girl's North Restroom						
			Boy's North Restroom						
M-GRT-37	M	Grout, Gray, Cementitious	Girl's West Foyer	Assumed	NF	G	220	SF	09/30/21
			Girl's West Restroom						
			Boy's West Restroom						
			Girl's North Foyer						
			Girl's North Restroom						
			Boy's North Restroom						
M-CMT-38	M	Ceramic Mosaic Tile, 2"X2", Gray, Smooth	Girl's West Foyer	Assumed	NF	G	1,500	SF	09/30/21
			Girl's West Restroom						
			Boy's West Restroom						
			Girl's North Foyer						
			Girl's North Restroom						
			Boy's North Restroom						
M-GRT-39	M	Grout, Gray, Cementitious	Girl's West Foyer	Assumed	NF	G	150	SF	09/30/21
			Girl's West Restroom						
			Boy's West Restroom						
			Girl's North Foyer						
			Girl's North Restroom						
			Boy's North Restroom						
M-SLT-40	M	Sealant, Gray, Pliable	Girl's West Restroom	Assumed	NF	G	8	SF	09/30/21
			Boy's West Restroom						
			Girl's North Restroom						
			Boy's North Restroom						
			Girl's East Restroom						
			Boy's East Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-EXJ-43	M	Expansion Joint, Red, Pliable	Exterior	Assumed	NF	G	8	SF	09/30/21
M-SLT-47	M	Sealant, Brown, Pliable	Library	Assumed	NF	G	5	SF	09/30/21
			Room 21						
			Corridor 1						
			Corridor 11						
M-SLT-48	M	Sealant, Black, Tar-Like	Library	Assumed	NF	G	7	SF	09/30/21
			Room 20						
			Corridor 5						
			Corridor 8						
M-VCT-50	M	Vinyl Composition Tile, 2"X24", Black, Smooth, Pattern	Multi-Purpose	Assumed	NF	G	200	SF	09/30/21
M-VCT-54	M	Vinyl Composition Tile, 2"X24", Green, Smooth, Pattern	Multi-Purpose	Assumed	NF	G	100	SF	09/30/21
M-EXJ-55	M	Expansion Joint, Brown, Pliable	Multi-Purpose	Assumed	NF	G	33	SF	09/30/21
			Kitchen						
			Exterior						
M-SAC-63	M	Sink Acoustical Coating, Gray, Rough	Room 36	Assumed	NF	G	8	SF	09/30/21
			Room 37						
			Room 38						
			Room 39						
M-SLT-64	M	Sealant (Flashings), White, Pliable	Main Roof	Assumed	NF	G	50	SF	09/30/21
M-MAS-65	M	Mastic (Penetrations and Flashings), Black, Brittle	Main Roof	Assumed	NF	G	1,300	SF	09/30/21
M-SLT-69	M	Sealant, Gray, Pliable	Roof-Mounted HVAC Units	Assumed	NF	G	15	SF	09/30/21
M-SLT-71	M	Sealant, Black, Pliable	Main Roof	Assumed	NF	G	10	SF	09/30/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M·MAS·72	M	Mastic (Penetrations and Flashing), Black, Tar-Like	Main Roof	Assumed	NF	G	250	SF	09/30/21
M·MAS·74	M	Mastic (Penetrations and Flashing), Black, Tar-Like	Main Roof	Assumed	NF	G	300	SF	09/30/21
M·SLT·75	M	Sealant (Penetrations and Flashing), White, Pliable	Main Roof	Assumed	NF	G	50	SF	09/30/21
M·SLT·76	M	Sealant (Flashings), Gray, Brittle	Entry Roofs Throughout	Assumed	NF	G	20	SF	09/30/21
M·SLT·77	M	Sealant (Penetrations), Cream, Tacky	Main Roof	Assumed	NF	G	5	SF	09/30/21
M·SLT·79	M	Sealant, Gray, Pliable	Exterior	Assumed	NF	G	10	SF	09/30/21
M·SLT·80	M	Sealant, Gray, Brittle	Exterior	Assumed	NF	G	5	SF	09/30/21
M·CON·81	M	Concrete, Gray, Cementitious	Exterior	Assumed	NF	G	26,100	SF	09/30/21
M·CMU·82	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	Exterior	Assumed	NF	G	20	SF	09/30/21
M·SLT·83	M	Sealant (Mechanical), Black, Tar-Like	Equipment Well	Assumed	NF	G	15	SF	09/30/21
M·PES·84	M	Pipe End Sealant, White, Brittle	Equipment Well	Assumed	NF	G	2	SF	09/30/21
M·SLT·85	M	Sealant, White, Pliable	Equipment Well	Assumed	NF	G	4	SF	09/30/21
M·GAS·86	M	Gasket, 8", Black, Paper-Like	Equipment Well	Assumed	NF	G	4	SF	09/30/21
M·MRT·87	M	Mortar, Gray, Cementitious	Exterior	Assumed	NF	G	2	SF	09/30/21
M·CON·88	M	Concrete, Gray, Cementitious	Room 1	Assumed	NF	G	55,000	SF	09/30/21
			Room 1 Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 2						
			Room 2 Restroom						
			Room 3						
			Room 4						
			Room 5						
			Room 6						
			Girl's West Foyer						
			Girl's West Restroom						
			Girl's Restroom West Hall						
			Boy's West Foyer						
			Water Heater Closet No. 1						
			Room 7						
			Room 8						
			Room 9						
			Room 10						
			Room 11						
			Room 12						
			Electrical No. 2						
			Reception						
			School Office						
			Health Office						
			Treatment						
			Hall No. 1						
			Office Storage Room No. 1						
			Fire Riser Room						
			Staff Restroom						
			Office No. 1						
			Principal						
			Hall No. 2						
			Conference Room						
			Conference Room Closet						
			Staff Women's Restroom						
			Staff Men's Restroom						
			Office Storage No. 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Faculty Workroom						
			Faculty Lounge						
			Phone Room						
			Janitor						
			Electrical No. 1						
			Library						
			Library Workroom						
			Audio Visual						
			Computer Room						
			Room 19						
			Room 20						
			Vestibule						
			Speech Office						
			Test						
			Room 21						
			Timeout						
			Room 22						
			Room 23						
			Water Heater Closet No. 2						
			Girl's North Foyer						
			Girl's North Restroom						
			Girl's North Restroom Hall						
			Boy's North Restroom						
			Room 26						
			Room 27						
			Room 28						
			Room 29						
			Room 30						
			Room 31						
			Room 32						
			Room 33						
			Room 34						
			Room 35						
			Room 36						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 37						
			Room 38						
			Room 39						
			Music						
			Music Storage						
			Stage						
			Stage Wing						
			Ramp						
			Multi-Purpose						
			Multi-Use Storage						
			Water Heater Closet No. 3						
			P.E. Storage						
			Office						
			Kitchen						
			Girl's East Restroom						
			Boy's East Restroom						
			Corridor No. 1						
			Corridor No. 2						
			Corridor No. 3						
			Corridor No. 4						
			Corridor No. 5						
			Corridor No. 6						
			Corridor No. 7						
			Corridor No. 8						
			Corridor No. 9						
			Corridor No. 10						
			Corridor No. 11						
			Corridor No. 12						
M-FDI-216	M	Fire Door Insulation, Metal/Wood Cladding	Room 42	Assumed	NF	G	147	SF	09/30/21
			Boy's Restroom						
			Girl's Restroom						
			Room 43						
			Room 44						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 13						
			Corridor 14						

***The following materials were sampled and analytically identified to be non asbestos-containing: M-BRK-45, M-MRT-46, S-STU-67, M-GWB-68, M-BUR-73 and M-BUR-78. Material M-APR-66 was not found.**

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Main-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-SLT-01	M	Sealant, White, Pliable	Exterior	Assumed	NF	G	1	SF	09/30/21
M-APR-02	M	Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	200	SF	09/30/21
M-VBF-03	M	Vapor Barrier Felt, Black, Asphaltic	Roof	Assumed	NF	G	200	SF	09/30/21

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Sto Shed-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\R1,R2-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\R3,R4-Tbl.doc

3-YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\RR-Tbl.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4350120012344 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-ADH-07, Adhesive (TWP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\07.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 438012501123169 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-FDI-08, Fire Door Insulation, Metal Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\08.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 438012001 V3164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-09, Fire Door Insulation, Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\09.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 438012621123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-15, Sealant, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ☒ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: ✓ Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MRT-16, Mortar (Glass Block), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\16.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 7/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 43851280112364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PES-23, Pipe End Sealant, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\23.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbin Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 12314 Signature of Inspector: Corbin Hall

*Material Reinspected: M-SAC-26, Sink Acoustical Coating, White, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\26.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 430128123166 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-30, Sealant (Duct), Gray, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\30.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 43801252112364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-33, Sealant (Fire Stop), Red, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\33.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380425012214 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-34, Glazed Wall Tile, 4"X6", Gray, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\34.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: Corbyn Hall Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 43801256123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-35, Glazed Wall Tile, 4"X6", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\35.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 436012501256 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-36, Glazed Wall Tile, 4"X6", Pink, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes ☐ No ☒
Evidence of Water Damage: _____ Yes ☐ No ☒
Evidence of Delamination or Other Damage: _____ Yes ☐ No ☒
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes ☐ No ☒

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes ☐ No ☒
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\36.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380125012344 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-37, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\37.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4800 D504123161 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-CMT-38, Ceramic Mosaic Tile, 2"X2", Gray, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\38.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4300012369 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GRT-39, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\39.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 430 1201 12364 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-SLT-40, Sealant, Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ☒ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\40.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380 2501 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-EXJ-43, Expansion Joint, Red, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\43.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4300125912314 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-BRK-45, Brick, 3"X16", Red, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ 3. Misc.

Material Status: 1. In-Place 2. Did Not Find ☒

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\45.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 43801280125164 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-MRT-46, Mortar, Red, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place 2. Did Not Find ☒

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\46.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380250163169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-47, Sealant, Brown, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\47.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 436125d12369 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-48, Sealant, Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\48.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 43801250123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-VCT-50, Vinyl Composition Tile, 2"X24", Black, Smooth, Pattern

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\50.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380128012364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-VCT-54, Vinyl Composition Tile, 2"X24", Green, Smooth, Pattern

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\54.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 430 125012345 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-EXJ-55, Expansion Joint, Brown, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\55.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4300000112344 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SAC-63, Sink Acoustical Coating, Gray, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\63.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4300 1200123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-64, Sealant (Flashings), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\64.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Conyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 438012501236 Signature of Inspector: Conyn Hall

*Material Reinspected: M-MAS-65, Mastic (Penetrations and Flashings), Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\65.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380 1202 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-APR-66, Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Brown Mineral Cap, Pads

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place 2. Did Not Find ✓

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\66.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbin Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 12316 Signature of Inspector: Corbin Hall

*Material Reinspected: S-STU-67, Stucco, Gray, Cementitious

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find ✓

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\67.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 43801200123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWB-68, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③. Misc.

Material Status: 1. In-Place 2. Did Not Find ✓

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\68.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 43801201123169 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-SLT-69, Sealant, Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\69.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 45101280112364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-71, Sealant, Black, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place / 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low /
Degree of Activity Near the Material: High _____ Medium _____ Low /
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\71.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 41501250123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MAS-72, Mastic (Penetrations and Flashing), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\72.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4390125012309 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-BUR-73, Built-Up Roofing, Black, Asphaltic, Metal Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place 2. Did Not Find ☒

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\73.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corsyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 43801252125169 Signature of Inspector: Corsyn Hall

*Material Reinspected: M-MAS-74, Mastic (Penetrations and Flashing), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\74.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 438012501123164 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-SLT-75, Sealant (Penetrations and Flashing), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\75.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380125012364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-76, Sealant (Flashings), Gray, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\76.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corby J Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4320125012345 Signature of Inspector: Corby J Hall

*Material Reinspected: M-SLT-77, Sealant (Penetrations), Cream, Tacky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc. ☒

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\77.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4370 125212369 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-BUR-78, Built-Up Roofing, Black, Asphaltic, Gravel Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place _____ 2. Did Not Find ✓

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\78.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4350 1250123456 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-SLT-79, Sealant, Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ☒ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\79.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380 1250123456 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-80, Sealant, Gray, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\80.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corby Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380 120112364 Signature of Inspector: Corby Hall

*Material Reinspected: M-CON-81, Concrete, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No

Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\81.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380 12001 125164 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-CMU-82, Concrete Masonry Unit, 8"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\82.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Conbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 436012501123164 Signature of Inspector: Conbyn Hall

*Material Reinspected: M-SLT-83, Sealant (Mechanical), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\83.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380 1259 125464 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PES-84, Pipe End Sealant, White, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\84.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-85, Sealant, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\85.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380 12521 123165 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GAS-86, Gasket, 8", Black, Paper-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\86.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 7/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4876 12501128164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MRT-87, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\87.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 4380 1254 12344 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CON-88, Concrete, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\88.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Main

AHERA certification number: 430125012514 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-216, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Main\216.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Storage

AHERA certification number: 43801250112364 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-SLT-01, Sealant, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Sto Shed\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Storage

AHERA certification number: 4300 12501234 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-APR-02, Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Sto Shed\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/30/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Mariposa Elementary School Building Name/Number: Storage

AHERA certification number: 4386 6561 12369 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-VBF-03, Vapor Barrier Felt, Black, Asphaltic

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Mariposa\Forms\Sto Shed\03.doc