

November 5, 2021

Mr. Mike Williams
Facilities Supervisor
Kyrene School District No. 28
8700 South Kyrene Road
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection
Asbestos-Containing Building Materials
Kyrene de las Brisas Elementary School
777 North Desert Breeze Boulevard – East #2, Chandler
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: None.

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC



Michael Hall
Environmental Division Manager

*Attachments: 3-Year Reinspection Tables
3-Year Reinspection Forms*

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Cvr Ltr.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-PSL-15	M	Pipe End Sealant (Fire Sprinklers), White, Pliable	Reception	Assumed	NF	G	500	SF	09/29/21
			Nurse						
			Treatment						
			Hall 2						
			Testing						
			Nurse Restroom						
			Storage 3						
			Storage 4						
			Assistant Principal						
			Custodial Office						
			Received						
			Received Closet						
			Riser Room						
			Principal						
			Hall 1						
			Conference 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			ESL						
			PTSO						
			Electrical 2						
			Electrical 3						
			Art Storage						
			Psychology						
			Special Ed 1						
			Special Ed Restroom						
			Special Ed 2						
			Storage 2						
			Special Ed 3						
			Speech						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Electrical 1						
			Electrical 4						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Preschool 10						
			Room 10 Restroom						
			Preschool 11						
			Room 11 Restroom						
			Classroom 12						
			Room BO1A						
			Classroom 13						
			Classroom 14						
			Room BOB						
			Classroom 15						
			Pod 1						
			Conference 2						
			Room 17						
			Classroom 20						
			Room 20 Restroom						
			Room BO2A						
			Classroom 21						
			Room 21 Restroom						
			Classroom 22						
			Room BO2B						
			Classroom 23						
			Classroom 24						
			Room BO2C						
			Classroom 25						
			Pod 2						
			Classroom 30						
			Room 30 Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room BO3A						
			Classroom 31						
			Room 31 Restroom						
			Classroom 32						
			Room BO3B						
			Classroom 33						
			Classroom 34						
			Room BO3C						
			Classroom 35						
			Classroom 40						
			Room 40 Restroom						
			Room BO4A						
			Classroom 41						
			Room 41 Restroom						
			Classroom 42						
			Room BO4B						
			Classroom 43						
			Classroom 44						
			Room BO4C						
			Classroom 45						
			Pod 4						
			Classroom 50						
			Room 50 Restroom						
			Room BO5A						
			Classroom 51						
			Room 51 Restroom						
			Classroom 52						
			Room BO5B						
			Classroom 53						
			Classroom 54						
			Room BO5C						
			Classroom 55						
			Pod 5						
			Multi-Purpose						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 3						
			Girl's Restroom 3						
			Storage 8						
			Storage 9						
			P.E. Office						
			P.E. Storage						
			Kitchen						
			Service Yard						
			Storage 6						
			Storage 7						
			Chair/Table Storage						
			Stage						
			Music						
			Storage 5						
			Classroom 60						
			Room 60 Restroom						
			Room BO6A						
			Classroom 61						
			Room 61 Restroom						
			Classroom 62						
			Room BO6B						
			Classroom 63						
			Classroom 64						
			Room BO6C						
			Classroom 65						
			Pod 6						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
			Corridor 8						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 9						
			Corridor 10						
M-FDI-16	M	Fire Door Insulation, Wood/Metal Cladding	Reception	Assumed	NF	G	2,625	SF	09/29/21
			Storage 4						
			Custodial Office						
			Received						
			Riser Room						
			Principal						
			Music						
			Corridor 8						
			Hall 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			ESL						
			PTSO						
			Electrical 2						
			Electrical 3						
			Art Storage						
			Psychology						
			Special Ed 1						
			Special Ed 2						
			Storage 2						
			Special Ed 3						
			Speech						
			Storage 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Electrical 1						
			Electrical 4						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Preschool 10						
			Preschool 11						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 12						
			Classroom 13						
			Classroom 14						
			Classroom 15						
			Conference 2						
			Classroom 20						
			Classroom 21						
			Classroom 22						
			Classroom 23						
			Classroom 24						
			Classroom 25						
			Secured Play Area 3						
			Classroom 30						
			Classroom 31						
			Classroom 32						
			Classroom 33						
			Classroom 34						
			Classroom 35						
			Secured Play Area 2						
			Classroom 40						
			Classroom 41						
			Classroom 42						
			Classroom 43						
			Classroom 44						
			Classroom 45						
			Secured Play Area 1						
			Classroom 50						
			Classroom 51						
			Classroom 52						
			Classroom 53						
			Classroom 54						
			Classroom 55						
			Multi-Purpose						
			Boy's Restroom 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Stage						
			Girl's Restroom 3						
			Storage 9						
			P.E. Storage						
			Kitchen						
			Service Yard						
			Classroom 60						
			Classroom 61						
			Classroom 62						
			Classroom 63						
			Classroom 64						
			Classroom 65						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
			Corridor 9						
			Corridor 10						
M-GWT-20	M	Glazed Wall Tile, 4"X4", White, Smooth	Nurse Restroom	Assumed	NF	G	9,000	SF	09/29/21
			Staff Men's Restroom						
			Staff Women's Restroom						
			Special Ed Restroom						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Room 10 Restroom						
			Room 11 Restroom						
			Room 20 Restroom						
			Room 21 Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 30 Restroom						
			Room 31 Restroom						
			Room 40 Restroom						
			Room 41 Restroom						
			Room 50 Restroom						
			Room 51 Restroom						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Room 60 Restroom						
			Room 61 Restroom						
			Corridor 5						
M-GWT-21	M	Glazed Wall Tile (Pattern), 4"x4", Gray, Smooth	Nurse Restroom	Assumed	NF	G	1,000	SF	09/29/21
			Staff Men's Restroom						
			Staff Women's Restroom						
			Special Ed Restroom						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Room 10 Restroom						
			Room 11 Restroom						
			Room 20 Restroom						
			Room 21 Restroom						
			Room 30 Restroom						
			Room 31 Restroom						
			Room 40 Restroom						
			Room 41 Restroom						
			Room 50 Restroom						
			Room 51 Restroom						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Room 60 Restroom						
			Room 61 Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GWT-22	M	Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth	Nurse Restroom	Assumed	NF	G	1,000	SF	09/29/21
			Staff Men's Restroom						
			Staff Women's Restroom						
			Special Ed Restroom						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Room 10 Restroom						
			Room 11 Restroom						
			Room 20 Restroom						
			Room 21 Restroom						
			Room 30 Restroom						
			Room 31 Restroom						
			Room 40 Restroom						
			Room 41 Restroom						
			Room 50 Restroom						
			Room 51 Restroom						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Room 60 Restroom						
			Room 61 Restroom						
M-GRT-23	M	Grout, Gray, Cementitious	Nurse Restroom	Assumed	NF	G	1,000	SF	09/29/21
			Staff Men's Restroom						
			Staff Women's Restroom						
			Special Ed Restroom						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Room 10 Restroom						
			Room 11 Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 20 Restroom						
			Room 21 Restroom						
			Room 30 Restroom						
			Room 31 Restroom						
			Room 40 Restroom						
			Room 41 Restroom						
			Room 50 Restroom						
			Room 51 Restroom						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Room 60 Restroom						
			Room 61 Restroom						
			Corridor 5						
M-CMT-24	M	Ceramic Mosaic Tile, 2"X2", Gray, Smooth, White Specks	Nurse Restroom	Assumed	NF	G	4,000	SF	09/29/21
			Staff Men's Restroom						
			Staff Women's Restroom						
			Special Ed Restroom						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Room 10 Restroom						
			Room 11 Restroom						
			Room 20 Restroom						
			Room 21 Restroom						
			Room 30 Restroom						
			Room 31 Restroom						
			Room 40 Restroom						
			Room 41 Restroom						
			Room 50 Restroom						
			Room 51 Restroom						
			Boy's Restroom 3						
			Girl's Restroom 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 60 Restroom						
			Room 61 Restroom						
			Corridor 5						
M-GRT-25	M	Grout, Gray, Cementitious	Nurse Restroom	Assumed	NF	G	400	SF	09/29/21
			Staff Men's Restroom						
			Staff Women's Restroom						
			Special Ed Restroom						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Room 10 Restroom						
			Room 11 Restroom						
			Room 20 Restroom						
			Room 21 Restroom						
			Room 30 Restroom						
			Room 31 Restroom						
			Room 40 Restroom						
			Room 41 Restroom						
			Room 50 Restroom						
			Room 51 Restroom						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Room 60 Restroom						
			Room 61 Restroom						
			Corridor 5						
M-PSL-34	M	Pipe Sealant (Fire Riser), Blue, Pliable	Riser Room	Assumed	NF	G	2	SF	09/29/21
M-ADH-36	M	Adhesive (FRP), Brown, Brittle	Custodial Office	Assumed	NF	G	20	SF	09/29/21
M-QPT-37	M	Quarry/Paver Tile, 12"X12", Gray, Smooth, White Specks	Custodial Office	Assumed	NF	G	75	SF	09/29/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GRT-38	M	Grout, Gray, Cementitious	Custodial Office	Assumed	NF	G	8	SF	09/29/21
M-CON-39	M	Concrete (Equipment Pad), Gray, Cementitious	Custodial Office	Assumed	NF	G	10	SF	09/29/21
M-GAS-48	M	Gasket, 10", Black, Vinyl-Like	Exterior	Assumed	NF	G	4	SF	09/29/21
M-GWT-53	M	Glazed Wall Tile, 4"X6", Gray, Smooth, Black And White Specks	Kitchen	Assumed	NF	G	40	SF	09/29/21
M-GRT-54	M	Grout, Gray, Cementitious	Kitchen	Assumed	NF	G	4	SF	09/29/21
M-QPT-55	M	Quarry/Paver Tile, 12"X12", Gray, Smooth, Black And White Specks	Kitchen	Assumed	NF	G	750	SF	09/29/21
M-GRT-56	M	Grout, Gray, Cementitious	Kitchen	Assumed	NF	G	75	SF	09/29/21
S-SAT-70	S	Spray-Applied Texture, White, Chalky	Corridor 1	Assumed	NF	G	8,500	SF	09/29/21
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
			Corridor 8						
			Corridor 9						
			Corridor 10						
M-GWB-71	M	Gypsum Wallboard, White, Chalky	Corridor 1	Assumed	NF	G	8,500	SF	09/29/21
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 7						
			Corridor 8						
			Corridor 9						
			Corridor 10						
S-JTC-72	S	Joint Compound, White, Chalky	Corridor 1	Assumed	NF	G	850	SF	09/29/21
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
			Corridor 8						
			Corridor 9						
			Corridor 10						
M-BUR-74	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	82,000	SF	09/29/21
M-MAS-75	M	Mastic (Penetrations And Flashings), Black, Tar-Like	Roof	Assumed	NF	G	5,000	SF	09/29/21
M-SLT-76	M	Sealant (Windows, Flashing), White, Pliable	Roof	Assumed	NF	G	1,000	SF	09/29/21
M-SLT-77	M	Sealant (Skylights), Black, Brittle	Roof	Assumed	NF	G	10	SF	09/29/21
M-SLT-78	M	Sealant (Flashings), Black, Tar- Like	Roof	Assumed	NF	G	10	SF	09/29/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-SLT-79	M	Sealant (Parapet), Cream, Pliable	Roof	Assumed	NF	G	10	SF	09/29/21
M-BUR-94	M	Built-Up Roofing, Black, Asphaltic, White Coating	Roof	Assumed	NF	G	600	SF	09/29/21
M-FDI-100	M	Fire Door Insulation, Wood/Metal Cladding	Storage 10	Assumed	NF	G	168	SF	09/29/21
			Corridor 11						
			Music Room						
			Exterior						

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMU-01	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious, Smooth	Exterior	Assumed	NF	G	350	SF	09/29/21
M-CMU-02	M	Concrete Masonry Unit (Pattern), 8"X16", Gray, Cementitious, Rough	Exterior	Assumed	NF	G	40	SF	09/29/21
M-CMU-03	M	Concrete Masonry Unit (Pattern), 4"X16", Gray, Cementitious, Rough	Exterior	Assumed	NF	G	10	SF	09/29/21
M-MRT-04	M	Mortar, Gray, Cementitious	Exterior	Assumed	NF	G	40	SF	09/29/21
M-CON-05	M	Concrete (Foundation), Gray, Cementitious	Storage	Assumed	NF	G	100	SF	09/29/21
M-SLT-06	M	Sealant (Doors), White, Pliable	Storage	Assumed	NF	G	4	SF	09/29/21
M-BUR-07	M	Built-Up Roofing, Black, Asphaltic, Tan Mineral Cap	Roof	Assumed	NF	G	100	SF	09/29/21
M-MAS-08	M	Mastic (Flashings), Black, Tar-Like	Roof	Assumed	NF	G	10	SF	09/29/21
M-SLT-09	M	Sealant (Flashings), White, Pliable	Roof	Assumed	NF	G	10	SF	09/29/21



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbin Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 43801260123K9 Signature of Inspector: Corbin Hall

*Material Reinspected: M-PSL-15, Pipe End Sealant (Fire Sprinklers), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4380 1254 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-16, Fire Door Insulation, Wood/Metal Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\16.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 430120110169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-20, Glazed Wall Tile, 4"X4", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\20.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4300 120012000 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-21, Glazed Wall Tile (Pattern), 4"X4", Gray, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\21.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/22/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 437012001123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-22, Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\22.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 43701201123104 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GRT-23, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\23.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Conby's Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4350 12701 62169 Signature of Inspector: Conby's Hall

*Material Reinspected: M-CMT-24, Ceramic Mosaic Tile, 2"X2", Gray, Smooth, White Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\24.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Cerbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4381250123169 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-GRT-25, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\25.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 43801252123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PSL-34, Pipe Sealant (Fire Riser), Blue, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\34.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4361252123169 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-ADH-36, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ☒ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\36.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4380 12001 12345 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-QPT-37, Quarry/Paver Tile, 12"X12", Gray, Smooth, White Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\37.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 123121 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-38, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\38.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 123102 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CON-39, Concrete (Equipment Pad), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\39.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/24/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main
AHERA certification number: 43701250112346 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GAS-48, Gasket, 10", Black, Vinyl-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\48.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 43801250123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-53, Glazed Wall Tile, 4"X6", Gray, Smooth, Black and White Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\53.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4380126012344 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GRT-54, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\54.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4380125012314 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-QPT-55, Quarry/Paver Tile, 12"X12", Gray, Smooth, Black and White Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\55.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4376125612364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-56, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\56.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 43801256123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-SAT-70, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\70.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Caryn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 43801250112364 Signature of Inspector: Caryn Hall

*Material Reinspected: M-GWB-71, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\71.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4380123012345 Signature of Inspector: Carbyn Hall

*Material Reinspected: S-JTC-72, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: ① Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\72.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4380125112364 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-BUR-74, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High _____ Medium _____ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\74.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 4380125012364 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-MAS-75, Mastic (Penetrations and Flashings), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High _____ Medium _____ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\75.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 43821250123064 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-76, Sealant (Windows, Flashing), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High _____ Medium _____ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\76.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 438012612369 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-77, Sealant (Skylights), Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes ☐ No ☒
Evidence of Water Damage: _____ Yes ☐ No ☒
Evidence of Delamination or Other Damage: _____ Yes ☐ No ☒
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes ☐ No ☒
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes ☐ No ☒

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes ☐ No ☒
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\77.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 438012511234 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-78, Sealant (Flashings), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High _____ Medium _____ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\78.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 438125112314 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-79, Sealant (Parapet), Cream, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc. 3

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\79.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main
AHRA certification number: 43801202112349 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-BUR-94, Built-Up Roofing, Black, Asphaltic, White Coating

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\94.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Brisas Elementary School Building Name/Number: Main

AHERA certification number: 43812541234 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-100, Fire Door Insulation, Wood/Metal Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Main\100.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Storage

AHERA certification number: 4380125412316 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CMU-01, Concrete Masonry Unit, 8"X16", Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Stor\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Storage

AHERA certification number: 43001250112364 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CMU-02, Concrete Masonry Unit (Pattern), 8"X16", Gray, Cementitious, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Stor\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Storage

AHERA certification number: 438012812564 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CMU-03, Concrete Masonry Unit (Pattern), 4"X16", Gray, Cementitious, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Stor\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Corey Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Storage
AHERA certification number: 43801252112316 Signature of Inspector: Corey Hall

*Material Reinspected: M-MRT-04, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc. ☒

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Stor\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/24/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Storage

AHERA certification number: 43881256123169 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-CON-05, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Stor\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Storage

AHERA certification number: 4380125712216 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-SLT-06, Sealant (Doors), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Stor\06.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Storage

AHERA certification number: 43801251234 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-BUR-07, Built-Up Roofing, Black, Asphaltic, Tan Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Stor\07.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/29/21 Person performing reinspection: Carbony Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Storage
AHRA certification number: 4350125012314 Signature of Inspector: Carbony Hall

*Material Reinspected: M-MAS-08, Mastic (Flashings), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Stor\08.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/29/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Brisas Elementary School Building Name/Number: Storage
AHERA certification number: 43801292123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-09, Sealant (Flashings), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Brisas\Forms\Stor\09.doc