

November 5, 2021

Mr. Mike Williams
Facilities Supervisor
Kyrene School District No. 28
8700 South Kyrene Road
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection
Asbestos-Containing Building Materials
Kyrene de los Cerritos Elementary School
14620 South Desert Foothills Parkway, Phoenix
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: M-GAS-35 could not be found in Main Building.

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC



Michael Hall
Environmental Division Manager

Attachments: *3-Year Reinspection Table*
3-Year Reinspection Forms

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-FDI-17	M	Fire Door Insulation, Wood/Metal Cladding	Office	Assumed	NF	G	2,793	SF	09/16/21
			Assistant Principal						
			Storage 01						
			Conference Room						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Principal						
			Receiving						
			Books						
			Storage 02						
			Mail						
			Medical						
			Electrical 2						
			Psychology						
			Special Ed 01						
			S.E. To						
			Special Ed 02						
			Special Ed 03						
			Electrical 3						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Storage 03						
			Speech						
			Kindergarten 01						
			Classroom 31						
			Classroom 32						
			Classroom 33						
			Classroom 35						
			Classroom 36						
			Multi-Purpose						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Stage						
			East Wing						
			Music 2						
			Kitchen						
			Electrical 4						
			Service Yard						
			P.E. Storage						
			P.E. Office						
			Storage 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Classroom 41						
			Classroom 42						
			Classroom 43						
			Classroom 44						
			Classroom 45						
			Classroom 46						
			Classroom 51						
			Classroom 52						
			Classroom 53						
			Kindergarten 02						
			Classroom 55						
			Classroom 56						
			Music 01						
			Storage 04						
			Art						
			Art Storage						
			Kiln						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Classroom 61						
			Classroom 62						
			Classroom 63						
			Classroom 64						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 65						
			Classroom 66						
			Classroom 71						
			Classroom 72						
			Classroom 73						
			Classroom 74						
			Classroom 75						
			Classroom 76						
			Electrical 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Janitor						
			Desk Storage						
			Classroom 81						
			Classroom 82						
			Classroom 83						
			Preschool 84						
			Classroom 85						
			Classroom 86						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
			Corridor 8						
			Corridor 9						
			Corridor 10						
			Corridor 11						
			Corridor 12						
			Exterior						
M-PSL-23	M	Pipe Sealant (Fire Sprinklers), Blue, Pliable	Office	Assumed	NF	G	50	SF	09/16/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Assistant Principal						
			Assistant Principal Closet						
			Storage 01						
			Conference Room						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Principal						
			Principal Closet						
			Receiving						
			Receiving Closet						
			Books						
			Storage 02						
			Mail						
			Cot						
			Cot Restroom						
			Medical						
			Nurse						
			Test						
			Electrical 2						
			Psychology						
			Special Ed 01						
			S.E. Storage						
			S.E. To						
			S.E. Restroom						
			Special Ed 02						
			Special Ed 03						
			Electrical 3						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Storage 03						
			Speech						
			Kindergarten 01						
			Kindergarten Restroom 1						
			Kindergarten To						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 31						
			Classroom 32						
			Classroom 33						
			Classroom 35						
			Classroom 36						
			Work Room 2						
			Multi-Purpose						
			Stage						
			East Wing						
			West Wing						
			Music 2						
			Music Storage						
			Chair Storage						
			Kitchen						
			Electrical						
			Service Yard						
			Water Heater						
			P.E. Storage						
			P.E. Office						
			Storage 5						
			Storage 6						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Classroom 41						
			Classroom 42						
			Classroom 43						
			Classroom 44						
			Classroom 45						
			Classroom 46						
			Work Room 6						
			Classroom 51						
			Classroom 52						
			Classroom 53						
			Kindergarten 02						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Kindergarten Restroom 2						
			Classroom 55						
			Classroom 56						
			Work Room 5						
			Music 01						
			Storage 04						
			Art						
			Art Storage						
			Kiln						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Classroom 61						
			Classroom 62						
			Classroom 63						
			Classroom 64						
			Classroom 65						
			Classroom 66						
			Work Room 4						
			Classroom 71						
			Classroom 72						
			Classroom 73						
			Classroom 74						
			Classroom 74 Restroom						
			Classroom 75						
			Classroom 76						
			Work Room 3						
			Electrical 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Janitor						
			Desk Storage						
			Classroom 81						
			Classroom 82						
			Classroom 83						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 83 Tlt						
			Preschool 84 Tlt						
			Preschool 84						
			Classroom 85						
			Classroom 86						
			Work Room 1						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
			Corridor 8						
			Corridor 9						
			Corridor 10						
			Corridor 11						
			Corridor 12						
M-GWT-24	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Boy's Restroom 2	Assumed	NF	G	9,000	SF	09/16/21
			Girl's Restroom 2						
			Cot Restroom						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Boy's Restroom 1						
			Girl's Restroom 1						
M-GWT-25	M	Glazed Wall Tile (Pattern), 4"X4", Gray, Smooth	Boy's Restroom 2	Assumed	NF	G	500	SF	09/16/21
			Girl's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Cot Restroom						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Boy's Restroom 1						
			Girl's Restroom 1						
M-GWT-26	M	Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth	Boy's Restroom 2	Assumed	NF	G	500	SF	09/16/21
			Girl's Restroom 2						
			Cot Restroom						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Boy's Restroom 1						
			Girl's Restroom 1						
M-GRT-27	M	Grout, White, Cementitious	Boy's Restroom 2	Assumed	NF	G	1,000	SF	09/16/21
			Girl's Restroom 2						
			Cot Restroom						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Boy's Restroom 1						
			Girl's Restroom 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMT-28	M	Ceramic Mosaic Tile, 2"X2", Gray, Smooth, White Specks	Cot Restroom	Assumed	NF	G	200	SF	09/16/21
M-CMT-29	M	Ceramic Mosaic Tile (Pattern), 2"X2", Gray, Smooth	Cot Restroom	Assumed	NF	G	20	SF	09/16/21
M-CMT-30	M	Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth	Cot Restroom	Assumed	NF	G	20	SF	09/16/21
M-GRT-31	M	Grout, Gray, Cementitious	Cot Restroom	Assumed	NF	G	20	SF	09/16/21
M-GAS-35	M	Gasket, 6"-8", Black, Vinyl-Like	Storage 01	Assumed	NF	G	2	SF	09/16/21
M-PES-46	M	Pipe End Sealant, Gray, Pliable	Music Storage	Assumed	NF	G	2	SF	09/16/21
M-ADH-50	M	Adhesive (FRP), Brown, Brittle	Kitchen	Assumed	NF	G	200	SF	09/16/21
M-QPT-51	M	Quarry/Paver Tile, 12"X12", Gray, Smooth, White Specks	Kitchen	Assumed	NF	G	1,500	SF	09/16/21
M-GRT-52	M	Grout, Gray, Cementitious	Kitchen	Assumed	NF	G	150	SF	09/16/21
M-SLT-58	M	Sealant (Fire Stop), Red, Pliable	Electrical 4	Assumed	NF	G	200	SF	09/16/21
M-BUR-59	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	80,000	SF	09/16/21
M-MAS-60	M	Mastic (Penetrations and Flashings), Black, Tar-Like	Roof	Assumed	NF	G	2,000	SF	09/16/21

3-YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-APR-01	M	Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Tan Mineral Cap	Roof	Assumed	NF	G	400	SF	09/16/21
M-VBF-02	M	Vapor Barrier Felt, Black, Asphaltic	Roof	Assumed	NF	G	400	SF	09/16/21

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Cerritos\Stor2-Tbl.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main
AHERA certification number: 4380 12501 123/29 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-17, Fire Door Insulation, Wood/Metal Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: 4380-12501-123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PSL-23, Pipe Sealant (Fire Sprinklers), Blue, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.
G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Cerritos\FORMS\Main\23.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: _____ Person performing reinspection: _____

Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: _____ Signature of Inspector: _____

*Material Reinspected: M-GWT-24, Glazed Wall Tile, 4"X4", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No

Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No

Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____

Degree of Activity Near the Material: High Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main
AHERA certification number: 4396 12501 123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-25, Glazed Wall Tile (Pattern), 4"X4", Gray, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: 4380 1252 123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-26, Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: 4390 1201 1236 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GRT-27, Grout, White, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: 438012501123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CMT-28, Ceramic Mosaic Tile, 2"X2", Gray, Smooth, White Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: 4380 1281 123109 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-CMT-29, Ceramic Mosaic Tile (Pattern), 2"X2", Gray, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. (Misc.)

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: 4380 1252 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CMT-30, Ceramic Mosaic Tile (Pattern), 1"X1", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/15/21 Person performing reinspection: Cordyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 12502 Signature of Inspector: Cordyn Hall

*Material Reinspected: M-GRT-31, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.
G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Cerritos\FORMS\Main\31.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carlynn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: 430126012312 Signature of Inspector: [Signature]

*Material Reinspected: M-GAS-35, Gasket, 6"-8", Black, Vinyl-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI Misc.

Material Status: 1. In-Place _____ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: 438012501123164 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-PES-46, Pipe End Sealant, Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main
AHERA certification number: 4380 12501 128169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-ADH-50, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High _____ Medium Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/12 Person performing reinspection: Carbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: 49043801250183169 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-QPT-51, Quarry/Paver Tile, 12"X12", Gray, Smooth, White Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.
G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Cerritos\Forms\Main\51.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbin Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main
AHERA certification number: 4380 12501 123169 Signature of Inspector: Corbin Hall

*Material Reinspected: M-GRT-52, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Carson Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: 4350 1050 123169 Signature of Inspector: Carson Hall

*Material Reinspected: M-SLT-58, Sealant (Fire Stop), Red, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main
AHERA certification number: 4390 12501 18.31.21 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-BUR-59, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.
G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Cerritos\FORMS>Main\59.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Main

AHERA certification number: 4380 18501 123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MAS-60, Mastic (Penetrations and Flashings), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/16/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Storage 2

AHERA certification number: 438012501/23169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-VBF-02, Vapor Barrier Felt, Black, Asphaltic

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/17/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de los Cerritos Elementary School Building Name/Number: Storage 2

AHERA certification number: 4380-12501-12³¹⁶⁹ Signature of Inspector: Corbyn Hall

*Material Reinspected: M-APR-01, Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Tan Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.