

November 5, 2021

Mr. Mike Williams
Facilities Supervisor
Kyrene School District No. 28
8700 South Kyrene Road
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection
Asbestos-Containing Building Materials
Kyrene de la Colina Elementary School
13612 South 36th Street, Phoenix
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

**Items of significance are: M-MAS-69, M-PNT-73, M-BUR-74 could not be found in Main Building.
M-APR-01, M-VBF-02 could not be found in Storage.**

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC



Michael Hall
Environmental Division Manager

*Attachments: 3-Year Reinspection Tables
3-Year Reinspection Forms*

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-MRT-05	M	Mortar (Glass Block), Gray, Cementitious	Reception	Assumed	NF	G	150	SF	09/20/21
			Treatment						
			Nurse Office						
			Faculty Lounge						
			Speech						
			Computer Room 33						
			Special Ed. Room 35						
			Special Ed. Room 36						
			Special Ed. Room 37						
			Kinder Room 10						
			Kinder Room 11						
			1st Grade Room 12						
			1st Grade Room 13						
			2nd Grade Room 14						
			1st Grade Room 15						
			2nd Grade Room 16						
			2nd Grade Room 17						
			3rd Grade Room 18						
			3rd Grade Room 19						
			3rd Grade Room 20						
			Gifted Room 21						
			4th Grade Room 22						
			4th Grade Room 23						
			4th Grade Room 25						
			5th Grade Room 26						
			5th Grade Room 27						
			6th Grade Room 28						
			6th Grade Room 29						
			6th Grade Room 30						
			Art Room 31						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Multi-Purpose						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			North Foyer						
			Corridor 5						
			Corridor 7						
			Corridor 8						
			Corridor 9						
			Foyer South						
			Corridor 12						
			Corridor 14						
			Exterior						
M-ADH-07	M	Adhesive (TWP), Brown, Brittle	Reception	Assumed	NF	G	2,750	SF	09/20/21
			School Office						
			Principal						
			Faculty Lounge						
			Speech						
			Library						
			Computer Room 33						
			Special Ed. Room 35						
			Special Ed. Office						
			Special Ed. Room 36						
			Special Ed. Room 37						
			Kinder Room 10						
			Kinder Room 11						
			1st Grade Room 12						
			1st Grade Room 13						
			2nd Grade Room 14						
			1st Grade Room 15						
			2nd Grade Room 16						
			2nd Grade Room 17						
			3rd Grade Room 18						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			3rd Grade Room 19						
			3rd Grade Room 20						
			Gifted Room 21						
			4th Grade Room 22						
			4th Grade Room 23						
			4th Grade Room 25						
			5th Grade Room 26						
			5th Grade Room 27						
			6th Grade Room 28						
			6th Grade Room 29						
			6th Grade Room 30						
			Art Room 31						
			Music						
M-FDI-13	M	Fire Door Insulation, Metal Cladding	Reception	Assumed	NF	G	819	SF	09/20/21
			Treatment						
			Faculty Lounge						
			West Girl's Foyer						
			West Boy's Restroom						
			Music						
			Multi-Purpose						
			Kitchen						
			Kinder Room 11						
			Kinder Room 10						
			North Boy's Restroom						
			North Girl's Foyer						
			Art Room 31						
			Corridor 12						
			Corridor 10						
			Corridor 7						
			Corridor 6						
			Corridor 5						
			Corridor 3						
			Corridor 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 2						
			Exterior						
M-FDI-14	M	Fire Door Insulation, Wood Cladding	Reception	Assumed	NF	G	1,344	SF	09/20/21
			Storage 1						
			East Foyer						
			Faculty Lounge						
			Hall 1						
			Hall 2						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Storage 2						
			Speech						
			Library Workroom						
			Computer Room 33						
			A/V						
			Janitor						
			Special Ed. Room 35						
			Special Ed. Room 36						
			Special Ed. Room 37						
			West Boy's Restroom						
			West Girl's Foyer						
			West Girl's Restroom						
			Hall 4						
			Kinder Room 10						
			Kinder Room 11						
			1st Grade Room 12						
			1st Grade Room 13						
			2nd Grade Room 14						
			1st Grade Room 15						
			2nd Grade Room 16						
			2nd Grade Room 17						
			3rd Grade Room 19						
			North Boy's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Hall 3						
			North Girl's Foyer						
			North Girl's Restroom						
			3rd Grade Room 18						
			3rd Grade Room 20						
			Gifted Room 21						
			4th Grade Room 22						
			4th Grade Room 23						
			5th Grade Room 24						
			4th Grade Room 25						
			5th Grade Room 26						
			5th Grade Room 27						
			6th Grade Room 28						
			6th Grade Room 29						
			6th Grade Room 30						
			Art Room 31						
			Music						
			Music Storage						
			Multi-Purpose						
			Multi-Purpose Storage						
			West Water/Heater Closet						
			P.E. Storage						
			Kitchen						
			South Boy's Restroom						
			South Girl's Restroom						
			Corridor						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			North Foyer						
			Corridor 5						
			Corridor 6						
			Corridor 7						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 8						
			Corridor 9						
			Foyer South						
			Corridor 10						
			Corridor 11						
			Corridor 12						
			Corridor 14						
M-PES-18	M	Pipe End Sealant, White, Brittle	Reception	Assumed	NF	G	200	SF	09/20/21
			School Office						
			Treatment						
			Nurse Office						
			Nurse Restroom						
			Hearing						
			Storage 1						
			East Foyer						
			Principal						
			Principal's Closet						
			Assistant Principal						
			Work Room						
			Faculty Lounge						
			Phone Room						
			Hall 1						
			Hall 2						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Storage 2						
			Speech						
			Library						
			Library Workroom						
			Computer Room 33						
			A/V						
			Janitor						
			Electrical						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Special Ed. Room 35						
			Special Ed. Office						
			Special Ed. Room 36						
			Special Ed. Room 37						
			Timeout						
			West Boy's Restroom						
			West Girl's Foyer						
			West Girl's Restroom						
			Hall 4						
			Kinder Room 10						
			Kinder Room 10 Toilet						
			Kinder Room 11						
			Kinder Room 11 Toilet						
			1 st Grade Room 12						
			1 st Grade Room 13						
			2 nd Grade Room 14						
			1 st Grade Room 15						
			North Boy's Restroom						
			North Girl's Foyer						
			North Girl's Restroom						
			Hall 3						
			North Water Heater Closet						
			2 nd Grade Room 16						
			2 nd Grade Room 17						
			3 rd Grade Room 18						
			3 rd Grade Room 19						
			3 rd Grade Room 20						
			Gifted Room 21						
			4 th Grade Room 22						
			4 th Grade Room 23						
			5 th Grade Room 24						
			4 th Grade Room 25						
			5 th Grade Room 26						
			5 th Grade Room 27						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			6 th Grade Room 28						
			6 th Grade Room 29						
			6 th Grade Room 30						
			Art Room 31						
			Music						
			Music Storage						
			Stage						
			East Wing						
			West Wing						
			Multi-Purpose						
			Multi-Purpose Storage						
			West Water Heater Closet						
			P.E. Storage						
			P.E. Office						
			Kitchen						
			South Boy's Restroom						
			South Girl's Restroom						
			Corridor						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			North Foyer						
			Corridor 5						
			Corridor 6						
			Corridor 7						
			Corridor 8						
			Corridor 9						
			Foyer South						
			Corridor 10						
			Corridor 11						
			Corridor 12						
			Corridor 14						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-SAC-20	M	Sink Acoustical Coating, Gray, Rough	East Foyer	Assumed	NF	G	275	SF	09/20/21
			Faculty Lounge						
			Speech						
			Library Workroom						
			Computer Room 33						
			Special Ed. Room 35						
			Special Ed. Room 36						
			Special Ed. Room 37						
			Music						
			Kinder Room 10						
			Kinder Room 11						
			1st Grade Room 12						
			1st Grade Room 13						
			2nd Grade Room 14						
			1st Grade Room 15						
			2nd Grade Room 16						
			2nd Grade Room 17						
			3rd Grade Room 18						
			3rd Grade Room 19						
			3rd Grade Room 20						
			Gifted Room 21						
			4th Grade Room 22						
			4th Grade Room 23						
			5th Grade Room 24						
			4th Grade Room 25						
			5th Grade Room 26						
			5th Grade Room 27						
			6th Grade Room 28						
			6th Grade Room 29						
			6th Grade Room 30						
			Art Room 31						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMT-30	M	Ceramic Mosaic Tile, Various Sizes, Red, Smooth, Orange/Blue/Brown/Tan/Yellow/Cream (Pattern)	Faculty Lounge	Assumed	NF	G	5	SF	09/20/21
M-GRT-37	M	Grout, Gray, Cementitious	Faculty Lounge	Assumed	NF	G	4	SF	09/20/21
M-BRK-40	M	Brick, 3"X16", Red, Cementitious	Library	Assumed	NF	G	40,000	SF	09/20/21
			East Wing						
			Multi-Purpose						
			Multi-Purpose Storage						
			P.E. Storage						
			P.E. Office						
			Corridor						
			Corridor 4						
			Corridor 7						
			Corridor 8						
			Corridor 11						
			Equipment Pit						
			East Courtyard						
			South Courtyard						
			Exterior						
M-MRT-41	M	Mortar, Gray, Cementitious	Library	Assumed	NF	G	4,000	SF	09/20/21
			East Wing						
			Multi-Purpose						
			Multi-Purpose Storage						
			P.E. Storage						
			P.E. Office						
			Corridor						
			Corridor 4						
			Corridor 7						
			Corridor 8						
			Corridor 11						
			Equipment Pit						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			East Courtyard						
			South Courtyard						
			Exterior						
M-ADH-45	M	Adhesive (FRP), Brown, Brittle	Janitor	Assumed	NF	G	20	SF	09/20/21
M-GWT-46	M	Glazed Wall Tile, 4"X6", Brown, Smooth	West Boy's Restroom	Assumed	NF	G	5,000	SF	09/20/21
			West Girl's Foyer						
			West Girl's Restroom						
			North Boy's Restroom						
			North Girl's Foyer						
			North Girl's Restroom						
			South Boy's Restroom						
			South Girl's Restroom						
M-GRT-47	M	Grout, Gray, Cementitious	West Boy's Restroom	Assumed	NF	G	500	SF	09/20/21
			West Girl's Foyer						
			West Girl's Restroom						
			North Boy's Restroom						
			North Girl's Foyer						
			North Girl's Restroom						
			South Boy's Restroom						
			South Girl's Restroom						
M-CMT-48	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth, Peppered	West Boy's Restroom	Assumed	NF	G	2,500	SF	09/20/21
			West Girl's Foyer						
			West Girl's Restroom						
			North Boy's Restroom						
			North Girl's Foyer						
			North Girl's Restroom						
			South Boy's Restroom						
			South Girl's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M·GRT·49	M	Grout, Gray, Cementitious	West Boy's Restroom	Assumed	NF	G	250	SF	09/20/21
			West Girl's Foyer						
			West Girl's Restroom						
			North Boy's Restroom						
			North Girl's Foyer						
			North Girl's Restroom						
			South Boy's Restroom						
			South Girl's Restroom						
M·VST·52	M	Stair Tread, 12"X72", Vinyl-Like, Circle Pattern	East Wing	Assumed	NF	G	50	SF	09/20/21
			West Wing						
M·MAS·53	M	Mastic, Yellow, Tacky	East Wing	Assumed	NF	G	50	SF	09/20/21
			West Wing						
M·ADH·63	M	Adhesive (GWT), Yellow, Brittle	West Boy's Restroom	Assumed	NF	G	5,000	SF	09/20/21
			West Girl's Foyer						
			West Girl's Restroom						
			North Boy's Restroom						
			North Girl's Foyer						
			North Girl's Restroom						
			South Boy's Restroom						
			South Girl's Restroom						
M·EXJ·66	M	Expansion Joint, Brown, Fibrous	Exterior	Assumed	NF	G	1,250	SF	09/20/21
M·GAS·67	M	Gasket, 8", Gray, Paper-Like	Equipment Pit	Assumed	NF	G	30	SF	09/20/21
M·MAS·69	M	Mastic (Penetrations and Flashings), Black, Tar-Like	Main Roof	Assumed	NF	G	1,000	SF	09/20/21
M·PNT·73	M	Paint (Penetrations and Flashings), Silver, Brittle, White, Pliable	Main Roof	Assumed	NF	G	1,000	SF	09/20/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-74	M	Built-Up Roofing, Black, Asphaltic, Gray Gravel Cap	Main Roof	Assumed	NF	G	57,000	SF	09/20/21
M-APR-75	M	Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Brown Mineral Cap	Main Roof	Assumed	NF	G	1,500	SF	09/20/21
M-CON-76	M	Concrete, Gray, Cementitious	Exterior	Assumed	NF	G	25,000	SF	09/20/21
M-FDI-124	M	Fire Door Insulation, Metal/Wood Cladding	A1 Girl's Restroom	Assumed	NF	G	630	SF	09/20/21
			A1 Boy's Restroom						
			Room A1 38						
			Room A1 39						
			Room A1 40						
			Room A1 41						
			Room A1 42						
			Room A1 43						
			Room A1 44						
			Room A1 45						
			Room A1 46						
			A1 Corridor 16						
			A1 Corridor 17						
			Room A2 47						
			Room A2 48						
			Room A2 49						
			Room A2 50						
			A2 Corridor 14						
			A2 Corridor 15						
			Exterior						

3-YEAR REINSPECTION TABLE IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-APR-01	M	Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Brown Mineral Cap	Roof	Assumed	NF	G	120	SF	09/20/2021
M-VBF-02	M	Vapor Barrier Felt, Black, Asphaltic	Roof	Assumed	NF	G	120	SF	09/20/2021

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Colina\Stor-Tbl.doc

3-YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Colina\43,45-Tbl.doc

3-YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Colina\44,46-Tbl.doc

3-YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Colina\47,49-Tbl.doc

3-YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Colina\48,50-Tbl.doc

3-YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Colina\51,53-Tbl.doc

3-YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Colina\52,54-Tbl.doc

3-YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Colina\60,61-Tbl.doc

3-YEAR REINSPECTION TABLE
IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		BUILDING HAS BEEN REMOVED FROM SITE.							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Colina\62-Tbl.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4370 1251 1236A Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MRT-05, Mortar (Glass Block), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carly Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4370 061 1234 Signature of Inspector: Carly Hall

*Material Reinspected: M-ADH-07, Adhesive (TWP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Corbyn Han
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 1301281234 Signature of Inspector: Corbyn Han

*Material Reinspected: M-FDI-13, Fire Door Insulation, Metal Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/24 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4304211214 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-FDI-14, Fire Door Insulation, Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/26/24 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 437026123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PES-18, Pipe End Sealant, White, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carlyn Hill
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 43701850112316 Signature of Inspector: Carlyn Hill

*Material Reinspected: M-SAC-20, Sink Acoustical Coating, Gray, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/24 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4370 12001 12344 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CMT-30, Ceramic Mosaic Tile, Various Sizes, Red, Smooth, Orange/Blue/Brown/Tan/Yellow/Cream (Pattern)

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / NO
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / NO
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / NO
Evidence of Water Damage: _____ Yes / NO
Evidence of Delamination or Other Damage: _____ Yes / NO
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / NO
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / NO

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / NO
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 437012512314 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GRT-37, GROUT, GRAY, CEMENTITIOUS

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No
Evidence of Water Damage: _____ Yes No
Evidence of Delamination or Other Damage: _____ Yes No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/24 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4370 1561 1564 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-BRK-40, Brick, 3"X16", Red, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Corbyn Han
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 439125d 034 Signature of Inspector: Corbyn Hale

*Material Reinspected: M-MRT-41, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4360 1250 1226 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-ADH-45, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Corbyn Han
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 43012011211 Signature of Inspector: Corbyn Han

*Material Reinspected: M-GWT-46, Glazed Wall Tile, 4"X6", Brown, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4376 12501 43169 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GRT-47, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Corbyn Hunt

Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4350 1201 123164 Signature of Inspector: Emman Peelle

*Material Reinspected: M-CMT-48, Ceramic Mosaic Tile, 2"X2", Tan, Smooth, Peppered

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 123114 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-49, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Corbyn Hull
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4370 1202 12314 Signature of Inspector: Corbyn Hull

*Material Reinspected: M-VST-52, Stair Tread, 12"X72", Vinyl-Like, Circle Pattern

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carlynn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4300 1261 12364 Signature of Inspector: Carlynn Hall

*Material Reinspected: M-MAS-53, Mastic, Yellow, Tacky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carbyn Han
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4370 1201 03164 Signature of Inspector: Carbyn Han

*Material Reinspected: M-ADH-63, Adhesive (GWT), Yellow, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4370 1250 1234 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-EXJ-66, Expansion Joint, Brown, Fibrous

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/24 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 43001250121864 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GAS-67, Gasket, 8", Gray, Paper-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 436126123161 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-MAS-69, Mastic (Penetrations and Flashings), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place _____ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: Installation of new roof

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 430125d123161 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-PNT-73, Paint (Penetrations and Flashings), Silver, Brittle, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place _____ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: Installation of new roof

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 430125012314 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-BUR-74, Built-Up Roofing, Black, Asphaltic, Gray Gravel Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place _____ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: Installation of new roof

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4390 USI 0344 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-APR-75, Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Brown Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place _____ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: Installation of new roof

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4390 1201 1234 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CON-76, Concrete, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Main

AHERA certification number: 4370125d123164 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-FDI-124, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Ceryn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Storage

AHERA certification number: 4370 1250 123164 Signature of Inspector: Ceryn Hall

*Material Reinspected: M-APR-01, Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Brown Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place _____ 2. Did Not Find ✓

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: Insulation of new roof

Material Friability: Has the friability of this material changed since the last inspection? Yes / ND
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/20/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene de la Colina Elementary School Building Name/Number: Storage

AHERA certification number: 4300450112814 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-VBF-02, Vapor Barrier Felt, Black, Asphaltic

Type of Asbestos-Containing Material: 1. Surf. 2. TSI **3** Misc.

Material Status: 1. In-Place _____ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: Installation of new roof

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.