

November 2, 2021

Mr. Mike Williams
Facilities Supervisor
Kyrene School District No. 28
8700 South Kyrene Road
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection
Asbestos-Containing Building Materials
Kyrene del Norte Elementary School
1331 East Redfield Road, Tempe
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: None.

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC

A handwritten signature in blue ink, appearing to read "Michael", is positioned above the printed name.

Michael
Environmental Division Manager

Attachments: *3-Year Reinspection Tables*
3-Year Reinspection Forms

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gravel Cap	Roof	Assumed	NF	G	80,000	SF	09/27/21
M-MAS-02	M	Mastic (Penetrations and Flashings), Black, Tar-Like	Roof	Assumed	NF	G	8,000	SF	09/27/21
M-SLT-03	M	Sealant (Clear Story Windows), Black, Brittle	Roof	Assumed	NF	G	15	SF	09/27/21
M-SLT-04	M	Sealant (Clear Story Windows), Black, Tar-Like	Roof	Assumed	NF	G	10	SF	09/27/21
M-SLT-05	M	Sealant (Clear Story Windows), Gray, Brittle	Roof	Assumed	NF	G	10	SF	09/27/21
M-SLT-12	M	Sealant (Duct), White, Pliable	Roof	Assumed	NF	G	25	SF	09/27/21
M-SLT-13	M	Sealant (Duct), Black, Tar-Like	Roof	Assumed	NF	G	25	SF	09/27/21
M-SLT-28	M	Sealant (Windows), Black, Gummy	Room D1	Assumed	NF	G	20	SF	09/27/21
			Room D2						
			Room D3						
			Room D4						
			Room D5						
			Room D6						
			Room E1						
			Room E2						
			Room E3						
			Room E4						
			Room G1						
			Room G2						
			Room G3						
			Room G4						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room G5						
			Room G6						
M-SAC-29	M	Sink Acoustical Coating, Gray, Rough	Room B1	Assumed	NF	G	44	SF	09/27/21
			Room B2						
			Room B3						
			Room B4						
			Room B6						
			Room D1						
			Room D2						
			Room D3						
			Room D4						
			Room D5						
			Room D6						
			Room E1						
			Room E2						
			Room E3						
			Room E4						
			Room G1						
			Room G2						
			Room G3						
			Room G4						
			Room G5						
			Room G6						
M-FDI-30	M	Fire Door Insulation, Wood/Metal Cladding	Electrical 1	Assumed	NF	G	2,856	SF	09/27/21
			Room US4						
			Room US3						
			Office						
			Conference						
			Health TO						
			Hall 2						
			Room B2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room B3						
			Room B4						
			Room B5						
			Room C4						
			Room C5						
			Room D1						
			Room D4						
			Room D5						
			Room D6						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Mechanical						
			Room E1						
			Room E4						
			Room E5						
			Room E6						
			Room F1						
			Room F2						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Music						
			Art						
			North Wing						
			P.E. Storage						
			Kitchen						
			Electrical 4						
			Water Heater						
			Can Wash						
			Table Storage						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Multi-Purpose						
			Electrical 3						
			Boy's Restroom 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 3						
			Janitor Closet						
			Room G1						
			Room G2						
			Room G3						
			Room G4						
			Room G5						
			Room G6						
			Library						
			Computer Lab						
			Room H1						
			Room H1 TO						
			Electrical 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Lounge						
			Book Room						
			H Work Room						
			Room US1						
			Room US2						
			Hall 1						
			Speech						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
			Custodial						
			Social Worker						
M-SAC-31	M	Sink Acoustical Coating, White, Rough	Room A1	Assumed	NF	G	50	SF	09/27/21
			Room A2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room B5						
			Room C1						
			Room C2						
			Room C3						
			Room C4						
			Room C5						
			Room C6						
			Room E5						
			Room E6						
			Room F1						
			Room F2						
			Music						
			Art						
			Room H1						
			Room H2						
			Lounge						
			Speech						
			Social Worker						
M-GWT-44	M	Glazed Wall Tile, 2"X2", Tan, Smooth	Room A1 Restroom	Assumed	NF	G	1,500	SF	09/27/21
			Room A2 Restroom						
			Room E6 Restroom						
			Boy's Restroom 5						
			Girl's Restroom 5						
M-GWT-45	M	Glazed Wall Tile (Pattern), 2"X2", Blue, Smooth, White Specks	Room A1 Restroom	Assumed	NF	G	75	SF	09/27/21
			Room A2 Restroom						
			Room E6 Restroom						
			Boy's Restroom 5						
			Girl's Restroom 5						
M-GRT-46	M	Grout, Gray, Cementitious	Room A1 Restroom	Assumed	NF	G	150	SF	09/27/21
			Room A2 Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room E6 Restroom						
			Boy's Restroom 5						
			Girl's Restroom 5						
M-CMT-49	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth, Peppered	Room B1 Restroom	Assumed	NF	G	100	SF	09/27/21
			Room B6 Restroom						
M-GRT-50	M	Grout, Gray, Cementitious	Room B1 Restroom	Assumed	NF	G	10	SF	09/27/21
			Room B6 Restroom						
M-CON-53	M	Concrete (Foundation), Gray, Cementitious	Administration	Assumed	NF	G	80,000	SF	09/27/21
			Electrical 1						
			Room US4						
			Room US3						
			Office						
			Principal						
			Conference						
			Health TO						
			Health Restroom						
			Conference Closet						
			Hearing						
			Hall 2						
			Health						
			Health Assistant						
			Storage 3						
			Storage 1						
			Room A1						
			Room A1 Restroom						
			Storage 2						
			Room A2						
			Room A2 Restroom						
			Room B1						
			Room B1 Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room B2						
			Room B3						
			B Storage						
			Room B4						
			Room B5						
			Room B5 Restroom						
			Room B6						
			Room B6 Restroom						
			B Work Room						
			Room C1						
			Room C2						
			Room C3						
			Room C4						
			Room C5						
			Room C6						
			C Work Room						
			Room D1						
			Room D2						
			Room D3						
			Room D4						
			Room D5						
			Room D6						
			D Work Room						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Mechanical						
			Room E1						
			Room E2						
			Room E3						
			Room E4						
			Room E5						
			Room E5 TO						
			Room E6						
			Room E6 Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			E Work Room						
			Room F1						
			Room F2						
			F Work Room						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Music						
			Music Office						
			Art						
			North Wing						
			Stage						
			South Wing						
			P.E. Storage						
			P.E. Office						
			Kitchen						
			Electrical 4						
			Water Heater						
			Can Wash						
			Table Storage						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Multi-Purpose						
			Electrical 3						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Janitor Closet						
			Room G1						
			Room G2						
			Room G3						
			Room G4						
			Room G5						
			Room G6						
			G Work Room						
			Library						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Software						
			Communication						
			Library Work Room						
			Computer Lab						
			Room H1						
			Room H1 TO						
			Room H1 Restroom						
			Room H2						
			Room H2 TO						
			Room H2 Restroom						
			Custodial						
			Electrical 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Custodial Office						
			Lounge						
			Phone						
			Book Room						
			H Work Room						
			Room US1						
			Room US2						
			Hall 1						
			Speech						
			Social Worker Office						
			Social Worker						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
			Exterior						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-ADH-54	M	Adhesive (FRP), Brown, Brittle	Custodial	Assumed	NF	G	5	SF	09/27/21
M-PSL-55	M	Pipe End Sealant (Sprinklers), White, Pliable	Administration	Assumed	NF	G	50	SF	09/27/21
			Electrical 1						
			Room US4						
			Room US3						
			Office						
			Principal						
			Conference						
			Health TO						
			Health Restroom						
			Conference Closet						
			Hearing						
			Hall 2						
			Health						
			Health Assistant						
			Storage 3						
			Storage 1						
			Room A1						
			Room A1 Restroom						
			Storage 2						
			Room A2						
			Room A2 Restroom						
			Room B1						
			Room B1 Restroom						
			Room B2						
			Room B3						
			B Storage						
			Room B4						
			Room B5						
			Room B5 Restroom						
			Room B6						
			Room B6 Restroom						
			B Work Room						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room C1						
			Room C2						
			Room C3						
			Room C4						
			Room C5						
			Room C6						
			C Work Room						
			Room D1						
			Room D2						
			Room D3						
			Room D4						
			Room D5						
			Room D6						
			D Work Room						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Mechanical						
			Room E1						
			Room E2						
			Room E3						
			Room E4						
			Room E5						
			Room E5 TO						
			Room E6						
			Room E6 Restroom						
			E Work Room						
			Room F1						
			Room F2						
			F Work Room						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Music						
			Music Office						
			Art						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			North Wing						
			Stage						
			South Wing						
			P.E. Storage						
			P.E. Office						
			Kitchen						
			Electrical 4						
			Water Heater						
			Can Wash						
			Table Storage						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Multi-Purpose						
			Electrical 3						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Janitor Closet						
			Room G1						
			Room G2						
			Room G3						
			Room G4						
			Room G5						
			Room G6						
			G Work Room						
			Library						
			Software						
			Communication						
			Library Work Room						
			Computer Lab						
			Room H1						
			Room H1 TO						
			Room H1 Restroom						
			Room H2						
			Room H2 TO						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room H2 Restroom						
			Custodial						
			Electrical 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Custodial Office						
			Lounge						
			Phone						
			Book Room						
			H Work Room						
			Room US1						
			Room US2						
			Hall 1						
			Speech						
			Social Worker Office						
			Social Worker						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
M-CMT-62	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth	Room E6 Restroom	Assumed	NF	G	2,000	SF	09/27/21
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 3						
			Girl's Restroom 3						
M-CMT-63	M	Ceramic Mosaic Tile (Pattern), 2"X2", Blue, Smooth, White Specks	Room E6 Restroom	Assumed	NF	G	100	SF	09/27/21
			Boy's Restroom 5						
			Girl's Restroom 5						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 3						
			Girl's Restroom 3						
M-GRT-64	M	Grout, Gray, Cementitious	Room E6 Restroom	Assumed	NF	G	200	SF	09/27/21
			Boy's Restroom 5						
			Girl's Restroom 5						
			Boy's Restroom 3						
			Girl's Restroom 3						
M-ADH-77	M	Adhesive (FRP), Brown, Brittle	Music	Assumed	NF	G	40	SF	09/27/21
M-CMU-78	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	North Wing	Assumed	NF	G	3,000	SF	09/27/21
			South Wing						
			P.E. Storage						
			P.E. Office						
			Table Storage						
			Water Heater						
			Electrical 3						
			Janitor Closet						
			Multi-Purpose						
M-MRT-79	M	Mortar, Gray, Cementitious	North Wing	Assumed	NF	G	300	SF	09/27/21
			South Wing						
			P.E. Storage						
			P.E. Office						
			Table Storage						
			Water Heater						
			Electrical 3						
			Janitor Closet						
			Multi-Purpose						
M-CON-87	M	Concrete, Gray, Cementitious	Janitor Closet	Assumed	NF	G	120	SF	09/27/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-SLT-88	M	Sealant (Doors, Windows), Brown, Pliable	P.E. Storage	Assumed	NF	G	5	SF	09/27/21
			P.E. Office						
			Water Heater						
			Table Storage						
			Multi-Purpose						
			Electrical 3						
			Janitor Closet						
M-SLT-91	M	Sealant (Duct), White, Pliable	Administration	Assumed	NF	G	200	SF	09/27/21
			Electrical 1						
			Room US4						
			Room US3						
			Office						
			Principal						
			Conference						
			Health TO						
			Health Restroom						
			Conference Closet						
			Hearing						
			Hall 2						
			Health						
			Health Assistant						
			Storage 3						
			Storage 1						
			Room A1						
			Room A1 Restroom						
			Storage 2						
			Room A2						
			Room A2 Restroom						
			Room B1						
			Room B1 Restroom						
			Room B2						
			Room B3						
			B Storage						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room B4						
			Room B5						
			Room B5 Restroom						
			Room B6						
			Room B6 Restroom						
			B Work Room						
			Room C1						
			Room C2						
			Room C3						
			Room C4						
			Room C5						
			Room C6						
			C Work Room						
			Room D1						
			Room D2						
			Room D3						
			Room D4						
			Room D5						
			Room D6						
			D Work Room						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Mechanical						
			Room E1						
			Room E2						
			Room E3						
			Room E4						
			Room E5						
			Room E5 TO						
			Room E6						
			Room E6 Restroom						
			E Work Room						
			Room F1						
			Room F2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			F Work Room						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Music						
			Music Office						
			Art						
			North Wing						
			Stage						
			South Wing						
			P.E. Storage						
			P.E. Office						
			Kitchen						
			Electrical 4						
			Water Heater						
			Can Wash						
			Table Storage						
			Boy's Restroom 4						
			Girl's Restroom 4						
			Multi-Purpose						
			Electrical 3						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Janitor Closet						
			Room G1						
			Room G2						
			Room G3						
			Room G4						
			Room G5						
			Room G6						
			G Work Room						
			Library						
			Software						
			Communication						
			Library Work Room						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Computer Lab						
			Room H1						
			Room H1 TO						
			Room H1 Restroom						
			Room H2						
			Room H2 TO						
			Room H2 Restroom						
			Custodial						
			Electrical 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Custodial Office						
			Lounge						
			Phone						
			Book Room						
			H Work Room						
			Room US1						
			Room US2						
			Hall 1						
			Speech						
			Social Worker Office						
			Social Worker						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
M-SLT-97	M	Sealant (Doors), White, Brittle	Exterior	Assumed	NF	G	50	SF	09/27/21
M-FDI-103	M	Fire Door Insulation, Metal/Wood Cladding	Storage 1	Assumed	NF	G	336	SF	09/27/21
			A1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			A2						
			B1						
			B6						
			C1						
			C2						
			C3						
			C6						
			D2						
			Mechanical						
			E2						
			E3						
			G5						
			H2						
			Custodial						
			Corridor 2						
			Corridor 7						
			North Corridor						
			Northeast Corridor						
			Southeast Corridor						
			Southwest Corridor						
M-CTG-120	M	Coating, White, Pliable	Roof	Assumed	NF	G	5,200	SF	09/27/21

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gravel Cap	Roof	Assumed	NF	G	2,750	SF	09/27/21
M-MAS-02	M	Mastic (Penetrations and Flashings), Black, Tar-Like	Roof	Assumed	NF	G	275	SF	09/27/21
M-SLT-03	M	Sealant (Duct), White, Pliable	Roof	Assumed	NF	G	5	SF	09/27/21
S-SAT-04	S	Spray-Applied Texture, White, Chalky	Living Room	Assumed	NF	G	4,300	SF	09/27/21
			Kitchen						
			Hall						
			Bedroom 1						
			Closet 1						
			Bedroom 2						
			Closet 2						
M-GWB-05	M	Gypsum Wallboard, White	Living Room	Assumed	NF	G	4,300	SF	09/27/21
			Kitchen						
			Hall						
			Bedroom 1						
			Closet 1						
			Bedroom 2						
			Closet 2						
S-JTC-06	S	Joint Compound, White, Chalky	Living Room	Assumed	NF	G	430	SF	09/27/21
			Kitchen						
			Hall						
			Bedroom 1						
			Closet 1						
			Bedroom 2						
			Closet 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M·SLT·08	M	Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable	Living Room	Assumed	NF	G	20	SF	09/27/21
			Kitchen						
			Hall						
			Bath						
			Toilet						
			Water Heater						
			Bedroom 1						
			Bedroom 2						
S·SAT·09	S	Spray-Applied Texture, White, Chalky	Kitchen	Assumed	NF	G	1,600	SF	09/27/21
			Laundry						
			Bath						
			Toilet						
			Water Heater						
			Closet 3						
M·GWB·10	M	Gypsum Wallboard, White, Chalky	Kitchen	Assumed	NF	G	1,600	SF	09/27/21
			Laundry						
			Bath						
			Toilet						
			Water Heater						
			Closet 3						
S·JTC·11	S	Joint Compound, White, Chalky	Kitchen	Assumed	NF	G	160	SF	09/27/21
			Laundry						
			Bath						
			Toilet						
			Water Heater						
			Closet 3						
M·SAC·12	M	Sink Acoustical Coating, Gray, Rough	Kitchen	Assumed	NF	G	2	SF	09/27/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CON-15	M	Concrete (Foundation), Gray, Cementitious	Living Room	Assumed	NF	G	2,100	SF	09/27/21
			Kitchen						
			Hall						
			Laundry						
			Bath						
			Toilet						
			Closet 3						
			Water Heater						
			Bedroom 1						
			Closet 1						
			Bedroom 2						
			Closet 2						
			Exterior						
S-STU-17	S	Stucco, Gray, Cementitious, Multi-Colored Stones	Exterior	Assumed	NF	G	3,000	SF	09/27/21
S-STU-18	S	Stucco, Gray, Cementitious	Exterior	Assumed	NF	G	650	SF	09/27/21
M-CON-19	M	Concrete (Entry), Gray, Cementitious	Exterior	Assumed	NF	G	650	SF	09/27/21
M-SLT-20	M	Sealant (Windows), Black, Pliable	Exterior	Assumed	NF	G	10	SF	09/27/21
M-SLT-21	M	Sealant (Door), Gray, Pliable	Exterior	Assumed	NF	G	1	SF	09/27/21

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMU-01	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	Equipment Yard	Assumed	NF	G	1,600	SF	09/27/21
			Exterior						
M-MRT-02	M	Mortar, Gray, Cementitious	Equipment Yard	Assumed	NF	G	160	SF	09/27/21
			Exterior						
M-CON-03	M	Concrete (Foundation), Gray, Cementitious	Equipment Yard	Assumed	NF	G	400	SF	09/27/21
M-CON-04	M	Concrete (Equipment Pads), Gray, Cementitious	Equipment Yard	Assumed	NF	G	80	SF	09/27/21
M-GAS-05	M	Gasket, 6"-8", Black, Vinyl-Like	Equipment Yard	Assumed	NF	G	2	SF	09/27/21
M-SLT-06	M	Sealant (Equipment), Black, Tar- Like	Equipment Yard	Assumed	NF	G	1	SF	09/27/21

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Equip-Tbl.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 123162 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-BUR-01, Mastic Built-Up Roofing, Black, Asphaltic, Gravel Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 43061250103164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MAS-02, Mastic (Penetrations and Flashings), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 12360 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-03, Sealant (Clear Story Windows), Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main
AHERA certification number: 4380 125d 123164 Signature of Inspector: Corbyn Hall
*Material Reinspected: M-SLT-04, Sealant (Clear Story Windows), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 4370125012316 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-05, Sealant (Clear Story Windows), Gray, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 43761284123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-12, Sealant (Duct), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Conbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 4370 1250 1250 Signature of Inspector: Conbyn Hall

*Material Reinspected: M-SLT-13, Sealant (Duct), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 4370-1252-123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-28, Sealant (Windows), Black, Gummy

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\28.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 4370 12501 12516 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SAC-29, Sink Acoustical Coating, Gray, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ☒ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\29.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 43012801123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-30, Fire Door Insulation, Wood/Metal Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc. 3

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\30.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Carbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 438012501 12364 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-SAC-31, Sink Acoustical Coating, White, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ☒ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\31.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 43001202100169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-44, Glazed Wall Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\44.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 438012501123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-45, Glazed Wall Tile (Pattern), 2"X2", Blue, Smooth, White Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\45.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-46, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\46.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 43012501122164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CMT-49, Ceramic Mosaic Tile, 2"X2", Tan, Smooth, Peppered

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\49.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/24 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main
AHERA certification number: 43061250123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-50, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\50.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 4/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 4386 1280172064 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CON-53, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\53.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Coryn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 45801252123169 Signature of Inspector: Coryn Hall

*Material Reinspected: M-ADH-54, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\54.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 43801250103164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PSL-55, Pipe End Sealant (Sprinklers), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\55.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Coryn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 4370125112365 Signature of Inspector: Coryn Hall

*Material Reinspected: M-CMT-62, Ceramic Mosaic Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Worte\Forms\Main\62.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 438025012316 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-64, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\64.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 436125112314 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-ADH-77, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ☒ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\77.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Coryn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 4370 1250 1236 Signature of Inspector: Coryn Hall

*Material Reinspected: M-CMU-78, Concrete Masonry Unit, 8"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Worte\Forms\Main\78.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Cortyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 430125112316 Signature of Inspector: Cortyn Hall

*Material Reinspected: M-MRT-79, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\79.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hull
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 4380125012316 Signature of Inspector: Corbyn Hull

*Material Reinspected: M-CON-87, Concrete, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium _____ Low _____
Degree of Activity Near the Material: High ☒ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\87.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Coby Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 43701257112316 Signature of Inspector: Coby Hall

*Material Reinspected: M-SLT-88, Sealant (Doors, Windows), Brown, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Worte\Forms\Main\88.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 30125012464 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-91, Sealant (Duct), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\91.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Cerbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 438012510316 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-SLT-97, Sealant (Doors), White, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\97.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 43502512361 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-103, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\103.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Main

AHERA certification number: 4376125112316 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CTG-120, Coating, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / NO
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / NO
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / NO
Evidence of Water Damage: _____ Yes / NO
Evidence of Delamination or Other Damage: _____ Yes / NO
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / NO
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / NO

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / NO
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Main\120.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 4370128125164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gravel Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apartment\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hull
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 4370125912464 Signature of Inspector: Corbyn Hull

*Material Reinspected: M-MAS-02, Mastic (Penetrations and Flashings), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apartment\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment
AHERA certification number: 430012301123160 Signature of Inspector: Corbyn Hall
*Material Reinspected: M-SLT-03, Sealant (Duct), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apert\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 438012501123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-SAT-04, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apartment\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 43801254121264 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWB-05, Gypsum Wallboard, White

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apartment\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 4302 1200 123104 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-JTC-06, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: ① Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apart\06.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Coryn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 4380 1280 12314 Signature of Inspector: Coryn Hall

*Material Reinspected: M-SLT-08, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apert\08.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment
AHERA certification number: 4380 1259 12364 Signature of Inspector: Corbyn Hall
*Material Reinspected: S-SAT-09, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apartment\09.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment
AHERA certification number: 4370 1250 12369 Signature of Inspector: Corbyn Hall
*Material Reinspected: M-GWB-10, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apart\10.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 4376128412404 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-JTC-11, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apartment\11.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 43701250112345 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SAC-12, Sink Acoustical Coating, Gray, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apart\12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 4380 12561 12316 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CON-15, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apart\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 4381260122109 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-STU-17, Stucco, Gray, Cementitious, Multi-Colored Stones

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High _____ Medium ✓ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apart\17.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbin Hall

Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 4380 12501 12316 Signature of Inspector: Corbin Hall

*Material Reinspected: S-STU-18, Stucco, Gray, Cementitious

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____

Degree of Activity Near the Material: High _____ Medium ✓ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apart\18.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 430123112314 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CON-19, Concrete (Entry), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apart\19.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 43101201123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-20, Sealant (Windows), Black, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3.) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apart\20.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Apartment

AHERA certification number: 420120112369 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-21, Sealant (Door), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium ✓ Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Apart\21.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Equipment

AHERA certification number: 4386 1284 12316 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CMU-01, Concrete Masonry Unit, 8"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Equip\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Equipment
AHERA certification number: 43701250112369 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MRT-02, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI ③ Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Equip\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Carson Hall

Facility: Kyrene del Norte Elementary School Building Name/Number: Equipment

AHERA certification number: 43801251123164 Signature of Inspector: Carson Hall

*Material Reinspected: M-CON-03, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High _____ Medium _____ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Equip\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/17/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene del Norte Elementary School Building Name/Number: Equipment

AHERA certification number: 430125112516 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CON-04, Concrete (Equipment Pads), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High _____ Medium _____ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Equip\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Equipment
AHERA certification number: 4380126112361 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GAS-05, Gasket, 6"-8", Black, Vinyl-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Equip\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/27/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene del Norte Elementary School Building Name/Number: Equipment
AHERA certification number: 4320125012301 Signature of Inspector: Corbyn Hall
*Material Reinspected: M-SLT-06, Sealant (Equipment), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ☒ 2. Did Not Find ☐

Material Condition: Has the condition of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / ☒ No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / ☒ No
Evidence of Water Damage: _____ Yes / ☒ No
Evidence of Delamination or Other Damage: _____ Yes / ☒ No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / ☒ No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ☒
Degree of Activity Near the Material: High _____ Medium _____ Low ☒
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / ☒ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / ☒ No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Norte\Forms\Equip\06.doc