

November 5, 2021

Mr. Mike Williams
Facilities Supervisor
Kyrene School District No. 28
8700 South Kyrene Road
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection
Asbestos-Containing Building Materials
Kyrene de la Esperanza Elementary School
14841 South 41st Place, Phoenix
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: None.

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC



Michael Hall
Environmental Division Manager

*Attachments: 3-Year Reinspection Tables
3-Year Reinspection Forms*

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Esperanza\Cvr Ltr.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-QPT-07	M	Quarry/Paver Tile, 8"X8", Red, Smooth	Room 35	Assumed	NF	G	13	SF	09/21/21
			Corridor C-04						
			Exterior						
M-GWT-10	M	Glazed Wall Tile, 8"X8", White, Smooth, Multi-Colored, Hand Painted Designs	Exterior	Assumed	NF	G	120	SF	09/21/21
M-GRT-11	M	Grout, Gray, Cementitious	Exterior	Assumed	NF	G	12	SF	09/21/21
M-CON-14	M	Concrete (Equipment Pad), Gray, Cementitious	Chiller Yard	Assumed	NF	G	1,000	SF	09/21/21
M-FDI-27	M	Fire Door Insulation, Wood Cladding	Reception	Assumed	NF	G	1,806	SF	09/21/21
			Fire Riser						
			Staff Lounge						
			Janitor Office						
			Principal						
			Assistant Principal						
			Storage 1						
			Electrical 1						
			Men's Restroom						
			Women's Restroom						
			Room 12						
			Room 13						
			Room 14						
			Room 15						
			Room 16						
			Room 17						
			Room 18						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 19						
			Room 20						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Room 21						
			Room 22						
			Room 24						
			Room 25						
			Room 26						
			Room 28						
			Room 29						
			Room 30						
			Room 31						
			Room 34A						
			Room 35						
			Room 35A						
			Room 35b						
			West Wing						
			Stage						
			East Wing						
			Room 36						
			Room 37						
			Room 38						
			Room 38A						
			Room 66						
			Room 66A						
			Room 67						
			Room 39						
			Room 40						
			Room 41						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Janitor 2						
			Room 42						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 43						
			Room 45						
			Room 46						
			Room 48						
			Room 49						
			Room 50						
			Room 51						
			Foyer 1						
			Room 54						
			Room 55						
			Room 55A						
			Room 56						
			Room 57						
			Room 57a						
			Room 58						
			Room 59						
			Room 60						
			Room 61						
			Room 61A						
			Foyer 2						
			Room 62						
			Room 62A						
			Room 63						
			Room 63A						
			Corridor C-01						
			Corridor C-02						
			Corridor C-03						
			Corridor C-05						
			Corridor C-06						
			Corridor C-07						
			Corridor C-09						
			Corridor C-10						
			Corridor C-11						
			Corridor C-12						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor C-13						
M-PSL-28	M	Pipe Sealant, Yellow, Pliable	Reception	Assumed	NF	G	75	SF	09/21/21
			Treatment						
			Nurse 1						
			Nurse Restroom						
			Fire Riser						
			Nurse 2						
			Workroom						
			Office 1						
			Phone						
			Staff Lounge						
			Janitor Office						
			Electrical 2						
			Principal						
			Principal Closet						
			Assistant Principal						
			Storage 1						
			Electrical 1						
			Men's Restroom						
			Women's Restroom						
			Room 12						
			Room 12A						
			12 Restroom						
			Room 13						
			Room 13A						
			13 Restroom						
			Room 14						
			14 Restroom						
			Room 15						
			Room 16						
			Room 17						
			Room 18						
			Room 19						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 20						
			Pod 1						
			Janitor 1						
			Girl's Restroom 1						
			Boy's Restroom 1						
			Chiller Yard						
			Room 21						
			Room 22						
			Room 23						
			Room 24						
			Room 25						
			Room 26						
			Room 27						
			Pod 2						
			Room 28						
			Room 29						
			Room 30						
			Room 31						
			Room 32						
			Room 33						
			Pod 3						
			Room 34						
			Room 34A						
			Janitor 3						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Room 35						
			Room 35A						
			Room 35B						
			West Wing						
			Stage						
			East Wing						
			Room 36						
			Room 37						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 37A						
			Room 38						
			Room 38A						
			Room 66						
			Room 66A						
			Room 67						
			Room 39						
			Room 40						
			Room 41						
			Room 41A						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Janitor 2						
			Room 42						
			Room 43						
			Room 44						
			Room 45						
			Room 46						
			Room 47						
			Pod 4						
			Room 48						
			Room 49						
			Room 50						
			Room 51						
			Room 52						
			Room 53						
			Pod 5						
			Foyer 1						
			Room 54						
			Room 55						
			Room 55A						
			Room 56						
			Room 56A						
			Room 57						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 57A						
			Room 58						
			Room 59						
			Room 59A						
			Room 59B						
			Room 60						
			Room 61						
			Room 61A						
			Foyer 2						
			Room 62						
			Room 62A						
			Room 63						
			Room 63A						
			Corridor C-01						
			Corridor C-02						
			Corridor C-03						
			Corridor C-04						
			Corridor C-05						
			Corridor C-06						
			Corridor C-07						
			Corridor C-08						
			Corridor C-09						
			Corridor C-10						
			Corridor C-11						
			Corridor C-12						
			Corridor C-13						
M-FDI-44	M	Fire Door Insulation, Metal Cladding	Reception	Assumed	NF	G	903	SF	09/21/21
			Treatment						
			Work Room						
			Janitor Office						
			Electrical 2						
			Room 12						
			Room 12A						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 13						
			Room 13A						
			Room 14						
			Room 23						
			Room 27						
			Room 32						
			Room 33						
			Room 34						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Room 35						
			Room 37						
			Room 37A						
			Kitchen Yard						
			Room 40						
			Art Patio						
			Room 44						
			Room 47						
			Room 52						
			Room 53						
			Corridor C-03						
			Corridor C-04						
			Corridor C-06						
			Corridor C-08						
			Corridor C-10						
			Corridor C-11						
			Corridor C-12						
			Corridor C-13						
			Exterior						
M-GWT-51	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Girl's Restroom 1	Assumed	NF	G	5,000	SF	09/21/21
			Boy's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 66						
			Room 67						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Room 62						
			Room 63						
M-GWT-52	M	Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth	Girl's Restroom 1	Assumed	NF	G	1,000	SF	09/21/21
			Boy's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Room 66						
			Room 67						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Room 62						
			Room 63						
M-GRT-53	M	Grout, Gray, Cementitious	Girl's Restroom 1	Assumed	NF	G	600	SF	09/21/21
			Boy's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Room 66						
			Room 67						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Room 62						
			Room 63						
M-CMT-54	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth, Peppered	Girl's Restroom 1	Assumed	NF	G	3,200	SF	09/21/21
			Boy's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 66						
			Room 67						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Room 62						
			Room 63						
M-GRT-55	M	Grout, Gray, Cementitious	Girl's Restroom 1	Assumed	NF	G	320	SF	09/21/21
			Boy's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Room 66						
			Room 67						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Room 62						
			Room 63						
M-ADH-56	M	Adhesive (FRP), Brown, Brittle	Room 37	Assumed	NF	G	100	SF	09/21/21
			Janitor 2						
			Room 62A						
M-PSL-57	M	Pipe Sealant, Green, Gummy	Chiller Yard	Assumed	NF	G	2	SF	09/21/21
M-SLT-58	M	Sealant (Equipment), Black, Gummy	Chiller Yard	Assumed	NF	G	2	SF	09/21/21
M-APL-59	M	Acoustical Ceiling Panel, 2'x2', Yellow, Fibrous Glass, Cloth Cover	Room 54	Assumed	NF	G	1,750	SF	09/21/21
			Room 57						
S-SAT-66	S	Spray-Applied Texture, White, Chalky	Entry	Assumed	NF	G	3,000	SF	09/21/21
			Kitchen						
			Bedroom 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Restroom 1						
			Living Room						
			Restroom 2						
			Bedroom 2						
M-GWB-67	M	Gypsum Wallboard, White, Chalky	Entry	Assumed	NF	G	3,000	SF	09/21/21
			Kitchen						
			Bedroom 1						
			Restroom 1						
			Living Room						
			Restroom 2						
			Bedroom 2						
S-JTC-68	S	Joint Compound, White, Chalky	Entry	Assumed	NF	G	300	SF	09/21/21
			Kitchen						
			Bedroom 1						
			Restroom 1						
			Living Room						
			Restroom 2						
			Bedroom 2						
M-QPT-69	M	Quarry/Paver Tile, 8"X8", White, Smooth	Entry	Assumed	NF	G	30	SF	09/21/21
M-GRT-70	M	Grout, Gray, Cementitious	Entry	Assumed	NF	G	3	SF	09/21/21
M-MAS-74	M	Mastic, Yellow, Tacky	Bedroom 1	Assumed	NF	G	1,200	SF	09/21/21
			Living Room						
			Bedroom 2						
M-GWT-75	M	Glazed Wall Tile, 4"X4", White, Smooth	Restroom 1	Assumed	NF	G	60	SF	09/21/21
			Restroom 2						
M-GRT-76	M	Grout, Gray, Cementitious	Restroom 1	Assumed	NF	G	60	SF	09/21/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Restroom 2						
M·SLT·77	M	Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable	Entry	Assumed	NF	G	11	SF	09/21/21
			Kitchen						
			Bedroom 1						
			Restroom 1						
			Restroom 2						
			Bedroom 2						
M·GRT·78	M	Grout (Glass Block), Gray, Cementitious	Entry	Assumed	NF	G	2	SF	09/21/21
M·FDI·122		Fire Door Insulation, Metal/Wood Cladding	NW Corridor (Rooms), SW Corridor (Rooms), Exterior	Assumed	NF	G	168	SF	09/21/21
M·FDI·130	M	Fire Door Insulation, Metal/Wood Cladding	Classroom A101	Assumed	NF	G	126	SF	09/21/21
			Classroom A102						
			A1 Corridor C14						
			Exterior						
M·FDI·230	M	Fire Door Insulation, Metal/Wood Cladding	Storage A202	Assumed	NF	G	105	SF	09/21/21
			Classroom A203						
			Classroom A204						
			A2 Corridor C15						

***Materials M·VSF·71 and M·MAS·72 were not found.**



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Cerbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 43701250123164 Signature of Inspector: Cerbyn Hall

*Material Reinspected: M-QPT-07, Quarry/Paver Tile, 8"X8", Red, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380 1269 123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-10, Glazed Wall Tile, 8"X8", White, Smooth, Multi-Colored, Hand Painted Designs

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4386 12561 123161 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-11, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 12601 123154 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CON-14, Concrete (Equipment Pad), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 43001201123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-27, Fire Door Insulation, Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 437012501123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PSL-28, Pipe Sealant, Yellow, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low

Degree of Activity Near the Material: High _____ Medium _____ Low

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carlyn Hall
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 12501 123164 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-FDI-44, Fire Door Insulation, Metal Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380 12001 128104 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GWT-51, Glazed Wall Tile, 4"X4", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 438012501123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-52, Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 123164 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GRT-53, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 437012501 12/26/19 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-CMT-54, Ceramic Mosaic Tile, 2"X2", Tan, Smooth, Peppered

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____

Degree of Activity Near the Material: High Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Conroy Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 1261 123164 Signature of Inspector: Conroy Hall

*Material Reinspected: M-GRT-55, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4310 12561 123109 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-ADH-56, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 12001 122164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PSL-57, Pipe Sealant, Green, Gummy

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4320 12001 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-58, Sealant (Equipment), Black, Gummy

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 1250 125164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-APL-59, Acoustical Ceiling Panel, 2'x2', Yellow, Fibrous Glass, Cloth Cover

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High _____ Medium Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 43101251123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-SAT-66, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 459012501123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWB-67, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____

Degree of Activity Near the Material: High Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 1251 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-JTC-68, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carlynn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 432012501123164 Signature of Inspector: Carlynn Hall

*Material Reinspected: M-QPT-69, Quarry/Paver Tile, 8"X8", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-70, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carlynn Hull
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4180 1251 121044 Signature of Inspector: Carlynn Hull

*Material Reinspected: M-VSF-71, Vinyl Sheet Flooring, Blue, Smooth, White Mottles, Gray Paper Backing

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place _____ 2. Did Not Find ✓

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: Material missing

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 438012501123166 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MAS-72, Mastic, Yellow, Tacky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place _____ 2. Did Not Find ✓

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: Material missing

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4376 125123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MAS-74, Mastic, Yellow, Tacky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4390 12561 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-75, Glazed Wall Tile, 4"X4", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 4/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 1251 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-76, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380 1250 12369 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-77, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380 1252 0234 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-78, Grout (Glass Block), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI **(3)** Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / **No**
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / **No**
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / **No**
Evidence of Water Damage: _____ Yes / **No**
Evidence of Delamination or Other Damage: _____ Yes / **No**
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / **No**

Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / **No**

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / **No**

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380125d, 123167 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-122, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 1201 12316 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-130, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Han

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4300 12501 123169 Signature of Inspector: Corbyn Han

*Material Reinspected: M-FDI-230, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.