

November 5, 2021

Mr. Mike Williams  
Facilities Supervisor  
Kyrene School District No. 28  
8700 South Kyrene Road  
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection  
Asbestos-Containing Building Materials  
Kyrene del Pueblo Middle School  
360 South Twelve Oaks Boulevard, Chandler  
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

**Items of significance are: None.**

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

**FM GROUP INC**



Michael Hall  
Environmental Division Manager

Attachments: *3-Year Reinspection Tables*  
*3-Year Reinspection Forms*

*G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Cvr Ltr.doc*

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-PLA-01	S	Plaster, Gray, Cementitious	Lockers 2	Assumed	NF	G	700	SF	10/04/21
			Lockers 1						
			Lockers 4						
S-SAT-02	S	Spray-Applied Texture, White, Chalky	Men's Restroom 1	Assumed	NF	G	1,500	SF	10/04/21
			Women's Restroom 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Lockers 1						
			Girl's Restroom						
			Boy's Restroom						
M-GWB-03	M	Gypsum Wallboard, White, Chalky	Men's Restroom 1	Assumed	NF	G	1,500	SF	10/04/21
			Women's Restroom 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Lockers 1						
			Girl's Restroom						
			Boy's Restroom						
S-JTC-04	S	Joint Compound, White, Chalky	Men's Restroom 1	Assumed	NF	G	150	SF	10/04/21
			Women's Restroom 1						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Lockers 1						
			Girl's Restroom						
			Boy's Restroom						
M-BRK-05	M	Brick, 4"X16", Tan, Cementitious	Lockers 2	Assumed	NF	G	15,000	SF	10/04/21
			Lockers 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Lockers 4						
			Courtyard 1						
			Courtyard 2						
			Exterior						
M-BRK-06	M	Brick, 4"X16", Red, Cementitious	Lockers 2	Assumed	NF	G	15,000	SF	10/04/21
			Lockers 1						
			Lockers 4						
			Courtyard 1						
			Courtyard 2						
			Exterior						
M-MRT-07	M	Mortar, Gray, Cementitious	Lockers 2	Assumed	NF	G	3,000	SF	10/04/21
			Lockers 1						
			Lockers 4						
			Courtyard 1						
			Courtyard 2						
			Exterior						
M-EXJ-08	M	Expansion Joint, Brown, Pliable	Lockers 2	Assumed	NF	G	50	SF	10/04/21
			Lockers 1						
			Lockers 4						
			Courtyard 1						
			Courtyard 2						
			Exterior						
M-QPT-09	M	Quarry/Paver Tile, 6"X6", Gray, Smooth	Lockers 1	Assumed	NF	G	200	SF	10/04/21
M-GRT-10	M	Grout, Gray, Cementitious	Lockers 1	Assumed	NF	G	20	SF	10/04/21
M-FDI-11	M	Fire Door Insulation, Metal/Wood Cladding	Men's Restroom 1	Assumed	NF	G	903	SF	10/04/21
			Women's Restroom 1						
			Work Room 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Work Room 2						
			Storage 1						
			Storage 2						
			Classroom A-2						
			Classroom A-3						
			Classroom A-4						
			Special Ed A-5						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Lockers 2						
			Classroom A-7						
			Classroom A-8						
			Classroom A-9						
			Storage 3						
			Hall 1						
			Storage 4						
			Classroom A-10						
			Storage 7						
			Classroom B-2						
			Classroom B-3						
			Classroom B-4						
			Classroom B-5						
			Classroom B-6						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Lockers 1						
			Classroom B-8						
			Classroom B-9						
			Storage 5						
			Hall 2						
			Storage 6						
			Classroom B-10						
			Utility						
			Janitor						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Courtyard 1						
			Courtyard 2						
			Exterior						
M-SLT-12	M	Sealant (Doors, Millwork, Fixtures), White, Pliable	Men's Restroom 1	Assumed	NF	G	25	SF	10/04/21
			Women's Restroom 1						
			Work Room 1						
			Work Room 2						
			Storage 1						
			Storage 2						
			Classroom A-2						
			Classroom A-3						
			Classroom A-4						
			Special Ed A-5						
			Special Ed To						
			Special Ed Office						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Classroom A-7						
			Classroom A-8						
			Classroom A-9						
			Storage 3						
			Hall 1						
			Storage 4						
			Classroom A-10						
			Classroom B-2						
			Classroom B-3						
			Classroom B-4						
			Classroom B-5						
			Classroom B-6						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Lockers 1						
			Classroom B-8						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom B-9						
			Storage 5						
			Hall 2						
			Storage 6						
			Classroom B-10						
			Utility						
			Janitor						
M-PSL-13	M	Pipe Sealant (Fire Sprinklers), White, Pliable	Men's Restroom 1	Assumed	NF	G	50	SF	10/04/21
			Women's Restroom 1						
			Work Room 1						
			Work Room 2						
			Storage 1						
			Storage 2						
			Classroom A-2						
			Classroom A-3						
			Classroom A-4						
			Special Ed A-5						
			Special Ed To						
			Special Ed Office						
			Girl's Restroom 2						
			Boy's Restroom 2						
			Lockers 2						
			Classroom A-7						
			Classroom A-8						
			Classroom A-9						
			Storage 3						
			Hall 1						
			Storage 4						
			Classroom A-10						
			Storage 7						
			Lockers 3						
			Classroom B-2						
			Classroom B-3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom B-4						
			Classroom B-5						
			Classroom B-6						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Lockers 1						
			Lockers 4						
			Classroom B-8						
			Classroom B-9						
			Storage 5						
			Hall 2						
			Storage 6						
			Classroom B-10						
			Utility						
			Janitor						
M-GWT-14	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Girl's Restroom 2	Assumed	NF	G	900	SF	10/04/21
			Boy's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
M-GWT-15	M	Glazed Wall Tile, 4"X4", Brown, Smooth	Girl's Restroom 2	Assumed	NF	G	900	SF	10/04/21
			Boy's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
M-GRT-16	M	Grout, Gray, Cementitious	Girl's Restroom 2	Assumed	NF	G	200	SF	10/04/21
			Boy's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMT-17	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth, White Specks	Girl's Restroom 2	Assumed	NF	G	800	SF	10/04/21
			Boy's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
M-GRT-18	M	Grout, Gray, Cementitious	Girl's Restroom 2	Assumed	NF	G	80	SF	10/04/21
			Boy's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
M-SLT-24	M	Sealant (Windows), Brown, Pliable	Classroom A-2	Assumed	NF	G	25	SF	10/04/21
			Classroom A-3						
			Special Ed A-5						
			Special Ed Office						
			Classroom A-7						
			Classroom A-8						
			Classroom A-9						
			Classroom A-10						
			Classroom B-2						
			Classroom B-3						
			Classroom B-5						
			Classroom B-6						
			Classroom B-8						
			Classroom B-9						
			Classroom B-10						
M-SAC-25	M	Sink Acoustical Coating, Black, Rough	Work Room 1	Assumed	NF	G	32	SF	10/04/21
			Work Room 2						
			Classroom A-2						
			Classroom A-3						
			Classroom A-4						
			Special Ed A-5						
			Classroom A-7						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom A-8						
			Classroom A-10						
			Classroom B-2						
			Classroom B-3						
			Classroom B-4						
			Classroom B-5						
			Classroom B-6						
			Classroom B-8						
			Classroom B-10						
M-VCT-31	M	Vinyl Composition Tile, 12"X12", Tan, Smooth, Brown Mottles	Men's Restroom 1	Assumed	NF	G	1,500	SF	10/04/21
			Women's Restroom 1						
			Work Room 1						
			Work Room 2						
			Storage 1						
			Storage 2						
			Storage 3						
			Hall 1						
			Storage 4						
			Storage 5						
			Hall 2						
			Storage 6						
			Utility						
M-MAS-32	M	Mastic, Black, Brittle	Men's Restroom 1	Assumed	NF	G	1,500	SF	10/04/21
			Women's Restroom 1						
			Work Room 1						
			Work Room 2						
			Storage 1						
			Storage 2						
			Storage 3						
			Hall 1						
			Storage 4						
			Storage 5						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Hall 2						
			Storage 6						
			Utility						
M-WAB-33	M	Wallbase (Coved), 4", Black, Vinyl-Like	Men's Restroom 1	Assumed	NF	G	125	SF	10/04/21
			Women's Restroom 1						
			Storage 1						
			Storage 2						
			Storage 3						
			Hall 1						
			Storage 4						
			Storage 7						
			Storage 5						
			Hall 2						
			Storage 6						
			Utility						
M-ADH-34	M	Adhesive, Brown, Brittle	Men's Restroom 1	Assumed	NF	G	125	SF	10/04/21
			Women's Restroom 1						
			Storage 1						
			Storage 2						
			Storage 3						
			Hall 1						
			Storage 4						
			Storage 7						
			Storage 5						
			Hall 2						
			Storage 6						
			Utility						
			Janitor						
M-SLT-35	M	Sealant (Windows), Black, Gummy	Special Ed A-5	Assumed	NF	G	5	SF	10/04/21
			Special Ed To						
			Special Ed Office						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GWB-38	M	Gypsum Wallboard, White, Chalky	Storage 7	Assumed	NF	G	1,400	SF	10/04/21
			Lockers 3						
			Utility						
			Janitor						
S-JTC-39	S	Joint Compound, White, Chalky	Storage 7	Assumed	NF	G	140	SF	10/04/21
			Lockers 3						
			Utility						
			Janitor						
M-GWT-40	M	Glazed Wall Tile, 4"X6", Brown, Smooth	Utility	Assumed	NF	G	10	SF	10/04/21
M-GRT-41	M	Grout, Gray, Cementitious	Utility	Assumed	NF	G	1	SF	10/04/21
M-CON-42	M	Concrete (Entries), Gray, Cementitious	Courtyard 1	Assumed	NF	G	5,000	SF	10/04/21
			Courtyard 2						
			Exterior						
M-SLT-43	M	Sealant (Doors), Tan, Pliable	Courtyard 1	Assumed	NF	G	25	SF	10/04/21
			Courtyard 2						
			Exterior						
M-SLT-44	M	Sealant (Windows), Brown, Pliable	Courtyard 1	Assumed	NF	G	25	SF	10/04/21
			Courtyard 2						
M-SLT-45	M	Sealant (Windows), Black, Gummy	Courtyard 1	Assumed	NF	G	25	SF	10/04/21
			Courtyard 2						
S-STU-46	S	Stucco, Gray, Cementitious	Courtyard 1	Assumed	NF	G	3,500	SF	10/04/21
			Courtyard 2						
			Exterior						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CON-47	M	Concrete (Courtyard), Gray, Cementitious	Courtyard 1	Assumed	NF	G	2,000	SF	10/04/21
			Courtyard 2						
M-BRK-48	M	Brick (Planters), 4"X16", Red, Cementitious	Courtyard 1	Assumed	NF	G	900	SF	10/04/21
			Courtyard 2						
M-MRT-49	M	Mortar, Gray, Cementitious	Courtyard 1	Assumed	NF	G	90	SF	10/04/21
			Courtyard 2						
M-BUR-50	M	Built-Up Roofing, Black, Asphaltic, Gravel Cap	Roof	Assumed	NF	G	13,000	SF	10/04/21
M-MAS-51	M	Mastic (Penetrations And Flashings), Black, Tar-Like	Roof	Assumed	NF	G	1,300	SF	10/04/21
M-APR-52	M	Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Tan Mineral Cap	Roof	Assumed	NF	G	600	SF	10/04/21
M-SLT-53	M	Sealant (Equipment), White, Pliable	Roof	Assumed	NF	G	20	SF	10/04/21
M-SLT-54	M	Sealant (Flashings), Gray, Pliable, Silver	Roof	Assumed	NF	G	25	SF	10/04/21

\*Material M-WAB-32 was not found in Janitor.



### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-SLT-10	M	Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable	Men's Restroom 1	Assumed	NF	G	50	SF	10/04/21
			Women's Restroom 1						
			Work Room 1						
			Work Room 2						
			Storage 4						
			Storage 5						
			Classroom G-2						
			Classroom G-3						
			Classroom G-4						
			Classroom G-5						
			Classroom G-6						
			Room G-6 To						
			G-6 Office						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Classroom G-7						
			Classroom G-8						
			Storage 6						
			Hall 2						
			Storage 7						
			Classroom G-9						
			Janitor						
			Classroom H-2						
			Classroom H-3						
			Classroom H-4						
			Special Ed H-5						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Classroom H-6						
			Classroom H-7						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom H-8						
			Storage 2						
			Hall 1						
			Storage 1						
			Classroom H-9						
			Storage 3						
M-SAC-11	M	Sink Acoustical Coating, Black, Rough	Work Room 1	Assumed	NF	G	32	SF	10/04/21
			Work Room 2						
			Classroom G-2						
			Classroom G-3						
			Classroom G-4						
			Classroom G-5						
			Classroom G-6						
			Classroom G-9						
			Classroom H-2						
			Classroom H-3						
			Classroom H-4						
			Classroom H-5						
			Special Ed H-6						
			Classroom H-7						
			Classroom H-9						
M-FDI-12	M	Fire Door Insulation, Metal/Wood Cladding	Men's Restroom 1	Assumed	NF	G	882	SF	10/04/21
			Women's Restroom 1						
			Work Room 1						
			Work Room 2						
			Storage 4						
			Storage 5						
			Classroom G-2						
			Classroom G-3						
			Classroom G-4						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom G-5						
			Classroom G-6						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Lockers 3						
			Classroom G-7						
			Classroom G-8						
			Storage 6						
			Hall 2						
			Storage 7						
			Classroom G-9						
			Janitor						
			Utility						
			Classroom H-2						
			Classroom H-3						
			Classroom H-4						
			Special Ed H-5						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Lockers 1						
			Classroom H-6						
			Classroom H-7						
			Classroom H-8						
			Storage 2						
			Hall 1						
			Storage 1						
			Classroom H-9						
			Storage 3						
			Courtyard 1						
			Courtyard 2						
			Exterior						
M-PSL-13	M	Pipe Sealant (Fire Sprinklers), White, Pliable	Men's Restroom 1	Assumed	NF	G	50	SF	10/04/21
			Women's Restroom 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Work Room 1						
			Work Room 2						
			Storage 4						
			Storage 5						
			Classroom G-2						
			Classroom G-3						
			Classroom G-4						
			Classroom G-5						
			Classroom G-6						
			Room G-6 To						
			G-6 Office						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Lockers 3						
			Classroom G-7						
			Classroom G-8						
			Storage 6						
			Hall 2						
			Storage 7						
			Classroom G-9						
			Janitor						
			Utility						
			Classroom H-2						
			Classroom H-3						
			Classroom H-4						
			Special Ed H-5						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Lockers 1						
			Classroom H-6						
			Classroom H-7						
			Classroom H-8						
			Storage 2						
			Hall 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 1						
			Classroom H-9						
			Lockers 2						
			Storage 3						
S-PLA-15	S	Plaster, Gray, Cementitious	Lockers 3	Assumed	NF	G	700	SF	10/04/21
			Lockers 1						
			Lockers 2						
M-BRK-16	M	Brick, 4"X16", Tan, Cementitious	Lockers 3	Assumed	NF	G	15,000	SF	10/04/21
			Lockers 1						
			Lockers 2						
			Courtyard 1						
			Courtyard 2						
			Exterior						
M-BRK-17	M	Brick, 4"X16", Red, Cementitious	Lockers 3	Assumed	NF	G	15,000	SF	10/04/21
			Lockers 1						
			Lockers 2						
			Courtyard 1						
			Courtyard 2						
			Exterior						
M-MRT-18	M	Mortar, Gray, Cementitious	Lockers 3	Assumed	NF	G	3,000	SF	10/04/21
			Lockers 1						
			Lockers 2						
			Courtyard 1						
			Courtyard 2						
			Exterior						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-EXJ-19	M	Expansion Joint, Brown, Pliable	Lockers 3	Assumed	NF	G	50	SF	10/04/21
			Lockers 1						
			Lockers 2						
			Courtyard 1						
			Courtyard 2						
			Exterior						
M-SLT-20	M	Sealant (Doors), Tan, Pliable	Lockers 3	Assumed	NF	G	32	SF	10/04/21
			Utility						
			Lockers 1						
			Courtyard 1						
			Courtyard 2						
			Exterior						
M-CON-21	M	Concrete (Equipment Pad), Gray, Cementitious	Lockers 1	Assumed	NF	G	25	SF	10/04/21
M-VCT-23	M	Vinyl Composition Tile, 12"X12", Tan, Smooth, Brown Mottles	Men's Restroom 1	Assumed	NF	G	1,200	SF	10/04/21
			Women's Restroom 1						
			Work Room 1						
			Work Room 2						
			Storage 4						
			Storage 5						
			Storage 6						
			Storage 7						
			Utility						
			Storage 2						
			Storage 1						
M-MAS-24	M	Mastic, Black, Brittle	Men's Restroom 1	Assumed	NF	G	1,200	SF	10/04/21
			Women's Restroom 1						
			Work Room 1						
			Work Room 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 4						
			Storage 5						
			Storage 6						
			Storage 7						
			Utility						
			Storage 2						
			Storage 1						
S·SAT·25	S	Spray-Applied Texture, White, Chalky	Men's Restroom 1	Assumed	NF	G	1,500	SF	10/04/21
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Janitor						
			Boy's Restroom 1						
			Girl's Restroom 1						
M·GWB·26	M	Gypsum Wallboard, White, Chalky	Men's Restroom 1	Assumed	NF	G	1,500	SF	10/04/21
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Janitor						
			Boy's Restroom 1						
			Girl's Restroom 1						
S·JTC·27	S	Joint Compound, White, Chalky	Men's Restroom 1	Assumed	NF	G	150	SF	10/04/21
			Women's Restroom 1						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Janitor						
			Boy's Restroom 1						
			Girl's Restroom 1						
M·ADH·28	M	Adhesive (FRP), Brown, Brittle	Janitor	Assumed	NF	G	10	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CON-29	M	Concrete (Foundation), Gray, Cementitious	Men's Restroom 1	Assumed	NF	G	12,000	SF	10/04/21
			Women's Restroom 1						
			Work Room 1						
			Work Room 2						
			Storage 4						
			Storage 5						
			Classroom G-2						
			Classroom G-3						
			Classroom G-4						
			Classroom G-5						
			Classroom G-6						
			Room G-6 To						
			G-6 Office						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Lockers 3						
			Classroom G-7						
			Classroom G-8						
			Storage 6						
			Hall 2						
			Storage 7						
			Classroom G-9						
			Janitor						
			Utility						
			Classroom H-2						
			Classroom H-3						
			Classroom H-4						
			Special Ed H-5						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Lockers 1						
			Classroom H-6						
			Classroom H-7						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom H-8						
			Storage 2						
			Hall 1						
			Storage 1						
			Classroom H-9						
			Lockers 2						
			Storage 3						
			Exterior						
M-WAB-30	M	Wallbase (Coved), 4", Black, Vinyl-Like	Janitor	Assumed	NF	G	50	SF	10/04/21
			Utility						
			Storage 3						
M-ADH-31	M	Adhesive, Brown, Brittle	Janitor	Assumed	NF	G	50	SF	10/04/21
			Utility						
			Storage 3						
M-GWT-32	M	Glazed Wall Tile, 4"x6", Tan, Smooth	Boy's Restroom 2	Assumed	NF	G	900	SF	10/04/21
			Girl's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
M-GWT-33	M	Glazed Wall Tile, 4"x6", Brown, Smooth	Boy's Restroom 2	Assumed	NF	G	900	SF	10/04/21
			Girl's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
M-GRT-34	M	Grout, Gray, Cementitious	Boy's Restroom 2	Assumed	NF	G	200	SF	10/04/21
			Girl's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMT-35	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth, White Specks	Boy's Restroom 2	Assumed	NF	G	800	SF	10/04/21
			Girl's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
M-GRT-36	M	Grout, Gray, Cementitious	Boy's Restroom 2	Assumed	NF	G	80	SF	10/04/21
			Girl's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
M-SLT-37	M	Sealant (Windows), Black, Gummy	Classroom G-6	Assumed	NF	G	25	SF	
			Room G-6 To						
			G-6 Office						
			Courtyard 1						
			Courtyard 2						
M-QPT-38	M	Quarry/Paver Tile, 6"X6", Gray, Textured	Lockers 3	Assumed	NF	G	200	SF	10/04/21
M-GRT-39	M	Grout, Gray, Cementitious	Lockers 3	Assumed	NF	G	20	SF	10/04/21
M-SLT-42	M	Sealant (Windows), Brown, Pliable	Courtyard 1	Assumed	NF	G	30	SF	10/04/21
			Courtyard 2						
M-CON-43	M	Concrete (Entries), Gray, Cementitious	Courtyard 1	Assumed	NF	G	6,000	SF	10/04/21
			Courtyard 2						
			Exterior						
M-CON-44	M	Concrete (Courtyards), Gray, Cementitious, Gravel Finish	Courtyard 1	Assumed	NF	G	2,000	SF	10/04/21
			Courtyard 2						
M-BRK-45	M	Brick (Planters), 4"X16", Red, Cementitious, White	Courtyard 1	Assumed	NF	G	900	SF	10/04/21
			Courtyard 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-MRT-46	M	Mortar, Gray, Cementitious	Courtyard 1	Assumed	NF	G	90	SF	10/04/21
			Courtyard 2						
S-STU-47	S	Stucco, Gray, Cementitious	Courtyard 1	Assumed	NF	G	3,500	SF	10/04/21
			Courtyard 2						
M-SLT-48	M	Sealant (Walls), Gray, Pliable	Exterior	Assumed	NF	G	15	SF	10/04/21
M-BUR-49	M	Built-Up Roofing, Black, Asphaltic, Gravel Cap	Roof	Assumed	NF	G	13,000	SF	10/04/21
M-MAS-50	M	Mastic (Penetrations And Flashings), Black, Tar-Like	Roof	Assumed	NF	G	400	SF	10/04/21
M-APR-51	M	Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Tan Mineral Cap	Roof	Assumed	NF	G	600	SF	10/04/21
M-SLT-52	M	Sealant (Equipment), White, Pliable	Roof	Assumed	NF	G	20	SF	10/04/21
M-SLT-53	M	Sealant (Flashings), Gray, Pliable, Silver	Roof	Assumed	NF	G	50	SF	10/04/21

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-SLT-10	M	Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable	School Office	Assumed	NF	G	50	SF	10/04/21
			Waiting						
			Office F-4						
			Principal						
			Assistant Principal						
			Counselor F-1						
			Janitor						
			Health Waiting						
			Health Office						
			Health Storage						
			Test						
			Health Restroom						
			Health						
			Electrical						
			Boy's Restroom						
			Girl's Restroom						
			Isolated Classroom						
			Staff Lounge						
			Tele Room						
			Mail						
			Receiving						
			Student Advisor 2						
			Student Advisor 1						
			Counselor F-5						
			Storage 1						
			Counselor F-7						
			Women's Restroom						
			Men's Restroom						
			Corridor 1						
			Corridor 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 3						
M-SLT-11	M	Sealant (Windows), Black, Gummy	School Office	Assumed	NF	G	30	SF	10/04/21
			Office F-4						
			Principal						
			Assistant Principal						
			Counselor F-1						
			Health Office						
			Health						
			Student Advisor 2						
			Student Advisor 1						
			Counselor F-5						
			Counselor F-7						
			Corridor 1						
			Corridor 2						
M-FDI-12	M	Fire Door Insulation, Metal/Wood Cladding	School Office	Assumed	NF	G	483	SF	10/04/21
			Waiting						
			Principal						
			Assistant Principal						
			Health Waiting						
			Health Storage						
			Health Office						
			Health						
			Electrical						
			Isolated Classroom						
			Staff Lounge						
			Receiving						
			Counselor F-5						
			Storage 1						
			Women's Restroom						
			Men's Restroom						
			Corridor 1						
			Corridor 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 3						
			Exterior						
M-MRT-13	M	Mortar (Glass Block), Gray, Cementitious	School Office	Assumed	NF	G	75	SF	10/04/21
			Staff Lounge						
			Mail						
			Receiving						
			Student Advisor 2						
M-PSL-15	M	Pipe Sealant (Fire Sprinklers), White, Pliable	School Office	Assumed	NF	G	50	SF	10/04/21
			Waiting						
			Office F-4						
			Principal						
			Assistant Principal						
			Counselor F-1						
			Janitor						
			Health Waiting						
			Health Office						
			Health Storage						
			Test						
			Health Restroom						
			Health						
			Electrical						
			Boy's Restroom						
			Girl's Restroom						
			Isolated Classroom						
			Staff Lounge						
			Tele Room						
			Mail						
			Receiving						
			Student Advisor 2						
			Student Advisor 1						
			Counselor F-5						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 1						
			Counselor F-7						
			Women's Restroom						
			Men's Restroom						
			Corridor 1						
			Corridor 2						
			Corridor 3						
M-GWB-16	M	Gypsum Wallboard, White, Chalky	School Office	Assumed	NF	G	3,500	SF	10/04/21
			Corridor 1						
			Corridor 2						
			Corridor 3						
S-JTC-17	S	Joint Compound, White, Chalky	School Office	Assumed	NF	G	350	SF	10/04/21
			Corridor 1						
			Corridor 2						
			Corridor 3						
M-SAC-18	M	Sink Acoustical Coating, Black, Rough	Health Office	Assumed	NF	G	10	SF	10/04/21
			Health						
			Isolated Classroom						
			Staff Lounge						
			Mail						
M-BRK-19	M	Brick, 4"X16", Tan, Cementitious	Receiving	Assumed	NF	G	6,000	SF	10/04/21
			Exterior						
M-BRK-20	M	Brick, 4"X16", Red, Cementitious	Receiving	Assumed	NF	G	6,000	SF	10/04/21
			Exterior						
M-MRT-21	M	Mortar, Gray, Cementitious	Receiving	Assumed	NF	G	1,200	SF	10/04/21
			Exterior						
M-EXJ-22	M	Expansion Joint, Brown, Pliable	Receiving	Assumed	NF	G	50	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Exterior						
M-VCT-23	M	Vinyl Composition Tile, 12"X2", Tan, Smooth, Brown Mottles	Janitor	Assumed	NF	G	600	SF	10/04/21
			Health Restroom						
			Boy's Restroom						
			Girl's Restroom						
			Women's Restroom						
			Men's Restroom						
M-MAS-24	M	Mastic, Black, Brittle	Janitor	Assumed	NF	G	600	SF	10/04/21
			Health Restroom						
			Boy's Restroom						
			Girl's Restroom						
			Women's Restroom						
			Men's Restroom						
M-WAB-25	M	Wallbase (Coved), 4", Black, Vinyl- Like	Janitor	Assumed	NF	G	125	SF	10/04/21
			Electrical						
			Boy's Restroom						
			Girl's Restroom						
			Women's Restroom						
			Men's Restroom						
M-ADH-26	M	Adhesive, Brown, Brittle	Janitor	Assumed	NF	G	125	SF	10/04/21
			Health Restroom						
			Electrical						
			Boy's Restroom						
			Girl's Restroom						
			Women's Restroom						
			Men's Restroom						
S-SAT-27	S	Spray-Applied Texture, White, Chalky	Health Restroom	Assumed	NF	G	2,500	SF	10/04/21
			Boy's Restroom						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom						
			Women's Restroom						
			Men's Restroom						
M·GWB·28	M	Gypsum Wallboard, White, Chalky	Health Restroom	Assumed	NF	G	2,500	SF	10/04/21
			Boy's Restroom						
			Girl's Restroom						
			Women's Restroom						
			Men's Restroom						
S·JTC·29	S	Joint Compound, White, Chalky	Health Restroom	Assumed	NF	G	250	SF	10/04/21
			Boy's Restroom						
			Girl's Restroom						
			Women's Restroom						
			Men's Restroom						
M·GWB·30	M	Gypsum Wallboard, White, Chalky	Janitor	Assumed	NF	G	750	SF	10/04/21
			Electrical						
S·JTC·31	S	Joint Compound, White, Chalky	Janitor	Assumed	NF	G	75	SF	10/04/21
			Electrical						
M·ADH·32	M	Adhesive (FRP), Brown, Brittle	Janitor	Assumed	NF	G	10	SF	10/04/21
M·GAS·33	M	Gasket, 8", Black, Vinyl-Like	Janitor	Assumed	NF	G	1	SF	10/04/21
M·VCT·34	M	Vinyl Composition Tile, 12"X12", White, Smooth, Gray Mottles	Electrical	Assumed	NF	G	50	SF	10/04/21
M·MAS·35	M	Mastic, Black, Brittle	Electrical	Assumed	NF	G	50	SF	10/04/21
M·CON·36	M	Concrete (Foundation), Gray, Cementitious	School Office	Assumed	NF	G	9,500	SF	10/04/21
			Waiting						
			Office F-4						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Principal						
			Assistant Principal						
			Counselor F-1						
			Janitor						
			Health Waiting						
			Health Office						
			Health Storage						
			Test						
			Health Restroom						
			Health						
			Electrical						
			Boy's Restroom						
			Girl's Restroom						
			Isolated Classroom						
			Staff Lounge						
			Tele Room						
			Mail						
			Receiving						
			Student Advisor 2						
			Student Advisor 1						
			Counselor F-5						
			Storage 1						
			Counselor F-7						
			Women's Restroom						
			Men's Restroom						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Exterior						
M-CON-37	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	4,000	SF	10/04/21
M-SLT-38	M	Sealant (Doors), Tan, Pliable	Exterior	Assumed	NF	G	15	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-SLT-39	M	Sealant (Windows), Brown, Pliable	Exterior	Assumed	NF	G	10	SF	10/04/21
S-STU-40	S	Stucco, Gray, Cementitious	Exterior	Assumed	NF	G	250	SF	10/04/21
M-BUR-41	M	Built-Up Roofing, Black, Asphaltic, Gravel Cap	Roof	Assumed	NF	G	9,500	SF	10/04/21
M-MAS-42	M	Mastic (Penetrations And Flashings), Black, Tar-Like, Silver	Roof	Assumed	NF	G	500	SF	10/04/21
M-APR-43	M	Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Tan Mineral Cap	Roof	Assumed	NF	G	200	SF	10/04/21
M-SLT-44	M	Sealant (Equipment), White, Pliable	Roof	Assumed	NF	G	10	SF	10/04/21
M-SLT-45	M	Sealant (Flashing), Gray, Pliable, Silver	Roof	Assumed	NF	G	50	SF	10/04/21

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-SLT-10	M	Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable	Speech	Assumed	NF	G	25	SF	10/04/21
			Speech T.O.						
			Computer Classroom 1						
			Office						
			Janitor						
			A/V Storage						
			Storage 1						
			Media Workshop						
			Media Center						
			Boy's Restroom						
			Girl's Restroom						
			Media Classroom						
			Computer Classroom 2						
			Special Education						
			Special Ed Office						
			Hall						
			Special Ed Restroom						
			Storage 2						
			Electrical						
M-SLT-11	M	Sealant (Windows), Black, Gummy	Computer Classroom 1	Assumed	NF	G	25	SF	10/04/21
			Office						
			Media Workshop						
			Media Center						
			Media Classroom						
			Computer Classroom 2						
			Special Education						
			Special Ed Office						
			Exterior						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-FDI-12	M	Fire Door Insulation, Metal/Wood Cladding	Speech	Assumed	NF	G	357	SF	10/04/21
			Computer Classroom 1						
			Storage 1						
			Janitor						
			A/V Storage						
			Media Workshop						
			Media Center						
			Media Classroom						
			Computer Classroom 2						
			Special Education						
			Electrical						
			Exterior						
M-PSL-14	M	Pipe Sealant (Fire Sprinklers), White, Pliable	Speech	Assumed	NF	G	25	SF	10/04/21
			Speech T.O.						
			Computer Classroom 1						
			Office						
			Storage 1						
			Janitor						
			A/V Storage						
			Media Workshop						
			Media Center						
			Boy's Restroom						
			Girl's Restroom						
			Media Classroom						
			Computer Classroom 2						
			Special Education						
			Special Ed Office						
			Hall						
			Special Ed Restroom						
			Storage 2						
			Electrical						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-SAT-15	S	Spray-Applied Texture, White, Chalky	Boy's Restroom	Assumed	NF	G	1,200	SF	10/04/21
			Girl's Restroom						
			Special Ed Restroom						
M-GWB-16	M	Gypsum Wallboard, White, Chalky	Boy's Restroom	Assumed	NF	G	1,200	SF	10/04/21
			Girl's Restroom						
			Special Ed Restroom						
S-JTC-17	S	Joint Compound, White, Chalky	Boy's Restroom	Assumed	NF	G	120	SF	10/04/21
			Girl's Restroom						
			Special Ed Restroom						
M-ADH-19	M	Adhesive (WAB), Cream, Pliable	Boy's Restroom	Assumed	NF	G	40	SF	10/04/21
			Girl's Restroom						
			Electrical						
M-VCT-20	M	Vinyl Composition Tile, 12"X12", Tan, Smooth, Brown Mottles	Boy's Restroom	Assumed	NF	G	100	SF	10/04/21
			Girl's Restroom						
M-MAS-21	M	Mastic, Black, Brittle	Boy's Restroom	Assumed	NF	G	100	SF	10/04/21
			Girl's Restroom						
M-SAC-23	M	Sink Acoustical Coating, Black, Rough	Speech	Assumed	NF	G	12	SF	10/04/21
			Computer Classroom 1						
			Media Workshop						
			Media Classroom						
			Computer Classroom 2						
			Special Education						
M-VCT-24	M	Vinyl Composition Tile, 12"X12", White, Smooth, Gray Mottles	Janitor	Assumed	NF	G	500	SF	10/04/21
			Special Ed Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 2						
			Electrical						
M-MAS-25	M	Mastic, Black, Brittle	Janitor	Assumed	NF	G	500	SF	10/04/21
			Special Ed Restroom						
			Storage 2						
			Electrical						
M-WAB-26	M	Wallbase (Coved), 4", Dark Gray, Vinyl-Like	Janitor	Assumed	NF	G	40	SF	10/04/21
			Special Ed Restroom						
			Storage 2						
M-ADH-27	M	Adhesive, Brown, Brittle	Janitor	Assumed	NF	G	40	SF	10/04/21
			Special Ed Restroom						
			Storage 2						
M-GWB-28	M	Gypsum Wallboard, White, Chalky	Janitor	Assumed	NF	G	1,000	SF	10/04/21
			Electrical						
S-JTC-29	S	Joint Compound, White, Chalky	Janitor	Assumed	NF	G	100	SF	10/04/21
			Electrical						
M-CON-30	M	Concrete (Foundation), Gray, Cementitious	Speech	Assumed	NF	G	15,000	SF	10/04/21
			Speech T.O.						
			Computer Classroom 1						
			Office						
			Storage 1						
			Janitor						
			A/V Storage						
			Media Workshop						
			Media Center						
			Boy's Restroom						
			Girl's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Media Classroom						
			Computer Classroom 2						
			Special Education						
			Special Ed Office						
			Hall						
			Special Ed Restroom						
			Storage 2						
			Electrical						
			Exterior						
M-CON-31	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	4,000	SF	10/04/21
M-BRK-32	M	Brick, 4"X16", Tan, Cementitious	Exterior	Assumed	NF	G	8,000	SF	10/04/21
M-BRK-33	M	Brick, 4"X16", Red, Cementitious	Exterior	Assumed	NF	G	8,000	SF	10/04/21
M-MRT-34	M	Mortar, Gray, Cementitious	Exterior	Assumed	NF	G	1,600	SF	10/04/21
M-EXJ-35	M	Expansion Joint, Tan, Pliable	Exterior	Assumed	NF	G	25	SF	10/04/21
M-SLT-36	M	Sealant (Doors), Brown, Brittle	Exterior	Assumed	NF	G	15	SF	10/04/21
M-SLT-37	M	Sealant (Windows), Black, Pliable	Exterior	Assumed	NF	G	20	SF	10/04/21
M-GAS-39	M	Gasket, 8", Black, Vinyl-Like	Janitor	Assumed	NF	G	1	SF	10/04/21
M-BUR-40	M	Built-Up Roofing, Black, Asphaltic, Gravel Cap	Roof	Assumed	NF	G	15,000	SF	10/04/21
M-MAS-41	M	Mastic (Penetrations and Flashings), Black, Tar-Like, Silver	Roof	Assumed	NF	G	500	SF	10/04/21
M-APR-42	M	Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Tan Mineral Cap	Roof	Assumed	NF	G	200	SF	10/04/21



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	<b>M/S/T</b>			<b>%/ASSUMED</b>	<b>NF/F</b>	<b>G/D/SD</b>		<b>LF/SF/EA</b>	
M-SLT-43	M	Sealant (Equipment), White, Pliable	Roof	Assumed	NF	G	10	SF	10/04/21
M-SLT-44	M	Sealant (Flashing), Gray, Pliable, Silver	Roof	Assumed	NF	G	25	SF	10/04/21
S-STU-45	S	Stucco, Gray, Cementitious	Roof	Assumed	NF	G	250	SF	10/04/21
M-SLT-46	M	Sealant (Windows), Brown, Pliable	Roof	Assumed	NF	G	10	SF	10/04/21

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Bldg400-Tbl.doc

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-FDI-10	M	Fire Door Insulation, Metal/Wood Cladding	Drama	Assumed	NF	G	651	SF	10/04/21
			Maintenance						
			Janitor						
			Home Economics						
			Home Economics Restroom						
			Storage 5						
			Art						
			Storage 4						
			Storage 3						
			Weight Room						
			Wood Shop						
			Classroom D5						
			Storage 1						
			Storage 2						
			Classroom D6						
			Music						
			Play Yard						
			Maintenance Yard						
			Home Economics Patio						
			Art Patio						
			Industrial Arts Yard						
			Exterior						
M-SLT-11	M	Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable	Drama	Assumed	NF	G	50	SF	10/04/21
			Laundry						
			Maintenance						
			Office 2						
			Janitor						
			Home Economics						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Home Economics Restroom						
			Storage 5						
			Office 1						
			Art						
			Storage 4						
			Storage 3						
			Weight Room						
			Wood Shop						
			Classroom D5						
			Storage 1						
			Storage 2						
			Classroom D6						
			Music						
M-SAC-12	M	Sink Acoustical Coating, Black, Rough	Classroom D5	Assumed	NF	G	20	SF	10/04/21
			Classroom D6						
			Music						
M-SLT-14	M	Sealant (Duct), Gray, Pliable	Drama	Assumed	NF	G	50	SF	10/04/21
			Laundry						
			Maintenance						
			Office 2						
			Janitor						
			Home Economics						
			Home Economics Restroom						
			Storage 5						
			Office 1						
			Art						
			Storage 4						
			Storage 3						
			Classroom D5						
			Storage 1						
			Storage 2						
			Classroom D6						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Music						
M-PSL-15	M	Pipe Sealant (Fire Sprinklers), White, Pliable	Drama	Assumed	NF	G	50	SF	10/04/21
			Laundry						
			Maintenance						
			Office 2						
			Janitor						
			Home Economics						
			Home Economics Restroom						
			Storage 5						
			Office 1						
			Art						
			Storage 4						
			Storage 3						
			Weight Room						
			Wood Shop						
			Classroom D5						
			Storage 1						
			Storage 2						
			Classroom D6						
			Music						
M-VCT-16	M	Vinyl Composition Tile, 12"X12", Tan, Smooth, Brown Mottles	Laundry	Assumed	NF	G	3,000	SF	10/04/21
			Maintenance						
			Janitor						
			Home Economics Restroom						
			Storage 5						
			Art						
			Storage 4						
			Storage 3						
M-MAS-17	M	Mastic, Black, Brittle	Laundry	Assumed	NF	G	3,000	SF	10/04/21
			Maintenance						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Janitor						
			Home Economics Restroom						
			Storage 5						
			Art						
			Storage 4						
			Storage 3						
M-CON-18	M	Concrete (Foundation), Gray, Cementitious	Drama	Assumed	NF	G	6,500	SF	10/04/21
			Drama Restroom						
			Drama Storage						
			Storage 6						
			Laundry						
			Maintenance						
			Office 2						
			Janitor						
			Home Economics						
			Home Economics Restroom						
			Storage 5						
			Office 1						
			Art						
			Storage 4						
			Storage 3						
			Weight Room						
			Wood Shop						
			Classroom D5						
			Storage 1						
			Storage 2						
			Classroom D6						
			Music						
			Exterior						
M-SLT-19	M	Sealant (Windows), Black, Gummy	Drama	Assumed	NF	G	20	SF	10/04/21
			Office 2						
			Home Economics						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Office 1						
			Art						
			Weight Room						
			Wood Shop						
			Classroom D5						
			Storage 2						
			Art Patio						
			Exterior						
M-SAC-22	M	Sink Acoustical Coating, Gray, Rough	Art	Assumed	NF	G	6	SF	10/04/21
M-CPT-23	M	Carpet, Brown, Fibrous	Office 1	Assumed	NF	G	100	SF	10/04/21
M-MAS-24	M	Mastic, Tan, Brittle	Office 1	Assumed	NF	G	100	SF	10/04/21
M-VCT-25	M	Vinyl Composition Tile, 12"X12", White, Smooth, Blue Mottles	Home Economics	Assumed	NF	G	1,500	SF	10/04/21
M-VCT-26	M	Vinyl Composition Tile, 12"X12", Blue, Smooth, Light Blue Mottles	Home Economics	Assumed	NF	G	300	SF	10/04/21
M-MAS-27	M	Mastic, Black, Brittle	Home Economics	Assumed	NF	G	1,800	SF	10/04/21
M-WAB-28	M	Wallbase (Coved), 4", Blue, Vinyl-Like	Office 2	Assumed	NF	G	65	SF	10/04/21
			Home Economics						
M-ADH-29	M	Adhesive, Brown, Brittle	Office 2	Assumed	NF	G	65	SF	10/04/21
			Home Economics						
S-SAT-30	S	Spray-Applied Texture, White, Chalky	Laundry	Assumed	NF	G	1,500	SF	10/04/21
			Janitor						
			Home Economics Restroom						
M-GWB-31	M	Gypsum Wallboard, White, Chalky	Laundry	Assumed	NF	G	1,500	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Janitor						
			Home Economics Restroom						
S-JTC-32	S	Joint Compound, White, Chalky	Laundry	Assumed	NF	G	150	SF	10/04/21
			Janitor						
			Home Economics Restroom						
M-GAS-35	M	Gasket, 6", Black, Vinyl-Like	Maintenance	Assumed	NF	G	1	SF	10/04/21
M-GWB-36	M	Gypsum Wallboard, White, Chalky	Maintenance	Assumed	NF	G	750	SF	10/04/21
S-JTC-37	S	Joint Compound, White, Chalky	Maintenance	Assumed	NF	G	75	SF	10/04/21
M-CON-38	M	Concrete (Entries), Gray, Cementitious	Play Yard	Assumed	NF	G	6,000	SF	10/04/21
			Maintenance Yard						
			Home Ec Patio						
			Art Patio						
			Industrial Arts Yard						
			Exterior						
M-BRK-39	M	Brick, 4"X16", Tan, Cementitious	Play Yard	Assumed	NF	G	13,500	SF	10/04/21
			Maintenance Yard						
			Home Ec Patio						
			Art Patio						
			Industrial Arts Yard						
			Exterior						
M-BRK-40	M	Brick, 4"X16", Red, Cementitious	Play Yard	Assumed	NF	G	13,500	SF	10/04/21
			Maintenance Yard						
			Home Ec Patio						
			Art Patio						
			Industrial Arts Yard						
			Exterior						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M·MRT·41	M	Mortar, Gray, Cementitious	Play Yard	Assumed	NF	G	2,700	SF	10/04/21
			Maintenance Yard						
			Home Ec Patio						
			Art Patio						
			Industrial Arts Yard						
			Exterior						
M·EXJ·42	M	Expansion Joint, Brown, Pliable	Play Yard	Assumed	NF	G	50	SF	10/04/21
			Maintenance Yard						
			Home Ec Patio						
			Art Patio						
			Industrial Arts Yard						
			Exterior						
M·SLT·43	M	Sealant (Doors), Tan, Brittle	Play Yard	Assumed	NF	G	20	SF	10/04/21
			Maintenance Yard						
			Home Ec Patio						
			Art Patio						
			Industrial Arts Yard						
			Exterior						
M·SLT·44	M	Sealant (Windows), Brown, Pliable	Art Patio	Assumed	NF	G	20	SF	10/04/21
			Exterior						
M·CON·45	M	Concrete (Equipment Pad), Gray, Cementitious	Exterior	Assumed	NF	G	20	SF	10/04/21
M·SLT·46	M	Sealant (Duct), Gray, Brittle	Industrial Arts Yard	Assumed	NF	G	5	SF	10/04/21
M·WDB·47	M	Woven Duct Boot, 4", Black, Vinyl-Like	Industrial Arts Yard	Assumed	NF	G	2	SF	10/04/21
M·BUR·48	M	Built-Up Roofing, Black, Asphaltic, Gravel Cap	Roof	Assumed	NF	G	6,500	SF	10/04/21



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	<b>M/S/T</b>			<b>%/ASSUMED</b>	<b>NF/F</b>	<b>G/D/SD</b>		<b>LF/SF/EA</b>	
M·MAS·49	M	Mastic (Penetrations And Flashings), Black, Tar-Like, Silver	Roof	Assumed	NF	G	400	SF	10/04/21
M·APR·50	M	Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Tan Mineral Cap	Roof	Assumed	NF	G	200	SF	10/04/21
M·SLT·51	M	Sealant (Equipment), White, Pliable	Roof	Assumed	NF	G	10	SF	10/04/21
M·SLT·52	M	Sealant (Flashings), Gray, Pliable, Silver	Roof	Assumed	NF	G	50	SF	10/04/21

**\*Material M·SAC·12 was not found in Home Economics.**

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BRK-06	M	Brick, 4"X16", Tan, Cementitious	Lobby	Assumed	NF	G	22,000	SF	10/04/21
			Hall 3						
			East Wing						
			Music						
			Guitar Lab						
			Storage 3						
			Cafeteria						
			Gym						
			Hall 1						
			Girl's Locker Room						
			P.E. Storage						
			P.E. Office 1						
			P.E. Office 2						
			Boy's Locker Room						
			Hall 2						
M-BRK-07	M	Brick, 4"X16", Red, Cementitious	Lobby	Assumed	NF	G	22,000	SF	10/04/21
			Hall 3						
			East Wing						
			Music						
			Guitar Lab						
			Storage 3						
			Cafeteria						
			Gym						
			Hall 1						
			Girl's Locker Room						
			P.E. Storage						
			P.E. Office 1						
			P.E. Office 2						
			Boy's Locker Room						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Hall 2						
M-MRT-08	M	Mortar, Gray, Cementitious	Lobby	Assumed	NF	G	4,400	SF	10/04/21
			Hall 3						
			East Wing						
			Music						
			Guitar Lab						
			Storage 3						
			Cafeteria						
			Gym						
			Hall 1						
			Girl's Locker Room						
			P.E. Storage						
			P.E. Office 1						
			P.E. Office 2						
			Boy's Locker Room						
			Hall 2						
M-EXJ-09	M	Expansion Joint, Brown, Pliable	Lobby	Assumed	NF	G	200	SF	10/04/21
			Hall 3						
			East Wing						
			Music						
			Guitar Lab						
			Storage 3						
			Cafeteria						
			Gym						
			Hall 1						
			Girl's Locker Room						
			P.E. Storage						
			P.E. Office 1						
			P.E. Office 2						
			Boy's Locker Room						
			Hall 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-SLT-10	M	Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable	Lobby	Assumed	NF	G	50	SF	10/04/21
			Girl's Restroom 1						
			Boy's Restroom 1						
			Kitchen						
			Kitchen Office						
			Kitchen Restroom						
			Kitchen Lockers						
			Storage 1						
			Electrical 1						
			Storage 2						
			Hall 3						
			East Wing						
			Music						
			Guitar Lab						
			Listening						
			Keyboard Lab						
			Storage 3						
			Cafeteria						
			Hall 1						
			Girl's Locker Room						
			P.E. Storage						
			P.E. Office 1						
			P.E. Restroom 1						
			P.E. Restroom 2						
			P.E. Office 2						
			Storage 5						
			Boy's Locker Room						
			Hall 2						
M-SAC-11	M	Sink Acoustical Coating, Black, Rough	Music	Assumed	NF	G	2	SF	10/04/21
M-SLT-12	M	Sealant (Windows), Black, Gummy	Kitchen	Assumed	NF	G	15	SF	10/04/21
			Kitchen Office						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Music						
			Guitar Lab						
			Listening						
			Girl's Locker Room						
			P.E. Office 1						
			P.E. Office 2						
			Boy's Locker Room						
M-FDI-17	M	Fire Door Insulation, Metal/Wood Cladding	Lobby	Assumed	NF	G	1,386	SF	10/04/21
			Girl's Restroom 1						
			Boy's Restroom 1						
			Kitchen						
			Kitchen Lockers						
			Storage 1						
			Electrical 1						
			Hall 3						
			Stage						
			East Wing						
			Music						
			Cafeteria						
			Gym						
			Storage 4						
			Hall 1						
			Girl's Locker Room						
			P.E. Storage						
			P.E. Office 1						
			P.E. Office 2						
			Storage 5						
			Boy's Locker Room						
			Hall 2						
			Exterior						
M-PSL-19	M	Pipe Sealant (Fire Sprinklers), White, Pliable	Lobby	Assumed	NF	G	50	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 1						
			Boy's Restroom 1						
			Kitchen						
			Kitchen Office						
			Kitchen Restroom						
			Kitchen Lockers						
			Storage 1						
			Electrical 1						
			Storage 2						
			Hall 3						
			Stage						
			East Wing						
			Music						
			Guitar Lab						
			Listening						
			Keyboard Lab						
			Storage 3						
			Cafeteria						
			Gym						
			Storage 4						
			Hall 1						
			Girl's Locker Room						
			P.E. Storage						
			P.E. Office 1						
			P.E. Restroom 1						
			P.E. Restroom 2						
			P.E. Office 2						
			Storage 5						
			Boy's Locker Room						
			Hall 2						
M-WAB-22	M	Wallbase (Coved), 4", Black, Vinyl-Like	Kitchen Office	Assumed	NF	G	75	SF	10/04/21
			Electrical 1						
			East Wing						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 4						
			Hall 1						
			Hall 2						
M-ADH-23	M	Adhesive, Brown, Brittle	Kitchen Office	Assumed	NF	G	75	SF	10/04/21
			Electrical 1						
			East Wing						
			Storage 4						
			Hall 1						
			Hall 2						
M-VST-24	M	Vinyl Stair Tread, 12"X36", Tan, Textured, Diamond Pattern	Hall 3	Assumed	NF	G	75	SF	10/04/21
			Cafeteria						
M-MAS-25	M	Mastic, Yellow, Tacky	Hall 3	Assumed	NF	G	75	SF	10/04/21
			Cafeteria						
M-VCT-26	M	Vinyl Composition Tile, 12"X12", White, Smooth, Gray Mottles	Electrical 1	Assumed	NF	G	5,000	SF	10/04/21
			Hall 3						
			Cafeteria						
M-MAS-27	M	Mastic, Black, Brittle	Electrical 1	Assumed	NF	G	5,000	SF	10/04/21
			Hall 3						
			Cafeteria						
M-VCT-28	M	Vinyl Composition Tile (Pattern), 12"X12", Brown, Smooth, White Mottles	Cafeteria	Assumed	NF	G	50	SF	10/04/21
M-QPT-32	M	Quarry/Paver Tile, 6"X6", Red, Smooth	Kitchen	Assumed	NF	G	2,200	SF	10/04/21
			Kitchen Restroom						
			Kitchen Lockers						
			Storage 1						
			Cafeteria						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GRT-33	M	Grout, Gray, Cementitious	Kitchen	Assumed	NF	G	220	SF	10/04/21
			Kitchen Restroom						
			Kitchen Lockers						
			Storage 1						
			Cafeteria						
M-VCT-34	M	Vinyl Composition Tile, 12"X12", Tan, Smooth, Brown Mottles	Kitchen Office	Assumed	NF	G	750	SF	10/04/21
			Storage 2						
			Storage 4						
			Hall 1						
			Hall 2						
M-MAS-35	M	Mastic, Black, Brittle	Kitchen Office	Assumed	NF	G	750	SF	10/04/21
			Storage 2						
			Storage 4						
			Hall 1						
			Hall 2						
S-SAT-37	S	Spray-Applied Texture, White, Chalky	Girl's Restroom 1	Assumed	NF	G	2,000	SF	10/04/21
			Boy's Restroom 1						
			Kitchen Restroom						
			Kitchen Lockers						
			P.E. Restroom 1						
			P.E. Restroom 2						
M-GWB-38	M	Gypsum Wallboard, White, Chalky	Girl's Restroom 1	Assumed	NF	G	2,000	SF	10/04/21
			Boy's Restroom 1						
			Kitchen Restroom						
			Kitchen Lockers						
			P.E. Restroom 1						
			P.E. Restroom 2						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-JTC-39	S	Joint Compound, White, Chalky	Girl's Restroom 1	Assumed	NF	G	200	SF	10/04/21
			Boy's Restroom 1						
			Kitchen Restroom						
			Kitchen Lockers						
			P.E. Restroom 1						
			P.E. Restroom 2						
M-GWB-40	M	Gypsum Wallboard, White, Chalky	Electrical 1	Assumed	NF	G	450	SF	10/04/21
S-JTC-41	S	Joint Compound, White, Chalky	Electrical 1	Assumed	NF	G	45	SF	10/04/21
M-CPT-43	M	Carpet, Brown, Fibrous	Storage 3	Assumed	NF	G	550	SF	10/04/21
M-MAS-44	M	Mastic, Yellow, Brittle	Storage 3	Assumed	NF	G	550	SF	10/04/21
M-GAS-45	M	Gasket, 8", Black, Vinyl-Like	Storage 3	Assumed	NF	G	1	SF	10/04/21
M-GWT-46	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Lobby	Assumed	NF	G	1,800	SF	10/04/21
			Girl's Restroom 1						
			Boy's Restroom 1						
			Girl's Locker Room						
			Boy's Locker Room						
M-GWT-47	M	Glazed Wall Tile, 4"X4", Brown, Smooth	Lobby	Assumed	NF	G	1,800	SF	10/04/21
			Girl's Restroom 1						
			Boy's Restroom 1						
			Girl's Locker Room						
			Boy's Locker Room						
M-GRT-48	M	Grout, Gray, Cementitious	Lobby	Assumed	NF	G	360	SF	10/04/21
			Girl's Restroom 1						
			Boy's Restroom 1						
			Girl's Locker Room						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Locker Room						
M-CMT-49	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth, White Specks	Girl's Locker Room	Assumed	NF	G	2,000	SF	10/04/21
			Boy's Locker Room						
M-GRT-50	M	Grout, Gray, Cementitious	Girl's Locker Room	Assumed	NF	G	200	SF	10/04/21
			Boy's Locker Room						
M-MRT-51	M	Mortar (Glass Block), Gray, Cementitious,	Exterior	Assumed	NF	G	40	SF	10/04/21
M-SLT-52	M	Sealant (Doors), Tan, Pliable	Lobby	Assumed	NF	G	25	SF	10/04/21
			Gym						
			Storage 4						
			Hall 1						
			Girl's Locker Room						
			Boy's Locker Room						
			Hall 2						
			Exterior						
M-GWB-53	M	Gypsum Wallboard, White, Chalky, Vinyl Cover	Lobby	Assumed	NF	G	500	SF	10/04/21
S-JTC-54	S	Joint Compound, White, Chalky	Lobby	Assumed	NF	G	50	SF	10/04/21
M-GWB-57	M	Gypsum Wallboard, White, Chalky	Storage 4	Assumed	NF	G	400	SF	10/04/21
S-JTC-58	S	Joint Compound, White, Chalky	Storage 4	Assumed	NF	G	40	SF	10/04/21
M-PLA-59	M	Plaster, Gray, Cementitious	Girl's Locker Room	Assumed	NF	G	5,000	SF	10/04/21
			Boy's Locker Room						
M-CON-60	M	Concrete (Foundation), Gray, Cementitious	Lobby	Assumed	NF	G	27,800	SF	10/04/21
			Girl's Restroom 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 1						
			Kitchen						
			Kitchen Office						
			Kitchen Restroom						
			Kitchen Lockers						
			Storage 1						
			Electrical 1						
			Storage 2						
			Hall 3						
			Stage						
			East Wing						
			Music						
			Guitar Lab						
			Listening						
			Keyboard Lab						
			Storage 3						
			Cafeteria						
			Gym						
			Storage 4						
			Hall 1						
			Girl's Locker Room						
			P.E. Storage						
			P.E. Office 1						
			P.E. Restroom 1						
			P.E. Restroom 2						
			P.E. Office 2						
			Storage 5						
			Boy's Locker Room						
			Hall 2						
			Exterior						
M-EXJ-61	M	Expansion Joint, Gray, Pliable	Exterior	Assumed	NF	G	150	SF	10/04/21
M-CON-62	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	8,000	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-QPT-63	M	Quarry/Paver Tile, 4"X16", Red, Cementitious	Exterior	Assumed	NF	G	250	SF	10/04/21
M-GRT-64	M	Grout, Gray, Cementitious	Exterior	Assumed	NF	G	25	SF	10/04/21
M-QPT-65	M	Quarry/Paver Tile, 4"X8", Red, Smooth	Exterior	Assumed	NF	G	250	SF	10/04/21
S-STU-66	S	Stucco, Gray, Cementitious	Exterior	Assumed	NF	G	100	SF	10/04/21
M-BUR-67	M	Built-Up Roofing, Black, Asphaltic, Gravel Cap	Roof	Assumed	NF	G	28,000	SF	10/04/21
M-MAS-68	M	Mastic (Penetrations And Flashings), Black, Tar-Like, Silver	Roof	Assumed	NF	G	1,500	SF	10/04/21
M-APR-69	M	Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Tan Mineral Cap	Roof	Assumed	NF	G	400	SF	10/04/21
M-SLT-70	M	Sealant (Equipment), White, Pliable	Roof	Assumed	NF	G	20	SF	10/04/21
M-SLT-71	M	Sealant (Flashings), Gray, Pliable, Silver	Roof	Assumed	NF	G	75	SF	10/04/21

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-SLT-10	M	Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable	Classroom I-2	Assumed	NF	G	100	SF	10/04/21
			Classroom I-3						
			Classroom I-4						
			Classroom I-5						
			Classroom I-6						
			Classroom I-7						
			Resource I-8						
			Classroom I-9						
			Storage 3						
			Storage 4						
			Workroom						
			Office 2						
			Storage 6						
			Boy's Restroom 2						
			Storage 7						
			Girl's Restroom 2						
			Storage 8						
			Janitor						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Storage 5						
			Music Office						
			Electrical						
			Music						
			Classroom J-2						
			Classroom J-3						
			Classroom J-4						
			Classroom J-5						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom J-6						
			Classroom J-7						
			Classroom J-7 TO						
			Classroom J-7 Shower						
			Classroom J-7 Restroom						
			Classroom J-9						
			Storage 1						
			Office 1						
			Storage 2						
M-FDI-11	M	Fire Door Insulation, Metal/Wood Cladding	Classroom I-2	Assumed	NF	G	1,134	SF	10/04/21
			Classroom I-3						
			Classroom I-4						
			Classroom I-5						
			Classroom I-6						
			Classroom I-7						
			Resource I-8						
			Classroom I-9						
			Storage 3						
			Storage 4						
			Workroom						
			Office 2						
			Storage 6						
			Boy's Restroom 2						
			Storage 7						
			Girl's Restroom 2						
			Storage 8						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Storage 5						
			Music Office						
			Electrical						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Music						
			Classroom J-2						
			Classroom J-3						
			Classroom J-4						
			Classroom J-5						
			Classroom J-6						
			Classroom J-7						
			Classroom J-9						
			Office 1						
			Storage 2						
			Courtyard 1						
			Courtyard 2						
			Exterior						
M-PSL-12	M	Pipe Sealant (Fire Sprinklers), White, Pliable	Classroom I-2	Assumed	NF	G	75	SF	10/04/21
			Classroom I-3						
			Classroom I-4						
			Classroom I-5						
			Classroom I-6						
			Classroom I-7						
			Resource I-8						
			Classroom I-9						
			Storage 3						
			Storage 4						
			Workroom						
			Office 2						
			Storage 6						
			Boy's Restroom 2						
			Storage 7						
			Girl's Restroom 2						
			Storage 8						
			Janitor						
			Boy's Restroom 1						
			Girl's Restroom 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 3						
			Boy's Restroom 3						
			Storage 5						
			Practice Room						
			Music Office						
			Electrical						
			Music						
			Classroom J-2						
			Classroom J-3						
			Classroom J-4						
			Classroom J-5						
			Classroom J-6						
			Classroom J-7						
			Classroom J-7 TO						
			Classroom J-7 Shower						
			Classroom J-7 Restroom						
			Classroom J-9						
			Storage 1						
			Office 1						
			Storage 2						
M-VCT-14	M	Vinyl Composition Tile, 12"X12", White, Smooth, Gray Streaks	Storage 3	Assumed	NF	G	2,200	SF	10/04/21
			Storage 4						
			Storage 6						
			Storage 7						
			Storage 8						
			Janitor						
			Storage 5						
			Music Office						
			Electrical						
			Classroom J-7						
			Storage 1						
			Office 1						



MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-MAS-15	M	Mastic, Black, Brittle	Storage 3	Assumed	NF	G	2,200	SF	10/04/21
			Storage 4						
			Storage 6						
			Storage 7						
			Storage 8						
			Janitor						
			Storage 5						
			Music Office						
			Electrical						
			Classroom J-7						
			Storage 1						
			Office 1						
M-SLT-16	M	Sealant (Windows), Black, Gummy	Office 2	Assumed	NF	G	6	SF	10/04/21
			Music Office						
			Music						
			Classroom J-7						
			Room J-7 TO						
			Exterior						
S-SAT-17	S	Spray-Applied Texture, White, Chalky	Boy's Restroom 2	Assumed	NF	G	2,500	SF	10/04/21
			Girl's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Room J-7 Shower						
			Room J-7 Restroom						
M-GWB-18	M	Gypsum Wallboard, White, Chalky	Boy's Restroom 2	Assumed	NF	G	2,500	SF	10/04/21
			Girl's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Girl's Restroom 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 3						
			Room J-7 Shower						
			Room J-7 Restroom						
S-JTC-19	S	Joint Compound, White, Chalky	Boy's Restroom 2	Assumed	NF	G	250	SF	10/04/21
			Girl's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Room J-7 Shower						
			Room J-7 Restroom						
M-GWT-20	M	Glazed Wall Tile, 4"X4", White, Smooth, Peppered	Boy's Restroom 2	Assumed	NF	G	3,000	SF	10/04/21
			Girl's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Room J-7 Shower						
			Room J-7 Restroom						
M-GWT-21	M	Glazed Wall Tile (Pattern), 2"X2", Black, Smooth	Boy's Restroom 2	Assumed	NF	G	100	SF	10/04/21
			Girl's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Room J-7 Shower						
			Room J-7 Restroom						
M-GRT-22	M	Grout, Gray, Cementitious	Boy's Restroom 2	Assumed	NF	G	300	SF	10/04/21
			Girl's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 1						
			Girl's Restroom 1						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Room J-7 Shower						
			Room J-7 Restroom						
M-CMT-23	M	Ceramic Mosaic Tile, 2"X2", White, Smooth, Peppered	Boy's Restroom 2	Assumed	NF	G	2,200	SF	10/04/21
			Girl's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Room J-7 Shower						
			Room J-7 Restroom						
M-GRT-24	M	Grout, Gray, Cementitious	Boy's Restroom 2	Assumed	NF	G	220	SF	10/04/21
			Girl's Restroom 2						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Girl's Restroom 3						
			Boy's Restroom 3						
			Room J-7 Shower						
			Room J-7 Restroom						
M-SAC-25	M	Sink Acoustical Coating, Black, Rough	Classroom I-2	Assumed	NF	G	26	SF	10/04/21
			Classroom I-3						
			Classroom I-4						
			Classroom I-5						
			Classroom I-6						
			Resource I-8						
			Workroom						
			Music						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom J-2						
			Classroom J-3						
			Classroom J-4						
			Classroom J-5						
			Classroom J-6						
M-GAS-28	M	Gasket, 8", Black, Vinyl-Like	Storage 5	Assumed	NF	G	1	SF	10/04/21
S-TOT-29	S	Troweled-On Texture, White, Chalky	Janitor	Assumed	NF	G	500	SF	10/04/21
			Electrical						
M-GWB-30	M	Gypsum Wallboard, White, Chalky	Janitor	Assumed	NF	G	500	SF	10/04/21
			Electrical						
S-JTC-31	S	Joint Compound, White, Chalky	Janitor	Assumed	NF	G	50	SF	10/04/21
			Electrical						
M-ADH-32	M	Adhesive (FRP), Brown, Brittle	Janitor	Assumed	NF	G	10	SF	10/04/21
M-GWB-33	M	Gypsum Wallboard, White, Chalky	Storage 6	Assumed	NF	G	200	SF	10/04/21
			Storage 8						
S-JTC-34	S	Joint Compound, White, Chalky	Storage 6	Assumed	NF	G	20	SF	10/04/21
			Storage 8						
M-BRK-35	M	Brick, 4"X16", Tan, Cementitious	Courtyard 1	Assumed	NF	G	22,000	SF	10/04/21
			Courtyard 2						
			Exterior						
M-BRK-36	M	Brick, 4"X16", Red, Cementitious	Courtyard 1	Assumed	NF	G	22,000	SF	10/04/21
			Courtyard 2						
			Exterior						
M-MRT-37	M	Mortar, Gray, Cementitious	Courtyard 1	Assumed	NF	G	4,400	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Courtyard 2						
			Exterior						
M-EXJ-38	M	Expansion Joint, Brown, Pliable	Courtyard 1	Assumed	NF	G	100	SF	10/04/21
			Courtyard 2						
			Exterior						
M-SLT-39	M	Sealant (Doors), Tan, Pliable	Courtyard 1	Assumed	NF	G	50	SF	10/04/21
			Courtyard 2						
			Exterior						
M-CON-40	M	Concrete (Entries), Gray, Cementitious	Courtyard 1	Assumed	NF	G	6,000	SF	10/04/21
			Courtyard 2						
			Exterior						
M-CON-41	M	Concrete (Courtyards), Gray, Cementitious, Gravel Finish	Courtyard 1	Assumed	NF	G	1,500	SF	10/04/21
			Courtyard 2						
M-BRK-42	M	Brick (Planters), 4"X16", Red, Cementitious, White	Courtyard 1	Assumed	NF	G	1,000	SF	10/04/21
			Courtyard 2						
M-MRT-43	M	Mortar, Gray, Cementitious	Courtyard 1	Assumed	NF	G	100	SF	10/04/21
			Courtyard 2						
M-CMU-44	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	Exterior	Assumed	NF	G	500	SF	10/04/21
M-CMU-45	M	Concrete Masonry Unit, 2"X16", Gray, Smooth	Exterior	Assumed	NF	G	10	SF	10/04/21
M-MRT-46	M	Mortar, Gray, Cementitious	Exterior	Assumed	NF	G	50	SF	10/04/21
M-QPT-47	M	Quarry/Paver Tile, 8"X8", Gray, Smooth	Exterior	Assumed	NF	G	1,500	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GRT-48	M	Grout, Gray, Cementitious	Exterior	Assumed	NF	G	150	SF	10/04/21
M-BUR-49	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	25,000	SF	10/04/21
M-MAS-50	M	Mastic (Penetrations And Flashings), Black, Tar-Like, Silver	Roof	Assumed	NF	G	1,500	SF	10/04/21
M-SLT-51	M	Sealant (Equipment), White, Pliable	Roof	Assumed	NF	G	10	SF	10/04/21
M-SLT-52	M	Sealant (Flashings), Gray, Pliable, Silver	Roof	Assumed	NF	G	50	SF	10/04/21

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Bldg700-Tbl.doc

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-APR-01	M	Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Tan Mineral Cap	Roof	Assumed	NF	G	400	SF	10/04/21
M-VBF-02	M	Vapor Barrier Felt, Black, Asphaltic	Roof	Assumed	NF	G	400	SF	10/04/21
M-CMU-03	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	Storage	Assumed	NF	G	1,200	SF	10/04/21
			Exterior						
M-MRT-04	M	Mortar, Gray, Cementitious	Storage	Assumed	NF	G	120	SF	10/04/21
			Exterior						
M-CON-05	M	Concrete (Foundation), Gray, Cementitious	Storage	Assumed	NF	G	400	SF	10/04/21
			Exterior						
M-CON-06	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	200	SF	10/04/21

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Storage-Tbl.doc

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-STU-01	S	Stucco, Gray, Cementitious	Canopy	Assumed	NF	G	40,000	SF	10/04/21
M-SLT-02	M	Sealant, Gray, Pliable	Canopy	Assumed	NF	G	250	SF	10/04/21

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Canopy-Tbl.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4330 1201 123165 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-PLA-01, Plaster, Gray, Cementitious

**Type of Asbestos-Containing Material:** ① Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\01.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 438012316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-SAT-02, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** ☒ Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\02.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 438012501236 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-GWB-03, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\03.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/21/21 Person performing reinspection: Carly Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4380/2501/23/65 Signature of Inspector: Craig Rehl

\*Material Reinspected: S-JTC-04, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\04.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4310 D5012364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BRK-05, Brick, 4"X16", Tan, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

#### Assessment:

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

#### Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\05.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/0/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4380 125112469 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-BRK-06, Brick, 4"X16", Red, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\06.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 438012501123166 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-MRT-07, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\07.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHRA certification number: 4380 1250 1236 Signature of Inspector: Carbyn Hall  
\*Material Reinspected: M-EXJ-08, Expansion Joint, Brown, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\08.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4380 12001 0369 Signature of Inspector: Carlyn Hall

\*Material Reinspected: M-QPT-09, Quarry/Paver Tile, 6"X6", Gray, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No

Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No

Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No

Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐

Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\09.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 4580120123165 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-GRT-10, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\10.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conyn Hill  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 4370 12501125165 Signature of Inspector: Conyn Hill  
\*Material Reinspected: M-FDI-11, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☒ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\11.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 4380125012014 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-12, Sealant (Doors, Millwork, Fixtures), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\12.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 437012501123165 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-PSL-13, Pipe Sealant (Fire Sprinklers), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\13.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbin Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4370125012365 Signature of Inspector: Corbin Hall

\*Material Reinspected: M-GWT-14, Glazed Wall Tile, 4"X4", Tan, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\14.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4386125612514 Signature of Inspector: Conbyn Hall

\*Material Reinspected: M-GWT-15, Glazed Wall Tile, 4"X4", Brown, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\15.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cortyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 43801250123169 Signature of Inspector: Cortyn Hall

\*Material Reinspected: M-GRT-16, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No

Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No

Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\16.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carly Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 438120120169 Signature of Inspector: Carly Hall

\*Material Reinspected: M-CMT-17, Ceramic Mosaic Tile, 2"X2", Tan, Smooth, White Specks

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\17.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4380120112345 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-18, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\18.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 43501200112119 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-24, Sealant (Windows), Brown, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\24.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cortyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 4510125912369 Signature of Inspector: Cortyn Hall

\*Material Reinspected: M-SAC-25, Sink Acoustical Coating, Black, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\25.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 431012821236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VCT-31, Vinyl Composition Tile, 12"X12", Tan, Smooth, Brown Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\31.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 438012511236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-32, Mastic, Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\32.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4380123212345 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-WAB-33, Wallbase (Coved), 4", Black, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: \_\_\_\_\_ High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: \_\_\_\_\_ High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\33.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Ceryn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 438012001236 Signature of Inspector: Ceryn Hall

\*Material Reinspected: M-ADH-34, Adhesive, Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No

Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No

Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\34.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hull  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 43861200123466 Signature of Inspector: Corbyn Hull

\*Material Reinspected: M-SLT-35, Sealant (Windows), Black, Gummy

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find       

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain:       

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain:       

**Assessment:**

Evidence of Physical Damage:        Yes / No  
Evidence of Water Damage:        Yes / No  
Evidence of Delamination or Other Damage:        Yes / No  
Explain:       

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection?        Yes / No  
Explain:       

Degree of Accessibility of the Material: High        Medium ✓ Low         
Degree of Activity Near the Material: High ✓ Medium        Low         
Location in an Air Plenum, Air Shaft, or Airstream:        Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed?        Yes / No  
Explain:       

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\35.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerby, Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 4390125012065 Signature of Inspector: Cerby Hall

\*Material Reinspected: M-GWB-38, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\38.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 43801250112345 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-39, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\39.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4385 1234 1234 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-GWT-40, Glazed Wall Tile, 4"X6", Brown, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\40.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cory Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4380 12581/2369 Signature of Inspector: Cory Hall

\*Material Reinspected: M-GRT-41, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes ☐ No ☒  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes ☐ No ☒  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes ☐ No ☒  
Evidence of Water Damage: \_\_\_\_\_ Yes ☐ No ☒  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes ☐ No ☒  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes ☐ No ☒  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes ☐ No ☒

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes ☐ No ☒  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\41.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4386126612369 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-CON-42, Concrete (Entries), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place / 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High / Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High / Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\42.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 438012001284 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-43, Sealant (Doors), Tan, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\43.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-44, Sealant (Windows), Brown, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\44.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 438612841284 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-SLT-45, Sealant (Windows), Black, Gummy

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\45.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4380125012314 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-STU-46, Stucco, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\46.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cortez Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 4380 1250102364 Signature of Inspector: Cortez Hall

\*Material Reinspected: M-CON-47, Concrete (Courtyard), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\47.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corby Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4380 12801 12314 Signature of Inspector: Corby Hall

\*Material Reinspected: M-BRK-48, Brick (Planters), 4"X16", Red, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\48.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conbyri Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 4580128212345 Signature of Inspector: Conbyri Hall

\*Material Reinspected: M-MRT-49, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\49.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4386125712369 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-BUR-50, Built-Up Roofing, Black, Asphaltic, Gravel Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\50.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4380 2501/2316 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-MAS-51, Mastic (Penetrations and Flashings), Black, Tar-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\51.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 438012341234 Signature of Inspector: Carlyn Hall

\*Material Reinspected: M-APR-52, Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Tan Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carlyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100  
AHERA certification number: 450125d1236 Signature of Inspector: Carlyn Hall

\*Material Reinspected: M-SLT-53, Sealant (Equipment), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\53.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlynn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 100

AHERA certification number: 4388 127512849 Signature of Inspector: Carlynn Hall

\*Material Reinspected: M-SLT-54, Sealant (Flashings), Gray, Pliable, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg100\54.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 4580 1252112064 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-10, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ☒ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\10.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
AHERA certification number: 4380128112064 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SAC-11, Sink Acoustical Coating, Black, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\11.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
ASHERA certification number: 4380 123125 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-FDI-12, Fire Door Insulation, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\FORMS\Bldg200\12.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/14/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 431012512316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-PSL-13, Pipe Sealant (Fire Sprinklers), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\13.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 4380 DSC 1226 Signature of Inspector: Carbyn Hall

\*Material Reinspected: S-PLA-15, Plaster, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\15.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 4380 125d 1234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BRK-16, Brick, 4"X16", Tan, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\16.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 438012812316 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-BRK-17, Brick, 4"X16", Red, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\17.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 43701284123166 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-MRT-18, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\18.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
AHERA certification number: 4310125a1236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-EXJ-19, Expansion Joint, Brown, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\19.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
AHERA certification number: 4380 12001/2001 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-20, Sealant (Doors), Tan, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☐ Medium ☒ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\20.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
AHERA certification number: 438125812314 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-CON-21, Concrete (Equipment Pad), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Foms\Bldg200\21.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 437012341236 Signature of Inspector: Conbyn Hall

\*Material Reinspected: M-VCT-23, Vinyl Composition Tile, 12"X12", Tan, Smooth, Brown Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\23.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 4380122412367 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-24, Mastic, Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ☒ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\24.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 438012361236 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: S-SAT-25, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\25.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
AHERA certification number: 438012511236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWB-26, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\26.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 438012501234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-27, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\27.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
AHERA certification number: 4380120412316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-ADH-28, Adhesive (FRP), Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\28.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 458012611236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-29, Concrete (Foundation), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\29.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
AHERA certification number: 4380120012314 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-WAB-30, Wallbase (Coved), 4", Black, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\30.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
AHERA certification number: 437012812849 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-ADH-31, Adhesive, Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find       

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain:       

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain:       

**Assessment:**

Evidence of Physical Damage:        Yes / No  
Evidence of Water Damage:        Yes / No  
Evidence of Delamination or Other Damage:        Yes / No  
Explain:       

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection?        Yes / No  
Explain:       

Degree of Accessibility of the Material: High        Medium ✓ Low         
Degree of Activity Near the Material: High ✓ Medium        Low         
Location in an Air Plenum, Air Shaft, or Airstream:        Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed?        Yes / No  
Explain:       

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\31.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
AHERA certification number: 4380125011236 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-GWT-32, Glazed Wall Tile, 4"X6", Tan, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes No  
Evidence of Water Damage: \_\_\_\_\_ Yes No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? Yes No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? Yes No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\FORMS\Bldg200\32.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carby, Hail  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 438012501238 Signature of Inspector: Caron Hull

\*Material Reinspected: M-GWT-33, Glazed Wall Tile, 4"X6", Brown, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\33.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 4380120012366 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-GRT-34, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\34.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/14/21 Person performing reinspection: Corby Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 4380125112366 Signature of Inspector: Corby Hall

\*Material Reinspected: M-CMT-35, Ceramic Mosaic Tile, 2"X2", Tan, Smooth, White Specks

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\35.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 4350 1289 12369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-36, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc. ☒

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\36.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
AHERA certification number: 4580120012016 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-37, Sealant (Windows), Black, Gummy

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\37.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
AHERA certification number: 4380125162169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-QPT-38, Quarry/Paver Tile, 6"X6", Gray, Textured

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\38.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
AHERA certification number: 14381251234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-39, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\39.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 4580125017306 Signature of Inspector: Carlyn Hall

\*Material Reinspected: M-SLT-42, Sealant (Windows), Brown, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\42.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 43801251236 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-CON-43, Concrete (Entries), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\43.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 430025412369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-44, Concrete (Courtyards), Gray, Cementitious, Gravel Finish

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\44.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 438012512365 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BRK-45, Brick (Planters), 4"X16", Red, Cementitious, White

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\45.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260.

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200  
ASHERA certification number: 43801254125169 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-MRT-46, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\46.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/14/21 Person performing reinspection: Carlynn Hull  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 43801250125069 Signature of Inspector: Carlynn Hull

\*Material Reinspected: S-STU-47, Stucco, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\47.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 4380125012367 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-48, Sealant (Walls), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find       

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain:       

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain:       

**Assessment:**

Evidence of Physical Damage:        Yes / No  
Evidence of Water Damage:        Yes / No  
Evidence of Delamination or Other Damage:        Yes / No  
Explain:       

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection?        Yes / No  
Explain:       

Degree of Accessibility of the Material: High        Medium ✓ Low         
Degree of Activity Near the Material: High ✓ Medium        Low         
Location in an Air Plenum, Air Shaft, or Airstream:        Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed?        Yes / No  
Explain:       

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\48.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 438012561244 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BUR-49, Built-Up Roofing, Black, Asphaltic, Gravel Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes ☐ No ☒  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes ☐ No ☒  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\49.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 4385125d1254 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-50, Mastic (Penetrations and Flashings), Black, Tar-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\50.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 438012501 bslc Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-APR-51, Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Tan Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\51.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 4501281123161 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-52, Sealant (Equipment), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\52.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 200

AHERA certification number: 438025012316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-53, Sealant (Flashings), Gray, Pliable, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg200\53.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4310120112369 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-SLT-10, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☒ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\10.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 450125112314 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-SLT-11, Sealant (Windows), Black, Gummy

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ☒ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\11.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4310 1251 121/14 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-FDI-12, Fire Door Insulation, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\12.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 43761200123161 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-13, Mortar (Glass Block), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\13.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300  
AHRA certification number: 4090 12511216 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-PSL-15, Pipe Sealant (Fire Sprinklers), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\15.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conbyn 494  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4870 1250 1234 Signature of Inspector: C. Bull

\*Material Reinspected: M-GWB-16, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\16.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbett Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4350 12216 Signature of Inspector: Curtis Hall

\*Material Reinspected: S-JTC-17, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** (1) Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\17.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4380126012314 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-SAC-18, Sink Acoustical Coating, Black, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\18.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 45851250123165 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BRK-19, Brick, 4"X16", Tan, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\19.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/14/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 438012501123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BRK-20, Brick, 4"X16", Red, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\20.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4300120012004 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-MRT-21, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\21.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 40301250122169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-EXJ-22, Expansion Joint, Brown, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\22.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corby Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 438125212364 Signature of Inspector: Corby Hall

\*Material Reinspected: M-VCT-23, Vinyl Composition Tile, 12"X2", Tan, Smooth, Brown Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\23.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 430012001123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-24, Mastic, Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\FORMS\Bldg300\24.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 438126123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-WAB-25, Wallbase (Coved), 4", Black, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\25.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 438P12512316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-ADH-26, Adhesive, Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\26.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4380125412451 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-SAT-27, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** ☒ 1. Surf. ☐ 2. TSI ☒ 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\27.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 43812512844 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-GWB-28, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\28.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corby Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4380125010367 Signature of Inspector: Corby Hall

\*Material Reinspected: S-JTC-29, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\29.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4380125412369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWB-30, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\30.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 438012551220167 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-31, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\31.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 43612212069 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-ADH-32, Adhesive (FRP), Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\32.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4386125612016 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-GAS-33, Gasket, 8", Black, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\33.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 43X125012364 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-VCT-34, Vinyl Composition Tile, 12"X12", White, Smooth, Gray Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\34.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4380125612361 Signature of Inspector: Carlyn Hall

\*Material Reinspected: M-MAS-35, Mastic, Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\35.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4370125012316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-36, Concrete (Foundation), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\36.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4380128012316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-37, Concrete (Entries), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\37.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 43801281123165 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-38, Sealant (Doors), Tan, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\38.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 43801201236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-39, Sealant (Windows), Brown, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\39.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300  
AHRA certification number: 4380 12501 12316 Signature of Inspector: Carbyn Hall

\*Material Reinspected: S-STU-40, Stucco, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\40.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4380125612369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BUR-41, Built-Up Roofing, Black, Asphaltic, Gravel Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\41.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Reul  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 4380128412349 Signature of Inspector: Corbyn Reul

\*Material Reinspected: M-MAS-42, Mastic (Penetrations and Flashings), Black, Tar-Like, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\42.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300  
AHERA certification number: 438012501231ca Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-APR-43, Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Tan Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\43.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300

AHERA certification number: 43812581234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-44, Sealant (Equipment), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\44.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 300  
AHERA certification number: 408012501/2369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-45, Sealant (Flashing), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg300\45.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400  
AHERA certification number: 4380123212364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-10, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\10.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4380125012316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-11, Sealant (Windows), Black, Gummy

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\11.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 43801201123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-FDI-12, Fire Door Insulation, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\12.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4530125412369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-PSL-14, Pipe Sealant (Fire Sprinklers), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No

Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\14.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400  
AHERA certification number: 4380 12512069 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-SAT-15, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\15.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 43801250123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWB-16, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\16.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400  
AHERA certification number: 43801250123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-17, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\17.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4370 1201 12516 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-ADH-19, Adhesive (WAB), Cream, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\19.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4380 1230 1234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VCT-20, Vinyl Composition Tile, 12"x12", Tan, Smooth, Brown Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\20.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4388125012369 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-MAS-21, Mastic, Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\21.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4380 12501236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SAC-23, Sink Acoustical Coating, Black, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\23.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400  
AHERA certification number: 43801250112349 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VCT-24, Vinyl Floor Tile, 12"x12", White, Smooth, Gray Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\24.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400  
AHERA certification number: 4380 125d 12514 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-25, Mastic, Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\25.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4380125212316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-WAB-26, Wallbase (Coved), 4", Dark Gray, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\26.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4380 1251 1236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-ADH-27, Adhesive, Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\27.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4380125012306 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWB-28, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\28.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4380123123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-29, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\29.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4370 125012365 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-30, Concrete (Foundation), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\FORMS\Bldg400\30.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4380 12501 23169 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-CON-31, Concrete (Entries), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\31.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conryn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4380 1234 1234 Signature of Inspector: Conryn Hall

\*Material Reinspected: M-BRK-32, Brick, 4"x16", Tan, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\32.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbri Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4386 12561 12369 Signature of Inspector: Carbri Hall

\*Material Reinspected: M-BRK-33, Brick, 4"x16", Red, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\33.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 438012521236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-34, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\34.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/14/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400  
AHERA certification number: 435012221236 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-EXJ-35, Expansion, Tan, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\35.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4380125012316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-36, Sealant (Doors), Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\36.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400  
AHERA certification number: 480 125112365 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-37, Sealant (Windows), B Lack, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\37.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 438012501120169 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-GAS-39, Gasket, 8", Black, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\39.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400  
AHERA certification number: 43801250112365 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BUR-40, Built-Up Roofing, Black, Asphaltic, Gravel Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No

Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\40.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hill  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 4380 B501 2369 Signature of Inspector: Corbyn Hill

\*Material Reinspected: M-MAS-41, Mastic (Penetrations and Flashing), Black, Tar-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\41.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400  
AHERA certification number: 43861282123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-APR-42, Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Tan Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\42.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 438012501120109 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-43, Sealant (Equipment), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\43.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 430812501230109 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-44, Sealant (Flashing), Gray, Pliable, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\44.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 400

AHERA certification number: 43801284/2014 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-STU-45, Stucco, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\FORMS\Bldg400\45.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 400  
AHERA certification number: 438012341234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-46, Sealant (Windows), Brown, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg400\46.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cambryn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 4380125216064 Signature of Inspector: Cambryn Hall

\*Material Reinspected: M-SLT-52, Sealant (Flashings), Gray, Pliable, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\52.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 4300125012259 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-SLT-51, Sealant (Equipment), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\51.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 4380 1234 1234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-APR-50, Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Tan Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\50.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 436012011234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-49, Mastic (Penetrations and Flashings), Black, Tar-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\49.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 4300 12501 12369 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-BUR-48, Built-Up Roofing, Black, Asphaltic, Gravel Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\FORMS\Bldg500\48.doc





Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 4350125012501 Signature of Inspector: Carbyn Hall  
\*Material Reinspected: M-WDB-47, Woven Duct Boot, 4", Black, Vinyl-Like

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\47.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 438212612064 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-46, Sealant (Duct), Gray, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conby, Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 14380 Dec 123164 Signature of Inspector: Coryn Bull

\*Material Reinspected: M-CON-45, Concrete (Equipment Pad), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\45.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 438-12511234 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-SLT-44, Sealant (Windows), Brown, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\44.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 4380128112369 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-SLT-43, Sealant (Doors), Tan, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\43.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 4500 12d1369 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-EXJ-42, Expansion Joint, Brown, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\42.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 43012501234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-41, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\41.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlynn Hull

Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 4301256124 Signature of Inspector: Carlynn Hull

\*Material Reinspected: M-BRK-40, Brick, 4"x16", Red, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No

Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No

Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\40.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 124025012964 Signature of Inspector: Carlyn Hall  
\*Material Reinspected: M-BRK-39, Brick, 4"x16", Tan, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\39.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 4380 b2 12345 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-CON-38, Concrete (Entries), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\38.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 438062512345 Signature of Inspector: Carbyn Hall  
\*Material Reinspected: S-JTC-37, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\37.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/11/21 Person performing reinspection: Carmen Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 43651252164 Signature of Inspector: Carmen Hall  
\*Material Reinspected: M-GWB-36, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\36.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/14/21 Person performing reinspection: Corsyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 4300125112364 Signature of Inspector: Corsyn Hall

\*Material Reinspected: M-GAS-35, Gasket, 6", Black, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\35.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hull  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 4300125012369 Signature of Inspector: Corbyn Hull  
\*Material Reinspected: S-JTC-32, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** ①. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\32.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 4380/252/6359 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-VCT-26, Vinyl Composition Tile, 12"x12", Blue, Smooth, Light Blue Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\26.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 436 120 1364 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-GWB-31, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/12 Person performing reinspection: Carly Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 4382122112366 Signature of Inspector: Carly Hall

\*Material Reinspected: S-SAT-30, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** ① Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\30.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/11/21 Person performing reinspection: Carlynn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 4380 125012236 Signature of Inspector: Carlynn Hall

\*Material Reinspected: M-ADH-29, Adhesive, Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\29.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 43801250112314 Signature of Inspector: Carbyn Hall  
\*Material Reinspected: M-WAB-28, Wallbase (Coved), 4", Blue, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Frms\Bldg500\28.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 43861250123456 Signature of Inspector: Cyrus Rull

\*Material Reinspected: M-MAS-27, Mastic, Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\27.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbony Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 43801250112366 Signature of Inspector: Carbony Hall

\*Material Reinspected: M-VCT-25, Vinyl Composition Tile, 12"x12", White, Smooth, Blue Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\25.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 43701283123169 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-MAS-24, Mastic, Tan, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☒ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☒ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\24.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 43802512006 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-CPT-23, Carpet, Brown, Fibrous

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\23.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerby Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 4501250123169 Signature of Inspector: Cerby Hall

\*Material Reinspected: M-SAC-22, Sink Acoustical Coating, Gray, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☒ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☒ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\22.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conbyr Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 43801250112349 Signature of Inspector: Conbyr Hall

\*Material Reinspected: M-SLT-19, Sealant (Windows), Black, Gummy

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\19.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 4380123164724 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-CON-18, Concrete (Foundation), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\18.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 45801250112069 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-MAS-17, Mastic, Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\17.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 4380125012365 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VCT-16, Vinyl Composition Tile, 12"x12", Tan, Smooth, Brown Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\16.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 43801259122167 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-PSL-15, Pipe Sealant (Fire Sprinklers), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\15.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 4380125812369 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-SLT-14, Sealant (Duct), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes ☐ No ☒  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes ☐ No ☒  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes ☐ No ☒  
Evidence of Water Damage: \_\_\_\_\_ Yes ☐ No ☒  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes ☐ No ☒  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes ☐ No ☒  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes ☐ No ☒

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes ☐ No ☒  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\14.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 4380 12501236 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-SAC-12, Sink Acoustical Coating, Black, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ☒ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\12.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500  
AHERA certification number: 4380125412869 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-11, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ☒ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\11.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 500

AHERA certification number: 4380125012364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-FDI-10, Fire Door Insulation, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg500\10.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/14/21 Person performing reinspection: Camryn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 43802811216 Signature of Inspector: Camryn Hall

\*Material Reinspected: M-BRK-06, Brick, 4"x16", Tan, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\06.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 43012012367 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-BRK-07, Brick, 4"x16", Red, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\07.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 438125d12314 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-MRT-08, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\08.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4350 b51056 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-EXJ-09, Expansion Joint, Brown, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\09.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 43012012314 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-10, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\10.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4320/200/2344 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-SAC-11, Sink Acoustical Coating, Black, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\11.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conborn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4380 1250 1236 Signature of Inspector: Conborn Hall

\*Material Reinspected: M-SLT-12, Sealant (Windows), Black, Gummy

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\12.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4370/2501/23/21 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-FDI-17, Fire Door Insulation, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\17.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4310 121123149 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-PSL-19, Pipe Sealant (Fire Sprinklers), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\19.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4380 1221 1236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-WAB-22, Wallbase (Coved), 4", Black, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\22.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380125112369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-ADH-23, Adhesive, Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\23.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4388122123169 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-VST-24, Vinyl Stair Tread, 12"x36", Tan, Textured, Diamond Pattern

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\24.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4386125011236 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-MAS-25, Mastic, Yellow, Tacky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☒ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\25.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4381281W149 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-VCT-26, Vinyl Composition Tile, 12"x12", White, Smooth, Gray Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\26.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4390 D501 B269 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-27, Mastic, Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\27.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 43801200112349 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VCT-28, Vinyl Composition Tile (Pattern), 12"x12", Brown, Smooth, White Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\28.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4080 128012362 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-QPT-32, Quarry/Paver Tile, 6"x6", Red, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\32.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380 D581 B364 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-GRT-33, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\33.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4301250123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VCT-34, Vinyl Composition Tile, 12"x12", Tan, Smooth, Brown Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\34.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHRA certification number: 438012312364 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-MAS-35, Mastic, Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\35.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380125512369 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: S-SAT-37, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\37.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4382 1201/2016 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-GWB-38, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\38.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4301201123169 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: S-JTC-39, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\39.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380 Bldg 600 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-GWB-40, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3.) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\40.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Couryn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380 1/501/2019 Signature of Inspector: Couryn Hall  
\*Material Reinspected: S-JTC-41, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\41.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380201206 Signature of Inspector: Carbyn Hall  
\*Material Reinspected: M-CPT-43, Carpet, Brown, Fibrous

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\43.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4386 b281123164 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-MAS-44, Mastic, Yellow, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\44.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4380 12001236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GAS-45, Gasket, 8", Black, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\45.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/14/21 Person performing reinspection: Conby, Kell  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4372 Dec 12/14 Signature of Inspector: Conby Kell  
\*Material Reinspected: M-GWT-46, Glazed Wall Tile, 4"x4", Tan, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\46.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4580 12501 12314 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-GWT-47, Glazed Wall Tile, 4"x4", Brown, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\FORMS\Bldg600\47.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4390122112369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-48, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No


**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\48.doc



Reinspection Date: 10/4/21 Person performing reinspection: Compton Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4300 Bay Oaks Signature of Inspector: Compton Hall  
\*Material Reinspected: M-CMT-49, Ceramic Mosaic Tile, 2"x2", Tan, Smooth, White Specks

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\49.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Cerby Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 430012012345 Signature of Inspector: Cerby Hall  
\*Material Reinspected: M-GRT-50, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\50.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conryn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHRA certification number: 438 1251206 Signature of Inspector: Conryn Hall  
\*Material Reinspected: M-MRT-51, Mortar (Glass Block), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\51.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380 12512364 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-SLT-52, Sealant (Doors), Tan, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\52.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbony Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4326 1201 12069 Signature of Inspector: Carbony Hall  
\*Material Reinspected: M-GWB-53, Gypsum Wallboard, White, Chalky, Vinyl Cover

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\53.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carly Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 43012501226 Signature of Inspector: Carly Hall  
\*Material Reinspected: S-JTC-54, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\54.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380 D001234 Signature of Inspector: Carbyn Hall  
\*Material Reinspected: M-GWB-57, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\57.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380/2581/2316 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: S-JTC-58, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\58.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hull  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4380 120128169 Signature of Inspector: Corbyn Hull

\*Material Reinspected: M-PLA-59, Plaster, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\59.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hull  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4300820112064 Signature of Inspector: Corbyn Hull  
\*Material Reinspected: M-CON-60, Concrete, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\60.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 430 1251 1236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-EXJ-61, Expansion Joint, Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\61.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4380 12301128/69 Signature of Inspector: Conyn Hall

\*Material Reinspected: M-CON-62, Concrete (Entries), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\62.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 430 1250 1236 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-QPT-63, Quarry/Paver Tile, 4"x16", Red, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\63.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380128012346 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-GRT-64, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\64.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380 12501 12364 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-QPT-65, Quarry/Paver Tile, 4"x8", Red, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ☒ 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\65.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 43001251236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-STU-66, Stucco, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\66.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 430120112361 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-BUR-67, Built-Up Roofing, Black, Asphaltic, Gravel Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\67.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 430 123 123 67 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-68, Mastic (Penetrations and Flashing), Black, Tar-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\68.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380 D-0112362 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-APR-69, Asphalt Prepared Roofing (Rolled), Black, Asphaltic, Tan Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\69.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/11/21 Person performing reinspection: Carly Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600  
AHERA certification number: 4380 12801 123169 Signature of Inspector: Carly Hall  
\*Material Reinspected: M-SLT-70, Sealant (Equipment), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\70.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 600

AHERA certification number: 4380 bsd 03/19 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-71, Sealant (Flashings), Gray, Pliable, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg600\71.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380125412345 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-10, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☒ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\10.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4360126112369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-FDI-11, Fire Door Insulation, Metal/Wood, Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\11.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carson Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380 1254 12569 Signature of Inspector: Carson Hall

\*Material Reinspected: M-PSL-12, Pipe Sealant (Fire Sprinklers), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\12.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 436012501236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VCT-14, Vinyl Composition Tile, 12"x12", White, Smooth, Gray Mottles

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\14.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380128123167 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-15, Mastic, Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\15.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380 1250 12365 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-16, Sealant (Windows), Black, Gummy

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\16.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conbyr Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4306212367 Signature of Inspector: Conbyr Hall

\*Material Reinspected: S-SAT-17, Spray-Applied Texture, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\17.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 430012001236 Signature of Inspector: Conbyn Hall

\*Material Reinspected: M-GWB-18, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\18.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 43801202112364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-19, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\19.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380120112369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-20, Glazed Wall Tile, 4"x4", White, Smooth, Peppered

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\20.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 43001200123161 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-21, Glazed Wall Tile, 4"x4", Black, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\21.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 430120112369 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-GRT-22, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\22.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 43801252125169 Signature of Inspector: Cyrus Hall

\*Material Reinspected: M-CMT-23, Ceramic Mosaic Tile, 2"x2", White, Smooth, Peppered

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\23.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/21/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 43801250123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-24, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\24.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 438122212121 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SAC-25, Sink Acoustical Coating, Black, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ☒ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

*\*Reference the original Management Plan for additional information.*

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\25.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4370 1281 12369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GAS-28, Gasket, 8", Black, Vinyl-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\28.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 439025012364 Signature of Inspector: Carbyn Hall

\*Material Reinspected: S-TOT-29, Troweled-On Texture, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\29.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/14/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 413065412345 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWB-30, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\30.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: S-JTC-31, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\31.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380 1282 12369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-ADH-32, Adhesive (FRP), Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\32.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380 D00112367 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWB-33, Gypsum Wallboard, White, Chalky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\33.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4381251234 Signature of Inspector: Carbyn Hall

\*Material Reinspected: S-JTC-34, Joint Compound, White, Chalky

**Type of Asbestos-Containing Material:** 1 Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\34.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4388128112369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BRK-35, Brick, 4"x16", Tan, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\35.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conryn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 436 12512029 Signature of Inspector: Conryn Hall

\*Material Reinspected: M-BRK-36, Brick, 4"x16", Red, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\36.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380 D6812316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-37, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\37.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4301241234 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-EXJ-38, Expansion Joint, Brown, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\38.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 43812501236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-39, Sealant (Doors), Tan, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ☒ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\39.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

ASHERA certification number: 438012511256 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-40, Concrete (Entries), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\40.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380 D21 D3169 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-CON-41, Concrete (Courtyards), Gray, Cementitious, Gravel Finish

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\41.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380128112319 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BRK-42, Brick (Planters), 4"x16", Red, Cementitious, White

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\42.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 43801251/236a Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-43, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\43.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380125112369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-44, Concrete Masonry Unit, 8"x16", Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\44.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4580125516361 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMU-45, Concrete Masonry Unit, 2"x16", Gray, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\45.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hull  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380120236 Signature of Inspector: Corbyn Hull

\*Material Reinspected: M-MRT-46, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\46.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380125012345 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-QPT-47, Quarry/Paver Tile, 8"x8", Gray, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\47.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4306 bsa 1236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-48, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\48.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380 1251/123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BUR-49, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\49.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/11/21 Person performing reinspection: Carbry Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4380125d 12316 Signature of Inspector: Carbry Hall

\*Material Reinspected: M-MAS-50, Mastic (Penetrations and Flashings), Black, Tar-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\50.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 43801254 1236 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-SLT-51, Sealant (Equipment), White, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\51.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: 700

AHERA certification number: 4280 / 250 / 1236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-52, Sealant (Flashings), Gray, Pliable, Silver

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Bldg700\52.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: Storage  
AHERA certification number: 4301201236 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-APR-01, Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Tan Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Storage\01.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: Storage  
AHERA certification number: 4300 1234 1234 Signature of Inspector: Carbyn Hall  
\*Material Reinspected: M-VBF-02, Vapor Barrier Felt, Black, Asphaltic

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Storage\02.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: Storage  
AHERA certification number: 438612511236 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-CMU-03, Concrete Masonry Unit, 8"X16", Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ☒ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Storage\03.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: Storage  
AHERA certification number: 43801251123169 Signature of Inspector: Carbyn Hall  
\*Material Reinspected: M-MRT-04, Mortar, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Storage\04.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: Storage

AHERA certification number: 4380 120124 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-CON-05, Concrete (Foundation), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Storage\05.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: Storage  
AHERA certification number: 4380125412367 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: M-CON-06, Concrete (Entries), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Storage\06.doc





15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: Canopy  
AHERA certification number: 4310120112364 Signature of Inspector: Corbyn Hall  
\*Material Reinspected: S-STU-01, Stucco, Gray, Cementitious

**Type of Asbestos-Containing Material:** ① Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Canopy\01.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene de Pueblo Middle School Building Name/Number: Canopy

AHERA certification number: 435020000316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-02, Sealant, Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Pueblo\Forms\Canopy\02.doc