

November 5, 2021

Mr. Mike Williams
Facilities Supervisor
Kyrene School District No. 28
8700 South Kyrene Road
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection
Asbestos-Containing Building Materials
Kyrene Middle School
1050 East Carver Road, Tempe
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: None.

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC



Michael Hall
Environmental Division Manager

*Attachments: 3-Year Reinspection Tables
3-Year Reinspection Forms*

G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\Kyrene\Cvr Ltr.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	22,000	SF	01/03/19
M-MAS-02	M	Mastic (Penetrations and Flashings), Black, Brittle	Roof	Assumed	NF	G	100	SF	01/03/19
M-SLT-03	M	Sealant (Doors, Walls, Flashings), Brown, Pliable	Lobby	Assumed	NF	G	50	SF	01/03/19
			Gymnasium						
			Gym Storage						
			Mechanical Room						
			Electrical Room						
			Exterior						
			Roof						
M-SLT-04	M	Sealant (Flashings), Gray, Pliable	Roof	Assumed	NF	G	25	SF	01/03/19
M-BRK-05	M	Brick, 4"X16", Red, Cementitious	Lobby	Assumed	NF	G	8,000	SF	01/03/19
			Gymnasium						
			Gym Storage						
			Mechanical Room						
			Electrical Room						
			Exterior						
			Roof						
M-CMU-06	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Tan	Roof	Assumed	NF	G	1,500	SF	01/03/19
M-CMU-07	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Smooth	Roof	Assumed	NF	G	1,500	SF	01/03/19
M-CMU-08	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Rough	Roof	Assumed	NF	G	1,500	SF	01/03/19

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMU-09	M	Concrete Masonry Unit, 8"X8", Dark Gray, Cementitious, Smooth	Exterior	Assumed	NF	G	5,000	SF	01/03/19
			Roof						
M-MRT-10	M	Mortar, Gray, Cementitious	Lobby	Assumed	NF	G	1,850	SF	01/03/19
			Gymnasium						
			Gym Storage						
			Mechanical Room						
			Electrical Room						
			Exterior						
			Roof						
M-SLT-11	M	Sealant (Flashings), Black, Pliable	Roof	Assumed	NF	G	10	SF	01/03/19
M-CMU-12	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	Roof	Assumed	NF	G	50	SF	01/03/19
S-STU-13	S	Stucco, Gray, Cementitious	Exterior	Assumed	NF	G	1,500	SF	01/03/19
			Roof						
M-MRT-14	M	Mortar (Glass Block), White, Cementitious	Gymnasium	Assumed	NF	G	10	SF	01/03/19
			Exterior						
M-SLT-15	M	Sealant (Doors, Windows, Millwork, Fixtures, Walls), White, Pliable	Gymnasium	Assumed	NF	G	32	SF	01/03/19
			Vestibule 4						
			Men's Locker Room						
			Vestibule 3						
			P.E. Office 1						
			P.E. Restroom 1						
			Vestibule 1						
			Vestibule 2						
			Team Locker 1						
			P.E. Storage						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Vestibule 5						
			Women's Showers						
			Women's Locker Room						
			P.E. Office 2						
			P.E. Restroom 2						
			Vestibule 7						
			Vestibule 8						
			Team Locker 2						
			P.E. Storage 2						
			Mechanical Room						
			Electrical Room						
M-CON-16	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	5,000	SF	01/03/19
M-CON-17	M	Concrete (Foundation), Gray, Cementitious	Lobby	Assumed	NF	G	24,000	SF	01/03/19
			Gymnasium						
			Vestibule 4						
			Men's Showers						
			Men's Locker Room						
			Mop Closet 1						
			Vestibule 3						
			P.E. Office 1						
			P.E. Restroom 1						
			Vestibule 1						
			Vestibule 2						
			Team Locker 1						
			P.E. Storage						
			Vestibule 5						
			Women's Showers						
			Women's Locker Room						
			Mop Closet 2						
			Vestibule 6						
			P.E. Office 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			P.E. Restroom 2						
			Vestibule 7						
			Vestibule 8						
			Team Locker 2						
			P.E. Storage 2						
			Gym Storage						
			Mechanical Room						
			Electrical Room						
			Exterior						
M-FDI-18	M	Fire Door Insulation, Metal/Wood Cladding	Lobby	Assumed	NF	G	1,029	SF	01/03/19
			Gymnasium						
			Vestibule 4						
			Men's Locker Room						
			Vestibule 3						
			Vestibule 1						
			Vestibule 2						
			Team Locker 1						
			P.E. Storage						
			Vestibule 5						
			Women's Locker Room						
			Vestibule 6						
			Vestibule 7						
			Vestibule 8						
			P.E. Storage 2						
			Gym Storage						
			Mechanical Room						
			Electrical Room						
M-CMU-20	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	Gym Storage	Assumed	NF	G	1,000	SF	01/03/19
			Mechanical Room						
			Electrical Room						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T								
M-PES-21	M	Pipe End Sealant, White, Pliable	Mechanical Room	%/ASSUMED Assumed	NF/F NF	G/D/SD G	2	LF/SF/EA SF	01/03/19
M-SLT-23	M	Sealant (Duct), Light Gray, Pliable	Mechanical Room	Assumed	NF	G	5	SF	01/03/19
M-WDB-24	M	Woven Duct Boot, 2", Black, Rubber-Like	Mechanical Room	Assumed	NF	G	10	SF	01/03/19
M-GWB-25	M	Gypsum Wallboard, White, Chalky	Mechanical Room	Assumed	NF	G	300	SF	01/03/19
S-JTC-26	S	Joint Compound, White, Chalky	Mechanical Room	Assumed	NF	G	30	SF	01/03/19
M-SLT-27	M	Sealant (Fire Stop), White, Pliable	Mechanical Room	Assumed	NF	G	10	SF	01/03/19
S-TOT-28	S	Troweled-On Texture, White, Chalky	Mop Closet 1	Assumed	NF	G	2,000	SF	01/03/19
			Mop Closet 2						
			P.E. Storage 2						
			Electrical Room						
M-GWB-29	M	Gypsum Wallboard, White, Chalky	Mop Closet 1	Assumed	NF	G	2,000	SF	01/03/19
			Mop Closet 2						
			P.E. Storage 2						
			Electrical Room						
S-JTC-30	S	Joint Compound, White, Chalky	Mop Closet 1	Assumed	NF	G	200	SF	01/03/19
			Mop Closet 2						
			P.E. Storage 2						
			Electrical Room						
S-SAT-32	S	Spray-Applied Texture, White, Chalky	Gymnasium	Assumed	NF	G	4,500	SF	01/03/19
			Vestibule 4						
			Vestibule 3						
			P.E. Office 1						
			Vestibule 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS G/D/SD	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Vestibule 2						
			P.E. Storage						
			Vestibule 5						
			Vestibule 6						
			P.E. Office 2						
			Vestibule 7						
			Vestibule 8						
			Gym Storage						
M-GWB-33	M	Gypsum Wallboard, White, Chalky	Gymnasium	Assumed	NF	G	4,500	SF	01/03/19
			Vestibule 4						
			Vestibule 3						
			P.E. Office 1						
			Vestibule 1						
			Vestibule 2						
			P.E. Storage						
			Vestibule 5						
			Vestibule 6						
			P.E. Office 2						
			Vestibule 7						
			Vestibule 8						
			Gym Storage						
S-JTC-34	S	Joint Compound, White, Chalky	Gymnasium	Assumed	NF	G	450	SF	01/03/19
			Vestibule 4						
			Vestibule 3						
			P.E. Office 1						
			Vestibule 1						
			Vestibule 2						
			P.E. Storage						
			Vestibule 5						
			Vestibule 6						
			P.E. Office 2						
			Vestibule 7						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Vestibule 8						
			Gym Storage						
S-SAT-39	S	Spray-Applied Texture, White, Chalky	Men's Locker Room	Assumed	NF	G	12,000	SF	01/03/19
			P.E. Restroom 1						
			Team Locker 1						
			Women's Locker Room						
			P.E. Restroom 2						
			Team Locker 2						
M-GWB-40	M	Gypsum Wallboard, White, Chalky	Men's Locker Room	Assumed	NF	G	12,000	SF	01/03/19
			P.E. Restroom 1						
			Team Locker 1						
			Women's Locker Room						
			P.E. Restroom 2						
			Team Locker 2						
S-JTC-41	S	Joint Compound, White, Chalky	Men's Locker Room	Assumed	NF	G	1,200	SF	01/03/19
			P.E. Restroom 1						
			Team Locker 1						
			Women's Locker Room						
			P.E. Restroom 2						
			Team Locker 2						
M-GWT-42	M	Glazed Wall Tile, 4", Light Green, Smooth	Men's Showers	Assumed	NF	G	2,000	SF	01/03/19
			Men's Locker Room						
			Team Locker 1						
			Women's Showers						
			Women's Locker Room						
			Team Locker 2						
M-GWT-43	M	Glazed Wall Tile, 4", Green, Smooth	Men's Showers	Assumed	NF	G	2,000	SF	01/03/19
			Men's Locker Room						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Team Locker 1						
			Women's Showers						
			Women's Locker Room						
			Team Locker 2						
M-GRT-44	M	Grout, Gray, Cementitious	Men's Showers	Assumed	NF	G	400	SF	01/03/19
			Men's Locker Room						
			Team Locker 1						
			Women's Showers						
			Women's Locker Room						
			Team Locker 2						
M-GWT-45	M	Glazed Wall Tile, 6"X8", White, Smooth	Men's Locker Room	Assumed	NF	G	3,000	SF	01/03/19
			Team Locker 1						
			Women's Locker Room						
			Team Locker 2						
M-GRT-46	M	Grout, Gray, Cementitious	Men's Locker Room	Assumed	NF	G	300	SF	01/03/19
			Team Locker 1						
			Women's Locker Room						
			Team Locker 2						
M-CMT-47	M	Ceramic Mosaic Tile, 4"X4", White, Smooth	Men's Locker Room	Assumed	NF	G	4,000	SF	01/03/19
			Team Locker 1						
			Women's Locker Room						
			Team Locker 2						
M-GRT-48	M	Grout, Gray, Cementitious	Men's Locker Room	Assumed	NF	G	400	SF	01/03/19
			Team Locker 1						
			Women's Locker Room						
			Team Locker 2						
M-CON-50	M	Concrete, White, Cementitious, Blue Specks	P.E. Restroom 1	Assumed	NF	G	75	SF	01/03/19

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			P.E. Restroom 2						
M-GWT-51	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Men's Showers	Assumed	NF	G	200	SF	01/03/19
			Men's Locker Room						
			Women's Showers						
			Women's Locker Room						
M-ADH-52	M	Adhesive (FRP), Brown, Brittle	Mop Closet 1	Assumed	NF	G	12	SF	01/03/19
			Mop Closet 2						
M-CMT-55	M	Ceramic Mosaic Tile, 2"X2", Light Green, Smooth	Men's Showers	Assumed	NF	G	750	SF	01/03/19
			Women's Showers						
M-CMT-56	M	Ceramic Mosaic Tile (Pattern), 2"X2", Green, Smooth	Men's Showers	Assumed	NF	G	250	SF	01/03/19
			Women's Showers						
M-CMT-57	M	Ceramic Mosaic Tile (Pattern), 2"X2", Tan, Smooth	Men's Showers	Assumed	NF	G	250	SF	01/03/19
			Women's Showers						
M-WAB-59	M	Wallbase (L-Shaped), 4", Black, Vinyl-Like	Gymnasium	Assumed	NF	G	125	SF	01/03/19
M-ADH-60	M	Adhesive, Cream, Pliable	Gymnasium	Assumed	NF	G	125	SF	01/03/19

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Bldg E-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	20,000	SF	01/03/19
M-MAS-02	M	Mastic (Penetrations and Flashings), Black, Brittle	Roof	Assumed	NF	G	100	SF	01/03/19
M-SLT-03	M	Sealant (Flashing), Gray, Pliable	Roof	Assumed	NF	G	50	SF	01/03/19
M-WDB-04	M	Woven Duct Boot, 2", Black, Rubber-Like	Classroom F100	Assumed	NF	G	50	SF	01/03/19
			Classroom F101						
			Classroom F102						
			Classroom F103						
			Classroom F104						
			Classroom F105						
			Classroom F106						
			Classroom F107						
			Storage 1						
			Mechanical 1						
			Classroom F108						
			Classroom F109						
			Room F109 Restroom						
			Classroom F110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom F200						
			Classroom F201						
			Classroom F202						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom F203						
			Classroom F204						
			Classroom F205						
			Classroom F206						
			Classroom F207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room F208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Roof						
M-SLT-05	M	Sealant (Duct), Gray, Pliable	Classroom F100	Assumed	NF	G	50	SF	01/03/19
			Classroom F101						
			Classroom F102						
			Classroom F103						
			Classroom F104						
			Classroom F105						
			Classroom F106						
			Classroom F107						
			Storage 1						
			Mechanical 1						
			Classroom F108						
			Classroom F109						
			Room F109 Restroom						
			Classroom F110						
			Room E110						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS G/D/SD	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom F200						
			Classroom F201						
			Classroom F202						
			Classroom F203						
			Classroom F204						
			Classroom F205						
			Classroom F206						
			Classroom F207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room F208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Roof						
M-SLT-06	M	Sealant (Duct), Pink, Pliable	Classroom F100	Assumed	NF	G	50	SF	01/03/19
			Classroom F101						
			Classroom F102						
			Classroom F103						
			Classroom F104						
			Classroom F105						
			Classroom F106						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom F107						
			Storage 1						
			Mechanical 1						
			Classroom F108						
			Classroom F109						
			Room F109 Restroom						
			Classroom F110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom F200						
			Classroom F201						
			Classroom F202						
			Classroom F203						
			Classroom F204						
			Classroom F205						
			Classroom F206						
			Classroom F207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room F208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Roof						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BRK-07	M	Brick, 4"X16", Red, Cementitious	Mechanical 3	Assumed	NF	G	5,000	SF	01/03/19
			Corridor 1						
			Corridor 2						
			Exterior						
M-CMU-08	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Tan	Exterior	Assumed	NF	G	5,000	SF	01/03/19
M-CMU-09	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Rough	Exterior	Assumed	NF	G	1,000	SF	01/03/19
M-CMU-10	M	Concrete Masonry Unit, 4"X16", Dark Gray, Cementitious, Smooth	Exterior	Assumed	NF	G	100	SF	01/03/19
M-CMU-11	M	Concrete Masonry Unit, 8"X8", Dark Gray, Cementitious, Smooth	Exterior	Assumed	NF	G	100	SF	01/03/19
M-MRT-12	M	Mortar, Gray, Cementitious	Mechanical 3	Assumed	NF	G	1,200	SF	01/03/19
			Exterior						
M-SLT-13	M	Sealant (Doors, Millwork, Walls), White, Pliable	Classroom F100	Assumed	NF	G	100	SF	01/03/19
			Classroom F101						
			Classroom F102						
			Classroom F103						
			Classroom F104						
			Classroom F105						
			Classroom F106						
			Classroom F107						
			Storage 1						
			Classroom F108						
			Classroom F109						
			Room F109 Restroom						
			Classroom F110						
			Room E110						
			Room E111						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 1						
			Girl's Restroom 1						
			Corridor 1						
			Classroom F200						
			Classroom F201						
			Classroom F202						
			Classroom F203						
			Classroom F204						
			Classroom F205						
			Classroom F206						
			Classroom F207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room F208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Exterior						
			Roof						
M-SLT-14	M	Sealant (Walls), Brown, Pliable	Corridor 1	Assumed	NF	G	50	SF	01/03/19
			Corridor 2						
			Exterior						
M-SLT-15	M	Sealant (Walls), Gray, Pliable	Exterior	Assumed	NF	G	50	SF	01/03/19
M-MRT-16	M	Mortar (Glass Block), White, Cementitious	Corridor 1	Assumed	NF	G	50	SF	01/03/19
			Corridor 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Exterior						
M-GWT-17	M	Glazed Wall Tile, 4"X4", Light Green, Smooth	Exterior	Assumed	NF	G	100	SF	01/03/19
M-GRT-18	M	Grout, Brown, Cementitious	Exterior	Assumed	NF	G	10	SF	01/03/19
S-TOT-19	S	Troweled-On Texture, White, Chalky	Mechanical 1	Assumed	NF	G	2,500	SF	01/03/19
			Room E110						
			Room E111						
			Mechanical 2						
			Room E210						
			Room E211						
			Exterior						
M-GWB-20	M	Gypsum Wallboard, White, Chalky	Mechanical 1	Assumed	NF	G	2,500	SF	01/03/19
			Room E110						
			Room E111						
			Mechanical 2						
			Room E210						
			Room E211						
			Exterior						
S-JTC-21	S	Joint Compound, White, Chalky	Mechanical 1	Assumed	NF	G	250	SF	01/03/19
			Room E110						
			Room E111						
			Mechanical 2						
			Room E210						
			Room E211						
			Exterior						
M-CON-22	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	12,500	SF	01/03/19

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CON-23	M	Concrete (Foundation), Gray, Cementitious	Classroom F100	Assumed	NF	G	25,000	SF	01/03/19
			Classroom F101						
			Classroom F102						
			Classroom F103						
			Classroom F104						
			Classroom F105						
			Classroom F106						
			Classroom F107						
			Storage 1						
			Mechanical 1						
			Mechanical 3						
			Classroom F108						
			Classroom F109						
			Room F109 Restroom						
			Classroom F110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom F200						
			Classroom F201						
			Classroom F202						
			Classroom F203						
			Classroom F204						
			Classroom F205						
			Classroom F206						
			Classroom F207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room F208						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
M-FDI-32	M	Fire Door Insulation, Metal/Wood Cladding	Classroom F100	Assumed	NF	G	1,323	SF	01/03/19
			Classroom F101						
			Classroom F102						
			Classroom F103						
			Classroom F104						
			Classroom F105						
			Classroom F106						
			Classroom F107						
			Storage 1						
			Mechanical 1						
			Classroom F108						
			Classroom F109						
			Room F109 Restroom						
			Classroom F110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Corridor 1						
			Classroom F200						
			Classroom F201						
			Classroom F202						
			Classroom F203						
			Classroom F204						
			Classroom F205						
			Classroom F206						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS G/D/SD	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom F207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room F208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
S-SAT-33	S	Spray-Applied Texture, White, Chalky	Corridor 1	Assumed	NF	G	1,200	SF	01/03/19
			Corridor 2						
S-SAT-34	S	Spray-Applied Texture, White, Chalky	Classroom F100	Assumed	NF	G	23,000	SF	01/03/19
			Classroom F101						
			Classroom F102						
			Classroom F103						
			Classroom F104						
			Classroom F105						
			Classroom F106						
			Classroom F107						
			Storage 1						
			Classroom F108						
			Classroom F109						
			Classroom F110						
			Classroom F200						
			Classroom F201						
			Classroom F202						
			Classroom F203						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS.	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom F204						
			Classroom F205						
			Classroom F206						
			Classroom F207						
			Storage 2						
			Storage 3						
			Work Room F208						
			Storage 4						
M-GWB-35	M	Gypsum Wallboard, White, Chalky	Classroom F100	Assumed	NF	G	23,000	SF	01/03/19
			Classroom F101						
			Classroom F102						
			Classroom F103						
			Classroom F104						
			Classroom F105						
			Classroom F106						
			Classroom F107						
			Storage 1						
			Classroom F108						
			Classroom F109						
			Classroom F110						
			Classroom F200						
			Classroom F201						
			Classroom F202						
			Classroom F203						
			Classroom F204						
			Classroom F205						
			Classroom F206						
			Classroom F207						
			Storage 2						
			Storage 3						
			Work Room F208						
			Storage 4						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-JTC-36	S	Joint Compound, White, Chalky	Classroom F100	Assumed	NF	G	2,300	SF	01/03/19
			Classroom F101						
			Classroom F102						
			Classroom F103						
			Classroom F104						
			Classroom F105						
			Classroom F106						
			Classroom F107						
			Storage 1						
			Classroom F108						
			Classroom F109						
			Classroom F110						
			Classroom F200						
			Classroom F201						
			Classroom F202						
			Classroom F203						
			Classroom F204						
			Classroom F205						
			Classroom F206						
			Classroom F207						
			Storage 2						
			Storage 3						
			Work Room F208						
			Storage 4						
M-SAC-38	M	Sink Acoustical Coating, Gray, Rough	Classroom F100	Assumed	NF	G	30	SF	01/03/19
			Classroom F101						
			Classroom F102						
			Classroom F103						
			Classroom F104						
			Classroom F105						
			Classroom F110						
			Classroom F200						
			Classroom F201						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom F202						
			Classroom F203						
			Classroom F204						
			Classroom F205						
			Work Room F208						
S-SAT-40	S	Spray-Applied Texture, White, Chalky	Room F109 Restroom	Assumed	NF	G	3,500	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWB-41	M	Gypsum Wallboard, White, Chalky	Room F109 Restroom	Assumed	NF	G	3,500	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
S-JTC-42	S	Joint Compound, White, Chalky	Room F109 Restroom	Assumed	NF	G	350	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-43	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Room F109 Restroom	Assumed	NF	G	2,500	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS G/D/SD	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-44	M	Glazed Wall Tile (Pattern), 4"X4", Light Green, Smooth	Room F109 Restroom	Assumed	NF	G	250	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-45	M	Glazed Wall Tile (Pattern), 4"X4", Dark Green, Smooth	Room F109 Restroom	Assumed	NF	G	250	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GRT-46	M	Grout, Gray, Cementitious	Room F109 Restroom	Assumed	NF	G	300	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-47	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth	Room F109 Restroom	Assumed	NF	G	1,000	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-48	M	Ceramic Mosaic Tile (Pattern), 2"X2", Light Green, Smooth	Room F109 Restroom	Assumed	NF	G	150	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-49	M	Ceramic Mosaic Tile (Pattern), 2"X2", Dark Green, Smooth	Room F109 Restroom	Assumed	NF	G	150	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GRT-50	M	Grout, Gray, Cementitious	Room F109 Restroom	Assumed	NF	G	130	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-SLT-52	M	Sealant (Doors, Windows), Black, Tar-Like	Corridor 1	Assumed	NF	G	15	SF	01/03/19
			Corridor 2						
M-SLT-54	M	Sealant (Fire Stop), Green, Pliable	Classroom F100	Assumed	NF	G	100	SF	01/03/19
			Classroom F101						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom F102						
			Classroom F103						
			Classroom F104						
			Classroom F105						
			Classroom F106						
			Classroom F107						
			Storage 1						
			Mechanical 1						
			Elevator						
			Mechanical 3						
			Classroom F108						
			Classroom F109						
			Room F109 Restroom						
			Classroom F110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom F200						
			Classroom F201						
			Classroom F202						
			Classroom F203						
			Classroom F204						
			Classroom F205						
			Classroom F206						
			Classroom F207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room F208						
			Staff Women's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
M-ADH-55	M	Adhesive (FRP), Brown, Brittle	Room E111	Assumed	NF	G	25	SF	01/03/19
M-PES-60	M	Pipe End Sealant, White, Pliable	Classroom F100	Assumed	NF	G	50	SF	01/03/19
			Classroom F101						
			Classroom F102						
			Classroom F103						
			Classroom F104						
			Classroom F105						
			Classroom F106						
			Classroom F107						
			Storage 1						
			Mechanical 1						
			Elevator						
			Mechanical 3						
			Classroom F108						
			Classroom F109						
			Room F109 Restroom						
			Classroom F110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom F200						
			Classroom F201						
			Classroom F202						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom F203						
			Classroom F204						
			Classroom F205						
			Classroom F206						
			Classroom F207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room F208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
M-CMU-61	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	Mechanical 3	Assumed	NF	G	100	SF	01/03/19
M-GAS-62	M	Gasket, 4", Black, Rubber-Like	Mechanical 3	Assumed	NF	G	10	SF	01/03/19

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Bldg F-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	20,000	SF	01/03/19
M-MAS-02	M	Mastic (Penetrations and Flashings), Black, Brittle	Roof	Assumed	NF	G	100	SF	01/03/19
M-SLT-03	M	Sealant (Flashing), Gray, Pliable	Roof	Assumed	NF	G	50	SF	01/03/19
M-WDB-04	M	Woven Duct Boot, 2", Black, Rubber-Like	Classroom G100	Assumed	NF	G	50	SF	01/03/19
			Classroom G101						
			Classroom G102						
			Classroom G103						
			Classroom G104						
			Classroom G105						
			Classroom G106						
			Classroom G107						
			Storage 1						
			Mechanical 1						
			Classroom G108						
			Classroom G109						
			Room G109 Restroom						
			Test						
			Classroom G110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom G200						
			Classroom G201						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom G202						
			Classroom G203						
			Classroom G204						
			Classroom G205						
			Classroom G206						
			Classroom G207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room G208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Roof						
M-SLT-05	M	Sealant (Duct), Gray, Pliable	Classroom G100	Assumed	NF	G	50	SF	01/03/19
			Classroom G101						
			Classroom G102						
			Classroom G103						
			Classroom G104						
			Classroom G105						
			Classroom G106						
			Classroom G107						
			Storage 1						
			Mechanical 1						
			Classroom G108						
			Classroom G109						
			Room G109 Restroom						
			Test						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom G110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom G200						
			Classroom G201						
			Classroom G202						
			Classroom G203						
			Classroom G204						
			Classroom G205						
			Classroom G206						
			Classroom G207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room G208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Roof						
M-SLT-06	M	Sealant (Duct), Pink, Pliable	Classroom G100	Assumed	NF	G	50	SF	01/03/19
			Classroom G101						
			Classroom G102						
			Classroom G103						
			Classroom G104						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom G105						
			Classroom G106						
			Classroom G107						
			Storage 1						
			Mechanical 1						
			Classroom G108						
			Classroom G109						
			Room G109 Restroom						
			Test						
			Classroom G110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom G200						
			Classroom G201						
			Classroom G202						
			Classroom G203						
			Classroom G204						
			Classroom G205						
			Classroom G206						
			Classroom G207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room G208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 2						
			Corridor 2						
			Roof						
M-BRK-07	M	Brick, 4"X16", Red, Cementitious	Corridor 1	Assumed	NF	G	5,000	SF	01/03/19
			Corridor 2						
			Exterior						
M-CMU-08	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Tan	Exterior	Assumed	NF	G	5,000	SF	01/03/19
M-CMU-09	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Rough	Exterior	Assumed	NF	G	1,000	SF	01/03/19
M-CMU-10	M	Concrete Masonry Unit, 4"X16", Dark Gray, Cementitious, Smooth	Exterior	Assumed	NF	G	100	SF	01/03/19
M-CMU-11	M	Concrete Masonry Unit, 8"X8", Dark Gray, Cementitious, Smooth	Exterior	Assumed	NF	G	100	SF	01/03/19
M-MRT-12	M	Mortar, Gray, Cementitious	Corridor 1	Assumed	NF	G	1,200	SF	01/03/19
			Corridor 2						
			Exterior						
M-SLT-13	M	Sealant (Doors, Millwork, Walls), White, Pliable	Classroom G100	Assumed	NF	G	50	SF	01/03/19
			Classroom G101						
			Classroom G102						
			Classroom G103						
			Classroom G104						
			Classroom G105						
			Classroom G106						
			Classroom G107						
			Storage 1						
			Classroom G108						
			Classroom G109						
			Room G109 Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom G110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Corridor 1						
			Classroom G200						
			Classroom G201						
			Classroom G202						
			Classroom G203						
			Classroom G204						
			Classroom G205						
			Classroom G206						
			Classroom G207						
			Storage 2						
			Mechanical 2						
			Storage 3						
			Work Room G208						
			Storage 4						
			Room E210						
			Room E211						
			Exterior						
			Roof						
M-SLT-14	M	Sealant (Doors, Walls, Flashing), Brown, Pliable	Corridor 1	Assumed	NF	G	25	SF	01/03/19
			Corridor 2						
			Exterior						
M-SLT-15	M	Sealant (Walls), Gray, Pliable	Exterior	Assumed	NF	G	50	SF	01/03/19
M-MRT-16	M	Mortar (Glass Block), White, Cementitious	Corridor 1	Assumed	NF	G	50	SF	01/03/19
			Corridor 2						
			Exterior						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GWT-17	M	Glazed Wall Tile, 4"X4", Light Green, Smooth	Exterior	Assumed	NF	G	100	SF	01/03/19
M-GRT-18	M	Grout, Brown, Cementitious	Exterior	Assumed	NF	G	10	SF	01/03/19
S-TOT-19	S	Troweled-On Texture, White, Chalky	Mechanical 1	Assumed	NF	G	2,500	SF	01/03/19
			Room E110						
			Room E111						
			Mechanical 2						
			Room E210						
			Room E211						
			Exterior						
M-GWB-20	M	Gypsum Wallboard, White, Chalky	Mechanical 1	Assumed	NF	G	2,500	SF	01/03/19
			Room E110						
			Room E111						
			Mechanical 2						
			Room E210						
			Room E211						
			Exterior						
S-JTC-21	S	Joint Compound, White, Chalky	Mechanical 1	Assumed	NF	G	250	SF	01/03/19
			Room E110						
			Room E111						
			Mechanical 2						
			Room E210						
			Room E211						
			Exterior						
M-CON-22	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	12,500	SF	01/03/19
M-CON-23	M	Concrete (Foundation), Gray, Cementitious	Classroom G100	Assumed	NF	G	25,000	SF	01/03/19

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom G101						
			Classroom G102						
			Classroom G103						
			Classroom G104						
			Classroom G105						
			Classroom G106						
			Classroom G107						
			Storage 1						
			Mechanical 1						
			Classroom G108						
			Classroom G109						
			Room G109 Restroom						
			Test						
			Classroom G110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom G200						
			Classroom G201						
			Classroom G202						
			Classroom G203						
			Classroom G204						
			Classroom G205						
			Classroom G206						
			Classroom G207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room G208						
			Staff Women's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Exterior						
M-FDI-32	M	Fire Door Insulation, Metal/Wood Cladding	Classroom G100	Assumed	NF	G	1,302	SF	01/03/19
			Classroom G101						
			Classroom G102						
			Classroom G103						
			Classroom G104						
			Classroom G105						
			Classroom G106						
			Classroom G107						
			Storage 1						
			Mechanical 1						
			Classroom G108						
			Classroom G109						
			Room G109 Restroom						
			Classroom G110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Corridor 1						
			Classroom G200						
			Classroom G201						
			Classroom G202						
			Classroom G203						
			Classroom G204						
			Classroom G205						
			Classroom G206						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom G207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room G208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
S-SAT-34	S	Spray-Applied Texture, White, Chalky	Classroom G100	Assumed	NF	G	23,000	SF	01/03/19
			Classroom G101						
			Classroom G102						
			Classroom G103						
			Classroom G104						
			Classroom G105						
			Classroom G106						
			Classroom G107						
			Storage 1						
			Classroom G108						
			Classroom G109						
			Test						
			Classroom G110						
			Classroom G200						
			Classroom G201						
			Classroom G202						
			Classroom G203						
			Classroom G204						
			Classroom G205						
			Classroom G206						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom G207						
			Storage 2						
			Storage 3						
			Work Room G208						
			Storage 4						
M-SAC-38	M	Sink Acoustical Coating, White, Rough	Classroom G100	Assumed	NF	G	30	SF	01/03/19
			Classroom G101						
			Classroom G102						
			Classroom G103						
			Classroom G104						
			Classroom G105						
			Classroom G108						
			Classroom G110						
			Classroom G200						
			Classroom G201						
			Classroom G202						
			Classroom G203						
			Classroom G204						
			Classroom G205						
S-SAT-40	S	Spray-Applied Texture, White, Chalky	Room G109 Restroom	Assumed	NF	G	3,500	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWB-41	M	Gypsum Wallboard, White, Chalky	Room G109 Restroom	Assumed	NF	G	3,500	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
S-JTC-42	S	Joint Compound, White, Chalky	Room G109 Restroom	Assumed	NF	G	350	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-43	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Room G109 Restroom	Assumed	NF	G	2,500	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-44	M	Glazed Wall Tile (Pattern), 4"X4", Light Green, Smooth	Room G109 Restroom	Assumed	NF	G	250	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-45	M	Glazed Wall Tile (Pattern), 4"X4", Green, Smooth	Room G109 Restroom	Assumed	NF	G	250	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GRT-46	M	Grout, Gray, Cementitious	Room G109 Restroom	Assumed	NF	G	300	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-47	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth	Room G109 Restroom	Assumed	NF	G	1,000	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-48	M	Ceramic Mosaic Tile (Pattern), 2"X2", Light Green, Smooth	Room G109 Restroom	Assumed	NF	G	150	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-49	M	Ceramic Mosaic Tile (Pattern), 2"X2", Dark Green, Smooth	Room G109 Restroom	Assumed	NF	G	150	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 2						
M-GRT-50	M	Grout, Gray, Cementitious	Room G109 Restroom	Assumed	NF	G	130	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-TWP-51	M	Tackable Wall Panel, Brown, Fibrous, Vinyl Cover	Classroom G100	Assumed	NF	G	3,500	SF	01/03/19
			Classroom G101						
			Classroom G102						
			Classroom G103						
			Classroom G104						
			Classroom G105						
			Classroom G106						
			Classroom G107						
			Classroom G200						
			Classroom G201						
			Classroom G202						
			Classroom G203						
			Classroom G204						
			Classroom G205						
			Classroom G206						
			Classroom G207						
M-SLT-52	M	Sealant (Doors, Windows), Black, Tar-Like	Corridor 1	Assumed	NF	G	15	SF	01/03/19
			Corridor 2						
M-SLT-54	M	Sealant (Fire Stop), Green, Pliable	Classroom G100	Assumed	NF	G	50	SF	01/03/19
			Classroom G101						
			Classroom G102						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom G103						
			Classroom G104						
			Classroom G105						
			Classroom G106						
			Classroom G107						
			Storage 1						
			Mechanical 1						
			Classroom G108						
			Classroom G109						
			Room G109 Restroom						
			Test						
			Classroom G110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom G200						
			Classroom G201						
			Classroom G202						
			Classroom G203						
			Classroom G204						
			Classroom G205						
			Classroom G206						
			Classroom G207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room G208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
M-ADH-55	M	Adhesive (FRP), Brown, Brittle	Room E111	Assumed	NF	G	25	SF	01/03/19
M-PES-60	M	Pipe End Sealant, White, Pliable	Classroom G100	Assumed	NF	G	50	SF	01/03/19
			Classroom G101						
			Classroom G102						
			Classroom G103						
			Classroom G104						
			Classroom G105						
			Classroom G106						
			Classroom G107						
			Storage 1						
			Mechanical 1						
			Elevator						
			Mechanical 3						
			Classroom G108						
			Classroom G109						
			Room G109 Restroom						
			Test						
			Classroom G110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom G200						
			Classroom G201						
			Classroom G202						
			Classroom G203						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom G204						
			Classroom G205						
			Classroom G206						
			Classroom G207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room G208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Bldg G-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	16,000	SF	01/03/19
M-MAS-02	M	Mastic (Penetrations and Flashings), Black, Brittle	Roof	Assumed	NF	G	100	SF	01/03/19
M-SLT-03	M	Sealant (Flashing), Gray, Pliable	Roof	Assumed	NF	G	50	SF	01/03/19
M-WDB-04	M	Woven Duct Boot, 2", Black, Rubber-Like	Classroom H100	Assumed	NF	G	50	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H106						
			Classroom H107						
			Storage 1						
			Mechanical 1						
			Classroom H108						
			Classroom H109						
			Room H109 Restroom						
			Classroom H110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom H200						
			Classroom H201						
			Classroom H202						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom H203						
			Classroom H204						
			Classroom H205						
			Classroom H206						
			Classroom H207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room H208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Roof						
M-SLT-05	M	Sealant (Duct), Gray, Pliable	Classroom H100	Assumed	NF	G	50	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H106						
			Classroom H107						
			Storage 1						
			Mechanical 1						
			Classroom H108						
			Classroom H109						
			Room H109 Restroom						
			Classroom H110						
			Room E110						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom H200						
			Classroom H201						
			Classroom H202						
			Classroom H203						
			Classroom H204						
			Classroom H205						
			Classroom H206						
			Classroom H207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room H208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Roof						
M-SLT-06	M	Sealant (Duct), Pink, Pliable	Classroom H100	Assumed	NF	G	50	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H106						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom H107						
			Storage 1						
			Mechanical 1						
			Classroom H108						
			Classroom H109						
			Room H109 Restroom						
			Classroom H110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom H200						
			Classroom H201						
			Classroom H202						
			Classroom H203						
			Classroom H204						
			Classroom H205						
			Classroom H206						
			Classroom H207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room H208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Roof						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMU-07	M	Concrete Masonry Unit, 4"X16", Red, Cementitious	Corridor 1	Assumed	NF	G	5,000	SF	01/03/19
			Corridor 2						
			Exterior						
M-CMU-08	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Tan	Exterior	Assumed	NF	G	5,000	SF	01/03/19
M-CMU-09	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Rough	Exterior	Assumed	NF	G	1,000	SF	01/03/19
M-CMU-10	M	Concrete Masonry Unit, 4"X16", Dark Gray, Cementitious, Smooth	Exterior	Assumed	NF	G	100	SF	01/03/19
M-CMU-11	M	Concrete Masonry Unit, 8"X8", Dark Gray, Cementitious, Smooth	Exterior	Assumed	NF	G	100	SF	01/03/19
M-MRT-12	M	Mortar, Gray, Cementitious	Mechanical 3	Assumed	NF	G	1,500	SF	01/03/19
			Exterior						
M-SLT-13	M	Sealant (Doors, Windows, Millwork, Walls), White, Pliable	Classroom H100	Assumed	NF	G	100	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H106						
			Classroom H107						
			Storage 1						
			Classroom H108						
			Classroom H109						
			Room H109 Restroom						
			Classroom H110						
			Room E110						
			Room E111						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 1						
			Girl's Restroom 1						
			Corridor 1						
			Classroom H200						
			Classroom H201						
			Classroom H202						
			Classroom H203						
			Classroom H204						
			Classroom H205						
			Classroom H206						
			Classroom H207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room H208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Exterior						
			Roof						
M-SLT-14	M	Sealant (Walls), Brown, Pliable	Corridor 1	Assumed	NF	G	50	SF	01/03/19
			Corridor 2						
			Exterior						
M-SLT-15	M	Sealant (Walls), Gray, Pliable	Exterior	Assumed	NF	G	50	SF	01/03/19
M-MRT-16	M	Mortar (Glass Block), White, Cementitious	Corridor 1	Assumed	NF	G	50	SF	01/03/19
			Corridor 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Exterior						
M-GWT-17	M	Glazed Wall Tile, 4"X4", Light Green, Smooth	Exterior	Assumed	NF	G	100	SF	01/03/19
M-GRT-18	M	Grout, Brown, Cementitious	Exterior	Assumed	NF	G	10	SF	01/03/19
S-TOT-19	S	Troweled-On Texture, White, Chalky	Mechanical 1	Assumed	NF	G	2,500	SF	01/03/19
			Room E110						
			Room E111						
			Mechanical 2						
			Room E210						
			Room E211						
			Exterior						
M-GWB-20	M	Gypsum Wallboard, White, Chalky	Mechanical 1	Assumed	NF	G	2,500	SF	01/03/19
			Room E110						
			Room E111						
			Mechanical 2						
			Room E210						
			Room E211						
			Exterior						
S-JTC-21	S	Joint Compound, White, Chalky	Mechanical 1	Assumed	NF	G	250	SF	01/03/19
			Room E110						
			Room E111						
			Mechanical 2						
			Room E210						
			Room E211						
			Exterior						
M-CON-22	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	2,000	SF	01/03/19

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CON-23	M	Concrete (Foundation), Gray, Cementitious	Classroom H100	Assumed	NF	G	32,000	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H106						
			Classroom H107						
			Storage 1						
			Mechanical 1						
			Classroom H108						
			Classroom H109						
			Room H109 Restroom						
			Classroom H110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom H200						
			Classroom H201						
			Classroom H202						
			Classroom H203						
			Classroom H204						
			Classroom H205						
			Classroom H206						
			Classroom H207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room H208						
			Staff Women's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Exterior						
M-FDI-32	M	Fire Door Insulation, Metal/Wood Cladding	Classroom H100	Assumed	NF	G	1,260	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H106						
			Classroom H107						
			Storage 1						
			Classroom H108						
			Classroom H109						
			Room H109 Restroom						
			Classroom H110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Corridor 1						
			Classroom H200						
			Classroom H201						
			Classroom H202						
			Classroom H203						
			Classroom H204						
			Classroom H205						
			Classroom H206						
			Classroom H207						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room H208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
			Exterior						
S-SAT-33	S	Spray-Applied Texture, White, Chalky	Corridor 1	Assumed	NF	G	1,200	SF	01/03/19
			Corridor 2						
S-SAT-34	S	Spray-Applied Texture, White, Chalky	Classroom H100	Assumed	NF	G	23,000	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H106						
			Classroom H107						
			Storage 1						
			Classroom H108						
			Classroom H109						
			Classroom H110						
			Classroom H200						
			Classroom H201						
			Classroom H202						
			Classroom H203						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom H204						
			Classroom H205						
			Classroom H206						
			Classroom H207						
			Storage 2						
			Storage 3						
			Work Room H208						
			Storage 4						
M-GWB-35	M	Gypsum Wallboard, White, Chalky	Classroom H100	Assumed	NF	G	23,000	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H106						
			Classroom H107						
			Storage 1						
			Classroom H108						
			Classroom H109						
			Classroom H110						
			Classroom H200						
			Classroom H201						
			Classroom H202						
			Classroom H203						
			Classroom H204						
			Classroom H205						
			Classroom H206						
			Classroom H207						
			Storage 2						
			Storage 3						
			Work Room H208						
			Storage 4						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-JTC-36	S	Joint Compound, White, Chalky	Classroom H100	Assumed	NF	G	2,300	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H106						
			Classroom H107						
			Storage 1						
			Classroom H108						
			Classroom H109						
			Classroom H110						
			Classroom H200						
			Classroom H201						
			Classroom H202						
			Classroom H203						
			Classroom H204						
			Classroom H205						
			Classroom H206						
			Classroom H207						
			Storage 2						
			Storage 3						
			Work Room H208						
			Storage 4						
M-SAC-38	M	Sink Acoustical Coating, White, Rough	Classroom H100	Assumed	NF	G	30	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H200						
			Classroom H201						
			Classroom H202						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom H203						
			Classroom H204						
			Classroom H205						
S-SAT-40	S	Spray-Applied Texture, White, Chalky	Room H109 Restroom	Assumed	NF	G	3,500	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWB-41	M	Gypsum Wallboard, White, Chalky	Room H109 Restroom	Assumed	NF	G	3,500	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
S-JTC-42	S	Joint Compound, White, Chalky	Room H109 Restroom	Assumed	NF	G	350	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-43	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Room H109 Restroom	Assumed	NF	G	2,500	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-44	M	Glazed Wall Tile (Pattern), 4"X4", Light Green, Smooth	Room H109 Restroom	Assumed	NF	G	250	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GWT-45	M	Glazed Wall Tile (Pattern), 4"X4", Dark Green, Smooth	Room H109 Restroom	Assumed	NF	G	250	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GRT-46	M	Grout, Gray, Cementitious	Room H109 Restroom	Assumed	NF	G	300	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-47	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth	Room H109 Restroom	Assumed	NF	G	1,000	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 2						
M-CMT-48	M	Ceramic Mosaic Tile, 2"X2", Light Green, Smooth	Room H109 Restroom	Assumed	NF	G	150	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-CMT-49	M	Ceramic Mosaic Tile, 2"X2", Green, Smooth	Room H109 Restroom	Assumed	NF	G	150	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-GRT-50	M	Grout, Gray, Cementitious	Room H109 Restroom	Assumed	NF	G	130	SF	01/03/19
			Boy's Restroom 1						
			Girl's Restroom 1						
			Staff Men's Restroom						
			Staff Women's Restroom						
			Boy's Restroom 2						
			Girl's Restroom 2						
M-TWP-51	M	Tackable Wall Panel, Brown, Fibrous, Vinyl Cover	Classroom H100	Assumed	NF	G	3,500	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H106						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom H107						
			Classroom H200						
			Classroom H201						
			Classroom H202						
			Classroom H203						
			Classroom H204						
			Classroom H205						
			Classroom H206						
			Classroom H207						
M-SLT-52	M	Sealant (Doors, Windows), Black, Tar-Like	Corridor 1	Assumed	NF	G	15	SF	01/03/19
			Corridor 2						
M-SLT-54	M	Sealant (Fire Stop), Green, Pliable	Classroom H100	Assumed	NF	G	100	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H106						
			Classroom H107						
			Storage 1						
			Mechanical 1						
			Classroom H108						
			Classroom H109						
			Room H109 Restroom						
			Classroom H110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom H200						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom H201						
			Classroom H202						
			Classroom H203						
			Classroom H204						
			Classroom H205						
			Classroom H206						
			Classroom H207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room H208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						
M-ADH-55	M	Adhesive (FRP), Brown, Brittle	Room E111	Assumed	NF	G	25	SF	01/03/19
M-PES-60	M	Pipe End Sealant, White, Pliable	Classroom H100	Assumed	NF	G	100	SF	01/03/19
			Classroom H101						
			Classroom H102						
			Classroom H103						
			Classroom H104						
			Classroom H105						
			Classroom H106						
			Classroom H107						
			Storage 1						
			Mechanical 1						
			Elevator						
			Mechanical 3						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom H108						
			Classroom H109						
			Room H109 Restroom						
			Classroom H110						
			Room E110						
			Room E111						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Stairwell						
			Corridor 1						
			Classroom H200						
			Classroom H201						
			Classroom H202						
			Classroom H203						
			Classroom H204						
			Classroom H205						
			Classroom H206						
			Classroom H207						
			Storage 2						
			Mechanical 2						
			Staff Men's Restroom						
			Storage 3						
			Work Room H208						
			Staff Women's Restroom						
			Storage 4						
			Room E210						
			Room E211						
			Boy's Restroom 2						
			Girl's Restroom 2						
			Corridor 2						

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
S-TOT-01	S	Troweled-On Texture, White, Chalky	Storage 5	Assumed	NF	G	5,000	SF	01/03/19
			Storage 6						
			Storage 7						
			Exterior						
M-GWB-02	M	Gypsum Wallboard, White, Chalky	Storage 5	Assumed	NF	G	5,000	SF	01/03/19
			Storage 6						
			Storage 7						
			Exterior						
S-JTC-03	S	Joint Compound, White, Chalky	Storage 5	Assumed	NF	G	500	SF	01/03/19
			Storage 6						
			Storage 7						
			Exterior						
S-STU-04	S	Stucco, Gray, Cementitious	Storage 5	Assumed	NF	G	1,000	SF	01/03/19
			Storage 6						
			Storage 7						
			Roof						
M-CMU-05	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious	Storage 5	Assumed	NF	G	7,000	SF	01/03/19
			Storage 6						
			Storage 7						
			Exterior						
M-BRK-06	M	Brick, 4"X16", Red, Cementitious	Exterior	Assumed	NF	G	2,200	SF	01/03/19
M-CMU-07	M	Concrete Masonry Unit, 8"X8", Gray, Cementitious	Exterior	Assumed	NF	G	150	SF	01/03/19

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-MRT-08	M	Mortar, Gray, Cementitious	Storage 5	Assumed	NF	G	950	SF	01/03/19
			Storage 6						
			Storage 7						
			Exterior						
M-SLT-09	M	Sealant (Doors, Windows, Walls), Gray, Pliable	Exterior	Assumed	NF	G	50	SF	01/03/19
M-SLT-10	M	Sealant (Doors), Tan, Pliable	Storage 5	Assumed	NF	G	16	SF	01/03/19
			Storage 7						
			Exterior						
M-CON-11	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	7,000	SF	01/03/19
M-CON-12	M	Concrete (Foundation), Gray, Cementitious	Work Room	Assumed	NF	G	8,000	SF	01/03/19
			Detention						
			Phone						
			Men's Restroom 1						
			Women's Restroom 1						
			Work Room Storage						
			Mechanical 1						
			Pantry						
			Storage 1						
			Food Lab						
			Restroom 2						
			Laundry						
			Storage 2						
			Storage 3						
			Storage 4						
			Storage 5						
			Storage 6						
			Storage 7						
			Art						
			Cad						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Exterior						
M-CMU-13	M	Concrete Masonry Unit, 8"X16", Gray, Cementitious	Storage 7	Assumed	NF	G	500	SF	01/03/19
			Exterior						
M-MRT-14	M	Mortar, Gray, Cementitious	Storage 7	Assumed	NF	G	50	SF	01/03/19
			Exterior						
M-CMU-15	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious	Exterior	Assumed	NF	G	150	SF	01/03/19
M-MRT-16	M	Mortar, Gray, Cementitious	Exterior	Assumed	NF	G	300	SF	01/03/19
M-FDI-17	M	Fire Door Insulation, Wood/Metal Cladding	Work Room	Assumed	NF	G	588	SF	01/03/19
			Detention						
			Men's Restroom 1						
			Women's Restroom 1						
			Mechanical 1						
			Storage 1						
			Food Lab						
			Storage 2						
			Storage 3						
			Storage 4						
			Storage 5						
			Storage 7						
			Art						
			Cad						
			Tech Lab						
			Tech Server						
			Storage 8						
			Mechanical 2						
			Exterior						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-CMU-18	M	Concrete Masonry Unit, 4"X16", Dark Gray, Cementitious	Exterior	Assumed	NF	G	50	SF	01/03/19
M-VCT-24	M	Vinyl Composition Tile, 12"X12", Tan, Smooth, Multi-Colored	Detention	Assumed	NF	G	6,000	SF	01/03/19
			Work Room Storage						
			Mechanical 1						
M-SLT-29	M	Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable	Work Room	Assumed	NF	G	43	SF	01/03/19
			Detention						
			Men's Restroom 1						
			Women's Restroom 1						
			Work Room Storage						
			Pantry						
			Storage 1						
			Food Lab						
			Restroom 2						
			Laundry						
			Storage 2						
			Storage 3						
			Storage 4						
			Art						
			Cad						
			Tech Lab						
			Tech Server						
			Storage 8						
			Dark Room						
			Mechanical 2						
M-SAC-30	M	Sink Acoustical Coating, Gray, Rough	Work Room	Assumed	NF	G	28	NF	01/03/19
			Detention						
			Food Lab						
			Art						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
M-GWB-31	M/S/T M	Gypsum Wallboard, White, Chalky	Work Room	%/ASSUMED Assumed	NF/F NF	G/D/SD G	9,000	LF/SF/EA SF	01/03/19
			Detention						
			Phone						
			Men's Restroom 1						
			Women's Restroom 1						
			Work Room Storage						
			Mechanical 1						
			Pantry						
			Storage 1						
			Food Lab						
			Restroom 2						
			Laundry						
			Storage 2						
			Storage 3						
			Storage 4						
			Art						
			Cad						
S-JTC-32	S	Joint Compound, White, Chalky	Work Room	Assumed	NF	G	900	SF	01/03/19
			Detention						
			Phone						
			Men's Restroom 1						
			Women's Restroom 1						
			Work Room Storage						
			Mechanical 1						
			Pantry						
			Storage 1						
			Food Lab						
			Restroom 2						
			Laundry						
			Storage 2						
			Storage 3						
			Storage 4						
			Art						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Cad						
M-ADH-33	M	Adhesive (Residual), Brown, Brittle	Work Room	Assumed	NF	G	3,000	SF	01/03/19
			Detention						
			Phone						
			Men's Restroom 1						
			Women's Restroom 1						
			Work Room Storage						
			Mechanical 1						
			Pantry						
			Storage 1						
			Food Lab						
			Restroom 2						
			Laundry						
			Storage 2						
			Storage 3						
			Storage 4						
			Art						
			Cad						
S-SAT-35	S	Spray-Applied Texture, White, Chalky	Men's Restroom 1	Assumed	NF	G	1,500	SF	01/03/19
			Women's Restroom 1						
			Restroom 2						
M-GWB-36	M	Gypsum Wallboard, White, Chalky	Men's Restroom 1	Assumed	NF	G	1,500	SF	01/03/19
			Women's Restroom 1						
			Restroom 2						
S-JTC-37	S	Joint Compound, White, Chalky	Men's Restroom 1	Assumed	NF	G	150	SF	01/03/19
			Women's Restroom 1						
			Restroom 2						
M-GWT-38	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Men's Restroom 1	Assumed	NF	G	1,000	SF	01/03/19

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Women's Restroom 1						
			Restroom 2						
M-GWT-39	M	Glazed Wall Tile (Pattern), 4"X4", Light Green, Smooth	Men's Restroom 1	Assumed	NF	G	100	SF	01/03/19
			Women's Restroom 1						
			Restroom 2						
M-GWT-40	M	Glazed Wall Tile (Pattern), 4"X4", Green, Smooth	Men's Restroom 1	Assumed	NF	G	100	SF	01/03/19
			Women's Restroom 1						
			Restroom 2						
M-GRT-41	M	Grout, Gray, Cementitious	Men's Restroom 1	Assumed	NF	G	120	SF	01/03/19
			Women's Restroom 1						
			Restroom 2						
M-CMT-42	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth	Men's Restroom 1	Assumed	NF	G	1,000	SF	01/03/19
			Women's Restroom 1						
			Restroom 2						
M-CMT-43	M	Ceramic Mosaic Tile, 2"X2", Light Green, Smooth	Men's Restroom 1	Assumed	NF	G	100	SF	01/03/19
			Women's Restroom 1						
			Restroom 2						
M-CMT-44	M	Ceramic Mosaic Tile, 2"X2", Green, Smooth	Men's Restroom 1	Assumed	NF	G	100	SF	01/03/19
			Women's Restroom 1						
			Restroom 2						
M-GRT-45	M	Grout, Gray, Cementitious	Men's Restroom 1	Assumed	NF	G	120	SF	01/03/19
			Women's Restroom 1						
			Restroom 2						
M-PSL-46	M	Pipe Sealant, White, Pliable	Mechanical 1	Assumed	NF	G	5	SF	01/03/19

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GAS-47	M	Gasket, 4", Black, Rubber-Like	Mechanical 1	Assumed	NF	G	5	SF	01/03/19
M-ADH-48	M	Adhesive (FRP), Brown, Brittle	Storage 1	Assumed	NF	G	25	SF	01/03/19
			Food Lab						
S-SAT-49	S	Spray-Applied Texture, White, Chalky	Tech Lab	Assumed	NF	G	3,000	SF	01/03/19
			Tech Server						
			Storage 8						
			Dark Room						
M-GWB-50	M	Gypsum Wallboard, White, Chalky	Tech Lab	Assumed	NF	G	3,000	SF	01/03/19
			Tech Server						
			Storage 8						
			Dark Room						
S-JTC-51	S	Joint Compound, White, Chalky	Tech Lab	Assumed	NF	G	300	SF	01/03/19
			Tech Server						
			Storage 8						
			Dark Room						
M-CON-52	M	Concrete (Foundation), Gray, Cementitious	Tech Lab	Assumed	NF	G	4,000	SF	01/03/19
			Tech Server						
			Storage 8						
			Dark Room						
			Mechanical 2						
			Exterior						
M-WDB-53	M	Woven Duct Boot, 2", Black, Rubber-Like	Work Room	Assumed	NF	G	50	SF	01/03/19
			Detention						
			Phone						
			Men's Restroom 1						
			Women's Restroom 1						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Work Room Storage						
			Mechanical 1						
			Pantry						
			Storage 1						
			Food Lab						
			Restroom 2						
			Laundry						
			Storage 2						
			Storage 3						
			Storage 4						
			Storage 5						
			Storage 6						
			Storage 7						
			Art						
			Cad						
			Tech Lab						
			Tech Server						
			Storage 8						
			Dark Room						
			Mechanical 2						
S-PLA-54	S	Plaster, Gray, Cementitious	Storage 5	Assumed	NF	G	400	SF	01/03/19
			Storage 6						
			Storage 7						

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Bldg J-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	17,000	SF	01/03/19
M-MAS-02	M	Mastic (Penetrations And Flashings), Black, Brittle	Roof	Assumed	NF	G	150	SF	01/03/19
M-SLT-03	M	Sealant (Flashing), Gray, Pliable	Roof	Assumed	NF	G	50	SF	01/03/19
S-STU-04	S	Stucco, Gray, Cementitious	Exterior	Assumed	NF	G	3,000	SF	01/03/19
			Roof						
M-CMU-05	M	Concrete Masonry Unit, 4"X16", Gray, Cementitious, Tan	Exterior	Assumed	NF	G	9,500	SF	01/03/19
			Roof						
M-MRT-06	M	Mortar, Gray, Cementitious	Exterior	Assumed	NF	G	950	SF	01/03/19
			Roof						
M-SLT-07	M	Sealant (Wall, Flashing), Tan, Pliable	Exterior	Assumed	NF	G	35	SF	01/03/19
			Roof						
M-CON-10	M	Concrete (Entries), Gray, Cementitious	Exterior	Assumed	NF	G	7,000	SF	01/03/19
M-SLT-12	M	Sealant (Windows), Black, Tar- Like	Exterior	Assumed	NF	G	16	SF	01/03/19
M-FDI-13	M	Fire Door Insulation, Metal/Wood Cladding	Reception	Assumed	NF	G	609	SF	01/03/19
			Office 1						
			Restroom						
			Hallway 01						
			Office 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Office 7						
			Iss						
			Supply 02						
			Hall 02						
			Professional Library						
			Vestibule 02						
			Men's Restroom						
			Women's Restroom						
			Computer 2						
			Computer						
			Storage 2						
			Mechanical						
			Vestibule 03						
			Health Office						
			Principal						
			Open Office						
			Library						
			Janitor						
			Corridor 01						
			Exterior						
S-SAT-15	S	Spray-Applied Texture, White, Chalky	Office 1	Assumed	NF	G	13,000	SF	01/03/19
			Conference						
			Office 2						
			Office 7						
			Vestibule 01						
			Iss						
			Supply 01						
			Supply 02						
			Professional Library						
			Computer 2						
			Storage 1						
			Printer						
			Computer						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Storage 2						
			Vestibule 3						
			Health Office						
			Nurse Storage						
			Treatment						
			Nurse Office						
			Principal						
			Principal Closet						
			Library						
			Media Work Room						
M-GWB-16	M	Gypsum Wallboard, White, Chalky	Office 1	Assumed	NF	G	13,000	SF	01/03/19
			Conference						
			Office 2						
			Office 7						
			Vestibule 01						
			Iss						
			Supply 01						
			Supply 02						
			Professional Library						
			Computer 2						
			Storage 1						
			Printer						
			Computer						
			Storage 2						
			Vestibule 3						
			Health Office						
			Nurse Storage						
			Treatment						
			Nurse Office						
			Principal						
			Principal Closet						
			Library						
			Media Work Room						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS G/D/SD	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F			LF/SF/EA	
S-JTC-17	S	Joint Compound, White, Chalky	Office 1	Assumed	NF	G	1,300	SF	01/03/19
			Conference						
			Office 2						
			Office 7						
			Vestibule 01						
			Iss						
			Supply 01						
			Supply 02						
			Professional Library						
			Computer 2						
			Storage 1						
			Printer						
			Computer						
			Storage 2						
			Vestibule 3						
			Health Office						
			Nurse Storage						
			Treatment						
			Nurse Office						
			Principal						
			Principal Closet						
			Library						
			Media Work Room						
M-SAC-29	M	Sink Acoustical Coating, Gray, Rough	Iss	Assumed	NF	G	10	SF	01/03/19
			Computer 2						
			Health Office						
			Treatment						
			Media Work Room						
M-GWT-30	M	Glazed Wall Tile, 4"X4", Tan, Smooth	Men's Restroom	Assumed	NF	G	1,000	SF	01/03/19
			Women's Restroom						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Nurse Restroom						
			Treatment						
M-GRT-31	M	Grout, Gray, Cementitious	Men's Restroom	Assumed	NF	G	150	SF	01/03/19
			Women's Restroom						
			Nurse Restroom						
			Treatment						
M-CMT-32	M	Ceramic Mosaic Tile, 2"X2", Tan, Smooth	Men's Restroom	Assumed	NF	G	800	SF	01/03/19
			Women's Restroom						
			Nurse Restroom						
			Treatment						
M-GRT-33	M	Grout, Gray, Cementitious	Men's Restroom	Assumed	NF	G	100	SF	01/03/19
			Women's Restroom						
			Nurse Restroom						
			Treatment						
S-SAT-34	S	Spray-Applied Texture, White, Chalky	Men's Restroom	Assumed	NF	G	2,500	SF	01/03/19
			Women's Restroom						
			Nurse Restroom						
			Treatment						
M-GWB-35	M	Gypsum Wallboard, White, Chalky	Men's Restroom	Assumed	NF	G	2,500	SF	01/03/19
			Women's Restroom						
			Nurse Restroom						
			Treatment						
S-JTC-36	S	Joint Compound, White, Chalky	Men's Restroom	Assumed	NF	G	250	SF	01/03/19
			Women's Restroom						
			Nurse Restroom						
			Treatment						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSES. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T								
S-TOT-37	S	Troweled-On Texture, White, Chalky	Hall 02	%/ASSUMED Assumed	NF/F NF	G/D/SD G	700	LF/SF/EA SF	01/03/19
			Mechanical						
M-GWB-38	M	Gypsum Wallboard, White, Chalky	Hall 02	Assumed	NF	G	700	SF	01/03/19
			Mechanical						
S-JTC-39	S	Joint Compound, White, Chalky	Hall 02	Assumed	NF	G	70	SF	01/03/19
			Mechanical						
M-GWT-41	M	Glazed Wall Tile (Pattern), 4"X4", Light Green, Smooth	Men's Restroom	Assumed	NF	G	250	SF	01/03/19
			Women's Restroom						
M-GWT-42	M	Glazed Wall Tile (Pattern), 4"X4", Green, Smooth	Men's Restroom	Assumed	NF	G	250	SF	01/03/19
			Women's Restroom						
M-CMT-43	M	Ceramic Mosaic Tile, 2"X2", Light Green, Smooth	Men's Restroom	Assumed	NF	G	100	SF	01/03/19
			Women's Restroom						
M-CMT-44	M	Ceramic Mosaic Tile, 2"X2", Green, Smooth	Men's Restroom	Assumed	NF	G	100	SF	01/03/19
			Women's Restroom						
M-ADH-45	M	Adhesive (FRP), Brown, Brittle	Janitor	Assumed	NF	G	15	SF	01/03/19
M-PES-46	M	Pipe End Sealant, White, Pliable	Mechanical	Assumed	NF	G	2	SF	01/03/19

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Bldg K-Tbl.doc

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	16,000	SF	01/03/19
M-FDI-17	M	Fire Door Insulation, Metal/Wood Cladding	Lobby	Assumed	NF	G	1,596	SF	01/03/19
			Vestibule 3						
			Room L100						
			Room L107						
			Storage 3						
			Electrical						
			Band						
			Band Storage						
			Storage 2						
			Concession 1						
			Staff Restroom						
			Hall 1						
			Janitor						
			Vestibule 2						
			Room L103						
			Table Storage						
			Room L104						
			Room L104 Closet						
			Storage 1						
			Room L105						
			Vestibule 1						
			Multi-Purpose						
			Multi-Purpose Storage						
			Unisex Restroom 2						
			Locker Room						
			Walk In 1						

Date Form Completed: 01/15/2019

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Walk In 2						
			Laundry Room						
			Mop Sink						
			Serving						
			Serving Storage						
			Concession 2						
			Vestibule 4						
			Storage 4						
			Building Manager						
			Men's Restroom						
			Women's Restroom						
			Exterior						
M-ADH-40	M	Adhesive (Residual), Brown, Brittle	Men's Restroom	Assumed	NF	G	4,000	SF	01/03/19
			Women's Restroom						
M-MAS-58	M	Mastic (VCT), Black, Brittle	Janitor	Assumed	NF	G	75	SF	01/03/19
M-ADH-77	M	Adhesive (Mirror), Brown, Brittle	Green Room	Assumed	NF	G	150	SF	01/03/19
M-ADH-80	M	Adhesive (FRP), Brown, Brittle	Building Manager	Assumed	NF	G	100	SF	01/03/19

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Bldg L-Tbl.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High _____ Medium _____ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: ALL ANGEL

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MAS-02, Mastic (Penetrations and Flashings), Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High _____ Medium _____ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Archer
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-03, Sealant (Doors, Walls, Flashings), Brown, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High Medium Low
Degree of Activity Near the Material: _____ High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: GA023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-04, Sealant (Flashings), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: GA023 Signature of Inspector: PA

*Material Reinspected: M-BRK-05, Brick, 4"X16", Red, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2 2. Did Not Find 1

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No

Evidence of Water Damage: _____ Yes No

Evidence of Delamination or Other Damage: _____ Yes No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium 2 Low 3

Degree of Activity Near the Material: High 1 Medium 2 Low 3

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-CMU-06, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Tan

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No

Evidence of Water Damage: _____ Yes No

Evidence of Delamination or Other Damage: _____ Yes No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\06.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anzor

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-07, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc. (3)

Material Status: 1. In-Place / 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High / Medium Low

Degree of Activity Near the Material: High / Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\07.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-08, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\08.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: E
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-09, Concrete Masonry Unit, 8"X8", Dark Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\09.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MRT-10, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\10.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 49023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-11, Sealant (Flashings), Black, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\11.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Bill Anderson

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-12, Concrete Masonry Unit, 8"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Bill Amber
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-STU-13, Stucco, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angel

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MRT-14, Mortar (Glass Block), White, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No

Evidence of Water Damage: Yes No

Evidence of Delamination or Other Damage: Yes No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\14.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAU ANGER

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-15, Sealant (Doors, Windows, Millwork, Fixtures, Walls), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: DAF

*Material Reinspected: M-CON-16, Concrete (Entries), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\16.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CON-17, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium Low

Degree of Activity Near the Material: High ✓ Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\17.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anstee

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 64023 Signature of Inspector: [Signature]

*Material Reinspected: M-FDI-18, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High Medium Low ✓

Degree of Activity Near the Material: High ✓ Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\18.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Weber

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-20, Concrete Masonry Unit, 8"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\20.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-PES-21, Pipe End Sealant, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No ✓
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No ✓
Explain:

Assessment:

Evidence of Physical Damage: Yes / No ✓

Evidence of Water Damage: Yes / No ✓

Evidence of Delamination or Other Damage: Yes / No ✓

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No ✓
Explain:

Degree of Accessibility of the Material: High Medium Low ✓

Degree of Activity Near the Material: High Medium Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No ✓

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No ✓
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\21.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-23, Sealant (Duct), Light Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\23.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-WDB-24, Woven Duct Boot, 2", Black, Rubber-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\24.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 60023 Signature of Inspector: PAJ

*Material Reinspected: M-GWB-25, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\25.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69223 Signature of Inspector: PA

*Material Reinspected: S-JTC-26, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\26.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-27, Sealant (Fire Stop), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\27.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAU ANGOR

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-TOT-28, Troweled-On Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High ✓ Medium Low

Degree of Activity Near the Material: High ✓ Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\28.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-29, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\29.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-30, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\30.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.15 Person performing reinspection: PAUL ANGEL

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-SAT-32, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\32.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Phil Anderson

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-33, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\33.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-34, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\34.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-SAT-39, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low

Degree of Activity Near the Material: High ✓ Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\39.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGELO

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-40, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\40.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: S-JTC-41, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\41.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Ambler

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69003 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-42, Glazed Wall Tile, 4", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\42.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-43, Glazed Wall Tile, 4", Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High ✓ Medium _____ Low _____
Degree of Activity Near the Material: _____ High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Foms\Bldg E\43.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-44, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\44.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-45, Glazed Wall Tile, 6"X8", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\45.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-GRT-46, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\46.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69013 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-47, Ceramic Mosaic Tile, 4"X4", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\47.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-48, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High — Medium — Low —

Degree of Activity Near the Material: High — Medium — Low —

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\48.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CON-50, Concrete, White, Cementitious, Blue Specks

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\50.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-51, Glazed Wall Tile, 4"X4", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\51.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-ADH-52, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High _____ Medium _____ Low _____
Degree of Activity Near the Material: _____ High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\52.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAU ANGCH

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-55, Ceramic Mosaic Tile, 2"X2", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\55.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Ambor
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-56, Ceramic Mosaic Tile (Pattern), 2"X2", Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\56.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOK
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-CMT-57, Ceramic Mosaic Tile (Pattern), 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\57.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 6902 Signature of Inspector: [Signature]

*Material Reinspected: M-WAB-59, Wallbase (L-Shaped), 4", Black, Vinyl-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\59.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: E

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-ADH-60, Adhesive, Cream Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low 1

Degree of Activity Near the Material: High 1 Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg E\60.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:
Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angel
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 49023 Signature of Inspector: [Signature]

*Material Reinspected: M-MAS-02, Mastic (Penetrations and Flashings), Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. (Misc.)

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes (No)
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes (No)
Explain: —

Assessment:

Evidence of Physical Damage: — Yes / (No)
Evidence of Water Damage: — Yes / (No)
Evidence of Delamination or Other Damage: — Yes / (No)
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes (No)
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / (No)

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes (No)
Explain: —

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Angor

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-SLT-03, Sealant (Flashing), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: ALL ANGEL

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-WDB-04, Woven Duct Boot, 2" Black, Rubber-like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No

Evidence of Water Damage: Yes No

Evidence of Delamination or Other Damage: Yes No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANKER

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-05, Sealant (Duct), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low 1

Degree of Activity Near the Material: High _____ Medium _____ Low 1

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANKER

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-SLT-06, Sealant (Duct), Pink, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No

Evidence of Water Damage: _____ Yes No

Evidence of Delamination or Other Damage: _____ Yes No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low 1

Degree of Activity Near the Material: High _____ Medium _____ Low 1

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\06.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-BRK-07, Brick, 4"X16", Red, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No

Evidence of Water Damage: _____ Yes No

Evidence of Delamination or Other Damage: _____ Yes No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____

Degree of Activity Near the Material: High 1 Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\07.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-08, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Tan

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No

Evidence of Water Damage: _____ Yes No

Evidence of Delamination or Other Damage: _____ Yes No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\08.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Ansel

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-09, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find 2.

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low _____
Degree of Activity Near the Material: High Medium Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\09.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anich

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69223 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-10, Concrete Masonry Unit, 4"X16", Dark Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes ✓ No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes ✓ No
Explain:

Assessment:

Evidence of Physical Damage: Yes ✓ No

Evidence of Water Damage: Yes ✓ No

Evidence of Delamination or Other Damage: Yes ✓ No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes ✓ No

Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes ✓ No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes ✓ No

Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\10.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAU Aniel
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: PAU

*Material Reinspected: M-CMU-11, Concrete Masonry Unit, 8"X8", Dark Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____
Degree of Activity Near the Material: High 1 Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\11.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: F
AHERA certification number: 49023 Signature of Inspector: [Signature]
*Material Reinspected: M-MRT-12, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find 2.

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low _____
Degree of Activity Near the Material: High Medium Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: Ry

*Material Reinspected: M-SLT-13, Sealant (Doors, Millwork, Walls), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____

Degree of Activity Near the Material: High 1 Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-14, Sealant (Walls), Brown, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: —

Assessment:

Evidence of Physical Damage: — Yes No
Evidence of Water Damage: — Yes No
Evidence of Delamination or Other Damage: — Yes No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: —

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\14.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAU AUGER

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69223 Signature of Inspector: RJF

*Material Reinspected: M-SLT-15, Sealant (Walls), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No

Evidence of Water Damage: _____ Yes No

Evidence of Delamination or Other Damage: _____ Yes No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No

Explain: _____

Degree of Accessibility of the Material: High Medium Low _____

Degree of Activity Near the Material: High Medium Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: Building F
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MRT-16, Mortar (Glass Block), White, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No
Evidence of Water Damage: _____ Yes No
Evidence of Delamination or Other Damage: _____ Yes No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High Medium Low _____
Degree of Activity Near the Material: High Medium Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\16.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-GWT-17, Glazed Wall Tile, 4"X4", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\17.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-18, Grout, Brown, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\18.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAU ANGOR

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-TOT-19, Troweled-On Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\19.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-20, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\20.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-21, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf 2. TSI 3.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low _____

Degree of Activity Near the Material: High Medium Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\21.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anzor
Facility: Kyrene Middle School Building Name/Number: F
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-CON-22, Concrete (Entries), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\22.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANSOR
Facility: Kyrene Middle School Building Name/Number: F
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-CON-23, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\23.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: ALL ANGOR
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69003 Signature of Inspector: [Signature]

*Material Reinspected: M-FDI-32, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High _____ Medium _____ Low _____
Degree of Activity Near the Material: _____ High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\32.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Wacht
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69223 Signature of Inspector: [Signature]

*Material Reinspected: S-SAT-33, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf 2. TSI 3.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No


Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\FORMS\Bldg F\33.doc



Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: F
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: S-SAT-34, Spray-Applied Texture, White, Chalky

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\35.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-35, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\35.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGELO

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-36, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High ✓ Medium Low

Degree of Activity Near the Material: High ✓ Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\36.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Ambler

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SAC-38, Sink Acoustical Coating, Gray, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\38.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-SAT-40, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\40.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-41, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Low Medium _____ Low _____

Degree of Activity Near the Material: High Low Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\41.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: F
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: S-JTC-42, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 1 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium Low
Degree of Activity Near the Material: High 1 Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\42.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angor

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-43, Glazed Wall Tile, 4"X4", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No

Evidence of Water Damage: _____ Yes No

Evidence of Delamination or Other Damage: _____ Yes No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\43.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: PAS

*Material Reinspected: M-GWT-44, Glazed Wall Tile (Pattern), 4"X4", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low _____

Degree of Activity Near the Material: High Medium Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F44.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-45, Glazed Wall Tile (Pattern), 4"X4", Dark Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\45.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANHART
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: B9023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-46, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\46.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69223 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-47, Ceramic Mosaic Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____

Degree of Activity Near the Material: High 1 Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\47.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-CMT-48, Ceramic Mosaic Tile (Pattern), 2"X2", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\48.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-49, Ceramic Mosaic Tile (Pattern), 2"X2", Dark Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\49.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAU ANGEL

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-50, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No

Evidence of Water Damage: _____ Yes No

Evidence of Delamination or Other Damage: _____ Yes No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\50.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-SLT-52, Sealant (Doors, Windows), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find 2.

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Low Medium _____ Low _____

Degree of Activity Near the Material: High Low Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\52.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angor
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: DG

*Material Reinspected: M-SLT-54, Sealant (Fire Stop), Green, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\54.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-ADH-55, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\55.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-PES-60, Pipe End Sealant, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High _____ Medium _____ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\60.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: PAJ

*Material Reinspected: M-CMU-61, Concrete Masonry Unit, 8"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\61.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAU ANGEL

Facility: Kyrene Middle School Building Name/Number: F

AHERA certification number: 69023 Signature of Inspector: PAU

*Material Reinspected: M-GAS-62, Gasket, 4", Black, Rubber-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High _____ Medium _____ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg F\62.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____

Degree of Activity Near the Material: High _____ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\FORMS\Bldg G\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MAS-02, Mastic (Penetrations and Flashings), Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year ReInsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69223 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-03, Sealant (Flashing), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Bill Anger
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: AS

*Material Reinspected: M-WDB-04, Woven Duct Boot, 2", Black, Rubber-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-05, Sealant (Duct), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low —

Degree of Activity Near the Material: High _____ Medium _____ Low —

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-06, Sealant (Duct), Pink, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\06.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER

Facility: Kyrene Middle School Building Name/Number: G

ASHERA certification number: G9023 Signature of Inspector: PA

*Material Reinspected: M-BRK-07, Brick, 4"X16", Red, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\07.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-08, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Tan

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\08.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-09, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\09.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAU ANGER
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-10, Concrete Masonry Unit, 4"X16", Dark Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\10.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: G
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-11, Concrete Masonry Unit, 8"X8", Dark Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low _____
Degree of Activity Near the Material: High Medium Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\11.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANKER

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: PAJ

*Material Reinspected: M-MRT-12, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-13, Sealant (Doors, Millwork, Walls), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANBOR

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-14, Sealant (Doors, Walls, Flashing), Brown, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No (X)
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No (X)
Explain:

Assessment:

Evidence of Physical Damage: Yes / No (X)

Evidence of Water Damage: Yes / No (X)

Evidence of Delamination or Other Damage: Yes / No (X)

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No (X)

Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No (X)

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No (X)

Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\14.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-15, Sealant (Walls), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: DJS

*Material Reinspected: M-MRT-16, Mortar (Glass Block), White, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\16.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-17, Glazed Wall Tile, 4"X4", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\17.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angor
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-18, Grout, Brown, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Farms\Bldg G\18.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-TOT-19, Troweled-On Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\19.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-20, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High ✓ Medium _____ Low _____
Degree of Activity Near the Material: _____ High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\20.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-21, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\21.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: PAJ

*Material Reinspected: M-CON-22, Concrete (Entries), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Frms\Bldg G\22.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anderson
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CON-23, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____
Degree of Activity Near the Material: _____
Location in an Air Plenum, Air Shaft, or Airstream: _____
High 1 Medium 2 Low 3
High 1 Medium 2 Low 3
Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\23.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-FDI-32, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\32.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-SAT-34, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\34.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angelo
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SAC-38, Sink Acoustical Coating, White, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\38.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: S-SAT-40, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\40.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: S-SAT-40, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\41.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anderson

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-41, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\41.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-42, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\42.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANKOR
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-43, Glazed Wall Tile, 4"X4", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\43.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-44, Glazed Wall Tile (Pattern), 4"X4", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High Medium Low _____
Degree of Activity Near the Material: _____ High Medium Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\44.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-45, Glazed Wall Tile (Pattern), 4"X4", Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\45.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: G
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-46, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\46.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-47, Ceramic Mosaic Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\47.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-48, Ceramic Mosaic Tile (Pattern), 2"X2", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\48.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anich
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-49, Ceramic Mosaic Tile (Pattern), 2"X2", Dark Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High Medium Low
Degree of Activity Near the Material: _____ High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\49.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-50, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\50.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-TWP-51, Tackable Wall Panel, Brown, Fibrous, Vinyl Cover

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No

Evidence of Water Damage: _____ Yes No

Evidence of Delamination or Other Damage: _____ Yes No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High Medium Low _____

Degree of Activity Near the Material: High Medium Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\51.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-52, Sealant (Doors, Windows), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium Low _____

Degree of Activity Near the Material: High Medium Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\52.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anhol

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-54, Sealant (Fire Stop), Green, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:

Evidence of Physical Damage: — Yes / No

Evidence of Water Damage: — Yes / No

Evidence of Delamination or Other Damage: — Yes / No

Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —

Degree of Activity Near the Material: High — Medium — Low —

Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: —

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\54.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 6923 Signature of Inspector: [Signature]

*Material Reinspected: M-ADH-55, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No

Evidence of Water Damage: _____ Yes No

Evidence of Delamination or Other Damage: _____ Yes No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\55.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PRUL ANGER

Facility: Kyrene Middle School Building Name/Number: G

AHERA certification number: 6923 Signature of Inspector: [Signature]

*Material Reinspected: M-PES-60, Pipe End Sealant, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg G\60.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR

Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: PAJ

*Material Reinspected: M-MAS-02, Mastic (Penetrations and Flashings), Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3- Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: H
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-03, Sealant (Flashing), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\FORMS\Bldg H\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER

Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-WDB-04, Woven Duct Boot, 2", Black, Rubber-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No

Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No

Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAU AUGER
Facility: Kyrene Middle School Building Name/Number: H
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-05, Sealant (Duct), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: H
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-06, Sealant (Duct), Pink, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\06.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger

Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-07, Concrete Masonry Unit, 4"X16", Red, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\07.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-CMU-08, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Tan

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\08.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAU ANGOR
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-09, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\09.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: BILL ANGER
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-10, Concrete Masonry Unit, 4"X16", Dark Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\10.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-11, Concrete Masonry Unit, 8"X8", Dark Gray, Cementitious, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High ✓ Medium _____ Low _____
Degree of Activity Near the Material: _____ High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\11.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MRT-12, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: H
AHERA certification number: 69023 Signature of Inspector: PAJ

*Material Reinspected: M-MRT-13, Sealant (Doors, Windows, Millwork, Walls), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No (X)
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No (X)
Explain:

Assessment:

Evidence of Physical Damage: Yes No (X)
Evidence of Water Damage: Yes No (X)
Evidence of Delamination or Other Damage: Yes No (X)
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No (X)
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No (X)

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No (X)
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGER

Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-14, Sealant (Walls), Brown, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\14.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angier

Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: GA023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-15, Sealant (Walls), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No

Evidence of Water Damage: _____ Yes No

Evidence of Delamination or Other Damage: _____ Yes No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium Low

Degree of Activity Near the Material: High ✓ Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANKER
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MRT-16, Mortar (Glass Block), White, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:
Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\16.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 6903 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-17, Glazed Wall Tile, 4"X4", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\17.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-18, Grout, Brown, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\18.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-TOT-19, Troweled-On Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 1 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High 1 Medium Low
Degree of Activity Near the Material: _____ High 1 Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\19.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-20, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\20.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anderson
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-21, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 1 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium Low

Degree of Activity Near the Material: High 1 Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\21.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL HANCOCK
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CON-22, Concrete (Entries), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\22.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CON-23, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\23.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAU Anzel

Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-FDI-32, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\32.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-SAT-33, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\33.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-SAT-34, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 1 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium Low
Degree of Activity Near the Material: High 1 Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\34.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 6923 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-35, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High ✓ Medium _____ Low _____
Degree of Activity Near the Material: _____ High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\35.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-36, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Farms\Bldg H\36.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SAC-38, Sink Acoustical Coating, White, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\38.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-SAT-40, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\40.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-41, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\FORMS\Bldg H\41.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-42, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\42.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-43, Glazed Wall Tile, 4"X4", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\43.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-44, Glazed Wall Tile (Pattern), 4"X4", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place — 2. Did Not Find —

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: —

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: —

Assessment:

Evidence of Physical Damage: — Yes / No
Evidence of Water Damage: — Yes / No
Evidence of Delamination or Other Damage: — Yes / No
Explain: —

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: —

Degree of Accessibility of the Material: High — Medium — Low —
Degree of Activity Near the Material: High — Medium — Low —
Location in an Air Plenum, Air Shaft, or Airstream: — Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: —

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\44.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul ANKOR
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69223 Signature of Inspector: PJG

*Material Reinspected: M-GWT-45, Glazed Wall Tile (Pattern), 4"X4", Dark Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\45.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Archer
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-46, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. (Misc)

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes (No)
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes (No)
Explain:

Assessment:

Evidence of Physical Damage: Yes (No)
Evidence of Water Damage: Yes (No)
Evidence of Delamination or Other Damage: Yes (No)
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes (No)
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes (No)

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes (No)
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\46.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: H
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-47, Ceramic Mosaic Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\47.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAU ANGOR
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-48, Ceramic Mosaic Tile, 2"X2", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No (X)
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No (X)
Explain:

Assessment:

Evidence of Physical Damage: Yes / No (X)
Evidence of Water Damage: Yes / No (X)
Evidence of Delamination or Other Damage: Yes / No (X)
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No (X)
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No (X)

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No (X)
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\48.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-49, Ceramic Mosaic Tile, 2"X2", Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\49.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANKER
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: PAJ

*Material Reinspected: M-GRT-50, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\50.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-TWP-51, Tackable Wall Panel, Brown, Fibrous, Vinyl Cover

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\51.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Ambler
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-52, Sealant (Doors, Windows), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No
Evidence of Water Damage: _____ Yes No
Evidence of Delamination or Other Damage: _____ Yes No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\52.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANKER
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-54, Sealant (Fire Stop), Green, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____
Degree of Activity Near the Material: High Medium Low _____
Location in an Air Plenum, Air Shaft, or Airstream: High Medium Low _____
Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\54.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: H

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-ADH-55, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:
Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:


Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\55.doc



Reinspection Date: 1.3.19 Person performing reinspection: Paul Angel
Facility: Kyrene Middle School Building Name/Number: H
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-PES-60, Pipe End Sealant, White, Pliable

G:\2018 Projects\10 ENV\KSD\18-183 December 3-Years\2.0\2.3\2.3.1\Kyrene\Forms\Bldg H\60.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-TOT-01, Troweled-On Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: High ✓ Medium _____ Low _____
Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANKER
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-02, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High ✓ Medium _____ Low _____
Degree of Activity Near the Material: _____ High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: DAG

*Material Reinspected: S-JTC-03, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-STU-04, Stucco, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-05, Concrete Masonry Unit, 4"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-BRK-06, Brick, 4"X16", Red, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium _____ Low _____

Degree of Activity Near the Material: High 1 Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\06.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: DAUL ANGER
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-07, Concrete Masonry Unit, 8"X8", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High 1 Medium _____ Low _____
Degree of Activity Near the Material: _____ High 1 Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\07.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MRT-08, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\08.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAU ANGOR
Facility: Kyrene Middle School Building Name/Number: J
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-09, Sealant (Doors, Windows, Walls), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\09.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angor
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-10, Sealant (Doors), Tan, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place / 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No (X)
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No (X)
Explain:

Assessment:

Evidence of Physical Damage: Yes / No (X)
Evidence of Water Damage: Yes / No (X)
Evidence of Delamination or Other Damage: Yes / No (X)
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No (X)
Explain:

Degree of Accessibility of the Material: High / Medium Low
Degree of Activity Near the Material: High / Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No (X)

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No (X)
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Farms\Bldg J\10.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-CON-11, Concrete (Entries), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\11.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CON-12, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No X
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No X
Explain:

Assessment:

Evidence of Physical Damage: Yes / No X
Evidence of Water Damage: Yes / No X
Evidence of Delamination or Other Damage: Yes / No X
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No X
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No X

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No X
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-13, Concrete Masonry Unit, 8"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No

Evidence of Water Damage: Yes No

Evidence of Delamination or Other Damage: Yes No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MRT-14, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\14.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angel
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-15, Concrete Masonry Unit, 4"X16", Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Angel

Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MRT-16, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\16.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-FDI-17, Fire Door Insulation, Wood/Metal Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\17.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMU-18, Concrete Masonry Unit, 4"X16", Dark Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\FORMS\Bldg J\18.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 59023 Signature of Inspector: [Signature]

*Material Reinspected: M-VCT-24, Vinyl Composition Tile, 12"X12", Tan, Smooth, Multi-Colored

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\24.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69033 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-29, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\FORMS\Bldg J\29.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAU ANGEL
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SAC-30, Sink Acoustical Coating, Gray, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\31.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-31 Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find 2

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: _____ High 1 Medium _____ Low _____
Degree of Activity Near the Material: _____ High 1 Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\31.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angelo
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-32, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low

Degree of Activity Near the Material: High ✓ Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\32.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-ADH-33, Adhesive (Residual), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: High _____ Medium _____ Low _____
Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\33.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anderson
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-SAT-35, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\FORMS\Bldg J\35.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angier
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-36, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\36.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-37, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 1 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium Low
Degree of Activity Near the Material: High 1 Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\37.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-38, Glazed Wall Tile, 4"X4", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: _____
Degree of Activity Near the Material: _____
Location in an Air Plenum, Air Shaft, or Airstream: _____
High ✓ Medium _____ Low _____
High ✓ Medium _____ Low _____
Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\38.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-39, Glazed Wall Tile (Pattern), 4"x4", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\39.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-40, Glazed Wall Tile (Pattern), 4"X4", Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\40.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-41, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low

Degree of Activity Near the Material: High Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\41.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-42, Ceramic Mosaic Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\42.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: J
AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: M-CMT-43, Ceramic Mosaic Tile, 2"X2", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\43.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-44, Ceramic Mosaic Tile, 2"X2", Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\44.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-45, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No
Evidence of Water Damage: _____ Yes No
Evidence of Delamination or Other Damage: _____ Yes No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\45.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-PSL-46, Pipe Sealant, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes No
Evidence of Water Damage: _____ Yes No
Evidence of Delamination or Other Damage: _____ Yes No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\46.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GAS-47, Gasket, 4", Black, Rubber-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\47.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 59023 Signature of Inspector: PA

*Material Reinspected: M-ADH-48, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\48.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANKER
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: G9023 Signature of Inspector: [Signature]

*Material Reinspected: S-SAT-49, Spay-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\49.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL LANGER
Facility: Kyrene Middle School Building Name/Number: J
AHERA certification number: 69003 Signature of Inspector: PLS

*Material Reinspected: M-GWB-50, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\50.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-51, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low

Degree of Activity Near the Material: High ✓ Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\51.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CON-52, Concrete (Foundation), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\52.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: GA023 Signature of Inspector: DAS

*Material Reinspected: M-WDB-53, Woven Duct Boot, 2", Black, Rubber-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\53.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Ansel
Facility: Kyrene Middle School Building Name/Number: J

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-PLA-54, Plaster, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg J\54.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANSO
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\01.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MAS-02, Mastic (Penetrations And Flashings), Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes /No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes /No
Explain:

Assessment:

Evidence of Physical Damage: Yes /No
Evidence of Water Damage: Yes /No
Evidence of Delamination or Other Damage: Yes /No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes /No
Explain:

Degree of Accessibility of the Material: High Medium Low ✓
Degree of Activity Near the Material: High Medium Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: Yes /No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes /No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\02.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-03, Sealant (Flashing), Gray, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place / 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low /
Degree of Activity Near the Material: High _____ Medium _____ Low /
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Farms\Bldg K\03.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Don Angel
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: DJ

*Material Reinspected: S-STU-04, Stucco, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\04.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: PAJ

*Material Reinspected: M-CMU-05, Concrete Masonry Unit, 4"X16", Gray, Cementitious, Tan

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\05.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGELO
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MRT-06, Mortar, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No

Evidence of Water Damage: Yes / No

Evidence of Delamination or Other Damage: Yes / No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low

Degree of Activity Near the Material: High ✓ Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\06.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-07, Sealant (Wall, Flashing), Tan, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\07.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CON-10, Concrete (Entries), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\10.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anker
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SLT-12, Sealant (Windows), Black, Tar-Like

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\12.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-FDI-13, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low ✓
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\13.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angelo
Facility: Kyrene Middle School Building Name/Number: K
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-SAT-15, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 1 2. TSI 3. Misc.

Material Status: 1. In-Place 1 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High 1 Medium Low
Degree of Activity Near the Material: High 1 Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\15.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-16, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\16.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angier
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: PA

*Material Reinspected: S-JTC-17, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\17.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-SAC-29, Sink Acoustical Coating, Gray, Rough

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\29.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANKOR
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-30, Glazed Wall Tile, 4"X4", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\30.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-31, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:
Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\31.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: K
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-32, Ceramic Mosaic Tile, 2"X2", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\32.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: K
AHERA certification number: 69003 Signature of Inspector: [Signature]

*Material Reinspected: M-GRT-33, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\33.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Angor
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-SAT-34, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENVKSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\34.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-35, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\35.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Ambler
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: PS

*Material Reinspected: S-JTC-36, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\36.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PLU Angel
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: PLU

*Material Reinspected: S-TOT-37, Troweled-On Texture, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. ...

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No
Evidence of Water Damage: Yes No
Evidence of Delamination or Other Damage: Yes No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\37.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Angelo
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-GWB-38, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\38.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: S-JTC-39, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\39.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anderson

Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69003 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-41, Glazed Wall Tile (Pattern), 4"X4", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes No
Explain:

Assessment:

Evidence of Physical Damage: Yes No

Evidence of Water Damage: Yes No

Evidence of Delamination or Other Damage: Yes No

Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes No

Explain:

Degree of Accessibility of the Material: High ✓ Medium Low

Degree of Activity Near the Material: High ✓ Medium Low

Location in an Air Plenum, Air Shaft, or Airstream: Yes No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes No

Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\41.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGOR
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 64223 Signature of Inspector: [Signature]

*Material Reinspected: M-GWT-42, Glazed Wall Tile (Pattern), 4"X4", Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High ✓ Medium Low
Degree of Activity Near the Material: High ✓ Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\42.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-CMT-43, Ceramic Mosaic Tile, 2"X2", Light Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low _____
Degree of Activity Near the Material: High Medium Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\43.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Ansel
Facility: Kyrene Middle School Building Name/Number: K
AHERA certification number: 69223 Signature of Inspector: PS

*Material Reinspected: M-CMT-44, Ceramic Mosaic Tile, 2"X2", Green, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\44.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: K

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-ADH-45, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\45.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: K
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-PES-46, Pipe End Sealant, White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg K\46.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: L
AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-BUR-01, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain:

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain:

Assessment:

Evidence of Physical Damage: Yes / No
Evidence of Water Damage: Yes / No
Evidence of Delamination or Other Damage: Yes / No
Explain:

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain:

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: Yes / No


Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain:

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg L\01.doc



Reinspection Date: 1-3-19 Person performing reinspection: Paul Anderson
Facility: Kyrene Middle School Building Name/Number: L
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-FDI-17, Fire Door Insulation, Metal/Wood Cladding

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg L\17.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: L
AHERA certification number: 69023 Signature of Inspector: [Signature]
*Material Reinspected: M-ADH-40, Adhesive (Residual), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg L\40.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1.3.19 Person performing reinspection: Paul Anger
Facility: Kyrene Middle School Building Name/Number: L

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-MAS-58, Mastic (VCT), Black, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg L\58.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 1-3-19 Person performing reinspection: PAUL ANGEL
Facility: Kyrene Middle School Building Name/Number: L

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-ADH-77, Adhesive (Mirror), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg L\77.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: _____ Person performing reinspection: PAUL ANGER
Facility: Kyrene Middle School Building Name/Number: L

AHERA certification number: 69023 Signature of Inspector: [Signature]

*Material Reinspected: M-ADH-80, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place _____ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*

G:\2018 Projects\10 ENV\KSD\18-259 3-Year Reinsp\2.0\2.3\2.3.1\Kyrene\Forms\Bldg L\80.doc