

September 21, 2021

Mr. Mike Williams
Facilities Supervisor
Kyrene School District No. 28
8700 South Kyrene Road
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection
Asbestos-Containing Building Materials
Kyrene de la Esperanza Elementary School
14841 South 41st Place, Phoenix
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.

The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

Items of significance are: None.

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

FM GROUP INC



Michael Hall
Environmental Division Manager

*Attachments: 3-Year Reinspection Tables
3-Year Reinspection Forms*

3-YEAR REINSPECTION TABLE

IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-01	M	Built-Up Roofing, Black, Asphaltic, Gravel Cap	Roof	Assumed	NF	G	70,000	SF	09/16/21
M-MAS-02	M	Mastic (Penetrations and Flashings), Black, Tar-Like, Silver	Roof	Assumed	NF	G	2,000	SF	09/16/21
M-SLT-03	M	Sealant (Flashings), Black, Pliable, Silver	Roof	Assumed	NF	G	200	SF	09/16/21
M-BUR-04	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	3,000	SF	09/16/21
M-MAS-05	M	Mastic (Penetrations and Flashings), Black, Tar-Like, Silver	Roof	Assumed	NF	G	200	SF	09/16/21
M-SLT-17	M	Sealant (Canopy), Gray, Pliable	Roof	Assumed	NF	G	25	SF	09/16/21
M-MAS-18	M	Mastic (Penetrations), Black, Tar-Like	Roof	Assumed	NF	G	1	SF	09/16/21
M-SLT-19	M	Sealant (Equipment), Gray, Pliable	Roof	Assumed	NF	G	5	SF	09/16/21
M-SLT-20	M	Sealant (Windows), Black, Pliable	Roof	Assumed	NF	G	10	SF	09/16/21
M-SLT-21	M	Sealant (Flashings), White, Brittle	Roof	Assumed	NF	G	5	SF	09/16/21
M-FDI-29	M	Fire Door Insulation, Metal/Wood Cladding	Reception	Assumed	NF	G	2,268	SF	09/16/21
			Electrical 2						
			Office 1						
			Women's Restroom 1						
			Men's Restroom 1						
			Telecom						
			Storage 6						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Faculty Lounge						
			Workroom						
			Hall 1						
			Fire Riser						
			Storage 7						
			Treatment						
			Hall 2						
			Kindergarten 1						
			Storage 1						
			Kindergarten 2						
			Storage 2						
			Kindergarten 3						
			Classroom 4						
			Classroom 5						
			Classroom 6						
			Classroom 7						
			Classroom 8						
			Classroom 9						
			Classroom 10						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Custodial 1						
			Classroom 13						
			Classroom 14						
			Classroom 15						
			Classroom 16						
			Classroom 17						
			Classroom 19						
			Classroom 20						
			Classroom 21						
			Classroom 23						
			Classroom 24						
			Classroom 27						
			Classroom 30						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 31						
			Art Service Yard						
			Speech 36						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Custodial 4						
			Library						
			Computer Lab						
			Library Office						
			Library Storage						
			Psychology						
			Special Ed 38						
			Special Ed 39						
			Room 39 Restroom						
			Special Ed 40						
			Conference						
			Music 43						
			Storage 5						
			Water Heater 1						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Stage						
			West Wing						
			East Wing						
			Multi-Purpose						
			Storage 3						
			Storage 4						
			Girl's Restroom 4						
			Boy's Restroom 4						
			P.E. Storage						
			P.E. Office						
			Kitchen						
			Water Heater 2						
			Kitchen Service Yard						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Table Storage						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
			Corridor 8						
			Corridor 9						
			Corridor 10						
			Exterior						
M-PSL-39	M	Pipe Sealant (Fire Sprinklers), White, Pliable	Reception	Assumed	NF	G	75	SF	09/16/21
			Principal						
			Principal Storage						
			Assistant Principal						
			Electrical 2						
			Office 1						
			Women's Restroom 1						
			Men's Restroom 1						
			Telecom						
			Storage 6						
			Faculty Lounge						
			Tele 1						
			Tele 2						
			Workroom						
			Hall 1						
			Nurse						
			Nurse Restroom						
			Fire Riser						
			Storage 7						
			Treatment						
			Hall 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Kindergarten 1						
			Kindergarten 1 Restroom						
			Storage 1						
			Kindergarten 2						
			Kindergarten 2 Restroom						
			Storage 2						
			Kindergarten 3						
			Kindergarten 3 Restroom						
			Classroom 4						
			Classroom 5						
			Classroom 6						
			Classroom 7						
			Classroom 8						
			Classroom 9						
			Workroom 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Custodial 1						
			Classroom 10						
			Classroom 11						
			Classroom 12						
			Classroom 13						
			Classroom 14						
			Classroom 15						
			Workroom 2						
			Classroom 16						
			Classroom 17						
			Classroom 18						
			Classroom 19						
			Classroom 20						
			Classroom 21						
			Workroom 3						
			Classroom 22						
			Classroom 23						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 24						
			Classroom 25						
			Classroom 26						
			Classroom 27						
			Workroom 4						
			Classroom 28						
			Classroom 29						
			Classroom 30						
			Classroom 31						
			Classroom 32						
			Classroom 33						
			Workroom 5						
			Art Service Yard						
			Speech 36						
			Room 36 To						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Custodial 4						
			Library						
			Computer Lab						
			Computer Lab Storage						
			Library Office						
			Library Storage						
			Psychology						
			Psychology Storage						
			Special Ed 38						
			Special Ed 39						
			Room 39 Restroom						
			Special Ed 40						
			Conference						
			Music 43						
			Storage 5						
			Water Heater 1						
			Boy's Restroom 5						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 5						
			Stage						
			West Wing						
			East Wing						
			Multi-Purpose						
			Storage 3						
			Storage 4						
			Girl's Restroom 4						
			Boy's Restroom 4						
			P.E. Storage						
			P.E. Office						
			Kitchen						
			Water Heater 2						
			Kitchen Service Yard						
			Table Storage						
			Entry						
			Living						
			Apt Kitchen						
			Dining						
			Laundry						
			Bedroom 1						
			Bedroom 1 Restroom						
			Pantry						
			Apt Hall						
			Apt Hall Closet						
			Bedroom 2						
			Guest Restroom						
			Corridor 1						
			Corridor 2						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-PES-40	M	Pipe End Sealant, White, Pliable	Reception	Assumed	NF	G	50	SF	09/16/21
			Principal						
			Principal Storage						
			Assistant Principal						
			Electrical 2						
			Office 1						
			Women's Restroom 1						
			Men's Restroom 1						
			Telecom						
			Storage 6						
			Faculty Lounge						
			Tele 1						
			Tele 2						
			Workroom						
			Hall 1						
			Nurse						
			Nurse Restroom						
			Fire Riser						
			Storage 7						
			Treatment						
			Hall 2						
			Kindergarten 1						
			Kindergarten 1 Restroom						
			Storage 1						
			Kindergarten 2						
			Kindergarten 2 Restroom						
			Storage 2						
			Kindergarten 3						
			Kindergarten 3 Restroom						
			Classroom 4						
			Classroom 5						
			Classroom 6						
			Classroom 7						
			Classroom 8						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Classroom 9						
			Workroom 1						
			Boy's Restroom 1						
			Girl's Restroom 1						
			Custodial 1						
			Classroom 10						
			Classroom 11						
			Classroom 12						
			Classroom 13						
			Classroom 14						
			Classroom 15						
			Workroom 2						
			Classroom 16						
			Classroom 17						
			Classroom 18						
			Classroom 19						
			Classroom 20						
			Classroom 21						
			Workroom 3						
			Classroom 22						
			Classroom 23						
			Classroom 24						
			Classroom 25						
			Classroom 26						
			Classroom 27						
			Workroom 4						
			Classroom 28						
			Classroom 29						
			Classroom 30						
			Classroom 31						
			Classroom 32						
			Classroom 33						
			Workroom 5						
			Art Service Yard						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Speech 36						
			Room 36 To						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Custodial 4						
			Library						
			Computer Lab						
			Computer Lab Storage						
			Library Office						
			Library Storage						
			Psychology						
			Psychology Storage						
			Special Ed 38						
			Special Ed 39						
			Room 39 Restroom						
			Special Ed 40						
			Conference						
			Music 43						
			Storage 5						
			Water Heater 1						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Stage						
			West Wing						
			East Wing						
			Multi-Purpose						
			Storage 3						
			Storage 4						
			Girl's Restroom 4						
			Boy's Restroom 4						
			P.E. Storage						
			P.E. Office						
			Kitchen						
			Water Heater 2						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Kitchen Service Yard						
			Table Storage						
			Entry						
			Living						
			Apt Kitchen						
			Dining						
			Laundry						
			Bedroom 1						
			Bedroom 1 Restroom						
			Pantry						
			Apt Hall						
			Apt Hall Closet						
			Bedroom 2						
			Guest Restroom						
			Corridor 1						
			Corridor 2						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
M-CPT-43	M	Carpet, Gray, Fibrous	Stage	Assumed	NF	G	650	SF	09/16/21
M-VCT-49	M	Vinyl Composition Tile (Pattern), 12"X12", Red, Smooth, Dark Red Mottles	Multi-Purpose	Assumed	NF	G	25	SF	09/16/21
M-VCT-50	M	Vinyl Composition Tile (Pattern), 12"X12", Black, Smooth, White Mottles	Multi-Purpose	Assumed	NF	G	25	SF	09/16/21
M-VCT-51	M	Vinyl Composition Tile (Strip), 2"X24", Red, Smooth	Multi-Purpose	Assumed	NF	G	25	SF	09/16/21
M-VCT-52	M	Vinyl Composition Tile (Strip), 2"X24", Blue, Smooth	Multi-Purpose	Assumed	NF	G	25	SF	09/16/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-VCT-53	M	Vinyl Composition Tile (Strip), 2"X24", Black, Smooth	Multi-Purpose	Assumed	NF	G	50	SF	09/16/21
M-VCT-54	M	Vinyl Composition Tile (Strip), 2"X24", Yellow, Smooth	Multi-Purpose	Assumed	NF	G	25	SF	09/16/21
M-VCT-55	M	Vinyl Composition Tile (Strip), 2"X24", Green, Smooth	Multi-Purpose	Assumed	NF	G	25	SF	09/16/21
M-ADH-59	M	Adhesive (FRP), Brown, Brittle	Kitchen	Assumed	NF	G	40	SF	09/16/21
M-GWT-67	M	Glazed Wall Tile, 4"X4", Gray, Smooth	Boy's Restroom 1	Assumed	NF	G	2,200	SF	09/16/21
			Girl's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Girl's Restroom 4						
			Boy's Restroom 4						
M-GWT-68	M	Glazed Wall Tile (Pattern), 4"X4", Black, Smooth	Boy's Restroom 1	Assumed	NF	G	100	SF	09/16/21
			Girl's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Girl's Restroom 4						
			Boy's Restroom 4						
M-GWT-69	M	Glazed Wall Tile (Pattern), 4"X4", Tan, Smooth	Boy's Restroom 1	Assumed	NF	G	100	SF	09/16/21
			Girl's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 5						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Girl's Restroom 5						
			Girl's Restroom 4						
			Boy's Restroom 4						
M-GRT-70	M	Grout, Gray, Cementitious	Boy's Restroom 1	Assumed	NF	G	2,200	SF	09/16/21
			Girl's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Girl's Restroom 4						
			Boy's Restroom 4						
M-CMT-71	M	Ceramic Mosaic Tile, 2"X2", Gray, Smooth, White Specks	Boy's Restroom 1	Assumed	NF	G	3,000	SF	09/16/21
			Girl's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Girl's Restroom 4						
			Boy's Restroom 4						
M-GRT-72	M	Grout, Gray, Cementitious	Boy's Restroom 1	Assumed	NF	G	300	SF	09/16/21
			Girl's Restroom 1						
			Boy's Restroom 3						
			Girl's Restroom 3						
			Boy's Restroom 5						
			Girl's Restroom 5						
			Girl's Restroom 4						
			Boy's Restroom 4						
M-GWB-74	M	Gypsum Wallboard, White, Chalky	Electrical 2	Assumed	NF	G	400	SF	09/16/21
S-JTC-75	S	Joint Compound, White, Chalky	Electrical 2	Assumed	NF	G	40	SF	09/16/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-FDI-114	M	Fire Door Insulation, Metal/Wood Cladding	Exterior	Assumed	NF	G	294	SF	

- **The following materials were not found: M-GWB-74, S-JTC-75, S-SAT-79, M-GWB-81, S-JTC-81, M-GWT-87, M-GRT-88, S-SAT-89, M-GWB-90, S-JTC-91, M-SLT-92, M-SLT-93 and M-SAC-94.**

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\SierraMain-Tbl.doc



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carlyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 43701250123164 Signature of Inspector: Carlyn Hall

*Material Reinspected: M-QPT-07, Quarry/Paver Tile, 8"X8", Red, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380 1269 123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-10, Glazed Wall Tile, 8"X8", White, Smooth, Multi-Colored, Hand Painted Designs

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4386 12561 123161 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-11, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 12601 123154 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-CON-14, Concrete (Equipment Pad), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low

Degree of Activity Near the Material: High _____ Medium _____ Low

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 43001201123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-27, Fire Door Insulation, Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 43701250112369 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PSL-28, Pipe Sealant, Yellow, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low

Degree of Activity Near the Material: High _____ Medium _____ Low

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 12501 123164 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-FDI-44, Fire Door Insulation, Metal Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 438012001128104 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GWT-51, Glazed Wall Tile, 4"X4", Tan, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 438012501123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-52, Glazed Wall Tile (Pattern), 4"X4", Blue, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 123164 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-GRT-53, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 437012501 12/26/19 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-CMT-54, Ceramic Mosaic Tile, 2"X2", Tan, Smooth, Peppered

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Coryn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 1261 123164 Signature of Inspector: Coryn Hall

*Material Reinspected: M-GRT-55, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4310 12561 123109 Signature of Inspector: Carbyn Hall

*Material Reinspected: M-ADH-56, Adhesive (FRP), Brown, Brittle

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 12001 122164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-PSL-57, Pipe Sealant, Green, Gummy

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low ✓
Degree of Activity Near the Material: High _____ Medium _____ Low ✓
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4320 12001 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-58, Sealant (Equipment), Black, Gummy

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low
Degree of Activity Near the Material: High _____ Medium _____ Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 1250 125164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-APL-59, Acoustical Ceiling Panel, 2'x2', Yellow, Fibrous Glass, Cloth Cover

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High _____ Medium Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 43101251123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-SAT-66, Spray-Applied Texture, White, Chalky

Type of Asbestos-Containing Material: 1 Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 459012501123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWB-67, Gypsum Wallboard, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 1251 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: S-JTC-68, Joint Compound, White, Chalky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carlynn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 432012501123164 Signature of Inspector: Carlynn Hall

*Material Reinspected: M-QPT-69, Quarry/Paver Tile, 8"X8", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-70, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Carbyn Hull
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4180 1251 121044 Signature of Inspector: Carbyn Hull

*Material Reinspected: M-VSF-71, Vinyl Sheet Flooring, Blue, Smooth, White Mottles, Gray Paper Backing

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place _____ 2. Did Not Find ✓

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: Material missing

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 438012601020166 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MAS-72, Mastic, Yellow, Tacky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place _____ 2. Did Not Find ✓

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: Material missing

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium _____ Low _____
Degree of Activity Near the Material: High _____ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4376 125123169 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-MAS-74, Mastic, Yellow, Tacky

Type of Asbestos-Containing Material: 1. Surf. 2. TSI (3) Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4390 12561 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GWT-75, Glazed Wall Tile, 4"X4", White, Smooth

Type of Asbestos-Containing Material: 1. Surf. 2. TSI Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 4/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 1251 123164 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-76, Grout, Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No

Evidence of Water Damage: _____ Yes / No

Evidence of Delamination or Other Damage: _____ Yes / No

Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High ✓ Medium _____ Low _____

Degree of Activity Near the Material: High ✓ Medium _____ Low _____

Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380 1250 12369 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-SLT-77, Sealant (Doors, Windows, Millwork, Fixtures), White, Pliable

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High Medium Low
Degree of Activity Near the Material: High Medium Low
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

**Reference the original Management Plan for additional information.*



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380 1252 0234 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-GRT-78, Grout (Glass Block), Gray, Cementitious

Type of Asbestos-Containing Material: 1. Surf. 2. TSI **(3)** Misc.

Material Status: 1. In-Place 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / **No**
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / **No**
Explain: _____

Assessment:
Evidence of Physical Damage: _____ Yes / **No**
Evidence of Water Damage: _____ Yes / **No**
Evidence of Delamination or Other Damage: _____ Yes / **No**
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / **No**
Explain: _____

Degree of Accessibility of the Material: High Medium _____ Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / **No**

- Assessment Classification:**
1. Damaged or significantly damaged thermal system insulation ACBM.
 2. Damaged friable surfacing ACBM.
 3. Significantly damaged friable surfacing ACBM.
 4. Damaged or significantly damaged friable miscellaneous ACBM.
 5. ACBM with potential for damage.
 6. ACBM with potential for significant damage.
 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / **No**
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4380125d, 123167 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-122, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3. Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Hall
Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4370 1201 12316 Signature of Inspector: Corbyn Hall

*Material Reinspected: M-FDI-130, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place 2. Did Not Find

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No

Explain: _____

Degree of Accessibility of the Material: High _____ Medium Low _____
Degree of Activity Near the Material: High Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No

Explain: _____

*Reference the original Management Plan for additional information.



15974 North 77th Street, Suite 100
Scottsdale, AZ 85260

3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/21/21 Person performing reinspection: Corbyn Han

Facility: Kyrene de las Esperanza Elementary School Building Name/Number: Main

AHERA certification number: 4300 12501 123169 Signature of Inspector: Corbyn Han

*Material Reinspected: M-FDI-230, Fire Door Insulation, Metal/Wood Cladding

Type of Asbestos-Containing Material: 1. Surf. 2. TSI 3 Misc.

Material Status: 1. In-Place ✓ 2. Did Not Find _____

Material Condition: Has the condition of this material changed since the last inspection? Yes / No
Explain: _____

Material Friability: Has the friability of this material changed since the last inspection? Yes / No
Explain: _____

Assessment:

Evidence of Physical Damage: _____ Yes / No
Evidence of Water Damage: _____ Yes / No
Evidence of Delamination or Other Damage: _____ Yes / No
Explain: _____

Potential for Disturbance: Has the potential for disturbance of this material changed since the last inspection? _____ Yes / No
Explain: _____

Degree of Accessibility of the Material: High _____ Medium ✓ Low _____
Degree of Activity Near the Material: High ✓ Medium _____ Low _____
Location in an Air Plenum, Air Shaft, or Airstream: _____ Yes / No

Assessment Classification:

- 1. Damaged or significantly damaged thermal system insulation ACBM.
- 2. Damaged friable surfacing ACBM.
- 3. Significantly damaged friable surfacing ACBM.
- 4. Damaged or significantly damaged friable miscellaneous ACBM.
- 5. ACBM with potential for damage.
- 6. ACBM with potential for significant damage.
- 7. Any remaining friable ACBM or friable suspected ACBM.

Recommended Action: As a result of this reinspection, has the recommended response action for this material changed? _____ Yes / No
Explain: _____

*Reference the original Management Plan for additional information.