

October 04, 2021

Mr. Mike Williams  
Facilities Supervisor  
Kyrene School District No. 28  
8700 South Kyrene Road  
Tempe, AZ 85284-2197

**Subject: 3-Year Reinspection  
Asbestos-Containing Building Materials  
Kyrene Traditional Academy  
(Former Kyrene del Sureno Elementary School)  
3375 West Galveston Street, Chandler  
FM Project 21-343**

Dear Mr. Williams:

FM GROUP INC has completed the 3-Year Reinspection of Asbestos-Containing Building Materials (ACBM) at the subject school. The forms detailing the results of this reinspection and reassessment of known ACBM are attached.


The attached tables and forms have been updated to reflect the findings as of the date of this Reinspection and should serve as the Management Plan update.

**Items of significance are: None.**

If you have any questions regarding this correspondence, please contact us immediately.

Sincerely,

**FM GROUP INC**



Michael Hall  
Environmental Division Manager

*Attachments: 3-Year Reinspection Tables  
3-Year Reinspection Forms*

*G:\2021 Projects\10 ENVKSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Cvr Ltr.doc*

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-ADH-07	M	Adhesive, Brown, Brittle	Reception	Assumed	NF	G	3,500	SF	10/04/21
			Hall 1						
			Principal Office						
			Psy/Conf.						
			Faculty Lounge						
			Computer						
			Speech						
			Special Ed. 1						
			Special Ed. 2						
			Special Ed. 3						
			Room 10						
			Room 11						
			Room 12						
			Room 13						
			Room 14						
			Room 15						
			Room 16						
			Room 17						
			Room 18						
			Room 19						
			Room 20						
			Room 21						
			Room 22						
			Room 23						
			Room 24						
			Room 25						
			Room 26						
			Room 27						
			Room 28						
			Room 29						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 30						
			Room 31						
			Music						
			Multi-Purpose						
M-MRT-10	M	Mortar (Glass Block), Gray, Cementitious	Reception	Assumed	NF	G	100	SF	10/04/21
			Treatment						
			Nurse's Office						
			Psy/Conf.						
			Faculty Work						
			Computer						
			Special Ed. 1						
			Special Ed. 2						
			Special Ed. 3						
			Room 10						
			Room 11						
			Room 12						
			Room 13						
			Room 14						
			Room 15						
			Room 16						
			Room 17						
			Room 18						
			Room 19						
			Room 20						
			Room 21						
			Room 22						
			Room 23						
			Room 24						
			Room 25						
			Room 26						
			Room 27						
			Room 28						
			Room 29						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 30						
			Room 31						
			Multi-Purpose						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			West Foyer						
			Corridor 7						
			Corridor 8						
			Corridor 9						
			Corridor 10						
			East Foyer						
			Corridor 11						
			Corridor 12						
			Corridor 13						
			Exterior						
M-FDI-13	M	Fire Door Insulation, Metal Cladding	Reception	Assumed	NF	G	693	SF	10/04/21
			Treatment						
			West Boy's Restroom						
			West Vestibule						
			Room 10						
			Room 11						
			Multi-Purpose						
			Kitchen						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			Corridor 7						
			Corridor 8						
			Corridor 9						
			Corridor 11						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 12						
			Corridor 13						
			Exterior						
M-FDI-14	M	Fire Door Insulation, Wood Cladding	Reception	Assumed	NF	G	1,050	SF	10/04/21
			Nurse's Restroom						
			Storage 1						
			North Foyer						
			Men's Restroom						
			Women's Restroom						
			Janitor						
			Library Workroom						
			Server Room						
			Speech						
			Special Ed. 3						
			Test Room						
			Special Ed. 2						
			Special Ed. 1						
			South Boy's Restroom						
			South Girl's Restroom Hall						
			Room 10						
			Room 11						
			Room 12						
			Room 13						
			Room 14						
			Room 15						
			Room 16						
			Room 17						
			Room 18						
			Room 19						
			Room 20						
			Room 21						
			Room 22						
			Room 23						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 24						
			Room 25						
			Room 26						
			Room 27						
			Room 28						
			Room 29						
			Room 30						
			Room 31						
			Music						
			Storage 6						
			Multi-Purpose						
			Kitchen Water Heater Closet						
			Storage 4						
			Storage 5						
			Kitchen						
			East Boy's Restroom						
			East Girl's Restroom						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			West Foyer						
			Corridor 7						
			Corridor 8						
			Corridor 9						
			Corridor 10						
			East Foyer						
			Corridor 11						
			Corridor 12						
M-GWT-16	M	Glazed Wall Tile, 6"X6", White, Smooth, Various	Corridor 14	Assumed	NF	G	70	SF	10/04/21
			Corridor 15						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 16						
M-GRT-17	M	Grout, Gray, Cementitious	Corridor 14	Assumed	NF	G	7	SF	10/04/21
			Corridor 15						
			Corridor 16						
M-SAC-29	M	Sink Acoustical Coating, White, Rough	North Foyer	Assumed	NF	G	56	SF	10/04/21
			Faculty Lounge						
			Library Workroom						
			Computer						
			Special Ed. 1						
			Special Ed. 2						
			Special Ed. 3						
			Room 12						
			Room 13						
			Room 14						
			Room 15						
			Room 16						
			Room 17						
			Room 18						
			Room 19						
			Room 20						
			Room 21						
			Room 22						
			Room 23						
			Room 24						
			Room 25						
			Room 26						
			Room 27						
			Room 28						
			Room 29						
			Room 30						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 31						
			Music						
M-ADH-36	M	Adhesive (FRP), Brown, Brittle	Janitor	Assumed	NF	G	150	SF	10/04/21
			Kitchen						
M-SLT-42	M	Sealant, Black, Tar-Like	Library	Assumed	NF	G	7	SF	10/04/21
			Corridor 5						
			Corridor 13						
			Corridor 15						
M-GWT-43	M	Glazed Wall Tile, 4"X4", Pink, Smooth, Black and White	South Vestibule	Assumed	NF	G	2,000	SF	10/04/21
			South Girl's Restroom						
			West Vestibule						
			West Girl's Restroom						
			East Girl's Restroom						
M-GRT-44	M	Grout, Gray, Cementitious	South Vestibule	Assumed	NF	G	200	SF	10/04/21
			South Girl's Restroom						
			West Vestibule						
			West Girl's Restroom						
			East Girl's Restroom						
M-CMT-45	M	Ceramic Mosaic Tile, 2"X2", Pink, Smooth	South Vestibule	Assumed	NF	G	550	SF	10/04/21
			South Girl's Restroom						
			Room 10 Toilet						
			Room 11 Toilet						
			West Vestibule						
			West Girl's Restroom						
			East Girl's Restroom						
M-GRT-46	M	Grout, Gray, Cementitious	South Vestibule	Assumed	NF	G	55	SF	10/04/21
			South Girl's Restroom						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 10 Toilet						
			Room 11 Toilet						
			West Vestibule						
			West Girl's Restroom						
			East Girl's Restroom						
M-GWT-47	M	Glazed Wall Tile, 4"X4", Blue, Smooth, Black and White	South Boy's Restroom	Assumed	NF	G	2,000	SF	10/04/21
			West Boy's Restroom						
			East Boy's Restroom						
M-GRT-48	M	Grout, Gray, Cementitious	South Boy's Restroom	Assumed	NF	G	200	SF	10/04/21
			West Boy's Restroom						
			East Boy's Restroom						
M-CMT-49	M	Ceramic Mosaic Tile, 2"X2", Blue, Smooth	South Boy's Restroom	Assumed	NF	G	550	SF	10/04/21
			West Boy's Restroom						
			East Boy's Restroom						
M-GRT-50	M	Grout, Gray, Cementitious	South Boy's Restroom	Assumed	NF	G	55	SF	10/04/21
			West Boy's Restroom						
			East Boy's Restroom						
M-VST-56	M	Vinyl Stair Tread, 10"X36", Gray, Vinyl-Like, Circle Pattern	North Wing	Assumed	NF	G	30	SF	10/04/21
M-MAS-57	M	Mastic, Yellow, Tacky	North Wing	Assumed	NF	G	30	SF	10/04/21
M-VCT-59	M	Vinyl Composition Tile, 24"X24", Gray, Vinyl-Like, Circle Pattern	Multi-Purpose	Assumed	NF	G	250	SF	10/04/21
M-MAS-60	M	Mastic, Yellow, Tacky	Multi-Purpose	Assumed	NF	G	250	SF	10/04/21
M-ACT-62	M	Acoustical Ceiling Panel, 2'x4', White, Chalky, Vinyl Cover	Kitchen	Assumed	NF	G	500	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-GWT-63	M	Glazed Wall Tile, 4"X6", Pink, Smooth	Room 10 Toilet	Assumed	NF	G	10	SF	10/04/21
			Room 11 Toilet						
M-GRT-64	M	Grout, Gray, Cementitious	Room 10 Toilet	Assumed	NF	G	1	SF	10/04/21
			Room 11 Toilet						
M-CON-65	M	Concrete, Gray, Cementitious	Reception	Assumed	NF	G	45,000	SF	10/04/21
			Treatment						
			Nurse's Office						
			Nurse's Restroom						
			Hearing						
			Storage 1						
			Hall 1						
			North Foyer						
			Principal Office						
			Principal's Closet						
			Counselor						
			Psy/Conf.						
			Faculty Work						
			Faculty Lounge						
			Men's Restroom						
			Women's Restroom						
			Storage 2						
			Unisex Restroom						
			Janitor						
			Elec. Closet						
			Library						
			Library Workroom						
			Computer						
			Server Room						
			Speech						
			Storage 3						
			Special Ed. 3						
			Test Room						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Special Ed. 2						
			Special Ed. 1						
			Timeout Room						
			South Boy's Restroom						
			South Vestibule						
			South Girl's Restroom						
			South Water Heater Closet						
			Exterior Electrical Closet						
			South Girl's Restroom Hall						
			Room 10						
			Room 10 Toilet						
			Room 11						
			Room 11 Toilet						
			Room 12						
			Room 13						
			Room 14						
			Room 15						
			West Boy's Restroom						
			West Vestibule						
			West Girl's Restroom						
			West Girl's Restroom Hall						
			West Water Heater Closet						
			Room 16						
			Room 17						
			Room 18						
			Room 19						
			Room 20						
			Room 21						
			Room 22						
			Room 23						
			Room 24						
			Room 25						
			Room 26						
			Room 27						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Room 28						
			Room 29						
			Room 30						
			Room 31						
			Music						
			Storage 6						
			Stage						
			North Wing						
			South Wing						
			Multi-Purpose						
			Kitchen Water Heater Closet						
			Storage 4						
			Storage 5						
			P.E. Office						
			Kitchen						
			East Boy's Restroom						
			East Girl's Restroom						
			Corridor 1						
			Corridor 2						
			Corridor 3						
			Corridor 4						
			Corridor 5						
			Corridor 6						
			West Foyer						
			Corridor 7						
			Corridor 8						
			Corridor 9						
			Corridor 10						
			East Foyer						
			Corridor 11						
			Corridor 12						
			Corridor 13						
			Corridor 14						
			Corridor 15						

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Corridor 16						
			Equipment Pad						
			Storage Building						
			Canopy						
M-CON-66	M	Concrete, Gray, Cementitious	Exterior	Assumed	NF	G	18,000	SF	10/04/21
M-STU-67	M	Stucco, Gray, Cementitious	Exterior	Assumed	NF	G	4,000	SF	10/04/21
			Roof						
M-EXJ-68	M	Expansion Joint, Red, Pliable	Library	Assumed	NF	G	100	SF	10/04/21
			Multi-Purpose						
			Corridor 8						
			Corridor 9						
			Corridor 14						
			Corridor 15						
			Corridor 16						
			Equipment Pad						
			Exterior						
			Roof						
M-EXJ-69	M	Expansion Joint, Brown, Fibrous	Exterior	Assumed	NF	G	500	SF	10/04/21
M-BUR-70	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	42,000	SF	10/04/21
M-MAS-71	M	Mastic (Penetrations and Flashings), Black, Brittle	Roof	Assumed	NF	G	100	SF	10/04/21
M-SLT-72	M	Sealant (Flashing), Gray, Pliable	Roof	Assumed	NF	G	25	SF	10/04/21
M-GAS-73	M	Gasket, 8", White, Paper-Like	Equipment Pad	Assumed	NF	G	5	SF	10/04/21
M-SLT-74	M	Sealant (Equipment), Black, Tar- Like	Equipment Pad	Assumed	NF	G	10	SF	10/04/21

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
M-BUR-75	M	Built-Up Roofing, Black, Asphaltic, White Coating	Canopy	Assumed	NF	G	200	SF	10/04/21
M-APR-76	M	Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Gray Mineral Cap	Storage Building	Assumed	NF	G	300	SF	10/04/21
M-VBF-77	M	Vapor Barrier Felt, Black, Asphaltic	Storage Building	Assumed	NF	G	300	SF	10/04/21
M-BUR-122	M	Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	6,000	SF	10/04/21
M-FDI-132	M	Fire Door Insulation, Metal/Wood Cladding	Classroom 6	Assumed	NF	G	294	SF	10/04/21
			Classroom 7						
			Classroom 8						
			Classroom 9						
			Storage 7						
			Corridor 18						
			Exterior						
M-BUR-222	M	Built-Up Roofing, Back, Asphaltic, Gray Mineral Cap	Roof	Assumed	NF	G	5,000	SF	10/04/21
M-FDI-232	M	Fire Door Insulation, Metal/Wood Cladding	North Boy's Restroom	Assumed	NF	G	252	SF	10/04/21
			North Girl's Restroom						
			Staff Restroom						
			Storage 5						
			Classroom 41						
			Classroom 42						
			Classroom 43						
			Classroom 44						
			Classroom 45						
			Classroom 46						
			Corridor 17						

3-Year Reinspection  
 Kyrene Traditional Academy (Former Kyrene del Sureno Elementary School), KSD  
 Main Building  
 FM Project 21-343

Date Form Completed: 10/04/2021

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
			Exterior						

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Main-Tbl.doc

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		<b>BUILDING HAS BEEN REMOVED FROM SITE.</b>							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Rest-Tbl.doc

**3-YEAR REINSPECTION TABLE**  
**IN-PLACE ASBESTOS-CONTAINING MATERIALS**

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		<b>BUILDING HAS BEEN REMOVED FROM SITE.</b>							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\50,51-Tbl.doc

**3-YEAR REINSPECTION TABLE**  
**IN-PLACE ASBESTOS-CONTAINING MATERIALS**

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		<b>BUILDING HAS BEEN REMOVED FROM SITE.</b>							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\52,53-Tbl.doc

### 3-YEAR REINSPECTION TABLE

#### IN-PLACE ASBESTOS-CONTAINING MATERIALS

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		<b>BUILDING HAS BEEN REMOVED FROM SITE.</b>							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\54,55-Tbl.doc

**3-YEAR REINSPECTION TABLE**  
**IN-PLACE ASBESTOS-CONTAINING MATERIALS**

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		<b>BUILDING HAS BEEN REMOVED FROM SITE.</b>							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\56,57-Tbl.doc

**3-YEAR REINSPECTION TABLE**  
**IN-PLACE ASBESTOS-CONTAINING MATERIALS**

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		<b>BUILDING HAS BEEN REMOVED FROM SITE.</b>							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\58,59-Tbl.doc

**3-YEAR REINSPECTION TABLE**  
**IN-PLACE ASBESTOS-CONTAINING MATERIALS**

MATERIAL SAMPLE CODE	MTL TYPE	MATERIAL DESCRIPTION	MATERIAL LOCATION	ANALYTICAL RESULTS	FRIABILITY	MATERIAL ASSESS. CLASS	MTL QUAN	UNITS	DATE LAST INSPECTED
	M/S/T			%/ASSUMED	NF/F	G/D/SD		LF/SF/EA	
		<b>BUILDING HAS BEEN REMOVED FROM SITE.</b>							

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\60,61-Tbl.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 43801250112345 Signature of Inspector: Carlyn Hall

\*Material Reinspected: M-ADH-07, Adhesive, Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☒ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☒ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\07.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 43861252125169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MRT-10, Mortar (Glass Block), Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 9/4/21 Person performing reinspection: Carlyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 123164 Signature of Inspector: Carlyn Hall

\*Material Reinspected: M-FDI-13, Fire Door Insulation, Metal Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\13.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3-YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 431012501123165 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-FDI-14, Fire Door Insulation, Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\14.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GWT-16, Glazed Wall Tile, 6"X6", White, Smooth, Various

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI (3) Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\16.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carby, Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4360250123169 Signature of Inspector: Carby Hall

\*Material Reinspected: M-GRT-17, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**  
Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\17.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4370 D50123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SAC-29, Sink Acoustical Coating, White, Rough

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**  
Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\29.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380 12001 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-ADH-36, Adhesive (FRP), Brown, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\36.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4302 12501 123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-42, Sealant, Black, Tar-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find       

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain:       

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain:       

**Assessment:**

Evidence of Physical Damage:        Yes / No  
Evidence of Water Damage:        Yes / No  
Evidence of Delamination or Other Damage:        Yes / No  
Explain:       

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection?        Yes / No  
Explain:       

Degree of Accessibility of the Material: High        Medium ✓ Low         
Degree of Activity Near the Material: High ✓ Medium        Low         
Location in an Air Plenum, Air Shaft, or Airstream:        Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed?        Yes / No  
Explain:       

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\42.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4301250123164 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-GWT-43, Glazed Wall Tile, 4"X4", Pink, Smooth, Black and White

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\43.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 43001200123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-44, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**  
Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\44.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/14/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 43801250103169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMT-45, Ceramic Mosaic Tile, 2"X2", Pink, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\45.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Heill  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 438012601123164 Signature of Inspector: Corbyn Heill

\*Material Reinspected: M-GRT-46, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**  
Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\46.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380 12601 12314 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-GWT-47, Glazed Wall Tile, 4"X4", Blue, Smooth, Black and White

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\47.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 43801250123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-48, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\48.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4370 12501 123169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CMT-49, Ceramic Mosaic Tile, 2"X2", Blue, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\49.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Conyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380125012364 Signature of Inspector: Conyn Hall

\*Material Reinspected: M-GRT-50, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\50.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4370128512369 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VST-56, Vinyl Stair Tread, 10"X36", Gray, Vinyl-Like, Circle Pattern

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\56.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380 125014304 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-57, Mastic, Yellow, Tacky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\57.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 43801261123169 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-VCT-59, Vinyl Composition Tile, 24"X24", Gray, Vinyl-Like, Circle Pattern

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\59.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380781123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-60, Mastic, Yellow, Tacky

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\60.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hull  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4310 12501 63104 Signature of Inspector: Carlyn Hull

\*Material Reinspected: M-ACT-62, Acoustical Ceiling Panel, 2'x4', White, Chalky, Vinyl Cover

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\62.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380128011236 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-GWT-63, Glazed Wall Tile, 4"X6", Pink, Smooth

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐  
Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\63.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 12314 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GRT-64, Grout, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\64.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380125012314 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-CON-65, Concrete, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**  
Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\65.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4570125016314 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-CON-66, Concrete, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No

Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ☒ Medium ☐ Low ☐

Degree of Activity Near the Material: High ☒ Medium ☐ Low ☐

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\66.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 43001250123164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-STU-67, Stucco, Gray, Cementitious

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\67.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380 1289 63169 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-EXJ-68, Expansion Joint, Red, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\68.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380 1251123164 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-EXJ-69, Expansion Joint, Brown, Fibrous

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\69.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 436012021123164 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-BUR-70, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\70.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 43012501123166 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-MAS-71, Mastic (Penetrations and Flashings), Black, Brittle

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\71.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 438, 1250, 123104 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-SLT-72, Sealant (Flashing), Gray, Pliable

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\72.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4386125012364 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-GAS-73, Gasket, 8", White, Paper-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc. 3

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\73.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4580 1250128164 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-SLT-74, Sealant (Equipment), Black, Tar-Like

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\74.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Cerbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380 12521 12814 Signature of Inspector: Cerbyn Hall

\*Material Reinspected: M-BUR-75, Built-Up Roofing, Black, Asphaltic, White Coating

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\75.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380 12501 03164 Signature of Inspector: Carbyn Hall

\*Material Reinspected: M-APR-76, Asphalt Prepared Roofing (Shingles), Black, Asphaltic, Gray Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI ③ Misc.

**Material Status:** 1. In-Place ☒ 2. Did Not Find ☐

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / ☒ No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Water Damage: \_\_\_\_\_ Yes / ☒ No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ☒  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / ☒ No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / ☒ No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\76.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380 1250 12314 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-VBF-77, Vapor Barrier Felt, Black, Asphaltic

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\77.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Carlyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 438012501 123109 Signature of Inspector: Carlyn Hall

\*Material Reinspected: M-BUR-122, Built-Up Roofing, Black, Asphaltic, Gray Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

#### Assessment:

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Degree of Activity Near the Material: High \_\_\_\_\_ Medium \_\_\_\_\_ Low ✓  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

#### Assessment Classification:

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\122.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 6/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4380 0001 02169 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-FDI-132, Fire Door Insulation, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3. Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\132.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/4/21 Person performing reinspection: Corbyn Hall  
Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 43801254128164 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-BUR-222, Built-Up Roofing, Back, Asphaltic, Gray Mineral Cap

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No  
Evidence of Water Damage: \_\_\_\_\_ Yes / No  
Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_  
Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_  
Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No  
Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\222.doc



15974 North 77<sup>th</sup> Street, Suite 100  
Scottsdale, AZ 85260

### 3 YEAR REINSPECTION OF ASBESTOS-CONTAINING BUILDING MATERIALS

Reinspection Date: 10/14/21 Person performing reinspection: Corbyn Hall

Facility: Kyrene del Sureno Elementary School Building Name/Number: Main

AHERA certification number: 4350 12021 0316 Signature of Inspector: Corbyn Hall

\*Material Reinspected: M-FDI-232, Fire Door Insulation, Metal/Wood Cladding

**Type of Asbestos-Containing Material:** 1. Surf. 2. TSI 3 Misc.

**Material Status:** 1. In-Place ✓ 2. Did Not Find \_\_\_\_\_

**Material Condition:** Has the condition of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Material Friability:** Has the friability of this material changed since the last inspection? Yes / No  
Explain: \_\_\_\_\_

**Assessment:**

Evidence of Physical Damage: \_\_\_\_\_ Yes / No

Evidence of Water Damage: \_\_\_\_\_ Yes / No

Evidence of Delamination or Other Damage: \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

**Potential for Disturbance:** Has the potential for disturbance of this material changed since the last inspection? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

Degree of Accessibility of the Material: High \_\_\_\_\_ Medium ✓ Low \_\_\_\_\_

Degree of Activity Near the Material: High ✓ Medium \_\_\_\_\_ Low \_\_\_\_\_

Location in an Air Plenum, Air Shaft, or Airstream: \_\_\_\_\_ Yes / No

**Assessment Classification:**

1. Damaged or significantly damaged thermal system insulation ACBM.
2. Damaged friable surfacing ACBM.
3. Significantly damaged friable surfacing ACBM.
4. Damaged or significantly damaged friable miscellaneous ACBM.
5. ACBM with potential for damage.
6. ACBM with potential for significant damage.
7. Any remaining friable ACBM or friable suspected ACBM.

**Recommended Action:** As a result of this reinspection, has the recommended response action for this material changed? \_\_\_\_\_ Yes / No

Explain: \_\_\_\_\_

\*Reference the original Management Plan for additional information.

G:\2021 Projects\10 ENV\KSD\21-343 3-Year Reinspection\2.0\2.3\2.3.1\KTA (Sureno)\Forms\Main\232.doc