



# ENVIRONMENTAL ASSISTANCE GROUP

179 NIBLICK ROAD #401 PASO ROBLES, CA 93446

PHONE: 805-286-4921 E-MAIL: [comply@haztrainer.com](mailto:comply@haztrainer.com)

## ASBESTOS HAZARD EMERGENCY RESPONSE ACT (AHERA) THREE-YEAR REINSPECTION REPORT – SPRING 2021

Conducted at:

CIRCLE VIEW ELEMENTARY SCHOOL  
6261 HOOKER DRIVE  
HUNTINGTON BEACH, CALIFORNIA 92647

Prepared for:

MS. KIM SLACK, DIRECTOR OF MAINTENANCE  
OCEAN VIEW SCHOOL DISTRICT  
8291 WARNER AVENUE  
HUNTINGTON BEACH, CA 92647

July 2021

Report generated/reviewed by:

Eldwin "Ed" Kennedy, CAC# 93-1249  
President  
Environmental Assistance Group

## TABLE OF CONTENTS

- I. EXECUTIVE SUMMARY
- II. SURVEY RESULTS REPORT
- III. DIAGRAM
- IV. INSPECTOR'S CERTIFICATION
- V. DISCLAIMER/REPORT LIMITATIONS

## I. EXECUTIVE SUMMARY

## I. EXECUTIVE SUMMARY

On June 30, 2021, Environmental Assistance Group (EAG), represented by Eldwin Kennedy Certified Asbestos Consultant (CAC), and Building Inspector Perry Robey, Certificate #26280, performed an asbestos three-year reinspection for asbestos-containing building materials (ACBMs) at Circle View Elementary School, located at 6261 Hooker Drive Huntington Beach, California 92647. The purpose of the Three- Year Reinspection was to assess the materials to comply with the U.S. Environmental Protection Agency (EPA) 40 CFR 763 Asbestos Hazard Emergency Response Act (AHERA) six-month surveillance and three-year reinspection requirement.

Prior to this three year reinspection, previous inspection reports were reviewed to determine which building materials had been previously tested and found to contain asbestos, which materials were determined not to be asbestos-containing, and whether any materials had not been tested for asbestos.

After the review of the previous building inspections, a complete visual walk-through inspection of the site was performed. The inspection revealed that conditions at Circle View Elementary School have changed since the last inspection in December 2020. Materials identified in the previous inspection provided by another consultant have been transposed to this report. Covered or hidden materials previously identified have not been verified as this would require destructive methods. Some materials identified in prior reports were only assumed and may be removed from this report after sampling. Materials previously identified as asbestos containing are as follows:

- Ceiling and wall tile mastic
- Acoustic ceiling spray
- Asbestos cement (transite) panels
- Pipe fitting insulation
- 9" x 9" vinyl floor tile and mastic
- Vinyl base mastic
- 12" x 12" grey vinyl floor tile and mastic
- Stucco

In addition, some material which had been previously assumed or was likely to be negative, was sampled and the results provided in this report. Materials which are identified by AHERA as non-asbestos containing materials (building materials not more than 1% asbestos containing) will not be assessed and will be moved to an Historical Data section in the next six-month surveillance report.

Remaining asbestos-containing materials located throughout the school were intact and in good condition at the time of the re-inspection unless noted otherwise. To ensure the materials' integrity and continued good condition, it is recommended that the materials be placed on the school's Operations and Maintenance (O&M) Program. Surveillance at six-month intervals is also recommended for all materials. Material descriptions and locations can be found in Section II (Survey Results Report), along with additional information for each material. If you have any questions, or if EAG can be of further assistance, please contact our office at 805-286-4921.

## II. SURVEY RESULTS REPORT

## II. SURVEY RESULTS REPORT GENERAL INFORMATION

Information in **RED** = Notes/Changes from the previous asbestos re-inspection report

ACM = Asbestos Containing Materials

ACBM = Asbestos Containing Building Materials

Assumed = The material looks like it is ACM but sample analyses determining asbestos content was not available.

NC = No Change since the last inspection

ND = No asbestos Detected

Suspect = ACM (like pipe insulation) could not be visually confirmed present. For example, the inspector believes it is likely to be inside of walls or ceiling spaces.

### **Type**

Misc = Miscellaneous building materials manufactured elsewhere and installed in or on the building

Surfacing = Material sprayed or trowelled onto interior or exterior building surfaces

TSI = Thermal System Insulation applied on pipes and ducts heating and/or cooling buildings

### **Friable**

Yes/No= Building materials that can be crumbled to powder by hand pressure when dry

### **Assessment :**

- (1) Damaged or significantly damaged thermal system insulation ACM.
- (2) Damaged friable surfacing ACM.
- (3) Significantly damaged friable surfacing ACM.
- (4) Damaged or significantly damaged friable miscellaneous ACM.
- (5) ACBM with potential for damage.
- (6) ACBM with potential for significant damage.
- (7) Any remaining friable ACBM or friable suspected ACBM.

**Response Action** = Recommendations for all ACM that was found during this inspection. The Response Actions indicate one of the following options.

<b>Response Action/ Priority Levels</b>	<b>Response</b>
1	Removal
2	Repair
3	Enclosure
4	Encapsulation
5	Operations and Maintenance (O&M) Program
6	Periodic Surveillance
7	Removed –No Action Necessary

Circle View Elementary School  
6261 Hooker Drive Huntington Beach, CA 92647  
AHERA Three-Year Reinspection – June 30, 2021

Bldg.	Location	Material	Approx. Quantity	Type	Friable	Sample Number	Lab Results % Asbestos	Assessment	Response Action	Notes
Bldg. 100 Rooms 1-5	Attic	Pipe elbows and fittings	Through-out	TSI	Yes			5	5/6	Assumed present. No access. <b>NC</b>
Bldg. 100 Rooms 1-5	Throughout under carpet	9x9 floor tile, various colors/ black mastic	4,000 sf	Misc.	No			5	5/6	Suspect under carpet and/or 12x12 tile. <b>NC</b>
Bldg. 100 Rooms 1-5	Throughout under windows	Asbestos cement (transite) panel	30 ea.	Misc.	No			4	5/6	Some scratches noted on the surface (below coat hangers) outside classrooms 1,3 & 5. <b>NC</b>
Bldg. 100 Rooms 1-5	Throughout	Brown ceiling & wall tile mastic	Through-out	Misc.	No	OVS421CV-1	ND			<b>NC</b> Will move to historical data
Bldg. 200 Rooms 6-8, K-1, K-2	Attic	Pipe elbows and fittings	~25 ea.	TSI	Yes			5	5/6	Not accessed <b>NC</b>
Bldg. 200 Rooms 6-8, K-1, K-2	Throughout under carpet	9x9 floor tile, various colors/ black mastic	4,000 sf.	Misc.	No			5	5/6	Suspect under carpet and/or floor tile. Room 6 damage at threshold. <b>Repaired</b>
Bldg. 200 Rooms 6-8, K-1, K-2	Classroom 7	9x9 floor tile	60 sf.	Misc.	No			4	5/6	<b>Minor damage</b>
Bldg. 200 Rooms 6-8, K-1, K-2	Throughout under windows	Asbestos cement (transite) panel	36 ea.	Misc.	No			4	5/6	Repairs to minor damages were observed under coat hooks outside classroom 8. (Metal) One rusted panel. Hole in panel o/s room 6. Hazard noted. Room 7-Screw points from soap dispenser attachment protruding through panel. <b>NC</b>
Bldg. 300 Rooms 9-13	Attic	Pipe elbows and fittings	~25 ea.	TSI	Yes			5	5/6	None observed <b>NC</b>
Bldg. 300 Rooms 9-13	Throughout under carpet	9x9 floor tile, various colors/ black mastic	4,000 sf.	Misc.	No			5	5/6	<b>NC</b>
Bldg. 300 Rooms 9-13	Throughout under windows	Asbestos cement (transite) panel	30 ea.	Misc.	No			5	5/6	<b>NC</b>
Bldg. 400	West Restrooms Attic	Pipe elbows and fittings	Through-out	TSI	Yes			5	5/6	None observed. (Check 12x12 in custodian office and storage) <b>NC</b>

Circle View Elementary School  
6261 Hooker Drive Huntington Beach, CA 92647  
AHERA Three-Year Reinspection – June 30, 2021

Bldg.	Location	Material	Approx. Quantity	Type	Friable	Sample Number	Lab Results % Asbestos	Assessment	Response Action	Notes
Bldg. 500 MPR	Communication Room in Auditorium	9x9 dark tan floor tile/black mastic	150 sf.	Misc.	No			5	5/6	NC
Bldg. 500 MPR	Storage, Speech, Faculty Lounge	Black floor mastic under tile or carpet	1500 sf.	Misc.	No			5	5/6	NC Minor spalling lounge. Minor damage at NE lounge threshold.
Bldg. 500 MPR	Exterior overhang	Exterior stucco	200 sf.	Surf.	No	OVS421CV-2	Trace Chrysotile			Stucco overhang is on north and south side of building. NC Will move to historical data
Bldg. 500 MPR	Exterior stucco wall	Yellow/gray baseboard mastic	400 sf.	Misc.	No			5	5/6	NC Sample
Bldg. 600 Admin.	Exterior office under window	A/C panels	2 ea.	Misc.	No			5	5/6	Metal NC
Bldg. 600 Admin.	Heater closet	9x9 tan floor tile	40 sf.	Misc.	No			5	5/6	NC
Bldg. 600 Admin.	Throughout	Black floor mastic	Through-out	Misc.	No			5	5/6	Suspect NC
Bldg. 600 Admin.	Throughout	Ceiling tile mastic	Through-out	Misc.	No	OVS421CV-5	ND			NC Will move to historical data
Bldg. 700 East Restrooms	Attic	Pipe elbows and fittings	Through-out	TSI	Yes			5	5/6	Suspect in ceiling and wall cavities. NC
Bldg. 700 Rooms 14-19	Attic	Pipe elbow and fittings	25 ea.	TSI	Yes			5	5/6	NC
Bldg. 700 Rooms 14-19	Throughout under carpet	9x9 floor tile, various colors/black mastic	4,000 sf.	Misc.	No			5	5/6	NC
Bldg. 700 Rooms 14-19	Throughout under windows	Asbestos cement (transite) panel	30 ea.	Misc.	No			4	5/6	Metal - Damage under hooks in Rm. 18
Bldg. 700 Rooms 14-19	Throughout	Ceiling tile mastic	Through-out	Misc.	No	OVS421CV-6	ND			NC Will move to historical data




Circle View Elementary School  
 6261 Hooker Drive Huntington Beach, CA 92647  
 AHERA Three-Year Reinspection – June 30, 2021

<i>Bldg.</i>	<i>Location</i>	<i>Material</i>	<i>Approx. Quantity</i>	<i>Type</i>	<i>Friable</i>	<i>Sample Number</i>	<i>Lab Results % Asbestos</i>	<i>Assessment</i>	<i>Response Action</i>	<i>Notes</i>
Bldg. 900 Rooms 20-25	Throughout under carpet	9x9 floor tile, various colors, and mastic	3,500 sf.	Misc.	No			5	5/6	Suspect NC
Bldg. 900 Rooms 20-25	Science storage inside Rm. 23	12x12 beige tile/mastic	200 sf.	Misc.	No	OVS421CV-7	2% Chrysotile	5	5/6	NC
Bldg. 900 Rooms 20-25	Throughout under windows	A/C panel (painted)	24 ea.	Misc.	No			4	5/6	Scratches observed outside Rms. 20, 24 & 25 Metal NC
Bldg. 900 Rooms 20-25	Rooms 22 & 23 rear areas	Acoustic ceiling spray	800 sf.	Surf.	No	OVS421CV- 8,9,10	Trace Chrysotile			NC Will move to historical data
Bldg. 900 Rooms 20-25	Outside Rms. 23 & 24	Exterior stucco	650 sf.	Surf.	No	OVS421CV- 3,4	Trace Chrysotile			Damaged outside 23. NC Will move to historical data

### III. DIAGRAM

Figure 1




# Campus Site Map

Ocean View School District  
Circle View Elementary School  
6261 Hooker Drive  
Huntington Beach, CA 92647



Figure 2




# Campus Site Map (West Side)

Ocean View School District  
Circle View Elementary School  
6281 Hooker Drive  
Huntington Beach, CA 92647



Figure 3



Legend  
RR = Restroom  
H = Heater Closet




# Campus Site Map (East Side)

Ocean View School District  
Circle View Elementary School  
6261 Hooker Drive  
Huntington Beach, CA 92647



#### IV. INSPECTOR'S CERTIFICATION

#### IV. INSPECTOR'S CERTIFICATION



## V. DISCLAIMER/REPORT LIMITATIONS



## **V. DISCLAIMER/REPORT LIMITATIONS**

All reports and recommendations are based on conditions and practices observed and information made available to Environmental Assistance Group (EAG) by the client and the designated sites/facilities on the days the inspection was completed. This report does not purport to set forth all hazards, or to indicate that other hazards do not exist. No responsibility is assumed by EAG for the control or correction of conditions or practices existing at the facilities, or at any other premises surveyed by EAG, for and on the behalf of the client. Services provided by EAG shall be governed by the standard of practice for professional services measured at the time those services are rendered.

All information contained in this report is proprietary and limited to the scope of services, parameters of the analytical methods used, and the conditions present at the time of this inspection. Any references to quantities are considered estimates and are not to be construed as actual.

The provided survey was not destructive. Prior to any demolition or renovation, a comprehensive (possibly destructive) "Renovation Survey" is highly recommended.