

Three-Year Asbestos Hazard Emergency Response Act Re-Inspection & Asbestos Management Plan Update

for
Barnstable Community Innovation School
165 Beares Way
Hyannis, Massachusetts

For Compliance with
Commonwealth of Massachusetts Department of Labor Standards (MADLS)
Asbestos Containing Materials in Schools Regulation (453 CMR 6.00)
and
EPA Asbestos Hazard Emergency Response Act
(Title 40 CFR, Part 763, Subpart E)

Barnstable Public Schools
Barnstable, Massachusetts

August 2020



Fuss & O'Neill, Inc.
108 Myrtle Street, Suite 502
Quincy, MA 02171



November 13, 2020

Mr. David Kanyock
Director of Facilities
Barnstable Public Schools
835 Falmouth Road
Barnstable, MA 02601

**RE: Three-Year AHERA Re-Inspection & Asbestos Management Plan Update
Barnstable Community Innovation School
165 Bearses Way, Hyannis, MA**
Fuss & O'Neill Reference No. 20150090.C90

Dear Mr. Kanyock:

Enclosed is the Three-Year AHERA Re-Inspection and Asbestos Management Plan Update report prepared by Fuss & O'Neill, Inc. for the Barnstable Community Innovation School located at 165 Bearses Way in Hyannis, Massachusetts (the "Site"). AHERA services were performed for Barnstable Public Schools (the "Client").

This report is an important document that must be kept on file at the school as well as at a central location where the Asbestos Management Plans are maintained.

If you should have any questions regarding this report, please do not hesitate to contact me. Thank you for this opportunity to have served your environmental needs.

Sincerely,

Dustin A. Diedricksen
Associate / Department Manager

DD/rs

Enclosure

108 Myrtle Street
Suite 502
Quincy, MA
02171
t 617.282.4675
800.286.2469
f 617.481.5885

www.fando.com

California
Connecticut
Maine
Massachusetts
New Hampshire
Rhode Island
Vermont

\\private\DFS\ProjectData\P2015\0090\C90\Deliverables\AMPs\Innovation School\DD_RCM_Innovation
School_AMP_20201113.docx

Table of Contents

Three-Year Asbestos Hazard Emergency Response Act Re-Inspection & Asbestos Management Plan Update Barnstable Community Innovation School

| | | |
|----------|---|-----------|
| 1 | Introduction | 1 |
| 1.1 | Background | 1 |
| 1.2 | Local Education Agency (LEA) Responsibilities | 1 |
| 1.3 | Key Personnel..... | 2 |
| 2 | Building Description | 3 |
| 3 | Three Year Re-Inspection..... | 3 |
| 3.1 | Re-Inspection Procedures | 3 |
| 4 | Re-Inspection Report..... | 4 |
| 4.1 | Review of Existing Records | 4 |
| 4.2 | Re-Inspection Summary..... | 4 |
| 4.3 | Newly Identified or Re-sampled ACBM Materials | 7 |
| 4.4 | Physical Assessment of ACBM | 7 |
| 5 | Management Plan Update | 8 |
| 5.1 | Recommended Response Actions..... | 8 |
| 5.2 | Periodic Surveillance | 9 |
| 5.3 | Preventive Measures..... | 9 |
| 5.4 | Abatement (Removal) Cost Estimates | 10 |
| 6 | EPA Accreditation Requirements | 11 |

Appendices

End of Report

| | |
|------------|---|
| APPENDIX A | EXISTING RECORDS CHECKLIST |
| APPENDIX B | RE-INSPECTION FORM 1 |
| APPENDIX C | RE-INSPECTION FORM 2 |
| APPENDIX D | PREVIOUSLY SAMPLED MATERIALS LABORATORY REPORTS |
| APPENDIX E | NEWLY INSTALLED MATERIALS SAFETY DATA SHEETS |
| APPENDIX F | SAMPLE 6-MONTH PERIODIC SURVEILLANCE FORM |
| APPENDIX G | PREVENTIVE MEASURES |
| APPENDIX H | FUSS & O'NEILL ASBESTOS ACCREDITATIONS & CERTIFICATIONS |

1 Introduction

1.1 Background

The Clean Air Act required the United States Environmental Protection Agency (EPA) to develop standards to address the potential health risks associated with adverse effects of asbestos exposure as an indoor contaminant. In October 1986, the EPA promulgated the Asbestos Hazard Emergency Response Act (AHERA) located at Title 40 CFR, Part 763, Subpart E.

The AHERA regulations require that local education agencies (LEAs) conduct inspections of each school building that they lease, own, or otherwise use as a school building to identify friable (easily crumbled or crushed to powder by hand pressure) and non-friable asbestos-containing building materials (ACBM) locations. The original inspections were required to have been completed prior to October 12, 1988.

AHERA also requires that buildings leased or acquired on or after October 12, 1988 that are to be used as a school building, shall be inspected for friable and non-friable ACBM prior to use as a school building. In the event of an emergency use of a building that has not been inspected for ACBM, the building shall be inspected within 30 days after commencement of such use.

The regulatory requirements remain in effect for a private or public school system, a church-affiliated school of any denomination, a school dedicated to the education of children with special needs, or a charter school. In the Commonwealth of Massachusetts, the Department of Labor Standards (MADLS) is responsible for AHERA regulation enforcement.

1.2 Local Education Agency (LEA) Responsibilities

The LEA is responsible for compliance with the AHERA regulation. The following responsibilities must be followed:

1. The LEA must designate a person to ensure that all AHERA requirements are properly implemented. The LEA's Designated Person must receive adequate training to perform their duties.
2. The LEA must ensure that the Asbestos Management Plan(s) (AMP) are maintained in a central location and at each facility. AMP and pertinent documentation shall be available for inspection or review at all times.
3. The LEA must inform all workers, building occupants, and legal representatives (as appropriate) in writing at least once per school year about asbestos-related activities and the availability of the AMP for each school building.

4. The LEA must ensure proper accreditation for all persons who perform asbestos inspections, asbestos re-inspections, AMP development/updates, Asbestos Work Plan (AWP) development, and response actions that may disturb asbestos; this includes operations and maintenance (O&M) activities.
5. The LEA must provide training for all custodial and maintenance staff who regularly perform building maintenance where ACBM are present. The training must be provided upon initial hire, and refresher training must be completed annually.
6. The LEA must provide information (disclosure) to any workers who may perform work and may come into contact with asbestos in school buildings where ACBM or presumed ACBM are present.
7. The LEA must ensure that known ACBM or presumed ACBM are provided with warning labels in routine maintenance areas.
8. The LEA must ensure that periodic surveillance is performed at least once every six months, after AMP implementation, in all school buildings that it leases, owns, or otherwise uses that contains ACBM or presumed ACBM.
9. The LEA must ensure that once every three years, after an AMP is implemented, a re-inspection is performed at each school building that it leases owns or otherwise uses that contains ACBM or presumed ACBM.

Refer to above-mentioned regulation for full requirements and responsibilities.

1.3 Key Personnel

A. Local Education Agency (LEA):

LEA: Barnstable Public Schools
Address: 230 South Street
Hyannis, MA 02601
Phone: (508) 862-4953

B. Designated Person:

Designated Person: Mr. Michael Lambros
Address: Deputy Director of Facilities
835 Falmouth Road
Barnstable, Massachusetts 02601
Phone: (508) 790-6490

C. Asbestos Consultant:

Firm: Fuss & O'Neill, Inc.
Address: 108 Myrtle Street, Suite 502
Quincy, MA 02171
Phone: (617) 282-4675

D. Asbestos Inspector:

Inspector: Robert Mallett
MADLS Certification Number: AI900557
Expiration Date: 06/01/2021

E. Asbestos Management Planner:

Planner: Dustin Diedricksen
MADLS Certification Number: AP900425
Expiration Date: 04/05/2021

2 Building Description

The Barnstable Community Innovation School is a two-story, concrete, brick, steel, and wood structure that was reportedly constructed in the 1950s.

3 Three Year Re-Inspection

3.1 Re-Inspection Procedures

This three-year AHERA re-inspection was conducted in accordance with EPA requirements of the AHERA regulation, Title 40 CFR, Part 763, Section 763.85 (b).

On August 26, 2020, Fuss & O'Neill, Inc. (Fuss & O'Neill) representative, Mr. Robert Mallett, performed the re-inspection.

During the re-inspection, Fuss & O'Neill conducted the following required tasks:

1. A visual re-inspection and reassessment of all known friable or Assumed ACBM.
2. A visual re-inspection of ACBM that was previously considered non-friable to determine if the present condition of the material has become friable.
3. Identification and assessment of any newly identified homogeneous area that contains friable ACBM since the last inspection or re-inspection.

4 Re-Inspection Report

4.1 Review of Existing Records

An important part of this AHERA re-inspection involved researching prior documentation, which is required to be present at the school as well as at the central recordkeeping location where AMP and pertinent documentation are stored.

Refer to *Appendix A* for the existing records checklist.

4.2 Re-Inspection Summary

The on-site portion of the re-inspection was documented on forms modeled after examples provided by the EPA and reviewed with the MADLS. The first form, **Re-Inspection Form 1**, identifies previous inspection data gathered during the initial AHERA inspection and subsequent re-inspection (refer to *Appendix B*). This form is useful to reference response actions (if any), which have been performed since the last inspection, as well as identifies the last known conditions of ACBM in the building. It additionally provides the inspector a “quick glance” reference when performing the re-inspection.

The second EPA form, **Re-Inspection Form 2**, is used to provide information and justification regarding re-assessment of the ACBM (refer to *Appendix C*). This form also provides response action recommendations, including a tentative schedule for completing response actions that recommend removal or repair.

Previous bulk sampling results can be found in Table 1 and Table 2. Refer to *Appendix D* for previously sampled materials laboratory reports.

Using EPA protocol and criteria, the following materials existing in the Barnstable Community Innovation School at the time of this three-year re-inspection have been determined and/or assumed to be **ACBM**. Please refer to the above-mentioned re-inspection forms for specific ACBM locations.

Table 1
Asbestos-Containing Building Materials (ACBM)
(Previous & Current Re-Inspections)

| Material | Location | Reference | Asbestos Content |
|---|--------------------------------|--|-------------------------|
| Gray Mudded Pipe-Fitting Insulation | Concealed within Pipe Chases | 2014 Initial AMP | Assumed ACBM |
| White/Gray Pipe Insulation | Concealed within Pipe Chases | 2014 Initial AMP | Assumed ACBM |
| 9" x 9" Brown Streaked Floor Tile | Rear Stairwells from Gymnasium | 2014 Initial AMP | Assumed ACBM |
| Black Mastic Associated with 9" x 9" Brown Streaked Floor Tile | Rear Stairwells from Gymnasium | 2014 Initial AMP | Assumed ACBM |
| 12" x 12" Brown/White Mottled Pattern Floor Tile | Classroom 2 | 2014 Initial AMP (Sample ID: 7-12-PB-32A) | 3% Chrysotile |
| Black Mastic Associated with 12" x 12" Brown/White Mottled Pattern Floor Tile | Classroom 2 | 2014 Initial AMP (Sample ID: 7-12-PB-33A) | 4% Chrysotile |

Using the EPA protocol, samples of the following suspect materials were collected and analyzed. The analytical results indicated that these materials are **non-ACBM**:

Table 2
Non-Asbestos-Containing Building Materials
(Previous & Current Re-Inspections)

| Material | Location | Reference |
|---|--|--|
| Brown Glue Daubs Associated with 12" x 12" Ceiling Tile | Main Offices, Cafeteria, Corridors, Classrooms, & Gymnasium | 2014 Initial AMP (Sample ID: 7-12-PB-18A-B) |
| White Skim Coat Ceiling Plaster | Main Offices, Art Storage, Gymnasium Office, Library, Cafeteria, Restrooms, Hallways, & Classrooms | 2014 Initial AMP & 2017 AMP Update (Sample ID: 7-12-PB-19A-C); (Sample ID: 7-19-PB-01A-C) |
| Gray Rough Coat Ceiling Plaster | Main Offices, Art Storage, Gymnasium Office, Library, Cafeteria, Restrooms, Hallways, & Classrooms | 2014 Initial AMP & 2017 AMP Update (Sample ID: 7-12-PB-20A-C); (Sample ID: 7-19-PB-02A-C) |
| White Skim Coat Wall Plaster | Main Office & Health Office | 2014 Initial AMP (Sample ID: 7-12-PB-21A-C) |

| Material | Location | Reference |
|--|--|---|
| Gray Rough Coat Wall Plaster | Main Office & Health Office | 2014 Initial AMP (Sample ID: 7-12-PB-22A-C) |
| 12" x 12" Tan Mottled Floor Tile | Main Office, Health Office, Classrooms, Hallways, Cafeteria, Library, & Teachers' Room | 2014 Initial AMP (Sample ID: 7-12-PB-23A-B) |
| Gray Mastic Associated with 12" x 12" Tan Mottled Floor Tile | Main Office, Health Office, Classrooms, Hallways, Cafeteria, Library, & Teachers' Room | 2014 Initial AMP (Sample ID: 7-12-PB-24A-C) |
| Gray Floor Leveling Compound | Main Office, Health Office, Classrooms, Hallways, Cafeteria, Library, & Teachers' Room | 2014 Initial AMP (Sample ID: 7-12-PB-25A-B) |
| Yellow Carpet Glue | Office By Exit Stairs/Central Foyer | 2014 Initial AMP (Sample ID: 7-12-PB-26A-B) |
| Gray Mud-Set Associated with Ceramic Floor Tile (No Grout) | Restrooms, Kitchen, & Gym Teacher's Office | 2014 Initial AMP & 2017 AMP Update (Sample ID: 7-12-PB-27A-B); (Sample ID: 7-19-PB-04A -B) |
| Brown Grout Associated with 1" x 1" Ceramic Floor Tile | Bathroom Off of Gymnasium Hallway | 2017 AMP Update (Sample ID: 7-19-PB-03A-B) |
| White Sheetrock (Gypsum Wallboard) | Cafeteria & Library | 2014 Initial AMP (Sample ID: 7-12-PB-28A-B) |
| White Joint Compound | Cafeteria & Library | 2014 Initial AMP (Sample ID: 7-12-PB-29A-C) |
| Yellow Base Cove Glue | Classrooms, Offices, Library, & Cafeteria | 2014 Initial AMP (Sample ID: 7-12-PB-30A-B) |
| Black Composite Window Sill | Classrooms, Restrooms, Cafeteria, & Gymnasium | 2014 Initial AMP (Sample ID: 7-12-PB-31A-B) |
| Gray Duct Caulking | Attic | 2014 Initial AMP (Sample ID: 7-12-PB-34A-B) |
| 1' x 1' Brown Cellulose Pore Ceiling Tile | Gymnasium & Main Hallway | 2017 AMP Update (Sample ID: 7-19-PB-05A-B) |
| Brown Glue Daubs Associated with 1' x 1' Brown Cellulose Pore Ceiling Tile | Gymnasium & Main Hallway | 2017 AMP Update (Sample ID: 7-19-PB-06A-B) |
| 2' x 2' Gray Ceiling Tile | Lobby & Hallway to Gymnasium | 2017 AMP Update (Sample ID: 7-19-PB-07A-B) |
| 2' x 4' Gray Ceiling Tile | Lobby & Hallway to Gymnasium | 2017 AMP Update (Sample ID: 7-19-PB-08A-B) |

Mr. Dustin Diedricksen reviewed the information obtained during this re-inspection. Mr. Diedricksen is an EPA-accredited and MADLS-certified Asbestos Management Planner.

4.3 Newly Identified or Re-sampled ACBM Materials

No newly identified suspect ACBM were identified in the building during this re-inspection.

AHERA regulations pertain to interior identified or Assumed ACBM and limited exterior ACBM. AHERA regulations do include ACBM located on exterior porticos, covered walkways, and mechanical equipment used to condition interior building air.

Any suspect ACBM encountered during renovation/demolition/maintenance activities that is not specifically identified in the AMP as a non-ACBM should be assumed to contain asbestos unless sample results indicate otherwise.

Safety Data Sheets (SDS) should be obtained and kept with the AHERA documentation for any newly installed materials in order to meet AHERA requirements. These SDS must demonstrate that asbestos-containing materials (ACM) were not installed in the building. We recommend that SDS for newly installed materials be inserted into *Appendix E*.

4.4 Physical Assessment of ACBM

During inspection, suspect ACBM were separated into three EPA categories: Thermal System Insulation (TSI), Surfacing ACBM, and Miscellaneous ACBM. TSI includes all materials used to prevent heat loss/ gain or water condensation on mechanical systems. Examples of TSI are pipe and fitting insulations, boiler insulation, and duct insulation. Surfacing ACBM is commonly used for fireproofing, decorative, and acoustical applications. Miscellaneous ACBM include all ACBM not listed in TSI or surfacing, such as sheet flooring, vinyl asbestos flooring, ceiling tiles, and construction mastics/adhesives.

Finally, ACBM were quantified in linear feet or square feet, depending on the nature of the material.

The ACBM identified during the inspection (and still remaining in the school) were re-assessed using the MADLS and AHERA guidelines for assessment of ACBM. The following assessment categories are listed:

- 1 Damaged or significantly damaged TSI ACM
- 2 Damaged friable surfacing ACM
- 3 Significantly damaged friable surfacing ACM
- 4 Damaged or significantly damaged friable miscellaneous ACM
- 5 ACBM with potential for damage
- 6 ACBM with potential for significant damage

- 7 Any remaining friable ACBM or friable suspected ACBM

Material locations, assessments, and recommended response actions are listed in the re-inspection forms.

5 Management Plan Update

5.1 Recommended Response Actions

Based on the inspection report, the physical walk-through inspection, and the existing ACBM conditions, the following response actions are recommended:

1. Removal – Not Applicable
2. Repair - Not Applicable
3. Enclosure – Not Applicable
4. Encapsulation – Not Applicable
5. Operations and Maintenance (O & M) - All remaining ACBM

A successful O & M Program includes the following elements:

- A. Cleaning: All areas of the school where friable ACBM or assumed friable ACBM are present should be cleaned at least once after completion of this re-inspection. Additional cleaning may be necessary if the Asbestos Management Planner makes a written recommendation indicating the methods and frequency of such cleaning.
- B. O & M Activities: The LEA shall ensure that the procedures described below are followed to protect building occupants from O & M activities that may disturb known or Assumed ACBM:
 1. Restrict entry into the area either by physically isolating or by scheduling.
 2. Post asbestos warning signs to prevent entry by unauthorized persons.
 3. Deactivate or temporarily shut off or divert the air-handling system to the area.
 4. Use proper work practices and engineering controls, such as wet methods, protective clothing, High Efficiency Particulate Air (HEPA) vacuums, mini-enclosures/glove bags, etc. to inhibit fiber migration.
 5. Place asbestos debris and other contaminated materials into a sealed, leak-tight container for disposal.
- C. Minor Fiber Release Episode: The LEA shall ensure that the procedures described below are followed in the event of a minor fiber release episode (i.e., disturbance of less than or equal to 3 linear/square feet of friable ACBM):

1. Saturate the debris using wet methods.
 2. Place the debris in a sealed, leak-tight container and clean the area.
 3. Repair the area of damaged ACBM with materials such as asbestos-free spackling, plaster or insulation or seal with an encapsulant.
- D. Major Fiber Release Episode: The LEA shall ensure that the procedures described below are followed in the event of a major fiber release episode (i.e., disturbance of greater than 3 linear/square feet of friable ACBM):
1. Restrict entry into the area and post asbestos warning signs.
 2. Deactivate or temporarily shut off or divert the air handling system from the area to prevent fiber migration.
 3. The response action for any major fiber release episode must be prepared by EPA-accredited Asbestos Project Designers and conducted by EPA-accredited personnel.
 4. The LEA shall notify the MADLS of any major fiber release episode within twenty-four hours of its occurrence and, if necessary, provide written notification as required by applicable federal and/or state regulations.

5.2 Periodic Surveillance

At least once every six months after an AMP is implemented, the LEA will conduct periodic surveillance in the school that contains ACBM or Assumed ACBM. The person conducting periodic surveillance will visually inspect all areas in the school where ACBM have been identified in the AMP, and record the date of surveillance, their name, and any changes in the ACBM condition; this information shall then be submitted to the LEA's Designated Person for inclusion in the AMP.

Refer to *Appendix F* for the Sample 6-Month Periodic Surveillance Form that may be used for conducting periodic surveillance.

5.3 Preventive Measures

The LEA shall institute appropriate preventive measures to eliminate the reasonable likelihood that ACBM will become damaged, deteriorated, and/or delaminated.

Refer to *Appendix G* for preventive measures designed for various types of ACBM that may exist in the school.

5.4 Abatement (Removal) Cost Estimates

Costs for abatement (removal) of all ACBM in the building are as follows:

**Table 3
Abatement Cost Estimates**

| Material | Location | Estimated Quantity | Estimated Contractor Cost |
|---|--------------------------------|---------------------------|----------------------------------|
| Gray Mudded Pipe-Fitting Insulation | Concealed within Pipe Chases | Unknown | \$25-\$30/LF |
| White/Gray Pipe Insulation | | | |
| 9" x 9" Brown Streaked Floor Tile & Associated Mastic | Rear Stairwells from Gymnasium | 100 SF | \$1,500 |
| 12" x 12" Brown/White Mottled Pattern Floor Tiles & Associated Mastic | Classroom 2 | 1,000 SF | \$5,000 |

SF=Square Feet

Asbestos training costs for custodial and maintenance workers (under O&M Program) are as follows:

**Table 4
Asbestos Training Cost Estimates**

| Training Course | Estimated Cost |
|--|-----------------------|
| Two-Hour Asbestos Awareness Training (Annual) | \$75/Person/Year |
| Asbestos Coordinator/LEA Designated Person Initial Training | \$250/Person |
| Asbestos Coordinator/LEA Designated Person Annual Refresher Training | \$200/Person/Year |
| Asbestos Operations & Maintenance Initial Training | \$300/Person |
| Asbestos Operations & Maintenance Annual Refresher Training | \$150/Person/Year |
| Three-Year Re-Inspections & AMP Updates | \$3,000 - 3,500 |

6 EPA Accreditation Requirements

EPA accreditations and MADLS Asbestos Inspector and Asbestos Management Planner certifications for Mr. Mallett and Mr. Diedricksen are provided in *Appendix H*.

Report prepared by Environmental Analyst, Robert Mallett.

Reviewed by:



Dustin A. Diedricksen
Associate / Department Manager

Appendix A

Existing Records Checklist

Existing Records Checklist

Local Education Agency (LEA): Barnstable Public Schools
835 Falmouth Road
Barnstable, MA 02601

School Building: Barnstable Community Innovation School

The following documentation is required to be present at both the LEA's office and at a centralized location in the school administrative office. The information included in this checklist will be verified to be present and complete as part of three-year re-inspection.

| DOCUMENTATION | | LOCATION | |
|---------------|--|----------|--------------|
| | | School | LEA Office |
| 1 | Original AHERA Operations and Maintenance Plan/Inspection Report | Yes | Yes |
| 2 | Three Year Re-Inspection (First and All Subsequent Inspections) | Yes | 2014 2017 |
| 3 | Parents and Teachers Notifications (Annually Since Last Re-Inspection) | Yes | Yes |
| 4 | Designated Person Identification and Proper Training | Yes | Yes |
| 5 | Designated Person Periodic Surveillance (Once Every Six Months) | Yes | Yes |
| 6 | Maintenance Staff Awareness Training Records | Yes | Yes |
| 7 | Outside Vendor Awareness Notification | Yes | Yes |
| 8 | Asbestos Warning Signs and Labels (Required Posting in Boiler Rooms and Mechanical Spaces Only) | Yes | N/A |
| 9 | Response Action Records (Includes Any Abatement Conducted Since Last 3-Year Re-Inspection) | N/A | N/A |

Comments: Items marked “**No**” indicate not present/available at the time of this inspection.

Inspector (LEA Office): Robert Mallett

Date: August 26, 2020

Inspector (School): Robert Mallett

Date: August 26, 2020

Appendix B

Re-Inspection Form 1

School: Barnstable Community Innovation School
 Address: 165 Bearses Way, Hyannis, MA

Date(s) of Original Inspection: 2014
 Date(s) of Subsequent Re-Inspections: 2017, 2020

| Homogeneous Material | | | Material Category | Friability | Assessment Category (1-7) | Recorded Locations | Response Actions Taken/Renovations/Other Comments |
|----------------------|------------------|---|-------------------|------------|---------------------------|------------------------------|---|
| Sample Number | Asbestos Content | Material Description | | | | | |
| Assumed ACBM | Assumed ACBM | Gray Mudded Pipe-Fitting Insulation | TSI | F | 5 | Concealed within Pipe Chases | |
| Assumed ACBM | Assumed ACBM | White/Gray Pipe Insulation | TSI | F | 5 | Concealed within Pipe Chases | |
| Assumed ACBM | Assumed ACBM | 9" x 9" Brown Streaked Floor Tile | Misc. | NF | 5 | Rear Stairwells from Gym | |
| Assumed ACBM | Assumed ACBM | Black Mastic Associated with 9" x 9" Brown Streaked Floor Tile | Misc. | NF | 5 | Rear Stairwells from Gym | |
| 7-12-PB-32A | 3% Chrysotile | 12" x 12" Brown/White Mottled Pattern Floor Tile | Misc. | NF | 5 | Classroom 2 | |
| 7-12-PB-33A | 4% Chrysotile | Black Mastic Associated with 12" x 12" Brown/White Mottled Pattern Floor Tile | Misc. | NF | 5 | Classroom 2 | |

Information abstracted by: Robert Mallett Date: August 26, 2020

Material Category: TSI = Thermal System Insulation, Surf. = Surfacing, Misc. = Miscellaneous

Friability: F = Friable, NF = Non-Friable

AHERA Assessment Categories:

1 = Damaged or significantly damaged TSI ACM; 2 = Damaged friable surfacing ACM; 3 = Significantly damaged friable surfacing ACM; 4 = Damaged or significantly damaged friable miscellaneous ACM; 5 = ACBM with potential for damage; 6 = ACBM with potential for significant damage; 7 = Any remaining friable ACBM or friable suspected ACBM

Appendix C



Re-Inspection Form 2

School: Barnstable Community Innovation School

 Date of Re-Inspection: August 26, 2020

 Homogeneous Material: Gray Mudded Pipe-Fitting Insulation

 Sample ID Number: Assumed ACBM



| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|--|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Concealed within Pipe Chases | F | Unknown | 5 | ACBM with potential for damage | Routine cleaning is not recommended within concealed locations Maintain under O&M Program | Ongoing |
| Were additional samples of this ACBM collected? No | | | | | Date of Management Planner Review: <u>November 13, 2020</u> | |
| Inspector's Name: <u>Robert Mallett</u> Inspector Signature: _____  Accreditation #/State: <u>AI900557/MA</u> Expiration Date: <u>06/01/2021</u> | | | | | Management Planner Name: <u>Dustin Diedricksen</u> Management Planner Signature: _____  Accreditation #/State: <u>AP900425/MA</u> Expiration Date: <u>04/05/2021</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____ | | | | | | |

School: Barnstable Community Innovation School

 Date of Re-Inspection: August 26, 2020

 Homogeneous Material: White/Gray Pipe Insulation

 Sample ID Number: Assumed ACBM

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|--|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Concealed within Pipe Chases | F | Unknown | 5 | ACBM with potential for damage | Routine cleaning is not recommended within concealed locations Maintain under O&M Program | Ongoing |
| Were additional samples of this ACBM collected? No | | | | | Date of Management Planner Review: <u>November 13, 2020</u> | |
| Inspector's Name: <u>Robert Mallett</u> Inspector Signature: _____  Accreditation #/State: <u>AI900557/MA</u> Expiration Date: <u>06/01/2021</u> | | | | | Management Planner Name: <u>Dustin Diedricksen</u> Management Planner Signature: _____  Accreditation #/State: <u>AP900425/MA</u> Expiration Date: <u>04/05/2021</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____ | | | | | | |

School: Barnstable Community Innovation School

 Date of Re-Inspection: August 26, 2020

 Homogeneous Material: 9" x 9" Brown Streaked Floor Tile

 Sample ID Number: Assumed ACBM

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|--|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Rear Stairwell from Gymnasium | NF | 100 SF | 5 | ACBM with potential for damage | Maintain under O&M Program | Ongoing |
| Were additional samples of this ACBM collected? No | | | | | Date of Management Planner Review: <u>November 13, 2020</u> | |
| Inspector's Name: <u>Robert Mallett</u> Inspector Signature: _____ Accreditation #/State: <u>AI900557/MA</u> Expiration Date: <u>06/01/2021</u> | | | | | Management Planner Name: <u>Dustin Diedricksen</u> Management Planner Signature: _____ Accreditation #/State: <u>AP900425/MA</u> Expiration Date: <u>04/05/2021</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____ | | | | | | |

School: Barnstable Community Innovation School

 Date of Re-Inspection: August 26, 2020

 Homogeneous Material: Black Mastic Associated with 9" x 9" Brown Streaked Floor Tile

 Sample ID Number: Assumed ACBM

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|--|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Rear Stairwell from Gymnasium | NF | 100 SF | 5 | ACBM with potential for damage | Maintain under O&M Program | Ongoing |
| Were additional samples of this ACBM collected? No | | | | | Date of Management Planner Review: <u>November 13, 2020</u> | |
| Inspector's Name: <u>Robert Mallett</u> Inspector Signature: _____ Accreditation #/State: <u>AI900557/MA</u> Expiration Date: <u>06/01/2021</u> | | | | | Management Planner Name: <u>Dustin Diedricksen</u> Management Planner Signature: _____ Accreditation #/State: <u>AP900425/MA</u> Expiration Date: <u>04/05/2021</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____ | | | | | | |





School: Barnstable Community Innovation School

Date of Re-Inspection: August 26, 2020

Homogeneous Material: 12"x 12" Brown/White Mottled Floor Tile

Sample ID Number: 7-12-PB-32A



| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|--|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Classroom 2 | NF | 1,000 SF | 5 | ACBM with potential for damage | Maintain under O&M Program | Ongoing |
| Were additional samples of this ACBM collected? No | | | | | Date of Management Planner Review: <u>November 13, 2020</u> | |
| Inspector's Name: <u>Robert Mallett</u> Inspector Signature: _____  Accreditation #/State: <u>AI900557/MA</u> Expiration Date: <u>06/01/2021</u> | | | | | Management Planner Name: <u>Dustin Diedricksen</u> Management Planner Signature: _____  Accreditation #/State: <u>AP900425/MA</u> Expiration Date: <u>04/05/2021</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____ | | | | | | |

School: Barnstable Community Innovation School

 Date of Re-Inspection: August 26, 2020

 Homogeneous Material: Black Mastic Associated with 12" x 12" Brown/White Mottled Floor Tile

 Sample ID Number: 7-12-PB-33A

| ACBM RE-INSPECTION FINDINGS | | | | | MANAGEMENT PLANNER RECOMMENDATIONS | |
|--|------------|--------------------|---------------------|--------------------------------|--|-----------------------|
| ACBM Location(s) by Assessment Category | Friability | Estimated Quantity | Assessment Category | Physical Description | Recommended Response Action(s) | Date Action Completed |
| Classroom 2 | NF | 1,000 SF | 5 | ACBM with potential for damage | Maintain under O&M Program | Ongoing |
| Were additional samples of this ACBM collected? No | | | | | Date of Management Planner Review: <u>November 13, 2020</u> | |
| Inspector's Name: <u>Robert Mallett</u> Inspector Signature: _____  Accreditation #/State: <u>AI900557/MA</u> Expiration Date: <u>06/01/2021</u> | | | | | Management Planner Name: <u>Dustin Diedricksen</u> Management Planner Signature: _____  Accreditation #/State: <u>AP900425/MA</u> Expiration Date: <u>04/05/2021</u> | |
| I, the LEA's Designated Person, have read and understood the recommendations made above: _____ Date: _____ | | | | | | |

Appendix D

Previously Sampled Materials Laboratory Reports

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com>cinnaslab@EMSL.com

| | |
|-------------|-----------|
| EMSL Order: | 041324594 |
| CustomerID: | ENVI54 |
| CustomerPO: | |
| ProjectID: | |

Attn: **Dustin Diedricksen**
Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040

Phone: (860) 646-2469
Fax: (888) 838-1160
Received: 09/12/13 3:00 PM
Analysis Date: 9/13/2013
Collected: 7/12/2013


Project: 20121793.A1E / Barnstable Public Schools: Horace Mann Elementary School

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|------------------------------|---|-------------------------------------|--------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-12PB 18A 041324594-0001 | Main Office: Office - Glue Daubs w/ 1'x1' Ceiling Tiles | Brown Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 18B 041324594-0002 | Main Office: Gym - Glue Daubs w/ 1'x1' Ceiling Tiles | Brown Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 19A 041324594-0003 | Main Office - Ceiling Plaster, Skim Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 19B 041324594-0004 | Main Office: Art Storage - Ceiling Plaster, Skim Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 19C 041324594-0005 | Main Office: Gym Office Closet - Ceiling Plaster, Skim Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 20A 041324594-0006 | Main Office - Ceiling Plaster, Rough Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 20B 041324594-0007 | Main Office: Art Storage - Ceiling Plaster, Rough Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 20C 041324594-0008 | Main Office: Gym Office Closet - Ceiling Plaster, Rough Coat | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |

Analyst(s)

Justine Schenck (24)
Nancy Stalter (15)


Stephen Siegel, CIH, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from 09/14/2013 00:08:02

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com>cinnaslab@EMSL.com

| | |
|-------------|-----------|
| EMSL Order: | 041324594 |
| CustomerID: | ENVI54 |
| CustomerPO: | |
| ProjectID: | |

Attn: **Dustin Diedricksen**
Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040

Phone: (860) 646-2469
Fax: (888) 838-1160
Received: 09/12/13 3:00 PM
Analysis Date: 9/13/2013
Collected: 7/12/2013


Project: **20121793.A1E / Barnstable Public Schools: Horace Mann Elementary School**

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|------------------------------|---|---|--------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-12PB 21A 041324594-0009 | Main Office - Wall Plaster, Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 21B 041324594-0010 | Main Office - Wall Plaster, Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 21C 041324594-0011 | Main Office - Wall Plaster, Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 22A 041324594-0012 | Main Office - Wall Plaster, Rough Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 22B 041324594-0013 | Main Office - Wall Plaster, Rough Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 22C 041324594-0014 | Main Office - Wall Plaster, Rough Coat | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 23A 041324594-0015 | Corridor Outside Custodian / Art Storage - 12"x12" Tan Mottled Pattern Floor Tile | Tan/White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 23B 041324594-0016 | Corridor Outside Custodian / Art Storage - 12"x12" Tan Mottled Pattern Floor Tile | Tan/White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |

Analyst(s)

Justine Schenck (24)
Nancy Stalter (15)


Stephen Siegel, CIH, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from 09/14/2013 00:08:02

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com>cinnaslab@EMSL.com

| | |
|-------------|-----------|
| EMSL Order: | 041324594 |
| CustomerID: | ENVI54 |
| CustomerPO: | |
| ProjectID: | |

Attn: **Dustin Diedricksen**
Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040

Phone: (860) 646-2469
 Fax: (888) 838-1160
 Received: 09/12/13 3:00 PM
 Analysis Date: 9/13/2013
 Collected: 7/12/2013


Project: 20121793.A1E / Barnstable Public Schools: Horace Mann Elementary School

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|------------------------------|---|--------------------------------------|--------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-12PB 24A 041324594-0017 | Corridor Outside Custodian / Art Storage - Associated Mastic | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 24B 041324594-0018 | Corridor Outside Custodian / Art Storage - Associated Mastic | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 24C 041324594-0019 | Corridor Outside Custodian / Art Storage - Associated Mastic | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 25A 041324594-0020 | Corridor Outside Custodian / Art Storage - Leveling Compound | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 25B 041324594-0021 | Corridor Outside Custodian / Art Storage - Leveling Compound | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 26A 041324594-0022 | Office by Exit - Carpet Glue | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 26B 041324594-0023 | Office by Exit - Carpet Glue | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |

Analyst(s)

 Justine Schenck (24)
 Nancy Stalter (15)


 Stephen Siegel, CIH, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from 09/14/2013 00:08:02

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com>cinnaslab@EMSL.com

| | |
|-------------|-----------|
| EMSL Order: | 041324594 |
| CustomerID: | ENVI54 |
| CustomerPO: | |
| ProjectID: | |

Attn: **Dustin Diedricksen**
Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040


Phone: (860) 646-2469
 Fax: (888) 838-1160
 Received: 09/12/13 3:00 PM
 Analysis Date: 9/13/2013
 Collected: 7/12/2013

Project: 20121793.A1E / Barnstable Public Schools: Horace Mann Elementary School

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|------------------------------|--|--------------------------------------|---------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-12PB 27A 041324594-0024 | Gym Technician Office - Ceramic Floor Tile (1 Type Only, No Grout) | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 27B 041324594-0025 | Gym Technician Office - Ceramic Floor Tile (1 Type Only, No Grout) | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 28A 041324594-0026 | Café / Lab Rooms - Sheetrock | White Fibrous Homogeneous | 15% Cellulose | 85% Non-fibrous (other) | None Detected |
| 7-12PB 28B 041324594-0027 | Café / Lab Rooms - Sheetrock | White Fibrous Homogeneous | 5% Cellulose | 95% Non-fibrous (other) | None Detected |
| 7-12PB 29A 041324594-0028 | Café / Lab Rooms - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 29B 041324594-0029 | Café / Lab Rooms - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 29C 041324594-0030 | Café / Lab Rooms - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 30A 041324594-0031 | Café / Lab Rooms - Yellow/Tan Base & Mastic | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |

Analyst(s)
 Justine Schenck (24)
 Nancy Stalter (15)


 Stephen Siegel, CIH, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from 09/14/2013 00:08:02

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com>cinnaslab@EMSL.com

| | |
|-------------|-----------|
| EMSL Order: | 041324594 |
| CustomerID: | ENVI54 |
| CustomerPO: | |
| ProjectID: | |

Attn: **Dustin Diedricksen**
Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040


Phone: (860) 646-2469
 Fax: (888) 838-1160
 Received: 09/12/13 3:00 PM
 Analysis Date: 9/13/2013
 Collected: 7/12/2013

Project: 20121793.A1E / Barnstable Public Schools: Horace Mann Elementary School

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|------------------------------|---|--------------------------------------|--------------|--------------------------|------------------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-12PB 30B 041324594-0032 | Café / Lab Rooms - Yellow/Tan Base & Mastic | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 31A 041324594-0033 | Room 6 - Composite Window | Black Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 31B 041324594-0034 | Room 9 - Composite Window | Black Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 32A 041324594-0035 | Room 2 - 12"x12" White Mottled Floor Tile | Brown Non-Fibrous Homogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| 7-12PB 32B 041324594-0036 | Room 2 - 12"x12" White Mottled Floor Tile | | | | Stop Positive (Not Analyzed) |
| 7-12PB 33A 041324594-0037 | Room 2 - Associated Mortar | Black Non-Fibrous Homogeneous | | 96% Non-fibrous (other) | 4% Chrysotile |
| 7-12PB 33B 041324594-0038 | Room 2 - Associated Mortar | | | | Stop Positive (Not Analyzed) |
| 7-12PB 33C 041324594-0039 | Room 2 - Associated Mortar | | | | Not Submitted |

Analyst(s)
 Justine Schenck (24)
 Nancy Stalter (15)


 Stephen Siegel, CIH, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from 09/14/2013 00:08:02

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com>cinnaslab@EMSL.com

| | |
|-------------|-----------|
| EMSL Order: | 041324594 |
| CustomerID: | ENVI54 |
| CustomerPO: | |
| ProjectID: | |

Attn: **Dustin Diedricksen**
Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040

Phone: (860) 646-2469
 Fax: (888) 838-1160
 Received: 09/12/13 3:00 PM
 Analysis Date: 9/13/2013
 Collected: 7/12/2013

Project: 20121793.A1E / Barnstable Public Schools: Horace Mann Elementary School

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|-------------------------------|----------------------------|------------------------------------|--------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-12PB 34A 041324594-0040 | Attic - Gray Duct Caulking | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 34B 041324594-0041 | Attic - Gray Duct Caulking | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 34B 041324594-0041A | Attic - Gray Duct Caulking | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |

Analyst(s)

 Justine Schenck (24)
 Nancy Stalter (15)

Stephen Siegel, CIH, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from 09/14/2013 00:08:02



41

146 Hartford Road, Manchester, CT 06040

341324594

Phone (860)646-2469 Fax (860) 649-6883

SAMPLE LOG FOR ASBESTOS BULKS

Sheet 4 of 4

Project Name: Burns Falls Public Schools

Project No. 20121793-AIE

Building: Horace Mann Elementary School
Horace

Project Manager: Dustin D

| Sample ID | Sample Location | Material | Result (%) |
|------------------|-------------------|--------------------------------|------------|
| 7-12 PB 18A | Main office | glue tabs with 1'x1' Cellulose | |
| B | Gym | ceiling tiles | |
| _____ | | | |
| 19A | Cells Man office | Ceiling Plaster - Shims Cont | |
| B | Art Storage | | |
| C | Gym office (down) | | |
| 20A | Man office | Ceiling plaster rough Cont | |
| B | Art Storage | | |
| C | Gym office (down) | | |
| 21A | Man office | wall plaster Shims Cont | |
| B | | | |
| C | | | |
| 22A | Man office | wall plaster rough Cont | |
| B | | | |
| C | | | |

RECEIVED
EMSL
CINNAMINSON, NJ
2013 SEP 12 A 10:49

Analysis Method: PLM Other

Turnaround Time ~~24hr~~ **3 Day**

Based on the turnaround time indicated above, analyses are due to EnviroScience on or before this date: _____ Please call the EnviroScience Laboratory if analyses will be late at (860) 646-2469.

Fax Results to the EnviroScience Laboratory at: 888-838-1160.

Special Instructions: Stop analysis on first positive sample in each homogeneous set of samples unless otherwise noted. Do not layer samples unless indicated. ~~EMSL 100 Point Count all samples of content < 4%, positive stop on all point counts.~~

~~on samples marked * which come out < 1% ACM or Non-ACM~~

Samples collected by: Paul Bateman Date: 7/12/13 Time: _____

Samples [Rec'd][Sent by] [Paul BA || **LD**] Date: [7/12/13 || **9/10**] Time: _____

Samples Received by: AK EMSL CK Date: 9/12/13 Time: 9:15A

Shipped To: EMSL State MA Other _____

Method of Shipment: Fed Ex Other _____

Q:\EnviroScience\Admin\FORMS\Asbestos Bulks Chain of Custody_rev 0611.doc

drop box

RECEIVED
SEP 11 2013
By SL 0830



SAMPLE LOG FOR ASBESTOS BULKS

Sheet ___ of ___

Project Name: Burns Falls Public Schools
Building: Horace Mann Elementary School

Project No. 20121793 AIE
Project Manager: Dustin D

| Sample ID | Sample Location | Material | Result (%) |
|------------------|---|---------------------------|--|
| 712 PB 23A | Corridor outside Custodian office 121412k | Tain Bottle | |
| B | Corridor outside Art Room | Pattern Floor tile | |
| _____ | | | |
| 24A | JAMP | Associated Master | 2013 SEP 12 A 10:49 RECEIVED EMSL CINNAMINSON, NJ |
| B | | | |
| C | | | |
| 25A | FRAMES | Leveling Compound | 2013 SEP 12 A 10:49 RECEIVED EMSL CINNAMINSON, NJ |
| B | | | |
| C | | | |
| _____ | | | |
| 26A | office by Exit Sign | Carpet tile | 2013 SEP 12 A 10:49 RECEIVED EMSL CINNAMINSON, NJ |
| B | | | |
| C | | | |
| _____ | | | |
| 27A | Gym Teacher office | Ceramic Floor tile mastic | 2013 SEP 12 A 10:49 RECEIVED EMSL CINNAMINSON, NJ |
| B | | (one tube only) NO grab | |
| C | | | |
| _____ | | | |

Analysis Method: PLM Other

Turnaround Time 24hr

Based on the turnaround time indicated above, analyses are due to EnviroScience on or before this date: _____. Please call the EnviroScience Laboratory if analyses will be late at (860) 646-2469.

Fax Results to the EnviroScience Laboratory at: 888-838-1160.

Special Instructions: Stop analysis on first positive sample in each homogeneous set of samples unless otherwise noted. Do not layer samples unless indicated. ~~EMSL 100 Point Count all samples of content < 4% positive stop on all point counts.~~

~~on samples marked * which come out < 1% A/m or Am after by PM~~


Samples collected by: Paul Bakeman Date: 7/12/13 Time: _____

Samples [Rec'd][Sent by] [PM BA] [LD] Date: [7/12/13] [9/10] Time: _____

Samples Received by: _____ Date: _____ Time: _____

Shipped To: EMSL State MA Other _____

Method of Shipment: Fed Ex Other _____





SAMPLE LOG FOR ASBESTOS BULKS

Sheet ___ of ___

Project Name: Barnstable Public Schools
Building: Horace Mann Elementary School

Project No. 20121793-AIE
Project Manager: Dustin D

| Sample ID | Sample Location | Material | Result (%) |
|-----------|-----------------|-------------------------------------|--|
| 7-R PB28A | cafeteria | Sheetrock | |
| A | Library | | |
| <hr/> | | | |
| 29A | } Same | Joint Compound | 2013 SEP 12 A 10:49 RECEIVED ENSL CINNAMINSON, NJ |
| B | | | |
| C | | | |
| 30A | } Same | Yellowtan 4" Base and mesh | |
| B | | | |
| C | | | |
| <hr/> | | | |
| 31A | Room 6 | Composite window sill | |
| B | 9 | | |
| <hr/> | | | |
| 32A | Room 2 | 12 x 12" Brassy Headers/rafters for | |
| B | | which | |
| <hr/> | | | |

Analysis Method: PLM Other

Turnaround Time 3 Day

Based on the turnaround time indicated above, analyses are due to EnviroScience on or before this date: _____ Please call the EnviroScience Laboratory if analyses will be late at (860) 646-2469.

Fax Results to the EnviroScience Laboratory at: 888-838-1160.

Special Instructions: Stop analysis on first positive sample in each homogeneous set of samples unless otherwise noted. Do not layer samples unless indicated. ~~ENSL 100 Point Count all samples of content < 4% positive stop on all point counts.~~


Samples collected by: Paul Bateman Date: 7/12/13 Time: _____

Samples [Rec'd][Sent by] [Paul Bateman] Date: [7/14/13] Time: [9/10]

Samples Received by: _____ Date: _____ Time: _____

Shipped To: EMSL State MA Other _____

Method of Shipment: Fed Ex Other _____





041324594

SAMPLE LOG FOR ASBESTOS BULKS

Sheet ___ of ___

Project Name: Burns Falls Public Schools
Building: Harvey Munn Elementary School

Project No. 20121793-AIE
Project Manager: Dustin D.

| Sample ID | Sample Location | Material | Result (%) |
|------------|-------------------|-----------------------|------------|
| 7-12 PB33A | Associated master | Room 2 | 90% F |
| D. | ↓ | ↓ | ↓ |
| C. | | | |
| 34A. | AHvc | gray Dust (wallpaper) | 50% F |
| B. | [Redacted] | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

RECEIVED
 EMSL
 CINNAMINSON, NJ
 2013 SEP 12 AM 10:49

Analysis Method: PLM Other Turnaround Time 24hr

Based on the turnaround time indicated above, analyses are due to EnviroScience on or before this date: _____. Please call the EnviroScience Laboratory if analyses will be late at (860) 646-2469.

Fax Results to the EnviroScience Laboratory at: 888-838-1160.

Special Instructions: Stop analysis on first positive sample in each homogeneous set of samples unless otherwise noted. Do not layer samples unless indicated. ~~At 100 Points Count all samples of content < 4% positive stop on all positive counts.~~ Please perform TEM/No.

On Samples marked * which come out < 1% ACM or Non-ACM by PLM

Samples collected by: Paul Bateman Date: 7/12/13 Time: _____

Samples [Rec'd][Sent by] [Paul Bateman] Date: [7/1/13] Time: _____

Samples Received by: _____ Date: _____ Time: _____

Shipped To: EMSL State NY Other _____

Method of Shipment: Fed Ex Other _____

RECEIVED
 SEP 11 2013
 By ML 0830



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 041722573

Customer ID: ENVI54

Customer PO: 20150090.A8E

Project ID:

Attention: Dustin Diedricksen
Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040

Phone: (617) 778-3750

Fax: (888) 838-1160

Received Date: 08/01/2017 9:30 AM

Analysis Date: 08/03/2017 - 08/07/2017

Collected Date: 07/19/2017

Project: Barnstable Public Schools / 20150090.A8E / Various Locations -Barnstable, MA

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--|--|-------------------------------|--------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-19-PB-01A <small>041722573-0001</small> | Horace Mann Charter Public School - Bathroom off Gym Hall - Ceiling Plaster - Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-01B <small>041722573-0002</small> | Horace Mann Charter Public School - Bathroom off Gym Hall - Ceiling Plaster - Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-01C <small>041722573-0003</small> | Horace Mann Charter Public School - Bathroom off Gym Hall - Ceiling Plaster - Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-02A <small>041722573-0004</small> | Horace Mann Charter Public School - Bathroom off Gym Hall - Ceiling Plaster - Rough Coat | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-02B <small>041722573-0005</small> | Horace Mann Charter Public School - Bathroom off Gym Hall - Ceiling Plaster - Rough Coat | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-02C <small>041722573-0006</small> | Horace Mann Charter Public School - Bathroom off Gym Hall - Ceiling Plaster - Rough Coat | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-03A <small>041722573-0007</small> | Horace Mann Charter Public School - Bathroom off Gym Hall - Brown Grout with 1x1 Ceramic Floor Tiles | Brown Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-03B <small>041722573-0008</small> | Horace Mann Charter Public School - Gym Office - Brown Grout with 1x1 Ceramic Floor Tiles | Brown Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-04A <small>041722573-0009</small> | Horace Mann Charter Public School - Bathroom off Gym Hall - Mudset with 1x1 Ceramic Floor Tiles | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-04B <small>041722573-0010</small> | Horace Mann Charter Public School - Gym Office - Mudset with 1x1 Ceramic Floor Tiles | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |

Initial report from: 08/07/2017 11:06:36



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 041722573
Customer ID: ENVI54
Customer PO: 20150090.A8E
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|---|---|---|--------------------------------------|-------------------------------------|--------------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-19-PB-05A 041722573-0011 | Horace Mann Charter Public School - Main Hall - Cellulose 1x1 Pore Ceiling Tiles | Brown Fibrous Homogeneous | 98% Cellulose | 2% Non-fibrous (Other) | None Detected |
| 7-19-PB-05B 041722573-0012 | Horace Mann Charter Public School - Gym - Cellulose 1x1 Pore Ceiling Tiles | Brown Fibrous Homogeneous | 98% Cellulose | 2% Non-fibrous (Other) | None Detected |
| 7-19-PB-06A 041722573-0013 | Horace Mann Charter Public School - Main Hall - Brown Glue Daubs associated with 1x1 Pore Ceiling Tiles | Brown Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-06B 041722573-0014 | Horace Mann Charter Public School - Gym - Brown Glue Daubs associated with 1x1 Pore Ceiling Tiles | Brown Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-07A 041722573-0015 | Horace Mann Charter Public School - Lobby - 2x2 Ceiling Tiles | Gray Fibrous Homogeneous | 45% Cellulose 50% Min. Wool | 5% Non-fibrous (Other) | None Detected |
| 7-19-PB-07B 041722573-0016 | Horace Mann Charter Public School - Lobby - 2x2 Ceiling Tiles | Gray Fibrous Homogeneous | 60% Cellulose 35% Min. Wool | 5% Non-fibrous (Other) | None Detected |
| 7-19-PB-08A 041722573-0017 | Horace Mann Charter Public School - Hallway to Gym - 2x4 Ceiling Tiles | Gray Fibrous Homogeneous | 50% Cellulose 40% Min. Wool | 10% Non-fibrous (Other) | None Detected |
| 7-19-PB-08B 041722573-0018 | Horace Mann Charter Public School - Hallway to Gym - 2x4 Ceiling Tiles | Gray Fibrous Homogeneous | 55% Cellulose 40% Min. Wool | 5% Non-fibrous (Other) | None Detected |
| 7-19-PB-09A 041722573-0019 | Barnstable High School Library - Brown Carpet Glue | Brown/Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-09B 041722573-0020 | Barnstable High School Library - Brown Carpet Glue | Brown/Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-09C 041722573-0021 | Barnstable High School Library - Brown Carpet Glue | Brown Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-10A 041722573-0022 | Cape Cod Collaborative School Custodial Area by Cafeteria - Sheetrock | Gray Non-Fibrous Homogeneous | 3% Glass | 97% Non-fibrous (Other) | None Detected |
| 7-19-PB-10B 041722573-0023 | Cape Cod Collaborative School Hall By Room T - Sheetrock | Gray Non-Fibrous Homogeneous | 3% Glass | 97% Non-fibrous (Other) | None Detected |
| 7-19-PB-10C 041722573-0024 | Cape Cod Collaborative School Main Bathrooms by Office - Sheetrock | Gray Non-Fibrous Homogeneous | 5% Cellulose 3% Glass | 92% Non-fibrous (Other) | None Detected |
| 7-19-PB-11A 041722573-0025 | Cape Cod Collaborative School Custodial Area by Cafeteria - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |

Initial report from: 08/07/2017 11:06:36



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 041722573
Customer ID: ENVI54
Customer PO: 20150090.A8E
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|-------------------------------|---|---|--|-------------------------------------|--------------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-19-PB-11B 041722573-0026 | Cape Cod Collaborative School Hall by Room T - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-11C 041722573-0027 | Cape Cod Collaborative School Main Bathrooms by Office - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-12A 041722573-0028 | Cape Cod Collaborative School Custodial Area - 12x12 Black Mottled Floor Tiles | Black Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-12B 041722573-0029 | Cape Cod Collaborative School Bathrooms - 12x12 Black Mottled Floor Tiles | Black Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-13A 041722573-0030 | Cape Cod Collaborative School Custodial Area - Associated Yellow Mastie | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-13B 041722573-0031 | Cape Cod Collaborative School Bathrooms - Associated Yellow Mastie | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-14A 041722573-0032 | Cape Cod Collaborative School Main Hallway - 12x12 Tan Mottled Floor Tiles | Tan Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-14B 041722573-0033 | Cape Cod Collaborative School Main Hallway - 12x12 Tan Mottled Floor Tiles | Tan Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-15A 041722573-0034 | Cape Cod Collaborative School Cafeteria - Associated Yellow Mastie | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-15B 041722573-0035 | Cape Cod Collaborative School Cafeteria - Associated Yellow Mastie | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-16A 041722573-0036 | Cape Cod Collaborative School Custodial Area - 2x4 Smooth Ceiling Tiles | Brown Fibrous Homogeneous | 98% Min. Wool | 2% Non-fibrous (Other) | None Detected |
| 7-19-PB-16B 041722573-0037 | Cape Cod Collaborative School Custodial Area - 2x4 Smooth Ceiling Tiles | Brown Fibrous Homogeneous | 98% Min. Wool | 2% Non-fibrous (Other) | None Detected |
| 7-19-PB-17A 041722573-0038 | Cape Cod Collaborative School Hallway - 2x4 Perforation Pattern Ceiling Tiles | Gray Fibrous Homogeneous | 50% Cellulose 40% Min. Wool | 10% Non-fibrous (Other) | None Detected |

Initial report from: 08/07/2017 11:06:36



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 041722573
Customer ID: ENVI54
Customer PO: 20150090.A8E
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|-------------------------------|---|---|--|-------------------------------------|---|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-19-PB-17B 041722573-0039 | Cape Cod Collaborative School Classrooms - 2x4-Pore-Striation-Pattern-Ceiling Tiles | Gray Fibrous Homogeneous | 45% Cellulose 50% Min.-Wool | 5% Non-fibrous (Other) | None Detected |
| 7-19-PB-18A 041722573-0040 | Cape Cod Collaborative School Hallway - 4" Gray-Base-Cove | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-18B 041722573-0041 | Cape Cod Collaborative School Classrooms - 4" Gray-Base-Cove | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-19A 041722573-0042 | Cape Cod Collaborative School Hallway - Tan-Glue-with 4" Gray-Base-Cove | Tan Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-19B 041722573-0043 | Cape Cod Collaborative School Hallway - Tan-Glue-with 4" Gray-Base-Cove | Tan Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-20A 041722573-0044 | Cape Cod Collaborative School Hallway - 1x1-Ceramic-Wall-Tile-Grout - White | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-20B 041722573-0045 | Cape Cod Collaborative School Hallway - 1x1-Ceramic-Wall-Tile-Grout - White | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-21A 041722573-0046 | Cape Cod Collaborative School Hallway - 1x1-Ceramic-Wall-Tile-Glue | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-21B 041722573-0047 | Cape Cod Collaborative School Hallway - 1x1-Ceramic-Wall-Tile-Glue | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-22A 041722573-0048 | Cape Cod Collaborative School Classrooms - Windows - Interior Window - Glazing Compound - Gray | Gray Non-Fibrous Homogeneous | | 96% Non-fibrous (Other) | 4% Chrysotile |
| 7-19-PB-22B 041722573-0049 | Cape Cod Collaborative School Classrooms - Windows - Interior Window - Glazing Compound - Gray | | | | Positive Stop (Not Analyzed) |
| 7-19-PB-23A 041722573-0050 | Cape Cod Collaborative School Portable Classrooms - Sheetrock | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |

Initial report from: 08/07/2017 11:06:36



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 041722573
Customer ID: ENVI54
Customer PO: 20150090.A8E
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|-------------------------------|--|---|--------------------------------------|-------------------------------------|--------------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-19-PB-23B 041722573-0051 | Cape Cod Collaborative School Library - Sheetrock | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-23C 041722573-0052 | Cape Cod Collaborative School Classrooms 5-/6 - Sheetrock | Gray Non-Fibrous Homogeneous | 4% Cellulose 2% Glass | 94% Non-fibrous (Other) | None Detected |
| 7-19-PB-24A 041722573-0053 | Cape Cod Collaborative School Portable Classrooms - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-24B 041722573-0054 | Cape Cod Collaborative School Library - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-24C 041722573-0055 | Cape Cod Collaborative School Classrooms 5-/6 - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-25A 041722573-0056 | Cape Cod Collaborative School Hall to Portables - 12x12 Tan Mottled Floor Tiles | Tan Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-25B 041722573-0057 | Cape Cod Collaborative School Hall to Portables - 12x12 Tan Mottled Floor Tiles | Tan Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-26A 041722573-0058 | Cape Cod Collaborative School Hall to Portables - Associated Yellow Mastie | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-26B 041722573-0059 | Cape Cod Collaborative School Hall to Portables - Associated Yellow Mastie | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-27A 041722573-0060 | Cape Cod Collaborative School Woodshop in Portables - 12x12 Tan Floor Tiles | Tan Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-27B 041722573-0061 | Cape Cod Collaborative School Woodshop in Portables - 12x12 Tan Floor Tiles | Tan Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-28A 041722573-0062 | Cape Cod Collaborative School Woodshop in Portables - Associated Yellow Mastie | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |

Initial report from: 08/07/2017 11:06:36



EMSL Analytical, Inc.

200 Route 130 North Cinnaminson, NJ 08077

Tel/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com> / cinnasblab@EMSL.com

EMSL Order: 041722573
Customer ID: ENVI54
Customer PO: 20150090.A8E
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|--|--|---|--|-------------------------------------|--------------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-19-PB-28B <small>041722573-0063</small> | Cape Cod Collaborative School - Woodshop in Portables - Associated Yellow Mastic | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-29A <small>041722573-0064</small> | Cape Cod Collaborative School - Rear Bathroom - Near Room 8 - Mudset with 1x1 Ceramic Floor Tiles | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-29B <small>041722573-0065</small> | Cape Cod Collaborative School - Rear Bathroom - Near Room 8 - Mudset with 1x1 Ceramic Floor Tiles | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (Other) | None Detected |
| 7-19-PB-30A <small>041722573-0066</small> | Cape Cod Collaborative School - Classroom 7 - 1x1 Pore Ceiling Tiles | Brown Fibrous Homogeneous | 98% Min. Wool | 2% Non-fibrous (Other) | None Detected |
| 7-19-PB-30B <small>041722573-0067</small> | Cape Cod Collaborative School - Classroom 7 - 1x1 Pore Ceiling Tiles | Brown Fibrous Homogeneous | 98% Min. Wool | 2% Non-fibrous (Other) | None Detected |
| 7-19-PB-31A <small>041722573-0068</small> | Cape Cod Collaborative School - Hallway - 2x4 Pore and Striation Pattern Ceiling Tiles | Gray Fibrous Homogeneous | 45% Cellulose 45% Min. Wool | 10% Non-fibrous (Other) | None Detected |
| 7-19-PB-31B <small>041722573-0069</small> | Cape Cod Collaborative School - Hallway - 2x4 Pore and Striation Pattern Ceiling Tiles | Gray Fibrous Homogeneous | 50% Cellulose 45% Min. Wool | 5% Non-fibrous (Other) | None Detected |

Analyst(s)

Stephen Severn (38)

Zackary Carbee (30)

Benjamin Ellis, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%

Samples analyzed by EMSL Analytical, Inc. South Portland, ME

Initial report from: 08/07/2017 11:06:36

041722573



FUSS & O'NEILL
EnviroScience, LLC

www.fando.com

50 Redfield Street, Suite 100, Boston, MA 02122

Phone (617) 282-4675 Fax (617) 282-8253

ASBESTOS BULK SAMPLE CHAIN OF CUSTODY

Sheet ___ of ___

Project Name: Barnstable Public Schools

Project No. 20150090.A8E

Site Address: Various Locations- Barnstable, MA

Project Manager: Dustin Diedricksen

Building Name/Number: Horace Mann ES/HS/CCC Collaborative/Waldorf

Total # of Samples: **68** (69) AC

| Sample ID (01A-Initials-Date) | Material Type | Sample Location | Comments/ Quantities |
|--|---|-----------------------|-------------------------|
| Horace Mann Charter Public School | | | |
| 7-19-PB-01A | Ceiling plaster-skim coat | Bathroom off gym hall | 500 SF |
| 7-19-PB-01B | Ceiling plaster-skim coat | Bathroom off gym hall | 500 SF |
| 7-19-PB-01C | Ceiling plaster-skim coat | Bathroom off gym hall | 500 SF |
| 7-19-PB-02A | Ceiling plaster-rough coat | Bathroom off gym hall | 500 SF |
| 7-19-PB-02B | Ceiling plaster-rough coat | Bathroom off gym hall | 500 SF |
| 7-19-PB-02C | Ceiling plaster-rough coat | Bathroom off gym hall | 500 SF |
| 7-19-PB-03A | Brown Grout with 1" x 1" ceramic floor tiles | Bathroom off gym hall | 500 SF |
| 7-19-PB-03B | Brown Grout with 1" x 1" ceramic floor tiles | Gym office | 500 SF |
| 7-19-PB-04A | Mudset with 1" x 1" ceramic floor tiles | Bathroom off gym hall | 500 SF |
| 7-19-PB-04B | Mudset with 1" x 1" ceramic floor tiles | Gym office | 500 SF |
| 7-19-PB-05A | Cellulose 1' x 1' pore ceiling tiles | Main Hall | 5,000 SF |
| 7-19-PB-05B | Cellulose 1' x 1' pore ceiling tiles | Gym | 5,000 SF |
| 7-19-PB-06A | Brown glue daubs associated with 1' x 1' pore ceiling tiles | Main Hall | 5,000 SF |
| 7-19-PB-06B | Brown glue daubs associated with 1' x 1' pore ceiling tiles | Gym | 5,000 SF |
| 7-19-PB-07A | 2' x 2' ceiling tiles | Lobby | 200 SF |
| 7-19-PB-07B | 2' x 2' ceiling tiles | Lobby | 200 SF |
| 7-19-PB-08A | 2' x 4' ceiling tiles | Hallway to gym | 1,000 SF |
| 7-19-PB-08B | 2' x 4' ceiling tiles | Hallway to gym | 1,000 SF |
| Barnstable High School | | | |
| 7-19-PB-09A | Brown carpet glue | Library | 5,000 SF |
| 7-19-PB-09B | Brown carpet glue | Library | 5,000 SF |
| 7-19-PB-09C | Brown carpet glue | Library | 5,000 SF |
| Cape Cod Collaborative School | | | |

2017 AUG - 1 PM
 CHINA
 500 SF

04, 722573



**FUSS & O'NEILL
EnviroScience, LLC**

www.fando.com

50 Redfield Street, Suite 100, Boston, MA 02122

Phone (617) 282-4675 Fax (617) 282-8253

| | | | |
|----------------------------------|--|-----------------------------|-----------|
| 7-19-PB-10A | Sheetrock | Custodial area by Cafeteria | 5,000 SF |
| 7-19-PB-10B | Sheetrock | Hall By room T | 5,000 SF |
| 7-19-PB-10C | Sheetrock | Main Bathrooms by office | 5,000 SF |
| 7-19-PB-11A | Joint Compound | Custodial area by Cafeteria | 5,000 SF |
| 7-19-PB-11B | Joint Compound | Hall By room T | 5,000 SF |
| 7-19-PB-11C | Joint Compound | Main Bathrooms by office | 5,000 SF |
| 7-19-PB-12A | 12" x 12" black mottled floor tiles | Custodial area | 600 SF |
| 7-19-PB-12B | 12" x 12" black mottled floor tiles | Bathrooms | 600 SF |
| 7-19-PB-13A | Associated yellow mastic | Custodial area | 600 SF |
| 7-19-PB-13B | Associated yellow mastic | Bathrooms | 600 SF |
| 7-19-PB-14A | 12" x 12" Tan mottled floor tiles | Main Hallway | 15,000 SF |
| 7-19-PB-14B | 12" x 12" tan mottled floor tiles | Main Hallway | 15,000 SF |
| 7-19-PB-15A | Associated yellow mastic | Cafeteria | 15,000 SF |
| 7-19-PB-15B | Associated yellow mastic | Cafeteria | 15,000 SF |
| 7-19-PB-16A | 2' x 4' smooth ceiling tiles | Custodial area | 500 SF |
| 7-19-PB-16B | 2' x 4' smooth ceiling tiles | Custodial area | 500 SF |
| 7-19-PB-17A | 2' x 4' pore striation pattern ceiling tiles | Hallway | 10,000 SF |
| 7-19-PB-17B | 2' x 4' pore striation pattern ceiling tiles | Classrooms | 10,000 SF |
| 7-19-PB-18A | 4" gray base cove | Hallway | 1,500 LF |
| 7-19-PB-18B | 4" gray base cove | Classrooms | 1,500 LF |
| 7-19-PB-19A | Tan glue with 4" gray base cove | Hallway | 1,500 LF |
| 7-19-PB-19B | Tan glue with 4" gray base cove | Classrooms | 1,500 LF |
| 7-19-PB-20A | 1" x 1" ceramic wall tile grout-white | Hallway | 1,500 SF |
| 7-19-PB-20B | 1" x 1" ceramic wall tile grout-white | Hallway | 1,500 SF |
| 7-19-PB-21A | 1" x 1" ceramic wall tile glue | Hallway | 1,500 SF |
| 7-19-PB-21B | 1" x 1" ceramic wall tile glue | Hallway | 1,500 SF |
| 7-19-PB-22A | Interior window glazing compound-gray | Classroom windows | 2,000 LF |
| 7-19-PB-22B | Interior window glazing compound-gray | Classroom windows | 2,000 LF |
| Waldorf Elementary School | | | |

2011 AUG 1
 10:00 AM
 15,000 SF
 15,000 SF
 600 SF
 600 SF
 600 SF
 600 SF

041722573



FUSS & O'NEILL
EnviroScience, LLC

www.fando.com

50 Redfield Street, Suite 100, Boston, MA 02122

Phone (617) 282-4675 Fax (617) 282-8253

| | | | |
|-------------|---|---------------------------|-----------|
| 7-19-PB-23A | Sheetrock | Portable classrooms | 5,000 SF. |
| 7-19-PB-23B | Sheetrock | Library | 5,000 SF |
| 7-19-PB-23C | Sheetrock | Classrooms 5/6 | 5,000 SF |
| 7-19-PB-24A | Joint Compound | Portable classrooms | 5,000 SF |
| 7-19-PB-24B | Joint Compound | Library | 5,000 SF |
| 7-19-PB-24C | Joint Compound | Classrooms 5/6 | 5,000 SF |
| 7-19-PB-25A | 12" x 12" Tan mottled floor tiles | Hall to portables | 400 SF |
| 7-19-PB-25B | 12" x 12" tan mottled floor tiles | Hall to portables | 400 SF |
| 7-19-PB-26A | Associated yellow mastic | Hall to portables | 400 SF |
| 7-19-PB-26B | Associated yellow mastic | Hall to portables | 400 SF |
| 7-19-PB-27A | 12" x 12" Tan floor tiles | Woodshop in portables | 750 SF |
| 7-19-PB-27B | 12" x 12" tan floor tiles | Woodshop in portables | 750 SF |
| 7-19-PB-28A | Associated yellow mastic | Woodshop in portables | 750 SF |
| 7-19-PB-28B | Associated yellow mastic | Woodshop in portables | 750 SF |
| 7-19-PB-29A | Mudset with 1" x 1" ceramic floor tiles | Rear bathroom-near room 8 | 500 SF |
| 7-19-PB-29B | Mudset with 1" x 1" ceramic floor tiles | Rear bathroom-near room 8 | 500 SF |
| 7-19-PB-30A | 1' x 1' pore ceiling tiles-no glue | Classroom 7 | 1,000 SF |
| 7-19-PB-30B | 1' x 1' pore ceiling tiles-no glue | Classroom 7 | 1,000 SF |
| 7-19-PB-31A | 2' x4' pore and striation pattern ceiling tiles | Hallway | 1,500 SF |
| 7-19-PB-31B | 2' x4' pore and striation pattern ceiling tiles | Hallway | 1,500 SF |

2017 AUG - 1 P 10:57
 CHINA SHI
 400 SF
 400 SF
 400 SF
 400 SF
 750 SF
 750 SF

Analysis Method: PLM Other

NO TEM - PLM only

Turnaround Time 5 day

One Week

Based on the turnaround time indicated above, analyses are due to EnviroScience on or before this date: _____ . Please call EnviroScience if analyses will not be completed for requested t/a/t at (617) 282-4675.

Email Results to: ddiedricksen@fando.com Do Not Mail Hard Copy Report FAX Results to: 888-838-1160.

Special Instructions: Stop analysis on first positive sample in each homogeneous set of samples unless otherwise noted. Do not layer samples unless indicated. Do not point count. ~~IF NOB, analyze all samples are all negative by PLM, analyze only the "A" sample (see method sheet) (PLM only) IF NOB, on a [redacted] t. Analyze a maximum of [redacted] samples by TEM.~~

NO TEM please

Samples Collected by: Paul Bateman Date: 7/19/17

Samples Sent by: Paul Bateman Date: 7/19/17 Time: _____

Shipped To: EMSL NJ Other _____

Method of Shipment: Fed Ex Lab Drop Off Other _____

Handwritten signature and date: 8-17 9:30

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com>cinnaslab@EMSL.com

| | |
|-------------|-----------|
| EMSL Order: | 041324594 |
| CustomerID: | ENVI54 |
| CustomerPO: | |
| ProjectID: | |

Attn: **Dustin Diedricksen**
Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040


Phone: (860) 646-2469
 Fax: (888) 838-1160
 Received: 09/12/13 3:00 PM
 Analysis Date: 9/13/2013
 Collected: 7/12/2013

Project: 20121793.A1E / Barnstable Public Schools: Horace Mann Elementary School

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|------------------------------|---|-------------------------------------|--------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-12PB 18A 041324594-0001 | Main Office: Office - Glue Daubs w/ 1'x1' Ceiling Tiles | Brown Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 18B 041324594-0002 | Main Office: Gym - Glue Daubs w/ 1'x1' Ceiling Tiles | Brown Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 19A 041324594-0003 | Main Office - Ceiling Plaster, Skim Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 19B 041324594-0004 | Main Office: Art Storage - Ceiling Plaster, Skim Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 19C 041324594-0005 | Main Office: Gym Office Closet - Ceiling Plaster, Skim Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 20A 041324594-0006 | Main Office - Ceiling Plaster, Rough Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 20B 041324594-0007 | Main Office: Art Storage - Ceiling Plaster, Rough Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 20C 041324594-0008 | Main Office: Gym Office Closet - Ceiling Plaster, Rough Coat | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |

Analyst(s)
 Justine Schenck (24)
 Nancy Stalter (15)


 Stephen Siegel, CIH, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from 09/14/2013 00:08:02

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com>cinnaslab@EMSL.com

| | |
|-------------|-----------|
| EMSL Order: | 041324594 |
| CustomerID: | ENVI54 |
| CustomerPO: | |
| ProjectID: | |

Attn: **Dustin Diedricksen**
Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040

Phone: (860) 646-2469
 Fax: (888) 838-1160
 Received: 09/12/13 3:00 PM
 Analysis Date: 9/13/2013
 Collected: 7/12/2013


Project: **20121793.A1E / Barnstable Public Schools: Horace Mann Elementary School**

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|------------------------------|---|---|--------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-12PB 21A 041324594-0009 | Main Office - Wall Plaster, Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 21B 041324594-0010 | Main Office - Wall Plaster, Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 21C 041324594-0011 | Main Office - Wall Plaster, Skim Coat | White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 22A 041324594-0012 | Main Office - Wall Plaster, Rough Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 22B 041324594-0013 | Main Office - Wall Plaster, Rough Coat | Gray Fibrous Homogeneous | 2% Cellulose | 98% Non-fibrous (other) | None Detected |
| 7-12PB 22C 041324594-0014 | Main Office - Wall Plaster, Rough Coat | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 23A 041324594-0015 | Corridor Outside Custodian / Art Storage - 12"x12" Tan Mottled Pattern Floor Tile | Tan/White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 23B 041324594-0016 | Corridor Outside Custodian / Art Storage - 12"x12" Tan Mottled Pattern Floor Tile | Tan/White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |

Analyst(s)

 Justine Schenck (24)
 Nancy Stalter (15)


 Stephen Siegel, CIH, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from 09/14/2013 00:08:02



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com>

cinnaslab@EMSL.com

| | |
|-------------|-----------|
| EMSL Order: | 041324594 |
| CustomerID: | ENVI54 |
| CustomerPO: | |
| ProjectID: | |


| | |
|--|--|
| Attn: Dustin Diedricksen Fuss & O'Neill EnviroScience, LLC 146 Hartford Road Manchester, CT 06040 | Phone: (860) 646-2469 Fax: (888) 838-1160 Received: 09/12/13 3:00 PM Analysis Date: 9/13/2013 Collected: 7/12/2013 |
| Project: 20121793.A1E / Barnstable Public Schools: Horace Mann Elementary School | |

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|------------------------------|---|--------------------------------------|--------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-12PB 24A 041324594-0017 | Corridor Outside Custodian / Art Storage - Associated Mastic | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 24B 041324594-0018 | Corridor Outside Custodian / Art Storage - Associated Mastic | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 24C 041324594-0019 | Corridor Outside Custodian / Art Storage - Associated Mastic | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 25A 041324594-0020 | Corridor Outside Custodian / Art Storage - Leveling Compound | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 25B 041324594-0021 | Corridor Outside Custodian / Art Storage - Leveling Compound | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 26A 041324594-0022 | Office by Exit - Carpet Glue | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 26B 041324594-0023 | Office by Exit - Carpet Glue | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |

Analyst(s)

 Justine Schenck (24)
 Nancy Stalter (15)


 Stephen Siegel, CIH, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from 09/14/2013 00:08:02

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com>cinnaslab@EMSL.com

| | |
|-------------|-----------|
| EMSL Order: | 041324594 |
| CustomerID: | ENVI54 |
| CustomerPO: | |
| ProjectID: | |

Attn: **Dustin Diedricksen**
Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040


Phone: (860) 646-2469
 Fax: (888) 838-1160
 Received: 09/12/13 3:00 PM
 Analysis Date: 9/13/2013
 Collected: 7/12/2013

Project: 20121793.A1E / Barnstable Public Schools: Horace Mann Elementary School

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|------------------------------|--|--------------------------------------|---------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-12PB 27A 041324594-0024 | Gym Technician Office - Ceramic Floor Tile (1 Type Only, No Grout) | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 27B 041324594-0025 | Gym Technician Office - Ceramic Floor Tile (1 Type Only, No Grout) | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 28A 041324594-0026 | Café / Lab Rooms - Sheetrock | White Fibrous Homogeneous | 15% Cellulose | 85% Non-fibrous (other) | None Detected |
| 7-12PB 28B 041324594-0027 | Café / Lab Rooms - Sheetrock | White Fibrous Homogeneous | 5% Cellulose | 95% Non-fibrous (other) | None Detected |
| 7-12PB 29A 041324594-0028 | Café / Lab Rooms - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 29B 041324594-0029 | Café / Lab Rooms - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 29C 041324594-0030 | Café / Lab Rooms - Joint Compound | White Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 30A 041324594-0031 | Café / Lab Rooms - Yellow/Tan Base & Mastic | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |

Analyst(s)
 Justine Schenck (24)
 Nancy Stalter (15)


 Stephen Siegel, CIH, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from 09/14/2013 00:08:02

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com>cinnaslab@EMSL.com

| | |
|-------------|-----------|
| EMSL Order: | 041324594 |
| CustomerID: | ENVI54 |
| CustomerPO: | |
| ProjectID: | |

Attn: **Dustin Diedricksen**
Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040


Phone: (860) 646-2469
 Fax: (888) 838-1160
 Received: 09/12/13 3:00 PM
 Analysis Date: 9/13/2013
 Collected: 7/12/2013

Project: 20121793.A1E / Barnstable Public Schools: Horace Mann Elementary School

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|------------------------------|---|--------------------------------------|--------------|--------------------------|------------------------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-12PB 30B 041324594-0032 | Café / Lab Rooms - Yellow/Tan Base & Mastic | Yellow Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 31A 041324594-0033 | Room 6 - Composite Window | Black Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 31B 041324594-0034 | Room 9 - Composite Window | Black Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 32A 041324594-0035 | Room 2 - 12"x12" White Mottled Floor Tile | Brown Non-Fibrous Homogeneous | | 97% Non-fibrous (other) | 3% Chrysotile |
| 7-12PB 32B 041324594-0036 | Room 2 - 12"x12" White Mottled Floor Tile | | | | Stop Positive (Not Analyzed) |
| 7-12PB 33A 041324594-0037 | Room 2 - Associated Mortar | Black Non-Fibrous Homogeneous | | 96% Non-fibrous (other) | 4% Chrysotile |
| 7-12PB 33B 041324594-0038 | Room 2 - Associated Mortar | | | | Stop Positive (Not Analyzed) |
| 7-12PB 33C 041324594-0039 | Room 2 - Associated Mortar | | | | Not Submitted |

Analyst(s)
 Justine Schenck (24)
 Nancy Stalter (15)


 Stephen Siegel, CIH, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from 09/14/2013 00:08:02

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (800) 220-3675 / (856) 786-5974

<http://www.EMSL.com>cinnaslab@EMSL.com

| | |
|-------------|-----------|
| EMSL Order: | 041324594 |
| CustomerID: | ENVI54 |
| CustomerPO: | |
| ProjectID: | |

Attn: **Dustin Diedricksen**
Fuss & O'Neill EnviroScience, LLC
146 Hartford Road
Manchester, CT 06040

Phone: (860) 646-2469
 Fax: (888) 838-1160
 Received: 09/12/13 3:00 PM
 Analysis Date: 9/13/2013
 Collected: 7/12/2013

Project: 20121793.A1E / Barnstable Public Schools: Horace Mann Elementary School

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample | Description | Appearance | Non-Asbestos | | Asbestos |
|-------------------------------|----------------------------|------------------------------------|--------------|--------------------------|---------------|
| | | | % Fibrous | % Non-Fibrous | % Type |
| 7-12PB 34A 041324594-0040 | Attic - Gray Duct Caulking | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 34B 041324594-0041 | Attic - Gray Duct Caulking | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |
| 7-12PB 34B 041324594-0041A | Attic - Gray Duct Caulking | Gray Non-Fibrous Homogeneous | | 100% Non-fibrous (other) | None Detected |

Analyst(s)

 Justine Schenck (24)
 Nancy Stalter (15)

Stephen Siegel, CIH, Laboratory Manager
 or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ NVLAP Lab Code 101048-0, AIHA-LAP, LLC-IHLAP Lab 100194, NYS ELAP 10872, NJ DEP 03036, PA ID# 68-00367

Initial report from 09/14/2013 00:08:02



41

146 Hartford Road, Manchester, CT 06040

341324594

Phone (860)646-2469 Fax (860) 649-6883

SAMPLE LOG FOR ASBESTOS BULKS

Sheet 4 of 4

Project Name: Burns Falls Public Schools

Project No. 20121793-AIE

Building: Horace Mann Elementary School

Project Manager: Dustin D

| Sample ID | Sample Location | Material | Result (%) |
|------------------|--------------------|--------------------------------|------------|
| 7-12 PB 18A | Main office | glue tabs with 1'x1' Cellulose | |
| B | Gym | ceiling tiles | |
| _____ | | | |
| 19A | Cells Man office | Ceiling Plaster - Shims Cont | |
| B | Art Storage | | |
| C | Gym office (clerk) | | |
| 20A | Man office | Ceiling plaster rough Cont | |
| B | Art Storage | | |
| C | Gym office clerk | | |
| 21A | Man office | wall plaster Shims Cont | |
| B | | | |
| C | | | |
| 22A | Man office | wall plaster rough Cont | |
| B | | | |
| C | | | |

RECEIVED
EMSL
CINNAMINSON, NJ
2013 SEP 12 A 10:49

Analysis Method: PLM Other

Turnaround Time ~~24hr~~ **3 Day**

Based on the turnaround time indicated above, analyses are due to EnviroScience on or before this date: _____ Please call the EnviroScience Laboratory if analyses will be late at (860) 646-2469.

Fax Results to the EnviroScience Laboratory at: 888-838-1160.

Special Instructions: Stop analysis on first positive sample in each homogeneous set of samples unless otherwise noted. Do not layer samples unless indicated. ~~EMSL 100 Point Count all samples of content < 4% positive stop on all point counts.~~

~~on samples marked * which come out < 1% ACM or Non-ACM~~

Samples collected by: Paul Bateman Date: 7/12/13 Time: _____

Samples [Rec'd][Sent by] [Paul BA || **LD**] Date: [7/12/13 || **9/10**] Time: _____

Samples Received by: AK EMSL CK Date: 9/12/13 Time: 9:15A

Shipped To: EMSL State MA Other _____

Method of Shipment: Fed Ex Other _____

Q:\EnviroScience\Admin\FORMS\Asbestos Bulks Chain of Custody_rev 0611.doc

drop box

RECEIVED
SEP 11 2013
By SL 0830



SAMPLE LOG FOR ASBESTOS BULKS

Sheet ___ of ___

Project Name: Burns Falls Public Schools

Project No. 20121793 AIE

Building: Horace Mann Elementary School

Project Manager: Dustin D

| Sample ID | Sample Location | Material | Result (%) |
|------------------|---|---------------------------|--|
| 712 PB 23A | Corridor outside Custodian office 1214124 | Tain Bottle | |
| B | Corridor outside Art Studio | Pattern Floor tile | |
| _____ | | | |
| 24A | JAMP | Associated Master | 2013 SEP 12 A 10:49 RECEIVED EMSL CINNAMINSON, NJ |
| B | | | |
| C | | | |
| 25A | FRAMES | Leveling Compound | |
| B | | | |
| C | | | |
| _____ | | | |
| 26A | office by Exit Sign | Carpet tile | |
| B | | | |
| C | | | |
| _____ | | | |
| 27A | Gym Teacher office | Ceramic Floor tile mastic | |
| B | | (one tube only) | |
| C | | NO grab | |
| _____ | | | |

Analysis Method: PLM Other

Turnaround Time 24hrs

Based on the turnaround time indicated above, analyses are due to EnviroScience on or before this date: _____. Please call the EnviroScience Laboratory if analyses will be late at (860) 646-2469.

Fax Results to the EnviroScience Laboratory at: 888-838-1160.

Special Instructions: Stop analysis on first positive sample in each homogeneous set of samples unless otherwise noted. Do not layer samples unless indicated. ~~EMSL 400 Point Count all samples of content < 4% positive stop on all point counts.~~

~~on samples marked * which come out < 1% Asbestos. Please perform TEM/EDS by PMJ~~


Samples collected by: Paul Bakeman Date: 7/12/13 Time: _____

Samples [Rec'd][Sent by] [PMJ BA] [LD] Date: [7/12/13] [9/10] Time: _____

Samples Received by: _____ Date: _____ Time: _____

Shipped To: EMSL State MA Other _____

Method of Shipment: Fed Ex Other _____





SAMPLE LOG FOR ASBESTOS BULKS

Sheet ___ of ___

Project Name: Barnstable Public Schools
Building: Horace Mann Elementary School

Project No. 20121793-AIE
Project Manager: Dustin D

| Sample ID | Sample Location | Material | Result (%) |
|-----------|-----------------|-------------------------------------|--|
| 7-R PB28A | cafeteria | Sheetrock | |
| A | Library | | |
| <hr/> | | | |
| 29A | } Same | Joint Compound | 2013 SEP 12 A 10:49 RECEIVED ENSL CINNAMINSON, NJ |
| B | | | |
| C | | | |
| 30A | } Same | Yellowtan 4" Base and mesh | |
| B | | | |
| C | | | |
| <hr/> | | | |
| 31A | Room 6 | Composite window sill | |
| B | 9 | | |
| <hr/> | | | |
| 32A | Room 2 | 12 x 12" Brassy Headers/rafters for | |
| B | | which | |
| <hr/> | | | |

Analysis Method: PLM Other

Turnaround Time 3 Day

Based on the turnaround time indicated above, analyses are due to EnviroScience on or before this date: _____ Please call the EnviroScience Laboratory if analyses will be late at (860) 646-2469.

Fax Results to the EnviroScience Laboratory at: 888-838-1160.

Special Instructions: Stop analysis on first positive sample in each homogeneous set of samples unless otherwise noted. Do not layer samples unless indicated. ~~ENSL 100 Point Count all samples of content < 4% positive stop on all point counts.~~

~~on samples marked * which come out < 1% ACM or Non-ACM by PSM~~


Samples collected by: Paul Bateman Date: 7/12/13 Time: _____

Samples [Rec'd][Sent by] [Paul Bateman] Date: [7/14/13] Time: [9/10]

Samples Received by: _____ Date: _____ Time: _____

Shipped To: EMSL State MA Other _____

Method of Shipment: Fed Ex Other _____





041324594

SAMPLE LOG FOR ASBESTOS BULKS

Sheet ___ of ___

Project Name: Burns Falls Public Schools
Building: Harvey Mann Elementary School

Project No. 20121793-AIE
Project Manager: Dustin D.

| Sample ID | Sample Location | Material | Result (%) |
|------------|---------------------|----------------------|------------|
| 7-12 PB33A | Associated material | Room 2 | 90% F |
| D. | ↓ | ↓ | ↓ |
| C. | | | |
| 34A | AHvc | gray Dust Containing | 50% F |
| B | _____ | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

RECEIVED
EMSL
CINNAMINSON, NJ
2013 SEP 12 AM 10:49

Analysis Method: PLM Other

Turnaround Time 24hr

Based on the turnaround time indicated above, analyses are due to EnviroScience on or before this date: _____ Please call the EnviroScience Laboratory if analyses will be late at (860) 646-2469.

Fax Results to the EnviroScience Laboratory at: 888-838-1160.

Special Instructions: Stop analysis on first positive sample in each homogeneous set of samples unless otherwise noted. Do not layer samples unless indicated. ~~EMSL 100 Point Count all samples of content < 4% positive stop on all point counts.~~ Please perform TEM/No.

On Samples marked * which come out < 1% ACM or Non-ACM by PLM

Samples collected by: Paul Bateman Date: 7/12/13 Time: _____

Samples [Rec'd][Sent by] [Paul Bateman] Date: [7/1/13] Time: _____

Samples Received by: _____ Date: _____ Time: _____

Shipped To: EMSL State NJ Other _____

Method of Shipment: Fed Ex Other _____

Q:\EnviroScience\Admin\FORMS\Asbestos Bulks Chain of Custody_rev 0611.doc

RECEIVED
SEP 11 2013
By JL 0830

Appendix E

Newly Installed Materials Safety Data Sheets

To be Provided by LEA

Appendix F

Sample 6-Month Periodic Surveillance Form



Sample 6- Month Periodic Surveillance Form

Local Education Agency (LEA): Barnstable Public Schools

Facility Name: Barnstable Community Innovation School

Date of Surveillance: _____

ACBM Damage Report

| Asbestos-Containing Building Material | Location | Previous Condition | Present Condition | Change in Condition (Yes/No) | Estimated Damaged Quantity | Comments |
|---|--------------------------------|--------------------|-------------------|------------------------------|----------------------------|----------|
| Gray Mudded Pipe-Fitting Insulation | Concealed within Pipe Chases | IA | | | | |
| White/Gray Pipe Insulation | Concealed within Pipe Chases | IA | | | | |
| 9" x 9" Brown Streaked Floor Tile | Rear Stairwells from Gymnasium | G | | | | |
| Black Mastic Associated with 9" x 9" Brown Streaked Floor Tile | Rear Stairwells from Gymnasium | G | | | | |
| 12" x 12" Brown/White Mottled Pattern Floor Tile | Classroom 2 | G | | | | |
| Black Mastic Associated with 12" x 12" Brown/White Mottled Pattern Floor Tile | Classroom 2 | G | | | | |

Conditions: D = Damaged; F = Fair; G = Good; IA = Inaccessible; N/A = Not Applicable; SD = Significant Damage; SF = Square Feet

Surveillance conducted by: _____
(print name)

(signature)

I, the LEA's Designated Person, have read and understood the findings noted above: _____

Date: _____

Appendix G

Preventive Measures

Preventive Measures for Various Asbestos-Containing Building Materials

A. Surfacing Materials

“Surfacing Materials” means materials in a school building that are applied by spray, trowel, or otherwise applied to surfaces. These include sprayed-applied fireproofing materials on structural members, ceiling and wall plasters, or other materials applied to surfaces for acoustical, fireproofing, or other purposes.

Surfacing Materials are generally considered friable and can release asbestos fibers if damaged by impact, air erosion, vibration, and/or water intrusion. When properly implemented, the following procedures will reduce the potential for fiber release:

1. Sprayed-Applied Fireproofing
 - a) Identify the materials and post warning signs on the laid-in or glued-in ceiling tile. If the decking is not covered, place the sign on the wall.
 - b) Maintain the materials in intact state and undamaged condition. During winter, pigeons, squirrels and other rodents tend to roost in boiler/machine rooms and dislodge sprayed-applied fireproofing on the decking. Prevent such possibilities.
 - c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, enclosure is a temporary solution. Encapsulation of damaged sprayed-on fireproofing material is not recommended.
 - d) Train the custodial people who are responsible for care and maintenance of surfacing materials. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Ceiling and Wall Plasters
 - a) Identify the materials and post asbestos warning signs.
 - b) Maintain the materials in intact state and undamaged condition. Avoid storing/stacking on/near the materials to reduce contact damage.
 - c) Prevent water leakage. If the material is significantly damaged, removal is the best option. For minor damage, repair or enclosure is a temporary solution.
 - d) Train the custodial people who are responsible for care and maintenance of surfacing materials.

B. Thermal System Insulation (TSI)

“Thermal System Insulation (TSI)” means insulating materials applied to pipes, pipe fittings, boilers, breechings, tanks, ducts, or other components to prevent process heat loss or gain, water condensation, or for other purposes (e.g., fire door insulation core).

TSI are generally considered friable ACBM. This means they can be easily damaged, increasing the potential for fiber release. When properly implemented, the following procedures will reduce the potential for fiber release:

1. Boiler and Breeching Insulation
 - a) Identify the locations and label the boiler. Warning signs should be posted outside the boiler room.
 - b) Reduce the likelihood of fiber release by ensuring that the insulation is not damaged. Avoid storing/stacking on/near the boiler to reduce contact damage.
 - c) Maintain the insulation in intact state and undamaged condition. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
 - d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Pipe, Pipe Fitting, Tank, Duct & Breeching Insulations
 - a) Identify the locations and label the materials. Warning signs should be posted outside of rooms that have TSI materials.
 - b) Reduce the likelihood of fiber release by ensuring that the materials are not damaged. Avoid storing/stacking near the materials to reduce contact damage.
 - c) Maintain all TSI materials in intact state and undamaged condition. Inspect the protective jackets for damage. Repair damaged areas as soon as possible to prevent further deterioration. If repair is not feasible due to extensive damage/deterioration, remove the material.
 - d) Train the custodial people who are responsible for care and maintenance of TSI. Please note that the repair/removal can only be performed by a licensed abatement contractor.

C. Miscellaneous Materials

“Miscellaneous Materials” are the other ACBM in a school building that are not categorized as Surfacing Materials or TSI. These include floor tiles, floor tile and carpet mastics, gypsum wallboard and joint compound, ceiling tiles, glue daubs, asbestos cement panels, cove base and associated glue, window/door caulking and glazing compounds, etc. The following maintenance procedures are recommended for these materials:

1. Vinyl Asbestos Floor Tiles (VAT)

Vinyl Asbestos Floor Tiles (VAT) are considered non-friable, however routine maintenance procedures such as spray-buffing, burnishing, wet scrubbing, and stripping can generate asbestos fibers. Following procedures, when properly implemented, will reduce the potential of fiber release:

- a) Do not sand, grind, or abrade the tiles. Stripping of VAT should be done as infrequently as possible. When stripping becomes necessary, follow the appropriate work practices. Never perform dry stripping.
- b) During spray-buffing or burnishing the floor, operate the machine at the lowest workable speed and use the least abrasive pad. Use a wet mop for routine cleaning whenever possible.
- c) Routinely check whether chair and desk glides are in good condition and replace when necessary. Worn glides can gouge the floor and cause fiber release.
- d) Place carpets/floor mats in all entrances to reduce abrasion of floor tiles by sand and pebbles. During winter, have parking lots and walkways swept to the extent possible to avoid the tracking of salt and ice-melting compounds into the school by the students.
- e) Train the custodial people who are responsible for care and maintenance of VAT. Please note that the repair/removal can only be performed by a licensed abatement contractor.

2. Wallboard and Joint Compound Assembly

- a) Since a number of different homogeneous assemblies may exist in a building, sheetrock/joint compound must be assumed to be ACM unless sample results prove otherwise. If any specific areas are going to be disturbed, samples of the material in that area should be collected and analyzed.
- b) Reduce the likelihood of fiber release by avoiding cutting or drilling holes through the sheetrock panels.

3. Ceiling Tile and Glue Daubs

- a) Reduce the likelihood of fiber release by limiting access to the space above the ceiling tiles. Maintain the ceiling tiles in undamaged condition. Replace any damaged or water-stained tile.
- b) If the ceiling tiles are non-asbestos, collect samples and analyze the glue daubs to identify asbestos-content before disturbing the tiles.

4. Asbestos Cement Panels, Window/Door Caulking and Glazing Compounds

- a) Maintain asbestos cement panels and window/door caulking and glazing compounds in undamaged condition.

5. Carpet Glue, Blackboard/Tack Board Glue, Floor Tile Mastic, Cove Base, and Mastic

- a) Reduce the likelihood of fiber release by leaving materials in place.
- b) Maintain materials in good condition. Collect samples and analyze to identify asbestos-content before disturbing.

Appendix H

Fuss & O'Neill Asbestos Accreditations & Certifications



THE COMMONWEALTH OF MASSACHUSETTS
EXECUTIVE OFFICE OF LABOR AND WORKFORCE DEVELOPMENT
DEPARTMENT OF LABOR STANDARDS

Michael Flanagan
Director

Asbestos Inspector

ROBERT C. MALLET

Eff. Date 06/01/20

Exp. Date 06/01/21

AI900557

Member of C.O.N.E.S.

bosnew BOS-renew

21





This is to certify that

Robert C Mallett



*has completed the requisite training, and has passed an examination for
reaccreditation as:*

Asbestos Inspector Refresher

pursuant to Title II of the Toxic Substance Control Act, 15 U.S.C. 2646

Course Location

Institute for Environmental Education
16 Upton Drive Wilmington, MA 01887

January 6, 2020

Course Dates

January 06, 2020

Examination Date

20-2958-106-402379

Certificate Number

January 06, 2021

Expiration Date

Training Director

16 Upton Drive, Wilmington, MA 01887

Telephone 978.658.5272

www.ieetrains.com

INSTITUTE FOR ENVIRONMENTAL EDUCATION



THE COMMONWEALTH OF MASSACHUSETTS
EXECUTIVE OFFICE OF LABOR AND WORKFORCE DEVELOPMENT
DEPARTMENT OF LABOR STANDARDS

Michael Flanagan
Interim Director

Asbestos Management Planner

DUSTIN A. DIEDRICKSEN

Eff. Date 04/16/20

Exp. Date 04/16/21

AP900425

Member of C.O.N.E.S.

BOSR

BOS-RENEW

21





This is to certify that

Dustin A Diedricksen

*has completed the requisite training, and has passed an examination for
reaccreditation*

Asbestos Management Planner Refresher

pursuant to Title II of the Toxic Substance Control Act, 15 U.S.C. 2646

Course Location

Institute for Environmental Education
16 Upton Drive Wilmington, MA 01887

December 18, 2019

Course Dates

19-2404-136-402162

Certificate Number

December 18, 2019

Examination Date

December 18, 2020

Expiration Date

Training Director

16 Upton Drive, Wilmington, MA 01887

Telephone 978.658.5272

www.ieetrains.com

INSTITUTE FOR ENVIRONMENTAL EDUCATION