

FACILITY CONDITION ASSESSMENT



**BUREAU
VERITAS**

prepared for

Richmond Public Schools
301 North Ninth Street
Richmond, VA 23219



PREPARED BY:

*Bureau Veritas
6021 University Boulevard, Suite 200
Ellicott City, MD 21043
800.733.0660
www.us.bureauveritas.com*

BV CONTACT:

*Bill Champion
Program Manager
800.733.0660 x7296234
Bill.Champion@bureauveritas.com*

BV PROJECT #:

166385.24R000-018.468

DATE OF REPORT:

August 15, 2024

ON SITE DATE:

March 11, 2024

Mary Munford Elementary School
211 Westmoreland Avenue
Richmond, VA 23226

Bureau Veritas

TABLE OF CONTENTS

| | |
|--|-----------|
| 1. Executive Summary | 1 |
| Property Overview and Assessment Details | 1 |
| Significant/Systemic Findings and Deficiencies | 2 |
| Facility Condition Index (FCI)..... | 3 |
| Immediate Needs..... | 4 |
| Key Findings | 5 |
| Plan Types | 7 |
| 2. Building Information | 8 |
| 3. Site Summary | 17 |
| 4. ADA Accessibility | 21 |
| 5. Purpose and Scope | 22 |
| 6. Opinions of Probable Costs | 24 |
| Methodology | 24 |
| Definitions | 25 |
| 7. Certification | 26 |
| 8. Appendices | 27 |



1. Executive Summary

Property Overview and Assessment Details

| General Information | |
|--|--|
| Property Type | Elementary School |
| Number of Buildings | 1 |
| Main Address | 211 Westmoreland Avenue, Richmond, VA 23226 |
| Site Developed | 1950 |
| Outside Occupants / Leased Spaces | None |
| Date(s) of Visit | March 11, 2024 |
| Management Point of Contact | Daniel Alu Project Engineer 800 Yard Street, Suite 115 Columbus, Ohio 43212 C: 614.949.1355 daniel.alu@gofmx.com |
| On-site Point of Contact (POC) | Ronald (Bobby) Hathaway Jr., Director of Facilities Department of Facility Services 1461 A Commerce Road Richmond, VA 23224 Office: (804) 780-6251 Mobile: (804) 325-0740 Email: Rhathawa@rvaschools.net |
| Assessment & Report Prepared By | Soulihe Nida |
| Reviewed By | Daniel White Technical Report Reviewer for Bill Champion Program Manager 800.733.0660 x7296234 Bill.Champion@bureauveritas.com |
| AssetCalc Link | Full dataset for this assessment can be found at: https://www.assetcalc.net/ |



Significant/Systemic Findings and Deficiencies

Historical Summary

Mary Munford Elementary School was originally constructed in 1950 and has undergone limited school wide renovation. The general use and occupants of the facility are administration, teachers, and students used for education.

Architectural

The school's architecture and façade is from original construction and consists of brick and CMU wall system. The structure shows limited evidence of settlement with mortar joint cracks in basement brick wall. The windows are aluminum, and the exterior doors consist of aluminum and steel. There are reports of high air leaks at varying windows throughout the building. Windows and both exterior and interior doors are observed to be dated and anticipated for replacement. The roofing is built up tar and gravel with roof leaks reported over older roofing sections. Partial roof replacements are observed over kindergarten wing and kitchen/ cafeteria. Full roof is approaching end of the lifecycle. The interior finishes are in dated are replaced on an as needed basis. Typical lifecycle interior and exterior finish replacements are budgeted and anticipated.

Mechanical, Electrical, Plumbing and Fire (MEPF)

The school utilizes steam boilers and a packaged unit for shared space and ductless splits systems for cooling individual classrooms and offices. Some of the HVAC equipment was replaced in 2017 and 2022; however, most date to early 2000 and have exceeded estimate useful life. Boilers are observed to be from 2007. The electrical system consists of a switchboard, transformers, and distribution panels, all original. There is a diesel generator present for emergency power. There is one hydraulic passenger elevator that serves both floors. The plumbing system uses gas water heaters for domestic hot water. The building is protected by a fire sprinkler system. The building has a fire alarm system in place along with exit lights, emergency lighting, alarms, and fire extinguishers.

Site

Overall, the site is well maintained with moderate landscaping features and irrigation is not present. There are building mounted and pole lighting. A small asphalt parking lot serves the facility and is due for seal and stripe. The play areas have a wooden deck, a pavilion, several play structures and sports surfaces all maintained.

Recommended Additional Studies

No additional studies recommended at this time.

Facility Condition Index (FCI)

One of the major goals of the FCA is to calculate the Facility Condition Index (FCI), which provides a theoretical objective indication of a facility’s overall condition. The FCI is defined as the ratio of the cost of current needs divided by the current replacement value (CRV) of the facility. In this report, each building is considered as a separate facility. The chart below presents the industry standard ranges and cut-off points.

| FCI Ranges and Description | |
|----------------------------|---|
| 0 – 5% | In new or well-maintained condition, with little or no visual evidence of wear or |
| 5 – 10% | Subjected to wear but is still in a serviceable and functioning condition. |
| 10 – 30% | Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life. |
| 30% and above | Has reached the end of its useful or serviceable life. Renewal is now necessary. |

The deficiencies and lifecycle needs identified in this assessment provide the basis for a portfolio-wide capital improvement funding strategy. In addition to the current FCI, extended FCI’s have been developed to provide owners the intelligence needed to plan and budget for the “keep-up costs” for their facilities. As such the 3-year, 5-year, and 10-year FCI’s are calculated by dividing the anticipated needs of those respective time periods by current replacement value. As a final point, the FCI’s ultimately provide more value when used to compare facilities across a portfolio instead of being over-analyzed and scrutinized as stand-alone mathematical values. The table below presents the current, 3-year, 5-year, and 10-year FCI’s for each facility:

| FCI Analysis Mary Munford Elementary School / Main Building(1950) | | | |
|---|------------------|---------|--------------|
| Replacement Value | Total SF | Cost/SF | |
| \$ 25,787,200 • | 64,468 | \$ 400 | |
| | Est Reserve Cost | | FCI |
| Current | \$ 2,000 | | 0.0 % |
| 3-Year | \$ 1,357,500 | | 5.3 % |
| 5-Year | \$ 3,074,300 | | 11.9 % |
| 10-Year | \$ 6,080,000 | | 23.6 % |



Immediate Needs

| Facility/Building | Total Items | Total Cost |
|--|-------------|----------------|
| Mary Munford Elementary School / Main Building | 2 | \$2,000 |
| Total | 2 | \$2,000 |

Main Building

| ID | Location Description | UF Code | Description | Condition | Plan Type | Cost |
|------------------------|----------------------|---------|---|-----------|---------------|----------------|
| 7472826 | Throughout building | Y1030 | ADA Entrances & Doors, Door Closer, To Less than 5 LB, Modify | NA | Accessibility | \$1,000 |
| 7472827 | Restrooms | Y1050 | ADA Restrooms, Lavatory, Pipe Wraps/Insulation, Install | NA | Accessibility | \$1,000 |
| Total (2 items) | | | | | | \$2,000 |



Key Findings



Roofing in Poor condition.

Built-Up
Main Building Mary Munford Elementary
School Classroom wing

Uniformat Code: B3010
Recommendation: **Replace in 2026**

Priority Score: **88.7**

Plan Type:
Performance/Integrity

Cost Estimate: \$348,600

\$\$\$\$

Roof system is very old and plagued with recurring leaks. - AssetCALC ID: 7568491



Basement Wall in Poor condition.

any type, Epoxy Injection of Cracks
Main Building Mary Munford Elementary
School Boiler room

Uniformat Code: A2010
Recommendation: **Repair in 2025**

Priority Score: **86.8**

Plan Type:
Performance/Integrity

Cost Estimate: \$3,400

\$\$\$\$

Settlement cracks in brick wall require repair in basement boiler room. - AssetCALC ID: 7438976



Sidewalk in Poor condition.

Concrete, Small Areas/Sections
Site Mary Munford Elementary School Site

Uniformat Code: G2030
Recommendation: **Replace in 2026**

Priority Score: **85.7**

Plan Type:
Performance/Integrity

Cost Estimate: \$4,200

\$\$\$\$

Damaged and ware to concrete pavers - AssetCALC ID: 7442421



Parking Lots in Poor condition.

Pavement, Asphalt
Site Mary Munford Elementary School Site

Uniformat Code: G2020
Recommendation: **Seal & Stripe in 2025**

Priority Score: **84.8**

Plan Type:
Performance/Integrity

Cost Estimate: \$6,200

\$\$\$\$

Paint is fading, striping needed - AssetCALC ID: 7426991





Suspended Ceilings in Poor condition.

Hard Tile, Replacement w/ ACT
Main Building Mary Munford Elementary School Throughout building

Uniformat Code: C1070
Recommendation: **Replace in 2025**

Priority Score: **81.8**
Plan Type:
Performance/Integrity
Cost Estimate: \$2,800

\$\$\$\$

Missing tiles - AssetCALC ID: 7472825



Suspended Ceilings in Poor condition.

Hard Tile, Replacement w/ ACT
Site Mary Munford Elementary School Throughout building

Uniformat Code: C1070
Recommendation: **Replace in 2025**

Priority Score: **81.8**
Plan Type:
Performance/Integrity
Cost Estimate: \$800

\$\$\$\$

Missing ceiling tiles - AssetCALC ID: 7442418



ADA Restrooms

Lavatory, Pipe Wraps/Insulation
Main Building Mary Munford Elementary School Restrooms

Uniformat Code: Y1050
Recommendation: **Install in 2024**

Priority Score: **63.9**
Plan Type: Accessibility
Cost Estimate: \$1,000

\$\$\$\$

Piping insulation missing - AssetCALC ID: 7472827



ADA Entrances & Doors

Door Closer, To Less than 5 LB
Main Building Mary Munford Elementary School Throughout building

Uniformat Code: Y1030
Recommendation: **Modify in 2024**

Priority Score: **63.9**
Plan Type: Accessibility
Cost Estimate: \$1,000

\$\$\$\$

Several aged doors requiring heavier forced and closer issues - AssetCALC ID: 7472826


Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance and highest on the list below.

Plan Type Descriptions

| | | |
|------------------------------|---|---|
| Safety | ■ | An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk. |
| Performance/Integrity | ■ | Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability. |
| Accessibility | ■ | Does not meet ADA, UFAS, and/or other accessibility requirements. |
| Environmental | ■ | Improvements to air or water quality, including removal of hazardous materials from the building or site. |
| Retrofit/Adaptation | ■ | Components, systems, or spaces recommended for upgrades in in order to meet current standards, facility usage, or client/occupant needs. |
| Lifecycle/Renewal | ■ | Any component or system that is neither deficient nor aged past EUL but for which future replacement or repair is anticipated and budgeted. |

Plan Type Distribution (by Cost)



10-YEAR TOTAL: \$6,469,200



2. Building Information



| Building Systems Summary | | |
|------------------------------|---|------------------|
| Address | 211 Westmoreland Avenue, Richmond, VA 23226 | |
| Constructed/Renovated | 1950 | |
| Building Area | 64,468 SF | |
| Number of Stories | 2 stories above grade | |
| <i>System</i> | <i>Description</i> | <i>Condition</i> |
| Structure | Masonry bearing walls with steel frame with wood, and concrete-topped metal decks and cast-in-place floors over concrete pad column footings | Fair |
| Façade | Primary Wall Finish: Brick, Secondary Wall Finish: CMU, Concrete integral to superstructure Windows: Aluminum | Fair |
| Roof | Primary: Flat construction built-up finish | Fair |
| Interiors | Walls: Painted gypsum board, ceramic tile Floors: terrazzo, quarry tile, VCT, ceramic tile Ceilings: Painted gypsum board, ACT | Fair |
| Elevators | Passenger: One hydraulic car serving all floors | Good |
| Plumbing | Distribution: Copper supply and cast-iron waste & venting Hot Water: Gas Water Heaters with integral tanks Fixtures: Toilets, urinals, and sinks in all restrooms | Fair |
| HVAC | Central System: Boilers feeding hydronic baseboard radiators Non-Central System: Split-system packaged units, unit heaters | Fair |

| Building Systems Summary | | |
|---------------------------------|--|------|
| Fire Suppression | Dry-pipe sprinkler system and fire extinguishers | Fair |
| Electrical | Source & Distribution: Main switchboard with copper wiring. Interior Lighting: LED, linear fluorescent, CFL, halogen Exterior Building-Mounted Lighting: LED, halogen Emergency Power: Diesel generator | Fair |
| Fire Alarm | Alarm panel with smoke detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs. | Fair |
| Equipment/Special | Commercial kitchen equipment | Fair |
| Accessibility | Potential moderate/major issues have been identified at this building and a detailed accessibility study is recommended. See the appendix for associated photos and additional information. | |
| Additional Studies | No additional studies are currently recommended for the building. | |
| Areas Observed | The interior spaces were observed to gain a clear understanding of the facility's overall condition. Other areas accessed and assessed included the exterior equipment and assets directly serving the buildings, the exterior walls of the facility, and the roofs. | |
| Key Spaces Not Observed | All key areas of the facility were accessible and observed | |



The table below shows the anticipated costs by trade or building system over the next 20 years.

| System Expenditure Forecast | | | | | | |
|------------------------------------|------------------|--------------------------------|-------------------------------|-------------------------------|---------------------------------|---------------------|
| System | Immediate | Short Term (1-2 yr) | Near Term (3-5 yr) | Med Term (6-10 yr) | Long Term (11-20 yr) | TOTAL |
| Structure | - | \$3,500 | - | - | \$3,497,700 | \$3,501,200 |
| Facade | - | - | \$141,400 | \$29,400 | \$1,347,900 | \$1,518,700 |
| Roofing | - | \$739,700 | \$1,500 | \$705,100 | - | \$1,446,200 |
| Interiors | - | \$2,900 | \$1,489,000 | \$753,500 | \$1,532,800 | \$3,778,200 |
| Conveying | - | - | - | \$12,100 | - | \$12,100 |
| Plumbing | - | - | \$53,900 | \$12,400 | \$1,226,300 | \$1,292,600 |
| HVAC | - | \$274,100 | \$7,500 | \$413,000 | \$1,077,900 | \$1,772,400 |
| Fire Protection | - | - | - | \$12,200 | \$487,600 | \$499,700 |
| Electrical | - | - | \$4,800 | \$437,400 | \$300,300 | \$742,500 |
| Fire Alarm & Electronic Systems | - | - | \$333,000 | \$146,600 | \$189,300 | \$669,000 |
| Equipment & Furnishings | - | - | \$21,100 | \$484,100 | \$83,000 | \$588,200 |
| Accessibility | \$2,000 | - | - | - | - | \$2,000 |
| TOTALS (3% inflation) | \$2,000 | \$1,020,100 | \$2,052,200 | \$3,005,600 | \$9,742,800 | \$15,822,700 |

NEEDS OVER TIME: The vertical blue bars in the graphic below represent the year-by-year needs identified for the facility. The orange line forecasts what would happen to the FCI (left Y axis) over time, assuming zero capital expenditures over the next ten years. The dollar amounts allocated for each year are associated with the values along the right Y axis.


Needs by Year with Unaddressed FCI Over Time

FCI Analysis: Mary Munford Elementary School Main Building

Replacement Value: \$25,787,200

Inflation Rate: 3.0%

Average Needs per Year: \$552,800



Main Building: Photographic Overview



1 - Front Elevation



2 - Left Elevation



3 - Right Elevation



4 - Rear Elevation




5 – Façade Overview



6 - Roof Overview



7 - Main entrance



8 - Lobby




9 - Main Office



10 - Library



11 - Typical Classroom



12 - Auditorium



13 - Staff Lounge



14 - Cafeteria



15 - Kitchen



16 - Restroom Fixtures



17 - Water heaters



18 - HVAC, Boilers



19 - HVAC, Rooftop Unit



20 - HVAC, Split system units



21 - Fire Alarm Panel



22 - Main Electrical Panel



23 - Emergency Generator



24 - Elevator

3. Site Summary



| Site Information | | |
|-----------------------------------|--|------------------|
| Site Area | 11.5 acres (estimated) | |
| Parking Spaces | 43 total spaces all in open lots; 3 of which are accessible | |
| <i>System</i> | <i>Description</i> | <i>Condition</i> |
| Pavement/Flatwork | Asphalt lots with limited areas of concrete aprons and pavement and adjacent concrete sidewalks, curbs, ramps, and stairs | Fair |
| Site Development | Building-mounted signage; dumpster enclosures, and site lights Playgrounds and sports fields Heavily furnished with park benches, picnic tables, trash receptacles | Fair |
| Landscaping and Topography | Limited landscaping features including lawns, trees, bushes, and planters. Irrigation present Low to moderate site slopes throughout | Fair |
| Utilities | Municipal water and sewer Local utility-provided electric and natural gas | Fair |
| Site Lighting | Pole-mounted: HPS, and metal halide | Fair |
| Ancillary Structures | Storage sheds, pavilion, and wood deck | Fair |
| Site Accessibility | Presently it does not appear an accessibility study is needed for the exterior site areas. See the appendix for associated photos and additional information. | |

| Site Information | |
|-------------------------------------|--|
| Site Additional Studies | No additional studies are currently recommended for the exterior site areas. |
| Site Areas Observed | The exterior areas within the property boundaries were observed to gain a clear understanding of the site’s overall condition. |
| Site Key Spaces Not Observed | All key areas of the exterior site were accessible and observed. |

The table below shows the anticipated costs by trade or site system over the next 20 years.

| System Expenditure Forecast | | | | | | |
|------------------------------|-----------|------------------------|-----------------------|-----------------------|-------------------------|--------------------|
| System | Immediate | Short Term (1-2 yr) | Near Term (3-5 yr) | Med Term (6-10 yr) | Long Term (11-20 yr) | TOTAL |
| Structure | - | - | - | \$2,000 | \$2,700 | \$4,700 |
| Interiors | - | \$800 | - | - | - | \$800 |
| Special Construction & Demo | - | - | - | \$126,100 | \$190,400 | \$316,400 |
| Site Development | - | \$9,000 | \$9,800 | \$53,700 | \$603,400 | \$675,900 |
| Site Pavement | - | \$10,800 | \$52,400 | \$7,400 | \$30,300 | \$100,800 |
| Site Utilities | - | - | \$117,100 | - | - | \$117,100 |
| TOTALS (3% inflation) | - | \$20,600 | \$179,200 | \$189,200 | \$826,800 | \$1,215,800 |



Site: Photographic Overview



1 - SITE, OVERVIEWS



2 - SITE, WALKWAYS



3 - SITE, PARKING AREA



4 - SITE, PLAY SURFACES



5 - SITE, SIGNAGE



6 - SITE, PLAYGROUND

4. ADA Accessibility

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of “areas of public accommodations” and “public facilities” on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

A public entity (i.e. city governments) shall operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities.

However, this does not:

1. Necessarily require a public entity to make each of its existing facilities accessible to and usable by individuals with disabilities;
2. Require a public entity to take any action that would threaten or destroy the historic significance of an historic property; or
3. Require a public entity to take any action that it can demonstrate would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens. In those circumstances where personnel of the public entity believe that the proposed action would fundamentally alter the service, program, or activity or would result in undue financial and administrative burdens, a public entity has the burden of proving that compliance with 35.150(a) of this part would result in such alteration or burdens. The decision that compliance would result in such alteration or burdens must be made by the head of a public entity or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity, and must be accompanied by a written statement of the reasons for reaching that conclusion. If an action would result in such an alteration or such burdens, a public entity shall take any other action that would not result in such an alteration or such burdens but would nevertheless ensure that individuals with disabilities receive the benefits or services provided by the public entity.

Removal of barriers to accessibility should be addressed from a liability standpoint in order to comply with federal law, but the barriers may or may not be building code violations. The Americans with Disabilities Act Accessibility Guidelines are part of the ADA federal civil rights law pertaining to the disabled and are not a construction code. State and local jurisdictions have adopted the ADA Guidelines or have adopted other standards for accessibility as part of their construction codes.

During the FCA, Bureau Veritas performed a limited high-level accessibility review of the facility non-specific to any local regulations or codes. The scope of the visual observation was limited to the same areas observed while performing the FCA and the categories set forth in the material included in the appendix. It is understood by the Client that the limited observations described herein do not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of this assessment. A full measured ADA survey would be required to identify more specific potential accessibility issues. Additional clarifications of this limited survey:

- This survey was visual in nature and actual measurements were not taken to verify compliance
- Only a representative sample of areas was observed
- Two overview photos were taken for each subsection regardless of perceived compliance or non-compliance
- Itemized costs for individual non-compliant items are included in the dataset
- For any “none” boxes checked or reference to “no issues” identified, that alone does not guarantee full compliance

A detailed follow-up accessibility study is included as a recommendation because potential moderate to major issues were observed at the subject site. Reference the appendix for specific data, photos, and tables or checklists associated with this limited accessibility survey.



5. Purpose and Scope

Purpose

Bureau Veritas was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

| Condition Ratings | |
|-----------------------|---|
| Excellent | New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service. |
| Good | Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service. |
| Fair | Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life. |
| Poor | Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life. |
| Failed | Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required. |
| Not Applicable | Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present. |

Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include a review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.



6. Opinions of Probable Costs

Cost estimates are attached throughout this report, with the Replacement Reserves in the appendix.

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means*, *CBRE Whitestone*, and *Marshall & Swift*, Bureau Veritas's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, Bureau Veritas opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its *effective age*, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of Bureau Veritas's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.



Definitions

Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with *Safety or Performance/Integrity* Plan Types, are considered Immediate Needs.

Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, Bureau Veritas's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

Bureau Veritas's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system or component replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.

7. Certification

Richmond Public Schools (the Client) retained Bureau Veritas to perform this Facility Condition Assessment in connection with its continued operation of Mary Munford Elementary School, 211 Westmoreland Avenue, Richmond, VA 23226, the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.


No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared for and is exclusively for the use and benefit of the Client identified on the cover page of this report. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and Bureau Veritas.

This report, or any of the information contained therein, is not for the use or benefit of, nor may it be relied upon by any other person or entity, for any purpose without the advance written consent of Bureau Veritas. Any reuse or distribution without such consent shall be at the client's or recipient's sole risk, without liability to Bureau Veritas.

Prepared by: Soulihe Nida,
Project Manager

Reviewed by:



Daniel White,
Technical Report Reviewer for
Bill Champion,
Program Manager
bill.champion@bureauveritas.com
800.733.0660 x7296234



8. Appendices

- Appendix A: Site Plan(s)
- Appendix B: Pre-Survey Questionnaire(s)
- Appendix C: Accessibility Review and Photos
- Appendix D: Component Condition Report
- Appendix E: Replacement Reserves
- Appendix F: Equipment Inventory List





Appendix A:

Site Plan(s)

Site Plan



| | | | |
|--|-----------------------|--------------------------------|---|
|  BUREAU VERITAS | Project Number | Project Name |  |
| | 166385.24R000-018.468 | Mary Munford Elementary School | |
| | Source | On-Site Date | |
| | Google | March 11, 2024 | |

Appendix B:

Pre-Survey Questionnaire(s)

Bureau Veritas Facility Condition Assessment: Pre-Survey Questionnaire

Building / Facility Name: Mary Munford Elementary School

Name of person completing form: Ronald Hathaway

Title / Association with property: Director of Facilities

Length of time associated w/ property: 30

Date Completed: 3/4/2024

Phone Number: 804-325-0740

Method of Completion: Electronic

Directions: Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses.

| Data Overview | | Response | | |
|---------------|--|---|------|--|
| 1 | Year/s constructed / renovated | 1950 | | |
| 2 | Building size in SF | 64468 | | |
| 3 | Major Renovation/Rehabilitation | | Year | Additional Detail |
| | | Façade | | Brick |
| | | Roof | | Tar and Gravel |
| | | Interiors | | CMU, VAT, VCT, Terrazzo, Glued tile, and some drop ceiling |
| | | HVAC | | Steam boilers, Mini split air conditioning |
| | | Electrical | | Original |
| | | Site Pavement | | Asphalt |
| | | Accessibility | 2007 | Satisfied the 2007 lawsuit requirement |
| Question | | Response | | |
| 4 | List other significant capital improvements (focus on recent years; provide approximate date). | Replaced air conditioning for the Auditorium, Replaced roof on kindergarten wing and kitchen and cafeteria. | | |
| 5 | List any major capital expenditures planned/requested for the next few years. Have they been budgeted? | Eliminate pneumatic controls, replace mini splits, replace generator, upgrade BAS no funding. | | |
| 6 | Describe any on-going extremely problematic, historically chronic, or immediate facility needs. | Reoccurring roof leaks in the older roofing | | |

| Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any Yes responses. (NA indicates "Not Applicable", Unk indicates "Unknown") | | | | | | |
|--|---|----------|----|-----|----|---|
| Question | | Response | | | | Comments |
| | | Yes | No | Unk | NA | |
| 7 | Are there any problems with foundations or structures, like excessive settlement? | | X | | | |
| 8 | Are there any wall, window, basement or roof leaks? | | X | | | |
| 9 | Has any part of the facility ever contained visible suspect mold growth, or have there been any indoor air quality or mold related complaints from occupants? | X | | | | Ceiling tiles roof leaks and air conditioning leaks |
| 10 | Are your elevators unreliable, with frequent service calls? | | X | | | |
| 11 | Are there any plumbing leaks, water pressure, or clogging/back-up problems? | | X | | | |
| 12 | Have there been any leaks or pressure problems with natural gas, HVAC supply/return lines, or steam service? | | X | | | |
| 13 | Are any areas of the facility inadequately heated, cooled or ventilated? Any poorly insulated areas? | X | | | | Hallways, windows leak |
| 14 | Is the electrical service outdated, undersized, or otherwise problematic? | | | X | | |
| 15 | Are there any problems or inadequacies with exterior lighting? | X | | | | |
| 16 | Is site/parking drainage inadequate, with excessive ponding or other problems? | | X | | | |
| 17 | Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified above? | | X | | | |
| 18 | ADA: Has an accessibility study been performed at the site? If so, indicate when. | X | | | | |
| 19 | ADA: If a study has occurred, have the associated recommendations been addressed? In full or in part? | X | | | | Satisfied the 2007 lawsuit requirement |
| 20 | ADA: Have there been regular complaints about accessibility issues, or associated previous or pending litigation? | | X | | | |

Appendix C: Accessibility Review and Photos

Visual Checklist - 2010 ADA Standards for Accessible Design

Property Name: Mary Munford Elementary School

BV Project Number: 166385.24R000-018.468

Abbreviated Accessibility Checklist

Facility History & Interview

| Question | | Yes | No | Unk | Comments |
|----------|--|-----|----|-----|--|
| 1 | Has an accessibility study been previously performed? If so, when? | X | | | |
| 2 | Have any ADA improvements been made to the property since original construction? Describe. | X | | | Satisfied the 2007 lawsuit requirement |
| 3 | Has building management reported any accessibility-based complaints or litigation? | | X | | |

Abbreviated Accessibility Checklist

Parking



OVERVIEW OF ACCESSIBLE PARKING AREA



OVERVIEW OF ACCESSIBLE PARKING AREA

| Question | | Yes | No | NA | Comments |
|----------|---|-----|----|----|--|
| 1 | Does the required number of standard ADA designated spaces appear to be provided ? | ✗ | | | Stall lanes and access aisles prevent need re-striping for enhanced visibility |
| 2 | Does the required number of van-accessible designated spaces appear to be provided ? | ✗ | | | |
| 3 | Are accessible spaces on the shortest accessible route to an accessible building entrance ? | ✗ | | | |
| 4 | Does parking signage include the International Symbol of Accessibility ? | ✗ | | | |
| 5 | Does each accessible space have an adjacent access aisle ? | ✗ | | | |
| 6 | Do parking spaces and access aisles appear to be relatively level and without obstruction ? | ✗ | | | |

Abbreviated Accessibility Checklist

Exterior Accessible Route



ACCESSIBLE RAMP



ACCESSIBLE PATH

| Question | | Yes | No | NA | Comments |
|----------|--|-----|----|----|----------|
| 1 | Is an accessible route present from public transportation stops and municipal sidewalks on or immediately adjacent to the property ? | ✗ | | | |
| 2 | Does a minimum of one accessible route appear to connect all public areas on the exterior, such as parking and other outdoor amenities, to accessible building entrances ? | ✗ | | | |
| 3 | Are curb ramps present at transitions through raised curbs on all accessible routes? | ✗ | | | |
| 4 | Do curb ramps appear to have compliant slopes for all components ? | ✗ | | | |
| 5 | Do ramp runs on an accessible route appear to have compliant slopes ? | ✗ | | | |
| 6 | Do ramp runs on an accessible route appear to have a compliant rise and width ? | ✗ | | | |

| | | | | | |
|---|---|---|--|--|--|
| 7 | Do ramps on an accessible route appear to have compliant end and intermediate landings ? | X | | | |
| 8 | Do ramps and stairs on an accessible route appear to have compliant handrails? | X | | | |
| 9 | For stairways that are open underneath, are permanent barriers present that prevent or discourage access? | X | | | |

Abbreviated Accessibility Checklist

Building Entrances



MAIN ENTRANCE



ADDITIONAL ENTRANCE

| Question | | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1 | Do a sufficient number of accessible entrances appear to be provided ? | ✗ | | | |
| 2 | If the main entrance is not accessible, is an alternate accessible entrance provided? | ✗ | | | |
| 3 | Is signage provided indicating the location of alternate accessible entrances ? | | | ✗ | |
| 4 | Do doors at accessible entrances appear to have compliant maneuvering clearance area on each side ? | ✗ | | | |
| 5 | Do doors at accessible entrances appear to have compliant hardware ? | ✗ | | | |
| 6 | Do doors at accessible entrances appear to have a compliant clear opening width ? | ✗ | | | |

| | | | | | |
|---|---|---|--|--|--|
| 7 | Do pairs of accessible entrance doors in series appear to have the minimum clear space between them ? | X | | | |
| 8 | Do thresholds at accessible entrances appear to have a compliant height ? | X | | | |

Abbreviated Accessibility Checklist

Interior Accessible Route



ACCESSIBLE INTERIOR PATH



STAIR RAILS

| Question | | Yes | No | NA | Comments |
|----------|--|-----|----|----|----------|
| 1 | Does an accessible route appear to connect all public areas inside the building ? | X | | | |
| 2 | Do accessible routes appear free of obstructions and/or protruding objects ? | X | | | |
| 3 | Do ramps on accessible routes appear to have compliant slopes ? | | | X | |
| 4 | Do ramp runs on an accessible route appear to have a compliant rise and width ? | | | X | |
| 5 | Do ramps on accessible routes appear to have compliant end and intermediate landings ? | | | X | |
| 6 | Do ramps on accessible routes appear to have compliant handrails ? | | | X | |

| | | | | | |
|----|---|---|---|---|---|
| 7 | Are accessible areas of refuge and the accessible means of egress to those areas identified with accessible signage ? | X | | | |
| 8 | Do public transaction areas have an accessible, lowered service counter section ? | X | | | |
| 9 | Do public telephones appear mounted with an accessible height and location ? | | | X | |
| 10 | Do doors at interior accessible routes appear to have compliant maneuvering clearance area on each side ? | X | | | |
| 11 | Do doors at interior accessible routes appear to have compliant hardware ? | X | | | |
| 12 | Do non-fire hinged, sliding, or folding doors on interior accessible routes appear to have compliant opening force ? | | X | | Several aged doors requiring heavier forced and closer issues |
| 13 | Do doors on interior accessible routes appear to have a compliant clear opening width ? | X | | | |

Abbreviated Accessibility Checklist

Elevators



LOBBY LOOKING AT CABS



EMERGENCY CALL PANEL

| Question | | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1 | Are hallway call buttons configured with the "UP" button above the "DOWN" button? | ✗ | | | |
| 2 | Is accessible floor identification signage present on the hoistway sidewalls on each level ? | ✗ | | | |
| 3 | Do the elevators have audible and visual arrival indicators at the lobby and hallway entrances? | ✗ | | | |
| 4 | Do the elevator hoistway and car interior appear to have a minimum compliant clear floor area ? | ✗ | | | |
| 5 | Do the elevator car doors have automatic re-opening devices to prevent closure on obstructions? | ✗ | | | |
| 6 | Do elevator car control buttons appear to be mounted at a compliant height ? | ✗ | | | |

| | | | | | |
|---|--|---|--|--|--|
| 7 | Are tactile and Braille characters mounted to the left of each elevator car control button ? | X | | | |
| 8 | Are audible and visual floor position indicators provided in the elevator car? | X | | | |
| 9 | Is the emergency call system on or adjacent to the control panel and does it not require voice communication ? | X | | | |

Abbreviated Accessibility Checklist

Public Restrooms



TOILET STALL OVERVIEW



SINK, FAUCET HANDLES AND ACCESSORIES

| Question | | Yes | No | NA | Comments |
|----------|---|-----|----|----|---------------------------|
| 1 | Do publicly accessible toilet rooms appear to have a minimum compliant floor area ? | ✗ | | | |
| 2 | Does the lavatory appear to be mounted at a compliant height and with compliant knee area ? | ✗ | | | |
| 3 | Does the lavatory faucet have compliant handles ? | ✗ | | | |
| 4 | Is the plumbing piping under lavatories configured to protect against contact ? | | ✗ | | Piping insulation missing |
| 5 | Are grab bars provided at compliant locations around the toilet ? | ✗ | | | |
| 6 | Do toilet stall doors appear to provide the minimum compliant clear width ? | ✗ | | | |

| | | | | | |
|---|--|---|--|--|--|
| 7 | Do toilet stalls appear to provide the minimum compliant clear floor area ? | X | | | |
| 8 | Where more than one urinal is present in a multi-user restroom, does minimum one urinal appear to be mounted at a compliant height and with compliant approach width ? | X | | | |
| 9 | Do accessories and mirrors appear to be mounted at a compliant height ? | X | | | |

Abbreviated Accessibility Checklist

Playgrounds & Swimming Pools



OVERVIEW OF PLAYGROUND



ACCESSIBLE ROUTE TO PLAYGROUND

| Question | | Yes | No | NA | Comments |
|----------|---|-----|----|----|----------|
| 1 | Is there an accessible route to the play area / s? | ✘ | | | |
| 2 | Has the play area been reviewed for accessibility ? | ✘ | | | |
| 3 | Are publicly accessible swimming pools equipped with an entrance lift ? | | | ✘ | |

Appendix D:

Component Condition Report



Component Condition Report | Mary Munford Elementary School / Main Building

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|------------------|------------------------------|-----------|---|------------|-----|---------|
| Structure | | | | | | |
| A1010 | Throughout building | Fair | Foundation System, Concrete or CMU Walls w/ Continuous Footings, 1-2 Story Building | 1,580 LF | 19 | 7426878 |
| A2010 | Boiler room | Poor | Basement Wall, any type, Epoxy Injection of Cracks, Repair | 40 LF | 0 | 7438976 |
| B1010 | Main building | Fair | Structural Framing, Masonry (CMU) Bearing Walls | 64,468 SF | 19 | 7568488 |
| Facade | | | | | | |
| B2010 | Building Exterior | Fair | Exterior Walls, Concrete | 2,200 SF | 19 | 7426880 |
| B2010 | Building Exterior | Fair | Exterior Walls, Brick | 13,300 SF | 19 | 7426879 |
| B2020 | Building Exterior | Fair | Window, Aluminum Double-Glazed, 16-25 SF | 120 | 4 | 7426882 |
| B2050 | Building Exterior | Fair | Exterior Door, Wood, Solid-Core Decorative High-End | 8 | 3 | 7438942 |
| B2050 | Building Exterior | Fair | Exterior Door, Aluminum-Framed & Glazed, Standard Swing | 16 | 8 | 7426885 |
| B2050 | Building Exterior | Fair | Exterior Door, Steel, Standard | 4 | 8 | 7426884 |
| Roofing | | | | | | |
| B3010 | Classroom wing | Poor | Roofing, Built-Up | 24,900 SF | 2 | 7568491 |
| B3010 | Kindergarten/Cafeteria roofs | Fair | Roofing, Built-Up | 19,300 SF | 9 | 7426887 |
| B3060 | Roof | Fair | Roof Hatch, Metal | 1 | 4 | 7426886 |
| Interiors | | | | | | |
| C1030 | Throughout building | Fair | Interior Door, Wood, Solid-Core | 21 | 7 | 7426890 |
| C1030 | Throughout building | Fair | Interior Door, Wood, Solid-Core | 60 | 14 | 7438959 |
| C1030 | Throughout building | Fair | Door Hardware, School, per Door | 60 | 8 | 7426891 |
| C1070 | Throughout building | Poor | Suspended Ceilings, Hard Tile, Replacement w/ ACT | 800 SF | 1 | 7472825 |
| C1070 | Throughout building | Fair | Suspended Ceilings, Acoustical Tile (ACT) | 46,268 SF | 10 | 7426892 |
| C1070 | Throughout building | Fair | Suspended Ceilings, Hard Tile, ACM Abatement & Replacement w/ ACT | 17,400 SF | 5 | 7426901 |
| C1090 | Restrooms | Fair | Toilet Partitions, Plastic/Laminate | 16 | 10 | 7426893 |
| C2010 | Throughout building | Fair | Wall Finishes, any surface, Prep & Paint | 132,238 SF | 4 | 7426895 |
| C2010 | Restrooms | Fair | Wall Finishes, Ceramic Tile | 840 SF | 14 | 7438931 |
| C2010 | Restrooms | Fair | Wall Finishes, Ceramic Tile | 1,950 SF | 14 | 7426894 |
| C2030 | Throughout building | Fair | Flooring, Vinyl Tile (VCT) | 38,000 SF | 5 | 7438958 |
| C2030 | Restrooms | Fair | Flooring, Ceramic Tile | 2,500 SF | 14 | 7426897 |
| C2030 | Throughout building | Fair | Flooring, Vinyl Tile (VCT), w/ Asbestos Abatement, Repair | 38,000 SF | 3 | 7438968 |
| C2030 | Classrooms | Fair | Flooring, Carpet, Commercial Standard | 29,000 SF | 5 | 7426899 |
| C2030 | Throughout building | Fair | Flooring, Terrazzo | 25,800 SF | 9 | 7438970 |
| C2030 | Cafeteria | Fair | Flooring, Quarry Tile | 3,000 SF | 24 | 7426896 |
| C2030 | Throughout building | Fair | Flooring, Vinyl Tile (VCT) | 38,000 SF | 5 | 7426898 |
| Conveying | | | | | | |
| D1010 | Elevator Machine Room | Good | Passenger Elevator, Hydraulic, 2 Floors, 1500 to 2500 LB, Renovate [Car 1] | 1 | 25 | 7426903 |
| D1010 | Elevator | Good | Elevator Cab Finishes, Standard | 1 | 10 | 7426902 |
| Plumbing | | | | | | |
| D2010 | Kitchen | Fair | Sink/Lavatory, Service Sink, Floor | 30 | 15 | 7438923 |

Component Condition Report | Mary Munford Elementary School / Main Building

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|-------------|---------------------|-----------|--|-----------|-----|---------|
| D2010 | Restrooms | Fair | Toilet, Commercial Water Closet | 24 | 13 | 7426913 |
| D2010 | Boiler room | Fair | Water Heater, Gas, Commercial (200 MBH) | 1 | 13 | 7439004 |
| D2010 | Restrooms | Fair | Sink/Lavatory, Wall-Hung, Vitreous China | 14 | 13 | 7426912 |
| D2010 | Restrooms | Fair | Urinal, Standard | 8 | 3 | 7426910 |
| D2010 | Throughout building | Fair | Plumbing System, Supply & Sanitary, Medium Density (excludes fixtures) | 64,468 SF | 14 | 7426908 |
| D2010 | Boiler room | Fair | Water Heater, Gas, Commercial (200 MBH) | 1 | 4 | 7426905 |
| D2010 | Utility closet | Fair | Sink/Lavatory, Service Sink, Floor | 4 | 10 | 7426915 |
| D2010 | Throughout building | Good | Drinking Fountain, Wall-Mounted, Bi-Level | 4 | 10 | 7426909 |
| D2030 | Boiler room | Fair | Pump, Sump | 1 | 4 | 7438934 |
| D2030 | Boiler room | Fair | Pump, Sump | 1 | 5 | 7438981 |
| D2060 | Boiler room | Fair | Air Compressor, Tank-Style | 1 | 3 | 7438972 |
| D2060 | Boiler room | Fair | Air Compressor, Tank-Style | 1 | 3 | 7438932 |
| HVAC | | | | | | |
| D3020 | Boiler room | Fair | Boiler, Gas, HVAC [Boiler 2] | 1 | 12 | 7426919 |
| D3020 | Boiler room | Fair | Boiler, Gas, HVAC [Boiler 1] | 1 | 13 | 7438943 |
| D3020 | Boiler room | Fair | Boiler Supplemental Components, Chemical Feed System | 1 | 9 | 7438986 |
| D3020 | Kitchen | Fair | HVAC Steam Components, Deaerator | 1 | 15 | 7438920 |
| D3020 | Building entrances | Fair | Radiator, Hydronic, Column/Cabinet Style (per EA) | 1 | 6 | 7438946 |
| D3030 | Site | Good | Split System Ductless, Single Zone, 4-TON | 1 | 12 | 7438925 |
| D3030 | Roof | Good | Split System Ductless, Single Zone, 4 TON | 1 | 13 | 7438928 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438990 |
| D3030 | Site | Good | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 13 | 7438977 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone, 3.5 TON | 1 | 2 | 7438965 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone, 3.5 TON | 1 | 2 | 7438999 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone, 3.5 TON | 1 | 2 | 7438993 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone, 3.5 TON | 1 | 2 | 7438933 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone, 3.5 TON | 1 | 2 | 7438947 |
| D3030 | Site | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438985 |
| D3030 | Site | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438979 |
| D3030 | Site | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438948 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438997 |
| D3030 | Site | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438941 |
| D3030 | Site | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438974 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438917 |
| D3030 | Site | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438996 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438927 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438921 |
| D3030 | Site | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438940 |
| D3030 | Site | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438915 |

Component Condition Report | Mary Munford Elementary School / Main Building

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|--|---------------------|-----------|--|-----------|-----|---------|
| D3030 | Site | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7439002 |
| D3030 | Roof | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438951 |
| D3030 | Site | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438995 |
| D3030 | Classrooms | Fair | Split System, Fan Coil Unit, DX, 3 TON | 27 | 2 | 7438922 |
| D3030 | Roof | Good | Split System Ductless, Single Zone, 4 TON | 1 | 13 | 7438944 |
| D3030 | Site | Fair | Split System Ductless, Single Zone, 2.5 TON | 1 | 2 | 7438994 |
| D3030 | Site | Fair | Split System Ductless, Single Zone, 2.5 to 3 TON | 1 | 2 | 7438939 |
| D3050 | Roof | Good | Packaged Unit, RTU, Pad or Roof-Mounted, 26 to 50 TON | 1 | 17 | 7426931 |
| D3050 | Throughout building | Fair | HVAC System, Ductwork, Medium Density | 64,468 SF | 10 | 7426934 |
| D3050 | Boiler room | Fair | HVAC Steam Components, Steam Trap | 1 | 3 | 7438913 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 36"Damper | 1 | 6 | 7438935 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | 1 | 8 | 7438924 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | 1 | 9 | 7439003 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 36"Damper | 1 | 6 | 7438980 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | 1 | 8 | 7439006 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 36"Damper | 1 | 8 | 7438975 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 36"Damper | 1 | 6 | 7438973 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | 1 | 8 | 7438963 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | 1 | 5 | 7426938 |
| D3060 | Roof | Good | Exhaust Fan, Roof or Wall-Mounted, 16" Damper | 1 | 14 | 7438937 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | 1 | 9 | 7438991 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 16" Damper, 1001 to 2000 CFM | 1 | 4 | 7426939 |
| D3060 | Roof | Fair | Exhaust Fan, Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | 1 | 8 | 7438916 |
| Fire Protection | | | | | | |
| D4010 | Kitchen | Fair | Fire Suppression System, Commercial Kitchen, per LF of Hood | 24 LF | 8 | 7426942 |
| D4010 | Throughout building | Fair | Fire Suppression System, Full System Install/Retrofit, Medium Density/Complexity, Renovate | 64,468 SF | 14 | 7426940 |
| Electrical | | | | | | |
| D5010 | Building exterior | Fair | Generator, Diesel, 35 to 60 KW | 1 | 10 | 7426943 |
| D5010 | Electrical room | Fair | Automatic Transfer Switch, ATS | 1 | 16 | 7426945 |
| D5020 | Electrical room | Fair | Distribution Panel, 120/208 V, 600 AMP | 1 | 12 | 7426952 |
| D5020 | Electrical room | Good | Distribution Panel, 120/208 V [Panel B] | 1 | 24 | 7438969 |
| D5030 | Throughout building | Fair | Electrical System, Wiring & Switches, Average or Low Density/Complexity | 64,468 SF | 14 | 7426953 |
| D5040 | Throughout building | Fair | Emergency & Exit Lighting, Exit Sign, LED | 20 | 3 | 7426955 |
| D5040 | Throughout building | Fair | Interior Lighting System, Full Upgrade, Medium Density & Standard Fixtures | 64,468 SF | 8 | 7426954 |
| D5040 | Building Exterior | Fair | Exterior Fixture w/ Lamp, any type, w/ LED Replacement, 250 W | 20 | 10 | 7426985 |
| Fire Alarm & Electronic Systems | | | | | | |
| D6020 | Throughout building | Fair | Low Voltage System, Facility-Wide, Phone & Data Lines | 64,468 SF | 4 | 7426956 |
| D6060 | Throughout building | Fair | Intercom/PA System, Public Address Upgrade, Facility-Wide | 64,468 SF | 6 | 7426957 |
| D7030 | Throughout building | Good | Security/Surveillance System, Full System Upgrade, Average Density | 64,468 SF | 13 | 7426958 |

Component Condition Report | Mary Munford Elementary School / Main Building

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|------------------------------------|---------------------|-----------|---|-----------|-----|---------|
| D7050 | Throughout building | Fair | Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install | 64,468 SF | 5 | 7426959 |
| D7050 | Office | Fair | Fire Alarm Panel, Fully Addressable | 1 | 9 | 7438949 |
| Equipment & Furnishings | | | | | | |
| E1030 | Kitchen | Fair | Foodservice Equipment, Prep Table Refrigerated, Salad/Sandwich | 1 | 6 | 7426967 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Refrigerator, 2-Door Reach-In [PTA] | 1 | 8 | 7439000 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Steamer, Tabletop | 1 | 4 | 7438945 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Prep Table Refrigerated, Salad/Sandwich [7] | 1 | 9 | 7426961 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Dairy Cooler/Wells | 1 | 6 | 7426978 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels [A] | 1 | 6 | 7426977 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Refrigerator, 2-Door Reach-In [1] | 1 | 10 | 7426960 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Refrigerator, 2-Door Reach-In [3] | 1 | 5 | 7426974 |
| E1030 | Kitchen | Good | Foodservice Equipment, Freezer, Chest [PTA] | 1 | 12 | 7439001 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Convection Oven, Double | 1 | 6 | 7426966 |
| E1030 | Kitchen | Fair | Sink/Lavatory, Commercial Kitchen, 2-Bowl | 1 | 11 | 7426916 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Dairy Cooler/Wells | 1 | 6 | 7438983 |
| E1030 | Kitchen | Fair | Sink/Lavatory, Commercial Kitchen, 3-Bowl | 1 | 11 | 7426914 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Mixer, Freestanding | 1 | 8 | 7426964 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Exhaust Hood, 8 to 10 LF | 1 | 6 | 7426963 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels | 1 | 6 | 7426971 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Steam Kettle [E] | 1 | 7 | 7426979 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Steamer, Tabletop | 1 | 4 | 7426969 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Refrigerator, 2-Door Reach-In [2] | 1 | 9 | 7438989 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Dairy Cooler/Wells | 1 | 6 | 7438918 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Convection Oven, Single [A*] | 1 | 7 | 7438978 |
| E1030 | Kitchen | Good | Foodservice Equipment, Freezer, Chest [PTA] | 1 | 12 | 7426975 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Refrigerator, 2-Door Reach-In [4] | 1 | 9 | 7426972 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Freezer, 2-Door Reach-In [2] | 1 | 7 | 7426976 |
| E1030 | Kitchen | Fair | Foodservice Equipment, Convection Oven, Single [B] | 1 | 6 | 7426970 |
| E1040 | Utility closet | Good | Ceramics Equipment, Kiln | 1 | 18 | 7426981 |
| E1040 | Throughout building | Good | Healthcare Equipment, Defibrillator (AED), Cabinet-Mounted | 1 | 7 | 7426982 |
| E2010 | Throughout building | Fair | Casework, Countertop, Plastic Laminate | 1,200 LF | 7 | 7426983 |
| E2010 | Throughout building | Fair | Casework, Cabinetry, Economy | 1,200 LF | 8 | 7426984 |
| Accessibility | | | | | | |
| Y1030 | Throughout building | NA | ADA Entrances & Doors, Door Closer, To Less than 5 LB, Modify | 8 | 0 | 7472826 |
| Y1050 | Restrooms | NA | ADA Restrooms, Lavatory, Pipe Wraps/Insulation, Install | 1 | 0 | 7472827 |

Component Condition Report | Mary Munford Elementary School / Site

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|------------------|----------|-----------|-----------------------------------|----------|-----|---------|
| Structure | | | | | | |
| B1080 | Site | Fair | Stair/Ramp Rails, Metal, Refinish | 1,120 LF | 6 | 7426987 |

Component Condition Report | Mary Munford Elementary School / Site

| UF L3 Code | Location | Condition | Asset/Component/Repair | Quantity | RUL | ID |
|---|---------------------|-----------|---|-----------|-----|---------|
| Interiors | | | | | | |
| C1070 | Throughout building | Poor | Suspended Ceilings, Hard Tile, Replacement w/ ACT | 230 SF | 1 | 7442418 |
| Special Construction & Demo | | | | | | |
| F1020 | Site | Fair | Shed/Gazebo/Shade Structure, Wood or Metal-Framed, Basic/Minimal | 250 SF | 18 | 7426988 |
| F1020 | Site | Fair | Shed/Gazebo/Shade Structure, Wood or Metal-Framed, Basic/Minimal | 250 SF | 17 | 7442422 |
| F1020 | Site | Good | Structural Flooring/Decking, Wood, Refinish | 4,100 SF | 7 | 7426989 |
| Pedestrian Plazas & Walkways | | | | | | |
| G2020 | Site | Poor | Parking Lots, Pavement, Asphalt, Seal & Stripe | 13,700 SF | 1 | 7426991 |
| G2020 | Site | Fair | Parking Lots, Pavement, Asphalt, Mill & Overlay | 13,700 SF | 3 | 7426990 |
| G2030 | Site | Poor | Sidewalk, Concrete, Small Areas/Sections | 210 SF | 2 | 7442421 |
| G2030 | Site | Fair | Sidewalk, Concrete, Large Areas | 820 SF | 16 | 7442424 |
| Athletic, Recreational & Playfield Areas | | | | | | |
| G2050 | Site | Fair | Play Structure, Multipurpose, Large | 1 | 7 | 7426997 |
| G2050 | Site | Fair | Sports Apparatus, Basketball, Backboard/Rim/Pole | 4 | 13 | 7426996 |
| G2050 | Site | Fair | Playfield Surfaces, Chips Wood, 3" Depth | 8,440 SF | 2 | 7442419 |
| G2050 | Site | Fair | Athletic Surfaces & Courts, Basketball/General, Asphalt Pavement | 54,900 SF | 11 | 7442423 |
| Sitework | | | | | | |
| G2060 | Site | Fair | Dumpster Enclosure, Masonry (CMU) Walls, 8' High (per LF), Replace/Install | 68 LF | 29 | 7442417 |
| G4050 | Site | Fair | Pole Light Fixture w/ Lamps, any type 20' High, w/ LED Replacement, Replace/Install | 26 | 4 | 7442415 |

Appendix E: Replacement Reserves



Appendix F: Equipment Inventory List

D10 Conveying

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|-----------------------------------|--------------------------------------|----------|--|-----------------------|--------------------------------|-------------|--------------|--------------|---------|-----|
| 1 | 7426903 | D1010 | Passenger Elevator [Car 1] | Hydraulic, 2 Floors, 1500 to 2500 LB | | Mary Munford Elementary School / Main Building | Elevator Machine Room | Schindler Elevator Corporation | 6-370407-40 | No dataplate | 2019 | 1575626 | |

D20 Plumbing

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|-----------------------|---------------------------|----------|--|-----------------|------------------------|-----------------|---------------|--------------|---------|-----|
| 1 | 7439004 | D2010 | Water Heater | Gas, Commercial (200 MBH) | | Mary Munford Elementary School / Main Building | Boiler room | State Industries, Inc. | BT-80400 | 1725106614872 | 2017 | 1575809 | |
| 2 | 7426905 | D2010 | Water Heater | Gas, Commercial (200 MBH) | | Mary Munford Elementary School / Main Building | Boiler room | State Industries, Inc. | SBD100199NET118 | 0908M001613 | 2009 | 1575810 | |
| 3 | 7438934 | D2030 | Pump | Sump | | Mary Munford Elementary School / Main Building | Boiler room | Reliable Electric | P56H1337H | FB563 | | 1575815 | |
| 4 | 7438981 | D2030 | Pump | Sump | | Mary Munford Elementary School / Main Building | Boiler room | Reliable Electric | P56H1337H | FB56C | 2009 | 1575816 | |
| 5 | 7438972 | D2060 | Air Compressor | Tank-Style | | Mary Munford Elementary School / Main Building | Boiler room | Curtis | E5-20 | EA6160540 | 2007 | 1575814 | |
| 6 | 7438932 | D2060 | Air Compressor | Tank-Style | | Mary Munford Elementary School / Main Building | Boiler room | Honeywell | E5-20 | A54080485 | 2007 | 1575813 | |

D30 HVAC

| Index | ID | UFCODE | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|---------------------------------------|---|----------|--|--------------------|-------------------------|--------------|---------------|--------------|---------|-----|
| 1 | 7438943 | D3020 | Boiler [Boiler 1] | Gas, HVAC | | Mary Munford Elementary School / Main Building | Boiler room | Smith Cast Iron Boilers | 28A-SW-10 | 288 10 070418 | 2007 | 1575807 | |
| 2 | 7426919 | D3020 | Boiler [Boiler 2] | Gas, HVAC | | Mary Munford Elementary School / Main Building | Boiler room | Smith Cast Iron Boilers | 28A-SW-10 | 288 10 070417 | 2007 | 1575806 | |
| 3 | 7438920 | D3020 | HVAC Steam Components | Deaerator | | Mary Munford Elementary School / Main Building | Kitchen | Carrier | FN1AAF006000 | 4620F24478 | 2020 | 1575633 | |
| 4 | 7438946 | D3020 | Radiator | Hydronic, Column/Cabinet Style (per EA) | 56 | Mary Munford Elementary School / Main Building | Building entrances | No dataplate | No dataplate | No dataplate | | | |
| 5 | 7438986 | D3020 | Boiler Supplemental Components | Chemical Feed System | | Mary Munford Elementary School / Main Building | Boiler room | Nalco | UN3266 | No dataplate | | | |
| 6 | 7438922 | D3030 | Split System | Fan Coil Unit, DX, 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Classrooms | Panasonic | | | 2002 | 1575708 | 27 |
| 7 | 7438990 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Roof | Panasonic | U-36PS1U6 | Illegible | | 1575684 | |
| 8 | 7438977 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | 38MBRCQ36AA3 | 3022V10726 | 2022 | 1575798 | |
| 9 | 7438985 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | U-36PS1U6 | 0001922 | 2001 | 1575801 | |
| 10 | 7438979 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | U-36PS1U6 | 0000322 | 2003 | 1575800 | |
| 11 | 7438948 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | U-36PS1U6 | 0003322 | 2004 | 1575796 | |
| 12 | 7438997 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Roof | Panasonic | U-36PS1U6 | 0004022 | 2004 | 1575679 | |
| 13 | 7438941 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | U-36PS1U6 | 0003922 | 2003 | 1575787 | |
| 14 | 7438974 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 2.5 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | U-36PS1U6 | 0010022 | 2001 | 1575788 | |
| 15 | 7438917 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Roof | Panasonic | U-36PS1U6 | 000-2122 | 2002 | 1575682 | |
| 16 | 7438996 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | U-36PS1U6 | 000272 | 2002 | 1575797 | |
| 17 | 7438927 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Roof | Panasonic | U-36PS1U6 | Illegible | 2000 | 1575683 | |
| 18 | 7438921 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3.5 TON | Mary Munford Elementary School / Main Building | Roof | Panasonic | U-42PS1U6 | Illegible | 2000 | 1575665 | |
| 19 | 7438940 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | U-36PS1U6 | 0004422 | 2004 | 1575802 | |
| 20 | 7438915 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | U-36PS1U6 | Illegible | 2000 | 1575789 | |
| 21 | 7439002 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | U-36PS1U6 | Illegible | 2002 | 1575786 | |

| | | | | | | | | | | | | |
|----|---------|-------|-----------------------|--|-----------|--|------|-------------------|-----------------|-------------|------|---------|
| 22 | 7438951 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | Illegible | Mary Munford Elementary School / Main Building | Roof | Panasonic | U 42PS1U6 | Illegible | 2000 | 1575677 |
| 23 | 7438995 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | U-36PS1U6 | 0004522 | 2004 | 1575803 |
| 24 | 7438939 | D3030 | Split System Ductless | Single Zone, 2.5 to 3 TON | 3 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | U-36PS1U6 | 0004242 | 2004 | 1575799 |
| 25 | 7438994 | D3030 | Split System Ductless | Single Zone, 2.5 TON | 2.5 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | U-36PS1U6 | 0013922 | 2001 | 1575790 |
| 26 | 7438965 | D3030 | Split System Ductless | Single Zone, 3.5 TON | 3.5 TON | Mary Munford Elementary School / Main Building | Roof | Panasonic | U-42PS1U6 | 0002322 | 2000 | 1575673 |
| 27 | 7438999 | D3030 | Split System Ductless | Single Zone, 3.5 TON | 3.5 TON | Mary Munford Elementary School / Main Building | Roof | Panasonic | U-42PS1U6 | 0003022 | 2004 | 1575675 |
| 28 | 7438993 | D3030 | Split System Ductless | Single Zone, 3.5 TON | 3.5 TONB | Mary Munford Elementary School / Main Building | Roof | Panasonic | U-42PS1U6 | Illegible | | 1575685 |
| 29 | 7438933 | D3030 | Split System Ductless | Single Zone, 3.5 TON | 3.5 TON | Mary Munford Elementary School / Main Building | Roof | Panasonic | U-42PS1U6 | 0002822 | 2002 | 1575676 |
| 30 | 7438947 | D3030 | Split System Ductless | Single Zone, 3.5 TON | 3.5 TON | Mary Munford Elementary School / Main Building | Roof | Panasonic | U-42PS1U6 | 0002522 | 2002 | 1575678 |
| 31 | 7438928 | D3030 | Split System Ductless | Single Zone, 4 TON | 4 TON | Mary Munford Elementary School / Main Building | Roof | Panasonic | 38MBRCQ48AA3 | 3022V10733 | 2022 | 1575672 |
| 32 | 7438944 | D3030 | Split System Ductless | Single Zone, 4 TON | 4 TON | Mary Munford Elementary School / Main Building | Roof | Panasonic | 38MBRCQ48AA3 | 2822V32344 | 2022 | 1575674 |
| 33 | 7438925 | D3030 | Split System Ductless | Single Zone, 4-TON | 4 TON | Mary Munford Elementary School / Main Building | Site | Panasonic | 38MBRCQ48AA3 | 3022V10931 | 2022 | 1575805 |
| 34 | 7426931 | D3050 | Packaged Unit | RTU, Pad or Roof-Mounted, 26 to 50 TON | 28 TON | Mary Munford Elementary School / Main Building | Roof | Daikin Industries | DPS028AHMG4DW-4 | FB0U21004f3 | 2021 | 1575791 |
| 35 | 7438937 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 16" Damper | | Mary Munford Elementary School / Main Building | Roof | Illegible | Illegible | Illegible | | 1575681 |
| 36 | 7438935 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 36"Damper | | Mary Munford Elementary School / Main Building | Roof | Illegible | Illegible | Illegible | | 1575664 |
| 37 | 7438980 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 36"Damper | | Mary Munford Elementary School / Main Building | Roof | Illegible | Illegible | Illegible | | 1575663 |
| 38 | 7438975 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 36"Damper | | Mary Munford Elementary School / Main Building | Roof | Illegible | Illegible | Illegible | | 1575671 |
| 39 | 7438973 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 36"Damper | | Mary Munford Elementary School / Main Building | Roof | Illegible | Illegible | Illegible | | 1575680 |
| 40 | 7426939 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 16" Damper, 1001 to 2000 CFM | | Mary Munford Elementary School / Main Building | Roof | Inaccessible | Illegible | Illegible | | 1575670 |
| 41 | 7438924 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | | Mary Munford Elementary School / Main Building | Roof | Illegible | Illegible | Illegible | | 1575667 |
| 42 | 7439003 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | | Mary Munford Elementary School / Main Building | Roof | Illegible | Illegible | Illegible | | 1575669 |
| 43 | 7439006 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | | Mary Munford Elementary School / Main Building | Roof | Illegible | Illegible | Illegible | | 1575795 |
| 44 | 7438963 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | | Mary Munford Elementary School / Main Building | Roof | Illegible | Illegible | Illegible | | 1575794 |
| 45 | 7426938 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | | Mary Munford Elementary School / Main Building | Roof | Illegible | Illegible | Illegible | | 1575649 |
| 46 | 7438991 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | | Mary Munford Elementary School / Main Building | Roof | Illegible | Illegible | Illegible | | 1575668 |
| 47 | 7438916 | D3060 | Exhaust Fan | Roof or Wall-Mounted, 24" Damper, 2001 to 5000 CFM | | Mary Munford Elementary School / Main Building | Roof | Illegible | Illegible | Illegible | | 1575666 |

D40 Fire Protection

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|-------------------------|------------------------------------|----------|--|-----------------|--------------|-------|--------|--------------|---------|-----|
| 1 | 7426942 | D4010 | Fire Suppression System | Commercial Kitchen, per LF of Hood | | Mary Munford Elementary School / Main Building | Kitchen | | | | | | 24 |

D50 Electrical

| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
|-------|---------|--------|------------------------------|---------------------|----------|--|-------------------|--------------|---------------|-----------------|--------------|---------|-----|
| 1 | 7426943 | D5010 | Generator | Diesel, 35 to 60 KW | | Mary Munford Elementary School / Main Building | Building exterior | Kohler | No dataplate | No dataplate | | 1575793 | |
| 2 | 7426945 | D5010 | Automatic Transfer Switch | ATS | | Mary Munford Elementary School / Main Building | Electrical room | Square D | 75T3HFISCUNLP | 34349-17222-041 | | 1575817 | |
| 3 | 7426952 | D5020 | Distribution Panel | 120/208 V, 600 AMP | | Mary Munford Elementary School / Main Building | Electrical room | Westinghouse | No dataplate | E2 | | 1575725 | |
| 4 | 7438969 | D5020 | Distribution Panel [Panel B] | 120/208 V | | Mary Munford Elementary School / Main Building | Electrical room | Square D | BX3673 | H2-4143 | 2019 | 1575718 | |

| 5 | 7426955 | D5040 | Emergency & Exit Lighting | Exit Sign, LED | | Mary Munford Elementary School / Main Building | Throughout building | | | | | | 20 |
|---|---------|--------|--------------------------------------|---|----------|--|---------------------|--------------------------|-----------------|----------------|--------------|---------|-----|
| D70 Electronic Safety & Security | | | | | | | | | | | | | |
| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
| 1 | 7438949 | D7050 | Fire Alarm Panel | Fully Addressable | | Mary Munford Elementary School / Main Building | Office | Simplex | No dataplate | No dataplate | | | |
| E10 Equipment | | | | | | | | | | | | | |
| Index | ID | UFCode | Component Description | Attributes | Capacity | Building | Location Detail | Manufacturer | Model | Serial | Dataplate Yr | Barcode | Qty |
| 1 | 7426966 | E1030 | Foodservice Equipment | Convection Oven, Double | | Mary Munford Elementary School / Main Building | Kitchen | Blodgett | No dataplate | No dataplate | | 1575639 | |
| 2 | 7426978 | E1030 | Foodservice Equipment | Dairy Cooler/Wells | | Mary Munford Elementary School / Main Building | Kitchen | Beverage-Air Corporation | SM34N | No dataplate | | 1575821 | |
| 3 | 7438983 | E1030 | Foodservice Equipment | Dairy Cooler/Wells | | Mary Munford Elementary School / Main Building | Kitchen | Beverage-Air Corporation | SM F49Y 1 S | 12408241 | | 1575628 | |
| 4 | 7438918 | E1030 | Foodservice Equipment | Dairy Cooler/Wells | | Mary Munford Elementary School / Main Building | Kitchen | True Manufacturing Co | TMC 34 S DS SS | 7485726 | | 1575825 | |
| 5 | 7426963 | E1030 | Foodservice Equipment | Exhaust Hood, 8 to 10 LF | | Mary Munford Elementary School / Main Building | Kitchen | CaptiveAire Systems | No dataplate | No dataplate | | 1575627 | |
| 6 | 7426971 | E1030 | Foodservice Equipment | Food Warmer, Proofing Cabinet on Wheels | | Mary Munford Elementary School / Main Building | Kitchen | Metro | C5 | No dataplate | | 1575822 | |
| 7 | 7426964 | E1030 | Foodservice Equipment | Mixer, Freestanding | | Mary Munford Elementary School / Main Building | Kitchen | Hobart | H6600 | 187-4489 | | 1575632 | |
| 8 | 7426967 | E1030 | Foodservice Equipment | Prep Table Refrigerated, Salad/Sandwich | | Mary Munford Elementary School / Main Building | Kitchen | Craig | ST-6-30-DE | No dataplate | | 1575643 | |
| 9 | 7438945 | E1030 | Foodservice Equipment | Steamer, Tabletop | | Mary Munford Elementary School / Main Building | Kitchen | Convotherm | No dataplate | No dataplate | | 1575644 | |
| 10 | 7426969 | E1030 | Foodservice Equipment | Steamer, Tabletop | | Mary Munford Elementary School / Main Building | Kitchen | Convotherm | SC-74-NU | 180315000291 | | 1575645 | |
| 11 | 7426960 | E1030 | Foodservice Equipment [1] | Refrigerator, 2-Door Reach-In | | Mary Munford Elementary School / Main Building | Kitchen | Hobart | QF2 | 32-1056730 | | 1575823 | |
| 12 | 7426976 | E1030 | Foodservice Equipment [2] | Freezer, 2-Door Reach-In | | Mary Munford Elementary School / Main Building | Kitchen | Delfield | GCR2P-S | N0: 1120339307 | | 1575634 | |
| 13 | 7438989 | E1030 | Foodservice Equipment [2] | Refrigerator, 2-Door Reach-In | | Mary Munford Elementary School / Main Building | Kitchen | Traulsen | G20010 | T19234812 | | 1575818 | |
| 14 | 7426974 | E1030 | Foodservice Equipment [3] | Refrigerator, 2-Door Reach-In | | Mary Munford Elementary School / Main Building | Kitchen | McCall | 7-7045T | S-772727 | | 1575642 | |
| 15 | 7426972 | E1030 | Foodservice Equipment [4] | Refrigerator, 2-Door Reach-In | | Mary Munford Elementary School / Main Building | Kitchen | Hobart | CF2 | 32-552846 | | 1575636 | |
| 16 | 7426961 | E1030 | Foodservice Equipment [7] | Prep Table Refrigerated, Salad/Sandwich | | Mary Munford Elementary School / Main Building | Kitchen | Craig | SCFT-50-NU | 1803150000292 | | 1575824 | |
| 17 | 7426977 | E1030 | Foodservice Equipment [A] | Food Warmer, Proofing Cabinet on Wheels | | Mary Munford Elementary School / Main Building | Kitchen | Metro | C5 | No dataplate | | 1575638 | |
| 18 | 7438978 | E1030 | Foodservice Equipment | Convection Oven, Single | | Mary Munford Elementary School / Main Building | Kitchen | ACCUTEMP | 208D8-300 | 4826 | | 1575631 | |
| 19 | 7426970 | E1030 | Foodservice Equipment [B] | Convection Oven, Single | | Mary Munford Elementary School / Main Building | Kitchen | Convotherm | C4 ED 6.2 0GS N | WS216091731 | | 1575637 | |
| 20 | 7426979 | E1030 | Foodservice Equipment [E] | Steam Kettle | | Mary Munford Elementary School / Main Building | Kitchen | Cleveland | KGL-40 | WT0596-911-01 | | 1575819 | |
| 21 | 7439001 | E1030 | Foodservice Equipment [PTA] | Freezer, Chest | | Mary Munford Elementary School / Main Building | Kitchen | No dataplate | No dataplate | No dataplate | | 1575630 | |
| 22 | 7426975 | E1030 | Foodservice Equipment [PTA] | Freezer, Chest | | Mary Munford Elementary School / Main Building | Kitchen | Hisense | No dataplate | No dataplate | | 1575629 | |
| 23 | 7439000 | E1030 | Foodservice Equipment [PTA] | Refrigerator, 2-Door Reach-In | | Mary Munford Elementary School / Main Building | Kitchen | True Manufacturing Co | 1 2749878 | T-49 | | 1575641 | |
| 24 | 7426916 | E1030 | Sink/Lavatory | Commercial Kitchen, 2-Bowl | | Mary Munford Elementary School / Main Building | Kitchen | | | | | | |
| 25 | 7426914 | E1030 | Sink/Lavatory | Commercial Kitchen, 3-Bowl | | Mary Munford Elementary School / Main Building | Kitchen | | | | | | |
| 26 | 7426981 | E1040 | Ceramics Equipment | Kiln | | Mary Munford Elementary School / Main Building | Utility closet | Skutt | KMT-1027 | 22B28-685 | 2022 | 1575710 | |
| 27 | 7426982 | E1040 | Healthcare Equipment | Defibrillator (AED), Cabinet-Mounted | | Mary Munford Elementary School / Main Building | Throughout building | | | | | | |