

# FACILITY CONDITION ASSESSMENT



**BUREAU  
VERITAS**

*prepared for*

**Richmond Public Schools**  
301 North Ninth Street  
Richmond, VA 23219



Westover Hills Elementary School  
1211 Jahnke Road  
Richmond, VA 23225

**PREPARED BY:**

*Bureau Veritas  
6021 University Boulevard, Suite 200  
Ellicott City, MD 21043  
800.733.0660  
[www.us.bureauveritas.com](http://www.us.bureauveritas.com)*

**BV CONTACT:**

*Bill Champion  
Program Manager  
800.733.0660 x7296234  
[Bill.Champion@bureauveritas.com](mailto:Bill.Champion@bureauveritas.com)*

**BV PROJECT #:**

*166385.24R000-024.468*

**DATE OF REPORT:**

*May 21, 2024*

**ON SITE DATE:**

*April 24, 2024*

**Bureau Veritas**

## TABLE OF CONTENTS

<b>1. Executive Summary</b> .....	<b>1</b>
Campus Overview and Assessment Details .....	1
Significant/Systemic Findings and Deficiencies .....	2
Facility Condition Index (FCI).....	4
Immediate Needs.....	5
Key Findings .....	7
Plan Types .....	11
<b>2. Main Building</b> .....	<b>12</b>
<b>3. Site Summary</b> .....	<b>22</b>
<b>4. ADA Accessibility</b> .....	<b>26</b>
<b>5. Purpose and Scope</b> .....	<b>28</b>
<b>6. Opinions of Probable Costs</b> .....	<b>30</b>
Methodology .....	30
Definitions .....	31
<b>7. Certification</b> .....	<b>32</b>
<b>8. Appendices</b> .....	<b>33</b>



# 1. Executive Summary

## Campus Overview and Assessment Details

General Information	
<b>Property Type</b>	Elementary school campus
<b>Number of Buildings</b>	1
<b>Main Address</b>	1211 Jahnke Road, Richmond, VA 43212
<b>Site Developed</b>	1955
<b>Outside Occupants / Leased Spaces</b>	None
<b>Date(s) of Visit</b>	April 24, 2024
<b>Management Point of Contact</b>	Daniel Alu Project Engineer 800 Yard Street, Suite 115 Columbus, Ohio 43212 C: 614.949.1355 <a href="mailto:daniel.alu@gofmx.com">daniel.alu@gofmx.com</a>
<b>On-site Point of Contact (POC)</b>	Ronald (Bobby) Hathaway Jr., Director of Facilities Department of Facility Services 1461 A Commerce Road Richmond, VA 23224 Office: (804) 780-6251 Mobil: (804) 325-0740 Email: <a href="mailto:Rhathawa@rvaschools.net">Rhathawa@rvaschools.net</a>
<b>Assessment &amp; Report Prepared By</b>	Peter Marra
<b>Reviewed By</b>	Daniel White Technical Report Reviewer for Bill Champion Program Manager 800.733.0660 x7296234
<b>AssetCalc Link</b>	Full dataset for this assessment can be found at: <a href="https://www.assetcalc.net/">https://www.assetcalc.net/</a>



## Significant/Systemic Findings and Deficiencies

### Historical Summary

Westover Hills Elementary is a public school in a suburban community. The population is 368 students and serves PK-5.

### Architectural

Westover Hills Elementary School is a one-story brick façade elementary school with a built-up roof. There are reports of the roof leaking. Stained ACT tiles were observed throughout the building. It was also reported that mold was observed on ACT tiles and on countertops. The windows are single pane aluminum framed and original to the build date. A new roof and windows have been budgeted for the short term. There is a small ceiling section between the kitchen and cafeteria that may contain asbestos. A study is recommended to analyze the ceiling materials. Wall cracks were reported in the first grade and kindergarten wing (room 5). It is reported the cracking is due to settlement. A study is recommended to analyze the structure and determine the source of the cracking. Terrazzo common hall floors have hairline cracks but in general look good for their age. The interior finishes have been periodically replaced as-needed over the years.

### Mechanical, Electrical, Plumbing and Fire (MEPF)

The heating throughout the facility is by gas boilers sending heated water to unit ventilators throughout the classrooms. The unit ventilators are quite dated and original to the 1955 build date. Teachers report the heat is either very hot or does not heat the classroom adequately. Cooling is achieved by split system DX condensing units of the roof and ceiling hung AHU in every classroom. Many teachers report the units are not working properly and do not know how to adjust the wall thermostats. Ventilation for the school is supplied by rooftop exhaust equipment. They are dented, rusting, and dated.

The plumbing fixtures were generally observed to be close to end of life. The domestic water service within the building is well maintained, with no evidence of leaks observed at the domestic piping. The domestic hot water service at the facilities consists of updated equipment and the supply appears to be adequate. No major issues were observed or reported.

The electrical system for the building has not been upgraded. It was reported the incoming power is not adequate to meet the needs of the school. On site personnel did not know if the emergency generator was working. It looked original to the building and was rusting. The interior lighting system utilizes linear florescent bulbs.

The fire alarm system controlled by a fully addressable panel reportedly functions well. The building is without a central fire suppression system. A sprinkler system was budgeted for safety and modernization. A security/surveillance system throughout the building and site offers protection for the facility.

### Site

Landscaping consists of trees, shrubs, and lawn areas that run along the front of the building and around the perimeter of the rear playing fields. The concrete sidewalks and front entrance are starting to crack. Some areas along the bus turnaround may pose a tripping hazard. The parking lot is located on the south side and provides parking for 44 cars. A second-grade modular classroom sits on the southeast corner of the lot. The building was constructed in 1992 and is nearing end of life. Textures plywood is delaminating and interior finishes are in need of modernization. The school is connected to the city's sports and recreation building. The upkeep of the fields and playground are reportedly not covered by the school's budget.

## Recommended Additional Studies

See the *Systems Summary* tables in the latter sections of this report for recommended additional studies associated with environmental and settlement.

## Facility Condition Index (FCI)

One of the major goals of the FCA is to calculate the Facility Condition Index (FCI), which provides a theoretical objective indication of a facility’s overall condition. The FCI is defined as the ratio of the cost of current needs divided by the current replacement value (CRV) of the facility. In this report, each building is considered as a separate facility. The chart below presents the industry standard ranges and cut-off points.

FCI Ranges and Description	
<b>0 – 5%</b>	In new or well-maintained condition, with little or no visual evidence of wear or
<b>5 – 10%</b>	Subjected to wear but is still in a serviceable and functioning condition.
<b>10 – 30%</b>	Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life.
<b>30% and above</b>	Has reached the end of its useful or serviceable life. Renewal is now necessary.

The deficiencies and lifecycle needs identified in this assessment provide the basis for a portfolio-wide capital improvement funding strategy. In addition to the current FCI, extended FCI’s have been developed to provide owners the intelligence needed to plan and budget for the “keep-up costs” for their facilities. As such the 3-year, 5-year, and 10-year FCI’s are calculated by dividing the anticipated needs of those respective time periods by current replacement value. As a final point, the FCI’s ultimately provide more value when used to compare facilities across a portfolio instead of being over-analyzed and scrutinized as stand-alone mathematical values. The table below presents the current, 3-year, 5-year, and 10-year FCI’s for each facility:

FCI Analysis   Westover Hills Elementary School / Main Building(1955)			
Replacement Value	Total SF	Cost/SF	
\$ 15,002,400	50,008	\$ 300	
	Est Reserve Cost		FCI
<b>Current</b>	\$ 317,200		<b>2.1 %</b>
3-Year	\$ 1,619,300		10.8 %
5-Year	\$ 5,236,500		34.9 %
10-Year	\$ 5,967,500		39.8 %

## Immediate Needs

Facility/Building	Total Items	Total Cost
Westover Hills Elementary School / Main Building	7	\$317,200
Westover Hills Elementary School / Site	2	\$7,600
<b>Total</b>	<b>9</b>	<b>\$324,800</b>

## Main Building

ID	Location Description	UF Code	Description	Condition	Plan Type	Cost
7567273	Room 6	D2010	Toilet, Child-Sized, Replace	Poor	Performance/Integrity	\$900
7567471	Roof - 5	D3030	Split System Ductless, Single Zone, 1.5 to 2 TON, Replace	Poor	Performance/Integrity	\$4,800
7567389	Room 29	D3030	Split System, Fan Coil Unit, DX, Replace	Poor	Performance/Integrity	\$2,100
7567419	Throughout classrooms	D3030	Unit Ventilator, approx/nominal 4 Ton, Replace	Poor	Performance/Integrity	\$254,400
7567457	Site	D5010	Generator, Diesel, Replace	Poor	Performance/Integrity	\$40,000
7567310	Throughout building	P2030	Engineering Study, Environmental, Asbestos (ACM) & Lead Base Paint (LBP), Evaluate/Report	NA	Environmental	\$5,000
7567416	Room 5	P2030	Engineering Study, Structural, Superstructure, Evaluate/Report	Poor	Performance/Integrity	\$10,000
<b>Total (7 items)</b>						<b>\$317,200</b>

Site

<u>ID</u>	<u>Location Description</u>	<u>UF Code</u>	<u>Description</u>	<u>Condition</u>	<u>Plan Type</u>	<u>Cost</u>
7567451	Site	D3010	Storage Tank, Fuel, Interior, Replace	Poor	Performance/Integrity	\$2,600
7567400	Site	G2030	Sidewalk, Asphalt, Replace	Poor	Performance/Integrity	\$5,000
<b>Total (2 items)</b>						<b>\$7,600</b>





### Key Findings



#### Generator in Poor condition.

Diesel  
Main Building Westover Hills Elementary School Site

Uniformat Code: D5010  
Recommendation: **Replace in 2024**

Priority Score: **88.9**

Plan Type:  
Performance/Integrity

Cost Estimate: \$40,000

\$\$\$\$

The generator Does not appear to be functioning. The maintenance staff is not aware of the status. - AssetCALC ID: 7567457



#### Roofing in Poor condition.

Built-Up  
Main Building Westover Hills Elementary School Roof

Uniformat Code: B3010  
Recommendation: **Replace in 2025**

Priority Score: **88.8**

Plan Type:  
Performance/Integrity

Cost Estimate: \$700,100

\$\$\$\$

It was reported that there are active roof leaks throughout the school - AssetCALC ID: 7567467



#### Storage Tank in Poor condition.

Fuel, Interior  
Site Westover Hills Elementary School Site

Uniformat Code: D3010  
Recommendation: **Replace in 2024**

Priority Score: **86.9**

Plan Type:  
Performance/Integrity

Cost Estimate: \$2,600

\$\$\$\$

The fuel tank is badly rusted and quite dated. It is not known if the generator is working. - AssetCALC ID: 7567451



#### Sidewalk in Poor condition.

Asphalt  
Site Westover Hills Elementary School Site

Uniformat Code: G2030  
Recommendation: **Replace in 2024**

Priority Score: **85.9**

Plan Type:  
Performance/Integrity

Cost Estimate: \$5,000

\$\$\$\$

The walkway is overgrown with grass and weeds and is uneven. - AssetCALC ID: 7567400



**Exhaust Fan in Poor condition.**

Centrifugal, 16" Damper  
Main Building Westover Hills Elementary  
School Roof

Uniformat Code: D3060  
Recommendation: **Replace in 2025**

Priority Score: **85.8**

Plan Type:  
Performance/Integrity

Cost Estimate: \$2,400

\$\$\$\$

Unit does not appear to be functioning - AssetCALC ID: 7567350



**Toilet in Poor condition.**

Child-Sized  
Main Building Westover Hills Elementary  
School Room 6

Uniformat Code: D2010  
Recommendation: **Replace in 2024**

Priority Score: **83.9**

Plan Type:  
Performance/Integrity

Cost Estimate: \$900

\$\$\$\$

Teacher reports the toilet leaks frequently. It is blocked off and not used due to this problem. - AssetCALC ID: 7567273



**Split System in Poor condition.**

Fan Coil Unit, DX  
Main Building Westover Hills Elementary  
School Room 29

Uniformat Code: D3030  
Recommendation: **Replace in 2024**

Priority Score: **81.9**

Plan Type:  
Performance/Integrity

Cost Estimate: \$2,100

\$\$\$\$

The unit reportedly does not function in air-conditioning mode - AssetCALC ID: 7567389



**Split System Ductless in Poor condition.**

Single Zone, 1.5 to 2 TON  
Main Building Westover Hills Elementary  
School Roof - 5

Uniformat Code: D3030  
Recommendation: **Replace in 2024**

Priority Score: **81.9**

Plan Type:  
Performance/Integrity

Cost Estimate: \$4,800

\$\$\$\$

Unit frequently does not work. It is currently not working. - AssetCALC ID: 7567471



**Recommended Follow-up Study:  
Structural, Superstructure**

Structural, Superstructure  
Main Building Westover Hills Elementary  
School Room 5

Uniformat Code: P2030  
Recommendation: **Evaluate/Report in 2024**

Priority Score: **81.9**

Plan Type:  
Performance/Integrity

Cost Estimate: \$10,000

**\$\$\$\$**

Cracking was reported in Room 5. It could potentially be a structural issue and a professional engineer should be retained to evaluate. - AssetCALC ID: 7567416



**Unit Ventilator in Poor condition.**

Approx/nominal 4 Ton  
Main Building Westover Hills Elementary  
School Throughout classrooms

Uniformat Code: D3030  
Recommendation: **Replace in 2024**

Priority Score: **81.9**

Plan Type:  
Performance/Integrity

Cost Estimate: \$254,400

**\$\$\$\$**

Unit ventilators are antiquated and do not keep rooms at comfortable temperature. - AssetCALC ID: 7567419



**Suspended Ceilings in Poor  
condition.**

Hard Tile, ACM Abatement & Replacement w/  
ACT  
Main Building Westover Hills Elementary  
School Cafeteria

Uniformat Code: C1070  
Recommendation: **Replace in 2025**

Priority Score: **81.8**

Plan Type:  
Performance/Integrity

Cost Estimate: \$10,100

**\$\$\$\$**

Ceiling tiles show previous repairs and stains. - AssetCALC ID: 7567365



### Ancillary Building in Poor condition.

Classroom/Office Module, Standard/Permanent  
Site Westover Hills Elementary School Site

Uniformat Code: F1020  
Recommendation: **Replace in 2025**

Priority Score: **81.8**

Plan Type:  
Performance/Integrity

Cost Estimate: \$212,800

**\$\$\$\$**

Modular building exterior wood siding is delaminating in multiple areas. Some of the holes are large enough that rodents are getting into the structure. The HVAC units are dated and have a difficult time conditioning the room. The roof is starting to leak and the VCT tiles are chipped in several areas. - AssetCALC ID: 7567397



### Recommended Follow-up Study: Environmental, Asbestos (ACM) & Lead Base Paint (LBP)

Environmental, Asbestos (ACM) & Lead Base Paint (LBP)  
Main Building Westover Hills Elementary School Throughout building

Uniformat Code: P2030  
Recommendation: **Evaluate/Report in 2024**

Priority Score: **72.9**

Plan Type: Environmental

Cost Estimate: \$5,000

**\$\$\$\$**

Hard ceiling tiles should be evaluated for the existence of asbestos. - AssetCALC ID: 7567310


## Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance and highest on the list below.

### Plan Type Descriptions

<b>Safety</b>	■	An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk.
<b>Performance/Integrity</b>	■	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability.
<b>Accessibility</b>	■	Does not meet ADA, UFAS, and/or other accessibility requirements.
<b>Environmental</b>	■	Improvements to air or water quality, including removal of hazardous materials from the building or site.
<b>Retrofit/Adaptation</b>	■	Components, systems, or spaces recommended for upgrades in in order to meet current standards, facility usage, or client/occupant needs.
<b>Lifecycle/Renewal</b>	■	Any component or system that is neither deficient nor aged past EUL but for which future replacement or repair is anticipated and budgeted.

### Plan Type Distribution (by Cost)



10-YEAR TOTAL: \$6,377,900





## 2. Main Building



Main Building: Systems Summary		
<b>Address</b>	1211 Jahnke Road, Richmond, VA 23225	
<b>Constructed/Renovated</b>	1955	
<b>Building Area</b>	50,008 SF	
<b>Number of Stories</b>	1 above grade	
<i>System</i>	<i>Description</i>	<i>Condition</i>
<b>Structure</b>	Masonry bearing walls with metal roof deck supported by open-web steel joists and concrete strip/wall footing foundation system	Fair
<b>Façade</b>	Primary Wall Finish: Brick Secondary Wall Finish: Stucco Windows: Aluminum	Fair
<b>Roof</b>	Primary: Flat construction with built-up finish	Poor
<b>Interiors</b>	Walls: Painted lath & plaster, painted ceramic tile Floors: VCT, ceramic tile, quarry tile, terrazzo, Ceilings: Painted lath & plaster and ACT	Fair
<b>Elevators</b>	None	--

<b>Main Building: Systems Summary</b>		
<b>Plumbing</b>	Distribution: Copper supply and cast iron waste & venting Hot Water: Gas On Demand water heater Fixtures: Toilets, urinals, and sinks in all restrooms	Fair
<b>HVAC</b>	Central System: Boilers, feeding fan coil and unit ventilators Non-Central System: Packaged units, Split-system heat	Poor
<b>Fire Suppression</b>	Fire extinguishers only	Good
<b>Electrical</b>	Source & Distribution: Main switchboard with copper wiring Fed from street pole with copper wiring Interior Lighting: linear fluorescent Exterior Building-Mounted Lighting: HPS Emergency Power: Diesel generator with automatic transfer switch	Fair
<b>Fire Alarm</b>	Alarm panel with smoke detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs	Fair
<b>Equipment/Special</b>	Commercial kitchen equipment	Fair
<b>Accessibility</b>	Presently it does not appear an accessibility study is needed for this building. See the appendix for associated photos and additional information.	
<b>Additional Studies</b>	<p>There is isolated evidence of deflection and movement in the kindergarten and first grade classrooms. A Professional Engineer with specific expertise in structural design and construction in this geographical area must be retained to evaluate the structure and to provide remedial recommendations consistent with local regulatory and code requirements. Although the estimated cost of repair cannot be accurately determined without the recommended study, a budgetary cost allowance to repair the affected elements is also included.</p> <p>Areas of suspected asbestos containing material were observed on the ceiling between the cafeteria and the commercial kitchen. The affected total areas is approximately 720 square feet in size. Based on the size of the affected areas (more than 30 square feet), the ceiling must be abated by a qualified remediation contractor. Mold was reportedly found on ACT tiles on the first floor and kindergarten wing. The cost to retain a consultant to conduct an extensive survey and to recommend clean-up methods and repairs is included.</p>	

## Main Building: Systems Summary

### Areas Observed

The interior spaces were observed to gain a clear understanding of the facility's overall condition. Other areas accessed and assessed included the exterior equipment and assets directly serving the buildings, the exterior walls of the facility, and the roofs.

### Key Spaces Not Observed

All key areas of the facility were accessible and observed.



The table below shows the anticipated costs by trade or building system over the next 20 years.

<b>System Expenditure Forecast</b>						
<b>System</b>	<b>Immediate</b>	<b>Short Term (1-2 yr)</b>	<b>Near Term (3-5 yr)</b>	<b>Med Term (6-10 yr)</b>	<b>Long Term (11-20 yr)</b>	<b>TOTAL</b>
Structure	-	-	-	-	-	-
Facade	-	-	\$155,700	-	\$53,000	\$208,700
Roofing	-	\$721,100	-	-	-	\$721,100
Interiors	-	\$10,400	\$544,800	\$222,900	\$738,700	\$1,516,700
Plumbing	\$900	-	\$862,000	\$111,900	\$7,900	\$982,800
HVAC	\$261,300	\$451,200	\$725,800	\$368,700	\$1,830,200	\$3,637,200
Fire Protection	-	-	\$401,200	-	-	\$401,200
Electrical	\$40,000	-	\$569,800	-	-	\$609,800
Fire Alarm & Electronic Systems	-	-	\$391,200	-	\$277,300	\$668,500
Equipment & Furnishings	-	\$4,900	\$81,200	\$27,400	\$146,100	\$259,600
Follow-up Studies	\$15,000	-	-	-	-	\$15,000
<b>TOTALS (3% inflation)</b>	<b>\$317,200</b>	<b>\$1,187,500</b>	<b>\$3,731,800</b>	<b>\$730,900</b>	<b>\$3,053,200</b>	<b>\$9,020,600</b>



**NEEDS OVER TIME:** The vertical blue bars in the graphic below represent the year-by-year needs identified for the facility. The orange line forecasts what would happen to the FCI (left Y axis) over time, assuming zero capital expenditures over the next ten years. The dollar amounts allocated for each year are associated with the values along the right Y axis.


## Needs by Year with Unaddressed FCI Over Time

### FCI Analysis: Westover Hills Elementary School Main Building

Replacement Value: \$15,002,400

Inflation Rate: 3.0%

Average Needs per Year: \$542,500



Main Building: Photographic Overview



1 - FRONT ELEVATION



2 - LEFT ELEVATION



3 - REAR ELEVATION



4 - RIGHT ELEVATION





5 - BUILDING FACADE



6 - PRIMARY ROOF OVERVIEW



7 - EDGE CONDITIONS



8 - RECEPTION AREA



9 - LIBRARY



10 - COMMERCIAL KITCHEN



11 - CAFETERIA



12 - TYPICAL CLASSROOM



13 - LOBBY



14 - ART CLASSROOM



15 - TYPICAL HALLWAY



16 - DOMESTIC WATER PIPING





17 - DOMESTIC HOT WATER SUPPLY



18 - MAIN MECHANICAL ROOM



19 - ROOFTOP MECHANICAL EQUIPMENT



20 - UNIT VENTILATOR



21 - SPLIT SYSTEM



22 - MAIN ELECTRICAL ROOM



23 - FIRE ALARM PANEL



24 - FIRE ALARM DEVICES

### 3. Site Summary



Site Information		
<b>Site Area</b>	3.51 acres (estimated)	
<b>Parking Spaces</b>	44 total spaces all in open lots; two of which are accessible	
<i>System</i>	<i>Description</i>	<i>Condition</i>
<b>Pavement/Flatwork</b>	Asphalt lots with limited areas of concrete aprons and pavement and adjacent concrete sidewalks, curbs, ramps,	Fair
<b>Site Development</b>	Building-mounted signage; chain link fencing Playgrounds and sports fields and courts fencing, and site lights (play areas under city’s recreational budget) Heavily furnished with picnic tables	Fair
<b>Landscaping and Topography</b>	Limited landscaping features including lawns, trees, bushes, and planters Irrigation not present	Fair
<b>Utilities</b>	Municipal water and sewer Local utility-provided electric and natural gas, fuel oil tanks	Good
<b>Site Lighting</b>	Pole-mounted: LED, HPS, metal halide	Fair
<b>Ancillary Structures</b>	Prefabricated modular buildings	Fair



Site Information	
<b>Site Accessibility</b>	Presently it does not appear an accessibility study is needed for the exterior site areas. See the appendix for associated photos and additional information.
<b>Site Additional Studies</b>	No additional studies are currently recommended for the exterior site areas.
<b>Site Areas Observed</b>	The exterior areas within the property boundaries were observed to gain a clear understanding of the site's overall condition.
<b>Site Key Spaces Not Observed</b>	All key areas of the exterior site were accessible and observed.

The table below shows the anticipated costs by trade or site system over the next 20 years.

System Expenditure Forecast						
System	Immediate	Short Term (1-2 yr)	Near Term (3-5 yr)	Med Term (6-10 yr)	Long Term (11-20 yr)	TOTAL
Structure	-	-	\$1,900	-	\$2,900	\$4,800
Interiors	-	-	\$4,200	-	-	\$4,200
HVAC	\$2,600	-	-	-	-	\$2,600
Special Construction & Demo	-	\$219,200	-	-	-	\$219,200
Site Pavement	\$5,000	\$11,500	\$135,100	\$13,300	\$33,200	\$198,000
Site Development	-	-	-	\$14,300	-	\$14,300
Site Utilities	-	-	\$3,400	-	-	\$3,400
<b>TOTALS (3% inflation)</b>	<b>\$7,600</b>	<b>\$230,600</b>	<b>\$144,500</b>	<b>\$27,600</b>	<b>\$36,100</b>	<b>\$446,400</b>

Site: Photographic Overview



1 - MAIN PARKING AREA



2 - SIDEWALKS AND LANDSCAPING



3 - ANCILLARY CLASSROOM



4 - PLAYGROUND



5 - COURTYARD



6 - PROPERTY SIGNAGE

## 4. ADA Accessibility

---

Generally, Title II of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of “areas of public accommodations” and “public facilities” on the basis of disability. Regardless of their age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

A public entity (i.e. city governments) shall operate each service, program, or activity so that the service, program, or activity, when viewed in its entirety, is readily accessible to and usable by individuals with disabilities.

However, this does not:

1. Necessarily require a public entity to make each of its existing facilities accessible to and usable by individuals with disabilities;
2. Require a public entity to take any action that would threaten or destroy the historic significance of an historic property; or
3. Require a public entity to take any action that it can demonstrate would result in a fundamental alteration in the nature of a service, program, or activity or in undue financial and administrative burdens. In those circumstances where personnel of the public entity believe that the proposed action would fundamentally alter the service, program, or activity or would result in undue financial and administrative burdens, a public entity has the burden of proving that compliance with 35.150(a) of this part would result in such alteration or burdens. The decision that compliance would result in such alteration or burdens must be made by the head of a public entity or his or her designee after considering all resources available for use in the funding and operation of the service, program, or activity, and must be accompanied by a written statement of the reasons for reaching that conclusion. If an action would result in such an alteration or such burdens, a public entity shall take any other action that would not result in such an alteration or such burdens but would nevertheless ensure that individuals with disabilities receive the benefits or services provided by the public entity.

Removal of barriers to accessibility should be addressed from a liability standpoint in order to comply with federal law, but the barriers may or may not be building code violations. The Americans with Disabilities Act Accessibility Guidelines are part of the ADA federal civil rights law pertaining to the disabled and are not a construction code. State and local jurisdictions have adopted the ADA Guidelines or have adopted other standards for accessibility as part of their construction codes.

During the FCA, Bureau Veritas performed a limited high-level accessibility review of the facility non-specific to any local regulations or codes. The scope of the visual observation was limited to the same areas observed while performing the FCA and the categories set forth in the material included in the appendix. It is understood by the Client that the limited observations described herein do not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of this assessment. A full measured ADA survey would be required to identify more specific potential accessibility issues. Additional clarifications of this limited survey:

- This survey was visual in nature and actual measurements were not taken to verify compliance
- Only a representative sample of areas was observed
- Two overview photos were taken for each subsection regardless of perceived compliance or non-compliance
- Itemized costs for individual non-compliant items are included in the dataset
- For any “none” boxes checked or reference to “no issues” identified, that alone does not guarantee full compliance

The following table summarizes the accessibility conditions of the general site and each significant building included in this report:

<b>Accessibility Summary</b>			
<i>Facility</i>	<i>Year Built/ Renovated</i>	<i>Prior Study Provided?</i>	<i>Major/Moderate Issues Observed?</i>
General Site	1955	No	No
Main Building	1955	No	No
Site	1955	No	No

No detailed follow-up accessibility study is currently recommended since no major or moderate issues were identified at the subject site. Reference the appendix for specific data, photos, and tables or checklists associated with this limited accessibility survey.





## 5. Purpose and Scope

### Purpose

Bureau Veritas was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

Condition Ratings	
<b>Excellent</b>	New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
<b>Good</b>	Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
<b>Fair</b>	Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.
<b>Poor</b>	Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life.
<b>Failed</b>	Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.
<b>Not Applicable</b>	Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.

## Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include a review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property's compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding of the property's overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.

## 6. Opinions of Probable Costs

---

Cost estimates are attached throughout this report, with the Replacement Reserves in the appendix.

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means*, *CBRE Whitestone*, and *Marshall & Swift*, Bureau Veritas's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

### Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, Bureau Veritas opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its *effective age*, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of Bureau Veritas's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.



## Definitions

### Immediate Needs

Immediate Needs are line items that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

For database and reporting purposes the line items with RUL=0, and commonly associated with *Safety* or *Performance/Integrity* Plan Types, are considered Immediate Needs.

### Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, Bureau Veritas's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

Bureau Veritas's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system or component replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined as Immediate Needs.

For the purposes of 'bucketizing' the System Expenditure Forecasts in this report, the Replacement Reserves have been subdivided and grouped as follows: Short Term (years 1-3), Near Term (years 4-5), Medium Term (years 6-10), and Long Term (years 11-20).

### Key Findings

In an effort to highlight the most significant cost items and not be overwhelmed by the Replacement Reserves report in its totality, a subsection of Key Findings is included within the Executive Summary section of this report. Key Findings typically include repairs or replacements of deficient items within the first five-year window, as well as the most significant high-dollar line items that fall anywhere within the ten-year term. Note that while there is some subjectivity associated with identifying the Key Findings, the Immediate Needs are always included as a subset.

## 7. Certification

---

Richmond Public Schools (the Client) retained Bureau Veritas to perform this Facility Condition Assessment in connection with its continued operation of Westover Hills Elementary School, 1211 Jahnke Road, Richmond, VA, the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.


The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.

No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared for and is exclusively for the use and benefit of the Client identified on the cover page of this report. The purpose for which this report shall be used shall be limited to the use as stated in the contract between the client and Bureau Veritas.

This report, or any of the information contained therein, is not for the use or benefit of, nor may it be relied upon by any other person or entity, for any purpose without the advance written consent of Bureau Veritas. Any reuse or distribution without such consent shall be at the client's or recipient's sole risk, without liability to Bureau Veritas.

**Prepared by:** Peter Marra,  
Project Manager

**Reviewed by:**   
\_\_\_\_\_  
Daniel White  
Technical Report Reviewer for  
Bill Champion  
Program Manager  
[bill.champion@bureauveritas.com](mailto:bill.champion@bureauveritas.com)  
800.733.0660 x7296234

## 8. Appendices

---

Appendix A: Site Plan

Appendix B: Pre-Survey Questionnaire

Appendix C: Accessibility Review and Photos

Appendix D: Component Condition Report

Appendix E: Replacement Reserves

Appendix F: Equipment Inventory List



# Appendix A:



## Site Plan

---



# Site Plan



 <b>BUREAU VERITAS</b>	<b>Project Number</b>	<b>Project Name</b>	 <b>N</b>
	166385.24R000-024.468	Westover Hills Elementary School	
	<b>Source</b>	<b>On-Site Date</b>	
	Google	April 24, 2024	

## Appendix B:

### Pre-Survey Questionnaires

---

## Bureau Veritas Facility Condition Assessment: Pre-Survey Questionnaire

**Building / Facility Name:** Westover Hill Elementary  
**Name of person completing form:** Ronald Hathaway  
**Title / Association with property:** Director of Facilities  
**Length of time associated w/ property:** 30  
**Date Completed:** 5/10/2024  
**Phone Number:** 804-325-0740  
**Method of Completion:** Electronic

**Directions:** Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses.

Data Overview		Response		
1	Year/s constructed / renovated	1955		
2	Building size in SF	50008		
3	Major Renovation/Rehabilitation		Year	Additional Detail
		Façade		Brick
		Roof		Tar and gravel
		Interiors		Plater and CMU
		HVAC		Hot water boilers, fan coil units, and mini split air conditioning
		Electrical		
		Site Pavement		Asphalt
		Accessibility	2007	Satisfied the 2007 lawsuit requirement
Question		Response		
4	List other significant capital improvements (focus on recent years; provide approximate date).	Add air conditioning to the gym 2020		
5	List any major capital expenditures planned/requested for the next few years. Have they been budgeted?	None		
6	Describe any on-going extremely problematic, historically chronic, or immediate facility needs.	Heating fan coil units original require frequent repairs		



Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any <b>Yes</b> responses. ( <b>NA</b> indicates "Not Applicable", <b>Unk</b> indicates "Unknown")						
Question		Response				Comments
		Yes	No	Unk	NA	
7	Are there any problems with foundations or structures, like excessive settlement?		X			
8	Are there any wall, window, basement or roof leaks?	X				
9	Has any part of the facility ever contained visible suspect mold growth, or have there been any indoor air quality or mold related complaints from occupants?		X			
10	Are your elevators unreliable, with frequent service calls?				X	
11	Are there any plumbing leaks, water pressure, or clogging/back-up problems?		X			
12	Have there been any leaks or pressure problems with natural gas, HVAC supply/return lines, or steam service?		X			
13	Are any areas of the facility inadequately heated, cooled or ventilated? Any poorly insulated areas?	X				Hallways
14	Is the electrical service outdated, undersized, or otherwise problematic?				X	
15	Are there any problems or inadequacies with exterior lighting?	X				
16	Is site/parking drainage inadequate, with excessive ponding or other problems?	X				
17	Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified above?		X			
18	ADA: Has an accessibility study been performed at the site? If so, indicate when.	X				
19	ADA: If a study has occurred, have the associated recommendations been addressed? In full or in part?	X				Satisfied the 2007 lawsuit requirement
20	ADA: Have there been regular complaints about accessibility issues, or associated previous or pending litigation?		X			



## Appendix C:

### Accessibility Review and Photos

---

## Visual Checklist - 2010 ADA Standards for Accessible Design

Property Name: Westover Hills Elementary School

BV Project Number: 166385.24R000-024.468

### Abbreviated Accessibility Checklist

#### Facility History & Interview

Question		Yes	No	Unk	Comments
1	Has an accessibility study been previously performed? If so, when?			X	
2	Have any ADA improvements been made to the property since original construction? Describe.			X	
3	Has building management reported any accessibility-based complaints or litigation?		X		

## Abbreviated Accessibility Checklist

### Parking



OVERVIEW OF ACCESSIBLE PARKING AREA



CLOSE-UP OF STALL

Question		Yes	No	NA	Comments
1	Does the required number of standard ADA designated spaces appear to be provided ?	✗			
2	Does the required number of van-accessible designated spaces appear to be provided ?	✗			
3	Are accessible spaces on the shortest accessible route to an accessible building entrance ?	✗			
4	Does parking signage include the International Symbol of Accessibility ?	✗			
5	Does each accessible space have an adjacent access aisle ?	✗			
6	Do parking spaces and access aisles appear to be relatively level and without obstruction ?	✗			

## Abbreviated Accessibility Checklist

### Exterior Accessible Route



ACCESSIBLE PATH



CURB CUT

Question		Yes	No	NA	Comments
1	Is an accessible route present from public transportation stops and municipal sidewalks on or immediately adjacent to the property ?	✗			
2	Does a minimum of one accessible route appear to connect all public areas on the exterior, such as parking and other outdoor amenities, to accessible building entrances ?	✗			
3	Are curb ramps present at transitions through raised curbs on all accessible routes?	✗			
4	Do curb ramps appear to have compliant slopes for all components ?	✗			
5	Do ramp runs on an accessible route appear to have compliant slopes ?	✗			
6	Do ramp runs on an accessible route appear to have a compliant rise and width ?	✗			

7	Do ramps on an accessible route appear to have compliant end and intermediate landings ?	X			
8	Do ramps and stairs on an accessible route appear to have compliant handrails?	X			
9	For stairways that are open underneath, are permanent barriers present that prevent or discourage access?	X			



# Abbreviated Accessibility Checklist

## Building Entrances



ACCESSIBLE ENTRANCE



SIGNAGE


Question		Yes	No	NA	Comments
1	Do a sufficient number of accessible entrances appear to be provided ?	X			
2	If the main entrance is not accessible, is an alternate accessible entrance provided?	X			
3	Is signage provided indicating the location of alternate accessible entrances ?	X			
4	Do doors at accessible entrances appear to have compliant maneuvering clearance area on each side ?	X			
5	Do doors at accessible entrances appear to have compliant hardware ?	X			
6	Do doors at accessible entrances appear to have a compliant clear opening width ?	X			



7	Do pairs of accessible entrance doors in series appear to have the minimum clear space between them ?	X			
8	Do thresholds at accessible entrances appear to have a compliant height ?	X			

## Abbreviated Accessibility Checklist

### Interior Accessible Route



ACCESSIBLE INTERIOR PATH



DOOR HARDWARE

Question		Yes	No	NA	Comments
1	Does an accessible route appear to connect all public areas inside the building ?	✗			
2	Do accessible routes appear free of obstructions and/or protruding objects ?	✗			
3	Do ramps on accessible routes appear to have compliant slopes ?	✗			
4	Do ramp runs on an accessible route appear to have a compliant rise and width ?	✗			
5	Do ramps on accessible routes appear to have compliant end and intermediate landings ?	✗			
6	Do ramps on accessible routes appear to have compliant handrails ?	✗			

7	Are accessible areas of refuge and the accessible means of egress to those areas identified with accessible signage ?		X		
8	Do public transaction areas have an accessible, lowered service counter section ?	X			
9	Do public telephones appear mounted with an accessible height and location ?	X			
10	Do doors at interior accessible routes appear to have compliant maneuvering clearance area on each side ?	X			
11	Do doors at interior accessible routes appear to have compliant hardware ?	X			
12	Do non-fire hinged, sliding, or folding doors on interior accessible routes appear to have compliant opening force ?	X			
13	Do doors on interior accessible routes appear to have a compliant clear opening width ?	X			

# Abbreviated Accessibility Checklist

## Public Restrooms



TOILET STALL OVERVIEW



SINK, FAUCET HANDLES AND ACCESSORIES

Question		Yes	No	NA	Comments
1	Do publicly accessible toilet rooms appear to have a minimum compliant floor area ?	✗			
2	Does the lavatory appear to be mounted at a compliant height and with compliant knee area ?	✗			
3	Does the lavatory faucet have compliant handles ?	✗			
4	Is the plumbing piping under lavatories configured to protect against contact ?	✗			
5	Are grab bars provided at compliant locations around the toilet ?	✗			
6	Do toilet stall doors appear to provide the minimum compliant clear width ?	✗			

7	Do toilet stalls appear to provide the minimum compliant clear floor area ?	X			
8	Where more than one urinal is present in a multi-user restroom, does minimum one urinal appear to be mounted at a compliant height and with compliant approach width ?	X			
9	Do accessories and mirrors appear to be mounted at a compliant height ?	X			

# Abbreviated Accessibility Checklist

## Playgrounds & Swimming Pools



ACCESSIBLE ROUTE TO PLAYGROUND



OVERVIEW OF PLAYGROUND

Question		Yes	No	NA	Comments
1	Is there an accessible route to the play area / s?	✘			
2	Has the play area been reviewed for accessibility ?	✘			
3	Are publicly accessible swimming pools equipped with an entrance lift ?	✘			



## Appendix D:

### Component Condition Report

---

## Component Condition Report | Westover Hills Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
<b>Structure</b>						
A1010	Throughout building	Fair	Foundation System, Concrete or CMU Walls w/out Footings, Concrete or CMU Walls w/out Footings	7,700 SF	21	7567275
B1010	Throughout	Fair	Structural Framing, Masonry (CMU) Bearing Walls, Repair	50,008 SF	21	7567320
<b>Facade</b>						
B2010	Building Exterior	Good	Exterior Walls, Insulated Finishing System (EIFS)	1,275 SF	20	7567374
B2010	Building Exterior	Fair	Exterior Walls, Glass Block	350 SF	4	7567446
B2010	Building Exterior	Fair	Exterior Walls, Brick	14,125 SF	21	7567285
B2020	Building Exterior	Fair	Glazing, any type by SF	2,000 SF	4	7567434
B2050	Building Exterior	Fair	Exterior Door, Wood, Solid-Core	4	4	7567388
B2050	Building Exterior	Fair	Exterior Door, Steel, Standard	13	5	7567445
<b>Roofing</b>						
B3010	Roof	Poor	Roofing, Built-Up	50,008 SF	1	7567467
<b>Interiors</b>						
C1070	Throughout	Fair	Suspended Ceilings, Acoustical Tile (ACT)	5,600 SF	4	7567355
C1070	Cafeteria	Poor	Suspended Ceilings, Hard Tile, ACM Abatement & Replacement w/ ACT	720 SF	1	7567365
C2010	Trailer	Fair	Wall Finishes, Vinyl	1,072 SF	4	7567330
C2010	Throughout building	Good	Wall Finishes, any surface, Prep & Paint	71,540 SF	7	7567364
C2010	Restrooms	Fair	Wall Finishes, Ceramic Tile	2,400 SF	5	7567303
C2030	Trailer	Fair	Flooring, Vinyl Tile (VCT)	1,064 SF	4	7567277
C2030	Classrooms	Fair	Flooring, Vinyl Tile (VCT), w/ Asbestos Abatement	12,000 SF	4	7567433
C2030	Media center	Fair	Flooring, Carpet, Commercial Standard	2,184 SF	4	7567421
C2030	Hall	Fair	Flooring, Terrazzo	5,600 SF	4	7567331
C2030	Cafeteria	Fair	Flooring, Quarry Tile	2,250 SF	10	7567444
C2030	Throughout	Fair	Flooring, Vinyl Tile (VCT)	25,910 SF	4	7567369

## Component Condition Report | Westover Hills Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
C2030	Restrooms	Fair	Flooring, Ceramic Tile	1,000 SF	5	7567349
C2050	Throughout building	Good	Ceiling Finishes, any flat surface, Prep & Paint	5,000 SF	7	7567366
C2050	Classrooms	Fair	Ceiling Finishes, any flat surface, Prep & Paint	37,624 SF	3	7567448
<b>Plumbing</b>						
D2010	Restrooms	Fair	Sink/Lavatory, Wall-Hung, Enameled Steel	20	6	7567306
D2010	Trailer	Good	Sink/Lavatory, Vanity Top, Stainless Steel	2	26	7567343
D2010	Throughout building	Good	Drinking Fountain, Wall-Mounted, Single-Level	5	10	7567299
D2010	Boiler room	Good	Water Heater, Gas, Tankless	1	12	7567344
D2010	Restrooms	Fair	Toilet, Child-Sized	19	6	7567272
D2010	Boiler room	Excellent	Backflow Preventer, Domestic Water	1	29	7567377
D2010	Throughout building	Fair	Sink/Lavatory, Vanity Top, Stainless Steel	12	4	7567399
D2010	Kitchen	Fair	Sink/Lavatory, Commercial Kitchen, 2-Bowl	1	16	7567290
D2010	Restrooms	Fair	Toilet, Commercial Water Closet	7	6	7567274
D2010	Room 6	Poor	Toilet, Child-Sized	1	0	7567273
D2010	Custodian room	Fair	Sink/Lavatory, Service Sink, Wall-Hung	1	4	7567278
D2010	Trailer	Good	Sink/Lavatory, Wall-Hung, Vitreous China	1	21	7567346
D2010	4	Good	Sink/Lavatory, Vanity Top, Solid Surface or Vitreous China	12	24	7567301
D2010	Boiler room	Good	Water Heater, Gas, Tankless	1	12	7567420
D2010	Restrooms	Fair	Urinal, Waterless	8	6	7567345
D2010	Kitchen	Good	Sink/Lavatory, Commercial Kitchen, 3-Bowl	1	26	7567407
D2010	Throughout building	Fair	Plumbing System, Supply & Sanitary, High Density (excludes fixtures)	50,008 SF	4	7567342
D2030	Roof	Fair	Plumbing System, Rain Water Drainage, High Density	50,008 SF	4	7567370
D2060	Boiler room	Fair	Air Compressor, Tank-Style	1	7	7567333
D2060	Boiler room	Fair	Supplemental Components, Compressed Air Dryer, Process Support	1	6	7567292
<b>HVAC</b>						

## Component Condition Report | Westover Hills Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D3020	Hall at Genius Grove	Fair	Radiator, Hydronic, Baseboard (per LF)	52 LF	6	7567348
D3020	Boiler room	Good	Boiler Supplemental Components, Expansion Tank	1	27	7567477
D3020	Throughout building	Fair	Radiator, Hydronic, Column/Cabinet Style (per EA)	20	4	7567403
D3020	Boiler room	Fair	Boiler, Gas, HVAC	1	17	7567304
D3020	Boiler room	Good	Boiler Supplemental Components, Expansion Tank	1	27	7567383
D3020	Boiler room	Fair	Boiler, Gas, HVAC	1	17	7567312
D3020	Boiler room	Good	Boiler Supplemental Components, Expansion Tank	1	27	7567384
D3020	Boiler room	Good	Boiler Supplemental Components, Expansion Tank	1	27	7567460
D3020	Cafeteria	Fair	Unit Heater, Hydronic	1	4	7567431
D3030	Roof 22	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567326
D3030	Roof - 9	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567354
D3030	Roof 14	Fair	Split System Ductless, Single Zone, 1.5 to 2 TON	1	2	7567319
D3030	Roof - 2	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567298
D3030	Roof - 3	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567442
D3030	Roof - 6	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567291
D3030	Roof - 20	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567392
D3030	Roof - 8	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567430
D3030	Roof	Fair	Split System, Condensing Unit/Heat Pump	1	4	7567435
D3030	Roof - 24	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567357
D3030	Throughout classrooms	Poor	Unit Ventilator, approx/nominal 4 Ton	24	0	7567419
D3030	Roof -- 1	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	3	7567423
D3030	Roof - 13	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	3	7567422
D3030	Roof - 17	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	3	7567279
D3030	Roof - 19	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567381
D3030	Modular A	Fair	Heat Pump, Packaged & Wall-Mounted, 3.5 to 4 TON	1	3	7567475

## Component Condition Report | Westover Hills Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D3030	Trailer	Fair	Packaged Terminal Air Conditioner, PTAC	1	4	7567417
D3030	Roof - 5	Poor	Split System Ductless, Single Zone, 1.5 to 2 TON	1	0	7567471
D3030	Roof - 16	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567339
D3030	Roof - 11	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567371
D3030	Roof	Fair	Split System, Condensing Unit/Heat Pump, 4 TON	1	2	7567335
D3030	Roof - 5	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567461
D3030	Roof - 23	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567317
D3030	Roof - 0	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567463
D3030	Roof - 21	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567458
D3030	Ropof - 7	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567424
D3030	Roof - 4	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567352
D3030	Room 29	Poor	Split System, Fan Coil Unit, DX	1	0	7567389
D3030	Roof - 12	Fair	Split System Ductless, Single Zone, 2.5 to 3 TON	1	2	7567450
D3030	Roof	Fair	Split System, Condensing Unit/Heat Pump	1	2	7567289
D3050	Boiler room	Fair	Pump, Distribution, HVAC Heating Water	1	15	7567456
D3050	Throughout building	Fair	HVAC System, Hydronic Piping, 2-Pipe	50,008 SF	4	7567411
D3050	29	Fair	Fan Coil Unit, Hydronic Terminal	1	10	7567360
D3050	Throughout building	Fair	HVAC System, Ductwork, High Density	50,008 SF	4	7567387
D3050	Boiler room	Fair	Pump, Distribution, HVAC Heating Water	1	2	7567402
D3050	Boiler room	Fair	Pump, Distribution, HVAC Heating Water	1	15	7567294
D3050	Boiler room	Fair	Pump, Distribution, HVAC Heating Water	1	5	7567455
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 16" Damper	1	4	7567453
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 12" Damper	11	5	7567307
D3060	Throughout	Fair	Supplemental Components, Air Purifier, Electrostatic, 2000 CFM	33	2	7568489
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 24" Damper	1	4	7567413

## Component Condition Report | Westover Hills Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 16" Damper	1	4	7567408
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 16" Damper	1	4	7567361
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 24" Damper	1	4	7567309
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 16" Damper	1	4	7567474
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 16" Damper	1	4	7567478
D3060	Roof	Fair	Exhaust Fan, Centrifugal, 24" Damper	1	4	7567412
D3060	Roof	Poor	Exhaust Fan, Centrifugal, 16" Damper	1	1	7567350
<b>Fire Protection</b>						
D4010	Kitchen exhaust hood	NA	Fire Suppression System, Commercial Kitchen, per LF of Hood	16 LF	4	7567449
D4010	Throughout building	NA	Fire Suppression System, Full System Install/Retrofit, High Density/Complexity, Renovate	50,008 SF	4	7567386
<b>Electrical</b>						
D5010	Site	Poor	Generator, Diesel	1	0	7567457
D5020	Electric equipment	Fair	Distribution Panel, 120/208 V	1	4	7567437
D5020	Boiler room	Fair	Distribution Panel, 120/208 V	1	4	7567376
D5020	Electric equipment	Fair	Supplemental Components, Circuit Breaker/Disconnect	1	4	7567334
D5020	Trailer	Fair	Distribution Panel, 120/240 V	1	4	7567380
D5030	Throughout building	Fair	Electrical System, Wiring & Switches, High Density/Complexity	50,008 SF	4	7567396
D5040	Throughout building	Fair	Interior Lighting System, Full Upgrade, High Density & Standard Fixtures	50,008 SF	4	7567358
D5040	Trailer	Fair	Interior Lighting System, Full Upgrade, High Density & Standard Fixtures	1,064 SF	4	7567351
<b>Fire Alarm &amp; Electronic Systems</b>						
D6020	Throughout building	Good	Low Voltage System, Facility-Wide, Phone or Data Lines Only	50,008 SF	14	7567327
D6060	Throughout building	Fair	Intercom/PA System, Public Address Upgrade, Facility-Wide	50,008 SF	4	7567426
D7030	Throughout building	Fair	Security/Surveillance System, Full System Upgrade, Average Density	50,008 SF	4	7567385
D7050	Office	Fair	Fire Alarm Panel, Fully Addressable	1	4	7567338
D7050	Throughout building	Fair	Fire Alarm System, Full System Upgrade, Standard Addressable, Upgrade/Install	50,008 SF	4	7567362



## Component Condition Report | Westover Hills Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
<b>Equipment &amp; Furnishings</b>						
E1030	Kitchen	Fair	Foodservice Equipment, Freezer, 2-Door Reach-In	1	4	7567414
E1030	Kitchen	Fair	Foodservice Equipment, Convection Oven, Single	1	4	7567314
E1030	Kitchen	Good	Foodservice Equipment, Refrigerator, 2-Door Reach-In	1	13	7567280
E1030	Kitchen	Fair	Foodservice Equipment, Refrigerator, 2-Door Reach-In	1	4	7567373
E1030	Kitchen	Good	Foodservice Equipment, Freezer, 2-Door Reach-In	1	12	7567379
E1030	Kitchen	Fair	Foodservice Equipment, Refrigerator, 2-Door Reach-In	1	4	7567305
E1030	Kitchen	Good	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels	1	10	7567382
E1030	Kitchen	Good	Foodservice Equipment, Prep Table Refrigerated, Salad/Sandwich	1	14	7567440
E1030	Kitchen	Fair	Foodservice Equipment, Dairy Cooler/Wells	1	7	7567464
E1030	Kitchen	Fair	Foodservice Equipment, Refrigerator, 2-Door Reach-In	1	2	7567297
E1030	Kitchen	Fair	Foodservice Equipment, Refrigerator, 3-Door Reach-In	1	4	7567429
E1030	Kitchen	Fair	Foodservice Equipment, Refrigerator, 2-Door Reach-In	1	4	7567340
E1030	Kitchen	Fair	Foodservice Equipment, Food Warmer, Proofing Cabinet on Wheels	1	4	7567302
E1030	Kitchen	Fair	Foodservice Equipment, Convection Oven, Single	1	4	7567454
E1030	Kitchen	Fair	Foodservice Equipment, Dairy Cooler/Wells	1	4	7567459
E1030	Kitchen	Good	Foodservice Equipment, Steamer, Tabletop	1	7	7567418
E1030	Kitchen	Fair	Foodservice Equipment, Freezer, 2-Door Reach-In	1	7	7567356
E1030	Kitchen	Fair	Foodservice Equipment, Exhaust Hood, 8 to 10 LF	1	4	7567393
E1030	Kitchen	Fair	Foodservice Equipment, Freezer, 2-Door Reach-In	1	3	7567415
E1030	Kitchen	Fair	Foodservice Equipment, Refrigerator, 2-Door Reach-In	1	8	7567321
E1030	Kitchen	Good	Foodservice Equipment, Food Warmer, Tabletop Drawers (Set of 4)	1	14	7567332
E1030	Kitchen	Fair	Foodservice Equipment, Food Warmer, Tabletop Drawers (Set of 4)	1	4	7567398
E2010	Classrooms	Fair	Casework, Cabinetry Economy	87 LF	4	7567481
<b>Follow-up Studies</b>						

## Component Condition Report | Westover Hills Elementary School / Main Building

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
P2030	Room 5	Poor	Engineering Study, Structural, Superstructure, Evaluate/Report	1	0	7567416
P2030	Throughout building	NA	Engineering Study, Environmental, Asbestos (ACM) & Lead Base Paint (LBP), Evaluate/Report	1	0	7567310

## Component Condition Report | Westover Hills Elementary School / Site

UF L3 Code	Location	Condition	Asset/Component/Repair	Quantity	RUL	ID
<b>Structure</b>						
B1010	Site	Fair	Exterior Ramp, Wood	150 SF	4	7567313
<b>Interiors</b>						
C1070	modular	Fair	Suspended Ceilings, Acoustical Tile (ACT)	1,064 SF	4	7567322
<b>HVAC</b>						
D3010	Site	Poor	Storage Tank, Fuel, Interior	1	0	7567451
<b>Special Construction &amp; Demo</b>						
F1020	Site	Poor	Ancillary Building, Classroom/Office Module, Standard/Permanent	1,064 SF	1	7567397
<b>Pedestrian Plazas &amp; Walkways</b>						
G2020	Site	Fair	Parking Lots, Pavement, Asphalt, Mill & Overlay	24,000 SF	4	7567479
G2020	Site	Fair	Parking Lots, Pavement, Asphalt, Seal & Stripe	24,000 SF	2	7567323
G2030	Site	Poor	Sidewalk, Asphalt	900 SF	0	7567400
G2030	Site	Fair	Sidewalk, Concrete, Large Areas	4,000 SF	4	7567441
<b>Sitework</b>						
G2060	Site	Fair	Signage, Property, Building-Mounted Individual Letters, Replace/Install	20	6	7567390
G2060	Site	Fair	Picnic Table, Wood/Composite/Fiberglass	15	6	7567443
G2060	Site	Good	Fences & Gates, Fence, Chain Link 4'	150 LF	31	7567367
G4050	Site	Fair	Exterior Fixture w/ Lamp, any type, w/ LED Replacement	5	4	7567476

## Appendix E: Replacement Reserves

---

Replacement Reserves Report



5/21/2024

Summary table with columns: Location, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, Total Escalated Estimate. Includes rows for Westover Hills Elementary School and Grand Total.

Westover Hills Elementary School

Westover Hills Elementary School / Main Building

Main table with columns: Uniformat Code, Location Description, ID, Cost Description, Lifespan (EUL), Age, RUL, Quantity, Unit, Unit Cost, Subtotal, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, Deficiency Repair Estimate. Contains detailed entries for various building components like exterior walls, roofing, flooring, and plumbing.







## Appendix F:

### Equipment Inventory List

---

**D20 Plumbing**

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	7567344	D2010	<b>Water Heater</b>	Gas, Tankless	3.95 GPM	Westover Hills Elementary School / Main Building	Boiler room	Navien	NPE-240A2(NG)	2087D2192876234	2021	<a href="https://rvaschools.gofmx.com/equipment/1560911">https://rvaschools.gofmx.com/equipment/1560911</a>	
2	7567420	D2010	<b>Water Heater</b>	Gas, Tankless	3.95 GPM	Westover Hills Elementary School / Main Building	Boiler room	Navien	NPE-240A2(NG)	2087W2192806243	2021	<a href="https://rvaschools.gofmx.com/equipment/1560923">https://rvaschools.gofmx.com/equipment/1560923</a>	
3	7567377	D2010	<b>Backflow Preventer</b>	Domestic Water	.75 IN	Westover Hills Elementary School / Main Building	Boiler room	Watts Regulator	LF009M3QT	311043	2023	<a href="https://rvaschools.gofmx.com/equipment/1560941">https://rvaschools.gofmx.com/equipment/1560941</a>	
4	7567333	D2060	<b>Air Compressor</b>	Tank-Style	10 HP	Westover Hills Elementary School / Main Building	Boiler room	Curtis			2011	<a href="https://rvaschools.gofmx.com/equipment/1560927">https://rvaschools.gofmx.com/equipment/1560927</a>	
5	7567292	D2060	<b>Supplemental Components</b>	Compressed Air Dryer, Process Support	100 CFM	Westover Hills Elementary School / Main Building	Boiler room	FS Curtis	CR10	HG010A1151010029	2010	<a href="https://rvaschools.gofmx.com/equipment/1560907">https://rvaschools.gofmx.com/equipment/1560907</a>	

**D30 HVAC**

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	7567451	D3010	<b>Storage Tank</b>	Fuel, Interior	140 GAL	Westover Hills Elementary School / Site	Site	Atlantic Fabritech	No dataplate	No dataplate	1955	<a href="https://rvaschools.gofmx.com/equipment/1560975">https://rvaschools.gofmx.com/equipment/1560975</a>	
2	7567304	D3020	<b>Boiler</b>	Gas, HVAC	1500 MBH	Westover Hills Elementary School / Main Building	Boiler room	Patterson-Kelley	N1500-MFD	FY26-11-35561	2011	<a href="https://rvaschools.gofmx.com/equipment/1560908">https://rvaschools.gofmx.com/equipment/1560908</a>	
3	7567312	D3020	<b>Boiler</b>	Gas, HVAC	1500 MBH	Westover Hills Elementary School / Main Building	Boiler room	Patterson-Kelley	N1500-MFD	FY26-11-35560	2011	<a href="https://rvaschools.gofmx.com/equipment/1560934">https://rvaschools.gofmx.com/equipment/1560934</a>	
4	7567348	D3020	<b>Radiator</b>	Hydronic, Baseboard (per LF)		Westover Hills Elementary School / Main Building	Hall at Genius Grove				2000		52
5	7567403	D3020	<b>Radiator</b>	Hydronic, Column/Cabinet Style (per EA)		Westover Hills Elementary School / Main Building	Throughout building				1955		20
6	7567431	D3020	<b>Unit Heater</b>	Hydronic	88 MBH	Westover Hills Elementary School / Main Building	Cafeteria	Trane	NA	2081.23	1955	<a href="https://rvaschools.gofmx.com/equipment/1561008">https://rvaschools.gofmx.com/equipment/1561008</a>	
7	7567477	D3020	<b>Boiler Supplemental Components</b>	Expansion Tank	106 GAL	Westover Hills Elementary School / Main Building	Boiler room	Bell & Gossett	B400	229085	2011	<a href="https://rvaschools.gofmx.com/equipment/1560961">https://rvaschools.gofmx.com/equipment/1560961</a>	
8	7567383	D3020	<b>Boiler Supplemental Components</b>	Expansion Tank	106 GAL	Westover Hills Elementary School / Main Building	Boiler room	Bell & Gossett	B400	228969	2011	<a href="https://rvaschools.gofmx.com/equipment/1560943">https://rvaschools.gofmx.com/equipment/1560943</a>	
9	7567384	D3020	<b>Boiler Supplemental Components</b>	Expansion Tank	106 GAL	Westover Hills Elementary School / Main Building	Boiler room	Bell & Gossett	B400	228459	2011	<a href="https://rvaschools.gofmx.com/equipment/1560963">https://rvaschools.gofmx.com/equipment/1560963</a>	
10	7567460	D3020	<b>Boiler Supplemental Components</b>	Expansion Tank	106 GAL	Westover Hills Elementary School / Main Building	Boiler room	Bell & Gossett	B400	229087	2011	<a href="https://rvaschools.gofmx.com/equipment/1560903">https://rvaschools.gofmx.com/equipment/1560903</a>	
11	7567475	D3030	<b>Heat Pump</b>	Packaged & Wall-Mounted, 3.5 to 4 TON	3.5 TON	Westover Hills Elementary School / Main Building	Modular A	Inaccessible	Inaccessible	Inaccessible	1992	<a href="https://rvaschools.gofmx.com/equipment/1560944">https://rvaschools.gofmx.com/equipment/1560944</a>	
12	7567417	D3030	<b>Packaged Terminal Air Conditioner</b>	PTAC	3 TON	Westover Hills Elementary School / Main Building	Trailer	Marvaire	Illegible	Illegible	1992	<a href="https://rvaschools.gofmx.com/equipment/1560964">https://rvaschools.gofmx.com/equipment/1560964</a>	
13	7567435	D3030	<b>Split System</b>	Condensing Unit/Heat Pump 4 TON		Westover Hills Elementary School / Main Building	Roof	Illegible	Illegible	2514X736		<a href="https://rvaschools.gofmx.com/equipment/1560958">https://rvaschools.gofmx.com/equipment/1560958</a>	
14	7567289	D3030	<b>Split System</b>	Condensing Unit/Heat Pump 4 TON		Westover Hills Elementary School / Main Building	Roof	Allegiance			2001	<a href="https://rvaschools.gofmx.com/equipment/1560939">https://rvaschools.gofmx.com/equipment/1560939</a>	
15	7567335	D3030	<b>Split System</b>	Condensing Unit/Heat Pump, 4 TON	4 TON	Westover Hills Elementary School / Main Building	Roof	Allegiance			2001	<a href="https://rvaschools.gofmx.com/equipment/1560936">https://rvaschools.gofmx.com/equipment/1560936</a>	
16	7567389	D3030	<b>Split System</b>	Fan Coil Unit, DX	1.5 TON	Westover Hills Elementary School / Main Building	Room 29	Trane	BAHB-509E-A	C810 29807	1955	<a href="https://rvaschools.gofmx.com/equipment/1574788">https://rvaschools.gofmx.com/equipment/1574788</a>	

17	7567319	D3030	<b>Split System Ductless</b>	Single Zone, 1.5 to 2 TON	2 TON	Westover Hills Elementary School / Main Building	Roof 14	Mitsubishi Electric	PUY-A24NHA4	Illegible	2011	<a href="https://rvaschools.gofmx.com/equipment/1574768">https://rvaschools.gofmx.com/equipment/1574768</a>	
18	7567471	D3030	<b>Split System Ductless</b>	Single Zone, 1.5 to 2 TON	2 TON	Westover Hills Elementary School / Main Building	Roof - 5	Mitsubishi Electric	PUY-A24NHA4	0ZU0240B	2012	<a href="https://rvaschools.gofmx.com/equipment/1574700">https://rvaschools.gofmx.com/equipment/1574700</a>	
19	7567326	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2.5 TON	Westover Hills Elementary School / Main Building	Roof 22	Mitsubishi Electric	PUY-A30NHA4	1ZU01899A	2011	<a href="https://rvaschools.gofmx.com/equipment/1560916">https://rvaschools.gofmx.com/equipment/1560916</a>	
20	7567354	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	3 TON	Westover Hills Elementary School / Main Building	Roof - 9	Mitsubishi Electric	PUY-A36NHA4	1ZU05772B	2012	<a href="https://rvaschools.gofmx.com/equipment/1560930">https://rvaschools.gofmx.com/equipment/1560930</a>	
21	7567298	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2 TON	Westover Hills Elementary School / Main Building	Roof - 2	Mitsubishi Electric	PUY-A42NHA4	04U02096C	2010	<a href="https://rvaschools.gofmx.com/equipment/1574797">https://rvaschools.gofmx.com/equipment/1574797</a>	
22	7567442	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2 TON	Westover Hills Elementary School / Main Building	Roof - 3	Mitsubishi Electric	PUYA42MHA	Inaccessible	2012	<a href="https://rvaschools.gofmx.com/equipment/1574795">https://rvaschools.gofmx.com/equipment/1574795</a>	
23	7567291	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	3 TON	Westover Hills Elementary School / Main Building	Roof - 6	Mitsubishi Electric	PUY-A36NHA4	1ZU05622B	2011	<a href="https://rvaschools.gofmx.com/equipment/1574793">https://rvaschools.gofmx.com/equipment/1574793</a>	
24	7567392	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2.5 TON	Westover Hills Elementary School / Main Building	Roof - 20	Mitsubishi Electric	PUY-A30NHA4	1ZU01833A	2011	<a href="https://rvaschools.gofmx.com/equipment/1574648">https://rvaschools.gofmx.com/equipment/1574648</a>	
25	7567430	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	3 TON	Westover Hills Elementary School / Main Building	Roof - 8	Mitsubishi Electric	PUY-A36NHA4	12U05774B	2011	<a href="https://rvaschools.gofmx.com/equipment/1574816">https://rvaschools.gofmx.com/equipment/1574816</a>	
26	7567357	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2.5 TON	Westover Hills Elementary School / Main Building	Roof - 24	Mitsubishi Electric	PUY-A30NHA4	1XU01635A	2011	<a href="https://rvaschools.gofmx.com/equipment/1560920">https://rvaschools.gofmx.com/equipment/1560920</a>	
27	7567423	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	3.5 TON	Westover Hills Elementary School / Main Building	Roof -- 1	Mitsubishi Electric	Inaccessible	Inaccessible	2011	<a href="https://rvaschools.gofmx.com/equipment/1574796">https://rvaschools.gofmx.com/equipment/1574796</a>	
28	7567422	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	3 TON	Westover Hills Elementary School / Main Building	Roof - 13	Mitsubishi Electric	Inaccessible	Inaccessible	2012	<a href="https://rvaschools.gofmx.com/equipment/1560898">https://rvaschools.gofmx.com/equipment/1560898</a>	
29	7567279	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2.5 TON	Westover Hills Elementary School / Main Building	Roof - 17	Mitsubishi Electric	Inaccessible	Inaccessible	2012	<a href="https://rvaschools.gofmx.com/equipment/1574787">https://rvaschools.gofmx.com/equipment/1574787</a>	
30	7567381	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2.5 TON	Westover Hills Elementary School / Main Building	Roof - 19	Mitsubishi Electric	Inaccessible	Inaccessible	2011	<a href="https://rvaschools.gofmx.com/equipment/1574688">https://rvaschools.gofmx.com/equipment/1574688</a>	
31	7567339	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2.5 TON	Westover Hills Elementary School / Main Building	Roof - 16	Mitsubishi Electric	PUY-A30NHA4	1ZU01372A	2012	<a href="https://rvaschools.gofmx.com/equipment/1574951">https://rvaschools.gofmx.com/equipment/1574951</a>	
32	7567371	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2.5 TON	Westover Hills Elementary School / Main Building	Roof - 11	Mitsubishi Electric	PUY-A30NHA4	1ZU01871A	2012	<a href="https://rvaschools.gofmx.com/equipment/1560906">https://rvaschools.gofmx.com/equipment/1560906</a>	
33	7567461	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	3.5 TON	Westover Hills Elementary School / Main Building	Roof - 5	Mitsubishi Electric	Inaccessible	Inaccessible	2012	<a href="https://rvaschools.gofmx.com/equipment/1574790">https://rvaschools.gofmx.com/equipment/1574790</a>	
34	7567317	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2.5 TON	Westover Hills Elementary School / Main Building	Roof - 23	Mitsubishi Electric	PYY-A30NHA4	1ZU01900A	2012	<a href="https://rvaschools.gofmx.com/equipment/1560899">https://rvaschools.gofmx.com/equipment/1560899</a>	
35	7567463	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2.5 TON	Westover Hills Elementary School / Main Building	Roof - 0	Mitsubishi Electric	PUY-A30NHA4	1ZU01846A	2012	<a href="https://rvaschools.gofmx.com/equipment/1560924">https://rvaschools.gofmx.com/equipment/1560924</a>	
36	7567458	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2.5 TON	Westover Hills Elementary School / Main Building	Roof - 21	Mitsubishi Electric	PUY-A30NHA4	1ZU01845A	2012	<a href="https://rvaschools.gofmx.com/equipment/1574729">https://rvaschools.gofmx.com/equipment/1574729</a>	
37	7567424	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	3 TON	Westover Hills Elementary School / Main Building	Ropof - 7	Mitsubishi Electric	PUY-A36NHA4	1ZU05777B	2012	<a href="https://rvaschools.gofmx.com/equipment/1574817">https://rvaschools.gofmx.com/equipment/1574817</a>	
38	7567352	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	3.5 TON	Westover Hills Elementary School / Main Building	Roof - 4	Mitsubishi Electric	Inaccessible	Inaccessible	2012	<a href="https://rvaschools.gofmx.com/equipment/1574811">https://rvaschools.gofmx.com/equipment/1574811</a>	
39	7567450	D3030	<b>Split System Ductless</b>	Single Zone, 2.5 to 3 TON	2.5 TON	Westover Hills Elementary School / Main Building	Roof - 12	Mitsubishi Electric	PUY-A30NHA4	1ZU01895A	2012	<a href="https://rvaschools.gofmx.com/equipment/1560902">https://rvaschools.gofmx.com/equipment/1560902</a>	
40	7567419	D3030	<b>Unit Ventilator</b>	approx/nominal 4 Ton	1251 CFM	Westover Hills Elementary School / Main Building	Throughout classrooms	Nesbitt			1955	<a href="https://rvaschools.gofmx.com/equipment/1574815">https://rvaschools.gofmx.com/equipment/1574815</a>	24

41	7567456	D3050	Pump	Distribution, HVAC Heating Water	5 HP	Westover Hills Elementary School / Main Building	Boiler room	Bell & Gossett	Illegible	C130680-02H11	2014	<a href="https://rvaschools.gofmx.com/equipment/1560932">https://rvaschools.gofmx.com/equipment/1560932</a>
42	7567402	D3050	Pump	Distribution, HVAC Heating Water	1.5 HP	Westover Hills Elementary School / Main Building	Boiler room	WEG	001580P3E 145JMV		2010	<a href="https://rvaschools.gofmx.com/equipment/1560935">https://rvaschools.gofmx.com/equipment/1560935</a>
43	7567294	D3050	Pump	Distribution, HVAC Heating Water	5 HP	Westover Hills Elementary School / Main Building	Boiler room	Bell & Gossett	NA	C133680-01811	2014	<a href="https://rvaschools.gofmx.com/equipment/1560912">https://rvaschools.gofmx.com/equipment/1560912</a>
44	7567455	D3050	Pump	Distribution, HVAC Heating Water	1.5 HP	Westover Hills Elementary School / Main Building	Boiler room	WEG	001580P3E 145JMV	NA	2014	<a href="https://rvaschools.gofmx.com/equipment/1560915">https://rvaschools.gofmx.com/equipment/1560915</a>
45	7567360	D3050	Fan Coil Unit	Hydronic Terminal	400 CFM	Westover Hills Elementary School / Main Building	29				2014	
46	7567307	D3060	Exhaust Fan	Centrifugal, 12" Damper	500 CFM	Westover Hills Elementary School / Main Building	Roof	No dataplate	No dataplate	No dataplate	2004	11
47	7567453	D3060	Exhaust Fan	Centrifugal, 16" Damper	1001 CFM	Westover Hills Elementary School / Main Building	Roof	Illegible	Illegible	Illegible		<a href="https://rvaschools.gofmx.com/equipment/1560960">https://rvaschools.gofmx.com/equipment/1560960</a>
48	7567408	D3060	Exhaust Fan	Centrifugal, 16" Damper	1100 CFM	Westover Hills Elementary School / Main Building	Roof	No dataplate	No dataplate	No dataplate	2000	<a href="https://rvaschools.gofmx.com/equipment/1560962">https://rvaschools.gofmx.com/equipment/1560962</a>
49	7567361	D3060	Exhaust Fan	Centrifugal, 16" Damper	2000 CFM	Westover Hills Elementary School / Main Building	Roof	No dataplate	No dataplate	No dataplate	2000	<a href="https://rvaschools.gofmx.com/equipment/1560967">https://rvaschools.gofmx.com/equipment/1560967</a>
50	7567474	D3060	Exhaust Fan	Centrifugal, 16" Damper	1100 CFM	Westover Hills Elementary School / Main Building	Roof	No dataplate	No dataplate	No dataplate	2000	<a href="https://rvaschools.gofmx.com/equipment/1560942">https://rvaschools.gofmx.com/equipment/1560942</a>
51	7567478	D3060	Exhaust Fan	Centrifugal, 16" Damper	1100 CFM	Westover Hills Elementary School / Main Building	Roof	No dataplate	No dataplate	No dataplate	2000	<a href="https://rvaschools.gofmx.com/equipment/1560959">https://rvaschools.gofmx.com/equipment/1560959</a>
52	7567350	D3060	Exhaust Fan	Centrifugal, 16" Damper	1100 CFM	Westover Hills Elementary School / Main Building	Roof	No dataplate	No dataplate	No dataplate	2000	<a href="https://rvaschools.gofmx.com/equipment/1560940">https://rvaschools.gofmx.com/equipment/1560940</a>
53	7567413	D3060	Exhaust Fan	Centrifugal, 24" Damper	5000 CFM	Westover Hills Elementary School / Main Building	Roof	No dataplate	No dataplate	No dataplate	2000	<a href="https://rvaschools.gofmx.com/equipment/1560937">https://rvaschools.gofmx.com/equipment/1560937</a>
54	7567309	D3060	Exhaust Fan	Centrifugal, 24" Damper	5000 CFM	Westover Hills Elementary School / Main Building	Roof	No dataplate	No dataplate	No dataplate	2000	<a href="https://rvaschools.gofmx.com/equipment/1560956">https://rvaschools.gofmx.com/equipment/1560956</a>
55	7567412	D3060	Exhaust Fan	Centrifugal, 24" Damper	5000 CFM	Westover Hills Elementary School / Main Building	Roof	NA	NA	NA	2000	<a href="https://rvaschools.gofmx.com/equipment/1560938">https://rvaschools.gofmx.com/equipment/1560938</a>
56	7568489	D3060	Supplemental Components	Air Purifier, Electrostatic, 2000 CFM	600 CFM	Westover Hills Elementary School / Main Building	Throughout				2021	33

**D40 Fire Protection**

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	7567449	D4010	Fire Suppression System	Commercial Kitchen, per LF of Hood		Westover Hills Elementary School / Main Building	Kitchen exhaust hood				1955		16

**D50 Electrical**

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	7567457	D5010	Generator	Diesel	50 KW	Westover Hills Elementary School / Main Building	Site	Kohler	No dataplate	No dataplate	1955	<a href="https://rvaschools.gofmx.com/equipment/1560946">https://rvaschools.gofmx.com/equipment/1560946</a>	
2	7567437	D5020	Distribution Panel	120/208 V	800 AMP	Westover Hills Elementary School / Main Building	Electric equipment	Square D			1955	<a href="https://rvaschools.gofmx.com/equipment/1560913">https://rvaschools.gofmx.com/equipment/1560913</a>	
3	7567376	D5020	Distribution Panel	120/208 V	600 AMP	Westover Hills Elementary School / Main Building	Boiler room	Westinghouse	NA	NA	1955	<a href="https://rvaschools.gofmx.com/equipment/1560931">https://rvaschools.gofmx.com/equipment/1560931</a>	
4	7567380	D5020	Distribution Panel	120/240 V	200 AMP	Westover Hills Elementary School / Main Building	Trailer	Westinghouse			1992		

**D70 Electronic Safety & Security**

Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
-------	----	--------	-----------------------	------------	----------	----------	-----------------	--------------	-------	--------	--------------	---------	-----



1	7567338	D7050	<b>Fire Alarm Panel</b>	Fully Addressable		Westover Hills Elementary School / Main Building	Office	NA	FS-250	NA	2005	<a href="https://rvaschools.gofmx.com/equipment/1560955">https://rvaschools.gofmx.com/equipment/1560955</a>	
<b>E10 Equipment</b>													
Index	ID	UFCode	Component Description	Attributes	Capacity	Building	Location Detail	Manufacturer	Model	Serial	Dataplate Yr	Barcode	Qty
1	7567314	E1030	<b>Foodservice Equipment</b>	Convection Oven, Single		Westover Hills Elementary School / Main Building	Kitchen	Garland		0511100217364	2005	<a href="https://rvaschools.gofmx.com/equipment/1561015">https://rvaschools.gofmx.com/equipment/1561015</a>	
2	7567454	E1030	<b>Foodservice Equipment</b>	Convection Oven, Single		Westover Hills Elementary School / Main Building	Kitchen	Garland		0511100217294	2005	<a href="https://rvaschools.gofmx.com/equipment/1560995">https://rvaschools.gofmx.com/equipment/1560995</a>	
3	7567464	E1030	<b>Foodservice Equipment</b>	Dairy Cooler/Wells		Westover Hills Elementary School / Main Building	Kitchen	Beverage-Air Corporation	ST34N-S	12006016	2016	<a href="https://rvaschools.gofmx.com/equipment/1560973">https://rvaschools.gofmx.com/equipment/1560973</a>	
4	7567459	E1030	<b>Foodservice Equipment</b>	Dairy Cooler/Wells		Westover Hills Elementary School / Main Building	Kitchen	Beverage-Air Corporation	SMF34Y	NA	2010	<a href="https://rvaschools.gofmx.com/equipment/1560952">https://rvaschools.gofmx.com/equipment/1560952</a>	
5	7567393	E1030	<b>Foodservice Equipment</b>	Exhaust Hood, 8 to 10 LF		Westover Hills Elementary School / Main Building	Kitchen	No dataplate	No dataplate	No dataplate	1995	<a href="https://rvaschools.gofmx.com/equipment/1560994">https://rvaschools.gofmx.com/equipment/1560994</a>	
6	7567382	E1030	<b>Foodservice Equipment</b>	Food Warmer, Proofing Cabinet on Wheels		Westover Hills Elementary School / Main Building	Kitchen	Metro	NA	C5HME033998	2019	<a href="https://rvaschools.gofmx.com/equipment/1561011">https://rvaschools.gofmx.com/equipment/1561011</a>	
7	7567302	E1030	<b>Foodservice Equipment</b>	Food Warmer, Proofing Cabinet on Wheels		Westover Hills Elementary School / Main Building	Kitchen	Cres Cor	NA	DBC-J285078-10	2010	<a href="https://rvaschools.gofmx.com/equipment/1560970">https://rvaschools.gofmx.com/equipment/1560970</a>	
8	7567332	E1030	<b>Foodservice Equipment</b>	Food Warmer, Tabletop Drawers (Set of 4)		Westover Hills Elementary School / Main Building	Kitchen	Delfield	ECOMARK000-40013F7R2TEM	2306820101392	2023	<a href="https://rvaschools.gofmx.com/equipment/1560972">https://rvaschools.gofmx.com/equipment/1560972</a>	
9	7567398	E1030	<b>Foodservice Equipment</b>	Food Warmer, Tabletop Drawers (Set of 4)		Westover Hills Elementary School / Main Building	Kitchen	Randell	9560-4M	T34372-1-5	1995	<a href="https://rvaschools.gofmx.com/equipment/1560974">https://rvaschools.gofmx.com/equipment/1560974</a>	
10	7567414	E1030	<b>Foodservice Equipment</b>	Freezer, 2-Door Reach-In		Westover Hills Elementary School / Main Building	Kitchen	Traulsen	G22010	T43016A07	2007	<a href="https://rvaschools.gofmx.com/equipment/1560950">https://rvaschools.gofmx.com/equipment/1560950</a>	
11	7567379	E1030	<b>Foodservice Equipment</b>	Freezer, 2-Door Reach-In		Westover Hills Elementary School / Main Building	Kitchen	Delfield	GBF2P-S	1120528566	2021	<a href="https://rvaschools.gofmx.com/equipment/1561009">https://rvaschools.gofmx.com/equipment/1561009</a>	
12	7567356	E1030	<b>Foodservice Equipment</b>	Freezer, 2-Door Reach-In		Westover Hills Elementary School / Main Building	Kitchen	Delfield	GCF2-S	1120213188	2016	<a href="https://rvaschools.gofmx.com/equipment/1560990">https://rvaschools.gofmx.com/equipment/1560990</a>	
13	7567415	E1030	<b>Foodservice Equipment</b>	Freezer, 2-Door Reach-In		Westover Hills Elementary School / Main Building	Kitchen	Traulsen	G22010	T1808 G12	2012	<a href="https://rvaschools.gofmx.com/equipment/1560991">https://rvaschools.gofmx.com/equipment/1560991</a>	
14	7567440	E1030	<b>Foodservice Equipment</b>	Prep Table Refrigerated, Salad/Sandwich		Westover Hills Elementary School / Main Building	Kitchen	Delfield	SCFT-60-NUP	2306820101393	2023	<a href="https://rvaschools.gofmx.com/equipment/1560953">https://rvaschools.gofmx.com/equipment/1560953</a>	
15	7567280	E1030	<b>Foodservice Equipment</b>	Refrigerator, 2-Door Reach-In		Westover Hills Elementary School / Main Building	Kitchen	Delfield	GBR2P-S	: 2212820200967	2022	<a href="https://rvaschools.gofmx.com/equipment/1560969">https://rvaschools.gofmx.com/equipment/1560969</a>	
16	7567373	E1030	<b>Foodservice Equipment</b>	Refrigerator, 2-Door Reach-In		Westover Hills Elementary School / Main Building	Kitchen	Traulsen	G20010	T45747H13	2013	<a href="https://rvaschools.gofmx.com/equipment/1560948">https://rvaschools.gofmx.com/equipment/1560948</a>	
17	7567305	E1030	<b>Foodservice Equipment</b>	Refrigerator, 2-Door Reach-In		Westover Hills Elementary School / Main Building	Kitchen	Raetone	SR-47-S2	B-7634R57	1995	<a href="https://rvaschools.gofmx.com/equipment/1560971">https://rvaschools.gofmx.com/equipment/1560971</a>	
18	7567297	E1030	<b>Foodservice Equipment</b>	Refrigerator, 2-Door Reach-In		Westover Hills Elementary School / Main Building	Kitchen	Traulsen	G20010	T168439H11	2011	<a href="https://rvaschools.gofmx.com/equipment/1561010">https://rvaschools.gofmx.com/equipment/1561010</a>	
19	7567340	E1030	<b>Foodservice Equipment</b>	Refrigerator, 2-Door Reach-In		Westover Hills Elementary School / Main Building	Kitchen	Traulsen	G22010	T31937A10	2010	<a href="https://rvaschools.gofmx.com/equipment/1560951">https://rvaschools.gofmx.com/equipment/1560951</a>	
20	7567321	E1030	<b>Foodservice Equipment</b>	Refrigerator, 2-Door Reach-In		Westover Hills Elementary School / Main Building	Kitchen	Delfield	CSRR12P-S	1707152002794	2017	<a href="https://rvaschools.gofmx.com/equipment/1560989">https://rvaschools.gofmx.com/equipment/1560989</a>	
21	7567429	E1030	<b>Foodservice Equipment</b>	Refrigerator, 3-Door Reach-In		Westover Hills Elementary School / Main Building	Kitchen	Traulsen	G30010	T08479J05	2008	<a href="https://rvaschools.gofmx.com/equipment/1560954">https://rvaschools.gofmx.com/equipment/1560954</a>	
22	7567418	E1030	<b>Foodservice Equipment</b>	Steamer, Tabletop		Westover Hills Elementary School / Main Building	Kitchen	Convotherm	WS20002AA2AAUL	WS216061535	2021	<a href="https://rvaschools.gofmx.com/equipment/1560988">https://rvaschools.gofmx.com/equipment/1560988</a>	