**OVERVIEW** 

FACILITY CONDITION ASSESSMENT

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

**COST SUMMARY** 



2700 Fountain Oaks Dr. Morgan Hill, Ca 95037 | jackson.mhusd.org

Year Built: 1977

Year Modernized: 2014-2016 (roof, restrooms,

mechanical systems, EMS)

Student Population (2016 - 2017): 567

Number of Classrooms: 25 Number of Portables: 5 Site Acreage: 9 acres

Building Area: 39,084 square feet

#### PRINCIPAL'S TOP 3 'WANTS'

- Cafeteria / Cafetorium
- Gvmnasium
- 3. Parking / traffic flow / fencing safety / directionality

# **Desired Program Support Improvements/Additions**

- Storage
  - PΕ
  - Art
  - Book room
- Science lab
- Student support spaces:
  - Counseling
  - Psychology
  - RSP
  - Pull-out rooms
  - Discovery counseling / intern
  - CALSOAP (college & career)
- Gymnasium

# **Functionality of Space**

Administration is tucked to the side of a hallway which enables parents/visitors to bypass the front desk.

# **ASSESSMENT RATING LEGEND:**

CATEGORY [0] No Work CATEGORY [1] Minor Work

Minor Modernization CATEGORY [2] CATEGORY [3] Standard Modernization CATEGORY [4] Major Modernization /

Reconfiguration

CATEGORY [5] Complete Replacement

# GENERAL ADA Compliance

Category [4]

Paved areas of the site appear to be at a slope that is steeper than current code permits and should be studied for regrading.

# **Parking**

Category [4]

Parking lot is reported to be undersized.

# **Concrete Paving**

Category [0]

- Concrete paving is in good condition at the outdoor dining area and seatwalls.
- Concrete paving is patchy at areas adjacent to buildings and is in fairly good condition.

# AC paving

Category [3]

 AC paving in parking lot and blacktop areas are in poor condition and need a new slurry coat and seal.

## Ramps & Stairs

Category [5]

Large ramp exists between upper and lower hardcourt areas and shows signs of cracking and uneven pavement.

**OVERVIEW** 

**FACILITY CONDITION ASSESSMENT** 

**EXISTING CAMPUS PLAN** 

CONCEPTUAL MASTER PLAN

**COST SUMMARY** 

## **ASSESSMENT RATING LEGEND:**

CATEGORY [0] No Work CATEGORY [1] Minor Work

Minor Modernization CATEGORY [2] CATEGORY [3] Standard Modernization CATEGORY [4] Major Modernization /

Reconfiguration

CATEGORY [5] Complete Replacement

# SITE AMENITIES

# **Drinking Fountains**

Category [5]

Drinking fountains are in poor condition; replacement is desired.

# **Shade Shelter**

Category [0]

- The site does not currently have a shade shelter.
- Shade shelters, covered walkways, building overhangs are desired.

#### Bike Area

Category [0]

No issues were observed or reported.

## **Covered Walkways**

Category [0]

This condition does not currently exist.

#### **Play Structures**

Category [0]

No issues were observed or reported.

#### Athletic Fields & Facilities

Category [0]

No issues were observed or reported.

## Landscape

Category [2]

 Many planter areas are in poor condition and need to be replanted.

#### Irrigation

Category [5]

- Irrigation controller needs to be updated.
- Backflow preventer needs to be replaced.

# Fencing & Gates

Category [0]

This condition does not currently exist.

#### ASSESSMENT OF BUILDINGS

#### Exterior

# **Paint**

Category [3]

The site is due for a fresh coat of paint.

#### Door / Frames / Locks

Category [2]

 Doors and frames appear to be original. Some exterior doors are in poor condition

#### Windows

Category [5]

Windows are original to the buildings; are single pane with wire glass. Replacement is recommended if buildings are to remain long-term.

#### Roof

Category [0]

Roof was replaced in 2014-2016.

# **ADA Compliance**

Category [3]

Exterior door thresholds do not have a smooth transition to adjacent paving.

#### Interior

Overall Rating: Category [-]

- Wall panels are original and outdated.
- Wall panel is damaged near the exterior door of room 9.

#### **Food Service**

Category [5]

- The heat-and-serve kitchen is extremely small.
- A hallway is used for the serving area.

## Restrooms

Category [0]

Restrooms have recently been modernized.

#### **ASSESSMENT OF SYSTEMS**

Site Utilities

**Domestic Water** 

Category [5]

Backflow preventer needs to be replaced.

# Fire Protection

Category [0]

No issues were observed or reported.

## Gas

Category [0]

No issues were observed or reported.

# Sewer

Category [0]

No issues were observed or reported.

## Storm Drain / Drainage

Category [0]

No issues were observed or reported.



# 5.3 JACKSON ACADEMY OF MATH & MUSIC

**OVERVIEW** 

**FACILITY CONDITION ASSESSMENT** 

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN

**COST SUMMARY** 

## **ASSESSMENT RATING LEGEND:**

CATEGORY [0] No Work
CATEGORY [1] Minor Work

CATEGORY [2] Minor Modernization
CATEGORY [3] Standard Modernization
CATEGORY [4] Major Modernization /

Reconfiguration

**CATEGORY** [5] Complete Replacement

#### Mechanical

Category [0]

· No issues were observed or reported.

# **Plumbing**

Category [0]

- Restrooms were recently modernized.
- · Isolation shut-off valves are needed at each building.

#### **Electrical**

#### Power

Category [0]

No issues were observed or reported.

#### Fire Alarm

Category [3]

Fire alarm panel needs to be replaced.

#### **Technology**

Category [0]

No issues were observed or reported.

#### Intercom / Clock / Bell

Category [0]

· No issues were observed or reported.

#### Security

Category [4]

 Not all security cameras are operational and need to be repaired and/or supplemented with additional cameras for full site coverage.

## Lighting

Category [0]

- No issues were observed or reported for the interior lighting.
- Security lighting is needed in the parking lot.

**OVERVIEW** 

**FACILITY CONDITION ASSESSMENT** 

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN







Parking



Typical Concrete Paving



Outdoor Dining



Hardcourts



Play Structure



Landscaping

**OVERVIEW** 

FACILITY CONDITION ASSESSMENT

**EXISTING CAMPUS PLAN** 

CONCEPTUAL MASTER PLAN



Windows



Exterior Door Hardware



Administration Office




Staff Work Room / Lounge



Counseling Office



Multipurpose Room



Kitchen



Food Serving Area

**OVERVIEW** 

**FACILITY CONDITION ASSESSMENT** 

EXISTING CAMPUS PLAN

CONCEPTUAL MASTER PLAN



Typical Classroom



Media Center



Restroom



Health Office



Teacher Prep Room



Special Feature: Piano Lab

**OVERVIEW** 

FACILITY CONDITION ASSESSMENT

**EXISTING CAMPUS PLAN** 

CONCEPTUAL MASTER PLAN





**OVERVIEW** 

FACILITY CONDITION ASSESSMENT

**EXISTING CAMPUS PLAN** 

CONCEPTUAL MASTER PLAN





# 5.3 JACKSON ACADEMY OF MATH & MUSIC

FACILITY CONDITION ASSESSMENT

**OVERVIEW** 

**EXISTING CAMPUS PLAN** 

**MASTER PLAN COST SCOPE OF WORK CATEGORIES** (2017\$)1. Modernize / Reconfigure Existing Classrooms \$ Existing Building Systems, Toilets & Improved Energy Efficiency \$ Site Utilities \$ 354.000 New Construction (Classrooms) \$ 19,639,000 Science, Arts, CTE & Electives Programs \$ 3,959,000 Performing Arts Improvements \$ 1,627,000 MPR, Student Union & Food Service Improvements \$ 9.815.000 Physical Education Improvements \$ 862,000 Staff & Parent Support \$ 5,789,000 10. Media Center & Student Support Services \$ 6,204,000 1,495,000 11. Safety & Security \$ 12. Parking & Drop-Off \$ 1,049,000 13. Outdoor Learning Courts, Quads & Landscape \$ 257,000 Exterior Play Spaces, Playfields & Hardcourts \$ 2,525,000 Instructional Design Furniture \$ 900,000 16. Technology Infrastructure and Equipment \$ **Total Construction / Project Cost (2017\$)** 54,475,000

The following items are excluded from this budget:

**COST SUMMARY** 

- Utility hook-up fees & City connection fees
- Off-site work and traffic signals
- Land acquisition costs

CONCEPTUAL MASTER PLAN

- Hazardous material surveys, abatement and disposal
- Escalation (costs are in 2017\$)