





Front Entrance – Southwest Elevation; Roof work continues on awning

West Elevation; Frames installed on classroom wing staircases



East Elevation; Frames installed in learning commons



Grand Hall – North Facing View; Framing, mechanical, insulation and drywall install continues



Grand Hall – North Facing View; Framing, mechanical, insulation and drywall install continues



Reception Area – Electrical,
and drywall install continues



South Classroom Wing (lower level) – West Facing View;
mechanical work continues. Painting to begin soon



South Classroom Wing (lower level) – Classroom; drywall complete.
Painting to begin soon



Learning Commons – Window frames newly installed. Framing and insulation of walls continue



North Classroom Wing (lower level) – West Facing View; Painting continues

North Classrooms Wing – Classroom; Painting continues





North Classroom Wing (upper level) – West Facing View; Painting continues



North Classroom Wing (upper level) – Classroom; Painting continues. Ceiling grid being installed

South Classroom Wing (upper level)
– Classroom; Drywall being installed

