



CBRE April 2, 2018



Front Entrance – Southwest Elevation; Brick, windows, and frames install continues




West Elevation; Brick installed. Windows and frames install continues



East Elevation; Brick, windows, and frames install continues





Grand Hall – North Facing View; Framing, mechanical, insulation and drywall install continues

Grand Hall – South Facing View; Framing, mechanical, insulation and drywall install continues



Grand Hall – North Facing View; Framing, mechanical, insulation and drywall install continues








Office Area – Electrical, mechanical, insulation, and drywall install continues



South Classroom Wing (lower level) – West Facing View; Insulation and drywall install continues



Gym - Mechanical work continues





Kitchen and Cafeteria – Framing and insulation install continues



North Classrooms Wing - Conference Room - Data cabling being installed



North Classroom Wing (lower level) – West Facing View; Framing and painting continues





North Classroom Wing (upper level) – West Facing View; Drywall for soffit finishing, painting in progress

North Classroom Wing (upper level) – Painting in progress



South Classroom Wing (upper level)

– West Facing View; Framing,
insulation, drywall, and window
frames install in progress



