




CBRE April 23, 2018



Front Entrance – South Elevation; Sitework in progress.

Sitework in progress.



East Elevation -








Grand Hall – North Facing View Adjacent to Gym; HVAC, electrical, insulation and drywall install continues.

Grand Hall – North Facing View; HVAC, electrical, framing, insulation and drywall install continues.







Gym – Framing install on stage/music room.

South Classroom Wing (lower level) –Painting in progress.






CBRE GYM, OFFICE AREA & SOUTH CLASSROOM WING (L1)

Learning Commons - Framing continues.

Cafeteria – Drywall and HVAC install continues.



North Classroom Wing (lower level) - Classroom; Ceiling install and painting in progress.



CBRE CAFETERIA, COMMONS & NORTH CLASSROOM WING (L1)



North Classroom Wing (upper level) – Teacher Restroom; Floor tile install.

North Classroom Wing (upper level) – Classroom; Ceiling install and painting in progress.



South Classroom Wing (upper level)

– Stairwell; Insulation and drywall install.



