



Clayton Construction Report  
May 7, 2018





Front Entrance – South Facing View; Sitework continues.



West Elevation – Plaza  
Between Classroom Wings;  
Sitework continues.





Grand Hall – North Facing View; HVAC, electrical, and drywall install continues.

Grand Hall – South Facing View; 2<sup>nd</sup> Floor windows newly installed.





Gym – Painting in progress. Stage currently framing for drywall.

Main Entrance – Entry doors newly installed.




South Classroom Wing (lower level) – Tilework to begin soon.







Learning Commons –Drywall install continues.



North Classroom Wing (lower level) – Restrooms; Floor tile install continues.



North Classroom Wing (lower level) – Wall tile install continues.



North Classroom Wing (upper level) – Wall tile install continues.

North Classroom Wing (upper level) – Light fixtures newly installed and wall tile complete.



North Classroom Wing (upper level) – Glass in classroom newly installed.

