







South Elevation – Main Entrance; Concrete and site work continues.



West Elevation – West Facing View; Concrete and site work continues.





Grand Hall – South Facing View; Ceiling tile install and painting in progress.



Grand Hall – South Facing View; Electrical work and painting in progress.





Office Area Hallway – Flooring newly installed.



South Classroom Wing (L1) – Hallway; Floor being installed. Tile work recently completed.



GYM, OFFICE AREA & SOUTH CLASSROOM WING (L1)



Learning Commons – Painting, HVAC and electrical work continues. Exterior tile recently completed.



North Classroom Wing (L1) – Carpet install continues.



North Classroom Wing (L1) – Classroom; Boards recently installed.





North Classroom Wing (upper level) – Carpet plastic cover recently removed.



South Classroom Wing (upper level) – Carpet recently installed.