



Maddox ECE Construction Report

April 16, 2018



Looking East across building (left). Entry vestibule (right).



Forming South Central body.



Underground IT conduit from MDF to Storage Rooms (left). IT conduit coming up to Teaching Wall (right).



Roof drain to underground storm drain.



Transformer set (left). Conduit to Electrical room (right).



Mock up wall progression.