



Maddox ECE Construction Report May 7, 2018

Crane has been erected to install steel.





Looking West across building, steel columns installed.



East wing with steel columns and floor slab.



Looking South across entire building footprint.