



## Maddox ECE Construction Report

May 7, 2018



Looking West across East wing. Steel structure placed around indoor playground area.





Looking North across central body.





Vapor barrier and radiant heating installed on East wing.





Looking East across building.

Mock-up wall progression.







Lifting in beams with crane (left). Signed beam to be placed in Director's office (right).