



## Maddox ECE Construction Report May 7, 2018



Glulam (glued laminated timber) beam installation.



Looking West. Glulams installed on East wing.



Looking North across central body (left). Interior of central body (right).





Looking East across building.



Leaving behind a few handprints.