



## Maddox ECE Construction Report June 18, 2018



East classrooms being framed.



East wing.



Windows framed.



Rain chain/benches.



Central body, looking at main entrance area.



Looking North across central body. Plumbing trenches underway.