



Maddox ECE Construction Report


June 11, 2018



Looking across West wing.



View of Southeast classrooms.



Acoustic deck installed on East wing.



Central body, looking at main entrance area.



Looking North across central body. Plumbing trenches underway.