



Maddox ECE Construction Report

August 20, 2018



Main Entrance Area.

Soffits at Multipurpose Openings.



Insulation & Drywall
in East wing.





East wing Classroom.



East wing exterior.



West wing exterior.