



Maddox ECE Construction Report

July 2, 2018



Brick being installed on East wing.



East Wing facing West.



West wing facing East.



Central body looking south at main entrance.



Almost ready to pour slab in Central body.



Central body, looking at main entrance area.