



Maddox ECE Construction Report

July 9, 2018



Brick being installed on East wing.



East Wing facing East.



West Wing facing West.



Drywall being installed in classrooms.



Central body looking south at main entrance. Central slab poured.



Raised platform in PD room.



Central body, looking at main entrance area.