



Maddox ECE Construction Report

July 16, 2018



Aerial view.



Aerial view.



East Wing facing East.



West Wing facing North.



Plumbing installed in bathrooms.



Central body looking south at main entrance.



Brick installation on East wing.



Central body, looking at main entrance area. Door frames installed.