



Maddox ECE Construction Report

July 30, 2018



Main entrance area.



East side brick & West side framing.




Exterior brick & brick ties on North side.



Northeast exterior brick.



Classroom soffits (left) view of playground entrance (right).



East wing with insulation installation.