

CLASSROOM LOCK SECURITY UPGRADES PHASE 3

CLARIFICATION 1

Clarification #	Question	Response
1.01	<p>Per the hardware description the cylinders for the exits are to be 20-757 or 20-763 with a 20-740 core. The cylinders called for are complete cylinders with cores already installed. There is no need for a second core. Should the cylinder numbers be changed to cylinder housings only (20-079 and 20-059 respectively)? This would make it easier for keying as the cores would not have to be removed from the housings prior to keying.</p> <p>On a similar note there are openings that call for cylinders 20-798 and 20-782 with 20-740 cores. These cylinders also would have a second core. Should these cylinders be changed to cylinder housings only (30-007 and 30-032/36-083 respectively)?</p>	<p>The intent was to have empty cylinder housings and cores being ordered separately, as the cores are a restricted item and need to be shipped to NSD. Respective part numbers are correct, except 20-059. Below in red are the FSIC housings originally specified, with the corresponding corrected part number for FSIC "Housing only, less core" cylinders.</p> <p>20-757 changed to: 20-079 20-763 changed to: 26-064</p> <p>20-798 changed to: 30-007 20-782 changed to: 30-032/36-083</p> <p>Please refer to Addendum 2.</p>