2411 E. 70th Terrace

Kansas City, Missouri 64132

REUSE ASSESSMENT

	SITE ASSESSMENT	MARKET ASSESSMENT	COMMUNITY FEEDBACK	Overall Appropriateness	DISPOSITION ALTERNATIVES (L)EASE) / (S)ALE
EDUCATION	3	3	4	3	L or S
Elementary					
Middle/High					
Day Care/ Early Childhood					
RESIDENTIAL	5	3	4	3	S
Market Rate					
Affordable		3			
Senior		3	4		
Mixed-Income					
New Construction					
Commercial	3	2	3	2	L or S
Office	4	2	3		
Retail	1	2			
COMMUNITY USE	4	3	5	3	L or S
Community Center			5		
Open Space					
Community Garden					
Mixed Use	4	3	5	3	L or S
Residential + Social Services					
Multi-tenant					
Demolish	1	2		1	S



BULDINC/SITE ASSESSMENT: Building is in fair condition; there is some water infiltration/sewer backup that must be addressed and deterioration of window lintels. The building size and layout are readily adaptable for multi-family housing (35 +/- units). Classroom size converts well into a single bedroom apartment or combines well into two bedroom apartments. The number and configuration of stairs and exits supports division of the building for multiple tenants (such as housing + community services/office). The building's exterior and interior design limit the visibility required for good retail use, but could work for office occupancy or as a business incubator. Classrooms could be converted into multi-person office space, although the ratio of circulation space to lease space is inefficient. There is only partial air conditioning, which will limit reuse options under a short-term lease scenario. Uses other than office or education will typically require installation of a fire sprinkler system (a community center may also be exempt depending on overall sq. footage and location of exits). The large playground east of the building offers opportunities for commercial infill or community use of the grounds (garden, open space, playground).

<u>Historic Assessment</u>: Building is a good example of an early 20th century Progressive Era school. Much of the original plan and fabric remain intact, although rooms have been reconfigured, some historic elements have been lost, and finishes have been updated. Appears eligible for listing in the National Register of Historic Places.

MARKET ASSESSMENT: Located at the intersection of two major arterials (Gregory Blvd & Prospect Ave) and with immediate access to Bruce R. Watkins Drive (Hwy. 71), Blenheim has very good access via multiple transportation modes. While the area has experienced substantial population decline since 1980 and growing vacancy rates, the loss has been less than the District-wide average. Home ownership rates also remain higher than the District-wide average.

LAND-USE AND ZONING ASSESSMENT: Land-use surrounding Blenheim is primarily single-family residential on the south, west and north with neighborhood commercial along Prospect Street. The current B3-2/R-5 zoning classification supports a variety of potential reuses, including education and some daycare, community center, and certain low intensity residential uses. Higher density residential would require rezoning. Commercial uses allowed under B3-2 zoning include retail sales and office. More commercial uses are allowable with a special use permit.

COMMUNITY FEEDBACK (*Site visit May12, 2011*): When the school was open, it provided much-needed health and social services to the community. Since the school closed, participants indicated that locals no longer have a convenient location to access these services, and supported reuse of the site for a health clinic, service center, food pantry, etc. They were also supportive of senior housing, or a combination of senior housing + senior services/community center, and use of the grounds for a community garden.

2411 E. 70th Terrace

Exterior terracotta and stone work in good Window lintels show signs of deterioration

Masonry requires repointing in several

locations condition

> **CIRCULATION HORIZ.** BUILDING SERVICES

AUDITORIUM

ADMINISTRATION CLASSROOMS

8 September 2011

MEDIA

CIRCULATION VERT.

RESTROOMS

GYMNASIUM CAFETERIA

GENERAL NOTES

Kansas City, Missouri 64132

Brake metal filler panels are separating

the building

ż

Basement

DEVELOPMENT INITIATIVES

Kanses City, Missouri SCHOOL DISTRICT

Blenheim - 2

rom windows in multiple locations

Window opening steel lintels are rusted

Broken and spalling brick at parape

Masonry damage

ی تے

¥

Parapet appears to be leaning

and expanding in multiple locations on

horizontally providing separation between Storm water is infiltrating basement and Classrooms range 750-1,100 SF in size Sufficient parking with easy access Large auditorium in good condition Building could be divided into multiple Large operable windows allow natural and converts well into a single or two uses, for example it could be divided vertically into multiple areas or ower floors and upper floors bedroom apartment units. light and ventilation gymnasium **KEY NOTES** •

•

- - Wood frame and transom
 - Stone surround ~i
- Tall multi-light transom at vestibule

J

<u>-</u>п

B

(ပ

IIK ł

ą

- Wide corridors and stairs
- Windows overlooking gym ġ.
 - Display case <u>ن</u>
- Fire place
- Cafeteria possibly consolidated œ.
- classrooms
- Historic doorway with multi-light transom and sidelights б.
- 10. Decorative plaster ceiling, procenium and
 - walls, highly intact space
- 11. Multiple classrooms consolidated to
 - create library

 - 12. Historic cabinets 13. Typical classroom
- Built in cabinet

몎

ļ

þ

۵ do

- с,
- Recessed coat closet ف
- Floating partition ö
- Wood framed chalkboards ъ
 - CONDITION NOTES
- Area well full of water к К
- Standing water on floor
- Sump pit flooded and pump was not ö
 - working
 - Mold on carpet

 - Mold odor this area
- Plaster damage at ceiling

 - Plaster damage at wall

DIVIDED FOR MULTIPLE USES UNLESS MORE EXITS ARE

PROVIDED

THIS LEVEL COULD NOT BE

- ப்ப்பு வு
- Mold on walls and floor
- Damage at roof coping

2411 E. 70th Terrace

Storm water is infiltrating basement and

CIRCULATION HORIZ. BUILDING SERVICES

AUDITORIUM

ADMINISTRATION CLASSROOMS

8 September 2011

MEDIA

CIRCULATION VERT.

RESTROOMS

GYMNASIUM CAFETERIA

Exterior terracotta and stone work in good Window lintels show signs of deterioration

Masonry requires repointing in several

locations condition

•

GENERAL NOTES

Kansas City, Missouri 64132

Brake metal filler panels are separating

rom windows in multiple locations

Window opening steel lintels are rusted

Broken and spalling brick at parape

4

BUILDING COULD BE DIVIDED FOR MULTIPLE USES AT THIS

LOCATION

Y

Masonry damage

ی تے

Parapet appears to be leaning

and expanding in multiple locations on

he building

ż

Ground Floor

DEVELOPMENT INITIATIVES

Kanses City, Missouri SCHOOL DISTRICT

Blenheim - 3

- norizontally providing separation between Classrooms range 750-1,100 SF in size Large operable windows allow natural Large auditorium in good condition Building could be divided into multiple and converts well into a single or two uses, for example it could be divided Sufficient parking with easy access Fall multi-light transom at vestibule vertically into multiple areas or Cafeteria possibly consolidated ower floors and upper floors Windows overlooking gym Wood frame and transom bedroom apartment units. Wide corridors and stairs light and ventilation Stone surround Display case gymnasium Fire place **KEY NOTES** œ

(2

٢

MECH. BELOW

MP

GYM BELOW

UX HH

6

- classrooms
- Historic doorway with multi-light transom and sidelights о

Σ z

MECH. BELOW

- 10. Decorative plaster ceiling, procenium and
 - walls, highly intact space
- 11. Multiple classrooms consolidated to
 - create library

 - 12. Historic cabinets 13. Typical classroom

c

F

ш

- Built in cabinet с,
- Recessed coat close ف
- Floating partition ö
- Wood framed chalkboards ė
 - CONDITION NOTES

S

- Area well full of water
- к К
- Standing water on floor
- Sump pit flooded and pump was not ö
 - working
 - - Mold on carpet

 - ப்ப்ப்
- Mold odor this area

- Plaster damage at ceiling
- Plaster damage at wall
- Mold on walls and floor
- amage at roof coping

- Ξ

2411 E. 70th Terrace

Storm water is infiltrating basement and

CIRCULATION HORIZ.

CIRCULATION VERT.

RESTROOMS

GYMNASIUM CAFETERIA

BUILDING SERVICES

ADMINISTRATION

8 September 2011

MEDIA

CLASSROOMS

AUDITORIUM

gymnasium

Exterior terracotta and stone work in good Window lintels show signs of deterioration

Masonry requires repointing in several

locations condition

•

GENERAL NOTES

Kansas City, Missouri 64132

Brake metal filler panels are separating

rom windows in multiple locations

Window opening steel lintels are rusted

Broken and spalling brick at parape

Masonry damage

ی تے

¥

BUILDING COULD BE DIVIDED FOR MULTIPLE USES AT THIS

LOCATION

Y

듮

•

Parapet appears to be leaning

and expanding in multiple locations on

he building

ż

First Floor

DEVELOPMENT INITIATIVES

Kanses City, Missouri SCHOOL DISTRICT

Blenheim - 4

- horizontally providing separation between Historic doorway with multi-light transom Classrooms range 750-1,100 SF in size Sufficient parking with easy access Large auditorium in good condition Building could be divided into multiple Large operable windows allow natural and converts well into a single or two uses, for example it could be divided Tall multi-light transom at vestibule vertically into multiple areas or Cafeteria possibly consolidated ower floors and upper floors Windows overlooking gym Wood frame and transom bedroom apartment units. Wide corridors and stairs light and ventilation Stone surround Display case classrooms Fire place **KEY NOTES** б. ~i ġ. <u>ن</u> œ •

ROOF

(°

- and sidelights
- 10. Decorative plaster ceiling, procenium and
 - 11. Multiple classrooms consolidated to walls, highly intact space
 - - create library

 - 12. Historic cabinets 13. Typical classroom
- Built in cabinet с,
- Recessed coat close ف
- Floating partition ö
- Wood framed chalkboards ъ
 - CONDITION NOTES
 - Area well full of water
 - к К
- Standing water on floor
- Sump pit flooded and pump was not ö
 - working
 - Mold on carpet
 - Mold odor this area
- Plaster damage at ceiling
- Plaster damage at wall ப்ப்பு வு
- Mold on walls and floor

- amage at roof coping

2411 E. 70th Terrace

Exterior terracotta and stone work in good Window lintels show signs of deterioration

Masonry requires repointing in several

locations condition

> **CIRCULATION HORIZ.** BUILDING SERVICES

AUDITORIUM

ADMINISTRATION

8 September 2011

CLASSROOMS

CIRCULATION VERT.

RESTROOMS

GYMNASIUM

CAFETERIA

MEDIA

•

GENERAL NOTES

Kansas City, Missouri 64132

Brake metal filler panels are separating

rom windows in multiple locations

Window opening steel lintels are rusted

Broken and spalling brick at parape

Masonry damage

ی تے

¥

BUILDING COULD BE DIVIDED FOR MULTIPLE USES AT THIS

LOCATION

Parapet appears to be leaning

and expanding in multiple locations on

he building

ż

Second Floor

DEVELOPMENT INITIATIVES

Kansas City, Missouri SCHOOL DISTRICT

Blenheim - 5

- Storm water is infiltrating basement and Classrooms range 750-1,100 SF in size Sufficient parking with easy access Large auditorium in good condition Building could be divided into multiple Large operable windows allow natural and converts well into a single or two uses, for example it could be divided bedroom apartment units. light and ventilation gymnasium
 - vertically into multiple areas or
- horizontally providing separation between ower floors and upper floors
 - **KEY NOTES**
 - Wood frame and transom _____
 - Stone surround
- Tall multi-light transom at vestibule
 - Wide corridors and stairs
- Windows overlooking gym

ROOF

AUDITORIUM BELOW

- Display case
- Fire place
- Cafeteria possibly consolidated œ
 - classrooms
- Historic doorway with multi-light transom о
 - and sidelights
- 10. Decorative plaster ceiling, procenium and
 - 11. Multiple classrooms consolidated to walls, highly intact space
 - - create library
 - 12. Historic cabinets 13. Typical classroom
- Built in cabinet с,

۳ß

ບ

X

ш

- Recessed coat close ف
- Floating partition ö
- Wood framed chalkboards
 - ъ
 - CONDITION NOTES
 - Area well full of water
- к К
- Standing water on floor
- Sump pit flooded and pump was not ö
 - working
 - Mold on carpet
 - Mold odor this area
- Plaster damage at ceiling

Plaster damage at wall Mold on walls and floor amage at roof coping

- ப்ப்பு வு

2411 E. 70th Terrace


Kansas City, Missouri 64132

PHOTOGRAPHS





Main entrance



Auditorium



Gymnasium



Corridor



Classroom