

Expiration Date: 10/28/2009

Certificate Number: 7020102108MOSR11347

Training Date: 10/21/2008

Missouri State Certificate for Asbestos Related Occupations

issued by Department of Natural Resources

P.O. Box 176

Jefferson City, MO 65102

Phone (573) 751-4817


Patricia J. Garcia

has successfully completed the requirements for certification as a SUPERVISOR. This Missouri State Certification is subject to review and the director may deny, suspend or revoke the certification per RSMo chapter 643.230.

10/28/2008

Date


Director of Air Pollution Control Program



CERTIFICATION NUMBER: 7020102108MOSR11347

THIS CERTIFIES

Patricia J. Garcia

HAS COMPLETED THE CERTIFICATION REQUIREMENTS FOR

Supervisor

APPROVED: 10/28/2008

EXPIRES: 10/28/2009

 Missouri
Department of
Natural Resources


Director of Air Pollution Control Program



CERT # MOSR 11347
 Exp. 10/28/09

KCMSD 2008 Triennial Re-inspection

660 / W.C. Bryant Elementary School
 319 Westover Road

Inspector: PATRICIA GARZA
 Inspection Date: 10/22/08

Building: 001 Room: 101 Drawing Group Code: 02 USA: 05 0" OD Quantity: 1081 SF
 Floor: B Gym Material: Tile, Vinyl Floor, 12X12
 Record No.: **6600283** Comment: (1992) Light yellow (1996) Quantity=3600 SF - color is white.

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present

Comment Fit Material? Yes No (Explain In Comment Area)

Justification: Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Water Damage <10% Exposed Surface Area
 Loose >10% Exposed Surface Area

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Other: 1,116 SF OF LIGHT YELLOW FLOOR TILE; 2,695 SF OF WHITE FLOOR TILE

Building: 001 Room: 102 Drawing Group Code: 13 USA: 24 0" OD Quantity: 16 SF
 Floor: B Corridor (Fan Room) Material: Cloth, Vibration Joint
 Record No.: **6600126** Comment: (1992) (2) Orange

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present

Comment Fit Material? Yes No (Explain In Comment Area)

Justification: Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Water Damage <10% Exposed Surface Area
 Loose >10% Exposed Surface Area

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Other: _____

Building: 001 Room: 102 Drawing Group Code: 13 USA: 25 0" OD Quantity: 10 SF
 Floor: B Corridor (Fan Room) Material: Cloth, Vibration Joint
 Record No.: **6600127** Comment: (1992) (1) Gray

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present

Comment Fit Material? Yes No (Explain In Comment Area)

Justification: Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Deterioration Forced Airstream
 Water Damage <10% Exposed Surface Area
 Loose >10% Exposed Surface Area

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Other: CHANGE QUANTITY TO 25 SF

KCMSD 2008 Triennial Re-inspection

660 / W.C. Bryant Elementary School
319 Westover Road

Inspector: Patricia Carlin
Inspection Date: 10/28/08

Building: 001 Room: 109 Floor: B Office	Drawing Group Code: 02 USA: 08 0" OD Quantity: 488 SF Material: Tile, Vinyl Floor, 9X9
Record No.: 6600099 Comment: (1992) Blue danube	
Quantity Within 20%? <input type="radio"/> Yes <input checked="" type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable <input type="radio"/> Friable <input type="radio"/> Covering <input type="radio"/> Non-friable <input type="radio"/> Enclosure <input type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)	
Justification:	
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Student Accessible <input type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area
<input type="radio"/> Other: _____	

Building: 001 Room: 109 Floor: B Office	Drawing Group Code: 02 USA: 09 0" OD Quantity: 468 SF Material: Tile, Vinyl Floor, 9X9
Record No.: 6600100 Comment: (1992) Beige	
Quantity Within 20%? <input type="radio"/> Yes <input checked="" type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable <input type="radio"/> Friable <input type="radio"/> Covering <input type="radio"/> Non-friable <input type="radio"/> Enclosure <input type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)	
Justification:	
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Student Accessible <input type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area
<input type="radio"/> Other: _____	

Building: 001 Room: 110 Floor: B Storage	Drawing Group Code: 02 USA: 08 0" OD Quantity: 64 SF Material: Tile, Vinyl Floor, 9X9
Record No.: 6600105 Comment: (1992) Blue danube	
Quantity Within 20%? <input type="radio"/> Yes <input checked="" type="radio"/> No (Give approximate quantity in Comment Area)	Assessment: <input type="radio"/> Not Assessable <input type="radio"/> Friable <input type="radio"/> Covering <input type="radio"/> Non-friable <input type="radio"/> Enclosure <input type="radio"/> Intact and Undamaged <input type="radio"/> Damaged (<10%) <input type="radio"/> Significantly Damaged (>10%) <input type="radio"/> Potential for Damage <input type="radio"/> Potential for Significant Damage
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)	
Justification:	
<input type="radio"/> Blistering <input type="radio"/> Physical Damage <input type="radio"/> Deterioration <input type="radio"/> Water Damage <input type="radio"/> Loose	<input type="radio"/> Student Accessible <input type="radio"/> Activity / Movement <input type="radio"/> Forced Airstream <input type="radio"/> <10% Exposed Surface Area <input type="radio"/> >10% Exposed Surface Area
<input type="radio"/> Other: _____	

KCMSD 2008 Triennial Re-inspection

660 / W.C. Bryant Elementary School
319 Westover Road

Inspector: Patricia Graham
Inspection Date: 10/22/08

Building: 001 Room: 116 Drawing Group Code: 13 USA: 22 0" OD Quantity: 16 SF
 Floor: B Boiler Room Material: Cloth, Vibration Joint
 Record No.: **6600159** Comment: (1992) (2) Black rubberized

Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment:	<input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable	<input checked="" type="radio"/> Covering
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input checked="" type="radio"/> Non-friable	<input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged	
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)	
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input checked="" type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)	
<input checked="" type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage	
<input type="radio"/> Other:	<input checked="" type="radio"/> Loose <input checked="" type="radio"/> >10% Exposed Surface Area	<input checked="" type="radio"/> Potential for Significant Damage	

Building: 001 Room: 117 Drawing Group Code: 13 USA: 22 0" OD Quantity: 22 SF
 Floor: B Fan Room Material: Cloth, Vibration Joint
 Record No.: **6600128** Comment: (1992) (1) Black rubberized

Quantity Within 20%?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment:	<input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable	<input checked="" type="radio"/> Covering
Comment Fit Material?	<input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input checked="" type="radio"/> Non-friable	<input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged	
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)	
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input checked="" type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)	
<input checked="" type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage	
<input type="radio"/> Other:	<input checked="" type="radio"/> Loose <input checked="" type="radio"/> >10% Exposed Surface Area	<input checked="" type="radio"/> Potential for Significant Damage	

Building: 001 Room: 117 Drawing Group Code: 05 USA: 41 0" OD Quantity: 2000 SF
 Floor: B Fan Room Material: Insulation, Exterior Duct
 Record No.: **6600496** Comment: (1992) Asbestos sheet between or on top of air ducts

Quantity Within 20%?	<input type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)	Assessment:	<input type="radio"/> Not Assessable
	<input checked="" type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable	<input type="radio"/> Covering
Comment Fit Material?	<input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)	<input type="radio"/> Non-friable	<input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged	
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)	
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)	
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage	
<input type="radio"/> Other:	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage	

KCMSD 2008 Triennial Re-inspection

660 / W.C. Bryant Elementary School
319 Westover Road

Inspector: Patricia Garcia
Inspection Date: 10/24/08

Building: 001 Room: 129C	Drawing Group Code: 02	USA: 34 0" OD Quantity: 54 SF
Floor: B Closet	Material: Sheeting, Linoleum/Vinyl	
Record No.: 6600187	Comment: (1992) Shelf lining	

Quantity Within 20%? <input type="radio"/> Yes <input checked="" type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input type="radio"/> Student Accessible	<input type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 210	Drawing Group Code: 02	USA: 17 0" OD Quantity: 111 SF
Floor: 1 Nurse's Room	Material: Tile, Vinyl Floor, 9X9	
Record No.: 6600434	Comment: (1992) Cherry red	

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input checked="" type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____	<input checked="" type="radio"/> >10% Exposed Surface Area	<input checked="" type="radio"/> Potential for Significant Damage

Building: 001 Room: 210	Drawing Group Code: 02	USA: 18 0" OD Quantity: 25 SF
Floor: 1 Nurse's Room	Material: Tile, Vinyl Floor, Border/Trim	
Record No.: 6600435	Comment: (1992) Perimeter x 6	

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input checked="" type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other: _____	<input checked="" type="radio"/> >10% Exposed Surface Area	<input checked="" type="radio"/> Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

660 / W.C. Bryant Elementary School
319 Westover Road

Inspector: Patricia Gamon
Inspection Date: 10/26/08

Building: 001 Room: 215	Drawing Group Code: 02	USA: 37 0" OD Quantity: 1794 SF
Floor: 1 Library	Material: Tile, Vinyl Floor	
Record No.: 6600276	Comment: (1992) Under carpet-unknown color-throughout library-possibly 9 x 9 (1996) 2650 SF.	

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input checked="" type="radio"/> Covering
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input checked="" type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input checked="" type="radio"/> Potential for Damage
<input type="radio"/> Other:	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

Building: 001 Room: 215	Drawing Group Code: 02	USA: 20 0" OD Quantity: 351 SF
Floor: 1 Library	Material: Tile, Vinyl Floor, 12X12	
Record No.: 6600423	Comment: (1992) Ivory	

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input checked="" type="radio"/> Covering
Comment Fit Material? <input type="radio"/> Yes <input checked="" type="radio"/> No (Explain In Comment Area)		<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input checked="" type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input checked="" type="radio"/> Potential for Damage
<input type="radio"/> Other:	<input type="radio"/> Loose <input type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

UNUSU CARPET

Building: 001 Room: 230	Drawing Group Code: 02	USA: 17 0" OD Quantity: 18 SF
Floor: 1 Restroom	Material: Tile, Vinyl Floor, 9X9	
Record No.: 6600438	Comment: (1992) Cherry red	

Quantity Within 20%? <input checked="" type="radio"/> Yes <input type="radio"/> No (Give approximate quantity in Comment Area)		Assessment: <input type="radio"/> Not Assessable
	<input type="radio"/> Not Found <input type="radio"/> Definitely Not Present	<input type="radio"/> Friable <input type="radio"/> Covering
Comment Fit Material? <input checked="" type="radio"/> Yes <input type="radio"/> No (Explain In Comment Area)		<input checked="" type="radio"/> Non-friable <input type="radio"/> Enclosure
Justification:	<input type="radio"/> Missing TSI Jacketing <input checked="" type="radio"/> Student Accessible	<input checked="" type="radio"/> Intact and Undamaged
<input type="radio"/> Blistering	<input type="radio"/> Physical Damage <input checked="" type="radio"/> Activity / Movement	<input type="radio"/> Damaged (<10%)
<input type="radio"/> Cracking	<input type="radio"/> Deterioration <input type="radio"/> Forced Airstream	<input type="radio"/> Significantly Damaged (>10%)
<input type="radio"/> Vibration	<input type="radio"/> Water Damage <input type="radio"/> <10% Exposed Surface Area	<input type="radio"/> Potential for Damage
<input type="radio"/> Other:	<input checked="" type="radio"/> >10% Exposed Surface Area	<input type="radio"/> Potential for Significant Damage

