

Expiration Date: **10/28/2009**

Certificate Number: 7020102108MOSR11347

Training Date: **10/21/2008**

Missouri State Certificate for Asbestos Related Occupations

issued by Department of Natural Resources

P.O. Box 176

Jefferson City, MO 65102

Phone (573) 751-4817


Patricia J. Garcia

has successfully completed the requirements for certification as a SUPERVISOR. This Missouri State Certification is subject to review and the director may deny, suspend or revoke the certification per RSMo chapter 643.230.

10/28/2008

Date


Director of Air Pollution Control Program



CERTIFICATION NUMBER: 7020102108MOSR11347

THIS CERTIFIES

Patricia J. Garcia

HAS COMPLETED THE CERTIFICATION REQUIREMENTS FOR

Supervisor

APPROVED: 10/28/2008

EXPIRES: 10/28/2009



Missouri
Department of
Natural Resources


Director of Air Pollution Control Program



CERT# MOSR 11347
EXP. 10/28/09

KCMSD 2008 Triennial Re-inspection

650 / J.S. Chick African Center School
4101 E. 53rd Street

Inspector: Patricia Garcia
Inspection Date: 11/07/08

Building: 001 Room: #3 Drawing Group Code: 16 USA: 36 0" OD Quantity: 3 SF
 Floor: T Crawl Space Material: Debris
 Record No.: **6500201** Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Comment Fit Material? Yes No (Explain In Comment Area)

Justification: Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Blistering Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: _____

Building: 001 Room: 10 Drawing Group Code: 07 USA: 55 4" OD Quantity: 5 EA
 Floor: G Classroom Material: Insulation, MJP on Non-Suspect Pipe
 Record No.: **6500459** Comment: (1992) Domestic hot water

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Comment Fit Material? Yes No (Explain In Comment Area)

Justification: Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Blistering Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: ABOVE CEILING TILE, IN BETWEEN FLOORS

Building: 001 Room: 10 Drawing Group Code: 07 USA: 56 4" OD Quantity: 5 EA
 Floor: G Classroom Material: Insulation, MJP on Non-Suspect Pipe
 Record No.: **6500359** Comment: (1992) Domestic cold water

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)
 Not Found Definitely Not Present

Assessment: Not Assessable
 Friable Covering
 Non-friable Enclosure
 Intact and Undamaged
 Damaged (<10%)
 Significantly Damaged (>10%)
 Potential for Damage
 Potential for Significant Damage

Comment Fit Material? Yes No (Explain In Comment Area)

Justification: Missing TSI Jacketing Student Accessible
 Physical Damage Activity / Movement
 Blistering Deterioration Forced Airstream
 Cracking Water Damage <10% Exposed Surface Area
 Vibration Loose >10% Exposed Surface Area
 Other: ABOVE CEILING TILE, IN BETWEEN FLOORS

KCMSD 2008 Triennial Re-inspection

650 / J.S. Chick African Center School

4101 E. 53rd Street

Inspector: _____

Inspection Date: _____

Building: 001 Room: 10
 Floor: G Classroom
 Record No.: 6500358
 Comment: (1992) Drain
 Drawing Group Code: 07 USA: 57 10" OD Quantity: 3 EA
 Material: Insulation, MJP on Non-Suspect Pipe

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Blistering
- Cracking
- Vibration
- Other:
- Loose
- Water Damage
- Deterioration
- Physical Damage
- Missing TSI Jacking
- Student Accessible
- Activity / Movement
- Forced Airstream
- <10% Exposed Surface Area
- >10% Exposed Surface Area

Assessment:

- Not Assessable
- Friable
- Covering
- Enclosure
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage

Building: 001 Room: 22
 Floor: G Boiler Room
 Record No.: 6500184
 Comment: (1992) -
 Drawing Group Code: 09 USA: 06 0" OD Quantity: 1 EA
 Material: Insulation, Fire Door

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Blistering
- Cracking
- Vibration
- Other:
- Loose
- Water Damage
- Deterioration
- Physical Damage
- Missing TSI Jacking
- Student Accessible
- Activity / Movement
- Forced Airstream
- <10% Exposed Surface Area
- >10% Exposed Surface Area

Assessment:

- Not Assessable
- Friable
- Covering
- Enclosure
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage

Building: 001 Room: 23
 Floor: G Storage
 Record No.: 6500175
 Comment: (1992) -
 Drawing Group Code: 09 USA: 06 0" OD Quantity: 1 EA
 Material: Insulation, Fire Door

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Blistering
- Cracking
- Vibration
- Other:
- Loose
- Water Damage
- Deterioration
- Physical Damage
- Missing TSI Jacking
- Student Accessible
- Activity / Movement
- Forced Airstream
- <10% Exposed Surface Area
- >10% Exposed Surface Area

Assessment:

- Not Assessable
- Friable
- Covering
- Enclosure
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

650 / J.S. Chick African Center School

4101 E. 53rd Street

Inspector: _____

Inspection Date: _____

Building: 001 Room: 24 Floor: G Custodian's Office
 Drawing Group Code: 09 USA: 06 0" OD Quantity: 1 EA
 Material: Insulation, Fire Door
 Record No.: 6500178 Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Blistering
- Cracking
- Vibration
- Other: _____

Assessment:

- Not Assessable
- Friable
- Non-friable
- Enclosure
- Covering
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage

Building: 001 Room: 25 Floor: G Fan Room
 Drawing Group Code: 13 USA: 24 0" OD Quantity: 20 SF
 Material: Cloth, Vibration Joint
 Record No.: 6500174 Comment: (1992) 1 unit dark gray

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Blistering
- Cracking
- Vibration
- Other: _____

Assessment:

- Not Assessable
- Friable
- Non-friable
- Enclosure
- Covering
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage

Building: 001 Room: 25 Floor: G Fan Room
 Drawing Group Code: 09 USA: 06 0" OD Quantity: 1 EA
 Material: Insulation, Fire Door
 Record No.: 6500171 Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Blistering
- Cracking
- Vibration
- Other: _____

Assessment:

- Not Assessable
- Friable
- Non-friable
- Enclosure
- Covering
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

650 / J.S. Chick African Center School

4101 E. 53rd Street

Inspector: _____
Inspection Date: _____

Building: 001 Room: 31A Corridor G
 Drawing Group Code: 09 USA: 43 0" OD Quantity: 2 EA
 Record No.: 6500387
 Comment: (1992) -

Justification:

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Missing TSI Jacketing Student Accessible Activity / Movement Intact and Undamaged Frangible Enclosure Not Assessable

Physical Damage Deterioration Blistering Cracking Vibration Other:

Water Damage Loose Potential for Significant Damage Potential for Damage Significantly Damaged (>10%) Damaged (<10%) Intact and Undamaged Frangible Enclosure Not Assessable

>10% Exposed Surface Area Forced Airstream Activity / Movement Student Accessible Intact and Undamaged Frangible Enclosure Not Assessable

<10% Exposed Surface Area Forced Airstream Activity / Movement Student Accessible Intact and Undamaged Frangible Enclosure Not Assessable

>10% Exposed Surface Area Forced Airstream Activity / Movement Student Accessible Intact and Undamaged Frangible Enclosure Not Assessable

Building: 001 Room: 43 Cafeteria G
 Drawing Group Code: 09 USA: 43 0" OD Quantity: 2 EA
 Record No.: 6500416
 Comment: (1992) -

Justification:

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Missing TSI Jacketing Student Accessible Activity / Movement Intact and Undamaged Frangible Enclosure Not Assessable

Physical Damage Deterioration Blistering Cracking Vibration Other:

Water Damage Loose Potential for Significant Damage Potential for Damage Significantly Damaged (>10%) Damaged (<10%) Intact and Undamaged Frangible Enclosure Not Assessable

>10% Exposed Surface Area Forced Airstream Activity / Movement Student Accessible Intact and Undamaged Frangible Enclosure Not Assessable

<10% Exposed Surface Area Forced Airstream Activity / Movement Student Accessible Intact and Undamaged Frangible Enclosure Not Assessable

>10% Exposed Surface Area Forced Airstream Activity / Movement Student Accessible Intact and Undamaged Frangible Enclosure Not Assessable

Building: 001 Room: 44 Corridor G
 Drawing Group Code: 09 USA: 06 0" OD Quantity: 2 EA
 Record No.: 6500140
 Comment: (1992) -

Justification:

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Missing TSI Jacketing Student Accessible Activity / Movement Intact and Undamaged Frangible Enclosure Not Assessable

Physical Damage Deterioration Blistering Cracking Vibration Other:

Water Damage Loose Potential for Significant Damage Potential for Damage Significantly Damaged (>10%) Damaged (<10%) Intact and Undamaged Frangible Enclosure Not Assessable

>10% Exposed Surface Area Forced Airstream Activity / Movement Student Accessible Intact and Undamaged Frangible Enclosure Not Assessable

<10% Exposed Surface Area Forced Airstream Activity / Movement Student Accessible Intact and Undamaged Frangible Enclosure Not Assessable

>10% Exposed Surface Area Forced Airstream Activity / Movement Student Accessible Intact and Undamaged Frangible Enclosure Not Assessable

KCMSD 2008 Triennial Re-inspection

650 / J.S. Chick African Center School

Inspector: _____

4101 E. 53rd Street

Inspection Date: _____

Building: 001 Room: 5 Floor: G Corridor
 Drawing Group Code: 09 USA: 06 0" OD Quantity: 2 EA
 Material: Insulation, Fire Door
 Record No.: 6500129
 Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Missing TSI Jacketing
- Physical Damage
- Deterioration
- Water Damage
- Loose
- Vibration
- Other:

Assessment: Not Assessable Frangible Covering Enclosure

Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

Building: 001 Room: C3B Floor: G Chase
 Drawing Group Code: 07 USA: 11 4" OD Quantity: 1 EA
 Material: Insulation, MJP on Wrapped Pipe Covering
 Record No.: 6500326
 Comment: (1992) Domestic cold water

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Missing TSI Jacketing
- Physical Damage
- Deterioration
- Water Damage
- Loose
- Vibration
- Other:

Assessment: Not Assessable Frangible Covering Enclosure

Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

Building: 001 Room: C3B Floor: G Chase
 Drawing Group Code: 06 USA: 10 4" OD Quantity: 1 LF
 Material: Insulation, Pipe, Paper
 Record No.: 6500325
 Comment: (1992) Domestic cold water

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Missing TSI Jacketing
- Physical Damage
- Deterioration
- Water Damage
- Loose
- Vibration
- Other:

Assessment: Not Assessable Frangible Covering Enclosure

Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

650 / J.S. Chick African Center School

Inspector: _____

4101 E. 53rd Street

Inspection Date: _____

Building: 001 Room: 100 Floor: 1 Classroom
 Drawing Group Code: 07 USA: 57 8" OD Quantity: 3 EA
 Material: Insulation, MJP on Non-Suspect Pipe

Record No.: 6500460
 Comment: (1992) Drain

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Blistering
- Cracking
- Vibration
- Other:
- Missing TSI Jacketing
- Physical Damage
- Deterioration
- Water Damage
- Loose
- Student Accessible
- Activity / Movement
- Forced Airstream
- <10% Exposed Surface Area
- >10% Exposed Surface Area

Assessment:

- Not Assessable
- Frangible
- Non-frangible
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage

Building: 001 Room: 105 Floor: 1 Classroom
 Drawing Group Code: 09 USA: 43 0" OD Quantity: 1 EA
 Material: Insulation, Fire Door

Record No.: 6500245
 Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Blistering
- Cracking
- Vibration
- Other:
- Missing TSI Jacketing
- Physical Damage
- Deterioration
- Water Damage
- Loose
- Student Accessible
- Activity / Movement
- Forced Airstream
- <10% Exposed Surface Area
- >10% Exposed Surface Area

Assessment:

- Not Assessable
- Frangible
- Non-frangible
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage

Building: 001 Room: 110 Floor: 1 Corridor
 Drawing Group Code: 09 USA: 43 0" OD Quantity: 2 EA
 Material: Insulation, Fire Door

Record No.: 6500238
 Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Blistering
- Cracking
- Vibration
- Other:
- Missing TSI Jacketing
- Physical Damage
- Deterioration
- Water Damage
- Loose
- Student Accessible
- Activity / Movement
- Forced Airstream
- <10% Exposed Surface Area
- >10% Exposed Surface Area

Assessment:

- Not Assessable
- Frangible
- Non-frangible
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

650 / J.S. Chick African Center School

4101 E. 53rd Street

Inspector: _____

Inspection Date: _____

Building: 001 Room: 112 Floor: 1 Corridor
 Record No.: 6500282 - Comment: (1992)

Drawing Group Code: 09 USA: 06 0" OD Quantity: 2 EA
 Material: Insulation, Fire Door

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Other:
- Vibration
- Cracking
- Blistering
- Physical Damage
- Missing TSI Jacketing
- Student Accessible
- Frable
- Non-frable
- Enclosure
- Not Assessable

Assessment:

- Yes
- No (Give approximate quantity in Comment Area)
- Not Found
- Definitely Not Present
- No (Explain in Comment Area)
- Loose
- Water Damage
- Deterioration
- Physical Damage
- Missing TSI Jacketing
- Student Accessible
- Activity / Movement
- Forced Air/Stream
- <10% Exposed Surface Area
- >10% Exposed Surface Area
- Potential for Significant Damage
- Potential for Damage
- Significantly Damaged (>10%)
- Damaged (<10%)
- Intact and Undamaged
- Frable
- Non-frable
- Enclosure
- Not Assessable

Building: 001 Room: 121 Floor: 1 Library
 Record No.: 6500006 - Comment: (1992) Low pressure steam

Drawing Group Code: 07 USA: 54 6" OD Quantity: 2 EA
 Material: Insulation, MJP on Non-Suspect Pipe

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Other:
- Vibration
- Cracking
- Blistering
- Physical Damage
- Missing TSI Jacketing
- Student Accessible
- Frable
- Non-frable
- Enclosure
- Not Assessable

Assessment:

- Yes
- No (Give approximate quantity in Comment Area)
- Not Found
- Definitely Not Present
- No (Explain in Comment Area)
- Loose
- Water Damage
- Deterioration
- Physical Damage
- Missing TSI Jacketing
- Student Accessible
- Activity / Movement
- Forced Air/Stream
- <10% Exposed Surface Area
- >10% Exposed Surface Area
- Potential for Significant Damage
- Potential for Damage
- Significantly Damaged (>10%)
- Damaged (<10%)
- Intact and Undamaged
- Frable
- Non-frable
- Enclosure
- Not Assessable

Building: 001 Room: 124 Floor: 1 Corridor
 Record No.: 6500289 - Comment: (1992)

Drawing Group Code: 09 USA: 06 0" OD Quantity: 2 EA
 Material: Insulation, Fire Door

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Other:
- Vibration
- Cracking
- Blistering
- Physical Damage
- Missing TSI Jacketing
- Student Accessible
- Frable
- Non-frable
- Enclosure
- Not Assessable

Assessment:

- Yes
- No (Give approximate quantity in Comment Area)
- Not Found
- Definitely Not Present
- No (Explain in Comment Area)
- Loose
- Water Damage
- Deterioration
- Physical Damage
- Missing TSI Jacketing
- Student Accessible
- Activity / Movement
- Forced Air/Stream
- <10% Exposed Surface Area
- >10% Exposed Surface Area
- Potential for Significant Damage
- Potential for Damage
- Significantly Damaged (>10%)
- Damaged (<10%)
- Intact and Undamaged
- Frable
- Non-frable
- Enclosure
- Not Assessable

KCMSD 2008 Triennial Re-inspection

650 / J.S. Chick African Center School

4101 E. 53rd Street

Inspector: _____

Inspection Date: _____

Building: 001 Room: PC132 Floor: 1 Pipe Chase
 Record No.: 6500335
 Comment: (1992) Low pressure steam

Drawing Group Code: 07 USA: 54 6" OD Quantity: 4 EA
 Material: Insulation, MJP on Non-Suspect Pipe

Assessment: Not Assessable Frangible Enclosure Covering Non-frangible Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

Justification: Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) Comment Fit Material? Yes No (Explain in Comment Area) Missing TSI Jacketing Student Accessible Physical Damage Activity / Movement Forced Airstream <10% Exposed Surface Area >10% Exposed Surface Area Blistering Cracking Vibration Other:

Building: 001 Room: PC132 Floor: 1 Pipe Chase
 Record No.: 6500337
 Comment: (1992) White

Drawing Group Code: 02 USA: 60 0" OD Quantity: 14 SF
 Material: Tile, Vinyl Floor, 9X9

Assessment: Not Assessable Frangible Enclosure Covering Non-frangible Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

Justification: Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) Comment Fit Material? Yes No (Explain in Comment Area) Missing TSI Jacketing Student Accessible Physical Damage Activity / Movement Forced Airstream <10% Exposed Surface Area >10% Exposed Surface Area Blistering Cracking Vibration Other:

Building: 001 Room: 206 Floor: 2 Stairs
 Record No.: 6500057
 Comment: (1992) -

Drawing Group Code: 09 USA: 06 0" OD Quantity: 2 EA
 Material: Insulation, Fire Door

Assessment: Not Assessable Frangible Enclosure Covering Non-frangible Intact and Undamaged Damaged (<10%) Significantly Damaged (>10%) Potential for Damage Potential for Significant Damage

Justification: Quantity Within 20%? Yes No (Give approximate quantity in Comment Area) Comment Fit Material? Yes No (Explain in Comment Area) Missing TSI Jacketing Student Accessible Physical Damage Activity / Movement Forced Airstream <10% Exposed Surface Area >10% Exposed Surface Area Blistering Cracking Vibration Other:

KCMSD 2008 Triennial Re-inspection

650 / J.S. Chick African Center School

Inspector: _____

4101 E. 53rd Street

Inspection Date: _____

Building: 001 Room: 209

Floor: 2 Stairs

Drawing Group Code: 09 USA: 06
Material: Insulation, Fire Door

0" OD Quantity: 2 EA

Record No.: 6500066
Comment: (1992) -

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Other
- Vibration
- Cracking
- Blistering
- Physical Damage
- Missing TSI Jacketing
- Student Accessible
- Activity / Movement
- Forced Airstream
- <10% Exposed Surface Area
- >10% Exposed Surface Area

Assessment:

- Not Assessable
- Frangible
- Non-frangible
- Enclosure
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage

Building: 001 Room: A-1

Floor: 2 Attic Space

Record No.: 6500195
Comment: (1992) 2 units-brown

Drawing Group Code: 13 USA: 26
Material: Cloth, Vibration Joint

0" OD Quantity: 12 SF

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Other
- Vibration
- Cracking
- Blistering
- Physical Damage
- Missing TSI Jacketing
- Student Accessible
- Activity / Movement
- Forced Airstream
- <10% Exposed Surface Area
- >10% Exposed Surface Area

Assessment:

- Not Assessable
- Frangible
- Non-frangible
- Enclosure
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage

Building: 001 Room: A-2

Floor: 2 Attic Space

Record No.: 6500204
Comment: (1992) 1 unit-brown

Drawing Group Code: 13 USA: 38
Material: Cloth, Vibration Joint

0" OD Quantity: 16 SF

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes No (Explain in Comment Area)

Justification:

- Other
- Vibration
- Cracking
- Blistering
- Physical Damage
- Missing TSI Jacketing
- Student Accessible
- Activity / Movement
- Forced Airstream
- <10% Exposed Surface Area
- >10% Exposed Surface Area

Assessment:

- Not Assessable
- Frangible
- Non-frangible
- Enclosure
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage

KCMSD 2008 Triennial Re-inspection

650 J.S. Chick African Center School

4101 E. 53rd Street

Building: 001 Room: C211A

Floor: 2 Chase

Record No.: 6500068

Comment: (1992) Low pressure steam

Drawing Group Code: 06 USA: 02
Material: Insulation, Pipe, Corrugated

4" OD Quantity: 20 LF

Inspection Date: _____

Inspector: _____

Quantity Within 20%? Yes No (Give approximate quantity in Comment Area)

Comment Fit Material? Yes Not Found Definitely Not Present

Justification:

- Blistering
- Cracking
- Vibration
- Other:

- Missing TSI Jacketing
- Physical Damage
- Deterioration
- Water Damage
- Loose

- Student Accessible
- Activity / Movement
- Forced Airstream
- <10% Exposed Surface Area
- >10% Exposed Surface Area

Assessment:

- Not Assessable
- Covering
- Enclosure
- Frangible
- Non-frangible
- Intact and Undamaged
- Damaged (<10%)
- Significantly Damaged (>10%)
- Potential for Damage
- Potential for Significant Damage